

# Boeing 737-500, G-OBMX

## AAIB Bulletin No: 2/97 Ref: EW/C96/9/3 Category: 1.1

<b>Aircraft Type and Registration:</b>	Boeing 737-500, G-OBMX
<b>No &amp; Type of Engines:</b>	2 CFM56-3C1 turbofan engines
<b>Year of Manufacture:</b>	1991
<b>Date &amp; Time (UTC):</b>	5 September 1996 at 0851 hrs
<b>Location:</b>	Near Lambourne
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 6 - Passengers - 64
<b>Injuries:</b>	Crew - Nil - Passengers - Nil
<b>Nature of Damage:</b>	Nil
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	55 years
<b>Commander's Flying Experience:</b>	13,640 hours (of which 5,525 hours were on type) Last 90 days - 214 hours Last 28 days - 74 hours
<b>Information Source:</b>	AAIB Field Investigation

## History of flight

The crew had flown an uneventful flight from London Heathrow to Brussels during which the aircraft had been fully serviceable. After a normal turnround, the same crew took-off for the return flight. The commander was the handling pilot and he engaged AutoPilot 'A' soon after establishing the aircraft on the departure from Brussels; in accordance with his company procedures, he had used auto-throttle from the beginning of his take-off roll. The climb and cruise were normal and the automatic control systems were operating correctly. During the descent, the crew were advised that there was a delay going into Heathrow, and were instructed to enter the 'Hold' at Lambourne. After approximately 15 minutes in the 'Hold', ATC instructed the crew to leave Lambourne at FL80 on a heading of 270°(M) at 220 kt IAS. The commander selected 'HDG SELECT' and '270°' on the Mode Control Panel (MCP) and, as the aircraft crossed Lambourne, it rolled out on the required heading.

With the aircraft still level at FL 80 and clear of any cloud, the crew were not visually aware of any other aircraft in their vicinity. Neither crew member had their feet on the rudder pedals but the commander had his hands lightly on the control wheel. The crew were then cleared to descend to FL 70 and the commander selected the new altitude, Vertical Speed ('V/S') and a descent rate of 1,000 feet per minute on the MCP. As the aircraft started the programmed descent, the Flight Service Manager (FSM) entered the cockpit. Both crew members turned in their seats to talk to the FSM and the commander took his hands off the control wheel as he turned. Shortly afterwards, both of the flight crew were aware of the aircraft banking to the left; the bank appeared rapid but smooth. They both turned back and the commander put his feet on the rudder pedals and his hands on the control wheel. As he did so, his impression was that the wheel and rudder were central. The aircraft appeared to be banked at least 30° and the impression of both crew members was that the aircraft was continuing to roll to the left. The commander immediately disconnected the autopilot and applied right rudder and right control wheel. Response to the control inputs was rapid and accurate and the aircraft was quickly brought back under control. After confirming that the rudder and aileron trim were neutral and that there were no system abnormalities, the autopilot was re-engaged. It operated correctly for the remainder of the flight although the commander manually disconnected it very early on the approach.

The first officer confirmed the commander's account of the incident. He also reached for the controls following the uncommanded roll, which he estimated as 50° bank. He also thought that the control wheel and rudder were central prior to the commander's manual input. Both crew members had experienced wake turbulence before but were not fully convinced that this was a wake encounter. They based this assessment on the fact that it was smoother and more extreme than their previous experience.

The incident was reported to AAIB and arrangements were made to read and analyse the recorded flight data and for AAIB personnel to be present during an investigative inspection.

### **Engineering investigation**

Following the incident, a full inspection of the aircraft roll control system was conducted with the assistance of the manufacturer. This inspection established that the control system was correctly rigged, well within the limits required, and functioned normally. The inspection was expanded to ensure that there had been no moisture ingress into the connectors of the avionics boxes which affect flight controls. It also showed that the protective shields, in the E & E bay behind the nose landing gear, were correctly located and in good condition. There was no evidence of moisture ingress into the bay from any source.

Additionally, a special check on the roll control system was performed to ensure confidence in the calibration and directional sense of the roll control signal to the flight data recorder system. This showed that both aspects were correct.

Enquiries of the manufacturer revealed that the maximum roll control deflection which the autopilot can achieve is, by design, about 4.5° of aileron movement (a control wheel movement of about 20°), depending on the stimulus. The maximum aileron movement which can be achieved by the pilot is about 20°, which requires a control wheel input of about 82°.

### **Weather conditions**

An aftercast was provided by The Meteorological Office at Bracknell. At 0800 hrs on the day of the incident, there was a ridge of high pressure established over England and Wales with a northeasterly airflow over southern England. There were no forecasts for turbulence on the day and no subsequent reports of turbulence being experienced. Analysis of the upper soundings suggest that there was a strong inversion around 5,000 feet amsl in the area of Lambourne and the wind speed at that level was 060°T/15kt.

### **Radar information**

Recorded radar information was obtained, correlated with the FDR, analysed and is displayed at Figure 2. It showed that G-OBMX was 1 minute 26 seconds or 6.35 nm behind a B767 aircraft which was also approaching Heathrow. A B757 aircraft which had just departed from Runway 09 at Heathrow, passed approximately at right angles to the track of the two inbound aircraft. As the B757 was 2,300 feet below G-OBMX, it was not considered relevant to the incident.

The tracks of the B767 and G-OBMX are very close and, considering the recorded wind and with G-OBMX descending geographically earlier than the B767, the position of the incident is consistent with G-OBMX encountering the wake shed by the B767.

### **FDR information**

A time history of the relevant parameters is shown at Figure 3. This shows that G-OBMX was level at FL 80, heading 270°M and at 220 kt IAS. Wind recorded at that level was 057°T/40kt. At 08:51:10 hrs, G-OBMX started a gentle descent. Shortly afterwards, as the aircraft descended through 7,800 feet, small perturbations appeared on the 'normal g' trace. Within two seconds, right roll control was applied; initially this kept the aircraft wings level. However, over the following three seconds, the aircraft started to roll to the left, albeit against an increasing aileron deflection to counter this movement. With the aileron then constant at about 5° deflection, G-OBMX continued to roll left at an increasing roll rate. The autopilot disengaged and a large right roll demand was applied to the aircraft. The maximum left roll rate derived from the data was more than 18° per second and this occurred after the right roll demand was applied. With the sampling intervals associated with the FDR data acquisition, the aircraft may have achieved a greater bank angle than the recorded 31°. The aircraft then recovered to wings level within four seconds. There are no subsequent indications of any further uncommanded flight path excursions.

Information from Boeing Commercial Airplane Group indicated that, from data obtained from a test programme, there are some key characteristics or attributes of wake encounters. External characteristics include perturbations in airspeed and in normal g without corresponding changes in pitch attitude; this can also sometimes be seen in random changes in lateral acceleration and angle of attack. Roll characteristics can be much more difficult to discern but include a roll angle that leads to a heading change and a roll rate increasing with time. The G-OBMX FDR data shows these classic characteristics. It also displays similarities with other recorded wake turbulence events.

### **Wake turbulence**

Aircraft vortex wake categories and spacing criteria are defined in the Manual of Air Traffic Services (MATS) - Part 1 Chapter 3 & Appendix B. The B767 is included in the heavy category and both the B757 and B737 are included in the medium category. The spacing required for a medium category aircraft behind a heavy category aircraft is five miles. The spacing between two medium category aircraft is three miles. However, Supplementary Instruction No 6 of 1994 to MATS

acknowledged the unique characteristics of the B757 and raised the spacing requirements of a medium category aircraft behind a B757 to four miles. These figures relate specifically to aircraft on final approach but, within the MATS, there is an instruction to apply spacing so that "aircraft of a lower weight category do not fly through the wake of an aircraft of a higher category within the area of maximum vortices. Where minimum separation between IFR flights is greater than the vortex wake spacing requirements then the IFR minima shall be applied."

CAA Aeronautical Information Circular (AIC) 178/1993 draws attention to the dangers associated with turbulence caused by aircraft wake vortices. The AIC makes the point that the separation minima cannot entirely remove the possibility of a wake turbulence encounter. The objectives of the minima are to reduce the probability of a vortex wake encounter to an acceptably low level, and to minimise the magnitude of the upset when an encounter does occur.

Wake vortices are present behind every aircraft but are particularly severe when generated by heavy aircraft. The characteristics of the wake vortex system generated are determined initially by the aircraft's gross weight, wing span, airspeed, configuration and attitude. Subsequently, these characteristics are altered by interaction between the vortices and the ambient atmosphere. Time to total decay can vary from a few seconds to a few minutes after the passage of the aircraft. For practical purposes, the vortex system in the wake of an aircraft may be regarded as being made up of two counter-rotating cylindrical air masses trailing aft from the aircraft, as shown in Figure 1. Studies suggest that, at medium level, the two vortices are separated by about three quarters of the aircraft's wingspan and, in still air, tend to drift slowly downwards, at a rate of approximately 400 feet per minute, and level off, usually not more than 1,000 feet below the flight path of the aircraft. However, their behaviour is not predictable, particularly in the aspects of their trajectory and decay.




Figure 1

## Discussion

The G-OBMX data shows the classic symptoms of a wake turbulence encounter. A review of the radar trace indicates that G-OBMX was following a B767, but slightly downwind. The separation, at 6.35 miles, was greater than the required minimum of 5 miles. With G-OBMX starting a descent geographically earlier than the B767, the uncommanded roll started as the B737 was 200 feet vertically below the flight path of the B767 at that geographical position (see Figure 2). Within three seconds, the ailerons were at their maximum available deflection to the right under autopilot authority (approximately  $4.5^\circ$ ) and could no longer prevent the aircraft from rolling left. The pilot's response was extremely quick to disengage the autopilot, and exert much greater roll control to counter the uncommanded roll and restore level flight. However, if he had had his hands on the

control wheel when the autopilot started to oppose the uncommanded roll, he would have been immediately aware of the control wheel moving.

It is not known what would have happened if the autopilot had remained in sole control. In these circumstances, the manufacturers state that there would be no reason for the autopilot to disconnect automatically. Both pilots considered that the roll would have continued and the FDR information indicates that the roll rate was high and increasing and that the aircraft achieved a bank angle of at least 31°. If G-OBMX had cleared the wake vortex before achieving too high a bank angle, it is probable that the autopilot would have recovered the aircraft to level flight.

This incident is an example of a severe wake turbulence encounter occurring even though the spacing between aircraft was greater than the recommended minimum. With the flow rate at major airports, aircraft are highly likely to be at the minimum spacing as they are being manoeuvred for approach. This incident was controllable with manual control inputs but doubt remains as to the outcome if the autopilot had been left to recover the situation. Good airmanship dictates a 'hands on' monitoring of the autopilot in such situations. Immediately following this incident, the operating company instituted a flying instruction to their crews to the effect that the handling pilot must be physically monitoring the controls below 10,000 feet agl.