

Piper PA-34-200T Seneca II, G-BGFT, 7 March 1996

AAIB Bulletin No: 6/96 Ref: EW/G96/03/03 Category: 1.3

Aircraft Type and Registration:Piper PA-34-200T Seneca II, G-BGFT

No & Type of Engines:2 Continental LTSIO-360-EB1A piston engines

Year of Manufacture:1978

Date & Time (UTC):7 March 1996 at 1504 hrs

Location:Filton Airport, Bristol

Type of Flight:Aerial Work (Training)

Persons on Board:Crew - 3 Passengers - None

Injuries:Crew - None Passengers - N/A

Nature of Damage:Damage to propellers, flaps and underside of fuselage

Commander's Licence:Airline Transport Pilot's Licence

Commander's Age:59 years

Commander's Flying Experience:11,079 hours (of which 1,543 were on type)

Last 90 days - 82 hours

Last 28 days - 35 hours

Information Source:Aircraft Accident Report Form submitted by the pilot

The aircraft was engaged on an Instrument Rating training flight from Oxford Kidlington. The instructor was supervising a student pilot who was conducting an NDB approach to Runway 09 at Filton under simulated asymmetric power. It is the company standard operating procedure, during this type of approach, to lower the landing gear when passing the Final Approach Fix as the final descent to Minimum Descent Altitude (MDA) is commenced. On completion of the approach, it was intended to conduct a touch and go landing.

The instructor reported that the student was having a degree of difficulty in controlling the aircraft and achieving the correct approach path. The instructor did not notice that the student had not lowered the landing gear at the appropriate point. After levelling off at MDA and transferring to visual flight, the student's handling was still causing the instructor some concern, to the extent that he took over control of the aircraft for the landing. The landing gear remained retracted throughout, the aircraft landed gently on its underside and slid to a halt. There was no fire and the occupants

vacated by the normal means. Subsequent inspection of the landing gear operating mechanism did not reveal any unserviceabilities.

The landing gear warning horn did not sound during the final phase of the approach as the throttles were retarded for landing. The warning horn system is activated by microswitches associated with low power throttle position. These are normally set up to activate the warning horn at a throttle position which corresponds approximately to a manifold pressure just below that used for the training asymmetric flight zero thrust setting. It is not possible to check this setting until the aircraft has been repaired.