

Concorde Type 1 Variant 102, G-BOAE, 5 May 1996

AAIB Bulletin No: 7/96 Ref: EW/C96/5/3 Category: 1.1

INCIDENT

Aircraft Type and Registration: Concorde Type 1 Variant 102, G-BOAE

No & Type of Engines: 4 Rolls Royce Olympus 593/610 turbojet engines

Year of Manufacture: 1977

Date & Time (UTC): 5 May 1996 at 1141 hrs

Location: Atlantic position 18_ West

Type of Flight: Public Transport

Persons on Board: Crew - 9 Passengers - 55

Injuries: Crew - None Passengers - None

Nature of Damage:

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 48 years

Commander's Flying Experience: 12,500 hours

Last 90 days - 85 hours

Last 28 days - 20 hours

Information Source: AAIB Field Investigation


The aircraft was on a scheduled flight from London Heathrow Airport to New York Kennedy Airport and had reached 18_ West at FL 490 and a speed of M1.97 when the crew felt a rumble on the flightdeck. The Master Warning Light for fuel then illuminated followed by the No 1 engine accumulator and fuel low pressure lights. The No 1 fuel low pressure magnetic indicator was seen to indicate open and the fuel scavenge pump had commenced operating. The No 1 fuel tank contents decreased rapidly to 450 kg suggesting that a fuel leak of some kind had occurred. The crew commenced a turn back towards London maintaining FL 490 and made a PAN call to Prestwick Oceanic Control on the HF radio. They then decelerated the aircraft to subsonic speed and carried out a precautionary shut-down of the No 1 engine.

When instructed by ATC, the crew selected the emergency code on the secondary radar transponder and were given a direct track to the Ockham VOR beacon. They were then cleared without delay to Heathrow where they carried out a "fuel saving" landing; this is an approved heavy-weight landing procedure. After the aircraft had taxied clear of the runway, it was inspected by the fire service who confirmed that there was no visible external fuel leak.

Fuel reconciliation checks between the gauged fuel contents of all the tanks, and the total fuel before flight less that which had been burnt by the engines, indicated that the 'missing' fuel had not been lost overboard, but had been transferred from No 1 tank to No 6 tank. This was subsequently confirmed by refilling No 1 tank from No 6 and switching on the No 1 engine feed pumps. The fuel then transferred from No 1 to No 6 tank.

The No 1 fuel collector tank feeds the No 1 engine and the delivery pipe passes through the No 6 tank. The access to the tank is severely limited, and consequently the pipe run consists of an assembly of 4 pipes and 5 pipe couplings. One of these pipe couplings had come apart, with the exception of its electrical bonding lead, and the coupling seal was found on the tank floor.

The compression seal coupling used on the fuel distribution pipework was designed to allow for expansion and contraction of the pipework in sympathy with airframe thermal expansion. Consequently the screw end cap defines the extent of the pipe movement rather than forming a fixed locating device. It is locked by a spring which sits between two adjacent lugs. Whilst not to Class 1 locking standards, there is no record of a previous coupling failure in the CAA data base.



Expanding fuel pipe coupling

The pipes were removed and replaced during an intermediate check for access to tank fuel leaks, but the pipe joint had remained intact during the subsequent ground runs and for two sectors

comprising flights to New York and return. The Concorde Operations Engineering Controller has conducted an internal enquiry into this lapse in quality and has made recommendations to his management to prevent a recurrence; these include a recommendation to carry out a duplicate check of fuel couplings.