

Spitfire IXT, G-TRIX

AAIB Bulletin No: 3/97 Ref: EW/C96/9/9 Category : 1.2

Aircraft Type and Registration:	Spitfire IXT, G-TRIX
No & Type of Engines:	1 Packard Merlin 266 piston engine
Year of Manufacture:	1944
Date & Time (UTC):	15 September 1996 at 1705 hrs
Location:	Chichester Airport
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - 1
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Both main landing gear legs collapsed, right wing tip damaged
Commander's Licence:	Private Pilot's Licence
Commander's Age:	37 years
Commander's Flying Experience:	718 hours (of which 82 were on type) Last 90 days - 12 hours Last 28 days - 4 hours
Information Source:	AAIB Field Investigation

History of the flight

A curved approach to land on Runway 24 was flown in nil wind, with all indications normal and the landing gear indicator showing green. A normal touchdown was executed, after which the stick was brought progressively back and brakes applied normally. A witness on the ground described the landing as good, with one bounce of approximately 1 to 2 feet. After touchdown, gentle left rudder was needed to hold the aircraft straight, but thereafter increasing amounts of left rudder were required to maintain heading as the speed decayed. As the aircraft crossed the runway intersection, at a speed of 'about 30 mph', the right landing gear was seen to collapse and the aircraft slewed rapidly to the right about the grounded right wing tip; it then slid in a curving path towards the right hand edge of the runway. As it slid off the runway to its left, the left landing gear collapsed inboard and the aircraft finally came to rest on the grass just beyond the intersection, having yawed through approximately 110° from the runway heading. The pilot had shut-off the fuel and magnetos

immediately he felt the right landing gear collapse, and there was no fire. There was no structural damage to the cockpit and the pilot, who was uninjured, was able to leave the aircraft without difficulty.

The pilot stated that he examined the runway after the accident and was able to identify the tyre marks from both main wheels. He noted that right tyre mark displayed distinct 'scuff' marks beginning at a point some 200 metres after touchdown, which persisted through the remainder of the ground roll, and which he attributed to a significant toeing-out of the right landing gear wheel.

The wings and the failed landing gear attachments were subsequently examined by AAIB at the repair facility to which they had been taken after the accident.

Landing gear arrangements

Each main landing gear is carried on a simple pintle housing attached to the aft face of the main spar by a ring of 6 attachment studs and nuts: see Figures 1a and 1b. The upper part of the main landing gear body comprises an actuating horn, which extends above the pintle, to which is connected a hydraulic retraction actuator.

Each landing gear is locked into both the extended and retracted position by a single lock mechanism, carried in a housing bolted to the rear face of the spar. This mechanism comprises a simple spring-loaded lock plunger, the engagement end of which is cut back at an angle of approximately 45° , supported in a plain bushing which allows the lock plunger to be rotated through 180° . As the landing gear extends from the retracted position, the horn part of the landing gear body comes into contact with the chamfered face of the spring loaded lock plunger, pushing the plunger back against the spring until it comes into line with a recess in the horn; at this point, the spring pushes the plunger into engagement with the horn, thus locking the landing gear in the DOWN position. Prior to retraction, both lock plungers are rotated in their housings through 180° by means of a chain and sprocket wheel arrangement connected to the cockpit landing gear selector, reversing the orientation of the chamfer and allowing the horn to be pulled back, out of lock engagement, by the retraction actuator. As the gear reaches its fully stowed position in the wing, a projecting uplock bracket attached to the landing gear body engages the (reversed) lock plunger, locking the gear in the UP position. Rotation of the lock plunger prior to gear extension allows the retraction actuator to pull the leg out of engagement with the uplock bracket, and re-positions the plunger in readiness to lock the gear DOWN.

The landing gear is raked forward significantly when the aircraft is in a 3-point attitude, as shown in Figure 2. Vertical ground reaction loads will therefore impose a loading action tending to wrench the landing gears forward about the pintle attachment to the spar, increasing the tensile loading on the pintle upper attachment studs. Drag loads due to braking and rolling resistance will produce a rearward loading, reducing the tensile loads in the upper studs and tending to generate tensile loads in the lower studs.

AAIB examination

Right main landing gear

The right landing gear pintle had separated from the spar due to fatigue failure of the two uppermost attachment studs, and subsequent overload failure of the remaining 4 studs due to a combination of

bending and thread-stripping. The fatigue crack had started at the threads in the vicinity of the nut back-face, and had resulted in pre-fracture cracking through approximately 50% to 70% of the stud cross-sections.

Damage to the spar immediately below the pintle, and the mode of failure of the lower attachment studs, suggested that the leg had wrenched forward and outboard about the lower pintle attachment studs, disengaging the horn part of the leg from the downlock plunger. The lock mechanism and its attachments to the spar were undamaged, consistent with the lock plunger having become disengaged at an early stage in the landing gear collapse.

Left main landing gear

The left landing gear pintle had been wrenched slightly away from the aft face of the spar, and the top inboard attachment stud had fractured in fatigue.

There was evidence that excessive side loads had been applied, forcing the landing gear inboard. The leverage forces thus developed had caused a partial failure of the lock housing attachment to the spar, which allowed the downlock plunger to disengage. The unrestrained leg had then pivoted inboard, against the inboard rib structure, partially wrenching the pintle from the spar.

Detailed examination of the failed studs

At the request of AAIB, all of the pintle attachment studs were index-marked (to show their orientation) and, after careful removal from the airframe, were forwarded to AAIB for more detailed examination.

Metallurgical examination confirmed the presence of fatigue in the two studs from the right side attachment, and also within the single stud from the left side, initiating in each case from multiple origins in the roots of the threads. Two separate, adjacent, fatigue cracks were found to be present in the fracture through the inboard stud from the right side. These had propagated from adjacent thread roots, and had merged during the final fracture of the stud. The directions of propagation of these two adjacent cracks differed slightly from one another, raising the possibility that this stud may have been removed in a cracked condition at some point in the aircraft's history, and re-fitted in a slightly different orientation. However, this could not be positively confirmed.

The fatigue fracture faces of the right studs each exhibited a dark region of discoloration associated with the early period of growth, followed by a region of clean fracture surface; these two regions being clearly differentiated. This suggested that, after the fatigue cracks had propagated a significant way through the studs, the aircraft may have been stored or taken out of service for a period before resuming operation again, giving rise to fresh fatigue growth.

Differences in fatigue growth characteristics were evident on each of the fracture faces from the two right side studs. The early stages of growth in each case were characterised by medium-cycle fatigue which had progressed into low-cycle fatigue during the latter period of growth, suggesting a higher loading regime during the latter part of the aircraft's history than previously. The fatigue characteristics on the fracture from the left side stud also showed variations. In this case, the initial medium-cycle fatigue regime changed dramatically into a very low cycle (high load) regime immediately prior to final fracture, the latter regime most probably being associated with juddering loads on the leg as the aircraft was sliding sideways following collapse of the right gear.

A general check for evidence of further fatigue cracks revealed that cracking had also initiated from a thread root in the lower outboard stud from the right side pintle attachment.

Stud condition

The threads appeared to have been die-cut, not rolled. Vickers hardness tests using a load of 10 kg gave values in the range 309 to 336 for the fatigue-fractured studs. Hardness checks on one lower attachment stud from each side revealed somewhat lower values, in the range 260 to 299. Neither the original specification of the stud material nor the correct method of cutting the thread has been positively established at the time of writing. It has not been possible to establish when the studs were installed, or their source.