

Lockheed Electra L188C, EI-CET

AAIB Bulletin No: 1/97 Ref: EW/C96/10/12 Category: 1.1

Aircraft Type and Registration:	Lockheed Electra L188C, EI-CET
No & Type of Engines:	4 Allison 501-D13 Turboprop engines
Year of Manufacture:	1961
Date & Time (UTC):	4 October 1996 at 0500 hrs
Location:	Coventry Airport
Type of Flight:	Cargo
Persons on Board:	Crew - 3 - Passengers - 1
Injuries:	Crew -None - Passengers - None
Nature of Damage:	Fracture of wheel rim from mainwheel, separation of tyre
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	47 years
Commander's Flying Experience:	8,200 hours (of which 780 were on type) Last 90 days - 117 hours Last 28 days - 40 hours
Information Source:	AAIB Field Investigation

The aircraft is understood to have shed the No 2 tyre whilst backtracking Runway 23 prior to take off at Coventry. There were no indications of abnormality at the time or during the subsequent take-off run, although the First Officer saw a tyre on the runway as the aircraft rotated. Air Traffic Control were able to confirm that the tyre was L188 equipment. The flight continued to Belfast Aldergrove where a flypast was carried out to enable a visual inspection to be made. It was confirmed that the No 2 tyre was missing. A normal approach and landing then took place at Belfast with the emergency services in attendance. Inspection after landing revealed that the complete inboard rim of the No 2 mainwheel was missing, its loss having allowed the tyre to leave the wheel. The rim was found on the runway at Coventry.

A metallurgical examination of the failed wheel half revealed that the hardness and conductivity remained in the correct range for the specified forged aluminium alloy (2014 T6). Examination of the fracture faces showed two relatively large areas of fatigue together with one smaller area, all being typical of medium cycle, medium stress tension fatigue. All three areas of fatigue originated at

the the inner cylindrical face of the wheel half, the two larger areas exhibiting multiple origins (See Photograph). This face is loaded in compression when the relevant area of the wheel is at the bottom and the wheel is supporting the aircraft weight. It is understood, however, that the loading becomes tensile as the relevant area rotates towards the top of its travel, thus producing a once per revolution fatigue cycle, in addition to any tensile loads arising in this area from stress distribution in the wheel created by landing loads. More complex loads are presumed to occur during any rapid turning manoeuvres on the ground.

One of the two larger fatigue areas was observed to have propagated almost through the section before overload failure had caused separation of the rim. The multiple initiations in the larger areas of fatigue did not appear to be associated with significant surface damage or corrosion.

Examination of the two fracture faces under ultra-violet light revealed evidence of long standing fluorescent dye penetrant on the faces of the two larger fatigued regions. Penetrant was visible throughout the depth of the smaller of the two major fatigue areas and extended to approximately 60% of the depth of the largest area.

The fluorescent dye penetrant inspection method is used to inspect the general surface condition of this wheel type when it is overhauled by the UK agents for the wheel manufacturer, the last organisation to carry out such an overhaul. An eddy-current inspection of the rim bead area is normally carried out before the fluorescent dye penetrant is applied, since this area is assumed to be the region most prone to cracking. The origins of all the fatigue areas identified were all in the part of the wheel which is not subjected to the eddy-current testing at overhaul. At the time of the incident the operator was carrying out only visual examination of the wheels at the time of tyre changes. The total number of flight cycles of the wheel from new are not recorded.

The remaining UK operators of the aircraft type became rapidly aware of the general nature of the problem and instituted appropriate inspections on their aircraft. Soon after these inspections began, two wheels from other L188 aircraft were identified as cracked. Examination of these by the wheel manufacturer's UK agents and AAIB revealed that the cracks were in the same general areas as the fatigue damage on the failed wheel of EI-CET.

The failed wheel half from EI-CET has been returned to the manufacturer for more detailed analysis.