

# Fokker 100, G-UKFN

AAIB Bulletin No: 6/2000

Ref: EW/C98/10/3

Category: 1.1

## INCIDENT

<b>Aircraft Type and Registration:</b>	Fokker 100, G-UKFN
<b>No &amp; Type of Engines:</b>	2 Rolls-Royce Tay 620-15 turbofan engines
<b>Year of Manufacture:</b>	1989
<b>Date &amp; Time (UTC):</b>	24 October 1998 at 1537 hrs
<b>Location:</b>	Southampton Airport
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew 5 - Passengers - 96
<b>Injuries:</b>	Crew None - Passengers - None
<b>Nature of Damage:</b>	No significant damage
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	46 years
<b>Commander's Flying Experience:</b>	6,523 hours (of which 1,516 were on type) Last 90 days - 128 hours  Last 28 days - 33 hours

**Information Source:** AAIB Field Investigation

## History of flight

The aircraft was scheduled to leave Stansted Airport at 0750 hrs for the first sector to Jersey Airport, however, the weather at the destination was unsuitable and the flight was delayed. The crew that eventually operated the service came on duty at 1035 hrs to relieve the original crew. The flight departed at 1319 hrs and arrived at Jersey about 1 hour later; it departed for Southampton at 1505 hrs.

Solent Radar positioned the aircraft downwind left for an ILS approach to Runway 20 at Southampton. The commander was the handling pilot and the autopilot and autothrottle were engaged. At 2,000 feet amsl, the flight conditions were relatively smooth and visual contact with the ground was intermittent. Abeam the airfield the selected airspeed was reduced to 220 kt. On the base leg, it was further reduced to 180 kt when the first stage of flap was lowered. This was followed by a further reduction to 160 kt when the landing gear was extended as the localiser was intercepted.

The second stage of flap was lowered when the glideslope was intercepted at 1,800 feet amsl, and the speed was selected to 140 kt. The runway was visual from about 1,200 feet amsl and the windscreen wipers were selected on because the crew assessed that they were in moderate rain. At about 800 feet amsl, land flap was lowered and the speed was selected to 136 kt; the minimum allowable speed (V<sub>ma</sub>) + 10 kt.

The commander recalled that, at about 500 feet amsl, he noticed the V<sub>ma</sub> information disappear from the speed tape on the Primary Flight Display (PFD). He saw the indicated airspeed decay rapidly to about 120 kt,

with the magenta trendvector down to about 115 kt. There was also a SPD LIM caption on the primary flying display (PFD) but neither pilot recalled hearing the audio warning chime.

With the autothrottle still engaged, the commander moved both power levers fully forward and disconnected the autopilot. At the same time he told the first officer to select the airspeed to 150 kt. The aircraft accelerated rapidly and he subsequently called for 136 kt to be reselected. Although the aircraft now appeared to be slightly high on the glideslope, the commander recalled seeing 3 whites and 2 reds on the PAPIs, and he decided to land.

The touchdown was, the commander estimated, between 150 and 300 metres beyond the ideal touchdown marker and was lighter than he would have liked on a wet runway. The spoilers deployed normally, reverse idle was selected and the autobrake, which was set to medium, initially appeared to provide sufficient retardation. It soon became apparent that more retardation was required and so the commander over-rode the autobrake and applied full pressure to his footbrakes. This did not appear to significantly increase retardation and so, at his request, the first officer also stood on the pedals again with little or no effect. The aircraft was rapidly approaching the runway end and the first officer suggested emergency reverse, which the commander selected. The aircraft left the runway and came to rest between the runway end and the arrester bed.

The air traffic controller estimated that the aircraft had touched down about 300 metres past the ideal touchdown marker, a distance that was subsequently confirmed by several other witnesses. He was concerned enough to activate the crash alarm as the aircraft passed taxiway Bravo. He declared a Full Emergency, which he upgraded to Aircraft Accident when he saw that the aircraft had left the paved surface at the end of the runway.

There was little damage to the aircraft and the passengers were evacuated in short time using the normal exits.

### **Aircraft and component examination**

The aircraft was examined by the operator after its recovery from the overrun area. The wheels and brakes were replaced and, after a series of preliminary checks, the aircraft was ferried empty to its maintenance base at Norwich. A more comprehensive programme of systems checks was then carried out. These included operational checks of the flap and Attitude/Heading Reference Systems, visual inspection of the left and right angle of attack (AOA) vanes for damage and freedom of movement and operational checks of those vanes. An operational check of the auto throttle system was also carried out. No faults were found in any of the above. The Flight Mode Panel (FMP) was removed from the aircraft and replaced. The aircraft was returned to service and performed satisfactorily thereafter.

The tyres and brakes, removed at Southampton, were examined. All tyres were within acceptable wear limits and showed no evidence of aquaplaning or wheel locking. The brakes removed from the aircraft were also within normal operating wear limits when pressurised in the workshop; no evidence of hydraulic leakage was noted and the rotors were free to turn after pressure release.

The removed FMP was subjected to preliminary testing by the aircraft manufacturer. A number of minor display and selection deficiencies were noted, but when functionally tested by the component manufacturer at their UK base, in the presence of an AAIB representative, no significant operating problems were found. The latter tests were carried out using Automatic Test Equipment with the mode panel mounted on a vibrating table to ensure that, as far as possible, any intermittent problems were identified. No evidence of any relevant defect could be found in the unit.

### **Meteorology**

An aftercast obtained from the Meteorological office indicated that, at 1500 hrs there was a cold front approaching the Southampton area from the west giving continuous rain which was moderate at times. No rainfall rate information was available however the following amounts were recorded over the period shown:

1100 to 1220 hrs	6.8 mm
1200 to 1300 hrs	3.6 mm
1300 to 1400 hrs	1.8 mm
1400 to 1500 hrs	2.6 mm
1500 to 1600 hrs	0.4 mm

Southampton info 'Echo' was current:

Runway 20 surface	Wet
Wind	230/11kt
Visibility	6,000metres
Weather	Rain
Cloud	FEW1,200 feet SCT2,000 feet

Temp/Dew point +13°/+13°C

QNH 987mb

The post incident observation, made at 1550 hrs, was:

Runway surface Wet

Wind 270°/14kt

Varying 210°to 320°

Visibility 6,000metres

Weather Rain

Cloud FEW700 feet

SCT900 feet

Temp/Dew point 12°/12°C

QNH 987mb

The upper wind structure around Southampton was complicated by the passage of a trough across the area at the time of the incident. There was medium level instability just north of the airfield and reported heavy rain shortly before the aircraft touched down would also indicate embedded instability on the trough.

The following estimate of the wind profile was based on archived data:

Surface 270°/15 kt with gust to 30 to 40 kt

1,000 feet 240°/40 kt

1,600 feet 260°/50 kt

2,000 feet 260°/50 kt

Note: Southampton may enjoy a sheltered position but surface wind gusts of 30 to 40 kt were reported at neighbouring locations.

When the aircraft made its final approach, the surface wind had veered, or was in the process of veering, from 240° to 270° and there was a 25 kt shear between 1,000 feet and the surface.

The commander recalled that, when ATC gave a surface wind check of 270/12 kt, the FMS wind at about 1,000 feet amsl was 240/40 kt.

The previous arrival was an HS125 aircraft that had landed at 1524 hrs. The commander reported that, although there was some turbulence during the approach, he had experienced no significant wind shear. The aircraft's anti-skid system had functioned during the landing roll, however there was no retardation problem. He concurred with the assessment of the runway condition as Wet. Once parked he had remained in the aircraft to complete the paperwork. He was about to leave the aircraft when there was what he described as a torrential downpour. He estimated that this had started about 30 seconds before FN touched down. The air traffic control assistant who had carried out the last airfield inspection before the incident was able to confirm that there had been a heavy rain shower shortly before 'FN' landed.

### **Aids to navigation**

The ILS DME on Runway 20 has a 3.1° glide slope, a localiser on 204°(M). A VOR and NDB are situated close to the runway threshold. All aids were serviceable. A complete routine Flight Inspection of the ILS was carried out on 3 November 1998 when it conformed to the required standards.

### **Airfield lighting**

The only airfield lighting relevant to this incident are the PAPIs, which consist of four lights, situated to the left of the runway. They are set for a 3.0° visual glide slope and are checked regularly for accuracy.

Normally, if the aircraft is on the visual glide slope the pilot will see the inner pair of lights red and the outer pair white. When the aircraft is on the ILS glide slope the aircraft is slightly above the visual glide slope and the innermost light is red and the remainder are white. This was confirmed by the Lighting Inspection Report associated with the ILS Flight Check on 3 November 1998.

### **Runway characteristics**

Runway 20 is 1,723 metres long and 37 metres wide. The touchdown threshold is displaced 45 metres and its elevation is 43 feet. The runway has a slight downslope of about 0.23%. The declared distance available beyond the threshold for landing is 1,605 metres. There is a 60 metre long paved area beyond the runway end and a 90 metre Runway End Safety Area. There is a soft ground arrester bed 19.5 metres beyond the paved area. The M27 motorway runs along the airport boundary fence that is just beyond the arrester bed.

The runway was constructed in the mid 1960s and has a brush finished concrete surface. Whilst it remains in good condition the surface characteristics, particularly the tendency to slow draining of standing water in heavy rain, have imposed significant operating penalties on modern jet aircraft. The Airport Authority carried out a thorough review of their options as regards the runway surface.

An immediate decision was taken to improve rainfall run-off by transverse grooving of the surface with grooves 3 mm wide, 3 mm deep and 6 mm apart. This work started soon after the incident and runway refurbishment was completed in April 1999.

### **Runway state assessment and reporting**

When water is present on the surface frequent inspections are made to determine the runway state. The normal frequency is at 30 minute intervals, however, this can be increased if rainfall intensity increases. The assessments are recorded in the ATC Watch Log. Runway state is reported in accordance with the table reproduced below which is found in MATS Part 1, Section 9, Chapter 2:

<b>Description</b>	<b>Runway Appearance</b>
Damp	When the surface shows a change of colour due to moisture.
Wet	When the surface is soaked, but no significant patches of standing water are visible.
Water patches	When significant patches of standing water are visible.
Flooded	When extensive standing water is visible.

Water patches will be reported when between 25% and 50% of the runway is covered with patches of water of any depth or 25% or less of the runway surface is covered by water patches exceeding 3 mm in depth. Depth measurements are taken about 3 metres each side of the runway centreline in each third of the total runway length. The runway is considered to be Flooded if more than 50% of the runway is covered by water patches of any depth.

Following review by SRG Working Group, a revised reporting scheme for wet runways was incorporated in the AIP amendment AIRAC 7/99 (effective date 15 July 1999), which was distributed in early June. The AIC addressing the Risks and Factors Associated with Operations on Runways affected by Snow, Slush or Water, incorporating the revised reporting scheme, was reissued on 3 June 1999 (AIC 61/1999 Pink 195).

The following runway assessments were recorded in the ATC Watch Log:

1255hrs      Water patches 80%, > 3 mm depth  
 1330hrs      Water patches < 25%, < 3 mm depth  
 1356hrs      Wet

1436hrs      Wet

1522hrs      Wet

A post incident runway inspection was carried out between 1540 and 1610 hrs. Depth of water measurements were taken every 20 to 30 metres and it was assessed that more than 25% of the runway was covered by water patches which were less than 3 mm deep.

### **Flight recorders**

The Cockpit Voice Recorder (CVR), a 30 minute recycling model A100, and the Flight Data Recorder (FDR), a Sundstrand UFDR, were replayed by the AAIB.

The aircraft was descending on the glidepath at around 700 feet amsl, with the autopilot engaged and the lift spoilers armed. The airspeed was around 148 kt CAS with variations of  $\pm 7$  kt in the turbulent conditions. With the autothrottle engaged, the power began to decrease to idle N1 (35%) on both engines. From the CVR, the crew at this stage commented that they had noticed the loss of the V<sub>min</sub> indication. Figure 1 shows a plot of height AAL, airspeed and groundspeed together with the derived headwind component and the autothrottle response. At about 600 feet agl the airspeed decreased to about 130 to 135 kt CAS following which the power, controlled by the autothrottle, began to increase again. The groundspeed showed a derived headwind which increased from 4 kt to 14 kt over 4 seconds. There was then a decrease in the derived headwind to 1 kt over the next two seconds. The airspeed continued to decrease, reaching a minimum of 119 kt CAS. The autothrottle clutch engaged discretely, recorded by the FDR then showed an intermittent indication. This was due to the crew overriding the power levers thereby declutching the autothrottle. The autopilot was disengaged 5 seconds later. The airspeed increased to about 140 kt IAS.

The aircraft continued the approach and touched down at an airspeed of 136 kt CAS, the lift spoilers were deployed and reverse idle was selected. The corrected initial deceleration level was  $-0.18g$ , which agreed with the medium autobrake deceleration target of  $-1.8 \text{ m/s}^2$ . Twelve seconds after touchdown there was an indication from the crew, on the CVR, that they had taken over with manual braking and there was a call off full reverse ten seconds later. From the FDR, at 102 kt CAS, there was an increase from reverse idle power 13 seconds after touchdown, to a maximum power level of 89% N1 20 seconds after touchdown. There was then an increase in the deceleration level to around  $0.4g$  and the aircraft came to rest 28 seconds after touchdown on a heading of  $187^\circ \text{M}$ . No braking parameters were recorded on the FDR.

### **Autothrottle behaviour**

The autothrottle control law generates a throttle command for both the speed error (the airspeed target selected on the FMP minus actual airspeed) and the alpha floor protection. The greater of the two commands is then used to adjust the throttles. The alpha floor protection uses average AOA for the minimum allowable

speed ( $V_{ma}$ ) calculation. If the difference between the two AOA vanes is more than  $2.6^\circ$  for more than 0.5 seconds the  $V_{ma}$  calculation becomes invalid and only the speed error throttle command is used. The loss of  $V_{ma}$  results in the loss of under speed protection and the  $V_{ma}$  related limit on speed selection no longer applies.

### **Flight simulation**

In order to understand the behaviour of the autothrottle during the approach below 700 feet the aircraft manufacturer performed simulations of the autothrottle control law. The initial assumption was that the crew had inadvertently misselected a target speed and the autothrottle had responded to this value when minimum speed protection was lost. Aircraft pitch attitude, CAS and longitudinal acceleration were used from the FDR and the output of the simulation was the autothrottle command. The initial simulations looked at three scenarios, from an initial target speed of 155 kt CAS, the target speed was changed to 135, 125 and 115 kt CAS. The scenario that most closely followed the autothrottle response of the FDR was when a speed target of 115 kt was selected.

The wind profile and the sudden torrential downpour indicated that there was a significant storm cell probably centred over or slightly to the west of the airfield. Under these conditions it is possible that a windshear profile existed which was more complex than a simple reduction of headwind component. During the incident flight the derived headwind component was noted to increase by 10 kt over 4 seconds followed by a 13 kt decrease over the next 2 seconds. Although there is a limit to the confidence which can be placed on the derivation of a wind component in such circumstances, the Type Certificate Holder was asked to consider the possibility that the aircraft had initially encountered a sudden increase of headwind component which would have caused a transient increase of CAS, followed by a decrease of CAS caused by a reduction of headwind components.

A fixed-base engineering simulator was then used to investigate various windshear profiles. To provide a datum for comparison, a target speed misselection of 116 kt was used, and an airspeed reduction to 119 kt again was demonstrated. For the windshear profile an initial wind of  $240^\circ/30$  kt, increasing to  $240^\circ/40$  kt at 750 feet (co-incident with the AOA mismatch) and changing to  $270^\circ/30$  kt at 650 feet was used. The target speed selected was 136 kt. This simulation also showed an airspeed drop to 119 kt, or below. This scenario was also demonstrated without the AOA mismatch and the airspeed still reduced to 119 kt. These simulations demonstrated that a combination of windshears, firstly increasing the headwind component and then reducing it, could also produce the loss of airspeed seen in the incident.

The Type Certificate Holder then carried out a more detailed performance estimation using the FDR data and the ATS control laws, in order to model the speed selection profile. The required inputs are not recorded and therefore this necessitated their derivation from the FDR accelerations. These were corrected by comparison of the integrated accelerations and velocities with the recorded FMS



ground speed and Drift Angle. These latter parameters, however, have substantial filtering applied. Using the corrected acceleration and velocity components the response of the ATS was simulated, using the full set of control laws, for a number of selected target speeds. This more detailed analysis showed that the selected target speed profile could be established, but only within a tolerance band due to the limitations of the recorded information. However it did show that the selected speed was 160 kt until the selection of land flap. The crew stated that the 140 kt selection was made with the second stage of flap. The analysis showed a further anomaly in the prediction of the selected speed, which reduced to 140 kt for a period of 2 seconds before returning to 160 kt. This brief reduction could represent an intentional selection which was immediately undone, or an inadvertent speed hold mode entry which could result from pushing in the speed select knob while making a selection. It remains a possibility that the anomaly was caused by switching between speed select and speed hold mode and the Type Certificate Holder continues to look at the possibility of a system-generated step.

Following the land flap selection the analysis further showed that the target speed became 140 kt, and then reduced further to 116 kt. The timing of this reduction could not be accurately determined. The target speed reduction occurred at least one second, but possibly four seconds before the autopilot 2 became engaged, and at least 10 seconds before LAND2 was annunciated.

## **Aircraft landing performance**

A double integration was performed from the FDR recording of longitudinal acceleration in order to calculate the stopping distance, and therefore the touchdown point. The total ground run was calculated as 1,085 metres from touchdown to the aircraft coming to a complete stop. The touchdown point was therefore estimated to be 600 metres from the threshold. This figure is consistent with the eye witness accounts of the touchdown being about 300 metres past the ideal touchdown marker.

Assuming medium autobraking with constant deceleration of 0.18g and a brake application speed of 132 kt CAS, the aircraft manufacturer calculated that the aircraft would have required 1,280 m to come to a full stop.

The aircraft manufacturer also provided landing ground roll distances assuming the following conditions:

Flap 42°; lift dump deployed; aircraft wt: 37,500 kg; pressure altitude 700 feet;

OAT 14°C; no wind; no slope.

No time delays were used for lift dump deployment, brake application and reverse selection. The brake application speed was 132 kt CAS. Reverse was assumed to reduce to idle reverse at 60 kt CAS. The wet runway coefficient was 0.5 x the dry runway.

It was not possible to define the precise condition of the runway during the landing roll but it is evident that it was somewhere between 'Wet' and 'Flooded'. The aircraft manufacturer calculated the following stopping distances for full braking and reverse idle:

Wet runway	854 metres
Flooded runway	1,764 metres

If normal maximum reverse thrust had been selected immediately after touchdown the distances would have been:

Wet runway	827 metres
Flooded runway	1,667 metres

### **Summary**

The initial set of simulations made the assumption that the crew had inadvertently selected a target speed below that required and that the autothrottle had responded to this value when minimum speed protection was lost. The scenario that most closely followed the autothrottle response of recorded on the FDR was when a target speed of 115 kt was selected. It would have been surprising if such a gross mis-selection had been made by the crew at a stage when they were visual with the runway and all was apparently normal. When interviewed after the incident, both flight crew members reported that the target speed had been selected to 136 kt when the flap had been selected to the land position, however, there was no evidence from any other source either to support or refute this.

The second set of simulations suggested that there was a combination of windshears that could result in the loss of airspeed seen in the incident. In this scenario the loss of minimum speed protection would not have been a factor as the autothrottle reference would have been the selected speed.

The third set of simulations led to a predicted sequence of target speed selection within the limitations of the data available. It was not possible to reconcile this sequence with the selections reported by the crew. Neither was it possible to exclude an anomalous target speed generated by the system, or errors produced by intermittent switching between speed select and speed hold modes. The Type Certificate Holder is continuing to look at the possibility of a system generated step.

The loss of minimum speed protection appears to have been the first thing the commander noticed and it was this that drew his attention to the reducing airspeed. The atmosphere on the flight deck had been relaxed up to this point, however, the distraction and apparent loss of confidence in the autoflight system led him to disconnect the autopilot and attempt to override the autothrottle. These events led to a destabilised approach

and, although the aircraft had recovered the normal approach path prior to the landing flare, the speed was still high and the aircraft eventually touched down at  $V_{ma} + 10$  kt.

The evidence suggests that the runway assessment prior the incident was correct but a heavy rain shower, shortly before the aircraft touched down, had caused a rapid deterioration in its condition to somewhere between Wet and Flooded.

The aircraft had landed lightly and fast, about 300 metres beyond the ideal touchdown marker, leaving some 1,000 metres of landing run available. The landing ground roll distances calculated by the Type Certificate Holder indicate that, had full braking been applied immediately, the aircraft would have stopped in 854 metres on a Wet runway. On a runway between Wet and Flooded, with the retardation technique used on this landing, an overrun was inevitable.

The commander had experienced no retardation problem during the landing in similar conditions at Jersey and had accepted the Southampton runway condition as Wet. He did not appear to have any doubts about stopping the aircraft in the runway remaining after touchdown and consequently showed no sense of urgency in applying maximum retardation. Nor had he considered carrying out a missed approach, probably for similar reasons, although this would have been an available option.

Despite the fact that it may have had limited effect, once the decision to continue the landing had been made, it would have been prudent to have overridden the auto-brake system, applied full braking and selected maximum reverse thrust immediately after touchdown.