

Pierre Robin DR400/180, G-DELS, 22 July 1996

AAIB Bulletin No: 12/1996

Ref: EW/C96/7/10 Category: 1.3

Aircraft Type and Registration:	Pierre Robin DR400/180, G-DELS
No & Type of Engines:	1 Lycoming O-360-A3A piston engine
Year of Manufacture:	1990
Date & Time (UTC):	22 July 1996 at 1605 hrs
Location:	Tockington Park Farm near Almondsbury, Bristol
Type of Flight:	Private
Persons on Board:	Crew - One - Passengers - Nil
Injuries:	Crew - One (Fatal) - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	67 years
Commander's Flying Experience:	750 hours (of which 577 were on type) Last 90 days - 11 hours Last 28 days - Not known
Information Source:	AAIB Field Investigation

History of the Flight

The aircraft involved in this accident was wholly owned by the pilot who had used it to fly extensively throughout the UK and mainland Europe since purchasing it in 1990. On the afternoon of the accident he had taken off from his home base at Wadebridge, Cornwall, to fly a family friend to Kemble. The weather for the route flown was fine with a strong south-westerly wind of 170° to 200° at 10 to 15 kt, with gusts up to 25 kt on the surface and a temperature of 29°C. At 2000 feet the wind was 200°/10kt with a temperature of 20°C. Due to the strong diurnal differential heating a 'heat low' had developed over England by 1700 hrs and there were reports from pilots of turbulence at low altitudes. During the flight north, the pilot had advised his passenger to fasten her seat harness more tightly because of the turbulence.

On arrival at Kemble at approximately 1530 hrs, the wind was reported by Royal Air Force Lyneham to be 190°/18 kt with gusts of about 7 kt. Kemble ATC tower was unmanned and the pilot elected to land on Runway 27. The passenger later stated that, due to the strong crosswind and turbulence, the pilot experienced considerable difficulty in making an approach and had to work hard to maintain wings level during the touchdown and subsequent landing roll. Witnesses reported hearing a prolonged squeal of the tyres, and a brief but large increase in engine power, suggesting that the pilot was having difficulty in controlling the aircraft at this stage, and may have inadvertently landed with the toe brakes applied.

When the aircraft arrived at the parking area the pilot, after greeting waiting relatives of his passenger, made a careful inspection of the aircraft with particular attention to the left wing. His passenger recalled him giving the wing a "tug". He made no comments about the condition of the aircraft during this inspection.

At approximately 1550 hrs, the aircraft took-off to return to Wadebridge. At 1600 hrs, the pilot contacted Filton Approach Control and advised them that he was routed from Kemble to Wadebridge in Cornwall and would like to overfly the airfield and then proceed down the Bristol Channel at 2000 feet under Flight Information Service (FIS). Filton acknowledged this call and allocated the aircraft a secondary radar transponder code.

At 1603 hrs, Filton Approach called the aircraft and advised the pilot that the QNH was 1013 mb and that he was identified on radar. The tone of the pilot's voice when he answered this call was calm and business-like, implying that the flight was proceeding normally. It is of note that when making both these radio calls to Filton, the pilot was very precise in his transmissions, prefacing all calls with the correct radio call sign. However, at 1604 hrs the pilot spoke to Filton again and asked for their surface wind; this transmission was made without a call sign and it was possible to detect a note of anxiety in the pilot's voice. Filton replied that the wind "is one nine zero, one five knots, it's been up to two one zero, one eight knots".

As soon as Filton had ended this transmission, the pilot made the following radio call: "I'm having trouble with my controls, I think I better declare a PAN and try and get into you. Having a job to turn left so if that's alright with you I'll make an approach for....., what's your runway, two one?...." at this point the pilot stopped talking, but the transmission switch was left on for seven seconds before he made the single statement "Oh God" and the transmission ended.

At about this time, a witness who lived in the vicinity reported that whilst working in his garden he noticed a light aircraft flying overhead at about 2000 feet. Shortly afterwards he heard a sound which he compared to that of a stout piece of timber breaking, followed by the engine throttling back and then power being reapplied. Other witnesses in the area reported hearing a 'dull crack' similar to the noise made by a leather hammer. A number of witnesses saw the aircraft descending in a spiral similar to that of a 'falling sycamore leaf' and observed that one wing was damaged, if not missing altogether. The descent was accompanied by a small cloud of debris. Emergency services were called to the scene and found the wreckage of the aircraft in a field, with the body of the pilot some ten metres away.

The wreckage trail

Debris from the aircraft was distributed along an elliptically-shaped wreckage trail some 900 metres in length, orientated approximately north-south, starting with a few isolated fragments of left

wingrib to the north and terminating at the main impact site at the southern end of the trail. Figure 1 is a sketch plan of the wreckage trail, showing key items of wreckage and the main impact site.

Main wreckage

The wreckage at the main impact site comprised the whole of the aircraft, except for the left wing and some fragments of cockpit perspex; otherwise, all extremities were present and the aircraft appeared intact at the time of ground impact. The pattern of impact damage, and the 'throw' of wreckage from the point of impact, was consistent with a high speed descent into the ground in an approximately 70° nose down pitch attitude, whilst in a wide spiralling motion to the right.

The body of the pilot lay separate from the main wreckage, approximately 10 metres to the west. The pattern of damage to the seats and instrument panel suggested that he was not in the cockpit when the aircraft struck the ground, and subsequent post mortem examination revealed a pattern of injury consistent with a free-fall impact. The pilot's lap strap harness was unbuckled prior to impact but the (keyhole-type) attachment of the shoulder harness to the lap strap buckle was still engaged. The canopy was unlatched, but it was not possible to establish how far it had been opened prior to impact.

Airborne separation debris

The left wing, comprising the outer wing panel and aileron with almost the whole of the top and bottom fabric skins still attached, but with the structure extensively disrupted and reduced in part to fragments of ribs and spar, had separated from the aircraft in flight and was found in the central part of the debris trail, toward the eastern edge. The remaining fragments of the disrupted left wing spar and rib structure, together with the aluminium cover-strip fairing from the outer end of the left wing tank, pieces of pitot tubing, and sections of trailing edge flap were scattered across the central region of the wreckage trail. Several pieces of canopy perspex were lying at the northwestern end of this debris region.

Maps, headphones, and other items of cockpit equipment were found scattered over the fields on the more westerly side of the trail, towards its southern end. These items had evidently been released from the aircraft during the latter part of its descent.

The left wing fuel tank had been released from the aircraft during the initial wing separation, but due to its concentrated mass had travelled further than the wing debris generally, coming to rest at the far end of the trail, slightly to the east of the main wreckage.

Runway investigation at Kemble Aerodrome

In light of the evident difficulty the pilot had experienced during the landing at Kemble, and the possibility that a heavy landing may have damaged and weakened the wing structure, the runway at Kemble was subsequently examined carefully in an effort to establish the nature of the landing.

A solid black tyre mark was found at a point approximately 180 metres from the threshold of Runway 27, beginning near the centreline and diverging to the left at a shallow angle. A second, less clearly defined, black tyre mark was found to the right of the first, but running parallel with it; both extended forward along the runway in a sensibly straight line for a distance of approximately 40 metres, after which they disappeared. The spacing between the marks corresponded precisely with the main wheel track of a Robin DR400, and their characteristics were consistent with *locked*

wheel tyre marks produced by an aircraft touching down with the brakes applied. The width of the individual marks increased progressively from the initial contact points, and there was no evidence to suggest that the touchdown had been at a high sink rate. Overall, the character of the marks implied a gentle touchdown at relatively high speed, slightly left wing low, close to the centreline but tracking slightly to the left; the aircraft then becoming airborne again. Having regard to the witness evidence of a sustained 'shriek' from the tyres of the landing aircraft, the transient increase in engine power, and the correspondence of the tyre mark spacing with the main wheel track of a Robin DR400, it was concluded that the marks on the runway were produced by G-DELS.

A close examination of the paved runway forward of the point where the aircraft had apparently become airborne, after its initial touchdown, failed to reveal any further tyre marks which could be attributed with confidence to G-DELS. However, much of this part of the runway comprised the taxiway intersection and was covered with numerous tyre marks from a recent motor race meeting which had been held at the airfield.

The grassed area adjoining the left edge of the runway, just beyond the taxiway intersection, was also examined carefully and a set of rolling wheel tyre tracks were found in the grass which had evidently been produced by an aircraft with a nose wheel undercarriage. The distance between the main wheel tracks also matched the track of a Robin DR400, and the position where the tracks began was consistent with the projected path of the aircraft following touchdown, as indicated by the angle of the initial tyre marks on the runway. There was little doubt that the marks had been produced by G-DELS.

The tracks in the grass initially comprised just the left and right main wheel tracks. These ran in an approximately straight line for about 15 metres, after which the left wheel track disappeared and the right became significantly heavier, consistent with a sudden transfer of weight from the left to the right main wheel at that stage. Some 5 metres further on, the left main wheel track reappeared and the right wheel track lightened and reverted back to its original character. A nose wheel track also became visible at this stage, very close to the left main wheel track, consistent with the aircraft having been yawed grossly to the left at that point, directional control evidently having been lost at that stage. Thereafter, the tracks followed a tightly curving arc to the left through approximately 180° of heading, crossing over the taxiway in the process, with the nose wheel continuing to track close to the left main wheel throughout. Some 25 metres after having crossed over the taxiway and onto the grass on the far side, the tracks straightened for a period, suggesting that directional control had been recovered at that point, before assuming a more gentle curve to the left and regaining the main runway at the southern corner of the taxiway intersection, opposite the point where the aircraft had originally departed the paved surface. The sketch at Figure 2 shows the approximate path followed by the aircraft during its excursion off the runway, together with the yaw angle at key stages implied by the proximity of the nose wheel to the left main wheel track.

The airfield had been harvested for hay prior to the accident, and large cylindrical bales of hay were distributed across many of the grassed areas adjoining the runways. These bales had subsequently been cleared from parts of the airfield, including the grassed area where the tyre tracks were found. However, the positions where the bales had originally been sited were indicated by associated impressions left in the grass, one of which was identified some 2.5 metres outboard of the left main wheel track, adjacent to the point where the aircraft had suddenly yawed to the left. Further inquiries, and comparison with photographs taken on the day after the accident, confirmed that a hay bale had been present at this position when the aircraft had landed.

Measurements were taken of a number of typical hay bales, and compared with the dimensions of the aircraft and its landing gear tracks. This showed that the left outer wing must have impacted the bale at the position shown in Figure 3. Such an impact would have yawed the aircraft violently to the left whilst at the same time causing the left wing to 'ride up' over the bale, lifting the left mainwheel clear of the ground and throwing additional weight onto the right mainwheel, and causing the violent yaw before the aircraft dropped back onto all three wheels on the far side of the bale, consistent with the evidence of the tyre tracks. An attempt was made to identify the bale in question from amongst those stacked on the far side of the airfield. One bale was found with damage consistent with the scenario described, but it was not possible to make a positive identification.

It was later confirmed by the passenger that the aircraft had indeed run over the grass during the landing at Kemble. She had also been aware of roll-type bales of hay in the vicinity, but was not conscious of the aircraft having struck any of them.

Examination of wreckage

The Robin DR 400 has a wood and fabric wing built around a thin-walled wooden box spar, comprising plywood side and top panels bonded to corner elements of rectangular section timber, a form of construction which confers excellent bending and torsional rigidity when intact, but very little stiffness in the event of loss of integrity at the joints of the box. The outboard part of the spar is cranked upward to accommodate the dihedral of the outer wing panels, this being accomplished structurally by scarfed joints in the various spar elements. Separate box structures attached to the aft sides of the main spar at the inboard end of each wing carry the main landing gears, these being intended to break away from the main spar box under excessive loading, without compromising the integrity of the spar. The remaining structure is built around the main spar and comprises sheet ply nose ribs forward of the spar and conventional latticework ribs aft, the latter supporting a lightweight trailing edge spar on which the ailerons and flaps are mounted. The nose ribs are skinned with thin plywood extending back to the spar on the upper surface, and approximately 30% to the spar on the lower surface. The depth of the main spar is slightly less than the maximum thickness of the wing, and the rib caps extend around the top and bottom of the (rectangular section) spar box to provide the required curvature for the wing section.

The wreckage from the separated left wing was laid out and partially reconstructed at the AAIB, Farnborough. It was apparent that the wing had been in excellent condition overall and there was no evidence of deterioration due to moisture ingress, fungal growth, or bond deterioration. The quality of the materials used and the standard of construction was extremely high, and none of the fractures had resulted from glue failure or any apparent material weakness or defect.

It was apparent that the outer panels of the left spar box had split away from their corner members, destroying the integrity of the *box structure* and substantially reducing both the bending and torsional stiffness of the wing, and would have resulted in bending and torsional loads during flight being transferred to the individual corner elements of the spar box as bending loads. This had resulted in overload failure of these elements near the region of maximum bending moment at the root of the wing, followed by consequential further breakup of the wing structure and separation of the left wing. The progressive loss of torsional stiffness as damage propagated through the spar would have tended to cause adverse twisting of the wing in response to aileron deflections, and a consequent reduction in aileron effectiveness. This was considered to have been the cause of the pilot's reported difficulty in turning the aircraft.

The left wing lower skin, just outboard of the dihedral break, exhibited a uniform 'scuffing' of the painted surface, comprising minute chordwise scratches extending from the leading edge back over the plywood skinned nosing. The nose ribs in this region were heavily crushed and fragmented, consistent with a *sandbag* type impact against the lower part of the leading edge. This region of damage coincided with the extent of damage expected from impact with the straw bale, and the scuffing was also consistent with such an impact. There were indications that the main spar had also suffered localised disruption immediately inboard of this region, almost certainly as part of this impact process; however, it was not possible to determine exactly what damage was due to the impact with the hay bale and which was due to the subsequent airborne breakup.

In summary, it was apparent that the breakup and airborne separation of the left wing had occurred as a result of spar damage sustained during the impact with the hay bale whilst landing at Kemble, this damage propagating further into the spar structure during the initial stages of the return flight and culminating in a spar failure at the inboard end of the wing, and wing separation in flight.

Implications of the wing impact

The witness evidence of the pilot inspecting the outer left wing very carefully, and *tugging* the wing, was consistent with an attempt by the pilot to assess the extent of damage following the impact with the hay bale. However, it is likely that external visible signs of damage would most probably have been limited to the light scuffing of the lower wing skin at the point of contact with the bale.

A metal monocoque wing structure with deformed ribs or spars will usually exhibit associated deformations of the external skins, providing a clear indication of the damage within. The wooden structure of the DR400 wing, however, whilst being both strong and damage tolerant, is less likely to show external signs of critical damage within. In this case, due to the compliance inherent in the plywood leading edge skinning and the in-plane stiffness of the nose ribs, the impact loads would have been transferred directly into the spar behind, until the nose ribs became crushed. After the event, the nose skins would have sprung back leaving little, if any, visible evidence of the crushed ribs and possible spar damage within. Because the spar box sits *inside* the wing profile, damage in the form of partial dislocation of the spar panels from the corner elements of the spar box would, in all probability, not have been apparent. It is therefore entirely conceivable that the pilot may have been misled as to the extent of the damage sustained, finding only light scuff marks under the leading edge and believing that it was safe for him to make the return journey before having the wing professionally assessed.