

BAe 146, G-ZAPK, 18 November 1996

AAIB Bulletin No: 8/97 Ref: EW/C96/11/7 Category: 1.1

INCIDENT

Aircraft Type and Registration:	BAe 146, G-ZAPK
No & Type of Engines:	4 ALF502 turbofan engines
Year of Manufacture:	1989
Date & Time (UTC):	18 November 1996 at 1347 hrs
Location:	London City Airport
Type of Flight:	Public Transport
Persons on Board:	Crew - 5 - Passengers - 47
Injuries:	Crew - None - Passengers - None
Nature of Damage:	None
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	61 years
Commander's Flying Experience:	13,545 hours (of which 4,700 were on type) Last 90 days - 190 hours Last 28 days - 39 hours
Information Source:	AAIB Field Investigation

History of flight

Flight recorder data was not available because it had been overwritten on subsequent flights. The history of this flight has therefore been derived from crew statements, witness accounts and recorded radar data.

The aircraft was being operated on a sector from Dublin to London City; the commander was the handling pilot. Just after 1344 hrs, the aircraft began a coupled ILS approach, from 3,000 feet, to Runway 28; the weather was CAVOK, the surface wind was 325°/10kt and the runway was dry.

The configuration for the approach was:

Landing gear down

Flap 33°

Airbrake open

The crew could not recall what VREF they had used, however, as the landing weight was about 31,260 kg the correct value would have been 109 kt. The command speed pointer (bug) on the ASI was set to VREF+5 kt, the recommended approach speed. The first officer recalled that the speed during the initial part of the approach was "bug+10kt" (VREF+15 kt). He drew the commander's attention to this and received an acknowledgement. He noted that, as the aircraft crossed the threshold, the speed was about "bug+7kt" (VREF+12 kt).

It was not clear where the aircraft touched down, but when it did it appeared to both pilots to be normal and the commander selected the engines to ground idle. He then selected the lift spoilers and applied the brakes but there was little retardation and he felt that the aircraft was "skating on glass". He said that he called "no brakes" and shortly afterwards the first officer called "no spoilers". The first officer noticed that there were no spoiler captions on the annunciator panel and the 'Lift Spoiler' warning on the glareshield was not illuminated.

When the commander recycled the spoiler lever the lift spoilers deployed. Almost immediately, he felt normal braking and the aircraft started to decelerate rapidly; the first officer was by now also applying pressure to the brake pedals.

The ATC controller had not noticed the initial part of the landing but he reported that the aircraft finally touched down between 1/3 and 1/2 way along the runway, nose wheel first. There was a considerable amount of "smoke" evident from the area where the main wheel touched. The controller, anticipating an overrun, pressed the crash alarm.

At about 1347 hrs, the aircraft came to a halt at the end of the starter extension to Runway 10. The controller told the AFS that he suspected a burst tyre and asked them to investigate and report. Shortly afterwards the crew asked the controller if there was any sign of fire. At the request of the AFS, the commander shutdown the engines and awaited an inspection.

At 1400 hrs, in the absence of any evidence of fire or tyre damage, the decision was made to restart the engines and to taxi to the stand. The commander checked the spoilers and they deployed normally consequently, after consulting the ground engineer, he decided that it was probably a "one off" problem and the aircraft and crew continued with their schedule.

Aircraft operator

The aircraft and crew were on lease to an Irish based company which operates a regular schedule between Dublin and London City Airport. The crew had not flown regularly into London City and were relatively inexperienced in this sphere of operation. However, they were properly trained and licensed to operate the flight; the training was carried out by another company which operates regularly into London City Airport.

London City Airport

The airport is situated in the docklands area of the city; it has a single runway which is designated 10/28. The landing distance available (LDA) in either direction is 1199 metres; the paved area beyond the western end of the runway is 75 metres long and is a starter extension for aircraft

departing from Runway 10; it is not part of the LDA. The limit of the touchdown zone on Runway 28 is marked by white lights set into the runway surface; these are 336 metres in from the threshold.

At the time of the incident, the airport had about 114 movements a day; the main aircraft types were BAe 146/RJ, De Havilland DHC8 and the Fokker 50. There were 11 main operators, although a total of 72 operators had been given approval to operate at London City Airport using a large range of aircraft types. Because of the unusual characteristics of the Airport and the steeper than normal approach path of 5.5° , the airport authority lays down several conditions with which an operator must comply before this approval is given.

BAe 146 normal approach procedure

The normal approach procedure for the BAe 146 aircraft is largely standard across the range of operators. Prior to localiser capture 18° flap is selected with a minimum speed of $V_{REF}+30$ kt. Once established on the localiser, 24° flap is selected and the speed reduced to $V_{REF}+20$ kt. At 1 1/2 dots below the glideslope, the landing gear is selected down, the flap is selected to 33° and the speed is reduced to $V_{REF}+5$ kt, which is bugged on the command speed pointer. At glideslope intercept, the airbrakes are selected out. The approach is flown in this configuration aiming to cross the threshold at V_{REF} . The landing flare is started and the power is reduced to flight idle; the flare should not be prolonged and, after the main wheel touchdown, the thrust levers are retarded to ground idle and then the wheel is lowered onto the runway. The lift spoilers are then selected by the Commander and braking commences. After touchdown the non handling pilot confirms "SPOILERS YELLOW/GREEN -BRAKE PRESSURE" or warns of a spoiler or brake failure. If it appears that the touchdown point will be beyond the touchdown zone limit a go-around must be initiated before the aircraft touches down.

Description of pertinent systems

Compression of both main oleos removes the flight idle (60% N2) baulk allowing the selection of Ground idle (50% N2) by the handling pilot.

The YELLOW (No 2 engine) hydraulic system powers the inboard lift spoilers and the roll spoilers. The GREEN (No 3 engine) hydraulic system powers the four outboard lift spoilers. The inboard spoilers deploy immediately they are selected provided either the nose oleo is compressed and either main oleo has been compressed in the previous 10 seconds or both main oleos are compressed. The outboard spoilers deploy 1.5 seconds after both main oleos are compressed. When the spoilers deploy green 'SPLR Y' and 'SPLRG' captions illuminate on the annunciator panel.

Should the spoilers not deploy there will be no 'SPLR Y' and 'SPLRG' captions on the annunciator panel. A 'Lift Spoiler' warning on the glareshield will illuminate subject to the following conditions:

1. If the spoilers are selected but do not deploy, the warning illuminates after 3 seconds and stays on until the spoilers do deploy or are deselected.
2. If any oleo is compressed and the spoilers are not selected, the warning illuminates after 6 seconds and stays on for 14 seconds or until cancelled.

Probable sequence of events

No technical defects were found at the time of the incident and none was reported subsequently which could be related to the event. In the absence of any evidence of a technical problem, and with no Flight Recorder data available, a probable sequence of events was derived from crew statements, witness accounts and the way in which the pertinent systems function.

With little or no headwind component it is difficult to lose excess speed once established on the 5.5° glideslope because the power setting is already very low (40 to 50% N1) and all the drag producing devices have been selected. If the approach, as in this case, starts at a higher than ideal airspeed, it is likely that a large part of this excess speed will be maintained throughout the approach. The first officer noted that the speed was about "bug+7 kt" at the threshold.

If the aircraft touched down firmly enough to compress the main oleos and withdraw the flight idle baulk but then became airborne again before the commander had transferred his right hand to the spoiler lever and moved it rearwards, the spoilers would not deploy. The 'Lift Spoiler' warning would normally have illuminated after 3 seconds, however, it is possible that the system was reset before the end of the period when the commander momentarily recycled the spoiler lever.

If the aircraft floated and the required combination of weight on wheels switches was not made, the spoilers would remain stowed and the wheel brakes would be only marginally effective, giving the commander the impression that the aircraft was "skating on glass"; this pilot impression has been identified in other accidents/incidents where lift spoilers have not deployed and the initial diagnosis is invariably a brake rather than a spoiler failure.

The commander's recycling of the lever was probably coincident with the aircraft having slowed sufficiently to settle onto the ground and make the conditions required for the spoilers to deploy. From this point the aircraft decelerated as would be expected with full braking applied.

Manufacturer's performance data

The aircraft manufacturer produced landing performance data for the BAe 146-200 at London City Airport under the following conditions:

Runway 28

Pressure altitude 144 feet (QNH - 1009 mb)

Temperature +6°C (ISA - 8.7°C)

Surface wind 320°/9 kt

Landing weight 31,261 kg

Runway surface Dry

The distance is based on the aircraft flying a 5.5° steep approach and crossing the runway threshold at 35 feet, at VREF. With all retardation devices serviceable the unfactored landing distance is 487 metres. If the lift spoilers fail but normal braking is still available, the unfactored landing distance becomes 679 metres.

The unfactored distance is measured during certification flying and uses flight test methods; it would not be expected that normal in-service landing techniques would routinely achieve this distance. A safety factor designed to compensate for the variables inherent in normal airline operation is applied to this distance to produce the Flight Manual standard landing performance. For dry runway performance this figure is 1.67; this includes an allowance for a threshold overspeed of up to 15 kt.

With all retardation devices serviceable the factored landing distance is 812 metres. If the same safety factor is applied in the case where the lift spoilers have failed but normal braking is still available the factored distance is 1,134 metres.

It should be noted that all the above figures apply to the conditions pertaining at the time of the incident when the aircraft was significantly below maximum landing weight (36,740 kg) and the runway was dry; a further factor of 1.15 would apply if the runway was wet.

Discussion of incident

If the aircraft crosses the threshold at 35 feet at $V_{REF}+15$ kt and touches down normally, it should stop inside the LDA even without the deployment of lift spoilers. However, when the elements which make up the safety factor move towards their limiting values the situation becomes more critical even in the relatively benign conditions of the incident flight.

If it appears that the touchdown point will be beyond the touchdown zone limit, the procedure is clear, a go-around must be initiated before touchdown; during this procedure the main wheels may well make ground contact.

If the landing continues and the aircraft touches down in the correct place and then becomes airborne again, or simply floats beyond the touch down zone limit the problem becomes more complex. It appears that there are situations when the pilot is unaware that the aircraft is not on the ground.

The manufacturer has given considerable thought to the concept of initiating a go-around after touchdown at London City Airport or any other similarly limiting airfield. The company feels that there are so many variables to be considered that it would be impossible to lay down a procedure which would totally preclude an even more serious incident developing. Because of this, they could not endorse any initiative that would encourage a crew to initiate a go around after the aircraft has touched down.

The situation of London City Airport is such that there is a limited amount of land in the overrun area of either runway and the consequences of a high speed overrun are potentially very serious. The basic defence against such an event lies in the formulation and application of suitable procedures to ensure that the aircraft arrives at the threshold in the correct configuration at the correct height and speed, and that the landing is positive and within the limit of the touchdown area. However, it would be prudent to consider some form of runway end and safety area enhancement which would compensate for the lack of a clear overrun area and would be capable of bringing an aircraft to a stop in the event of a misjudged touchdown and/or the failure of retardation devices. The feasibility of installing some form of soft ground arresting device is under consideration by the airport authority: this, in its basic form is a pit which gets progressively deeper with distance from the runway end and is filled with a soft retarding substance such as sintered ash.

Study of landings at London City Airport

In 1991/1992 the CAA undertook a project at London City Airport the aims of which were:

1. To provide a statistical usage definition of a typical DHC-7 operation in the verification and formulation of existing and proposed design and operational requirements.
2. To develop a prototype operational exceedance programme for a commuter aircraft.
3. To examine the specialist area of steep approaches and STOL operations.
4. To enable the operator to establish the relevance and usefulness of a FDR programme to his operation.
5. To encourage other operators to start similar programmes.

The project provided a useful insight into the operation of the DHC-7 aircraft in a steep approach environment. As the BAe 146 has become a major type at the Airport, it could prove equally useful to undertake a similar study related to this aircraft. The manufacturer has already suggested that a working group should be formed to discuss BAe 146 operations at London City Airport; it could prove an ideal forum for initial discussions on the level of co-operation and the methods of the study.

Safety Recommendation:

97-27: It is therefore recommended that the CAA, in conjunction with the manufacturer, airport authority and operators, carry out a project to determine the scatter of significant landing parameters for the BAe 146 aircraft operating into London City Airport.