Liferaft survey report



This report is the property of RFD Beaufort Limited and, as such, the contents must be treated as confidential and be used only for the purpose for which it is supplied.

#### MAIB INVESTIGATION – FAILED DEPLOYMENT OF ML LIFEGUARD FORTIES TYPE LIFERAFT

#### Object:

To investigate the possible cause of a failed deployment of a ML Lifeguard Forties type liferaft

#### Date:

Wednesday 7 th November 2007

#### Location:

RFD Beaufort Limited, Kingsway, Dunmurry, Belfast BT17 9AF

#### Present:

Marine Technical Manager, RFD Beaufort Ltd

- Quality Engineer, RFD Beaufort Ltd
- Principal Marine Surveyor, MCA
- Managing Director, Premium Liferaft Services

#### Background:

of the Marine Accident Investigation Branch (MAIB), recently reported to RFD Beaufort Limited, that a ML Lifeguard Forties liferaft failed to inflate properly, when operated as a result of a marine accident. The marine accident involved two chartered fishing boats which collided at a reported speed of approximately 30 miles per hour.

The collision resulted in one of the vessels sinking quickly, during which time the liferaft was deployed. It was reported that the force of the inflation was sufficient to break the container banding straps, securing both halves of the container together. The liferaft was then reported to only partially inflate to a condition where it was considered not possible to be boarded. The end of the painter line was secured to the deck of the vessel and therefore the liferaft was pulled down beneath the water surface as the vessel sank. The liferaft was subsequently released some days later and returned to RFD Beaufort Limited for investigation.

#### Details:

#### Life raft details:

Manufacturer: Lifeguard Manufactured: July 1989

Type: ML Lifeguard Forties

Persons: Four Serial No. 40687 Container: Rigid/Flat Floor: Inflatable

Painter length: 10 m (cut to release from wreck)

RFD Beaufort Limited Kingsway, Dunmurry Belfast, BT17 9AF T: F:



Marine Report No: 40/07 Date Compiled: 07-11-07 Page 2 of 3

Gas Bottle: CO2/N2
Type: 3.5 lb
Tare weight: 3.6 kg
Total Weight: 5.1 kg
Serial No. 653560

The liferaft was removed from the transport protection bag. The liferaft was inspected before being inflated with no obvious signs of damage being observed.

The liferaft was inflated using a shop airline. The liferaft was again examined with the only observation being that the pressure relief valve (PRV) to the lower buoyancy tube failed to reseat. This PRV issue was considered not to be the reason why the liferaft did not fully inflate. No other damage was observed at this stage.

The cylinder and inflation system was inspected. The cylinder showed signs of what was considered to be significant corrosion. It was also noted that the cylinder had not been hydrostatically tested since 1999. The cylinder is required to be hydrostatically tested every 5 years. Premium Liferaft Services assured us that the cylinder had been check weighed at the last service in January 2007. However this check is not recorded by Premium Liferaft Services. ML Lifeguard Service Manuals for this raft state that cylinder check weights should be recorded. The Kidde type operating head was examined and it had appeared to function properly.



The cylinder was separately tested for leaks. Some water was removed in the cylinder before being pressurised with Carbon Dioxide.

The test was conducted using 25ml of a Carbon Dioxide chemical detection fluid. The detection fluid is initially intense pink in colour. The detection fluid (25ml) was placed in a plastic bag and secured around the neck of the cylinder.

The bag was left in position for 1 hour. At the end of this period, the test fluid was seen to be completely colourless, This indicated that at least 0.0022g of Carbon dioxide had escaped. The cylinder was then immersed in water to locate the point of leakage. No leakage point could be observed which indicates that the leak is extremely small.

The liferaft was then subjected to a one hour air-holding test. The bottom buoyancy failed the airholding test though the failure was considered not to be the reason why the liferaft only partially inflated. It should be noted that the liferaft is subject to an airholding test at each annual service. However Premium Liferaft Services advised that no records of the test are retained.

Marine Report No: 40/07 Date Compiled: 07-11-07 Page 3 of 3

It was also noted that only one half of the container was recovered with the liferaft. No damage to the recovered container half was noted.

#### Conclusion:

We are still to complete tests on the liferaft hose and hydrosatically test the cylinder. If the tests on the cylinder and the hose show no signs of failure it is our opinion that the partial inflation could be considered to be caused by a cylinder that was leaking.

Witnessed by:	
	RFD Beaufort Ltd
	KI D Beautoft Etu
Witnessed by:	
	MCA
Witnessed by:	
	RFD Beaufort Ltd
Witnessed by:	
	Premium Liferaft Services

Liferaft maintenance sheet

NE:

DU

SURVEYOR

Web site http://www.liferafts.com

E-mail: info@liferafts.com

1 or 3.

WITH COMPLIMENTS

M. A. I. B. Southany ton

ATTN

1317.

INSP

SERVICE STATION

- Cat & Serving record as

CYL

DATE



THE LIFERAFT HIRE COMPANY

Liferaft House Burnham Business Park Burnham-on-Crouch Essex CM0 8TE

Tel: Maldon Fax: Maldon

	222L		No.		AGENT	LS			ow	NER/VESSEL	
LIFER	FORT	ES			PERSONS	CAPACITY	CATALOGI 3039		SER	40687	
	IIGID ITAINER	SIME	MSE OR	P/ LE	AINTER ENGTH		AL PACK			HYDROSTATIC RE	LEASE IF FITT SERIAL No.
***	RADE	INFLAT		- 10	O MTS.	K	ORC	/2			
CYLI	NDER INFO			RIAL No	). <sub> </sub> T/	ARE WT. K		Continue parameter	GAS (	CHARGE Kg.	TOTAL WEIG
1	3/211	)	6535	560	3	•60	C03/13	104	4/0	30056	5.10
2											
.3											
4											
5											
TECH	INICAL PA	CKER			INSPECT	OR	(C.)		FIRS	7/90	
926	Д	NN	UA	LI	NSP	ECT	ION	CEI	RT	IFICATE	

MODIFICATIONS AND SPECIAL TESTS

**CARRIED OUT** 

LIFERAFT LOG CARD

	131	7.			LIFE	RAFT	LOG C	ARE	)				
	ER CONFIR		No.		AGENT				OWNE	R/VESS	EL		
•	2221	<b>+</b> 5			F	2رح		.50					
LIFEF	FORT	ES			PERSON:	SCAPACITY	CATALOGI 3039		SERIA	+06:	87:		
CO	RIGID NTAINER	SIM	OFF	PA	INTER NGTH	SURVIV	AL PACK		F		ATIC REL	EASE I	F FITT
***	M319/E	INFLAT FLO	TABLE OR	. 10	) <sub>MTS.</sub>	R	orc						
CYLI CYL REF	NDER INFO			IIAL No.		ARE WT. K	.   GAS		GAS CHA	DGE V.		TOTAL	
1	31/211		6535			-60	Co <sup>2</sup> /N <sup>2</sup>		4/00			TOTAL	
2		i)							<u> </u>	000		.,,,,	<u></u>
3													
4													
5				N-1990									
0		NN	UA	LIP	NSP		ION				ATE		
INSP YEAR	SERV	ICE STAT	NOI	CYL	DATE	MODIFI	CATIONS A	ND SPE	CIAL TES	its	SURV	YOR	NE INS DU
<b>1</b> st			9.					100					
2 <sub>nd</sub>			241103371										
3 <sub>rd</sub>											.00		
4 <sub>th</sub>									All 1 3242				
5 <sub>th</sub>								8			A CONTRACTOR OF THE CONTRACTOR		
6th													
7 <sub>th</sub>													
8 <sub>th</sub>						E II as		. F					
9th			matiki.Nasa in Wennes			396 T	[4					10 × 20 × 10 × 10 × 10 × 10 × 10 × 10 ×	
													_

#### PREMIUM LIFERAFT SERVICES

#### LIFERAFT SERVICING RECORD

Serial Nº 40687 Manufacturer: Lifeguard Raft Type: Old Style Cont. Pack: RORC

Manufacture date: 1 Jul 1989

1st Service Date: 24 Jul 1990

Flare Change:

Replacements:

Torch Cells, R.K. Adhesive,

Additional Work: 

2nd Service Date: 1 Jul 1991

Flare Change:

Replacements:

Torch Cells, R.K. Adhesive, H/H., A.S.S. Tabs. Flares.

Additional Work:

3rd Service Date: 31 Jul 1992

Flare Change:

Replacements:

Torch Cells, R.K. Adhesive,

Additional Work:

4th Service Date: 9 Jul 1993

Flare Change:

Replacements: Torch Cells, R.K. Adhesive.

Additional Work:

5th Service Date: 21 Jul 1994

Flare Change:

Replacements:

Torch Cells, R.K. Adhesive, H/H, A.S.S. Tabs, Flares.

Additional Work:

6th Service Date: 23 Aug 1995

Flare Change:

Replacements:

Torch Cells, R.K.Adhesive,

Additional Work: NO TO THE PORT OF THE PORT OF

7th Service Date: 8 Nov 1996

Flare Change:

Torch Cells, R.K.Adhesive, RB2 Arch light conversion kit Replacements:

fitted.M/H, A.S.S.Tabs,

Additional Work:

8th Service Date: 26 Nov 1997

Flare Change:

Torch Cells, R.K.Adhesive, Replacements:

Additional Work:

9th Service Date: 8 Jan 1999

Flare Change:

Torch Cells, R.K. Adhesive, canister repair, a.s.s. Replacements:

tabs. Cylinder required re-test & re-charge so was repl.

Additional Work:

10th Service Date: 3 Feb 2000

Flare Change:

Torch Cells, R.K. Adhesive, H/H. Replacements:

Additional Work:

11th Service Date: 2 May 2001

Flare Change:

Torch Cells, R.K. Adhesive, Painter, RB2, Container Replacements:

FLAIG CHAINEL Replacements:

Torch Cells, R.K. Adhesive, Painter, RB2, Container

Additional Work:

12th Service Date: 12 Jun 2002

Flare Change:

Replacements: Additional Work: Torch Cells, R.K. Adhesive, H/H.

PREMIUM LIFERAFT SERVICES

LIFERAFT SERVICING RECORD

Serial Nº 40687 Manufacturer: Lifeguard Raft Type: Old Style Cont.

Pack: RORC

Manufacture date: 1 Jul 1989

13th Service Date: 21 Jan 2003

Flare Change:

Replacements:

Torch Cells. R.K.Adhesive,

Additional Work:

14th Service Date: 10 Oct 2003

Flare Change:

Replacements:

Torch Cells, R.K.Adhesive, 3/S.

Additional Work:

15th Service Date: 17 Jan 2005

Flare Change:

Replacements:

Torch Cells, R.K.

Additional Work:

16th Service Date: 26 Jan 2007 Flare Change: 26 Jan 2007

Replacements:

TORCH CELLS, ADMESIVE, PAINTER, H/H, S/S,

THE REPORT OF THE PROPERTY OF

Additional Work: CHANGED CONTAINER

17th Service Date:

Flare Change: Replacements: Additional Work:

(R.K. - Repair Kit, H/H - Hand Held Flares, Paras - Parachute Flares, A.S.S.Tabs - Anti Seasickness Tablets,)

Α	nn	ex	C

PLRS service technician certificate of approval (RFD Beaufort)



# Certificate of Approval

COURSE ATTENDED: Lifeguard Marine Products - Refresher Level

This is to certify that the named individual has successfully completed an RFD Beaufort training course, and is competent to inspect, service, repair and pack the lifesaving equipment specified. The certificate is valid for a period of 3 years and may be withdrawn at the discretion of the awarding manufacturer or local authorities. The certificate is only valid whilst the named individual is employed at the specified Service Station, and whilst that Service Station has a current servicing agreement with the manufacturer.

Trained Employee:

81182

Registered No.: Date of Issue:

12-Dec-2003

Employed At: Premium Liferaft Services

Liferaft House

Burnham -on-crouch

Essex

CM0 8TE

United Kingdom

Brand	Product Category	Approval	Expires
Lifeguard	Forties Liferaft 4, 6, 8 Person	1	12-Dec-2006
Lifeguard	Release Hooks	1	12-Dec-2006
Lifeguard	Rescue Boats	1	12-Dec-2006

Kev: = Competent = Supervision Only

Training Manager

Instructor

Director

_				_
Λ.	าท	0	•	Г
$\rightarrow$			Λ.	L

PLRS SOLAS liferaft certificate of re-inspection (Viking)

ESSEX CMO 8TE

INFLATABLE SAFETY AND SURVIVAL EQUIPMENT TRADE ASSOCIATION LIMITED

ISSETA FORM No 197



### CERTIFICATE OF RE-INSPECTION

This is to certify that the liferaft detailed below has been surveyed, controlled and tested in compliance with requirements from:

		Inflatable Life	aft	
Identification:	Type: 4DK	Capacity:	Serial No: 4DK-RO21191	Date of manufacture:
	Fabric type:	Length of painter:		Max stowage height:
	N/A	26 m/inside	m/outside	13 m
Cylinders:	Serial No:	Contents CO <sub>2</sub> :	Contents N <sub>2</sub> :	Latest hyd. test:
	S11770	1.632 KG	0.068 KG	12-99
	1			
Equipment:	Unit:	Type:	Serial No:	Expiry date:
	Emergency pack:	SOLAS A PACK	4DK-R021191	
	EPIRB:			
	HRU test:			
	Radar reflector:	PAINS WESSEX	1193051	
	First aid kit:	BCB	5133	11-02
Tests:	NAP-test:	Gas inflation test:	Floor seam test:	Load test davit-launched
	Yes/no: NO	Yes/no: YES	Yes/no: YES	Yes/no: NO
	Latest test*:	Latest test*:	Latest test*:	Latest test*:
	* Latest test date	(month/year)		
Verification:	Date of inspection:	Servicing station No and na	ame:	Date issued to ship:
	21-08-01	PREMIUM LIFERAF	T SERVICES 380	21-08-01
	National Marine authority ID No:	Remarks / modification:	£	
	This inflatable liferaft re	quires servicing 12 months from th	e latest inspection date in acco	ordance with the SOLAS regulation
Flagstate of ship:				
IMO No:				
International call si	gnal:		For authorized serv	vicing station (printed name)
Name of ship / own PREMIUM LIFERAF	LIFERAFT SERVICE	S		
BURNHAM	BUSINESS PARK -ON-CROUCH			Signature

Head office: VIKING LIFE-SAVING EQUIPMENT A/S · Sædding Ringvej · P.O. Box 3060 · DK · 6710 Esbjerg V · Tel + 45 76 11 81 00 · Fax + 45 76 11 81 01 · Tlx 54114 vikng dk e-mail: viking@viking-life.com · www.viking-life.com

MCA liferaft service station inspection reports



## CONTROL OF INFLATABLE LIFERAFT SERVICE STATIONS

To (*11) Stijvevol-jerobetoje (A9)	noil ( ) and (	
2 (Headkot Shipping SalAly)	ananche III (1911) - 1915 (Manne Olice) II	Harwich
		ouganilled target comproved by November
	STANDARD CHECKLIST	
Based on the IMO	Resolution A 761(18) «Recommendations or ring stations for inflatable life afts as set dow	reonaltions for the
applowal our soul	ime stations do alline en alle alle alle alle alle alle alle	
al ton.	Premium Liferaft Services, Burnham on Croud	ch.
ale of the protection 15 June 2	008	Viking & Zodiac
	COMMENTER OF GENERAL STATE	BAWKK
BAMISES STATE OF THE MAN	Gas hot air blowers for winter	Satisfactory
The part of the pa	North facing and translucent	Satisfactory
n de la companya de l	Roller door - only opened during receipt and delivery.	Satisfactory
Under Control of	Sodium lights	Satisfactory
	Smooth cement floor	Satisfactory
None Security Leading	Viking Zodiac Mr A. Wade 07/2005 31/05/04 Mr I.D. Baker 08/2008 26/05/07 Mr M. Barr 07/2005 N/A	Urgent requirement - see remarks
to the English ManualS	Viking updated 04/2006 Zodiac updated 02/2006	On computer internet
Same Records	Paper and electronic	Satisfactory
	Large open warehouse with attached office	Satisfactory
mano clusaccess contains	Through large roller shutter door	Satisfactory
and a constitution of the state of the constitution of the state of th	Two compressors	Satisfactory
(2 Suctan Ramps Vaseumseleaner	Two industrial suction pumps	Satisfactory
Magometer liest and Records Satisfactory	Digitron tested 24/06/05	-Satisfactory

	**************************************	PARTITION AND THE PARTITION OF THE PARTI
STIDIRES Gas Bottles	2 x 12 man, 4 x 14 man and 5 x 6 man	Bottles recharged locally on demand.
Records (Rejeasé, Notes etc.)	Records available in the office and on computer	Satisfactory
L Wales are need to be a second or the second of the secon	Viking Zodiac Both types obtained on demand due to short shelf life	Agreeable due to large stock of service liferafts
A Journal of the Strate		Satisfactory
A THE REPART REPARTS	11 @ 08/09	Satisfactory
	Viking 13 @ 11/08 Zodiac 14 @ 06/09	Satisfactory
	52 @ 04/10	Satisfactory
valencius	39 litres @ 02/11	Satisfactory
	7 @ 11/09	Satisfactory
	Tested 12/2005	Satisfactory
Angustroje Blidarski dapis.	Yes	Satisfactory
	Yes	Satisfactory .
arentin race	No	
eris Industrial de parti	Yes	•
	BFA and LIFEGUARD	Liferafts being re-packed
		•
Carrie - Carriero Metaglicio di S	1994 & 1989	•
and index follows:	No No	•
pm a solution to	0 seconds	•
	0 seconds	•
a veire en analysis	0 seconds	
	11 of Hammar dated to 2009	Satisfactory
PARTHUM INCOMMENTS AREMA		
Services has one person with currence been cancelled at short notice. Whattendance difficult. It is important	able to attending courses for both Viking and Zodiac is a sent certification. Personnel have been booked to attend visite other courses are then rearranged, these are often protected that Premium Liferaft Services continues to try to place make with regard to the difficulties of making a seal when record on 40 Ale and ISAE liferafts.	omulgated at short notice making embers of staff on these courses.
was used on lifejackets but now us		
South at Harwich		WE OF
TO WOLLD	Signed: 1	(Face and the second se
16 June 200	6 Name	Martiture and coastiguard Apartoy



# CONTROL OF INFLATABLE LIFERAFT SERVICE STATIONS

		<b>"我想象"。在"3.20"。1445—1453—1453—1453</b>
To:- 1. Surveyor-in-Charge /AOM	From	The state of the s
2. Head of Shipping Safety B	ranch - HQ Marine Office:-	Harwich
		wantime and Coastguard Agency
Based on the IMO F approval of servici	STANDARD CHECKLIST  Resolution A 761(18) - Recommendations on a ng stations for inflatable [ferafts as set down	onditions for the in OSG Doc-419
Station	Premium Liferaft Services, Burnham on Crouch	
Date of Inspection 26 October 2		Viking & Zodiac
TEM:	GOMMENTS ON GONDITION (	REWARKS
PREMISES Heating 7 Ventilation	Gas hot air blowers for winter	Satisfactory
Skylights etc. screened against UV / sunlight	North facing and translucent	Satisfactory
Draft Protection	Roller door - only opened during receipt and delivery.	Satisfactory
Lighting	Sodium lights	Satisfactory
Cléanliness	Smooth cement floor	Satisfactory
RSONNEL Names, Certificate No.s. & Dates of lastie / Expliry	Viking Zodiac Mr A. Wade 07/2005 31/05/04 Mr I.D. Baker 08/2008 26/05/07 Mr M. Barr 07/2005 N/A	Urgent requirement - see remarks
Service Manuels	Viking updated 04/2006 Zodiac updated 02/2006	On computer internet
Service Records Organisation and Layout	Paper and electronic	Satisfactory
Organisation and Layout	Large open warehouse with attached office	Satisfactory
In and Out access for rafts	Through large roller shutter door	Satisfactory
Inflation air from inside station	Two compressors	Satisfactory
Suction Pumps - Vacuum Cleaner	Two industrial suction pumps	Satisfactory
Manometer Test and Records Satisfactory	Digitron tested 24/06/05	-Satisfactory

	ITEM SQUEEN	COMMENTS ON CONDITION	REMARKS
STORES	Gas Bottles	2 x 4 man, 9 x 6 man, 8 x 12/14 man and 6 x 8 man	Bottles recharged locally on demand.
Records	(Release Notes etc.)	Records available in the office and on computer	Satisfactory
A	dhesive Dates & Type	Viking Zodiac Both types obtained on demand due to short shelf life	Agreeable due to large stock of service liferafts
	Pyrotechnics Dates	Paras Smokes Hand 90 @ 10/09 40 @ 10/09 100 @ 10/09	Satisfactory
	-First Aid Kits Dates	34 @ 11/09	Satisfactory
	Repair Kits Dates	Viking 8 @ 11/08 Zodiac 30 @ 06/09	Satisfactory
	Food Dates	72 @ 04/11	Satisfactory
	Water Dates	90 litres @ 08/11	Satisfactory
La	easick Tablets Dates	60 @ 07/10	Satisfactory
	Scales Test Date	Tested 12/2005	Satisfactory
Ample To	ools, Plugs & Adaptor	Yes	Satisfactory
	Marked Hall Board	Yes	Satisfactory
	Raft Inflated	No	• *
The state of the s	acked Raft Inspected	Yes	• 000000
244	Туре	None	SOLAS being re-packed
	Serial Number	:	•
	Date of Manufacture		•
	Painter Pull	•	-
	Time Boardable	-	
	Arches Up	. 10	-
	Valves Blowing Off	•	•
Hydro	statio Release Units	20 of Hammar dated to 2009	Satisfactory
Additional	Comments / Remar	ksc	
During the pa are fitted to L	ast few months PLRS I Ifeguard's, BFA's and ards. In a required situa	for November and December 2006.  have had 4 x pressure relief valves (A6's all made by L  Zodiac's. 3 x PRV have broken at flange to stub join a  ation, this would lead to complete failure of the liferaft  g date of the raft may be 2001/2. 3 out of the 4 liferafts	nd 1 x PRV has blown the centre valve compartment/tube. From the failures that
	The state of the s		r en 1
Issued at	Harwich	Signed	JURINE OF THE
1			Maritime and Gonzald Agency
Date	27 October 20	Name Name	MARWICH
	5 y 28		L Official Stamp

PLRS customer owned liferaft servicing report

#### PREMIUM LIFERAFT SERVICES - LIFERAFT SERVICING REPORT

Liferaft House Burnham Business Park Burnham on Crouch Essex CM0 8TE Tel: 01621-784858 Fax 01621 785934

Owner:			Inspection Certificate No	07/044
Manufacturer. LIFEGUARD	Size & Type: 8 Pers FORTIES	Container	Pack: R.O.R.C.	<u>Serial No.</u> 80025
Date of Manufacture: 09/1998	Last serviced by & Dat Premium Liferafts 0	-	<u>Service Date:</u> 16/03/2007	Next Service Due: 03/2008

<b>Pressure Tests</b>	Relief Valves		Time		Start		End	
	Open	Closed	Start	End	Pressure	Temp.	Pressure	Temp.
Upr Buoyancy	70.00	61.50	08.50	09.50	61.50	17°C	60.00	17°C
Lr Buoyancy	75.00	61.50	08.50	09.50	61.50	17°C	60.00	17°C
Floor	***	***	09.05	09.50	12.00	17°C	8.00	17°C

CYLINDER DETAILS				EMERGENCY PACK(S)		S	Replace (No	
Cylinder No. 0188673				Basic Pack				
CO <sub>2</sub> Weight		2.780		Bailer	1			
N <sub>2</sub> Weight <b>0.070</b>		Bellows	1					
Tare Weight 8.274			Paddles 🗸					
Full Weight 11.124			Repair Kit	1		Adhesive		
.est & Refurbish 19/01/2005			Sponges	/				
Last Hydrostatic Test	19/01/2005 01/2010			Leak Stoppers	1			
Next test due				Instructions Card	1			
INFLATION SYSTEM	Pass	Fail	See Com.	SOLAS No.2 Signals Card	1			
Operating Head	1			Pack Bag.	1			
Operating Head Cover	1			R.O.R.C. Pack				
Firing Line	1			Hand Held Flares (3)	1		-	
Conduit	1			Anti-Seasickness Tablets	1			
Red Safety cap	N/A			Signalling Torch	1		4 Batteries	
High Pressure Hose	1			Offshore E Pack			, Dutterio	
'O' Rings	N/A			Parachute Flares (2)	1	_		
Inlet valves & P.R.V's.	1			Spare Torch Batteries & Bulb				
Top up valves	1			First Aid Kit	1	_		
HULL & EQUIPMENT				Drinking Water				
Upper Buoyancy ✓			Graduated Beaker					
Lower Buoyancy	1			Additional Equipment				
Arch	1			Additional Eduipment	T			
Floor	1				+			
Line & patches (int)	1							
Lifeline & patches (ext)	1							
Righting Strap	1			Valise	Pass	Fail	See Com	
Boarding Ladder	1			Fabric	N/A	Faii	occ com	
Painter & Patch	1			Handles	N/A	-		
Drogue & Patch	1			Painter Storage	N/A			
Ouoit & Line	1			Container	IVA	_		
Safety Knife & patch	1		1	Gasket	1	T		
Cylinder Pocket	1			Tape	N/A			
Water Ballast Pockets	1			Bursting Bands / Lashing Strap	J.	+		
Canopy & Entrance	1			Painter Storage	1	+		
Retro Reflective Tape	1			Labels	1	-		
Rainwater collector			Vacuum/Hermetic Pack.					
Arch Light (internal)	1			Vacuum/hermetic Bag	N/A			
Arch Light (external)	1			Sealing Strip	N/A N/A	-	-	
Arch Light Batteries	1			Seating Strip	IN/A			
Deflation Plug	1			PLEASE TURN OVER FOR	OFNER	2011	*	

ISAF offshore special regulations liferaft requirements

#### **APPENDIX A part II**

Appendix A does not cover liferafts intended for category 0 races

#### The ISAF liferaft

The ISAF liferaft specification (OSR Appendix A part II) was published in 2002 pending completion of ISO standard 9650 and served the offshore community well.

As ISO 9650 is now widely available ISAF is following previouslyestablished policy to promote the ISO standard as its primary reference. It is the intention of ISAF that the ISAF specification will continue to be an acceptable alternative although manufacturers may choose to no longer market products under the ISAF name. The complete ISAF liferaft specification is at www.sailing.org/specialregs

Please refer to the text of Special Regulations for further details.

Chairman Special Regulations Liferaft Working Party November 2007

### ISAF OFFSHORE SPECIAL REGULATIONS

ISAT OFFSHORE SPECIAL REGULATIONS	
contain at least a SOLAS "A" pack.	Category
and the transfer from the first of the first	
4.20.2 Liferaft(s) shall be provided capable of carrying the whole crew when each liferaft shall comply with either:-	MoMu1,2
a) OSR 4.20.1 (b) (SOLAS), or	MoMu1,2
<ul> <li>b) for liferafts manufactured prior to January 2003, OSR Appendix A part I (ORC), or</li> </ul>	MoMu1,2
<ul> <li>OSR Appendix A part II (ISAF) when, unless otherwise specified by a race organizer, the floor shall include thermal insulation, or</li> </ul>	MoMu1,2
d) ISO 9650 Part I Type I Group A (ISO) when each liferaft shall contain at least a Pack 2 (<24h) and-	MoMu1,2
i) shall have a semi-rigid boarding ramp, and	MoMu1,2
<ul><li>ii) shall be so arranged that any high-pressure hose shall not impede the boarding process, and</li></ul>	MoMu1,2
<li>iii) shall have a topping-up means provided for any inflatable boarding ramp, and</li>	MoMu1,2
iv) when the liferaft is designed with a single ballast pocket this shall be accepted provided the liferaft otherwise complies with ISO 9650 and meets a suitable test of ballast pocket strength devised by the manufacturer and	MoMu1,2
<ul> <li>v) compliance with OSR 4.20.2 (d) i-iv shall be indicated on the liferaft certificate.</li> </ul>	MoMu1,2
1.20.3 Liferaft Packing and Stowage	MoMu0,1,2
A Liferaft shall be either:-	MoMu0,1,2
<ul> <li>a) packed in a transportable rigid container or canister and stowed on the working deck or in the cockpit, or:-</li> </ul>	MoMu0,1,2
<ul> <li>b) packed in a transportable rigid container or canister or in a valise and stowed in a purpose-built rigid compartment containing liferaft(s) only and opening into or adjacent to the cockpit or working deck, or through a transom, provided that:-</li> </ul>	MoMu0,1,2
<ul> <li>i) each compartment is watertight or self-draining (self- draining compartments will be counted as part of the cockpit volume except when entirely above working deck level or when draining independently overboard</li> </ul>	MoMu0,1,2
Page - 40 -	