Recommendation(s) Status: Collision at Pickering Station North York Moors Railway

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

Key to Recommendation Status

Implemented:	All actions to deliver the recommendation have been completed.	
Implemented by alternative	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB	
means:	during the investigation.	
Implementation ongoing:	Work to deliver the intent of the recommendation has been agreed and is in the process of being delivered.	
In-progress:	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is in place to implement the recommendation; and work is in progress to provide this.	
Non-implementation:	Regulation 12(2)(b)(iii) = recommendation considered and no implementation action to be taken.	
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.	


RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following.



The red triangle shows recommendations where the RAIB has concerns that no actions have been taken in response to a recommendation.



The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.



Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

Number/ Date/ Report No/ Inv Title / Current Status		Safety Recommendation	Summary of current status (based on latest report from the relevant safety authority or public body)
1 05/05/2007 29/2007 Collision at Pickering Station NYMR Status: Implemented		The NYMR should immediately mandate that the person who operates the hand points at Pickering south should remain at the points after operating them, and should only call a locomotive past them when the ground signal clears, after again checking the lie of the points (paragraphs 41 and 43); or The NYMR should install a system at Pickering south that provides an indication to the train crew in the cab as to the lie of the points (paragraph 41).	The NYMR has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
	05/05/2007 29/2007 at Pickering Station NYMR nplemented	The NYMR should introduce procedures to ensure that after an accident no rolling stock or other evidence is moved without considering the effect on people involved, and only in compliance with the Rail Accident (Investigation and Reporting) Regulations, 2005.	The NYMR has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.

09 November 2015 Page 2 of 2