

Report of Thorough Examination of Loader Crane



**Service Division - Tel. 08444 996688**

AVAILABLE & COST EFFECTIVE - WWW.ATLASGMBH.COM

**LOADER CRANE SERVICE INSPECTION/THOROUGH EXAMINATION REPORT 105391**

CUSTOMER	Inverlussa(crane sales)	64089	MK Job No.	731754
DEPOT	oban	CR. HRS	MILEAGE	
MAKE	atlas	MODEL	170vcs a12	SERIAL No.
VEHICLE	m v carol anne	MODEL		REG No.
AUX EQUIP		MODEL		SERIAL No.
ROTATOR-IF APL		MODEL		SERIAL No.

Item Code	COMPONENT	1 2 3 4 5	Item Code	COMPONENT	1 2 3 4 5	Item Code	COMPONENT	1 2 3 4 5
1	Subframe	■ ■ ■ ■ ■	50	TOP SEAT	■ ■ ■ ■ ■	90	Winch Rope	■ ■ ■ ■ ■
2	Hold down bolts	■ ■ ■ ■ ■	51	Top Seat	■ ■ ■ ■ ■	91	Rotator	■ ■ ■ ■ ■
3	Crane base	■ ■ ■ ■ ■	52	Fabrication	■ ■ ■ ■ ■	92	Rotator link Pin	■ ■ ■ ■ ■
4	Pendulum Beam	■ ■ ■ ■ ■	53	Access	■ ■ ■ ■ ■	93	Rotator Bolts	■ ■ ■ ■ ■
5	Hydraulic Tank	■ ■ ■ ■ ■	54	Emergency Stop	■ ■ ■ ■ ■	<b>ATTACHMENT/GRAB</b>		
6	Boom Stowage	■ ■ ■ ■ ■	<b>STANDUP CONTROLS (T1)</b>			94	Hoses	■ ■ ■ ■ ■
7	PTO Switch	■ ■ ■ ■ ■	55	T1 Platform fabrication	■ ■ ■ ■ ■	95	Rams	■ ■ ■ ■ ■
8	Handbrake Interlock	■ ■ ■ ■ ■	56	Controls	■ ■ ■ ■ ■	96	Pins/Bushes	■ ■ ■ ■ ■
9	Hydraulic Pump	■ ■ ■ ■ ■	57	Access	■ ■ ■ ■ ■	97	Fabrication	■ ■ ■ ■ ■
10	Pressure Feed Hose	■ ■ ■ ■ ■	<b>COLUMN</b>			98	Cross Rods	■ ■ ■ ■ ■
11	Suction Hose	■ ■ ■ ■ ■	58	Hoses	■ ■ ■ ■ ■	99	Rubbers	■ ■ ■ ■ ■
12	Hand/Auto Throttle	■ ■ ■ ■ ■	59	Bearings (Neck/Foot)	■ ■ ■ ■ ■	100	Cutting Edge	■ ■ ■ ■ ■
13	<b>OUTRIGGER LEGS</b>	■ ■ ■ ■ ■	60	Slew Cylinders	■ ■ ■ ■ ■	101	Clips	■ ■ ■ ■ ■
14	Beams	■ ■ ■ ■ ■	61	Slew Position Sensors	■ ■ ■ ■ ■	102	General Wear	■ ■ ■ ■ ■
15	Rollers	■ ■ ■ ■ ■	62	Fabrication	■ ■ ■ ■ ■	<b>INFORMATION PLATES</b>		
16	Cam locks and R Clips	■ ■ ■ ■ ■	63	Top Pin/Bushes	■ ■ ■ ■ ■	103	Load Plates	■ ■ ■ ■ ■
17	Secondary leg locks	■ ■ ■ ■ ■	<b>MAIN LIFT</b>			104	CE Plates	■ ■ ■ ■ ■
18	Leg Stops	■ ■ ■ ■ ■	64	Cylinder	■ ■ ■ ■ ■	105	Serial Plate	■ ■ ■ ■ ■
19	Outrigger Hoses	■ ■ ■ ■ ■	65	L.H.V / H.F.V	■ ■ ■ ■ ■	<b>ELECTRICS</b>		
20	Stabilizer Legs	■ ■ ■ ■ ■	66	Pins/Bushes	■ ■ ■ ■ ■	106	Wiring	■ ■ ■ ■ ■
21	Mechanical Leg	■ ■ ■ ■ ■	67	Cylinder Power Link	■ ■ ■ ■ ■	107	Control Box	■ ■ ■ ■ ■
22	Mechanical Leg Pin/R Clip	■ ■ ■ ■ ■	<b>BOOM</b>			108	ON/OFF Button	■ ■ ■ ■ ■
23	Feet	■ ■ ■ ■ ■	68	Fabrication	■ ■ ■ ■ ■	109	Emergency Stop	■ ■ ■ ■ ■
24	Stabilizer Hoses	■ ■ ■ ■ ■	<b>JIB CYLINDER</b>			110	O.L.P Lights	■ ■ ■ ■ ■
25	Stabilizer Rams	■ ■ ■ ■ ■	69	Cylinder	■ ■ ■ ■ ■	111	O.L.P System	■ ■ ■ ■ ■
26	Stabilizer Ram Pins	■ ■ ■ ■ ■	70	L.H.V /H.F.V	■ ■ ■ ■ ■	112	General Condition	■ ■ ■ ■ ■
27	Hydraulic Folding Legs	■ ■ ■ ■ ■	71	Pins/Bushes	■ ■ ■ ■ ■	113	Leg Lights	■ ■ ■ ■ ■
28	Pressure Sensors	■ ■ ■ ■ ■	72	Jib to Boom Pin/Bushes	■ ■ ■ ■ ■	<b>SAFE STOWAGE SYSTEM</b>		
29	Beam Position Sensors	■ ■ ■ ■ ■	<b>JIB KICKING LINK</b>			114	Visual Alarm	■ ■ ■ ■ ■
<b>VALVE BLOCK</b>			73	Jib Kicking Link	■ ■ ■ ■ ■	115	Audible Alarm	■ ■ ■ ■ ■
30	Dump Valve	■ ■ ■ ■ ■	74	Pins/Bushes	■ ■ ■ ■ ■	116	Boom Above Horizontal	■ ■ ■ ■ ■
31	Dump Valve Solenoid	■ ■ ■ ■ ■	<b>JIB</b>			117	Boom outside Body	■ ■ ■ ■ ■
32	Main Relief Valve	■ ■ ■ ■ ■	75	Fabrication	■ ■ ■ ■ ■	118	Legs Not Stowed	■ ■ ■ ■ ■
33	Main Relief Valve Seals	■ ■ ■ ■ ■	76	Hoses/Pipes	■ ■ ■ ■ ■	119	Radio Remote Stowage	■ ■ ■ ■ ■
34	Outrigger Spool	■ ■ ■ ■ ■	77	Rotary Banjo/L.H.V	■ ■ ■ ■ ■	<b>RADIO REMOTE</b>		
35	Slew Spool	■ ■ ■ ■ ■	<b>JIB EXTENSIONS</b>			120	Receiver	■ ■ ■ ■ ■
36	Main Lift Spool	■ ■ ■ ■ ■	78	Fabrication	■ ■ ■ ■ ■	121	Transmitter	■ ■ ■ ■ ■
37	Jib Spool	■ ■ ■ ■ ■	79	Cylinders	■ ■ ■ ■ ■	122	Battery Charger	■ ■ ■ ■ ■
38	Extension Spool	■ ■ ■ ■ ■	80	Cylinder Guides	■ ■ ■ ■ ■	123	Battery Condition	■ ■ ■ ■ ■
39	Auxiliary Spool	■ ■ ■ ■ ■	81	Wear Pads	■ ■ ■ ■ ■	<b>OTHER SAFETY EQUIPMENT</b>		
40	Auxiliary Valve Seals	■ ■ ■ ■ ■	82	Pins/Bushes	■ ■ ■ ■ ■	<b>AUTOLUBE SYSTEM</b>		
41	Overload Protection	■ ■ ■ ■ ■	<b>AUXILIARY EQUIPMENT</b>			125	General Condition	■ ■ ■ ■ ■
42	Overload Protection Seals	■ ■ ■ ■ ■	83	Hose Guides and Carriers	■ ■ ■ ■ ■	126	Operation	■ ■ ■ ■ ■
43	Valve Bank Pipes	■ ■ ■ ■ ■	84	Quick Release Couplings	■ ■ ■ ■ ■	127	Container Contents	■ ■ ■ ■ ■
44	Swivel Connections	■ ■ ■ ■ ■	85	(B30) Head Fabrication	■ ■ ■ ■ ■	128	Pipework	■ ■ ■ ■ ■
45	Valve block leaks	■ ■ ■ ■ ■	86	(B30) Head Pins/Clip	■ ■ ■ ■ ■	<b>PRESSURE SETTING BAR</b>		
46	Control Levers	■ ■ ■ ■ ■	87	Hook	■ ■ ■ ■ ■	<b>VEHICLE RPM</b>		
47	Control Lever Decals	■ ■ ■ ■ ■	88	Shackle	■ ■ ■ ■ ■			
48	Cross Rods/Cables	■ ■ ■ ■ ■	89	Hook Safety Catch	■ ■ ■ ■ ■			
49	Pressure Gauge/Fittings	■ ■ ■ ■ ■		Winch	■ ■ ■ ■ ■			

Item Code	DEFECT	STATUS	ACTION REQUIRED	DEADLINE
1	103 no load plates	D: Damage W: Wear & Tear	phoned [redacted] he will send to customer	
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				

Date	Start	Time on site	Time off site	Time Home	Mileage
	10 30	12 30	14 30	18 30	212

COMMENTS	PARTS USED FOR SERVICE
Set o/p as per sales booklet as [redacted] over phone lunch 12 00 1230	ITEM PART No. QTY
	1
	2
FAXED TO: FAX No.	3
TIME DATE	4
CONFIRMED	5
	6

<input type="checkbox"/> If this box is ticked, it is in our opinion the crane is unsafe to use until the above repairs marked 'immediate' are effected	GENERAL SERVICE	<input type="checkbox"/>	
	CRANE GREASED	<input type="checkbox"/>	
	HYDRAULIC FILTER CHECKED	<input type="checkbox"/>	HYDRAULIC OIL CHANGED/TOPPED UP <input type="checkbox"/>
	HYDRAULIC FILTER RENEWED	<input type="checkbox"/>	AUTOLUBE TOPPED UP <input type="checkbox"/>

CUSTOMER	ENGINEER
NAME [redacted]	NAME [redacted]
POSITION owner	I hereby acknowledge I have/am proceeding work using the applicable Risk Assessment & Method Statement
DATE 23 3 15	DATE 23 3 15
CUSTOMER SIGNATURE	ENGINEERS SIGNATURE
[redacted signature]	[redacted signature]
CUSTOMERS SIGN HERE	ATLAS SIGN HERE

How did you rate our service today?  Excellent  Good  OK  Poor  Very poor






**Service Division - Tel. 08444 996688**
**AVAILABLE & COST EFFECTIVE - WWW.ATLASGMBH.COM**
**REPORT OF THOROUGH EXAMINATION OF LOADER CRANE 302288**  
**Lifting operation and lifting equipment regulations 1998 (Regulation 9)**

Date of Last Thorough Examination:	23 3 15	CALL No.	64089
Latest date by which the next thorough examination must be carried out:	23 3 16	Record Identification: No.	
Employer (and or equipment owner) Address:	Inverlussa Oban	Address at which examination was made.	Same
Reg No./Chassis No.	m v carol anne	Equipment Make/Model	atlas 170vcs a12
Loader Mounting details	marine crana	Serial No.	0170 p00535
		Year of Manufacture	2015

**Safe working load - to cover range of SWL's & configurations & particulars of any test i.e. 10% for annual/ 25% in all other cases**

	Load Radius (Metres)	Test Load (Kgs)	Safe Loading (Kilogrammes)	Overload %
1	10.8	2000	1500	25
2	8.45		2000	
3				

**NOTE: IF THE DATE OF LAST THOROUGH EXAMINATION IS UNKNOWN A 25% OVERLOAD MUST BE APPLIED**

Nature of Examination	Please tick as appropriate	12 Monthly examination 9(3)(a)(ii)	<input type="checkbox"/> + 10%
Second hand/ Non CE 9(1)	<input type="checkbox"/> + 25%	4 Yearly	<input type="checkbox"/> + 25%
1st examination following installation 9(2)	<input checked="" type="checkbox"/> + 25%	In accordance with examination scheme 9(3)(a)(iii)	<input type="checkbox"/> + 10%
6 monthly examination 9(3)(a)(i)	<input type="checkbox"/> + 25%	Following exceptional circumstances 9(3)(a)(iv)	<input type="checkbox"/> + 25%

 Identification of any part found to have a defect which is or could become a danger to persons.  
 The particulars of any repair, renewal or alteration required to remedy the defect either immediately or within a specified time.

Other defects and remedies

Observation and condition of attachment (state, make, model and serial no.)

**CUSTOMER**

 NAME   
 POSITION   
 DATE   
 CUSTOMER SIGNATURE

CUSTOMERS SIGN HERE

**ENGINEER**

 NAME   
 I hereby acknowledge I have/am proceeding work using the applicable Risk Assessment & Method Statement  
 DATE   
 ENGINEERS SIGNATURE

ATLAS SIGN HERE

 How did you rate our service today?  Excellent  Good  OK  Poor  Very poor

Report from Caparo Testing Technologies on the Lock Nuts



Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**

A Division of Caparo Engineering Limited

**LABORATORY INVESTIGATION REPORT**

Date Received/Tested ..... 21<sup>st</sup> July 2015 ..... (Page ..... 1 ..... of ..... 9 ..... )  
 Customer ..... Marine Accident Investigation ..... Enquiry from ..... [REDACTED] .....  
 Address ..... Spring Place, 105 Commercial Road, Southampton, SO15 1GH .....  
 Certificate No. .... PEJ168 ..... Order No. .... N/A ..... Customers Ref. No. .... N/A .....  
 Material Specification ..... ISO 898-2 GRADE 8 ..... Dimensions ..... M24 Nyloc Nut .....

M24 x 2.0 pitch fine threaded nuts and a location plate were submitted by yourselves for a detailed investigation.

**CHEMICAL ANALYSIS** (Analytical Method Used: - OES) – Location Plate

C%	Si%	Mn%	P%	S%	Cr%	Mo%	Ni%	Al%	Co%
0.130	0.285	0.549	0.011	0.022	0.097	0.009	0.123	0.0104	0.012
Cu%	Nb%	Ti%	V%	W%	Pb%	Sn%	Ca%	B%	
0.316	0.002	<0.0010	0.001	0.003	<0.003	0.016	0.0009	<0.0002	

**CHEMICAL ANALYSIS** (Analytical Method Used: - OES) – M24 x 2.0 Nut

C%	Si%	Mn%	P%	S%	Cr%	Mo%	Ni%	Al%	Co%
0.109	0.088	0.426	0.013	0.031	0.003	0.026	0.0279	0.013	0.039
Cu%	Nb%	Ti%	V%	W%	Pb%	Sn%	Ca%	B%	
0.039	0.002	<0.0010	0.001	0.002	<0.003	0.004	0.0016	<0.0002	

**PROOF LOAD TEST**

Result (Kn)	
Requirements for grade 8 Nut style 1 - 395.5kn	Thread stripped on nut at a force of 301.21Kn – failed to meet grade 8 requirements

**VICKERS HARDNESS TEST** (ASTM E384: 2011E1) - Nut

HV – 10kg
225

**BRINELL HARDNESS TEST** (ASTM E 18: 2014A) - Plate

HRB
85

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.  
 Without the embossed stamp mark on this test report it is not the original.  
 The tests are carried out to the most up to date standards where possible.  
 The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.  
 Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified  
 The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.  
 Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.



Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**

A Division of Caparo Engineering Limited

**LABORATORY INVESTIGATION REPORT**

Date Received/Tested.....21<sup>st</sup> July 2015.....(Page.....2.....of.....9.....)  
 Customer.....Marine Accident Investigation.....Enquiry from [REDACTED].....  
 Address.....Spring Place, 105 Commercial Road, Southampton, SO15 1GH.....  
 Certificate No. ....PFJ168.....Order No. ....N/A.....Customers Ref. No. ....N/A.....  
 Material Specification .....ISO 898-2 GRADE 8.....Dimensions .....M24 Nyloc Nut.....

**VICKERS HARDNESS SURVEY (BS EN ISO 6507-1: 2005)**

TEST	50gm
1	209.7
2	203.6
3	203
4	199.4
5	209.3

**Note:** Location of hardness test taken 0.5m, as close as possible to the nominal major diameter of the nut thread. Ref: ISO 898-2 9.2.33

**Coating Thickness - (by micro examination)**

A micro section was cut from the sample. The micro sections were encased in a resin base and then polished to a 1 micron surface finish.

Results (mm)	
EXTERNAL SURFACE	UPTO 0.0488
THREADED PROFILE	Nil

Photos 1 and 2

**DECARBURISATION INSPECTION (ASTM F2328-14)**

A longitudinal section was taken from the sample and polished, then etched in 2% Nital.

Examination of the section showed no evidence of decarburization.

No decarburization was detected, due to material had not been heat treated.

Photo 6

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.  
 Without the embossed stamp mark on this test report it is not the original.  
 The tests are carried out to the most up to date standards where possible.  
 The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.  
 Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified  
 The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.  
 Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.



Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**  
A Division of Caparo Engineering Limited

**LABORATORY INVESTIGATION REPORT**

Date Received/Tested ..... 21<sup>st</sup> July 2015 ..... (Page ..... 3 ..... of ..... 9 .....)  
 Customer ..... Marine Accident Investigation ..... Enquiry from .....  
 Address ..... Spring Place, 105 Commercial Road, Southampton, SO15 1GH .....  
 Certificate No. .... PEJ168 ..... Order No. .... N/A ..... Customers Ref. No. .... N/A .....  
 Material Specification ..... ISO 898-2 GRADE 8 ..... Dimensions ..... M24 Nyloc Nut .....

**MICROSTRUCTURE**

**Micrographic Examination** (ASTM: E 3: 2001 (R2007) E1)

A longitudinal section was taken from three samples and polished, then etched in 2% Nital.  
 Photo's 4, 5 and 6 – Non heat treated structure was evident that of a ferrite/pearlite structure.

**MACROSTRUCTURE** (ASTM: E340-01 (2012))

A longitudinal section was taken from the sample and subjected to a Macro etch in 50% HCL to boiling point for a time of approximately 8 minutes.

Photo 3

**DETERMINATION OF INCLUSION CONTENT** (ASTM: E 45: 2011 – Method A)

A longitudinal section was taken from the sample and polished.

Examination of the section revealed an inclusion content, as follows: -

TYPE A		TYPE B		TYPE C		TYPE D	
Thin	Heavy	Thin	Heavy	Thin	Heavy	Thin	Heavy
0.5	0	1	0	1.5	0	0	1.5

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.  
 Without the embossed stamp mark on this test report it is not the original.  
 The tests are carried out to the most up to date standards where possible.  
 The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.  
 Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified  
 The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.  
 Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.





Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**

A Division of Caparo Engineering Limited

## LABORATORY INVESTIGATION REPORT

Date Received/Tested ..... 21<sup>st</sup> July 2015 ..... (Page ..... 4 ..... of ..... 9 .....)  
Customer ..... Marine Accident Investigation ..... Enquiry from ..... [REDACTED] .....  
Address ..... Spring Place, 105 Commercial Road, Southampton, SO15 1GH .....  
Certificate No. .... PEJ168 ..... Order No. .... N/A ..... Customers Ref. No. .... N/A .....  
Material Specification ..... ISO 898-2 GRADE 8 ..... Dimensions ..... M24 Nyloc Nut .....

### COMMENTS

M24 Zinc plated nylon lock nuts were submitted for testing/investigation to establish possible cause of thread striping from nuts.

The nuts had failed as part of a fixing kit, for fixing a brick and block type crane to a back of a lorry.

Dimensions of the nut established that the nut was in fact manufactured in accordance with DIN 985. This established a thin nut type (M24 fine thread pitch 2.0) with reduced loadability (Style O).

Loadability of the design of nut would be in accordance with Din 267 Part 4 based on a proof load of 800 N/mm<sup>2</sup> proof load value 307000N.

The marking/identification of the nut did not indicate that the nut was that of reduced loadability, has it was identified as a Grade 8 nut (Style 1) nominal size nut, and not 08 (Style 0) this would indicate that the nut was in fact a thin nut with reduced loadability.

Loadability of a regular style nut Grade 8 would have a proof load strength based on 1030 M/mm<sup>2</sup> for M24 fine thread nut proof load value 395500N.

Quote from BS EN ISO 898-2:2012 – Thin nuts (Style O) have a reduced loadability compared to regular nuts (Style 1) or high nuts (Style 2) and are not designed to provide resistance to thread striping.

This would indicate that the incorrect type of nut was selected/used for the application of being part of the fixing kit supplied with the brick and block type crane.

Several tests – see attached report was carried out to establish what condition / material grade and proof load strength resistance the nut displayed.

Testing revealed that in fact the M24 Nut actually displayed material grade type, that of a 06 type nut.

Load ability of 06 thin type nut in accordance with DIN 267 Part 4 based on a proof stress of 800N/mm<sup>2</sup> would give a proof load value of 23000N

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.

Without the embossed stamp mark on this test report it is not the original.

The tests are carried out to the most up to date standards where possible.

The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.

Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified

The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.

Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.



Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**  
A Division of Caparo Engineering Limited

## LABORATORY INVESTIGATION REPORT

Date Received/Tested ..... 21<sup>st</sup> July 2015 ..... (Page ..... 5 ..... of ..... 9 ..... )  
Customer ..... Marine Accident Investigation ..... Enquiry from ..... [REDACTED] .....  
Address ..... Spring Place, 105 Commercial Road, Southampton, SO15 1GH .....  
Certificate No. .... P.F.J.168 ..... Order No. .... N/A ..... Customers Ref. No. .... N/A .....  
Material Specification ..... ISO 898-2 GRADE 8 ..... Dimensions ..... M24 Nyloc Nut

06 Thin type nut (style O reduced loadability) would be manufactured from a plain carbon steel, containing small amounts of Mn only, and no further alloy element to assist in the ability to be heat treated for a nut of size such as M24.

Compare that to a grade 8 nut of regular size – would have normally been made from a low alloyed steel, followed by heat treatment operation. This would result in a much stronger nut, with much high proof load strength to be obtained.

Micro evaluation of the nut established that the nut had been supplied in the NON heat treated condition i.e. Displayed a ferrite and pearlite structure and not that of the tempered martensitic structure that would have been evident for a grade 8 nut.

Quote from BS EN ISO 898-2:2012

Section 6 Materials – Nuts with fine pitch thread and property classes 05,6 (with D>M16), 8 {regular nuts (Style 1)}, 10 and 12 shall be quenched and tempered (Heat treated condition).

BS EN ISO 898-2:2012 Table 2

Also identifies the maximum property class of mating bolt, screw or stud for a given nut grade.

This for a grade 10.9 stud (as supplied in the fixing kit) then the correct nut to be used would be a grade 10 Nut of regular size (Style 1)

From BS EN ISO 898-2:2012

### Section 5 Design of bolt and nut assemblies

Regular nuts (Style 1) and high nuts (Style 2) shall be material with externally threaded fasteners according to table 2. However, nuts of a higher property class may replace nuts of lower property class.

Unfortunately this was not the case with the fixing kit supplier in that a much lower grade of nut was used.

Grade 10 nut or high grade 12 nut should have been selected for a 10.9 grade stud assembly.

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.  
Without the embossed stamp mark on this test report it is not the original.  
The tests are carried out to the most up to date standards where possible.  
The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.  
Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified  
The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.  
Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.



Unit 11, Planetary Road Industrial Estate  
Willenhall, Wolverhampton  
West Midlands  
WV13 3XA

Tel: 01902 305200  
Fax: 01902 303200  
Email: willenhall@caparotesting.com



**CTT: Willenhall**  
A Division of Caparo Engineering Limited

**LABORATORY INVESTIGATION REPORT**

Date Received/Tested ..... 21<sup>st</sup> July 2015 ..... (Page ..... 6 ..... of ..... 9 ..... )  
 Customer ..... Marine Accident Investigation ..... Enquiry from ..... [REDACTED] .....  
 Address ..... Spring Place, 105 Commercial Road, Southampton, SO15 1GH .....  
 Certificate No. .... PEJ168 ..... Order No. .... N/A ..... Customers Ref. No. .... N/A .....  
 Material Specification ..... ISO 898-2 GRADE 8 ..... Dimensions ..... M24 Nyloc Nut .....

Incorrect identification of nut and incorrect material grade of nut was the cause of threads of the nut to fail.

See Photos below

Signed for and on behalf of CTT: Willenhall:


[REDACTED SIGNATURE]

- [REDACTED] - Chief Chemist
- [REDACTED] - General Manager
- [REDACTED] - Operations Manager


**Date of Signing:** 24 July 2015

DECARBURISATION, MICROSTRUCTURE AND MACROSTRUCTURE ARE CURRENTLY OUTSIDE THE SCOPE OF OUR UKAS ACCREDITATION

N.B. Opinions and interpretations based on test results are outside the scope of UKAS Accreditation.  
 Without the embossed stamp mark on this test report it is not the original.  
 The tests are carried out to the most up to date standards where possible.  
 The results on this Test Certificate do not in anyway confer approval of the quality of Manufacture of the Material.  
 Results obtained from testing that that has been subcontracted to an alternative UKAS laboratory shall be clearly identified  
 The test results on this report only relate to the item(s) submitted for testing on the Purchase Order detailed.  
 Document Control No. 22. Laboratory Investigation Report. Issue No.: 1, Issue Date: October 2013.



**PHOTO 1 X 500 MAGNIFICATION – SURFACE COATING OF THREADED PROFILE**



**PHOTO 2 X 100 MAGNIFICATION – COATING THICKNESS EXTERNAL SURFACE**






PHOTO 3 - ETCHED IN 50% HCL



PHOTO 4 - FERRITE/PEARLITE STRUCTURE X100 MAGNIFICATION






PHOTO 5 - FERRITE/PEARLITE STRUCTURE X500 MAGNIFICATION




PHOTO 6 - X100 MAGNIFICATION – SURFACE PROFILE OF THREAD

Report from Bolt Science on the failure of the Holding Down Fasteners

***Report on the Failure  
of the  
Holding Down Fasteners on a Crane***

Report completed for  
Marine Accident Investigation Branch

Report completed by:

██████████ *CEng BSc PhD MIMechE*

Bolt Science Limited  
([www.boltscience.com](http://www.boltscience.com))  
6 October 2015

This report is based upon the particular instructions and requirements of our client, it is personal to the client, confidential and non-assignable. It is not intended for and should not be relied upon by any third party and no responsibility is undertaken to any third party.

This report shall not be reproduced, except in full, without the written approval of Bolt Science Limited. Where our instructions consist exclusively of testing samples, the results and our conclusions relate only to the samples tested.



# Report on the Failure of Holding Down Fasteners on a Crane

## Contents

---

1. Abstract and Introduction.....	2
2. Details of the Installation/Joint .....	3
3. Loading acting on the fasteners at the time of the accident. ....	5
4. Thread Stripping Calculations.....	6
5. Torque-Preload Calculations .....	9
Introduction.....	9
Nuts tightened to 600 Nm .....	10
Nuts tightened to 350 Nm .....	11
6. Discussion/Conclusions.....	12

## 1. Abstract and Introduction

---

My understanding is that a number of fasteners failed that were holding down a crane to its foundation. The holding down fasteners consisted of two rows of M24 property class 10.9 studs, each row having 4 sets of fasteners. The studs had M24 x 2 (fine pitch series) threads. On each stud two nuts were located under the foundation with a single, thin, non-metallic prevailing torque type ('Nyloc') nut used to tighten the stud.

A summary of the results of the calculations completed in this report are:

Calculated thread stripping load for the nut:	254 kN
Anticipated preload range with a tightening torque of 600 Nm	139 to 231 kN
Anticipated preload range with a tightening torque of 350 Nm	48 to 133 kN
Load acting on a single bolt due to lifting the load at the point of failure	90.6 kN

Since the applied force from lifting is significantly lower than the anticipated thread stripping load, then either one or more of the points below likely applies:

1. One or more of the nut threads had been partially stripped (sheared) by the tightening process, the applied loading subsequently sustained being sufficient to completely shear the threads.
2. The thread tolerances are not as assumed in the analysis, that is, the thread dimensions were outside normal practice.
3. The deformation of the washers resulted in the force needed to strip the threads being reduced.
4. The fasteners were not evenly loaded due to the orientation of the applied load or due to some fasteners being only partially tight.

The thread tolerances that have been used in this report are based upon industry standard practices but it is unknown at the time of writing what are the thread dimensions of the nuts and bolts involved in this accident. Thread dimensions have a significant influence on the thread stripping characteristics.


It is uncertain whether the collapse of the washer occurred during tightening or was damaged during the collapse of the crane. If the deformation of the washer occurred when the nuts were initially tightened, which is a distinct possibility, it would point towards the preload in the fastener being high. The large gap under the washer would also result in bending stresses being incurred by the washer in addition to the direct bearing stresses. If the washer distorted during tightening, an uneven loading would occur in the threads resulting in thread stripping load being lowered. Such loading is not represented in a standard proof load test or in the calculations presented in this report. The author has previously observed such a reduction on an offset pull test on a fine threaded fastener.

It is good practice for the nuts to be as strong, or stronger, than the bolts to avoid the risk of thread stripping if the nuts are over-tightened. That is, considering that property class 10.9 bolts had used in this application, full height property class 10 nuts should have been used.

## Report on the Failure of Holding Down Fasteners on a Crane

### 2. Details of the Installation/Joint

My understanding is that a number of fasteners failed that were holding down a 170.2 VCS crane to its foundation. The holding down fasteners consisted of two rows of M24 property class 10.9 studs, each row having 4 sets of fasteners. The studs had M24 x 2 (fine pitch series) threads. The arrangement of the assembly and the joint is shown in figure 1. On each stud two nuts were located under the foundation with a single thin non-metallic prevailing torque type ('Nyloc') nut used to tighten the stud. My understanding is that the nut was to the standard DIN 985<sup>1</sup>. The key dimensions of the nut, taken from the DIN standard are shown in figure 2.




<sup>1</sup> DIN 985 Prevailing torque type thin nuts with nonmetallic insert.



## Report on the Failure of Holding Down Fasteners on a Crane

My understanding is that when the crane was lifting a weight of 2.2 tonnes, the nuts on one side failed by thread stripping allowing the crane to topple.



Based upon a metallurgical investigation report<sup>2</sup>, a hardness survey revealed that the hardness was 225 HV10. From BS EN ISO 18265 this hardness corresponds to a tensile strength of 720 MPa.


As can be seen in figure 3, one or more of the washers had been severely distorted, before or as a result of the accident.



<sup>2</sup> The report has been redacted - no reference available at the time of writing.

### 3. Loading acting on the fasteners at the time of the accident.

Just prior to the failure, the fasteners would sustain the load/moment from the crane as direct axial forces. On the side which the fasteners failed the loading would be tending to push the nut off the stud. The assumed dimensions, to allow an estimate of the axial force acting on an individual fastener are shown in figure 4.



Taking moments about the front reaction point  $F_f$  gives:

$$2.2(9500 - 276) + 1.7(4750 - 276) = 755 \times F_r$$

$$F_r = 36.95 \text{ tonne} = 362497 \text{ N}$$

The load per fastener would be  $362497 / 4 = 90624 \text{ N}$

#### 4. Thread Stripping Calculations

---

Thread stripping is a failure mode that is best avoided since it may go unnoticed at the time of assembly. It starts at the first engaged thread, due to thread deformations causing it to carry the highest load and successively shears off subsequent threads. This may take several hours to complete and so may appear fine at the time of assembly. The risk is therefore present that a defective product may enter service. In this application, because of the short length of engagement and the material used for the internal thread being substantially weaker than the external thread, overtightening the bolt could cause thread stripping to occur.

Thread stripping strength depends upon the area of the thread being stripped and the shear strength of the thread material. The calculations will be based upon the work of Alexander<sup>3</sup>, his work is also used in VDI 2230. The stripping strength of the external thread is, in general, different to the stripping strength of the internal thread. The thread stripping strengths are:

$$F_{int} = AS_s \cdot \tau_{int} \cdot C1 \cdot C3$$

$$F_{ext} = AS_n \cdot \tau_{ext} \cdot C1 \cdot C2$$

Where

- $F_{int}$  = Stripping strength of the internal thread
- $F_{ext}$  = Stripping strength of the external thread
- $T_{int}$  = Shear strength of the internal thread material
- $T_{ext}$  = Shear strength of the external thread material
- UTS = Tensile strength of the thread
- $AS_s$  = Shear area of the external thread
- $AS_n$  = Shear area of the internal thread
- Shear Ratio = Ratio of the shear to tensile strengths.
- C1 = Nut dilation factor
- C2 = Thread bending factor for external threads
- C3 = Thread bending factor of internal threads

The shear areas can be calculated using the equations shown below. For the external thread:

$$AS_s = \frac{\pi}{p} \cdot LE \cdot D_{1max} \left( \frac{p}{2} + 0.57735(d_{2min} - D_{1max}) \right)$$

and for the internal thread

$$AS_n = \frac{\pi}{p} \cdot LE \cdot d_{min} \left( \frac{p}{2} + 0.57735(d_{min} - D_{2max}) \right)$$

Where:

- p = Thread Pitch mm
- LE = Length of Thread Engagement mm
- $D_{1max}$  = Maximum minor diameter of the internal thread mm
- $D_{2max}$  = Maximum pitch diameter of the internal thread mm
- $d_{2min}$  = Minimum pitch diameter of the external thread mm
- $d_{min}$  = Minimum major diameter of the external thread mm

No information has been provided as to the tolerance classes of the male or female thread. Standard practice is to use a 6g tolerance class for the bolt thread and a 6H tolerance class for the nut thread. My

---

<sup>3</sup> Alexander, E.M., *Analysis and design of threaded assemblies*. 1977 SAE Transactions, Paper No. 770420

## Report on the Failure of Holding Down Fasteners on a Crane

understanding is that the major diameter of the bolt thread is within the tolerance band for a 6g tolerance class. Based upon a 6g/6H tolerance class combination, the thread details are:

Parameter	Symbol	Formula	Value
Basic major diameter	d	Nominal size	24
Thread Pitch	p	pitch	2
Basic pitch diameter	d <sub>2</sub>	d - 0.6495p	22.701
Basic minor diameter	d <sub>1</sub>	d - 1.0825p	21.835

### External Thread M24 x 2 6g

Maximum Major Dia.	23.962 mm
Minimum Major Dia.	23.682 mm
Maximum Pitch Dia.	22.663 mm
Minimum Pitch Dia.	22.493 mm
Maximum Minor Dia.	21.835 mm
Minimum Minor Dia.	21.261 mm

### Internal Thread M24 x 2 6H

Minimum Major Dia.	24.000 mm
Maximum Pitch Dia.	22.925 mm
Minimum Pitch Dia.	22.701 mm
Maximum Minor Dia.	22.210 mm
Minimum Minor Dia.	21.835 mm

The ISO 898-1 standard specifies the mechanical property requirements for a bolt of property class 10.9:

Minimum Tensile Strength	1040 N/mm <sup>2</sup>
Maximum Hardness	39 HRC
Maximum Tensile Strength	1230 N/mm <sup>2</sup> (note this is the conversion 39 HRC <sup>4</sup> )
Ratio of the shear to tensile strength	0.62 <sup>5</sup>
Minimum Bolt Shear Strength	645 N/mm <sup>2</sup>

Based upon a laboratory report<sup>6</sup>, the nut hardness was measured as 225 HV10. From BS EN ISO 18265, this hardness converts to a tensile strength of 720 N/mm<sup>2</sup>. Taking the ratio of shear to tensile strength as being 0.65<sup>7</sup> gives a shear strength of 468 N/mm<sup>2</sup>.

Figure 2 shows the overall dimensions of the nut taken from DIN 985<sup>8</sup>. This standard shows that the bearing face is countersunk. The countersink region will not be effective in carrying load when compared to the full thread. The diameter of the countersink has a maximum diameter of 25.9 mm. Alexander allowed 40% effectiveness for the height of the countersink. Assuming countersinking on the bearing face side only, the height of the countersink section will be:

$$LE = 15 - \left[ \frac{25.9 - 21.835}{2} \right] (1 - 0.4) = 13.78 \text{ mm}$$

Based upon research reported by Alexander, part of the nut thread can be bell-mouthed. Bell-mouthing is partial tapering of the tapped hole due to instability of the drill as it first creates the hole. Bell-mouthing affects the shear strength of the bolt thread. This can be accounted for by varying the diameter over

<sup>4</sup> The standard: *BS EN ISO 18265: 2003 - metallic materials - conversion of hardness values*, was used to convert the hardness value to an approximate tensile strength.

<sup>5</sup> Taken from table 7 for a property class 10.9 bolt in *VDI 2230 Part 1 (December 2014) Systematic calculation of highly stressed bolted joints. Joints with one cylindrical bolt*

<sup>6</sup> The report has been redacted - no reference available at the time of writing.

<sup>7</sup> Table 6 in *VDI 2230 Part 1 (December 2014) Systematic calculation of highly stressed bolted joints. Joints with one cylindrical bolt* quotes the shear ratio as being between 0.65 to 0.85 for heat treatable steel.

<sup>8</sup> The nuts are stated to be to DIN 985 by the laboratory report provided to the author.

## Report on the Failure of Holding Down Fasteners on a Crane

discreet increments. The maximum degree of bell-mouthing is approximately 1.03 times the minor diameter and can be accounted for by employing the mean diameter over the length of bell-mouthing. The length of the bell-mouthed section LB is typically taken as being 0.5 d where d is the nominal thread diameter. The mean diameter of the bell mouthed section of the nut  $D_m$  is:

$$D_m = \frac{(D_1 + 1.03D_1)}{2} = \frac{(21.835 + 1.03 \times 21.835)}{2} = 22.163 \text{ mm}$$

The internal thread shear area will be:

$$AS_n = \frac{\pi}{p} \cdot LE \cdot d_{\min} \left( \frac{p}{2} + 0.57735(d_{\min} - D_{2\max}) \right)$$

$$AS_n = \frac{\pi}{2} \times 13.78 \times 23.682 \left( \frac{2}{2} + 0.57735(23.682 - 22.925) \right) = 736.65 \text{ mm}^2$$

The external shear area will be:

$$AS_s = \frac{\pi}{p} \cdot LE \cdot D_{1\max} \left( \frac{p}{2} + 0.57735(d_{2\min} - D_{1\max}) \right) = \frac{\pi}{2} \times 13.78 \times 22.210 \left( \frac{2}{2} + 0.57735(22.493 - 22.210) \right) = 559.3 \text{ mm}^2$$

Under load the bearing face of the nut expands radially. This nut dilation is due to the wedging action of the 60 degree threads which has the effect of increasing the minor diameter and reducing the effect shear areas of both the nut and bolt. Alexander accounted for this effect by the use of a nut dilation factor C1.

The nut dilation factor C1 is determined using the following equation:

$$C1 = \left[ -\left(\frac{S}{D}\right)^2 + 3.8\left(\frac{S}{D}\right) - 2.61 \right] \quad \text{for } 1.4 \leq \frac{S}{D} < 1.9 \quad \frac{S}{D} \text{ is the width across flats to nom. dia.}$$

For this nut:  $S/D = 35/24 = 1.458$

$$C1 = \left[ -\left(\frac{S}{D}\right)^2 + 3.8\left(\frac{S}{D}\right) - 2.61 \right] = \left[ -(1.458)^2 + 3.8(1.458) - 2.61 \right] = 0.805$$

The thread bending factor for internal threads C3 can be determined from the following equation:

$$C3 = 0.728 + 1.769R_s - 2.896R_s^2 + 1.296R_s^3 \quad \text{for } 0.4 < R_s < 1$$

$$C3 = 0.897 \quad \text{for } R_s \geq 1$$

The strength ratio  $R_s$  is defined as:  $R_s = \frac{(\sigma_n AS_n)}{(\sigma_s AS_s)}$

where  $\sigma_n$  is the tensile strength of the nut and  $\sigma_s$  is the tensile strength of the bolt. Substituting values gives:

$$R_s = \frac{(\sigma_n AS_n)}{(\sigma_s AS_s)} = \frac{(720 \times 736.65)}{(1040 \times 559.3)} = 0.912$$

Using this value to determine the C3 factor:

$$C3 = 0.728 + 1.769 \times 0.912 - 2.896 \times 0.912^2 + 1.296 \times 0.912^3 = 0.916$$

The force needed to strip the internal thread will be:



## Report on the Failure of Holding Down Fasteners on a Crane

$$F_{\text{int}} = AS_s \cdot \tau_{\text{int}} \cdot C1 \cdot C3 = 736.65 \times 468 \times 0.805 \times 0.916 = 254213 \text{ N}$$

Since it has been found that nut dilation more readily occurs when the threads are rotating, the thread stripping load achieved when a nut is being tightened can be less than that which would be achieved by a proof load type of test.

### 5. Torque-Preload Calculations

---

#### Introduction

The mathematical model relating the applied torque and tension in the bolt (preload) is generally given by:

$$T = \frac{F}{2} \left[ \frac{p}{\pi} + \frac{\mu_t d_2}{\cos \beta} + D_e \mu_n \right]$$

This can be simplified for metric and Unified thread forms to:

$$T = F \left[ 0.15915 p + 0.57735 \mu_t d_2 + \frac{D_e \mu_n}{2} \right]$$

$$\text{with } D_e = \frac{d_o + d_i}{2}$$

where

T	Total tightening torque
F	Bolt preload
$\mu_t$	Coefficient of friction for the threads
d	Nominal major diameter of the thread i.e. for a M24 thread d=24mm
$d_2$	The basic pitch diameter of the thread. For metric threads $d_2=d-0.6495p$
$\beta$	The half included angle for the threads
p	Pitch of the thread.
$\mu_n$	Coefficient of friction for the nut face or bolt head
$D_e$	The effective bearing diameter of the nut
$d_o$	The outer bearing diameter of the nut
$d_i$	The inner bearing diameter of the nut face

My understanding is that the nuts were tightened to 600 Nm. The torque specified by the manufacturer is 350 Nm. The major unknown in determining the bolt preload that would result from the tightening torque is the value of the coefficient of friction. This nut had a prevailing torque created by a non-metallic (polymer) insert. My understanding is that the nuts had a zinc coating. Such nuts can be provided with a light coating of lubricant, often wax, to prevent galling.

Based upon VDI 2230, galvanic coatings such as the zinc coating used in this application would fall into friction coefficient class B (friction coefficient range 0.08 to 0.16) if a lubricant had been used and into friction coefficient class C (friction coefficient range 0.14 to 0.24) without a lubricant.

The countersink diameter of the nut is 25.9 mm diameter which would be the inner bearing diameter (my understanding is that the tab washer has a hole diameter of 25 mm). The outer bearing diameter is taken as 33.2 mm.

$$\text{The effective bearing diameter is: } D_e = \frac{d_o + d_i}{2} = \frac{33.2 + 25.9}{2} = 29.55 \text{ mm}$$

The torque-tension equation can be adjusted to allow for the prevailing torque that the nut will possess and can be transposed to give:

## Report on the Failure of Holding Down Fasteners on a Crane

$$F = \frac{T - T_p}{\left[ 0.15915p + 0.57735\mu_t d_2 + \frac{D_e \mu_n}{2} \right]}$$

Where  $T_p$  is the prevailing torque of the nut. My understanding is that there is no information on the actual prevailing torque of the nut. The standard BS EN ISO 2320<sup>9</sup> provides some details as to the likely value of the prevailing torque on first tightening. For a M24 property class 6 nut, the specified maximum first installation prevailing torque for a non-metallic insert type nut is 40 Nm with the minimum first removal torque being 11.5 Nm. From experience of testing this type of nut, in practice, the prevailing torque displayed by this type of nut tends to be closer to the first removal torque. Hence in these calculations a prevailing torque of 11.5 Nm will be assumed.

Whether a thin or normal height type of nut is used does not make a difference to the torque-tension relationship if it is assumed that the coefficient of friction is the same in both circumstances. Also, if it is assumed that the coefficient of friction is the same, whether a plain nut or one having a nut with a prevailing torque is used makes only a small difference in the preload. (This is due to the prevailing torque normally being only a small fraction of the overall tightening torque.)

### Nuts tightened to 600 Nm

For a tightening torque of 600 Nm with a coefficient of friction of 0.08, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[ 0.15915p + 0.57735\mu_t d_2 + \frac{D_e \mu_n}{2} \right]} = \frac{[600 - 11.5] \times 1000}{\left[ 0.15915 \times 2 + 0.57735 \times 0.08 \times 22.701 + \frac{29.55 \times 0.08}{2} \right]} = 230919$$

For a tightening torque of 600 Nm with a coefficient of friction of 0.14, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[ 0.15915p + 0.57735\mu_t d_2 + \frac{D_e \mu_n}{2} \right]} = \frac{[600 - 11.5] \times 1000}{\left[ 0.15915 \times 2 + 0.57735 \times 0.14 \times 22.701 + \frac{29.55 \times 0.14}{2} \right]} = 139409$$

For a tightening torque of 600 Nm with a coefficient of friction of 0.24, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[ 0.15915p + 0.57735\mu_t d_2 + \frac{D_e \mu_n}{2} \right]} = \frac{[600 - 11.5] \times 1000}{\left[ 0.15915 \times 2 + 0.57735 \times 0.24 \times 22.701 + \frac{29.55 \times 0.24}{2} \right]} = 83957$$

The stress area ( $A_s$ ) of the thread can be calculated from:

$$A_s = 0.7854(d - 0.9382p)^2 = 0.7854(24 - 0.9382 \times 2)^2 = 384.4 \text{ mm}^2$$

Hence the above loadings represent a direct stress in the bolt threads of between:

$$\sigma = \frac{230919}{384.4} = 600.7 \text{ N/mm}^2 \quad \text{to} \quad \frac{83957}{384.4} = 218.4 \text{ N/mm}^2$$

These stresses represent a utilisation of the minimum yield strength (the 0.2% non-proportional limit) for a property class 10.9 bolt of between 23% to 64%.

<sup>9</sup> BS EN ISO 2320 - Prevailing torque type steel hexagon nuts - mechanical and performance requirements

## Report on the Failure of Holding Down Fasteners on a Crane

The bearing stress would be:  $\sigma = \frac{230919}{\frac{\pi}{4}(33.2^2 - 25.9^2)} = 681 \text{ N/mm}^2$  to  $\frac{83957}{\frac{\pi}{4}(33.2^2 - 25.9^2)} = 248 \text{ N/mm}^2$

### Nuts tightened to 350 Nm

Repeating the above calculations with a torque of 350 Nm gives:

For a tightening torque of 350 Nm with a coefficient of friction of 0.08, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[0.15915p + 0.57735\mu_r d_2 + \frac{D_e \mu_n}{2}\right]} = \frac{[350 - 11.5] \times 1000}{\left[0.15915 \times 2 + 0.57735 \times 0.08 \times 22.701 + \frac{29.55 \times 0.08}{2}\right]} = 132807 \text{ N}$$

For a tightening torque of 350 Nm with a coefficient of friction of 0.14, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[0.15915p + 0.57735\mu_r d_2 + \frac{D_e \mu_n}{2}\right]} = \frac{[350 - 11.5] \times 1000}{\left[0.15915 \times 2 + 0.57735 \times 0.14 \times 22.701 + \frac{29.55 \times 0.14}{2}\right]} = 80181 \text{ N}$$

For a tightening torque of 350 Nm with a coefficient of friction of 0.24, the bolt preload F would be:

$$F = \frac{T - T_p}{\left[0.15915p + 0.57735\mu_r d_2 + \frac{D_e \mu_n}{2}\right]} = \frac{[350 - 11.5] \times 1000}{\left[0.15915 \times 2 + 0.57735 \times 0.24 \times 22.701 + \frac{29.55 \times 0.24}{2}\right]} = 48289 \text{ N}$$

Hence the above loadings represent a direct stress in the bolt threads of between:

$$\sigma = \frac{132807}{384.4} = 345 \text{ N/mm}^2 \quad \text{to} \quad \frac{48289}{384.4} = 126 \text{ N/mm}^2$$

These stresses represent a utilisation of the minimum yield strength (the 0.2% non-proportional limit) for a property class 10.9 bolt of between 13% to 37%.

The bearing stress would be:  $\sigma = \frac{132807}{\frac{\pi}{4}(33.2^2 - 25.9^2)} = 392 \text{ N/mm}^2$  to  $\frac{48289}{\frac{\pi}{4}(33.2^2 - 25.9^2)} = 143 \text{ N/mm}^2$

### 6. Discussion/Conclusions

---

A summary of the results of the calculations completed in this report are:

Calculated thread stripping load for the nut:	254 kN
Anticipated preload range with a tightening torque of 600 Nm	139 to 231 kN
Anticipated preload range with a tightening torque of 350 Nm	48 to 133 kN
Load acting on a single bolt due to lifting the load at the point of failure	90.6 kN

Since the applied force from lifting is significantly lower than the anticipated thread stripping load, then either one or more of the points below applies:

1. One or more of the nut threads had been partially stripped (sheared) by the tightening process, the applied loading subsequently sustained being sufficient to completely shear the threads.
2. The thread tolerances are not as assumed in the analysis, that is, the thread dimensions were outside normal practice.
3. The deformation of the washers resulted in the force needed to strip the threads being reduced.
4. The fasteners were not evenly loaded due to the orientation of the applied load or due to some fasteners being only partially tight.

The thread stripping calculations presented in this report are based upon Alexander's theory. To quote from BS EN ISO 898-2: 2014<sup>10</sup>: "*Extensive experimental tests proved Alexander's theory through practical results. Actual studies, including FEM-based calculations, confirmed Alexander's theory.*"

The thread tolerances that have been used in this report are based upon industry standard practices but it is unknown at the time of writing what are the thread dimensions of the nuts and bolts involved in this accident. Thread dimensions have a significant influence on the thread stripping characteristics.

It is uncertain whether the collapse of the washer occurred during tightening or was damaged during the collapse of the crane. If the deformation of the washer occurred when the nuts were initially tightened, which is a distinct possibility, it would point towards the preload in the fastener being high. My understanding is that the washer is made from mild steel. The limiting surface pressure for mild steel depends upon the specific steel used. For a low strength mild steel (tensile strength 340 N/mm<sup>2</sup>), the limiting surface pressure<sup>11</sup> is 490 N/mm<sup>2</sup>. This would point towards the preload value approaching or exceeding the thread stripping load.

The large gap under the washer would also result in bending stresses being incurred by the washer in addition to the direct bearing stresses. If the washer distorted during tightening an uneven loading would occur in the threads, resulting in the thread stripping load being lowered. Such loading is not represented in a standard proof load test or in the calculations presented in this report. The author has previously observed such a reduction on an offset pull test on a fine threaded fastener.

It is unknown whether all the nuts were tight, if one or more were loose this could result in the remaining fasteners sustaining a disproportionate share of the applied force from the lifting operation. This could result in the failure of the highest loaded fastener followed by load shedding, resulting in the failure of subsequent fasteners. Since thread shearing requires displacement of at least half the thread pitch, the load shedding hypothesis is a possibility but not probable in the author's view.

Fasteners of property class 10.9 and above are susceptible to hydrogen embrittlement and stress corrosion cracking. It is unknown to the author why property class 10.9 bolts are being used in an application where there is the potential for stress corrosion cracking to occur. At the 350 Nm specified torque level a property class 8.8 bolt would have been suitable, such bolts are not susceptible to hydrogen embrittlement.

---


<sup>10</sup> ISO 898-2 - 2012 Mechanical properties of fasteners made of carbon steel and alloy steel – Nuts with specified property classes – Coarse thread and fine pitch thread

<sup>11</sup> From table A9, VDI 2230 Part 1 (December 2014) *Systematic calculation of highly stressed bolted joints. Joints with one cylindrical bolt*

## ***Report on the Failure of Holding Down Fasteners on a Crane***

It is good practice for the nuts to be as strong, or stronger, than the bolts to avoid the risk of thread stripping if the nuts are over-tightened. That is, considering that property class 10.9 bolts had used in this application, full height property class 10 nuts should have been used.



 CEng FIMechE BSc PhD  
Bolt Science Limited



Advisory Notice issued by the National Workboat Association



## Advice, Award and Reminders

1 message

**National Workboat Association** <secretary@workboatassociation.org>

20 November 2015 at  
11:14

Reply-To: secretary@workboatassociation.org

To: secretary@workboatassociation.org

If you are having difficulties reading this email, [click here](#)



Tel: +44 (0) 1430 470013



### **NWA Advisory Notice to Owners / Operators of Coded Workboats**

As a result of independent investigations into several recent incidents concern has been raised that modifications and/or additions have been made to Code vessels without any reference to the Certifying Authority responsible for that vessel's coding. We have been asked by the MCA and MAIB to issue this advice:-

Owners and Operators are reminded of their responsibility under both MGN 280 and the revised Workboat Code, to "notify and seek approval from the Certifying Authority prior to implementing any change or modification to the vessel." – see Ch 27.11.5 of the revised code. Recent incidents have shown that even apparently minor alterations can have a serious effect on the stability and/or the safe operation of the vessel.

Whilst writing, we would also remind you that it is the Owner / Operator's responsibility to advise the Certifying Authority when a vessel is due for its next certification survey, to ensure the vessel is made available for survey and to ensure the certification is maintained in date.

### **Award in Maritime Studies: Use of Radar and Electronic Chart Systems in Code Vessels**

This award has been created at the request of the NWA and MSA for those candidates who have

undertaken the following courses;-

*"Use of Radar for Safe Navigation and Collision Avoidance on Domestic and Code Vessels"*

*"Operate non-ECDIS marine Electronic Chart Systems"*

As you should be aware both these courses are strongly recommended under the revised Workboat Code and will become a requirement within 3 years. These courses are run separately as 3 days each, or can be run concurrently as a 5 day course. One of our Associate members, MARITAS, has been running these courses as their 'RADECS' course for some time and will now be the first training provider to gain approval to be able to offer this award as part of the course certification. Anyone interested in getting crew members onto these courses, or hosting a course at your premises should contact [REDACTED] at MARITAS – [dc@maritas.co.uk](mailto:dc@maritas.co.uk)

Hopefully, other Training Providers will be looking to offer this course going forward as there will be significant demand once the revised Workboat Code is published in the near future.

#### **Reminder – Have you Booked you Room(s) for the Annual Dinner/AGM 21st/22nd January?**

We had a good early flush of room bookings following the last Newsletter ref the Annual Dinner and AGM to be held at the Lakeside on 21st/22nd January, but we know there are quite a few regular attendees and new members who have not yet booked – I would encourage you to put your booking through to me – [secretary@workboatassociation.org](mailto:secretary@workboatassociation.org) - sooner rather than later, as we do not want anyone to be disappointed.

– and if that is not sufficient warning for you . [REDACTED] says – if you haven't booked by the time I give him the list in a week or so, he'll be chasing you himself!! – you have been warned!

#### **And Lastly, Don't Forget - Safety Forum – Weds 25th November at Hoylake Sailing School**

Secretary

DISCLAIMER: The information in this message is confidential and may be legally privileged. It is intended solely for the addressee. Access to this message by anyone else is unauthorised. If you are not the intended recipient, any disclosure, copying, or distribution of the message, or any action or omission taken by you in reliance on it, is prohibited and may be unlawful. Please delete the message immediately. Thank you.

This email has been sent to the email address: [secretary@workboatassociation.org](mailto:secretary@workboatassociation.org)

To unsubscribe from any more newsletters from National Workboat Association, please click this link and you will be immediately removed: [Unsubscribe](#)

2015 © National Workboat Association | Powered by [BlueBox™](#)