

## CONTENTS

### SPECIAL BULLETINS / INTERIM REPORTS

None

### SUMMARIES OF AIRCRAFT ACCIDENT ('FORMAL') REPORTS

None

### AAIB FIELD INVESTIGATIONS

#### COMMERCIAL AIR TRANSPORT

##### FIXED WING

None

##### ROTORCRAFT

None

#### GENERAL AVIATION

##### FIXED WING

None

##### ROTORCRAFT

|                   |        |           |   |
|-------------------|--------|-----------|---|
| Robinson R22 Beta | G-CHZN | 06-Jan-12 | 3 |
|-------------------|--------|-----------|---|

#### SPORT AVIATION / BALLOONS

|                   |        |           |    |
|-------------------|--------|-----------|----|
| Schleicher ASW 24 | G-CGDU | 30-Apr-12 | 43 |
|-------------------|--------|-----------|----|

### AAIB CORRESPONDENCE INVESTIGATIONS

#### COMMERCIAL AIR TRANSPORT

|                  |        |           |    |
|------------------|--------|-----------|----|
| Airbus A319-111  | G-EZDN | 04-Jul-12 | 51 |
| Airbus A320-214  | G-MRJK | 30-May-12 | 53 |
| Boeing 757-2K2   | G-LSAN | 07-Aug-12 | 57 |
| Hawker Hunter T7 | G-VETA | 16-Sep-12 | 63 |
| Sikorsky S-76C   | G-CGOU | 26-Sep-12 | 66 |

#### GENERAL AVIATION

|                      |        |           |    |
|----------------------|--------|-----------|----|
| AS350B2 Ecureuil     | G-BXGA | 16-Oct-12 | 68 |
| AS350B2 Ecureuil     | G-ORKY | 08-Oct-12 | 70 |
| Cessna F172H Skyhawk | G-CGRE | 18-Aug-12 | 72 |
| Cessna 172S Skyhawk  | D-EFUC | 02-Aug-12 | 73 |
| CZAW Sportcruiser    | G-CFNV | 11-Aug-12 | 74 |

## AAIB CORRESPONDENCE INVESTIGATIONS (Cont)

### GENERAL AVIATION (Cont)

|                            |        |           |    |
|----------------------------|--------|-----------|----|
| Focke Wulf (Piaggio) P149D | D-EARY | 17-Nov-12 | 75 |
| Jodel D120 Paris-Nice      | G-ATLV | 21-Oct-12 | 76 |
| Mooney M20J                | N12ZX  | 08-Sep-12 | 77 |
| Percival Proctor 3         | G-ALJF | 24-Jul-12 | 80 |
| Piper PA-25-235 Pawnee     | G-BFEV | 18-Aug-12 | 82 |
| Piper PA-38-112 Tomahawk   | D-EIBR | 03-Nov-12 | 83 |
| Robin DR400/500 President  | G-VIRR | 15-Oct-12 | 85 |
| Robinson R22 Beta          | G-BTHI | 14-Aug-12 | 87 |
| Rotorway Executive 162F    | G-FLIT | 26-Aug-12 | 89 |

### SPORT AVIATION / BALLOONS

|                               |        |           |    |
|-------------------------------|--------|-----------|----|
| Escapade 912(1)               | G-CDKL | 22-Sep-12 | 93 |
| Mainair Blade                 | G-MZED | 22-Sep-12 | 94 |
| Pegasus Quantum 15            | G-MYRN | 17-Nov-12 | 95 |
| Rotorsport UK MT-03 gyroplane | G-CFKA | 31-Jul-12 | 96 |

## MISCELLANEOUS

### ADDENDA and CORRECTIONS

|                    |        |           |     |
|--------------------|--------|-----------|-----|
| Robinson R44 Raven | G-GDOV | 16-May-11 | 101 |
| Thruster T600N 450 | G-CBIO | 17-Jan-12 | 102 |

List of recent aircraft accident reports issued by the AAIB 103

**(ALL TIMES IN THIS BULLETIN ARE UT C)**

**AAIB Field Investigation reports**



**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Robinson R22 Beta, G-CHZN   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming O-320-B2C piston engine  |                   |
| <b>Year of Manufacture:</b>            | 1988 (Serial no: 884)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 6 January 2012 at 1126 hrs  |                   |
| <b>Location:</b>                       | Ely, Cambridgeshire   |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - 1 (Fatal)  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Aircraft destroyed  |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence (Helicopters)   |                   |
| <b>Commander's Age:</b>                | 50 years  |                   |
| <b>Commander's Flying Experience:</b>  | 59 hours (of which 59 were on type) – Helicopters<br>4,960 hours – Aeroplanes<br>Last 90 days - 18 hours<br>Last 28 days - 12 hours |                   |
| <b>Information Source:</b>             | AAIB Field Investigation  |                   |

**Synopsis**

The Robinson R22 helicopter was flying from Manston to Fenland. Near Ely, witnesses on the ground saw it pitch and roll rapidly, the two main rotor blades separated from the rotor head and the aircraft fell to the ground. The pilot was fatally injured.

The accident was caused by main rotor divergence resulting in mast bumping, the rotor blades striking the airframe and rotor blade separation. The report includes Safety Recommendations, to the EASA and the FAA, that refer to the certification requirements for future light helicopters, to reduce the risk of 'loss of main rotor control' accidents.

**History of the flight***Background information*

The pilot of G-CHZN was an experienced fixed-wing pilot with 4,960 hours of flying experience. He held an ATPL(A), and was a Flight Instructor (FI(A)) and examiner. His PPL(H) was issued on 14 December 2011 and he had flown six flights in the Robinson R22 between that date and the date of the accident. The pilot planned to build his helicopter flying hours to gain a CPL(H) and FI(H) and, prior to the accident flight, he had a total time of 58 hours flying helicopters, all of which were in the R22.

### The accident flight

G-CHZN departed from Manston Airport at 0958 hrs for a flight to Fenland Airfield. It climbed to 2,000 feet amsl, passed Whitstable and crossed the Thames estuary tracking towards Southend Airport. Information on the route flown by the helicopter is shown in Figures 1 and 2. When north of the estuary, it descended to approximately 1,500 feet amsl and remained predominantly between 1,200 and 1500 ft amsl for the remainder of the flight. The helicopter continued north towards Earls Colne airfield and, after passing overhead, turned towards Cambridge. At 1056 hrs, the pilot contacted Cambridge Airport

and asked to pass overhead, en route to Fenland. The controller instructed him to report when he was 5 nm from the airport.

The helicopter remained on track for Cambridge Airport until 1105 hrs when it was approximately 12 nm to the south-east, near the town of Haverhill. At this point the pilot turned 30° to the right onto a track of approximately 345°T, which took him towards Newmarket. At 1111 hrs, he reported to the controller that he was “5 MILES TO RUN” and confirmed that he was routing directly towards the overhead of Cambridge Airport. The controller gave the pilot an SSR code and, when he had identified G-CHZN on his radar, informed the pilot that he was




Figure 1

Track derived from GPS unit and radar data




Figure 2

Information relating to the final 20 minutes of flight

10 miles east of Cambridge tracking north. The pilot replied: “AFFIRM, JUST TURNING LEFT”. The controller transmitted that he thought the pilot had been lost and the pilot apologised.

At 1114 hrs, the controller told the pilot of G-CHZN that he would be unable to clear him through the overhead of the airport because of traffic in the circuit. The pilot acknowledged the information and turned towards Fenland. At 1118 hrs, the pilot reported his altitude as “ONE THOUSAND FOUR HUNDRED FEET, QNH 1026”, which was the last radio transmission received from the helicopter.

At 1121 hrs, G-CHZN was on a northerly track when it entered the western stub of the Mildenhall Military Aerodrome Traffic Zone (MATZ). The helicopter was at 1,350 ft amsl and the MATZ stub extended from 1,033 ft to 3,033 ft amsl. At 1123 hrs, approximately 3 nm south of the town of Ely, the pilot turned left towards Fenland and, at 1125:48 hrs, G-CHZN disappeared from radar. Wreckage of the helicopter was found in a field 2 miles south-west of Ely.

### Witness information

Two witnesses were standing approximately 600 m southwest of the accident site. One witness observed the helicopter fly over his farm at what he estimated to be 1,500 ft agl on a heading of approximately 300°(M). While he was watching, he thought the helicopter had started to perform some aerobatics because it suddenly began to roll left. The other witness also saw the helicopter roll to the left, and both heard a “pop as if it was a paper bag you banged in your hands”. Both witnesses also saw objects separate from the helicopter. The helicopter then fell inverted to the ground without rotating about any axis. One of the witnesses thought that the helicopter engine sounded louder than most helicopters but was confident that the engine note was constant until the point when the helicopter rolled. The other witness thought that the helicopter pitched up before it rolled to the left.

A third witness was standing approximately 200 m southwest of the accident site. He heard a “backfire” or a “pop”, which made him look around. He saw a puff of smoke and a few sparks and he thought the body of

the helicopter remained intact. He did not see it roll and he was not aware of any rotor blades detaching from the helicopter.

**Recorded information**


Recorded information was available from radars at Stansted Airport, Debden and Cambridge Airport, a GPS<sup>1</sup> unit from the helicopter, and ground based radio telephony (RTF) recorders. Information from the GPS is shown in Figure 3.

*Radar and GPS information*

The radars at Stansted Airport, Debden and Cambridge Airport are located approximately 29 nm, 23 nm and 11 nm to the south of the accident site and recorded the helicopter’s position at a nominal rate of once every four, six and five seconds respectively. The helicopter’s

transponder was transmitting Mode A information only as the Mode C function was inoperative, thus no altitude record was available from the radar recordings. The final radar positions were between 15 m and 220 m of where the helicopter’s fuselage impacted the ground, with the last recorded position at 1125:48 hrs.

The GPS unit, which was normally attached to the top of the instrument panel in G-CHZN, was found 50 m away from the main wreckage. Although damaged, a track log of the flight was recovered containing aircraft GPS-derived position, track, altitude and groundspeed recorded at a nominal rate of once every thirty seconds. The GPS track log commenced at 0958 hrs as the helicopter departed Manston Airport and ended at 1125:20 hrs. The final GPS position was 875 m to the south-east of where the helicopter’s fuselage impacted



**Figure 3**  
G-CHZN – GPS-derived information

**Footnote**

<sup>1</sup> Honeywell-manufactured Skymap IIIC.



the ground. There was a close correlation between the radar and GPS information.

Navigation using this GPS unit may be performed by programming a route, using the DIRECT TO<sup>2</sup> function, displaying the map, or a permutation of all three functions. Routes are stored within the memory of the GPS but no route had been programmed between Manston Airport and Fenland Airfield. It could not be determined whether the DIRECT TO function was being used or the map was being displayed as these settings were lost when the unit became disconnected from its electrical supply during the accident. Had the map been selected, the Mildenhall MATZ would have been displayed. The unit can provide an aural warning when entering airspace such as a MATZ but this function was selected OFF.

At 1125:20 hrs, the final GPS point was recorded with the helicopter at an altitude of 1,504 ft (approximately 1,480 ft agl) and on a track of 333°. The three radar tracks, which continued beyond the final recording of the GPS, indicated that the helicopter continued on a track of approximately 330° until it disappeared from radar at 1125:48 hrs. Due to the nominal accuracy of the radar and the low recording rate of the GPS unit, it could not be determined whether the helicopter made any sudden manoeuvres during this, or any other period of the flight.

#### *Radio Telephony (RTF) information*

RTF records were available from Manston, Southend and Cambridge Airports. The final series of transmissions were compared with those made earlier in

the flight to determine if there were any inconsistencies or abnormalities in the background sounds that might have been generated by the helicopter's rotor system or engine. No inconsistencies or abnormalities were found.

The pilot did not refer to any problem with the helicopter's controls or engine during any of the radio transmissions.

#### *Mobile phone information*

It was established from mobile phone records that the pilot neither made nor received a phone call or electronic message during the flight.

#### *Information about other aircraft or birds in the vicinity*

Radar records from shortly before the accident were analysed to determine if G-CHZN might have encountered wake turbulence<sup>3</sup> from a nearby aircraft or if the pilot might have been required to alter the helicopter's flight path suddenly to avoid another aircraft, or birds.

When G-CHZN was last recorded by radar at 1125:48 hrs, the nearest aircraft was a Cessna 182 orbiting 2.5 nm ahead of it. The Cessna 182 was at an altitude of 2,600 ft, approximately 1,100 ft above the last recorded altitude of G-CHZN. In the three minutes before the accident, there was no record of any aircraft having flown within 1.7 nm of the accident site at an altitude of less than 10,000 ft. The fact that there was no radar record of any other aircraft in the immediate vicinity of G-CHZN did not exclude the possibility that birds were present.

---

#### **Footnote**

<sup>2</sup> A route may consist of a series of legs interspersed with waypoints, whilst the DIRECT TO function consists of just one flight leg. When the DIRECT TO function is in use, the GPS will display a track line for the pilot to follow. At any time, a new position on the map may be selected using the front-mounted joystick and a new track selected using the DIRECT TO option.

---

#### **Footnote**

<sup>3</sup> Both fixed- and rotary-wing aircraft generate vortices at the wing (or rotor) tips as a consequence of producing lift. The strongest vortices are generated by heavy aircraft flying slowly, and these pose the greatest risk to light aircraft (light is categorised as aircraft weighing less than 17,000 kg). In the most severe case, a complete loss of control may occur.

It is highly unlikely that G-CHZN encountered wake turbulence or that the pilot manoeuvred suddenly to avoid a conflicting aircraft. The possibility that the pilot manoeuvred suddenly to avoid birds could not be discounted.

### **Aviation pathology**

The pilot received fatal injuries when the aircraft struck the ground. Post-mortem examination revealed that he had an undiagnosed medical condition which had the potential to cause intermittent symptoms such as palpitations, anxiety, tremor, headache and nausea, although there was no evidence that he had previously experienced these symptoms. The possibility that he experienced an acute episode of the symptoms in-flight could not be excluded entirely but was considered unlikely.

The pilot had a laceration on the palm of his right hand, which suggested that he was grasping something, most likely the cyclic control, at the time the aircraft struck the ground. This indicated that he was still conscious at the time.

Toxicological tests revealed no evidence of alcohol but no tests were carried out for drugs or carbon monoxide. However, examination of the exhaust manifold in the area of the cabin air heating shroud did not reveal any cracks that would permit a carbon monoxide leak.

### **Weather - Met Office report**

The Met Office produced an assessment of the weather conditions that existed in the area at the time of the accident. A warm front was pushing into the west of the UK under a ridge of high pressure. The weather in the area of the accident was good, with visibility of 30 km or more and little cloud below 25,000 ft. The light, westerly wind did not appear to have been strong enough to generate low

level turbulence. Mountain waves<sup>4</sup> were visible on the satellite picture over the southern Pennines and there was a very small possibility that their influence extended as far south-east as Cambridgeshire leading to areas of light turbulence. It was unlikely, however, that there would have been moderate turbulence at such a distance from the mountains.

Data from the Larkhill radiosonde<sup>5</sup>, launched at 1000 hrs on 6 January 2012, suggested that the temperature in the area of the accident at 1,500 feet amsl was approximately 5°C and the dewpoint was approximately 0°C. Figure 4 shows that moderate or serious carburettor icing is possible at any engine power with this combination of temperature and dewpoint.

### **Aircraft description**

The Robinson R22 Beta is a two-seat light helicopter powered by a four-cylinder carburetted Lycoming O-320-B2C piston engine (Figure 5). It has a standard mechanical collective and cyclic control system with no hydraulic assistance. The main rotor gearbox is driven by the engine via a sheave<sup>6</sup> and belt system and the main rotor consists of two all-metal main rotor blades connected to the main rotor hub by coning bolts at coning hinges<sup>7</sup>. The main rotor hub is mounted to the main rotor shaft with a teeter hinge located above the coning hinges (Figure 6) and blade pitch is

---


#### **Footnote**

<sup>4</sup> A mountain wave is a powerful air mass immediately downstream of a transverse mountain range, rotating about a horizontal axis. There can be a succession of such waves.

<sup>5</sup> Instrumentation for the measurement of atmospheric data, usually temperature, pressure and humidity, carried aloft by balloon.

<sup>6</sup> A sheave is a wheel with a groove for a belt to run on.

<sup>7</sup> The coning hinges are also referred to as flapping hinges. Flapping and coning both refer to motion of the blades about their hinge. 'Flapping' refers to the up and down motion of a single blade about its hinge during one rotation of the main rotor hub. Coning is the upward motion imparted to both blades by the combination of lift and the centrifugal reaction to rotation. The coning angle is the angle between the longitudinal axis of the rotor blade (assuming no blade bending) and the plane described by the path of the rotor tip (the rotor disc plane of rotation).



**Figure 4**


**Carburettor Icing Chart**

*Extract from: CAA Safety Sense Leaflet 14  
Piston Engine Icing*



**Figure 5**

**Accident aircraft - G-CHZN**



**Figure 6**

Robinson R22 Main Rotor Hub and Assembly

controlled by pitch links which connect the pitch horns to the rotating swashplate. The rotating swashplate is moved by the fixed swashplate, which is connected via push-pull tubes to the cyclic and collective controls in the cockpit.

The maximum authorised weight (MAW) of the R22 is 1,370 lb and G-CHZN's weight at the time of the accident was estimated at 1,206 lb (164 lb below the MAW).

#### **Aircraft maintenance history**

G-CHZN was manufactured in 1988 and had accumulated 6,407 hours on the airframe and 1,595 hours on the engine at the time of the accident. The aircraft's last maintenance check was a 50-hour check that was completed on 6 December 2011

(28 flying hours prior to the accident). No defects were found during this check apart from an inoperative landing light and inoperative navigation light. The previous check was a 100-hour check, completed on 20 October 2011, which did not involve any significant rectification work apart from replacement of the engine rocker cover gaskets. The aircraft's last annual maintenance check was on 16 May 2011 which included replacement of the drive belts. There was no record of the pitch control links having been disturbed in the year prior to the accident. The last known disturbance of the rotor system was when the main rotor blades were removed in April 2010 to replace the spindle bearings. The airframe's last overhaul was in September 2006, at 4,812 hours.

### Accident site and initial wreckage examination


The main wreckage was found lying inverted in a field 2 miles south-west of Ely with its main rotor shaft buried in the ground (Figure 7). The lack of ground marks surrounding the wreckage indicated that the helicopter had struck the ground in an inverted attitude with very little horizontal speed. The main rotor (MR) blades were missing and one blade was found 315 m south-east of the main wreckage, in a hedge with its root embedded in the ground and its tip in the air (this will be referred to as MR blade No 1). The other MR blade was found 450 m east of the main wreckage lying flat in a field (this will be referred to as MR blade No 2). Both blades had separated from the main rotor hub at the coning hinge. Scattered along the length of a 500 m wreckage trail (Figure 8) orientated to the south-east of the main wreckage were multiple pieces

of broken 'perspex' transparency and items from the cockpit. The left door, a small part of the right door and parts from the front left skid were located about 220 m from the main wreckage.

One tail rotor blade had separated near its root and was not found – the other tail rotor blade was still attached and intact but slightly bent. There was no evidence of the main rotor having struck the tail boom (tail boom separation following main rotor contact has been a characteristic of a number of R22 inflight structural failures). The vertical and horizontal tail assembly had detached and was resting on the ground 2 m aft of the tail rotor. All other significant parts of the helicopter were accounted for except for the pitch link from MR blade No 1 and its connecting bolts, and the heads of both coning bolts, which could not be located despite a detailed search in the fields.



**Figure 7**  
Main wreckage



**Figure 8**

Wreckage plot overlaid with probable final track (dashed red line)  
 (image copyright Google Earth™ mapping service/Getmapping plc)

## Detailed wreckage examination

### *Airframe*

The airframe was significantly disrupted from the inverted impact. Both fuel tanks had ruptured and there was no remaining fuel, although a small fuel sample was recovered from the filter bowl and it had the appearance and odour of 100LL AVGAS and was free of water. The left door, which had separated in flight, had its latch in the closed and locked position and

its hinge pins were in place. The left door's structure had failed in overload around the hinges and the top rear quarter of the window frame had been sliced off. The right door was found to have separated from its hinge attachment when the helicopter struck the ground – its latch was in the closed and unlocked position. A small section of the upper rear corner of the right door window frame had been cut and had separated in flight. The left skid had failed in flight at the front, consistent with it having been struck by a solid object such as a

main rotor blade. The damage to the tail boom, and separation of the vertical and horizontal tail assembly, was consistent with the ground impact loads.

The pilot had been seated in the right seat and his shoulder and lap harness were found to be secure. The left seat flying controls had been disconnected and were found stowed beneath the left seat. The bulb filaments from the warning and caution lights were examined for indications of 'stretch' which can indicate that a bulb was hot and therefore 'on' at impact, but no significant indications of stretch were found. The 'clutch light' caution bulb was too badly damaged to assess. The magneto switch was found set to the left magneto but the key was bent so it could have moved in the impact. The clutch switch was engaged and guarded and both the battery and alternator switches were ON. The governor switch was OFF but this is a small unguarded switch at the end of the collective and could have been easily knocked. The vertical speed indicator was pegged at its maximum indicated rate of descent, 2,200 ft/min, and the altimeter pressure setting


was 1025 hPa. The carburettor temperature gauge had suffered internal damage and could not be tested. The carburettor hot air selector was found extended by 2 cm – full hot air extension was 6.5 cm.

#### *Flight controls*

A detailed examination of the flight controls revealed numerous overload failures of push-pull control tubes but all were consistent with impact forces. There were no flight control disconnects and no evidence of a control restriction.

#### *Main rotor blades*

MR blade No 1 was bent downwards in a curve (Figure 9) and its lower skin was crinkled along the full span while the upper skin was crinkled from mid-span outwards. The blade also had a slight aft bend near the tip. The leading edge of the blade was undamaged, but it had a few black and red smears. At about 2.36 m span there was light scuffing on the leading edge which could have been caused by contact with the left skid. At



**Figure 9**

Main rotor blades No 1 and No 2 as recovered from the accident site


the blade's root the spindle tusk was bent 'aft' by about 10° (aft meaning opposite to the direction of rotation). The pitch horn was intact, but slightly bent, and there were witness marks at the edges of the hole that had secured the missing pitch link bolt – this indicated that a force was applied to the bolt before it separated. The spindle bearings were free to rotate with no 'ratchety' feel.

MR blade No 2 was bent aft at about mid-span and had a crinkled upper and lower skin (Figure 9). There was no leading edge or tip damage, but there were a few red and white smears on the leading edge. The spindle tusk was bent aft by about 40°. The pitch horn had failed near the blade root and metallurgical examination of the fracture surface revealed that this was an overload failure. The separated pitch horn was still attached to the pitch link which was still attached to the rotating swashplate. The spindle bearings were free to rotate with no 'ratchety' feel.

#### *Main rotor hub assembly*

The main rotor hub was damaged as a result of the in-flight main rotor blade separations (Figure 10). The No 1 coning bolt had failed and was bent aft and the aft lug was also bent outwards. Metallurgical examination of the coning bolt fracture surface revealed that it had failed in overload with no evidence of fatigue. This evidence indicated that MR blade No 1 had separated following a radial and aft loading at the coning bolt that was in excess of design loads. MR blade No 2 had separated in a similar manner, failing the No 2 coning bolt in overload, and tearing the aft lug rearwards (Figure 10 – right image) – metallurgical examination of the hub fracture surfaces did not reveal any evidence of fatigue.

Both elastomeric teeter stops (Figure 10) were damaged and had split in the middle. This occurs when the blades flap downwards to an extreme angle and strike the mast and is known as 'mast bumping'. Witness marks on



**Figure 10**

Main rotor head as recovered from accident site, showing damaged teeter stops and drive link disconnected from rotating swashplate




the hub above the coning bolts also revealed that the blades had flapped upwards to an extreme angle and had struck the hub.

The No 1 pitch link had separated and the bolts at both the swashplate end and pitch horn end were missing. The pitch link bolt at the swashplate end secures the drive link to the swashplate through an eye end, so when this bolt separated the drive link detached from the swashplate as shown in Figure 10 (the drive link attaches on the inside of the swashplate, shown in Figure 6). Witness marks in the eye end of the drive link indicated that the bolt had been forced sideways and this lined up with a witness mark on the inside of the swashplate attachment hole. Such witness marks would not have been made if the nut had simply come off the bolt, or had broken, but the marks indicated that a high force was applied and therefore probably failed the bolt in overload. Similar witness marks at the pitch horn end of the pitch link indicated that this bolt probably also failed in overload, resulting in the separation of the No 1 pitch link. The

No 2 pitch link was found still secured at both ends but had separated from the blade where the pitch horn had failed (Figure 11).

#### *Rotary drive components*

The main rotor gearbox and tail rotor gearbox were free to rotate. An inspection of the main rotor gearbox ring gear did not reveal any damage and there was no overheat indication on the 'telatemp' (thermal indicator) sticker. There was also no evidence of rotor brake overheat, indicating that the rotor brake was off. There were overload failures in the tail rotor shaft but no disconnects. The upper and lower sheaves were free to rotate and the 'sprag' clutch internal to the upper sheave was functioning. One drive belt had a clean cut through it but was otherwise undamaged indicating that it was probably cut during the impact. The other drive belt was undamaged, but had separated from the sheave as a result of overload failure of the clutch actuator. Although the clutch actuator had failed, it was found extended to a normal in-flight position.



**Figure 11**


Main rotor blade roots, coning bolts, hub and No 2 pitch link  
(No 1 coning bolt removed from hub, No 2 pitch link disconnected from rotating swashplate.  
No 1 pitch link and coning bolt heads were not found)

### Powerplant

There was an impact imprint on the upper sheave from five teeth on the engine's starter ring gear (Figure 12) which probably occurred when the helicopter struck the ground inverted, causing the engine to strike the sheave. If the engine had been running at impact then multiple scores on the upper sheave would have been expected, therefore the engine was probably not rotating at impact. Fuel flow from the fuel tanks to the engine is by a gravity-feed system with no fuel pump, therefore the helicopter's inverted attitude prior to impact could have interrupted the fuel flow and caused engine stoppage prior to impact. To determine if engine stoppage had been an initiating event to the accident a strip examination was carried out.

The engine had sustained damage to its upper surface in the impact and all the valve pushrods were bent. Once the pushrods were removed the engine could be rotated by hand but there was external impact damage to the No 4 cylinder wall which prevented full stroke of the No 4 piston. The No 4 cylinder was removed revealing an undamaged piston, which showed that the engine was not rotating when this impact damage occurred. With the No 4 cylinder removed the engine was free to rotate. The engine teardown did not reveal any mechanical faults, excessive wear or evidence of overheating, the spark plugs were in good condition and the valves actuated normally. The right magneto had broken off in the impact but when tested it produced a good steady spark from 105 rpm and up (minimum specification 150 rpm). The left magneto was loose but it had also suffered impact damage – it produced a good steady spark from 120 rpm and up.

The carburettor was removed from the engine and bench tested. There was a small leak from the inlet nut measured at about 0.5 l/hr but when the nut was



**Figure 12**

Impact imprint on upper sheave from starter ring gear

tightened the leak stopped. It is possible that the inlet hose had been knocked in the impact loosening the nut, but if the leak had been present in flight it would have had minimal impact on engine performance because a typical cruise fuel flow rate is 8 US gal/hr (30.4 l/hr). All tests and measurements of the carburettor were within specification except for some wear on the body and mixture lever which would have resulted in a slightly over-rich setting with the lever in the 'full rich' position. However, this wear would have existed prior to the accident flight and no engine performance problems had been reported.

There were no disconnections in the throttle, mixture or carburettor heat control linkages. The carburettor heat selector moves a guillotine in the air box which slides between a cold air intake and a hot air intake. The guillotine was found positioned such that 73% of the area of the cold air inlet was open and 31% of the area the hot air intake was open (that is, more cold air than hot air was selected).

The electronic engine governor and motor, which adjusts the throttle to maintain the rotor rpm within the 'green

band' limits, were removed for testing. The electronic governor casing had been slightly distorted by impact forces and the governor failed the 'acceptance procedure' bench test. An internal examination revealed that this was caused by a faulty input/output IC4 chip. When the chip was removed and replaced with a new one the governor passed all the specification tests. Examination of the IC4 chip revealed that the chip package material had become disbonded and several of the internal fine bond wires had broken. However, there was no discolouration of the die or melting of the bond wires, which would have been an indication of an electronic fault. Consultation with an electronics expert revealed that the package disbond was more likely to have been caused by impact loads than as a result of an electronic fault, but this could not be proven. The governor motor which actuates the throttle was also tested and found to operate normally within specification.

### Causes of main rotor divergence

The evidence from the damage to the main rotor hub and to the teeter stops revealed that the main rotor blades had flapped to extreme up and down angles prior to separation. This extreme flapping is known as 'main rotor divergence' as the disk of the main rotor diverges from its normal plane of rotation. There are a number of factors that are known to cause main rotor divergence in helicopters with teetering two-bladed rotors such as the R22; they are 'Low-g manoeuvre', 'Low rotor rpm', 'Turbulence' and 'Large abrupt control inputs', and these are described as follows:

#### *'Low-g manoeuvre'*

A low-g manoeuvre results from pushing the cyclic forwards which causes the rotor disk to unload and generate less than 1g, making the pilot feel light in the seat. In a helicopter such as the R22, with a teetering rotor head, pitch and roll moments are generated by

tilting the rotor thrust vector relative to the helicopter's CG. In a low-g manoeuvre this rotor thrust is reduced which reduces the pilot's ability to roll and pitch the helicopter. However, the tail rotor continues to produce thrust and will generate a right roll.<sup>8</sup> During this roll the rotor disk tilt angle lags behind the airframe roll rate, which reduces the flapping margin between the blades and mast on the left side of the helicopter. If a pilot then applies left cyclic to correct for the right roll this will have little effect on the roll rate but it will cause the rotor blades to flap down further on the left side of the helicopter, further reducing the flapping margin and possibly leading to mast contact ('mast bumping'), airframe contact and mast separation. The Robinson R22 Pilot's Operating Handbook (POH) states that the best way to avoid mast bumping is to avoid abrupt cyclic pushovers during forward flight and that if the pilot encounters a feeling of weightlessness, to bring the cyclic aft to regain main rotor thrust before applying lateral cyclic control.

#### *'Low rotor rpm'*

The flapping angle of a blade is determined by a combination of forces, principally the weight of the blade, the aerodynamic forces (lift and drag) and the centrifugal reaction to rotation. In normal flight the lift of a blade significantly exceeds its weight (each blade is lifting half the weight of the helicopter) but the centrifugal reaction prevents the lift from causing the blade to flap up to the hub stops. Two things can happen if the rotor rpm drops: both blades can flap up excessively as the centrifugal reaction reduces and the low rpm can result in rotor stall, with the retreating blade

---

#### Foonote

<sup>8</sup> The main rotor rotates counter-clockwise as viewed from above which creates a torque effect that tries to rotate the aircraft clockwise. This is countered by the tail rotor which produces a thrust to the right which creates a balancing counter-clockwise moment. When the aircraft is pitched nose down in a low-g manoeuvre, this tail rotor thrust acting above the CG causes the aircraft to roll right.

stalling first causing it to flap down excessively<sup>9</sup>. The end result is main rotor divergence which can lead to the blades striking the mast and/or parts of the airframe.

Low rotor rpm can be caused by an engine failure, or loss of engine power, if it is followed by a delay in the pilot lowering the collective to maintain rotor rpm. Low rotor rpm and blade stall can also be caused by the pilot pulling up excessively on the collective, which causes the main rotor blades to pitch up excessively ('over-pitching') and results in the drag on the blades exceeding the engine power available. This is more likely to occur at high weight and high altitude where the rotor blades are already operating at high pitch angles.

### *Turbulence*

Flying in turbulence can lead to the rotor experiencing large vertical gusts of wind. A large gust downwards through the rotor disc can lead to unloading of the rotor, which could result in low-g, and a large gust upwards would load the rotor and increase the blade angle of attack. These situations can be exacerbated if the pilot over-controls the helicopter in the turbulence, because over-controlling can result in excessive blade flapping and main rotor divergence (see next paragraph). The R22 POH states that 'Flying in high winds or turbulence should be avoided' but that if it is encountered the airspeed should be reduced to between 60 and 70 KIAS.

### *Large abrupt control inputs*

A very large and abrupt control input in either pitch or roll could cause the rotor hub to teeter excessively about the teeter bolt and result in the blades striking the mast and/or airframe. There is no force feedback

---

#### **Footnote**

<sup>9</sup> In the low rpm case, it is the retreating blade that will stall first with the helicopter in forward flight because it has a lower airspeed than the advancing blade and therefore is at a higher angle of attack to maintain the same lift as the advancing blade.

in the control system, other than a bungee in the pitch axis, so only light forces are required to apply full cyclic deflection in pitch or roll. As previously discussed, a large abrupt upwards collective deflection could also cause blade stall. Full abrupt cyclic control deflections have never been flight tested on the R22 because of the risk to flight safety but simulator studies confirm that mast bumping and blade stall could occur. A study by the US National Transportation Safety Board (NTSB) (discussed later) stated that:

*'Large, abrupt control inputs can lead directly to mast bumping or induce blade stall, which, in turn, can lead to mast bumping.'*

Based on an analysis of an R22 accident in Richmond, California, a study by Bell Helicopters and a study by the Georgia Institute of Technology, the NTSB concluded that:

*'the low inertia main rotor blade can diverge from normal rotation to strike the body of the helicopter in just a few revolutions of the blade. This would take less than 0.5 seconds when the blade is operating at a normal rate of 530 rpm. Thus, unless the instructor is actually holding the cyclic handle and preventing a large, abrupt input, there is insufficient time for the instructor to react once a student makes such an input.'*

### **Aircraft manufacturer's explanations of the evidence**

The aircraft manufacturer's accident investigators were consulted during the investigation and the rotor head components and main rotor blade roots from G-CHZN were taken to the aircraft manufacturer for examination. They commented that main rotor blade separation at the coning bolt was unusual but that they had seen it before. They did not consider the evidence

to be indicative of an overspeed situation as rotor overspeed usually results in ‘brinelling’ of the spindle bearings creating a ‘ratchety’ feel when rotated, which was not the case in G-CHZN. They stated that the coning bolts probably failed as a result of aerodynamic loads being applied to rotor blades that had pitched up or down to 90°. Failure of the pitch links would allow the blades to pitch to any angle, and the coning bolts are not designed to withstand the drag loads on a blade that had pitched to 90°, the upper or lower surface being presented flat to the airstream like a paddle. The aft bending (opposite the direction of rotation) of the coning bolts and hub lugs supports this theory.

To explain the failure of the No 1 pitch link, the manufacturer set up a rig of an R22 main rotor head assembly (Figure 13), with the elastomeric teeter stops removed to simulate the geometric situation following mast bumping where the stops have been split and the blade root is striking the mast. Normally the pitch link is aligned vertically, perpendicular to the plane of rotation, and experiences pure tensile and compressive loads, but at extreme teetering angles the pitch link tilts aft. This allows bending loads to be applied to the pitch link and retaining bolts. The aerodynamic forces during rotor blade divergence could be sufficient to pitch the rotor blade further nose down than in Figure 13, which would force the pitch link down and fail the lower attachment bolt in a downwards and forward direction. This was consistent with the witness marks found in the swashplate attachment hole and the eye end of the drive link.

Failure and separation of the No 1 pitch link lower attachment bolt would have resulted in a loss of drive to the rotating swashplate, because the same bolt secures the drive link. This would cause the rotor to ‘overtake’ the swashplate which would have caused a nose down pitching moment of blade No 2 as the No 2 pitch link

lower attachment bolt lagged behind the upper bolt. It is possible that separation of MR blade No 2 followed this sequence and that it was blade separation that caused the pitch horn to fail.

The physical evidence could, therefore, be explained by main rotor divergence and subsequent mast bumping but there was insufficient evidence to determine the cause of the main rotor divergence. The aircraft manufacturer considered that low rpm was more likely than low-g because the forces on the mast in the low-g situation are more likely to fracture the mast and shaft causing the head to separate, which did not occur in G-CHZN. The manufacturer also considered that low rpm would be required to cause a blade to flap up sufficiently to cause the No 1 pitch link to separate in the manner described.



**Figure 13**

R22 rotor head with elastomeric teeter stops removed to simulate the static geometry when mast bumping occurs. The MR blade on the left has been pitched to the maximum nose-down position that could be attained with hand force – the pitch link is no longer ‘over-centre’

The manufacturer agreed that more evidence is required to fully understand the causes of accidents involving main rotor divergence, and is investigating the feasibility of installing a small lightweight (non crash-protected) flight data recorder on the R22, R44 and R66. The technology already exists to create a small light-weight recorder that includes solid-state 3-axis gyros, 3-axis accelerometers, GPS and an altitude pressure sensor, but one of the challenges is to develop a lightweight and non-invasive means of measuring control positions.

The manufacturer also plans to carry out research on carburettor icing using an environmental chamber and to test the effects of installing a heated throttle butterfly in the carburettor.

#### **Safety information - Robinson R22 Pilot's Operating Handbook**

Section 10 of the R22 POH contains Safety Notices that warn pilots about the handling characteristics explained in the previous paragraphs. The Safety Notices are reproduced in full in Appendices A to F but certain sections are discussed below.

Safety Notice SN-10, *Fatal Accidents Caused by Low RPM Rotor Stall* states:

*'A primary cause of fatal accidents in light helicopters is failure to maintain rotor RPM. No matter what causes the low rotor RPM, the pilots must first roll on throttle and lower the collective simultaneously to recover RPM before investigating the problem.'*

Safety Notice SN-11, *Low-g Pushovers – Extremely Dangerous*, states:

*'Pushing the cyclic forward following a pull up or rapid climb, or even from level flight, produces a low-g (weightless) flight condition. If the helicopter is still pitching forward when the pilot applies aft cyclic to reload the rotor, the rotor disc may tilt aft relative to the fuselage before it is reloaded. The main rotor torque reaction will then combine with tail rotor thrust to produce a powerful right rolling moment on the fuselage. With no lift from the rotor, there is no lateral control to stop rapid right roll and mast bumping can occur. Severe in-flight mast bumping usually results in main rotor shaft separation and/or rotor blade contact with the fuselage.'*

Safety Notice SN-24, *Low RPM Rotor Stall Can Be Fatal*, states:

*'As the RPM of the rotor gets lower, the angle of attack of the rotor blades must be higher to generate the lift required to support the weight of the helicopter. As with the aeroplane wing, the blade aerofoil will stall at a critical angle, resulting in a sudden loss of lift and a large increase in drag. The increased drag on the blade acts like a huge rotor brake, causing the rotor RPM to rapidly decrease, further increasing the rotor stall.'*

In a fixed-wing aircraft, a pilot's reaction to a stall warning horn would be to reduce the angle of attack of the wing by moving the control column forward and to add power. Safety Notice SN-29, *Airplane Pilots High Risk When Flying Helicopters*, states:

*'In a helicopter, application of forward stick when the pilot hears a horn (low RPM) would drive the RPM even lower and could result in rotor stall, especially if he also "adds power" (up collective). In less than one second the pilot could stall his rotor, causing the helicopter to fall out of the sky.'*

In order to descend, for example to avoid a bird or other aircraft, a fixed-wing pilot would push the control column forward whereas a helicopter pilot should lower the collective lever with very little movement of the cyclic control. Safety Notice SN-29 states:

*'A rapid forward movement of the helicopter cyclic stick under these conditions would result in a low "g" condition which would cause mast bumping, resulting in separation of the rotor shaft or one blade striking the fuselage.'*

Carburettor icing typically causes a loss of rpm or manifold pressure. Safety Notice SN-31, *Governor Can Mask Carb Ice*, states:

*'The governor will automatically adjust throttle to maintain constant RPM which will also result in constant manifold pressure.'*

The flying training organisation that prepared the pilot to gain his PPL(H) reported that he had shown a good understanding of the issues discussed in this section of the report. In addition, it commented that he was cautious, had "completely and utterly the right attitude" and was not overconfident. The operator from which the pilot hired G-CHZN also commented that the pilot understood these issues.

## Special regulatory requirements for R22 operation

### *Special Federal Aviation Regulation (SFAR) Number 73*

In March 1995 the FAA introduced SFAR 73, as an Emergency Rule, which gives special requirements for pilots in the USA wishing to fly the R22 helicopter<sup>10</sup>. The requirements were introduced to ensure that pilots flying the helicopter were aware of, and trained to respect, the handling characteristics previously explained in this report. The rule was due to expire on 31 December 1997 but was extended twice and in June 2009 was made permanent.

SFAR 73 required (and continues to require) awareness training to be undertaken to cover energy management, mast bumping, low rotor rpm (blade stall), low-g hazards and rotor rpm decay. In addition, no person could act as PIC of an R22 helicopter unless that person had already obtained at least 200 hours flying helicopters, at least 50 hours of which were gained in the R22. Alternatively, a pilot required at least 10 hours of dual instruction in the R22 before being cleared to fly as PIC. Every 12 months, a pilot must undergo a check flight, which must include training in advanced autorotation, engine rotor rpm control without the use of the governor, low rotor rpm recognition and recovery, and the effects of low-g manoeuvres and proper recovery procedures.

The CAA informed UK owners/operators of the R22, in *Letter to Owners/Operators (LTO) 1485*, that the awareness training specified by SFAR 73 was adequately covered by the existing CAA-recognised flight crew training syllabus. In addition:

---

#### Footnote

<sup>10</sup> SFAR No 73 also applies to the Robinson R44 helicopter, a larger four-seat version of the R22 employing the same rotor head system.

*'Provided that they have accumulated at least 200 flight hours on helicopters, at least 50 hours of which are on the specific type (R22 or R44) being flown, UK licensed helicopter pilots are deemed to have completed the awareness training.'*

The European Aviation Safety Agency (EASA) does not issue helicopter class ratings and, before flying the R22 as PIC, a pilot must undergo a type rating course (or the PPL(H) course leading to a type rating) and the rating must be renewed every 12 months. However, the theoretical elements that are mandated in SFAR 73 are not present in the PPL syllabus. EASA Safety Information Bulletin 2009–35 recommended that SFAR 73 training be implemented for Robinson helicopter training in EU states. In response, EASA proposes to incorporate awareness training in the PPL(H) syllabus by amending the Annex, *Acceptable Means of Compliance and Guidance Material to Part-FCL*,<sup>11</sup> to ED Decision 2011/016/R<sup>12</sup>.

#### *FAA Airworthiness Directive (AD) 95–26–04*

In 1995, FAA Airworthiness Directive (AD) 95–26–04 was issued to prevent main rotor stall or mast bumping leading to loss of control of R22 helicopters. Limitations were added to the POH, which were to be observed unless the pilot had logged 200 or more flight hours in helicopters, at least 50 which were gained in the R22, and had completed the awareness training specified in SFAR 73. The limitations were:

- '(1) Flight when surface winds exceed 25 kt, including gusts, is prohibited.*
- (2) Flight when surface wind gust speeds exceed 15 kt is prohibited.*
- (3) Continued flight in moderate, severe, or extreme turbulence is prohibited.'*

#### **NTSB study of Robinson R22 main rotor loss of control accidents, 1996**

In April 1996 the US NTSB published '*Special Investigation Report – Robinson Helicopter Company R22 Loss of Main Rotor Control Accidents*' (NTSB/SIR-96/03) which examined a number of R22 'loss of main rotor control accidents'<sup>13</sup> and made recommendations intended to prevent recurrence. The study determined that, between 1981 and 1994, the rate for R22 fatal accidents involving loss of main rotor control or loss of control for unknown reasons (LOC<sup>14</sup>) was 1.509 per 100,000 flight hours, three times higher than for the next highest helicopter.

The study was also prompted, in part, by an R22 accident in 1992<sup>15</sup> which involved an in-flight breakup that resulted in the tail boom and the mast assembly (with blades attached) separating from the airframe. In this accident, involving an instructor and student pilot, spectral analysis of an audiotape that was onboard revealed that the rotor rpm was normal and did not decay before the breakup. Examination of the wreckage did not reveal any evidence of a pre-impact control

---

#### **Footnote**

<sup>11</sup> Acceptable Means of Compliance and Guidance Material to Commission Regulation (EU) No 1178/2011 of 3 November 2011 laying down technical requirements and administrative procedures related to civil aviation aircrew pursuant to Regulation (EC) No 216/2008 of the European Parliament and of the Council.

<sup>12</sup> Decision Number 2011/016/R of the Executive Director of the European Aviation Safety Agency dated 15 December 2011.

---

#### **Footnote**

<sup>13</sup> The study uses the term 'loss of main rotor control' which is essentially the same as 'main rotor divergence'.

<sup>14</sup> The NTSB defined LOC as '*involved an in flight: loss of main rotor control; structural failure of the main rotor blade that did not involve pre-existing fatigue of rotor blade materials; or, loss of aircraft control or collision with terrain for unknown reasons, in the absence of structural failure, encounter with instrument meteorological conditions, or pilot impairment due to drugs or alcohol.*'

<sup>15</sup> Accident to Robinson R22 (registration N83858) on 29 June 1992 near Richmond, California, USA.



system or airframe failure that might have initiated the breakup. The NTSB could not find evidence of a specific event that caused or allowed the main rotor blades to diverge from their normal flightpath plane and strike the airframe - there was no loss of rotor rpm and the circumstances did not support a deliberate low-g manoeuvre. This accident remains unexplained.

Between 1981 and the publication of their study in 1996 the NTSB investigated or researched 31 R22 and three R44 accidents involving in-flight loss of main rotor control and contact of the main rotor blades with the tail boom or fuselage.

The NTSB also conducted a detailed examination of six of its most recent (at the time) R22 accidents involving loss of main rotor control and determined that most of the damage occurred after the main rotor blades began to diverge from their normal plane of rotation. The NTSB was aware of only two cases in which an R22 exhibited signs of significant mast bumping and was able to land. The report stated that:

*'once over-teetering and mast bumping occurs, structural failure of the main rotor mast or shaft is highly likely and would be quickly followed by overload of the pitch control system of the blade. The available wreckage from all six accidents is consistent with this scenario.'*

The report details a number of R22 technical reviews and studies that were carried out by the US Federal Aviation Administration (FAA) in the 1980s and 1990s. These resulted in the new pilot training requirements (SFAR 73), and aircraft modifications (an electronic governor and an increased 'low rpm' warning threshold) primarily to address the issue of accidents caused by loss of rotor rpm. Other than the training requirements, there were no changes made to address

the issue of low-g or large abrupt control inputs which are the other possible causes of main rotor divergence.

The first two safety recommendations (A-96-9 and A-96-10) in the NTSB's report concerned pilot training requirements and they were accepted and implemented by the FAA. The third recommendation (A-96-11) concerned certification requirements and followed from a paragraph in the body of the report which stated:

*'The Safety Board believes that the FAA should require helicopter manufacturers to provide data on the response of helicopters to large, abrupt cyclic inputs as a part of the certification process and require operational limitations or other measures for those helicopters that are more responsive, such as the R22.'*

The safety recommendation to the FAA (A-96-11) stated:

*'Require helicopter manufacturers to provide data on the response of helicopters to flight control inputs to be used as part of the certification process, and require operational limitations or other measures for those helicopters that are highly responsive.'*

Recommendations A-96-12 and A-96-14 asked the FAA and NASA respectively to develop a:

*'simulator model of lightweight helicopters, using flight tests and whirl tower tests as needed to validate the model, to create a national resource tool for the study of flight control systems and main rotor blade dynamics.'*

### Responses to recommendations in the NTSB study

The FAA's response to recommendation A-96-11 was to amend Advisory Circular (AC) 27.661, which concerns 'Rotor Blade Clearance'. The relevant procedure stated that testing for blade clearance compliance should be conducted:

*'in all areas of the envelope during all operational manoeuvres expected throughout the life of the aircraft'*

and should include a blade flapping survey to determine flapping angles/margins, blade bending, and blade clearance from the entire airframe, and it should determine what margins exist at low rpm.

The AC did not define a flight envelope or define what:

*'all operational manoeuvres expected'*

were and neither did it define what clearance margins would be acceptable. It did not specifically require that data be gathered on the response to large, abrupt cyclic inputs as originally intended by the NTSB study. Nevertheless, the NTSB closed this recommendation in March 2000 and recorded 'Acceptable Action'.

In response to recommendations A-96-12 and A-96-14, NASA awarded a contract to Advanced Rotorcraft Technology Inc., to conduct a one-year study of 'Rotor Dynamics Analysis of Light Helicopters'. The study involved the development of a simulator model closely based on the R22 and included an analysis of the blade response following gust inputs. The study did not identify any inherent dynamic problems for a two-bladed rotor with a teetering hub and offset flapping hinge; however, it stated that the results could not be validated because appropriate flight and wind tunnel test data was

not available, particularly at high angles of attack and sideslip. The investigation into the response following large abrupt control inputs was limited. The study made a number of recommendations for further work, including gathering experimental data and modelling the elastic properties of rotor blades, which could affect the blade-to-airframe clearance in extreme manoeuvring. After reviewing the study, the NTSB closed the safety recommendation and stated that:

*'Although R22 helicopters are not accident free, the operating envelope and more stringent weather/training requirements imposed by the FAA appear to have greatly reduced instances of loss of main rotor control for R22s. The Safety Board is persuaded that the results of the NASA study indicate that there is no justification for flight or wind tunnel testing at this time.'*

### R22 main rotor loss of control accidents since the NTSB study

The 1996 NTSB study stated that following the FAA's implementation of new operational, experience and training requirements for R22 pilots (SFAR 73 and AD 95-26-04):

*'There have been no in-flight rotor/fuselage contacts of the R22 in the United States in the past year since the changes were implemented. Although the Safety Board cannot conclude that the operational changes will eliminate all in-flight rotor strikes, the absence of such accidents since these actions were implemented suggests that they have been effective.'*

However, since the NTSB study was published in 1996, there have been at least 16 fatal R22 accidents involving loss of main rotor control, including G-CHZN

(Appendices G & H) – 10 in the USA and 6 elsewhere. Out of the 10 accidents in the USA, one is still under investigation, and three were concluded to have been caused by ‘Main rotor divergence for undetermined reason.’ Out of the 16, three were attributed to possible turbulence, five to possible low rpm, and one to low-g. Two of the accidents involved separation of a single main rotor blade at the coning bolt and one accident, in addition to G-CHZN, involved separation of both main rotor blades at the coning bolts (Appendices G & H): In this accident (N7779M, near Del Valle, Texas, 27/6/2011) a pitch link was found to have separated due to failure of the bolts at both ends (Figure G2 in Appendix G).

#### Light helicopter stability and control requirements

The certification requirements for light helicopters are contained in EASA Certification Specification CS-27 and in the USA equivalent, FAA Aviation Regulation (FAR) Part 27. The regulations require that the rotorcraft ‘*must be safely controllable and manoeuvrable*’ during various flight conditions. Flight controls may not exhibit excessive breakout force or friction, but there are no restrictions on how light the control forces can be. In terms of static longitudinal stability a rearward movement of the control must result in a reduction in airspeed and a forward movement must result in an increase. However, there are no stability-related stick force requirements for light helicopters, unlike for light fixed-wing aircraft where there is a requirement to demonstrate that the stick force varies with speed (CS-23 and FAR-23). For light fixed-wing aircraft there are requirements to demonstrate that any short-period oscillation is heavily damped and any long-period oscillation must not be so unstable as to cause unacceptable pilot workload; there are no equivalent dynamic stability requirements for light helicopters.

In November 2005 NASA published a report on ‘*The Implications of Handling Qualities in Civil Helicopter Accidents Involving Hover and Low Speed Flight*’<sup>16</sup>, co-authored by the Deputy Director of the National Rotorcraft Technology Center at NASA. The study considered hover, hover-taxi and low speed accidents, which occurred mainly on helicopters that had no stability augmentation. Out of 547 accidents analysed, 126 (or 23%) ‘*could be attributed to loss of control by the pilot which was caused or aggravated by inadequate or deficient handling qualities.*’ The report stated that the FAA:

*‘imposes standards for handling qualities as defined in the Federal Aviation Regulation (FAR) Part 27; however, these require only minimal standards. Military helicopters must meet the requirements of ADS-33D-PRF which are more stringent than those of the old MIL-H-8501.’*

The report concluded that:

*‘From the accidents reviewed, and the other statistics on civil helicopter accidents attributed to loss of control, it is puzzling why poor handling qualities have not been pinpointed as causes or factors in the accidents. Improvements in handling qualities were not even recommended, within the scope of this research, as a means or investment in safety to reduce the frequency of such accidents.*

*It can be inferred that a significant reduction in accidents, injuries, and property damage*

#### Footnote

<sup>16</sup> ‘*The Implications of Handling Qualities in Civil Helicopter Accidents Involving Hover and Low Speed Flight*’ (TM-2005-213473) by Daniel Dugan, Deputy Director of the National Rotorcraft Technology Center at NASA Ames, and Cdr Kevin Delamer, Navy Liaison Officer at the same centre.

*could be achieved by the integration of stability augmentation systems into the control systems of the lower priced helicopters.'*

The report goes on to recommend that:

*'The feasibility of designing or incorporating a low cost, lightweight stability augmentation system should be explored by the helicopter manufacturers. Today's technology may provide the means to accomplish a goal of significantly improving the handling qualities of their helicopters. Where a hydraulic system is not practical for inclusion in the design, the technology exists to provide the secondary or automatic flight control system functions with small electrical actuators.'*

#### **Additional information - Stability augmentation systems for light helicopters**

In November 2009 Cobham PLC obtained a supplemental type certificate (STC) for the installation of a stability augmentation system called HeliSAS on the larger Robinson R44 helicopter. This system is an 'attitude command'/'attitude hold' augmentation system and includes force feedback. It can maintain the helicopter in a cruise attitude or in a hover with the pilot's hands free of the cyclic. Pilot-applied cyclic force is required to manoeuvre the helicopter away from the trim condition and releasing the cyclic will result in the helicopter automatically returning to the trim condition. The system was tested by the aircraft manufacturer, by a NASA test pilot and by a test pilot from the National Test Pilot School in 2005, and 'very favourable' comments were received (ref NASA report TM-2005-213473). The system tested weighed 5.5 kg and had a projected cost in 2005 of \$30,000 (ref NASA report TM-2005-213473).

The HeliSAS system is not currently available for purchase on the R44 and has not been designed for the R22, but it is an available modification for the Bell 206, Bell 407 and Eurocopter AS350.

#### **Additional information - Pilot reaction times following a loss of power in single-engine helicopters**

A significant factor in R22 accidents involving loss of engine power is the short time period a pilot has to lower the collective lever and enter autorotation before the rotor enters an unrecoverable stalled condition. The time available for a pilot to respond to a loss of power is primarily a function of rotor design and the inertia in the rotor system. The R22 rotor blades have relatively low inertia compared to larger helicopters. The certification requirements in CS 27.143(d) and FAR 27.143(d) state that, after complete engine failure, a single-engine rotorcraft must be controllable with a corrective action time delay following power failure of at least:

- '(i) For the cruise condition, one second, or normal pilot reaction time (whichever is greater); and*
- (ii) For any other condition, normal pilot reaction time.'*

'Normal pilot reaction time' is not defined in the regulations but according to the CAA a figure of 0.3 seconds is typically used. Therefore, a minimum of 1 second reaction time is required in cruise and only 0.3 seconds in any other flight condition.

During manufacturer flight testing of the R22 in 1982, the collective lever was lowered approximately 1.6 seconds after a 'power chop' during the cruise, and one second during the climb, to demonstrate that the helicopter met the certification requirements. Time delays beyond these would have risked stalling the rotor.

EASA has initiated rulemaking task RMT.0246 (MDM.050) entitled ‘*Pilot Intervention Time Following Power Failure in Single-Engine Helicopters*’, and has requested tenders for carrying out a regulatory impact assessment to investigate the effects of changing the requirements for pilot reaction time. The terms of reference question whether the existing rules and certification practices are representative of normal pilot response in such situations. Research previously undertaken by the CAA (CAA Paper 99001) had identified, through simulation, mean values up to 4.1 seconds, with up to 5.7 seconds if the 90th percentile pilot was considered.

## Analysis

### *Accident site and wreckage examination*

The evidence from the accident site revealed that the helicopter had suffered an in-flight breakup. Both MR blades had leading edge paint transfer marks consistent with having struck parts of the airframe, shattering the cockpit ‘perspex’ transparency, severing the left door and part of the right door. One of the MR blades (probably MR blade No 1) had severed the left front skid. For the MR blades to do this damage the main rotor had to diverge from its normal plane of rotation and strike the mast (mast bumping) and there was clear evidence on the mast and hub that this had occurred. Both MR blades had then separated from the hub, failing both coning bolts in overload – these failures must have occurred in very rapid succession because the main rotor gearbox had not separated from the airframe (a failure mode that would have been observed if a single MR blade had remained attached for any time because of the out-of-balance forces that would have existed). There was no evidence of fatigue, corrosion or material defects in the rotor head components analysed – all failure modes were overload. The coning bolts most likely failed as a result of the blades pitching to an extreme

up or down angle with the resulting drag loads on the blades exceeding the design loads of the bolts and failing the hub lugs in an aft (opposite the direction of rotation) manner. The evidence was not consistent with a rotor overspeed.

The No 1 pitch link and retaining bolts were not found but the witness marks inside the bolt attachment holes indicated that a very high bending force had been applied to both bolts – these witness marks would not have been produced if the nuts had come off the bolts. The aircraft manufacturer considered that the bolts could have failed as a result of extreme nose-down pitching of the No 1 MR blade coupled with high upwards flapping. It is very unusual for both ends in a pitch link to fail but another example is shown in Figure G2, Appendix G. With its pitch link separated, the No 1 MR blade was free to pitch to any angle and, if the rotor blade stalled, the resulting aerodynamic moment would probably have pitched it down. Once the upper surface of the blade was presented flat to the airstream, the blade would have overloaded the coning bolt and separated. The No 2 MR blade probably separated almost immediately, failing the pitch horn.

The wreckage examination did not reveal any evidence of a disconnected flight control or restriction and there was no evidence that a failure in any of the rotary drive components precipitated the main rotor divergence. The powerplant examination did not reveal any faults that might have caused a loss of power and fuel records indicated that there was sufficient fuel onboard at the time of the accident.

The possibility of carburettor ice having formed inside the carburettor causing a loss of power or engine stoppage could not be ruled out. The carburettor hot air selector was extended by 2 cm which resulted in some

hot air, but mostly cold air, entering the air box. The atmospheric conditions at the time were conducive to carburettor icing and, although the engine was probably operating at cruise power, the engine is de-rated such that the throttle butterfly is only partially open even at cruise power settings, which makes carburettor icing more likely.

In summary, the physical evidence clearly pointed to main rotor divergence, also known as a 'loss of main rotor control', as being the cause of the rotor head failures, airframe failures and main rotor blade separation.

#### *Causes of main rotor divergence*

There are several factors that can cause main rotor divergence: low-g flight, low rpm, turbulence and large abrupt control inputs. The meteorological conditions at the time were not conducive to turbulence caused by wind or mountain wave activity so it is unlikely that turbulence was a factor in the accident. Further, radar evidence allowed the investigation to discount the presence of wake turbulence from a nearby aircraft as a factor.

#### *Low-g pushover*

A low-g pushover was a possible cause of the main rotor divergence. The rotor struck the left door and left front skid, which are typical features of low-g accidents because the pilot's natural response to a rapid right roll (induced in a low-g situation) is to apply full left cyclic which, when the rotor is unloaded, can cause the rotor disk to tilt to an extreme left angle and strike the airframe. A possible reason for the pilot to perform a low-g pushover would have been to initiate a rapid descent by pushing forward on the cyclic, perhaps because he realised he had entered the Mildenhall MATZ and wanted to descend below it, or perhaps because he wanted to avoid a bird, or birds, by descending. Alternatively,

the pilot might have pushed forward on the cyclic to level the helicopter having pulled up to avoid a bird, or birds, or to correct for an unexpected pitch-up during a period of inattention or distraction. Although moving the cyclic forward is an inappropriate technique in a helicopter in these circumstances, the pilot's experience was primarily in fixed-wing aircraft in which moving the control column forward rapidly would have been appropriate. Application of the incorrect technique in circumstances such as these is known to be hazardous and Safety Notices within the R22 POH warn pilots of the possible consequences.

Some features of low-g accidents were absent in this case. In many R22 accidents associated with low-g, the mast separated just below the rotor head, which did not occur with G-CHZN. However, it is not certain whether mast separation will always occur and it may be dependent on the severity of the entry to low-g or the actual reduction in g that is achieved. Another feature missing from the low-g scenario was that a low-g pushover results in a rapid roll to the right, whereas witnesses reported seeing a rapid roll to the left.

#### *Low rotor rpm*

Low rotor rpm and subsequent rotor stall can cause main rotor divergence. Low rotor rpm is caused either by a loss of engine power followed by the pilot reacting too slowly to lower the collective, or by the pilot raising the collective too much and over-pitching the blades. G-CHZN was in the cruise at relatively low altitude, and at least 164 lb below its maximum weight, which are conditions that would not require a particularly high blade pitch angle. Nevertheless, a loss of rotor rpm due to over-pitching might have occurred had the pilot made a large upward input on the collective, perhaps to climb over a bird, or birds. The aircraft manufacturer believed that excessive upward flapping of the blades would

be required to fail the No 1 pitch link in the manner observed, and that this would not occur at high rpm because the centrifugal reaction to rotation would limit the flapping angle.

A loss of rotor rpm due to a loss of power is a possible factor in this accident, although no evidence of an engine fault was found. There was evidence that the engine had stopped prior to impact but this was likely to have occurred in any case due to an interruption in fuel flow as a result of the helicopter's inverted attitude prior to impact. The atmospheric conditions were conducive to carburettor icing, which might have caused a reduction in power. The electronic governor on the R22 can mask the onset of carburettor icing because, as the ice builds and the power reduces, the governor automatically increases the throttle to compensate. This prevents the drop in manifold air pressure that would normally alert the pilot to the problem. Once the throttle has been fully opened, and if ice is still building, power and rotor RPM will reduce quickly. If the pilot does not respond by lowering the collective within about 1.5 seconds the rotor can enter an unrecoverable condition and the engine can stop.

In a number of R22 accidents that have been attributed to low rotor rpm there was evidence that the tail boom had been struck by the main rotor, with the retreating blade stalling first, causing it to drop and strike the tail boom. This did not happen with G-CHZN but cyclic control inputs made by the pilot at the time of the rotor stall may have an effect on whether or not the tail boom is struck.

#### *Large abrupt cyclic inputs*

According to the NTSB study '*Large, abrupt control inputs can lead directly to mast bumping or induce blade stall, which, in turn, can lead to mast bumping.*' This, and other, studies imply that large cyclic inputs in any

direction could cause mast bumping. Full cyclic control deflections at cruise speed have not been demonstrated in flight due to the '*significant risk to flight safety*' but simulator modelling provides some evidence to support the theory. A large abrupt sideways cyclic input, if maintained, would generate a rapid roll that would invert the helicopter very quickly, according to the manufacturer. This might explain the rapid roll observed by witnesses but it is difficult to explain what would have caused the pilot to do this, unless it was inadvertent and possibly due to a distraction. In a fixed-wing aircraft it is more difficult to apply full control deflection at increasing speed because the control forces increase with deflection. This is not the case in a light helicopter like the R22 without a stability augmentation system and only very light forces are required to obtain full deflection. The helicopter manufacturer explained that light cyclic control forces are required for controllability in the hover because in some cases large and rapid control deflections are required.

It is possible that a combination of low rpm, an abrupt control input and low-g caused the main rotor divergence in G-CHZN. If carburettor ice caused a loss of rotor rpm this would have triggered the low rpm audio warning, and this warning sounds like the stall warning in some light fixed-wing aircraft. The response of a fixed-wing pilot to a stall warning is often to push forward on the controls to un-stall the wing. This would be an inappropriate response from the pilot in these circumstances, but understandable given that the vast majority of his flying was in fixed-wing aircraft. The loss of rotor rpm could explain why the pitch link failed in the way that was observed. The forward deflection of the cyclic, leading to a low-g flight condition, could explain the rapid roll but only if the witnesses were mistaken and the roll was, in fact, to the right.

*Incapacitation*

The investigation considered the possibility that the pilot became incapacitated and that this was the initiating event that led to the main rotor divergence. This possibility was considered unlikely because post-mortem examination indicated that the pilot was probably conscious at impact and it is unlikely that the pilot suffered an acute episode of symptoms associated with his undiagnosed medical condition.

**Safety action and Safety Recommendations**

R22 accidents involving main rotor divergence were analysed in depth by the NTSB in 1996. They concluded that:

*‘the FAA should require helicopter manufacturers to provide data on the response of helicopters to large, abrupt cyclic inputs as a part of the certification process.’*

This recommendation was implemented in part by changes to AC-27.661 which required manufacturers to carry out a blade flapping survey. However, the AC did not define what the control deflections should be or what the rate of input should be. It specified that margins should be determined but it did not specify what the margins should be. The NTSB closed their recommendation (A-96-11) with an ‘Acceptable’ response, but this was influenced by the reduction in R22 ‘main rotor loss of control’ accidents that had occurred in the mid 1990s. The NTSB attributed this to the increased training and experience requirements imposed by the FAA. However, since the 1996 NTSB study there have been at least a further 16 fatal R22 accidents involving loss of main rotor control.

*Reaction time*

Some of these accidents were probably caused by a loss of rotor rpm following a loss of power without the pilot lowering the collective quickly enough. In the R22 the pilot must react to a loss of power by lowering the collective in less than about 1.5 seconds in the cruise, or 1 second in the climb, to prevent rotor stall. EASA has therefore initiated a Regulatory Impact Assessment to study the effect of increasing the required reaction times.

*Handling qualities*

Another probable factor in continuing fatal accidents involving R22 ‘main rotor loss of control’ relates to the handling qualities. Only light control forces are required to apply full cyclic deflection in the R22, making it easy inadvertently to enter a low-g situation or to make an abrupt and rapid control input leading to rotor stall and mast bumping. In contrast to fixed-wing aircraft, there are no certification requirements for stick forces for light civilian helicopters and the certification requirements in FAR-27 (FAA), and now CS-27 (EASA), have changed little in several decades and are less stringent than the equivalent military requirements. The NASA Ames study (TM-2005-213473) recommended that manufacturers should explore the feasibility of designing a low-cost, lightweight stability augmentation system, which would also provide benefits for the reduction of low-speed and hovering helicopter accidents. A stability augmentation system would provide some control force feedback thereby making large abrupt cyclic inputs less likely, as well as recovering the aircraft to a safe attitude should the pilot release the cyclic control. There may be other design solutions which would reduce the likelihood of ‘loss of main rotor control’ accidents.



Therefore the certification requirements for future helicopter designs should be updated and improved to reduce the risk of 'loss of control' and 'loss of main rotor control' accidents. It is desirable that the EASA and FAA co-operate in this task and therefore the following two Safety Recommendations are made:

**Safety Recommendation 2012-038**

The European Aviation Safety Agency should amend the requirements in Certification Specification Part 27 to reduce the risk of 'loss of main rotor control' accidents in future light helicopter designs.

**Safety Recommendation 2012-039**

The Federal Aviation Administration should amend the requirements in Federal Aviation Regulation Part 27 to reduce the risk of 'loss of main rotor control' accidents in future light helicopter designs.

Fatal accidents involving the R22 continue to occur due to main rotor divergence, the causes of which are rarely determined conclusively because the pilot's control inputs leading up to the divergence are rarely known. If the helicopter manufacturer succeeds in developing a lightweight flight data recorder for the R22 that includes recordings of control positions, it is likely that there will be new insights into the causes of main rotor divergence.

Work is being carried out to investigate changing the certification requirements to allow a longer pilot reaction time to a loss of rpm, because the probability of a fatal outcome following a loss of power in a light helicopter is high. This report has recommended that the regulators amend the certification requirements to reduce the risk of 'loss of main rotor control' accidents in future light helicopters.

**Conclusions**

This accident to G-CHZN was caused by main rotor divergence which resulted in mast bumping, the rotor blades striking the airframe and rotor blade separation. The main rotor divergence was probably caused by a loss of rotor rpm (not followed by rapid lowering of the collective lever), a low-g pushover, a large abrupt control input - or a combination thereof. A loss of rotor rpm could have been caused by a build-up of carburettor ice which was not recognised and removed by applying sufficient carburettor heat. A low-g pushover or a large abrupt control input could have been generated for a number of reasons, and the light control forces in the R22 make it relatively easy to enter such conditions.

## Appendix A

### Safety Notice SN-10

Issued: Oct 82 Rev: Feb 89; Jun 94

#### FATAL ACCIDENTS CAUSED BY LOW RPM ROTOR STALL

A primary cause of fatal accidents in light helicopters is failure to maintain rotor RPM. To avoid this, every pilot must have his reflexes conditioned so he will instantly add throttle and lower collective to maintain RPM in any emergency.

The R22 and R44 have demonstrated excellent crashworthiness as long as the pilot flies the aircraft all the way to the ground and executes a flare at the bottom to reduce his airspeed and rate of descend. Even when going down into rough terrain, trees, wires or water, he must force himself to lower the collective to maintain RPM until just before impact. The ship may roll over and be severely damaged, but the occupants have an excellent chance of walking away from it without injury.

Power available from the engine is directly proportional to RPM. If the RPM drops 10%, there is 10% less power. With less power, the helicopter will start to settle, and if the collective is raised to stop it from settling, the RPM will be pulled down even lower, causing the ship to settle even faster. If the pilot not only fails to lower collective, but instead pulls up on the collective to keep the ship from going down, the rotor will stall almost immediately. When it stalls, the blades will either "blow back" and cut off the tail cone or it will just stop flying, allowing the helicopter to fall at an extreme rate. In either case, the resulting crash is likely to be fatal.

No matter what causes the low rotor RPM, the pilot must first roll on throttle and lower the collective simultaneously to recover RPM before investigating the problem. It must be a conditioned reflex. In forward flight, applying aft cyclic to bleed off airspeed will also help recover lost RPM.

## Appendix B

**ROBINSON**  
HELICOPTER COMPANY**Safety Notice SN-11**

Issued: Oct 82 Rev: Nov 00

**LOW-G PUSHOVERS - EXTREMELY DANGEROUS**

Pushing the cyclic forward following a pull-up or rapid climb, or even from level flight, produces a low-G (weightless) flight condition. If the helicopter is still pitching forward when the pilot applies aft cyclic to reload the rotor, the rotor disc may tilt aft relative to the fuselage before it is reloaded. The main rotor torque reaction will then combine with tail rotor thrust to produce a powerful right rolling moment on the fuselage. With no lift from the rotor, there is no lateral control to stop the rapid right roll and mast bumping can occur. Severe in-flight mast bumping usually results in main rotor shaft separation and/or rotor blade contact with the fuselage.

The rotor must be reloaded before lateral cyclic can stop the right roll. To reload the rotor, apply an immediate gentle aft cyclic, but avoid any large aft cyclic inputs. (The low-G which occurs during a rapid autorotation entry is not a problem because lowering collective reduces both rotor lift and rotor torque at the same time.)

Never attempt to demonstrate or experiment with low-G maneuvers, regardless of your skill or experience level. Even highly experienced test pilots have been killed investigating the low-G flight condition. Always use great care to avoid any maneuver which could result in a low-G condition. Low-G mast bumping accidents are almost always fatal.

**NEVER PERFORM A LOW-G PUSHOVER!!**

## Appendix C

**ROBINSON**  
 HELICOPTER COMPANY

**Safety Notice SN-24**

Issued: Sep 86 Rev: Jun 94


**LOW RPM ROTOR STALL CAN BE FATAL**

Rotor stall due to low RPM causes a very high percentage of helicopter accidents, both fatal and non-fatal. Frequently misunderstood, rotor stall is not to be confused with retreating tip stall which occurs only at high forward speeds when stall occurs over a small portion of the retreating blade tip. Retreating tip stall causes vibration and control problems, but the rotor is still very capable of providing sufficient lift to support the weight of the helicopter.

Rotor stall, on the other hand, can occur at any airspeed and when it does, the rotor stops producing the lift required to support the helicopter and the aircraft literally falls out of the sky. Fortunately, rotor stall accidents most often occur close to the ground during takeoff or landing and the helicopter falls only four or five feet. The helicopter is wrecked but the occupants survive. However, rotor stall also occurs at higher altitudes and when it happens at heights above 40 or 50 feet AGL it is most likely to be fatal.

Rotor stall is very similar to the stall of an airplane wing at low airspeeds. As the airspeed of an airplane gets lower, the nose-up angle, or angle-of-attack, of the wing must be higher for the wing to produce the lift required to support the weight of the airplane. At a critical angle (about 15 degrees), the airflow over the wing will separate and stall, causing a sudden loss of lift and a very large increase in drag. The airplane pilot recovers by lowering the nose of the airplane to reduce the wing angle-of-attack below stall and adds power to recover the lost airspeed.

The same thing happens during rotor stall with a helicopter except it occurs due to low rotor RPM instead of low airspeed. As the RPM of the rotor gets lower, the angle-of-attack of the rotor blades must be higher to generate the lift required to support the weight of the helicopter. Even if the collective is not raised by the pilot to provide the higher blade angle, the helicopter will start to descend until the



Wing or rotor blade unstalled and stalled.

## Appendix C cont

**ROBINSON**  
HELICOPTER COMPANY

---

## Safety Notice SN-24 (continued)

upward movement of air to the rotor provides the necessary increase in blade angle-of-attack. As with the airplane wing, the blade airfoil will stall at a critical angle, resulting in a sudden loss of lift and a large increase in drag. The increased drag on the blades acts like a huge rotor brake causing the rotor RPM to rapidly decrease, further increasing the rotor stall. As the helicopter begins to fall, the upward rushing air continues to increase the angle-of-attack on the slowly rotating blades, making recovery virtually impossible, even with full down collective.

When the rotor stalls, it does not do so symmetrically because any forward airspeed of the helicopter will produce a higher airflow on the advancing blade than on the retreating blade. This causes the retreating blade to stall first, allowing it to dive as it goes aft while the advancing blade is still climbing as it goes forward. The resulting low aft blade and high forward blade become a rapid aft tilting of the rotor disc sometimes referred to as "rotor blow-back". Also, as the helicopter begins to fall, the upward flow of air under the tail surfaces tends to pitch the aircraft nose-down. These two effects, combined with aft cyclic by the pilot attempting to keep the nose from dropping, will frequently allow the rotor blades to blow back and chop off the tailboom as the stalled helicopter falls. Due to the magnitude of the forces involved and the flexibility of rotor blades, rotor teeter stops will not prevent the boom chop. The resulting boom chop, however, is academic, as the aircraft and its occupants are already doomed by the stalled rotor before the chop occurs.

## Appendix D

**ROBINSON**  
HELICOPTER COMPANY

---

**Safety Notice SN-25**

Issued: Dec 86 Rev: Nov 99

**CARBURETOR ICE**

Carburetor ice can cause engine stoppage and is most likely to occur when there is high humidity or visible moisture and air temperature is below 70°F (21°C). When these conditions exist, the following precautions must be taken:

**During Takeoff** - Unlike airplanes, which take off at wide open throttle, helicopters take off using only power as required, making them vulnerable to carb ice, especially when engine and induction system are still cold. Use full carb heat (it is filtered) during engine warm-up to preheat induction system and then apply carb heat as required during hover and takeoff to keep CAT gage out of yellow arc.

**During Climb or Cruise** - Apply carb heat as required to keep CAT gage out of yellow arc.

**During Descent or Autorotation** -

R22 - Below 18 inches manifold pressure, ignore CAT gage and apply full carb heat.

R44 - Apply carb heat as required to keep CAT gage out of yellow arc and full carb heat when there is visible moisture.

**Appendix E****Safety Notice SN-29**

Issued: Mar 93 Rev: Jun 94

**AIRPLANE PILOTS HIGH RISK WHEN FLYING HELICOPTERS**

There have been a number of fatal accidents involving experienced pilots who have many hours in airplanes but with only limited experience flying helicopters.

The ingrained reactions of an experienced airplane pilot can be deadly when flying a helicopter. The airplane pilot may fly the helicopter well when doing normal maneuvers under ordinary conditions when there is time to think about the proper control response. But when required to react suddenly under unexpected circumstances, he may revert to his airplane reactions and commit a fatal error. Under those conditions, his hands and feet move purely by reaction without conscious thought. Those reactions may well be based on his greater experience, ie. the reactions developed flying airplanes.

For example, in an airplane his reaction to a warning horn (stall) would be to immediately go forward with the stick and add power. In a helicopter, application of forward stick when the pilot hears a horn (low RPM) would drive the RPM even lower and could result in rotor stall, especially if he also "adds power" (up collective). In less than one second the pilot could stall his rotor, causing the helicopter to fall out of the sky.

Another example is the reaction necessary to make the aircraft go down. If the helicopter pilot must suddenly descend to avoid a bird or another aircraft, he rapidly lowers the collective with very little movement of the cyclic stick. In the same situation, the airplane pilot would push the stick forward to dive. A rapid forward movement of the helicopter cyclic stick under these conditions would result in a low "G" condition which could cause mast bumping, resulting in separation of the rotor shaft or one blade striking the fuselage. A similar situation exists when terminating a climb after a pull-up. The airplane pilot does it with forward stick. The helicopter pilot must use his collective or a very gradual, gentle application of forward cyclic.

To stay alive in the helicopter, the experienced airplane pilot must devote considerable time and effort to developing safe helicopter reactions. The helicopter reactions must be stronger and take precedence over the pilot's airplane reactions because everything happens faster in a helicopter. The pilot does not have time to realize he made the wrong move, think about it, and then correct it. It's too late; the rotor has already stalled or a blade has already struck the airframe and there is no chance of recovery. To develop safe helicopter reactions, the airplane pilot must practice each procedure over and over again with a competent instructor until his hands and feet will always make the right move without requiring conscious thought. **AND, ABOVE ALL, HE MUST NEVER ABRUPTLY PUSH THE CYCLIC STICK FORWARD.**

Also see Safety Notices SN-11 and SN-24.

**Appendix F****ROBINSON**  
HELICOPTER COMPANY

---

**Safety Notice SN-31**

Issued: Dec 96

**GOVERNOR CAN MASK CARB ICE**

With throttle governor on, carb ice will not become apparent as a loss of either RPM or manifold pressure. The governor will automatically adjust throttle to maintain constant RPM which will also result in constant manifold pressure. When in doubt, apply carb heat as required to keep CAT out of yellow arc during hover, climb, or cruise, and apply full carb heat when manifold pressure is below 18 inches.

Also remember, if carb heat assist is used it will reduce carb heat when you lift off to a hover and the control may require readjustment in flight.



## Appendix G

### R22 ‘main rotor loss of control accidents’ since 1996 NTSB study

Since the NTSB study was published in 1996 there have been at least 16 fatal R22 accidents involving loss of main rotor control (including G-CHZN) – 10 in the USA and 6 elsewhere in the UK, France, Canada and New Zealand (Appendix H for full list). These were identified using primarily the NTSB’s accident database which included some but not all fatal R22 accidents outside the USA. These accidents all involved main rotor divergence and those accidents with evidence of an engine problem or which were associated with a loss of rpm at high altitude were excluded from the list. Out of the 10 accidents in the USA, one is still under investigation, and three were concluded to have been caused by ‘*Main rotor divergence for undetermined reason*’. Out of the 16, three were attributed to possible turbulence, five to possible low rpm, and one to low-g. Two of the accidents involved separation of a single main rotor blade at the coning bolt, and one accident, in addition to G-CHZN, involved separation of both main rotor blades at the coning bolt. These are discussed below.

On 17 January 2003 an R22 (registration ZK-HUL) suffered an in-flight breakup after departing from Masterton Aerodrome in New Zealand. The pilot had 157 hours on helicopters including 10.5 hours on the R22. Shortly after takeoff at about 400 feet, witnesses heard a loud noise and saw pieces flying off the helicopter and then it fell straight to the ground. One main rotor blade had detached from the hub and had ‘*fractured the hub trailing edge side mounting bolt hole area in overload.*’ This detached blade was found to have entered the cabin at an extreme, almost vertical angle, slicing off the left half of the canopy as well as the left door. An instructor had commented that this particular helicopter had a tendency for the collective pitch to increase when flown hands off with insufficient collective friction applied. The report stated that the pilot may have removed his hand from the collective in order to adjust the cyclic control trim with insufficient collective friction applied. The investigation concluded that the initiating factor was unlikely to have been an engine failure and that:

*‘the accident sequence was consistent with over-pitching of the main rotor, resulting in loss of control and the striking of the airframe by one main rotor blade.’*

On 20 February 2004 an R22 (registration C-FILW) suffered an in-flight breakup at Kumealon Inlet, British Columbia, Canada. The pilot had approximately 1,200 hours on the R22. There were no witnesses to the accident but one main rotor blade was found 150 m from the main wreckage site and it had separated following overload failure of the coning bolt. There was evidence of mast bumping but there were no obvious blade strikes to the airframe. The engine and its accessories demonstrated signatures of power/rotation at impact. Turbulence had been reported in the area and the investigation report concluded that:

*‘The helicopter encountered turbulent air that unloaded the main-rotor system resulting in damage that led to the helicopter becoming uncontrollable. Subsequent forces overloaded and broke one of the main rotor blade attachment bolts, and the blade separated.’*

On 27 June 2011 an R22 (registration N7779M) suffered an in-flight breakup near Del Valle, Texas, USA. This accident is still under investigation but the NTSB provided the following information. The pilot had logged 220 flight hours, all of which were on the R22. Witnesses reported seeing it flying just above the trees and as it crossed the Colorado River they heard a loud ‘pop’ or ‘bang’ and saw something fall off the helicopter into the river. Both main rotor blades were found to have separated at the coning bolt and were located 265 m and 297 m respectively from the main wreckage. Both bolts were determined to have failed in overload and a corner of the hub had also failed, similar to the hub on G-CHZN (Figure G1). There was also clear evidence of mast bumping. One pitch link had failed at the upper thread and the other pitch link had separated following failure of both attachment bolts (Figure G2).



**Figure G1**

Rotor head components recovered from R22 accident (N7779M) near Del Valle, Texas  
– blade roots have been cut for examination



**Figure G2**

Separated pitch link from R22 accident (N7779M) near Del Valle, Texas  
– bolts at both ends have failed

## Appendix H

### R22 'Loss of Main Rotor Control' Fatal Accidents since 1996 NTSB study

The following list excludes accidents with clear evidence of an engine failure or low rpm caused by high altitude. The list was established using primarily data from the NTSB database which captures some but not all non-US fatal R22 accidents.

6/1/2012, G-CHZN, Cambridgeshire, UK

Both main rotor blades separated in flight at the coning bolt. Left skid and left door separated in flight. Main rotor divergence for undetermined reason.

27/6/2011, N7779M, Del Valle, TX, USA

Both main rotor blades separated in flight at the coning bolt. Still under investigation.

09/12/2010, G-CBVL, France

Main rotor struck left door and left skid in flight. Possible turbulence. Still under investigation.

2/6/2010, N522SA, Spokane, WA, USA

Student pilot on a solo flight. Helicopter 'fell' to ground and tail boom separated. Witnesses observed 'V-shaped' main rotor. Possible low rotor rpm. Still under investigation.

20/9/2009, N956SH, Forest Grove, OR, USA

An instructor and a pilot training to become an instructor were seen to be performing autorotations. Main rotor blades were bent upwards and teeter stops split. Tail boom intact. Low rpm bulb filament stretched. Attributed to low rotor rpm.

31/1/2009, N4160A, Fillmore, CA, USA

Main rotor severed tail boom in flight. Both main rotor blades bent up. '*There was no evidence found that would explain the main rotor disc's divergence from the normal plane of rotation and its subsequent contact with the tail boom.*'

13/3/2008, N2215R, Wilmington, NC, USA

Both main rotor blades coned up. Evidence of in-flight tail boom strike. Attributed to low rotor rpm.

27/11/2004, N4029Q, Arlington, WA, USA

Both doors separated in flight. Some evidence of tail boom contact. Door pins not installed. '*The initiating event that produced the main rotor divergence could not be determined.*'

29/08/2004, N871CL, Northport, NY, USA

Main rotor shaft separated and both pitch links failed. No tail boom damage. Possible low-g to avoid a kite.

20/02/2004, C-FILW, British Columbia, Canada

In-flight breakup. One main rotor blade separated in flight at the coning bolt. Possible turbulence.

17/01/2003, ZK-HUL, Masterton, New Zealand

In-flight breakup shortly after takeoff. One main rotor blade detached from the hub. Attributed to inadvertent over-pitching of the main rotor.

13/07/2002, G-VFSI, Warwickshire, UK

Tail boom separated. Mast bumping. Possible inadvertent control input by passenger.

16/05/2001, C-FHRL, British Columbia, Canada

Flight instructor and student onboard. Tail boom separated and mast bent. Main rotor seen stationary and coned up. Attributed to low rotor rpm due to possible carburettor icing.

18/08/2000, N8313Z, Watsonville, CA, USA

Student pilot. Main rotor shaft separated. Damage to left door and left skid. *'The initiating event that produced the main rotor divergence could not be determined.'*

26/2/1998, N8457J, Littlerock, CA, USA

Main rotor shaft separated. Attributed to mountain wave turbulence.

19/10/1996, N512HH, Halsey, OR, USA

Main rotor blades separated (both bent or broken upward). Tail boom separated. Overload failure of one pitch link. No hub to mast contact. Low rpm and oil bulb filaments stretched. Attributed to low rotor rpm.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Schleicher ASW 24, G-CGDU   |                   |
| <b>No &amp; Type of Engines:</b>       | N/A   |                   |
| <b>Year of Manufacture:</b>            | 1991 (Serial no: 24118)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 30 April 2012 at 1342 hrs   |                   |
| <b>Location:</b>                       | Near Dunstable, Bedfordshire  |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - 1 (Fatal)  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Aircraft destroyed  |                   |
| <b>Commander's Licence:</b>            | BGA Gliding Certificate   |                   |
| <b>Commander's Age:</b>                | 65  |                   |
| <b>Commander's Flying Experience:</b>  | 274 hours (of which 10 were on type)<br>Last 90 days - 17 hours<br>Last 28 days - 8 hours |                   |
| <b>Information Source:</b>             | AAIB Field Investigation  |                   |

**Synopsis**

The pilot was carrying out his second flight of the day from a winch launch. He turned downwind and was seen to make an orbit to the right before continuing downwind. The glider made a brief, steep, wings-level climb before levelling off at a height of about 300 ft. It then banked to the left, before entering what was described as a spiral dive to the right. After turning through approximately 270°, the glider impacted the ground in a steep nose-down attitude. The pilot was fatally injured. The most likely cause of the accident was a stall leading to a loss of control, with insufficient height available to recover.

**History of the flight**

The weather conditions at the gliding site near Dunstable were good, but with a blustery wind from the south-east, estimated at 10 to 15 kt, with some stronger gusts. Recorded wind data from an anemometer located at a proposed wind farm site close to Stoke Hammond, some 8 nm north-west of the gliding site, indicated a wind around the time of the accident of generally 130° at 14 kt, gusting 24 kt. The visibility was in excess of 10 km and there was scattered cumulus cloud with a base of 4,500 ft. A red wind sock was being flown at the gliding site. This indicated to pilots that the weather conditions were such that it was recommended that only instructor pilots and those with a Silver standard gliding qualification should fly. Although the pilot was not an instructor and did not hold a Silver qualification,

he had recently returned from a club trip to the Pyrenees where he had flown in more challenging conditions.

The pilot had considered taking an aero-tow for his first launch, but given the wind direction, he elected to carry out a winch launch. He flew a circuit to the right and returned to the field. After lunch he carried out a second winch-launched flight. The glider released from the launch at 900 ft aal and made a right turn, flying along the line of the Dunstable Downs ridge. It then made a gentle, continuous turn to the right through approximately 180°, followed by a single orbit to the right, rolling out on a northerly heading. Shortly thereafter the glider was seen by a witness to pull up steeply and level off. It then banked to the left before entering a spiral dive which the witness thought was to the right.

The glider was seen by other witnesses to be in a steep nose-down attitude before impacting the ground in a field of crops, fatally injuring the pilot. One witness described the glider skidding or yawing with its nose to the right prior to impact.

### Weight and balance

The glider maximum allowable takeoff mass was 500 kg. The empty mass was 253 kg, as shown on the Weighing Record. The pilot's weight plus parachute and equipment was 110 kg, giving an all up mass of 363 kg for the accident flight.

|                          |               |                |                |
|--------------------------|---------------|----------------|----------------|
| <i>Air Brake Setting</i> | <i>320 kg</i> | <i>410 kg</i>  | <i>500 kg</i>  |
| <i>Closed</i>            | <i>35 kt</i>  | <i>39.5 kt</i> | <i>43.5 kt</i> |

### Aircraft operating manual

The operating manual contains two pieces of information relevant to the accident. These are:

The 1g stall speeds, which are promulgated at paragraph 5.2.2, shown in Table 1.

Paragraph 3.6 sets out the procedure for recovery from a spiral dive [sic]:

#### *'Spiral Dive Recovery*

*Depending on the aileron position during spinning with forward C.G. positions - that is: the C.G. range when the ASW 24 will no more sustain a steady spin - it will immediately or after a few turns develop a spiral dive, or slipping turn similar to a spiral dive.*

*These conditions will both be terminated by:*

- (1) applying opposite rudder*
- (2) applying aileron opposite to direction of turn.'*

### Stalls

The British Gliding Association (BGA) Instructor Manual, Chapter 18, provides a comprehensive description of stall recognition and recovery and lesson plans for teaching this.

**Table 1**

Stall speeds at prescribed glider weights; airbrakes closed

Of significance in this accident is the combination of the glider's groundspeed and the tailwind component during the level-off after the steep pull-up manoeuvre, which would have placed the glider's airspeed close to the 1g stall airspeed of around 37 kt. A pull up will cause a loss of airspeed and levelling off results in a reduction in g. If the airspeed decays slightly below the normal 1g stall speed whilst levelling off, the glider will not stall. However, once the glider returns to the 1g state, it is in then danger of stalling unless corrective action is taken. If the glider is yawed or turning at this point, the stall may be accompanied by a wing drop. The Manual explains that recovery from this situation requires two actions: firstly, lowering the nose to unstall the wing and attain a safe airspeed and secondly, levelling the wings before pulling out.

### **Medical and pathological information**

The post-mortem examination showed that the pilot had died of multiple injuries sustained as a result of the accident. The pathologist also reported that there was no evidence of drugs or alcohol having been consumed, nor was there any evidence of natural disease which could have contributed to the accident.

### **Engineering investigation**

The aircraft damage and ground impact marks were consistent with the effects of the aircraft striking the ground in a right hand spiral dive.

Examination of the wreckage showed that the glider was structurally complete prior to impact, with the landing gear retracted and the airbrakes closed. No evidence of any pre-impact failure was found in the structure or controls. The aircraft damage was consistent with the expected effects of impacting the ground in a spiral dive.

### **Recorded data**

Two GPS receivers and an iPAQ Personal Digital Assistant (PDA) were recovered from the glider.


The Garmin GPSIII Pilot did not record any data but was used to pass GPS data to the iPAQ which recorded the GPS position and GPS altitude once per second. The iPAQ recorded both the first flight of the day and the subsequent accident flight (Figure 1). The recording of the accident flight stopped whilst in the air in the vicinity of the accident site, most likely due to the loss of buffered data when the iPAQ was damaged in the impact. This installation used a GPS antenna mounted on the glider.

The Garmin GPSMAP 60Cx also recorded the accident flight. A new sample point was only recorded whenever there was sufficient change in the position or motion to trigger it. This resulted in a less comprehensive recording than the iPAQ recording. The portable unit used an integral GPS antenna; the location of the unit in the cockpit was unknown. The data extends to the ground but is unreasonable at the end, most likely due to the loss of sight of sufficient GPS satellites to generate an accurate position.

Figure 2 shows the iPAQ recorded GPS altitude data for the accident flight, as well as the derived altitude rate and derived groundspeed. The accident flight started at 1329 hrs and the recording ended approximately three minutes later.

### **Analysis**

The pilot had completed a flight in the morning, the profile of which was recorded on the iPAQ. He did not raise any issues regarding that flight, which appears to have been conducted safely. He did not execute any pull-up manoeuvre on the first flight.



**Figure 1**


The first (green) and second/accident (red) flights

On the accident flight, for a reason that was not determined, the pilot elected to execute a pull-up manoeuvre. A possible explanation is that he was exploiting an area of lift, in order to gain height. The GPS data show that the glider's groundspeed reduced to 47 kt as it reached the top of the pull up, at which point it banked to the left. The wind direction and strength was such that it would have produced a tailwind component of 10 kt or possibly greater, given the gusty conditions. This, in combination with the low groundspeed, indicates that the glider's airspeed

would have been close to, or possibly even below, the 1g stall speed of 37 kt for the given weight.

It is not known if the bank to the left was the pilot's intention or the result of a wing drop, but the witness evidence suggests that the glider then stalled and entered a spiral dive to the right, from which there was insufficient height to recover. The wreckage examination confirmed that the aircraft was in a right hand spiral dive on impact.





**Figure 2**

Recorded GPS altitudes and derived altitude rates and ground speeds for the accident flight, sourced from the iPAQ

## Conclusion

The investigation concluded that the probable cause of the accident was a stall and loss of control due to an excessive loss of airspeed during a pull-up manoeuvre. There was insufficient height available to execute a recovery.



## **AAIB correspondence reports**

These are reports on accidents and incidents which were not subject to a Field Investigation.

They are wholly, or largely, based on information provided by the aircraft commander in an Aircraft Accident Report Form (AARF) and in some cases additional information from other sources.

The accuracy of the information provided cannot be assured.



**SERIOUS INCIDENT**

|  |   |
|--|---|
| <b>Aircraft Type and Registration:</b> | Airbus A319-111, G-EZDN   |
| <b>No &amp; Type of Engines:</b>       | 2 CFM56-5B5/3 turbofan engines  |
| <b>Year of Manufacture:</b>            | 2008 (Serial no: 3608)  |
| <b>Date &amp; Time (UTC):</b>          | 4 July 2012 at 1405 hrs   |
| <b>Location:</b>                       | Prague Airport, Czech Republic  |
| <b>Type of Flight:</b>                 | Commercial Air Transport (Passenger)  |
| <b>Persons on Board:</b>               | Crew - 6                      Passengers - 149  |
| <b>Injuries:</b>                       | Crew - None                      Passengers - None  |
| <b>Nature of Damage:</b>               | None  |
| <b>Commander's Licence:</b>            | Airline Transport Pilot's Licence   |
| <b>Commander's Age:</b>                | 52 years  |
| <b>Commander's Flying Experience:</b>  | 13,500 hours (of which 5,000 were on type)<br>Last 90 days - 204 hours<br>Last 28 days - 43 hours |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot and company air safety report                |

**Synopsis**

The pilots calculated takeoff performance using the full length of Runway 24 at Prague, when in fact the available runway length was considerably reduced by temporary works. They realised the mistake during takeoff when the aircraft approached works at the temporary runway end.

**Description of the event**

The two pilots reported for duty at Stansted Airport at 0600 hrs to fly a four-sector duty. In their pre-flight briefing package, the crew noted a NOTAM for Prague Airport to the effect that the available length of Runway 24 was temporarily reduced by works from 3,715 m to 2,500 m.

The aircraft landed at Prague on Runway 30 after the third sector of the duty and the flight crew started preparation for their final flight to Stansted. The runway in use for takeoff was Runway 24; the pilots listened to the ATIS broadcast, but it was reportedly in heavily accented English. They did not glean from it that the runway length was reduced, and had forgotten the content of the associated NOTAM seen at the pre-flight stage. Thus, the airport details copied by the co-pilot to the paper flight plan did not contain any reference to the reduced length, and their subsequent takeoff performance calculations were based upon takeoff using the normal runway length. The commander later attributed the oversight to reduced crew awareness at the end of a lengthy duty period.

The pilots' route manuals contained airport charts for both the normal (full runway length) and the temporary (reduced) distances. As the crew were not aware during planning that the available length was reduced, they referred only to the normal charts. The commander considered that the presence of both normal and temporary charts in the route manual contributed to the incident. He also noted that the crew's pre-flight activities had been interrupted by a visit to the flight deck by an acquaintance, and thought that this distraction may also have been a factor.

The work in progress on Runway 24 was at the departure end, not easily visible to the crew at the start of the takeoff roll. Also, as the aircraft had landed on Runway 30, the crew had not seen the works at that stage either. The commander noted later that there were no warnings from ATC<sup>1</sup> or ground signage indicating that the runway length was reduced.

The takeoff run appeared normal to the pilots until the point they realised the aircraft was rapidly approaching works on the runway. The aircraft rotated and became airborne at the planned speeds but approached much closer to the works than would have been intended. The event posed a considerable distraction for the crew which, combined with a frequency change immediately after takeoff, led to them failing to select the landing gear up or check that it was retracted prior to reaching landing gear limit speed. Flap retraction was normal, and the aircraft continued to its destination.

---

**Footnote**

<sup>1</sup> The ATIS content regarding runway length was a valid form of communication for the runway length information and standard procedures require that crews acknowledge to ATC the most recent ATIS received, using its identifying letter.

**ACCIDENT**

|  |  |
|--|--|
| <b>Aircraft Type and Registration:</b> | Airbus A320-214, G-MRJK  |
| <b>No &amp; Type of Engines:</b>       | 2 CFM 56-5B4/2P turbofan engines   |
| <b>Year of Manufacture:</b>            | 1999 (Serial no: 1081)   |
| <b>Date &amp; Time (UTC):</b>          | 30 May 2012 at 0624 hrs  |
| <b>Location:</b>                       | London Luton Airport   |
| <b>Type of Flight:</b>                 | Commercial Air Transport (Passenger)   |
| <b>Persons on Board:</b>               | Crew - 6                      Passengers - 180   |
| <b>Injuries:</b>                       | Crew - None                      Passengers - None   |
| <b>Nature of Damage:</b>               | G-MRJK - Right stabilizer<br>G-OZBM - APU tail cone  |
| <b>Commander's Licence:</b>            | Airline Transport Pilot's Licence  |
| <b>Commander's Age:</b>                | 48 years   |
| <b>Commander's Flying Experience:</b>  | 10,512 hours (of which 6,317 were on type)<br>Last 90 days - 26 hours<br>Last 28 days - 16 hours |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB           |

**Synopsis**

G-MRJK was being pulled forward onto the taxiway centreline after pushback from Stand 43 at London Luton Airport when it collided with G-OZBM, parked on Stand 46 directly behind it. Both aircraft were damaged.

**History of the flight**

The tug intended to push G-MRJK from Stand 43, on the East Apron, would not start. The only available replacement tug and towbar, which were the largest operated by the handling agent and approximately 2.5 m longer than the original equipment, were brought to the stand and the pushback commenced. A headset operative was in attendance. The weather was clear with a low sun.

Initially, G-MRJK was pushed back and to its left towards a blast fence, so that its tail pointed into the south-west corner of the East Apron. The headset operative stood to the aircraft's left in order to monitor the proximity of the blast fence and maintain visual contact with the aircraft commander. When the aircraft was pointing into the corner the tug driver judged that its main landing gear had not crossed the rear of a stand road that passes behind Stands 46 to 48, and that the nosewheel had not crossed the taxiway centreline. G-MRJK was then pulled forward to line up with the taxiway centreline so that it could exit the East Apron under its own power. As G-MRJK was being pulled forward its right horizontal stabilizer made contact with the APU tail cone of the

unoccupied G-OZBM, which was on Stand 46 directly behind Stand 43. Figure 1 shows layout of the East Apron and the approximate position of each aircraft at the point of collision.


A passing dispatcher who witnessed the pushback thought that the aircraft would collide just before G-MRJK was stopped. As it was pulled forward he saw a small object fall off one of the aircraft and raised the alarm to the pushback team, via his manager, after the aircraft had come to a stop prior to the tug being disconnected. Neither pilot on G-MRJK felt the impact, nor did the tug driver.

G-MRJK sustained significant damage to its right horizontal stabilizer, G-OZBM sustained a scrape to its tail cone.

This was the first recorded pushback incident on the East Apron.

### Pushback procedures

The pushback was 'S' shaped, 'non-standard' and different from the pushback modelled for this stand by the airport operator. The pushback model had not been shared with the handling agent, however. The airport operator commented that the choice of pushback was a matter of airline, handling agent or tug driver preference.



**Figure 1**

Approximate position of the aircraft at the time of the collision.



The handling agent had not performed a risk assessment of pushbacks from individual stands where a 'non-standard' pushback was required, as was the case on the East Apron.

It was commonly accepted that, to ensure the tail of an aircraft did not encroach the rear of the stand road opposite, the aircraft's nosewheel should not cross the taxiway centreline during pushback. This was not a formal procedure, however, and the handling agent noted that it was sometimes necessary to push the nosewheel over the centreline in order to position an aircraft.

An airport instruction existed requiring an individual at the back-of-stand roadway to stop traffic prior to an aircraft crossing the road when being pushed back. After this incident the handling agent considered placing another person on the other side of the taxiway on the opposite road but during trials found that such a person could not be seen by the pushback team and would not be useful. There was no local instruction requiring one.

The handling agent reported that its training package did not state clearly that, if a pushback driver was unsure of the clearance of an aircraft, the driver should stop the pushback and check.

### **Ground handler's comments**

The tug driver and headset operative stated that the rising sun was very bright and glare off the taxiway affected their vision during the pushback to such an extent that it was difficult to determine the position of the rear of the aircraft relative to the rear of stand road and the taxiway centreline; neither was in possession of sunglasses.

#### *Tug driver*

The tug driver commented that at the time of the incident he was suffering from the symptoms of a cold and felt

tired, coming to the end of a night shift which started at 2000 hrs the previous evening and during which he had not had a break. However, he did not think this impaired his judgement.

He added that he had, on several occasions, pushed aircraft from Stand 43 while Stand 46 was occupied, without incident and using the same method and reference point to determine when to stop the aircraft. He was aware that the aircraft's nosewheel should not cross the taxiway centreline and believed it had not done so on this occasion.

### **Discussion**

During the pushback the tug driver and headset operative were dazzled by glare from the sun reflected off the taxiway, which meant that they could not see the rear of the aircraft clearly. Their ability to judge the manoeuvre may also have been affected by the use of a tug and towbar combination longer than that to which they were accustomed. Consequently, the rear of the aircraft was pushed back over the rear of stand road where it encroached into Stand 46. The tug driver was tired and had symptoms of a cold, which may have affected his judgement.

### **Safety actions**

As a result of this incident the aircraft handling agent has stopped using the long tug and towbar to pushback aircraft on the East Apron. It will also conduct risk assessments of all 'non-standard' pushbacks at every airport where it operates.

The handling agent will amend its driver training package to state clearly that if a tug driver is unsure of the clearance of the aircraft, he should stop the pushback and check.

The airport operator's pushback models have been shared with the handling agent and will be used in training to increase pushback driver awareness.

**INCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Boeing 757-2K2, G-LSAN   |                   |
| <b>No &amp; Type of Engines:</b>       | 2 Rolls-Royce RB211-535E4 turbofan engines   |                   |
| <b>Year of Manufacture:</b>            | 1994 (Serial no: 26635)  |                   |
| <b>Date &amp; Time (UTC):</b>          | 7 August 2012 at 1535 hrs  |                   |
| <b>Location:</b>                       | Over the North Sea, approximately 85 nm north-east of Newcastle Airport                          |                   |
| <b>Type of Flight:</b>                 | Commercial Air Transport (Non-Revenue)   |                   |
| <b>Persons on Board:</b>               | Crew - 2   | Passengers - 1    |
| <b>Injuries:</b>                       | Crew - None  | Passengers - None |
| <b>Nature of Damage:</b>               | None   |                   |
| <b>Commander's Licence:</b>            | Airline Transport Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 51 years   |                   |
| <b>Commander's Flying Experience:</b>  | 8,058 hours (of which 6,017 were on type)<br>Last 90 days - 136 hours<br>Last 28 days - 41 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB           |                   |

**Synopsis**

Approximately three hours of a post-maintenance airtest had elapsed when the flight crew identified a lateral fuel imbalance, which they determined as being caused by a fuel leak from the right engine. The flight crew carried out the 'Engine Fuel Leak' QRH checklist which resulted in the right engine being shut down, following which the crew made a single-engine diversion and landing at Newcastle Airport, without further incident. The cause of the fuel leak was identified as a damaged O-ring seal in a part of the right engine's fuel system that had been recently replaced due to embodiment of a recommended Service Bulletin. The engine manufacturer and maintenance organisation involved are both implementing safety actions intended to prevent a recurrence.

**History of the flight**

The aircraft had undergone a 'C-check' maintenance inspection and, following two uneventful post-maintenance flights totalling 1 hour and 20 minutes, was being flown on an airtest prior to release to service. Approximately three hours of the airtest had elapsed when, during a routine fuel check, the crew noticed a lateral fuel discrepancy of approximately 600 kg, with the right wing fuel tank quantity indicating less than the left wing fuel tank. Shortly afterwards the EICAS FUEL CONFIG warning illuminated as the fuel imbalance increased to 800 kg.


The flight crew carried out the 'Fuel Configuration' section of the quick-reference handbook (QRH), which

further directed them to complete the QRH's 'Engine Fuel Leak' checklist; this required a visual check for an engine fuel leak. An engineering observer who was aboard the aircraft for the airtest reported that he could see fuel leaking from the right engine and this was visually confirmed by the first officer. The commander made a PAN radio call to Scottish ATC and requested a direct routing to Newcastle Airport, some 85 nm to the south west, which he determined to be the closest suitable airport. The flight crew then completed the 'Engine Fuel Leak' checklist by shutting down the right engine, following which they carried out an uneventful single-engine diversion and landing at Newcastle Airport.

### Engineering inspection

Inspection of the right engine's fuel system revealed that the source of the fuel leak was the pump-end flanged joint of the fuel supply tube running between the high pressure (HP) fuel pump and the fuel flow governor (Figure 1). This fuel tube had been installed during the C-check as part of a recommended Service Bulletin, RB.211-73-G230. This Service Bulletin recommends the replacement of earlier standards of fuel tube that were the source of previous fuel leaks; the AAIB report on G-TCBA, published in AAIB Bulletin 4/2011, refers to one such incident.

When the fuel supply tube was removed from the engine, one of the two bolts that attached the flange to the HP fuel pump body was found to be only finger-



*Figures courtesy of Rolls-Royce and Boeing*


**Figure 1**

Location of the supply and overspill fuel tubes between the HP fuel pump and fuel flow governor, including detail of the supply tube's flanged end fitting

tight and the flange's O-ring seal was damaged, with a section missing (Figure 2). Both attachment bolts were new items that had been fitted during the installation of the fuel tube, however the bi-hex head of the lower bolt exhibited an unexpected degree of galling (Figure 3), consistent with a socket slipping off the head of the bolt during tightening of the bolted-flange joint.

The threads on the lower bolt were found to be damaged, as was the start thread of the wire-thread insert in the pump body which had been displaced upwards slightly, and metallic debris was present on the insert's threads.

Examination of the damaged thread forms showed that the bolt had not been cross-threaded, rather that the start thread of the wire-thread insert had 'picked up' during insertion of the bolt, causing a progressive rounding-over of the bolt's threads as the bolt was tightened. A subsequent trial at the HP fuel pump manufacturer's overhaul facility, using a new bolt in the same hole, showed that whilst similar damage occurred to the bolt threads, the bolt torque specified in the Service Bulletin, 102 lbf-in, was only achieved when the flanged joint was fully fastened. It is therefore unlikely that the damaged wire-thread insert caused the lower bolt to remain only



**Figure 2**

Damaged O-ring seal, pump body and wire-thread insert



**Figure 3**

Lower bolt showing damaged threads and galling marks on head

partially inserted, despite the required bolt torque value being applied during assembly of the tube to the fuel pump. The torque wrench used during the installation of the fuel tubes was checked, determined to perform within calibration limits, and was declared to be serviceable.

The face of the pump body, to which the fuel tube adjoins, exhibited fresh galling and scratch marks around the lower bolt hole and around the periphery of the fuel tube flange interface, indicating that a degree of difficulty was experienced in assembling the fuel tube to the pump body.

#### **Maintenance actions preceding the incident**

In order to progress the planned maintenance activity on the aircraft, embodiment of the Service Bulletin had taken place whilst the right engine was removed from the aircraft and installed in a transport cradle, as both of the aircraft's pylons had been removed for other, unrelated, maintenance purposes. The lower parts of the engine, including the area where the fuel tubes were to be replaced, were close to the ground and partially obstructed by the cradle's steel framework. These restrictions made access significantly more difficult than if the engine had been mounted on its pylon, or in an engine overhaul fixture.

The Service Bulletin was accomplished in a hangar by a mechanic and inspected by a licensed engineer, both of whom were familiar with the task. The mechanic described the access to the fuel tubes and the visibility of the fuel tube's flanged joints at the HP fuel pump as "not good". He experienced initial difficulty in retaining the fuel tube O-rings when using fuel as a lubricating and retaining fluid and applied 'Nycos 65' petroleum grease to retain the O-rings within their grooves. Whilst Nycos 65 was effective in retaining the O-rings, it is not an approved material for use in the engine fuel or oil systems as it does not readily dissolve in fuel or oil, and may block small metering orifices in fuel control systems.

The mechanic installed and tightened the fuel tube bolts in accordance with the Service Bulletin instructions; for each fuel tube this required tightening three bolts at the fuel flow governor end of the tube before then tightening the two bolts at the HP fuel pump. He reported that the flanged joints on both fuel tubes appeared to be properly seated and flush, as did the licensed engineer who inspected and certified the task. On completion of the C-check the aircraft's engines were ground run at full power and no leaks were detected from either engine. The aircraft was subsequently flown to Norwich Airport for repainting before returning to the

maintenance provider's base and no fuel leaks were experienced on either of these sectors.

### **Engine manufacturer's investigation**

Following the incident the engine manufacturer conducted an investigation into the installation difficulty of both the supply and overspill return fuel tubes as specified in the Service Bulletin. This activity showed that for both fuel tubes, it was significantly easier for a mechanic to align and torque the HP fuel pump flange bolts before then tightening the fuel flow governor flange bolts, which is the reverse of the bolt tightening sequence specified in the Service Bulletin. Retention of the O-rings within the grooves in the fuel tube flanges was also identified as a problem, particularly at the HP fuel pump ends where access and visibility are limited. Application of a viscous assembly fluid to specification OMat 1069, which is approved for use on fuel system components, was identified as a suitable measure to retain the O-rings during assembly of the joints.

### **Analysis**

The nature of the damage to the fuel supply tube's O-ring was consistent with it becoming partially displaced and subsequently pinched during the assembly of the tube's joint to the HP fuel pump. The failure of the O-ring was insidious in that no leak occurred during the full power ground run and eventual failure of the O-ring under fuel pressure loading occurred only after 4 hours and 20 minutes of flight had elapsed. The detachment of the pinched section of O-ring reduced the end load on the fuel tube flange, causing the upper attachment bolt to appear to be only finger-tight immediately after the diversion to Newcastle Airport.

The galling damage observed on the lower flange bolt and pump body, together with the damaged wire-thread insert suggests that difficulties were experienced

during alignment of the flange's bolt holes to the fuel pump body. The investigation conducted by the engine manufacturer confirmed that tooling and visual access to both pairs of flange bolts at the fuel pump is limited, and that locating and tightening the bolts was made additionally difficult by the assembly sequence specified in the Service Bulletin.

### **Conclusion**

The fuel leak was caused by the fuel supply tube's O-ring seal becoming trapped in the joint between the tube and the HP fuel pump body during assembly, before subsequently failing under fuel pressure load during flight. Two contributory factors were identified in the investigation: embodiment of the Service Bulletin whilst the engine was mounted in a transport cradle, which made access to the fuel tubes more difficult than if the engine had been mounted on its pylon, and the bolt-tightening sequence specified in the Service Bulletin, that exacerbated the difficulty of aligning the fuel tube to the HP fuel pump and therefore increased the probability of displacement the O-ring from the tube's flange groove.

### **Safety actions**

The engine manufacturer is revising the Service Bulletin and engine manual to require that the fuel flow governor supply and overspill return tubes have their bolts tightened in the opposite order to that presently specified. The modified Service Bulletin text will also include a recommendation to apply a viscous assembly fluid to OMat 1069 specification to aid, during assembly, retention of the O-rings within their grooves in the tube end flanges.

The maintenance organisation is drafting a Quality Advisory Notice to its staff to communicate the findings of this investigation in addition to similar findings

from an internal MEDA investigation carried out following the fuel leak event. The organisation has also classified the Service Bulletin as a '*Flight Safety Sensitive Task*', requiring independent inspection during

the critical stages of the task including installation of the O-ring seals, lubrication with viscous assembly fluid, installation of the fuel tubes and torque tightening of the attachment bolts.



**SERIOUS INCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Hawker Hunter T7, G-VETA   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Rolls Royce Avon Mk 122 turbojet engine  |                   |
| <b>Year of Manufacture:</b>            | 1958 (Serial no: 41H-693751)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 16 September 2012 at 1151 hrs  |                   |
| <b>Location:</b>                       | Cotswold Airport (Kemble), Gloucestershire   |                   |
| <b>Type of Flight:</b>                 | Private  |                   |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - None |
| <b>Injuries:</b>                       | Crew - None  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Under-wing fuel drop tank damaged  |                   |
| <b>Commander's Licence:</b>            | Airline Transport Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 48 years   |                   |
| <b>Commander's Flying Experience:</b>  | 12,985 hours (of which 25 were on type)<br>Last 90 days - 185 hours<br>Last 28 days - 65 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot   |                   |

**Synopsis**

The aircraft's left inboard fuel drop tank detached during landing. A technical investigation by the aircraft operator established that insufficient clearances and free play within the tank release mechanism created a situation whereby the drop tank could detach with a relatively small externally applied force.

**History of the flight**

During the landing rollout on Runway 26, the pilot was advised by ATC that something had dropped from his aircraft. There were no adverse handling effects, and ATC subsequently advised that it was believed to be a fuel drop tank which had detached. The aircraft was taxied to parking, accompanied by a fire tender. No fuel leaks were apparent.

The left inboard drop tank had detached, with no damage to the airframe. The pilot reported that the drop tanks had been partially filled at departure, all in-flight fuel indications were normal, and the drop tanks had emptied well before the aircraft returned for what was described as a gentle landing.

**Technical investigation**

The aircraft operating company conducted an internal investigation into the incident. The drop tank is held in place by an electro-mechanical release unit (EMRU), whose jaws close around a lug on the top of the drop tank to hold it in place. A jettison system test was carried out, which the EMRU passed. However, when the weight used for the test was shaken severely and forward

pressure was applied, the jaws of the EMRU released the weight. This effect was repeated several times. The EMRU from the right side was substituted for the suspect unit, but the fault reoccurred. When the left EMRU was fitted to the right side, the fault did not occur, thus ruling out the EMRU as the source of the problem.

The investigation then turned to the left pylon fusing and release housing (FRH), which contains the EMRU. It was found that there was insufficient clearance between the manual release and reset plungers and the top of the FRH casing. It was also noted that the release plunger did not have very much free play and travel before it actuated the internal latching mechanism. There was a notable difference between the left and right FRHs in these respects, and tests on several spare FRHs found the free play and travel to be consistently greater than those of the FRH installed on the aircraft's left pylon.

A replacement FRH was fitted and the pylon reassembled using the original EMRU. The release system was then tested and found to be working normally. The investigation concluded that the uncommanded release of the drop tank had occurred due to a combination of the inadequate clearance and free play, which acted to produce a 'hair trigger'. This then required only a slight jolt on landing to cause the mechanical release of the FRH internal latching mechanism and drop tank release.

### Previous occurrence

On 18 October 2008, a Hunter F6A was involved in a similar incident, in which the left drop tank also detached on landing (AAIB reference EW/C2008/10/14). Tests on that occasion did not reveal any faults with the tank jettison system, and it was presumed that the force on the EMRU jaws imparted at the moment of landing had been sufficient to cause them to open sufficiently to release the tank.

The AAIB report into the incident observed that Swiss registered Hunters were equipped with a clamp lock around the jaws of the inboard EMRUs to prevent them from opening. This prevented the inboard drop tanks from being jettisoned, either deliberately or inadvertently. However, the report also noted that the Hunter was accepted on to the UK register under a Permit-to-Fly based on an aircraft standard that did not include the Swiss modification. Thus, the modification was not cleared for use on UK aircraft. The position of the UK CAA was that the safety record of the aircraft standard as cleared for flight did not give grounds for concern.

### Advice on jettisoning fuel tanks

Civil Aviation Publication (CAP) 632 details the terms under which ex-military aircraft can be operated on the UK register under a Permit-to-fly. It states that:

*'drop tanks should only be jettisoned as a last resort and when their retention would imperil the aircraft and crew and bring increased risk to persons on the ground'. It also states that 'pilots should be aware that empty drop tanks have a negligible effect on gliding or range performance of jet aircraft. Therefore, consideration should be given to retaining them in the event of forced landing.'*

### Safety action

The aircraft operator consulted other operators of Hawker Hunter aircraft (including a military test pilot current on type), as well as original aircraft documentation. Considering also the published advice from the CAA concerning drop tanks, and the in-service experience of the Swiss modification, the operator concluded that it would be desirable to disarm the inboard drop tank jettison system (the outboard drop tank jettison

systems may not be disarmed due to aircraft operating limitations).

The aircraft operator has expressed an intention to consult the UK CAA with a view to obtaining approval for a modification to allow the inboard fuel drop

tank jettison system to be inhibited. The proposed modification would entail electrical and mechanical isolation of the system, together with a mechanical lock the same as, or similar to, that used on Swiss Hunters.

**SERIOUS INCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Sikorsky S-76C, G-CGOU   |                   |
| <b>No &amp; Type of Engines:</b>       | 2 Turbomeca Arriel 2S2 turboshaft engines  |                   |
| <b>Year of Manufacture:</b>            | 2010 (Serial no: 760780)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 26 September 2012 at 0825 hrs  |                   |
| <b>Location:</b>                       | 19 nm east-north-east of Humberside Airport  |                   |
| <b>Type of Flight:</b>                 | Commercial Air Transport (Passenger)   |                   |
| <b>Persons on Board:</b>               | Crew - 2   | Passengers - 8    |
| <b>Injuries:</b>                       | Crew - None  | Passengers - None |
| <b>Nature of Damage:</b>               | None   |                   |
| <b>Commander's Licence:</b>            | Airline Transport Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 47 years   |                   |
| <b>Commander's Flying Experience:</b>  | 3,750 hours (of which 1,700 were on type)<br>Last 90 days - 113 hours<br>Last 28 days - 36 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot   |                   |

**Synopsis**

There was a smell of smoke in the cockpit and cabin during flight, together with an unusual and uncommanded flying motion. A precautionary landing was made, and a subsequent investigation identified that an electrical short had occurred in a wiring loom.

**History of the flight**

The helicopter was flying from Humberside Airport to a platform in the Ravenspurn Gas Field when the incident occurred. During a short cruise climb, the helicopter began to pitch nose up and roll to the right, so the commander disengaged the autopilot and established straight and level flight. The co-pilot remarked that he could smell smoke and suggested a return to Humberside. As the commander turned the helicopter, he noticed it

was in STABILITY AUGMENTATION SYSTEM mode and was yawing in an uncommanded "fishtailing" motion. The crew transmitted a 'PAN PAN' call and informed ATC of the situation. Although there was no visible smoke, a strong smell persisted. The commander decided to make a precautionary landing at a private coastal airfield less than two miles away. The eight passengers were briefed for the precautionary landing, which was completed safely. After landing, some of the passengers reported that they too had smelt smoke in the cabin and been aware of the fishtailing motion.

After landing, circuit breakers for the number 2 cyclic control trim and the collective control trim were found tripped. An engineering investigation established

that electrical shorting had occurred in a wiring loom situated above the forward left cabin area. The operating company issued a fleet-wide technical directive to inspect the wiring loom for signs of damage and to take corrective action where appropriate.

A temporary repair to the helicopter was carried out in accordance with manufacturer's procedures and the aircraft was flown to a maintenance base where a permanent repair was made. Following appropriate tests and checks the helicopter was returned to service.

The manufacturer has been in contact with the operator, and considers that in this case the wiring bundles were probably disturbed during a customer option installation. However, the manufacturer also recognizes that the area is potentially susceptible to chafing and is currently studying several methods of product improvement that would reduce this susceptibility for both future and delivered aircraft.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | AS350B2 Ecureuil, G-BXGA  |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Turbomeca Arriel 1D1 turboshaft engine  |                   |
| <b>Year of Manufacture:</b>            | 1991 (Serial no: 2493)  |                   |
| <b>Date &amp; Time (UTC):</b>          | 16 October 2012 at 1313 hrs   |                   |
| <b>Location:</b>                       | 1.5 nm south of Kettlewell, Yorkshire   |                   |
| <b>Type of Flight:</b>                 | Aerial Work   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - None   | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Impact damage to tail rotor blades  |                   |
| <b>Commander's Licence:</b>            | Commercial Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 66 years  |                   |
| <b>Commander's Flying Experience:</b>  | 16,127 hours (of which 2,335 were on type)<br>Last 90 days - 132 hours<br>Last 28 days - 30 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |                   |

**Synopsis**

The helicopter was approaching a field site, with an empty chain lifting sling suspended below. During the approach, the sling struck the tail rotor blades, producing a loud bang and a high frequency vibration. Cockpit indications were normal, and the pilot continued to a minimum power landing. The helicopter operator introduced a number of safety actions as a result of this and a similar, earlier accident.

**History of the flight**

The helicopter was engaged on an operation to move power line poles from a field site to a construction area, some 15 km away. After completing several uneventful return flights, the helicopter was returning to the field site when, as the helicopter was descending towards the

site at 75 to 80 kt, the pilot heard a loud bang and felt a high frequency vibration.

Cockpit indications remained normal. As the landing site came into view, the pilot warned the ground crew by radio of the situation, jettisoned the empty lifting sling just before touchdown and carried out a minimum power landing without further incident. It was subsequently found that the empty chain lifting sling had made contact with both tail rotor blades, tail rotor driveshaft cover and the port horizontal stabiliser.

The pilot reported that the weather at the time was generally fine, although there was a westerly wind of 25 kt, gusting to 35 kt. He described some turbulence

near the hills, but not so much as to cause major concern.

### **Previous occurrence and safety action**

A similar incident occurred to another of the operator's AS350B2 helicopters, G-ORKY, the previous week, on 8 October 2012 (AAIB report reference EW/G2012/10/07, in this Bulletin).

The helicopter operator conducted an internal investigation into the two accidents, which concluded that the sling had entered the tail rotors due to high airspeed. This was probably coupled with a descent and associated nose-up attitude, with turbulence being a contributory factor.

The chain lifting sling was 7 m long and covered in a cloth sheath. The helicopter operator conducted a flight trial which established that this sling angled further back in flight than a sling without a sheath, which was the type of sling originally trialled. The operator subsequently removed the cloth sheaths from the majority of the sling length, which was increased to 10 m. A Safety Bulletin was issued to all affected pilots and ground crew, highlighting the changes and stressing the need to adhere to the 80 kt speed limit, whilst being prepared to reduce speed further in unfavourable flight conditions.

**ACCIDENT**

|  |  |
|--|--|
| <b>Aircraft Type and Registration:</b> | AS350B2 Ecureuil, G-ORKY   |
| <b>No &amp; Type of Engines:</b>       | 1 Turbomeca Arriel 1D1 turboshaft engine   |
| <b>Year of Manufacture:</b>            | 1988 (Serial no: 2153)   |
| <b>Date &amp; Time (UTC):</b>          | 8 October 2012 at 1200 hrs   |
| <b>Location:</b>                       | Cairngorms National Park, Scotland   |
| <b>Type of Flight:</b>                 | Commercial Air Transport (Cargo)   |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - None  |
| <b>Injuries:</b>                       | Crew - None                      Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to vertical stabiliser and tail rotor system  |
| <b>Commander's Licence:</b>            | Commercial Pilot's Licence   |
| <b>Commander's Age:</b>                | 60 years   |
| <b>Commander's Flying Experience:</b>  | 20,307 hours (of which >10,000 were on type)<br>Last 90 days - 155 hours<br>Last 28 days - 66 hours      |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot and investigation report by the helicopter operator |

**Synopsis**

The helicopter was nearing the end of a transit flight, with an empty chain lifting sling suspended beneath it, when it encountered localised severe turbulence. The sling struck the tail rotor system but there were no adverse handling issues and the helicopter landed safely. The helicopter operator introduced a number of safety measures as a result of the accident.

**History of the flight**

The helicopter was nearing the end of a transit flight to a pick-up site, equipped with an empty chain lifting sling suspended beneath it. The pilot reported that the helicopter encountered localised severe turbulence while flying at the maximum allowed airspeed for the configuration,

80 kt. This caused it to sink rapidly, about 60 to 80 ft. The pilot heard a bang and immediately realised that the chain had struck the aircraft, probably in the region of the tail boom. The sling was normally visible in the cargo mirrors, but it had disappeared from view.

There were no uncommanded yawing movements and no vibration. So, with the helicopter responding normally to control inputs, the pilot made a normal approach to land. However, when it was reported by ground crew that the chain was wrapped around the tail boom, the pilot reduced speed, to slower than normal, and carried out an uneventful landing. It was subsequently established that the tail rotor system had sustained considerable damage.



The helicopter operator conducted an internal investigation, which concluded that the sling had entered the tail rotor due to high airspeed. This was probably coupled with a descent and associated nose-up attitude, with turbulence being a contributory factor.

The chain lifting sling was 7 m long and covered in a cloth sheath. The helicopter operator conducted a flight trial which established that this sling angled further back in flight than a sling without a sheath, which was the type of sling originally trialled. The operator subsequently removed the cloth sheaths from the majority of the

sling length, which was increased to 10 m. A Safety Bulletin was issued to all affected pilots and ground crew, highlighting the changes and stressing the need to adhere to the 80 kt speed limit, whilst being prepared to reduce speed further in unfavourable flight conditions.

#### **Further occurrence**

Eight days later a similar event occurred on another of the operator's AS350B2 helicopters, G-BXGA, before the above safety action had been taken. See AAIB report reference EW/G2012/10/17, in this Bulletin.

**ACCIDENT**

|  |   |
|--|---|
| <b>Aircraft Type and Registration:</b> | Cessna F172H Skyhawk, G-CGRE  |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming O-360-A4M piston engine  |
| <b>Year of Manufacture:</b>            | 1967 (Serial no: 410)   |
| <b>Date &amp; Time (UTC):</b>          | 18 August 2012 at 1438 hrs  |
| <b>Location:</b>                       | Near Baas Hill, Hoddesdon, Hertfordshire  |
| <b>Type of Flight:</b>                 | Aerial Work   |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - 1  |
| <b>Injuries:</b>                       | Crew - 1 (Minor)          Passengers - 1 (Minor)  |
| <b>Nature of Damage:</b>               | Damage to engine, nose and wings  |
| <b>Commander's Licence:</b>            | Commercial Pilot's Licence  |
| <b>Commander's Age:</b>                | 41 years  |
| <b>Commander's Flying Experience:</b>  | 782 hours (of which 305 were on type)<br>Last 90 days - 32 hours<br>Last 28 days - 14 hours |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |

The aircraft was returning to Old Sarum from Durham Tees Valley Airport when, approximately 2 hours 40 minutes after takeoff, the engine began to run rough and lose power. Despite the application of carburettor heat, and the selection of the fuel mixture to RICH, the engine continued to lose power. The pilot carried out a forced landing in a field which resulted in damage to the aircraft's nose and wings. Both occupants received minor injuries but were able to leave the aircraft unassisted.

The pilot reported that the fuel tanks had been filled to maximum capacity (195 litres) prior to takeoff at Durham Tees Valley. The pilot's report indicated that approximately 70 litres of fuel should have been present in the fuel tanks at the time of the incident. A review of the weather conditions prevalent at the time of the accident showed there was the potential for moderate carburettor icing at cruise engine power settings. It is therefore possible that the presence of carburettor icing may have contributed to the loss of engine power.

**ACCIDENT**

|  |  |
|--|--|
| <b>Aircraft Type and Registration:</b> | Cessna 172S Skyhawk, D-EFUC  |
| <b>No &amp; Type of Engines:</b>       | 1 Centurion 2.0s (TAE 125-02-114) diesel engine  |
| <b>Year of Manufacture:</b>            | 1998 (Serial No: 172S8003)   |
| <b>Date &amp; Time (UTC):</b>          | 2 August 2012 at 1416 hrs  |
| <b>Location:</b>                       | Dunsop Bridge, Lancashire  |
| <b>Type of Flight:</b>                 | Aerial Work  |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - 1   |
| <b>Injuries:</b>                       | Crew - None                      Passengers - None   |
| <b>Nature of Damage:</b>               | Damage to propeller, and right wing leading edge dent                                      |
| <b>Commander's Licence:</b>            | Commercial Pilot's Licence   |
| <b>Commander's Age:</b>                | 40 years   |
| <b>Commander's Flying Experience:</b>  | 408 hours (of which 80 were on type)<br>Last 90 days - 61 hours<br>Last 28 days - 43 hours |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                       |

The aircraft had departed Blackpool Airport for a photography sortie. About two hours after departure, while cruising at about 1,700 ft amsl, the engine suddenly lost power. Both engine FADEC<sup>1</sup> warning lights illuminated and although the propeller continued to turn, only 5% power was indicated on the engine display. The pilot exercised the power lever but there was no response from the engine. He turned the electric fuel pump on but this did not have any effect either. He selected a field, prepared for a forced landing and made a MAYDAY call on the Blackpool Radar frequency. The pilot made a

successful landing into a grass field, but during the ground roll the wheels dug into the soft ground and the aircraft momentarily pitched over onto its nose before settling upright. The pilot shut down the aircraft and he and his passenger vacated normally.

Following the aircraft's recovery a maintenance organisation attempted to download the recorded FADEC data but this was unsuccessful. At the time of writing no further examination of the engine or FADEC had been carried out.

**Footnote**

<sup>1</sup> Full Authority Digital Engine Control.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | CZAW Sportcruiser, G-CFNV   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Rotax 912 ULS piston engine   |                   |
| <b>Year of Manufacture:</b>            | 2009 (Serial no: LAA 338-14844)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 11 August 2012 at 1040 hrs  |                   |
| <b>Location:</b>                       | Skegness Airfield, Lincolnshire   |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - 1    |
| <b>Injuries:</b>                       | Crew - None   | Passengers - None |
| <b>Nature of Damage:</b>               | Nose leg and propeller  |                   |
| <b>Commander's Licence:</b>            | National Private Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 62 years  |                   |
| <b>Commander's Flying Experience:</b>  | 596 hours (of which 202 were on type)<br>Last 90 days - 30 hours<br>Last 28 days - 10 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |                   |

Following an uneventful flight and landing on Runway 11, the aircraft was being taxied to parking via Runway 03. Whilst travelling at a fast walking pace, the lower end of the nose leg fractured, pitching the aircraft onto its nose. The propeller shattered, but the engine continued to run for a brief period before the pilot turned the ignition system off and exited the aircraft.

Examination revealed that the nose leg had fractured at a location that was not readily accessible for inspection. The pilot reported some evidence of pre-existing cracking of the fracture surface. The grass runway surface at the scene of the accident was judged to be relatively smooth and level.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Focke Wulf (Piaggio) P149D, D-EARY  |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming GO-435-A piston engine   |                   |
| <b>Year of Manufacture:</b>            | 1959 (Serial no: 057)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 17 November 2012 at 1604 hrs  |                   |
| <b>Location:</b>                       | Stretton Airfield, near Warrington  |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - None   | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to wing leading edges, landing gear and propeller                                  |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence   |                   |
| <b>Commander's Age:</b>                | 69 years  |                   |
| <b>Commander's Flying Experience:</b>  | 1,391 hours (of which 37 were on type)<br>Last 90 days - 6 hours<br>Last 28 days - 1 hour |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                      |                   |

The aircraft had undergone an annual maintenance check at Caernarfon Airfield, followed by a local test flight. The pilot had decided to break the subsequent flight to his base airfield in North Yorkshire with a stop at Stretton Airfield. He obtained permission to use the airfield, and the forecast weather, which showed fine conditions and a surface wind from 240° at 8 to 12 kt. On arrival overhead Stretton, the conditions were found to be as forecast and the pilot carried out an approach to Runway 27.

The runway surface was variable, with only an 18 m strip on the north side (right side, viewed from the

27 approach) maintained in a suitable condition. The approach was into a low sun, which made judgement of height difficult. Just before touchdown, the pilot applied rudder to remove drift and align the aircraft with the runway. However, it continued just above the runway and drifted to the right. The right wing struck a large bush, which yawed the aircraft to the right and into a hedge.

The pilot attributed the accident to his continuing with the approach when the low sun and a stroboscopic effect made judgement of height difficult.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Jodel D120 Paris-Nice, G-ATLV   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Continental Motors Corp O-200-A piston engine   |                   |
| <b>Year of Manufacture:</b>            | 1960 (Serial no: 224)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 21 October 2012 at 1640 hrs   |                   |
| <b>Location:</b>                       | Shenstone Airfield, Staffordshire   |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - None   | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to right wing and landing gear   |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence   |                   |
| <b>Commander's Age:</b>                | 55 years  |                   |
| <b>Commander's Flying Experience:</b>  | 345 hours (of which 55 were on type)<br>Last 90 days - 11 hours<br>Last 28 days - 2 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                      |                   |

The aircraft took off from Runway 33 at Shenstone Airfield for a local circuit flight. The weather was fine, with a surface wind from 050° at 7 kt. The pilot flew a visual circuit to land back on Runway 33. During the ground roll after landing, the pilot lost directional control of the aircraft and it veered off the runway to the left before striking the base of a windsock. The pilot was uninjured but the aircraft suffered substantial damage to the right wing leading edge and further damage to the undercarriage.

The pilot noted that the approach had been both high and fast. He attributed the accident to his preoccupation with the relatively light crosswind from the right, such that he had applied an excessive amount of left rudder, which led to the runway excursion.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Mooney M20J, N12ZX  |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming IO-360-B1E engine  |                   |
| <b>Year of Manufacture:</b>            | 1991 (Serial no: 24-3227)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 8 September 2012 at 1115 hrs  |                   |
| <b>Location:</b>                       | Oxford Airport, Kidlington  |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - None   | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Propeller and engine unserviceable; abrasions to aircraft lower skin, collapsed landing gear    |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence   |                   |
| <b>Commander's Age:</b>                | 67 years  |                   |
| <b>Commander's Flying Experience:</b>  | 5,088 hours (of which 4,958 were on type)<br>Last 90 days - 67 hours<br>Last 28 days - 24 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot and further information on aircraft damage |                   |

**Synopsis**

The aircraft's landing gear failed to retract fully on takeoff but remained in an unlocked position. The aircraft subsequently landed on Runway 19 at Oxford (Kidlington) Airport. The gear collapsed, as anticipated by the pilot, and the aircraft came to a stop upright, with no injuries to the pilot and minor damage to the aircraft and runway.

**Background**

The pilot had some 4,958 hours flying Mooney aircraft and had been the sole pilot of N12ZX since she purchased it in 1994. The pilot reported that she had had "no gear trouble previously with this airplane" and that it is usual for her to do a practice emergency gear

extension while the aircraft is on jacks during annual maintenance.

The normal 50-hour maintenance items had been carried out on the aircraft on 30 August 2012. The pilot reported that prior to the reported incident she had flown 8.7 flight hours after the 50-hour check, with three 3 takeoffs and landings and "no sign of a gear problem".

**History of the flight**

The pilot took off from Oxford (Kidlington) Airport on an IFR flight plan for Szczecin, Poland. When the pilot operated the electrical gear retraction system it became clear "within the first minute after takeoff" that


the gear had not retracted. On this aircraft there are two independent cockpit indications, one electrical and one mechanical, that indicate the status of the landing gear. The electrical indication of 'Gear Unsafe' remained lit, indicating that the gear was neither locked down nor locked up; the mechanical indication was stuck between the 'gear up' and 'gear locked down' positions. These indicated to the pilot that the gear was at least partially extended, but unlocked.

The pilot notified the Tower that she had a gear problem and flew for approximately one hour outside the ILS sector and VFR pattern, attempting to lock the gear either up or down. A manual gear extension system exists for occasions when there are electrical problems. The pilot tried "numerous times" to engage the system but with no success; it is noted that during previous 100-hour maintenance the pilot tested the system successfully whilst the aircraft was jacked up. The pilot flew past the

Tower and confirmed from ATC that the wheels were out but the landing gear was "at a strange angle". The pilot decided to land on the paved runway, rather than the grass, to minimise the risk of the aircraft flipping over. After touchdown the aircraft came to a halt safely, with no injuries to the pilot and minimal damage to the runway, and the pilot was able to exit through the door.

### Inspection of damage

A recovery team removed the aircraft from the runway shortly after the incident and it was stored in a hangar at Oxford Airport. It was reported that initially the salvage crew were not able to extend the right main gear and had found a broken connecting rod in the mechanical linkage (Figure 1). Once this was removed they were able to extend the gear. The condition of the linkage prior to the accident is unknown and it is possible this damage was caused during the landing.



*Image from Mooney Airplane Company Inc.  
M20J Illustrated Parts Catalogue*

**Figure 1**

Mooney M20J Landing Gear Retraction System



Inspection of the aircraft in the hangar revealed scrape marks on the outside of the nose gear doors, aircraft belly skin and other areas, with the damage consistent with that likely to be sustained during the landing. The steel lugs on the nose gear had also sheared from their 'A-frame' weld attachments, which indicated that the gear collapsed on landing and then folded back into the gear bay. Other damage was noted with respect to the landing gear retraction system:

- (a) RH connecting rod was bowed
- (b) LH connecting rod was eroded
- (c) Pin on RHS was missing

It is likely that damage (a) and (b) was caused during the landing. It was not possible to ascertain whether the missing pin would have caused the gear to jam.

### **Assessment of the cause**

The pilot considers that the cause of the gear retraction failure was either an actuator failure or a structural failure within the mechanical linkage. The actuator was to be tested but the results were not available at the time of publication.

**ACCIDENT**

|  |  |
|--|--|
| <b>Aircraft Type and Registration:</b> | Percival Proctor 3, G-ALJF   |
| <b>No &amp; Type of Engines:</b>       | 1 De Havilland Gipsy Queen 2 piston engine   |
| <b>Year of Manufacture:</b>            | 1940 (Serial no: K.427)  |
| <b>Date &amp; Time (UTC):</b>          | 24 July 2012 at 1630 hrs   |
| <b>Location:</b>                       | Airstrip 12 nm south-west of Ashford, Kent   |
| <b>Type of Flight:</b>                 | Private  |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - None  |
| <b>Injuries:</b>                       | Crew - 1 (Serious)      Passengers - N/A   |
| <b>Nature of Damage:</b>               | Damage to wings, engine bearer and propeller, aft fuselage and landing gear                  |
| <b>Commander's Licence:</b>            | Private Pilot's Licence  |
| <b>Commander's Age:</b>                | 78 years   |
| <b>Commander's Flying Experience:</b>  | 3,200 hours (of which 1,067 were on type)<br>Last 90 days - 2 hours<br>Last 28 days - 1 hour |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot   |

**Synopsis**

The pilot attempted to fly a go-around after the aircraft bounced on touchdown. Despite using full power, the aircraft remained at slow speed and did not climb out of ground effect. It veered to the right and, after touching down a second time, struck a tree and substantial hedgerow. The pilot was taken to hospital with serious injuries.

**History of the flight**

The accident occurred at the end of a return flight to Le Touquet, as the aircraft was landing at a private airstrip. The grass runway at the airstrip was orientated 11/29 and about 350 m long. The weather was fine, with no wind and a temperature of 27°C. The pilot, who was familiar

with the airstrip, having flown from it for a number of years, elected to land in the easterly direction.

He allowed the aircraft to become slightly slow just before touchdown and applied power to correct. The aircraft bounced and he applied full power to fly a go-around. However, the aircraft did not climb but remained in ground effect at low airspeed, with full flaps still selected, and started to veer to the right. The pilot was unable to raise the flaps, because of the airspeed, so elected, instead, to reduce power and land. He then intended to perform a "ground loop", before the aircraft reached a substantial hedge and ditch ahead. However, before he could do so, the aircraft's left wing struck a

small oak tree, swinging the aircraft to the left and into the hedge, where it came to rest. There was no fire but the pilot, who was wearing a lap strap harness, sustained serious injuries. The emergency services attended the scene and the county Fire and Rescue Service freed the pilot from the wreckage, before he was taken to hospital.

In his report, the pilot attributed the accident to a combination of his handling of the aircraft and the hot, calm conditions.

**ACCIDENT**

|  |  |
|--|--|
| <b>Aircraft Type and Registration:</b> | Piper PA-25-235 Pawnee, G-BFEV   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming O-540-B2C5 piston engine  |
| <b>Year of Manufacture:</b>            | 1977 (Serial no: 25-7756060)   |
| <b>Date &amp; Time (UTC):</b>          | 18 August 2012 at 1400 hrs   |
| <b>Location:</b>                       | Kirton in Lindsey Airfield, Lincolnshire   |
| <b>Type of Flight:</b>                 | Aerial Work  |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - None  |
| <b>Injuries:</b>                       | Crew - None                      Passengers - N/A  |
| <b>Nature of Damage:</b>               | Structural damage to right landing gear  |
| <b>Commander's Licence:</b>            | Private Pilot's Licence  |
| <b>Commander's Age:</b>                | 56 years   |
| <b>Commander's Flying Experience:</b>  | 450 hours (of which n/k were on type)<br>Last 90 days - 13 hours<br>Last 28 days - 4 hours |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                       |

The aircraft was being operated as a glider tug at Kirton in Lindsey Airfield. On the seventh landing of the day the pilot reported hearing a "crack" sound just after touchdown. Suspecting a failure in the landing gear, the pilot shut down the engine whilst taxiing. The aircraft came to a controlled stop with the right wing low, but not touching the ground. The damage was inspected by the repair agency for the aircraft. Inspection revealed that the hydraulic damping unit, to which the undercarriage retaining bungees are attached, had sheared at its upper end, causing the landing gear partially to collapse on the right side.

The repair agency consider that the bungees that hold the landing gear in place prevented total collapse of the landing gear, and damage to the wing and propeller, and comment that inspection of this strut is part of the aircraft periodic 50-hour check. The repair agency suggests that pilots who fly this aircraft regularly inspect the top of the strut for signs of wear. The pilot assessed the cause of the failure to be "wear and tear".

**ACCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Piper PA-38-112 Tomahawk, D-EIBR   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming O-235-L2A piston engine   |                   |
| <b>Year of Manufacture:</b>            | 1981 (Serial no: 38-81A0117)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 3 November 2012 at 1630 hrs  |                   |
| <b>Location:</b>                       | Dornoch Airfield, Scotland   |                   |
| <b>Type of Flight:</b>                 | Private  |                   |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - None |
| <b>Injuries:</b>                       | Crew - None  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to nose landing gear, forward fuselage, cockpit, engine and propeller             |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 51 years   |                   |
| <b>Commander's Flying Experience:</b>  | 223 hours (of which 75 were on type)<br>Last 90 days - 7 hours<br>Last 28 days - 4 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                     |                   |

**Synopsis**

The pilot was conducting a practice forced landing. Just before touchdown, the right wing lifted abruptly and the aircraft pitched forward and struck the ground. It yawed to the left and departed the runway before overturning on the adjacent grass.

**History of the flight**

The pilot took off from Inverness Airport and flew 20 nm north to Dornoch Airfield, with the intention of carrying out practice forced landings (PFL) there. The weather was fine, with a light surface wind.

Overhead Dornoch, there appeared to be negligible surface wind, so the pilot commenced a PFL to Runway 28. However, it became apparent that the

wind actually favoured the opposite runway, so he discontinued the PFL and flew a satisfactory PFL to Runway 10, using two stages of flap. The runway at Dornoch was grass, 775 m long.

The pilot took off again and climbed for a further PFL, with the windsock still indicating a light easterly wind which favoured Runway 10. The pilot described the second approach as being slightly lower than the first, so did not use flap. The aircraft arrived at the runway at 70 kt, which was allowed to reduce to 65 kt in the flare. The pilot described that the right wing then lifted abruptly. He attempted to level the wings and applied full power to go around, but the aircraft pitched violently nose down and yawed to the left. The aircraft had nearly

come to a stop on the long grass adjacent to the runway when it pitched slowly forward and turned over.

The pilot, who was uninjured, made the aircraft safe and released his harness without difficulty. However, he was initially unable to open either cabin door. Other persons

arrived on scene after a few minutes but they too were unable to open the doors (each door is secured by a latch, and both doors are also secured by a single latch in the cabin roof). Eventually, the pilot was able to release the roof latch and open a door.

**ACCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Robin DR400/500 President, G-VIRR  |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming IO-360-A1B6 piston engine   |                   |
| <b>Year of Manufacture:</b>            | 2001 (Serial no: 31)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 15 October 2012 at 1145 hrs  |                   |
| <b>Location:</b>                       | Runway 27, Jersey Airport  |                   |
| <b>Type of Flight:</b>                 | Private  |                   |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - None |
| <b>Injuries:</b>                       | Crew - None  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Nose landing gear and propeller damaged  |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 81 years   |                   |
| <b>Commander's Flying Experience:</b>  | 3,245 hours (of which 3,235 were on type)<br>Last 90 days - 17 hours<br>Last 28 days - 0 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot   |                   |

**Synopsis**

The aircraft was landing on Runway 27 with a crosswind component and bounced several times on touchdown. The final contact was very heavy and the nose landing gear collapsed. The pilot was at a loss to explain why this had happened on an aircraft with which he was very familiar.

**History of the flight**

The aircraft was returning to Jersey from a trip to Shobdon and had been receiving the Jersey ATIS, which contained information concerning a likely shower and a cloud base of 1,300 ft. As he approached the north coast of Jersey, the shower had arrived but the pilot had Runway 27 in view.

Changing frequency to Jersey Tower, he was cleared to approach and recalled receiving information that the wind was in the order of 240° at 18-20 kt. In view of this he decided to position for a slightly longer final approach than he would for calmer conditions – he estimated about 1½ miles. The pilot elected for a more power-on approach, which was his normal practice when there is a crosswind element, and employed the “crossed controls” method, which he had found to work best for this aircraft. He maintained a steady track on the runway heading and recalled receiving revised wind information from the tower a further two or three times, which he did not acknowledge. Applying just the first stage of flap, he touched down at a slightly higher speed than he would for calmer conditions but was not at all concerned and

expected a normal rollout. Unfortunately, the aircraft appeared to bounce about three times before dropping violently to the ground from a height of 10-20 ft, with the pilot feeling he had no control. He thinks the final impact was on all three landing gears and the nosewheel collapsed. After a ground slide, the aircraft came to rest and the pilot made a short radio transmission before he exited having switched off the electrics and fuel.

He is at a loss to explain what went wrong during what

he described as “a routine crosswind landing” in an aircraft he was extremely familiar with. He did not discount the possibility of a sudden gust of wind but has no recollection of that happening.



**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Robinson R22 Beta, G-BTHI   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Lycoming O-320-B2C piston engine  |                   |
| <b>Year of Manufacture:</b>            | 1991 (Serial no: 1732)  |                   |
| <b>Date &amp; Time (UTC):</b>          | 14 August 2012 at 1230 hrs  |                   |
| <b>Location:</b>                       | Leicester Airport   |                   |
| <b>Type of Flight:</b>                 | Training  |                   |
| <b>Persons on Board:</b>               | Crew - 2  | Passengers - None |
| <b>Injuries:</b>                       | Crew - 2 (Minor)  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Substantial   |                   |
| <b>Commander's Licence:</b>            | Commercial Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 66 years  |                   |
| <b>Commander's Flying Experience:</b>  | 22,215 hours (of which 10,098 were on type)<br>Last 90 days - 77 hours<br>Last 28 days - 44 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |                   |

**Synopsis**

During approach, the helicopter was subject to severe vibration, a clutch warning and low rotor rpm warnings. The pilot initiated an autorotation but the aircraft began to yaw to the right uncontrollably. The helicopter landed heavily in a field and turned over and the two crew members suffered minor injuries.

**History of the flight**

G-BTHI was on an instructional flight and the instructor was the handling pilot. The helicopter was on final approach to Runway 24, at approximately 150 to 200 ft agl and 50 kt, when severe vibration was felt through the airframe and controls. The pilot stated that the vibration was so severe he could not read any of the instruments and he instinctively increased airspeed and made a short

MAYDAY call. While he was transmitting, the clutch warning light illuminated followed immediately by the low rotor rpm light and warning horn. The pilot entered autorotation but, instead of yawing left as expected, the aircraft yawed right despite the subsequent application of full left yaw pedal. The helicopter was turning towards a public road and so the pilot increased the rate of turn using the cyclic control to ensure that the helicopter did not pass over it.

The helicopter had turned through approximately 280° as it approached the ground. The pilot applied full up input on the collective control to try to cushion the touchdown but the aircraft landed heavily, with little forward speed but considerable right yaw, and rolled onto its left side.

The student exited the helicopter through the right door and the instructor exited through the broken front windscreen. Both occupants were treated at the scene for minor injuries.

### **Pilots Operating Handbook (POH)**

The R22 POH states that a loss of tail rotor thrust in forward flight is usually indicated by nose right yaw which cannot be corrected by applying left yaw pedal. Pilots are advised to enter autorotation immediately, maintain at least 70 kt airspeed if practical and perform an autorotation landing.

### **Pilot's assessment of the cause**

The pilot assessed that he had suffered a tail rotor failure. After inspection of the wreckage, he found that:

1. The tail rotor drive had failed at the intermediate flex plate coupling, which is just aft of the clutch actuator.
2. There was a large quantity of wire wrapped around the tail rotor drive shaft, which was probably the power supply for the anti-collision light.
3. The drive shaft damper assembly within the tail boom had broken from its bracket.
4. The clutch fuse was found out of its housing (if the clutch fuse fails, the clutch light illuminates).

He did not determine whether the drive failed at the intermediate flex plate coupling first, or whether the initiating failure was the drive shaft damper assembly separating from its bracket.

**ACCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Rotorway Executive 162F, G-FLIT  |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Rotorway RI 162F piston engine   |                   |
| <b>Year of Manufacture:</b>            | 1998 (Serial no: 6324)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 26 August 2012 at 1315 hrs   |                   |
| <b>Location:</b>                       | Near Haslemere, Surrey   |                   |
| <b>Type of Flight:</b>                 | Private  |                   |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - None |
| <b>Injuries:</b>                       | Crew - None  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to tail rotor blade tips  |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence  |                   |
| <b>Commander's Age:</b>                | 72 years   |                   |
| <b>Commander's Flying Experience:</b>  | 536 hours (of which 365 were on type)<br>Last 90 days - 4 hours<br>Last 28 days - 1 hour |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                     |                   |

**Synopsis**

Whilst in the cruise, the helicopter suddenly yawed and the engine rpm increased rapidly. The pilot closed the throttle and entered an autorotative descent. The subsequent landing was achieved with only minor damage to the helicopter. It was found that the loss of drive to the main rotor system was caused by the fatigue failure of a drive shaft. There was a history of shaft failures on this helicopter type, mostly involving an earlier design; this aircraft was equipped with the latest design standard.

**Circumstances of the accident**

The aircraft was returning from Dunsfold to a private landing site near Petersfield, and was on a track of around 250° at an airspeed of 70-80 mph. Due to a

headwind, the groundspeed was around 60-70 mph, which had encouraged the pilot to maintain a relatively low altitude of around 1,000 ft. As the helicopter neared rising ground near Haslemere the pilot turned towards the south and started to climb. Without warning, the helicopter yawed violently and the engine rpm rapidly increased, entering the red sector of the tachometer. The pilot estimated that within 2 seconds he had closed the throttle and set up the helicopter for autorotation. However, as a result of a late initiation of the climb, the aircraft was at a height of only 700-800 ft agl. This limited the time available to choose a landing site and, with only a few seconds before it was necessary to flare, it became apparent that the surface of the selected field was uneven. As a consequence the helicopter landed

on an upslope, with the uneven surface resulting in the tail rotor contacting the ground. However the pilot was uninjured and there was no other damage.


### The investigation

It subsequently became apparent that there had been a failure of the secondary driveshaft, such that the engine was no longer driving the main rotor. The drive-train components of the helicopter are illustrated in Figure 1.

The vertically orientated engine drives the secondary pulley, via a set of 'V' belts. This rotates on the secondary shaft which has the tail rotor drive pulley at its lower end and a sprocket assembly, which drives the main rotor via a triple chain assembly, at its upper end. It can be seen that the location of the failure resulted in an immediate loss of drive to the main rotors, although the tail rotor continued to be driven until the pilot closed the throttle, thus activating the free-wheel system.


Figures 2 and 3 show a diagram of the secondary shaft assembly, together with a photograph of the failure. It can be seen that the failure occurred adjacent to the lower edge of the inner race of the upper bearing. The components were returned to the manufacturer in the USA, where the shaft, which is solid, was subjected to a metallurgical analysis. Figure 4 shows the two shaft halves following removal.

The examination indicated that the fracture occurred as a result of rotational bending fatigue, with area of the fracture origin and the final overload failure indicated in Figure 5. The surface of the shaft adjacent to the fracture showed evidence of mechanical wear in comparison to the surface finish elsewhere on the shaft; a photograph of this is also shown in Figure 5. It can be seen that the region was coincident with the location of the upper bearing, with the fracture occurring close to one end of it. The longitudinal scores were on top of the circumferential wear and are likely to have occurred during bearing removal.




**Figure 1**

Main components of the drive-train, position of shaft failure arrowed





**Figure 2**  
Diagram of shaft assembly



**Figure 3**  
Pulley and bearing, showing both fracture faces of the failed shaft



**Figure 4**  
The two pieces of the shaft after removal from the aircraft



**Figure 5**  
Photographs of the fracture face and smeared surface close to the fracture origin

The metallurgical report indicated that the area of wear was consistent with a fretting process which, in the region of the fracture origin, was associated with missing flakes of metal. The report additionally indicated that this may have induced a fatigue crack. No material defects were observed either in the origin or in the microstructure.

### **Other information**

The 35 mm diameter secondary shaft was introduced on new aircraft in 2001 and replaced a similar design of 30 mm diameter, which had experienced a number of failures. Two failures of the new design, at low operating hours, occurred during that year, with the causes associated with misalignment during installation. The only other recorded failure was that which occurred to G-FLIT, with the shaft having achieved 248 operating hours.

The upper bearing, into which the secondary shaft is located, constitutes a critical part of the drive-train in that any misalignment could result in a significant radial load on the bearing (and in consequence, a once-per-revolution bending load on the shaft). The bearing is lubricated via a grease nipple and can become hot during normal operation, especially when new and immediately after lubrication. The bearing casing has adhesive temperature indicators and is additionally monitored by means of a temperature sensor connected to a cockpit gauge. In the case of G-FLIT, there was

no report of unusually high temperature indications prior to the failure, although the pilot commented that moderately high temperatures had been observed during the 'running in' period shortly after installation of the shaft. The pilot also commented that the fretting or spalling marks on the shaft surface were often observed on this type of helicopter.

No problems were observed with the bearing itself.

### **Discussion**

The drive shaft failure was found to be the result of a fatigue crack that initiated close to the location of the upper bearing. The failure was similar in nature to those that had occurred to an earlier, smaller diameter shaft, as well as two apparently isolated occurrences involving the new 35 mm shaft. The metallurgical examination of the shaft from G-FLIT indicated that the fatigue may have initiated in a region of fretting on the shaft surface, close to the point where it emerged from the lower face of the upper bearing. The experience of previous shaft failures indicates that the installation is susceptible to misalignment. The evidence of fretting-plus-bending fatigue failure suggests that an element of misalignment featured in this incident. However, although there may be scope for additional development of this part of the drive-train, the larger diameter shaft represents an improvement in service experience in comparison with the previous version.

**ACCIDENT**

|  |  |                        |
|--|--|------------------------|
| <b>Aircraft Type and Registration:</b> | Escapade 912(1), G-CDKL  |                        |
| <b>No &amp; Type of Engines:</b>       | 1 Rotax 912-UL piston engine   |                        |
| <b>Year of Manufacture:</b>            | 2005 (Serial no: BMAA/HB/359)  |                        |
| <b>Date &amp; Time (UTC):</b>          | 22 September 2012 at 1300 hrs  |                        |
| <b>Location:</b>                       | Eshott Airfield, Northumberland  |                        |
| <b>Type of Flight:</b>                 | Private  |                        |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - 1         |
| <b>Injuries:</b>                       | Crew - None  | Passengers - 1 (Minor) |
| <b>Nature of Damage:</b>               | Damage to propeller and right wing, landing gear collapsed                               |                        |
| <b>Commander's Licence:</b>            | National Private Pilot's Licence   |                        |
| <b>Commander's Age:</b>                | 51 years   |                        |
| <b>Commander's Flying Experience:</b>  | 114 hours (of which 27 were on type)<br>Last 90 days - 5 hours<br>Last 28 days - 2 hours |                        |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                     |                        |

The aircraft was being flown on a flight from an airfield in North Yorkshire to Eshott in Northumberland. The weather at Eshott was fine, with a light easterly wind and good visibility. On arrival, the pilot was informed by the Air/Ground operator that Runway 26 was in use, which was an asphalt runway, 550 m in length.

The aircraft (a tailwheel type) was not fully aligned with the runway on touchdown. The pilot applied rudder to correct the situation but lost control of the aircraft, which 'ground looped'. Its right main landing gear collapsed

and the right wing made contact with the runway. The propeller also contacted the runway and shattered. The cockpit area was undamaged; the pilot and his passenger vacated the aircraft via the side doors.

Whilst on final approach, the pilot had noticed an aircraft taxiing towards the runway threshold for departure. He thought he had been distracted by this aircraft, with the result that the aircraft landed whilst not fully aligned, and that his use of rudder had led to the loss of control.

**ACCIDENT**

|  |   |
|--|---|
| <b>Aircraft Type and Registration:</b> | Mainair Blade, G-MZED   |
| <b>No &amp; Type of Engines:</b>       | 1 Rotax 582-2V piston engine  |
| <b>Year of Manufacture:</b>            | 1996 (Serial no: 1092-0796-7-W895)  |
| <b>Date &amp; Time (UTC):</b>          | 22 September 2012 at 1148 hrs   |
| <b>Location:</b>                       | Eshott Airfield, Northumberland   |
| <b>Type of Flight:</b>                 | Training  |
| <b>Persons on Board:</b>               | Crew - 1                      Passengers - 1  |
| <b>Injuries:</b>                       | Crew - 1 (Minor)          Passengers - 1 (Serious)  |
| <b>Nature of Damage:</b>               | Trike unit and wing were both damaged beyond economic repair; further damage to an EV-97 Eurostar |
| <b>Commander's Licence:</b>            | Private Pilot's Licence   |
| <b>Commander's Age:</b>                | 50 years  |
| <b>Commander's Flying Experience:</b>  | 666 hours (of which 534 were on type)<br>Last 90 days - 13 hours<br>Last 28 days - 8 hours        |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |

The pilot reports that his aircraft, a weight-shift microlight, was on a normal approach for Runway 01 (asphalt) at Eshott Airfield, following a Robinson R22 light helicopter in light winds. The approach was good, with the correct speed and approach angle, maintaining a constant distance from the helicopter ahead, until, crossing the threshold, G-MZED was "pulled from the sky" and impacted the ground at a high rate of descent. The aircraft bounced across the neighbouring grass

runway and collided with a parked EV-97 Eurostar aircraft. Both occupants of G-MZED suffered injuries, were released from the wreckage by bystanders and taken to hospital by air ambulance.

The pilot considers that the accident was caused by the microlight's encounter with the helicopter's downwash and that he had not been aware of the likely severity of this effect.



**ACCIDENT**

|  |  |                   |
|--|--|-------------------|
| <b>Aircraft Type and Registration:</b> | Pegasus Quantum 15, G-MYRN   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Rotax 582-48 piston engine   |                   |
| <b>Year of Manufacture:</b>            | 1994 (Serial no: 6801)   |                   |
| <b>Date &amp; Time (UTC):</b>          | 17 November 2012 at 1100 hrs   |                   |
| <b>Location:</b>                       | 4 nm south-east of Perth (Scone) Aerodrome, Perthshire                                     |                   |
| <b>Type of Flight:</b>                 | Private  |                   |
| <b>Persons on Board:</b>               | Crew - 1   | Passengers - None |
| <b>Injuries:</b>                       | Crew - None  | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to front landing gear and wing  |                   |
| <b>Commander's Licence:</b>            | National Private Pilot's Licence   |                   |
| <b>Commander's Age:</b>                | 56 years   |                   |
| <b>Commander's Flying Experience:</b>  | 218 hours (of which 150 were on type)<br>Last 90 days - 20 hours<br>Last 28 days - 6 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot                                       |                   |

The aircraft took off from Perth Aerodrome for a 40-minute flight. It had flown earlier that day without fault, and the pilot had refuelled it prior to his flight. The weather conditions were clear and dry with light winds, but cold.

About five minutes after takeoff the engine started to run rough, although the engine instruments showed normal indications. The pilot reduced power and identified a farm field in which to land. As he neared the field, he realised that it was crossed by wire fencing. With the engine now stopped, he was forced to manoeuvre to avoid the fencing, and eventually landed in a muddy

field north of the chosen one. The aircraft turned over, sustaining minor damage, although the pilot was not injured.

The pilot subsequently dismantled the engine, which was found to have seized. The reason for the seizure was not positively confirmed, but the pilot believed that it may have been due to a lack of lubrication. Prior to refuelling for the flight, he put the correct amount of lubricant in the fuel tank, followed by the fuel (MOGAS). He considered it possible that inadequate mixing of the two had taken place.

**ACCIDENT**

|  |   |                   |
|--|---|-------------------|
| <b>Aircraft Type and Registration:</b> | Rotorsport UK MT-03 gyroplane, G-CFKA   |                   |
| <b>No &amp; Type of Engines:</b>       | 1 Rotax 914-UL piston engine  |                   |
| <b>Year of Manufacture:</b>            | 2008 (Serial no: RSUK/MT-03/051)  |                   |
| <b>Date &amp; Time (UTC):</b>          | 31 July 2012 at 1355 hrs  |                   |
| <b>Location:</b>                       | Rufforth Airfield East, York  |                   |
| <b>Type of Flight:</b>                 | Private   |                   |
| <b>Persons on Board:</b>               | Crew - 1  | Passengers - None |
| <b>Injuries:</b>                       | Crew - None   | Passengers - N/A  |
| <b>Nature of Damage:</b>               | Damage to rotors, propeller, mast, pod and nose leg   |                   |
| <b>Commander's Licence:</b>            | Private Pilot's Licence   |                   |
| <b>Commander's Age:</b>                | 57 years  |                   |
| <b>Commander's Flying Experience:</b>  | 300 hours (of which all were on type)<br>Last 90 days - 54 hours<br>Last 28 days - 17 hours |                   |
| <b>Information Source:</b>             | Aircraft Accident Report Form submitted by the pilot  |                   |

**Synopsis**

The aircraft overshot the end of the runway on landing, crossing the perpendicular runway and coming to rest in an adjacent field. The pilot was uninjured and considers that he had misjudged the safety margin required.

**History of the flight**

The pilot made a standard overhead join at Rufforth Airfield East at 1,600 feet, having received no response to his call on the SAFETYCOM frequency. The pilot used the airfield windsock to judge that the wind direction for Runway 14 was a direct headwind and chose this runway for landing. Runway 14 is the shorter runway at Rufforth East at 220 m with zero slope and an asphalt surface; surface condition on the day was reported as dry.

Observing no other aircraft in the circuit, or operating at the adjacent airfield (Rufforth West), the pilot flew a wide circuit, followed by a power-off descent from 700 feet as required for Runway 14. The pilot established a descent at 50 mph and judged the aircraft would touch down at approximately one-third of the runway length.

During the final approach it became apparent to the pilot that the touchdown would be further down the runway, at about mid-point, and he made two wide 'S-turns'. After realigning on the runway he flared and landed with power off. The pilot reports that, although he kept the stick fully back on landing, the aircraft "did not decelerate as normal".

The aircraft continued to roll, crossing Runway 23/05, and “bumped” up an earth verge beyond. The nose lifted, followed by the left side of the aircraft as the left mainwheel contacted the verge, the aircraft was tipped onto its right side and the rotor stopped immediately.

The pilot reports that he had applied brakes after touchdown but not very much speed reduction resulted. He estimated that the aircraft came to rest 15 feet into the field.

### **Pilot’s comments**

The pilot considered that he had misjudged the safety margin required for a safe landing. He commented that the moderately strong winds he had encountered during

the flight may have dropped, or even changed direction, during his final approach, accounting for the need for the ‘S-turns’.

The pilot added that as the aircraft lurched to the right he probably tipped in the same direction and may have inadvertently moved the control stick to the right, contributing to the aircraft tipping over.



## **Miscellaneous**

This section contains Addenda, Corrections and a list of the ten most recent Aircraft Accident ('Formal') Reports published by the AAIB.

The complete reports can be downloaded from the AAIB website ([www.aaib.gov.uk](http://www.aaib.gov.uk)).



**BULLETIN CORRECTION**

|  |                                      |
|--|--------------------------------------|
| <b>AAIB File:</b>                      | EW/G2011/05/08                       |
| <b>Aircraft Type and Registration:</b> | Robinson R44 Raven, G-GDOV           |
| <b>Date &amp; Time (UTC):</b>          | 16 May 2011 at 1443 hrs              |
| <b>Location:</b>                       | Gidleigh Park Hotel, Chagford, Devon |
| <b>Information Source:</b>             | Aircraft Accident Report Form        |

**AAIB Bulletin No 8/2011, page 43 refers**

In this report it was incorrectly stated that the helicopter had rolled onto its left side. The report should have reflected that the helicopter had rolled onto its **right** side.

The online version of this report was corrected on 3 January 2013.

**BULLETIN ADDENDUM****Aircraft Type & Registration**

Thruster T600N 450, G-CBIO

**Date & Time (UTC):**

17 January 2012 at 1150 hrs

**Location:**

Near Compton Abbas Airfield, Dorset

**Information Source:**

Aircraft Accident Report Form

**AAIB Bulletin No 8/2012, page 60 refers**

Following the publication of this AAIB Bulletin, the LAA (Light Aircraft Association) and the BMAA (British Microlight Aircraft Association) both wrote to the AAIB on issues concerning the electrical carburettor heat system installed in G-CBIO.

In the 'Carburettor heat system' section of the Bulletin, details of the electrical carburettor heat system installed on G-CBIO were provided. The LAA and the BMAA both stressed to the AAIB that such systems are designed to be operated throughout the duration of a flight and are intended to prevent the formation of carburettor ice, not to melt it once formed. This is in contrast to conventional heated air intake systems that require pilot operation during certain phases of flight, such as throttling back before landing. In the accident to G-CBIO, the pilot reported that he had turned on the aircraft's electrical carburettor heat system at the start of his descent into Compton Abbas.

The LAA and the BMAA re-iterated the comment (made in the 'Airworthiness requirements' section of the AAIB Bulletin, G-CBIO, 8/2012) that BCAR Section S does **not** contain any requirements for induction system icing protection or for specific levels of engine reliability.

Regarding the 'Safety actions' section of the AAIB Bulletin, the BMAA commented:

*'The safety actions on the BMAA at the end of the report have not been agreed by the BMAA. The BMAA has already written to inspectors, and in its magazine to members, of the importance of having modifications approved if required by regulation. The second action on the BMAA to advise inspectors of the approved type of carburettor heat systems would include an electric heater now fitted as a standard to this type of engine.'*

The LAA also stressed that the aircraft owner remains primarily responsible for the modification standard of an aircraft. The AAIB accepts that this situation was not clearly stated in the Bulletin account.

This addendum was included in the online version of this report on 10 February 2013.



**TEN MOST RECENTLY PUBLISHED  
FORMAL REPORTS  
ISSUED BY THE AIR ACCIDENTS INVESTIGATION BRANCH**

|        |  |        |  |
|--------|--|--------|--|
| 1/2010 | Boeing 777-236ER, G-YMMM<br>at London Heathrow Airport<br>on 17 January 2008.<br>Published February 2010.  | 6/2010 | Grob G115E Tutor, G-BYUT<br>and Grob G115E Tutor, G-BYVN<br>near Porthcawl, South Wales<br>on 11 February 2009.<br>Published November 2010.  |
| 2/2010 | Beech 200C Super King Air, VQ-TIU<br>at 1 nm south-east of North Caicos<br>Airport, Turks and Caicos Islands,<br>British West Indies<br>on 6 February 2007.<br>Published May 2010. | 7/2010 | Aerospatiale (Eurocopter) AS 332L<br>Super Puma, G-PUMI<br>at Aberdeen Airport, Scotland<br>on 13 October 2006.<br>Published November 2010.  |
| 3/2010 | Cessna Citation 500, VP-BGE<br>2 nm NNE of Biggin Hill Airport<br>on 30 March 2008.<br>Published May 2010.   | 8/2010 | Cessna 402C, G-EYES and<br>Rand KR-2, G-BOLZ<br>near Coventry Airport<br>on 17 August 2008.<br>Published December 2010.  |
| 4/2010 | Boeing 777-236, G-VIIR<br>at Robert L Bradshaw Int Airport<br>St Kitts, West Indies<br>on 26 September 2009.<br>Published September 2010.  | 1/2011 | Eurocopter EC225 LP Super Puma,<br>G-REDU<br>near the Eastern Trough Area Project<br>Central Production Facility Platform in<br>the North Sea<br>on 18 February 2009.<br>Published September 2011. |
| 5/2010 | Grob G115E (Tutor), G-BYXR<br>and Standard Cirrus Glider, G-CKHT<br>Drayton, Oxfordshire<br>on 14 June 2009.<br>Published September 2010.  | 2/2011 | Aerospatiale (Eurocopter) AS332 L2<br>Super Puma, G-REDL<br>11 nm NE of Peterhead, Scotland<br>on 1 April 2009.<br>Published November 2011.  |

Unabridged versions of all AAIB Formal Reports, published back to and including 1971,  
are available in full on the AAIB Website

<http://www.aaib.gov.uk>