

# **Service Inquiry**

Puma XW229 11 Oct 15

Defence Accident Investigation Branch

#### **PART 1.1 - COVERING NOTE**

SI/18/15/XW229

15 Sep 16

DG DSA

# SERVICE INQUIRY INVESTIGATION INTO ACCIDENT INVOLVING A PUMA HC MK 2 XW229 AT HEADQUARTERS RESOLUTE SUPPORT, KABUL, AFGHANISTAN ON 11 OCT 15

- 1. The Service Inquiry Panel assembled at Farnborough, on the 15 Oct 15 by order of the DG DSA for the purpose of investigating the accident involving Puma HC Mk2 XW229 on 11 Oct 15 and to make recommendations in order to prevent recurrence. The Panel has concluded its inquiries and submits the provisional report for the Convening Authority's consideration.
- 2. The following inquiry papers are enclosed:

Part 1 (The Report)

Part 1.1 Covering Note

Part 1.2 Convening Orders & TORs

Part 1.3 Narrative of Events

Part 1.4 Analysis and Findings

Part 1.5 Recommendations

Part 1.6 Convening Authority Comments

Part 2 (The Record of Proceedings)

Part 2.1 Diary of Events

Part 2.2 List of Witnesses

Part 2.3 Witnesses Statements

Part 2.4 List of Attendees

Part 2.5 List of Exhibits

Part 2.6 Exhibits

Part 2.7 List of Annexes

Part 2.8 Annexes

Part 2.9 Schedule of matters Not Germane

Part 2.10 Master Schedule

**PRESIDENT** 

Commander Royal Navy President XW229 SI

**MEMBERS** 

Major Engineering Member XW229 SI Squadron Leader Aircrew Member XW229 SI



# **PART 1.2**

# Convening Order including Terms of Reference Glossary





# Service Inquiry Convening Order

15 Oct 15

SI President SI Members Hd Defence AIB DSA Legad

Copy to:

COS/SofS PS/PUS MA/Min(AF) DPSO/CDS NA/CNS MA/CGS PSO/CAS PSO/Comd JFC

MA/D MAA MA/Comd JHC Stn Cdr Benson

MA/VCDS MA/CJO

DSA DG/SI/05/15 – CONVENING ORDER FOR THE SERVICE INQUIRY INTO THE AIRCRAFT ACCIDENT INVOLVING PUMA MK2 XW229 ON 11 OCT 15 AT 1625(D) IN KABUL, AFGHANISTAN.

- 1. A Service Inquiry (SI) is to be held under Section 343 of Armed Forces Act 2006 and in accordance with JSP 832 Guide to Service Inquiries (Issue 1.0 Oct 08).
- 2. The purpose of this SI is to investigate the circumstances surrounding the subject aircraft accident and to make recommendations in order to prevent recurrence.
- 3. The SI Panel will formally convene at the Defence Accident Investigation Branch (Defence AIB), Farnborough at 0930Z on Thu 15 Oct 15 prior to deploying to theatre.
- 4. The SI Panel comprises:

President:

Cdr RN

Members:

Sqn Ldr RAF

- 5. The legal advisor to the SI is **Maj** (DSA Legad) and technical investigation/inquiry assistance is to be provided by the Defence Accident Investigation Branch (Defence AIB).
- 6. The SI is to investigate and report on the facts relating to the matters specified in its Terms of Reference (TOR) and otherwise to comply with those TOR (at Annex). It is to record all evidence and express opinions as directed in the TOR.



7. Attendance at the SI by advisors/observers is limited to the following:

Head Defence AIB - Unrestricted Attendance.

Defence AIB investigators in their capacity as advisors to the SI Panel – Unrestricted Attendance<sup>1</sup>.

and and Reference, RAFCAM HF Psychologists – Unrestricted Attendance

**USA Military Observer - name tbc** 

French Military Observer - name tbc

- 8. On return from theatre the SI Panel will work initially from the Defence Accident Investigation Branch facilities at Farnborough and Boscombe Down. Permanent working accommodation, equipment and assistance suitable for the nature and duration of the SI will be requested by the SI President in due course.
- 9. Reasonable costs will be borne by DG DSA under UIN

Original Signed

R F Garwood AM DG DSA – Convening Authority

Annex:

A. Terms of Reference for the SI into aircraft occurrence involving Puma Mk2 XW229 on 11 Oct 15 at 1625(D) in Kabul, Afghanistan.

<sup>&</sup>lt;sup>1</sup> On a case by case basis as authorised by Hd Defence AIB.



ANNEX A TQ PUMA XW229 SI Convening Order Dated 15 Oct 15

# TERMS OF REFERENCE FOR THE SERVICE INQUIRY INTO THE AIRCRAFT ACCIDENT INVOLVING PUMA MK2 XW229 ON 11 OCT 15 AT 1625(D) IN KABUL, AFGHANISTAN.

- 1. As the nominated Inquiry Panel for the subject SI, you are to:
  - a. Investigate and, if possible, determine the cause of the occurrence, together with any contributory, aggravating and other factors and observations.
  - b. Ascertain whether the personnel involved were acting in the course of their duties.
  - c. Examine what policies, orders and instructions were applicable and whether they were complied with.
  - d. Determine the state of serviceability of the aircraft and relevant equipment.
  - e. Establish the level of training, relevant competencies, qualifications and currency of the individuals involved in the activity.
  - f. Review the levels of authority and supervision covering the task during which the incident occurred.
  - g. Identify if the levels of planning and preparation were commensurate with the activities' objectives.
  - h. Investigate and comment on relevant fatigue implications of individuals' activities prior to the matter under investigation.
  - i. Determine any relevant equipment deficiencies.
  - Confirm that the aircraft post-crash management procedures were adequate and carried out correctly.
  - k. Determine and comment on any broader organizational and/or resource factors.
  - I. Assess whether the security of personnel, equipment or information was compromised and if so to what degree.
  - m. Ascertain the value of loss/damage to the Service.
  - n. Assess any Health and Safety at Work and Environmental Protection implications in line with JSP 375 and JSP 418.
  - n. Report and make appropriate recommendations to DG DSA.
- 2. You are to ensure that any material provided to the Inquiry by the United States, or any other foreign state, is properly identified as such, and is marked and handled in accordance with MOD



security guidance. This material continues to belong to those nations throughout the SI process. Before the SI report is released to a third party, authorization should be sought from the relevant authorities in those nations to release, whether in full or redacted form, any of their material included in the SI report, or amongst the documents supporting it. The relevant NATO European Policy (NEP) or International Policy and Plans (IPP) team should be informed early when dealing with any US or other foreign state material.

3. During the course of your investigations, should you identify a potential conflict of interest between the CA and the Inquiry, you are to pause work and take advice from your DSA Legal Advisor, Hd Defence AIB and DG DSA. Following that advice it may be necessary to reconvene reporting directly to MOD PUS.



# PART 1.2 - GLOSSARY OF TERMS

ACA	Airspace Control Authority
ACO	Airspace Control Order
ACP	Airspace Control Plan
ACP	Auto-Pilot Caution Panel
ADS	Air System Document Set
AFCS	Automatic Flight Control System
AFG	Aircrew Flying Guide
AFT	Annual Flying Task
AGL	Above Ground Level
AH	Airbus Helicopters
AHRS	Attitude and Heading Reference System
AIB	Accident Investigation Branch
AIDU	Aeronautical Information Documents Unit
AIL	Advance Information Leaflet
AIP	Aeronautical Information Publication
AIRAC	Aeronautical Information Regulation And Control
ALARP	As Low As Reasonably Practicable
ALM	Air Load Master
AMSL	Above Mean Sea Level
ANA	Afghan National Army
AO	Area of Operations
AOB	Angle of Bank
AP	Auto-Pilot
APG	Aviation Procedures Guide
ARM	Accident Route Matrix
ASMP	Air Safety Management Plan
ASMS	Air Safety Management System
ATC	Air Traffic Control
ATEC	Aircraft Test and Evaluation Centre
ATO	Air Tasking Order
ATP	Allied Tactical Publication
AUM	All Up Mass
AVAD	Automatic Voice Alert Device
AWC	Air Warfare Centre
BALCS	Body Armour Load Carriage System
BDOC	Base Defence Operations Centre
C2	Command and Control
CAS	Calibrated Airspeed
CAT	Category



1

CCTV	Closed Circuit Television
CEP	Communications Ear Plug
CFACC	Combined Forces Air Component Commander
CFIT	Controlled Flight into Terrain
CI	Command Instruction
CLE	Clearance with Limited Evidence
CofC	Chain of Command
CofG	Centre of Gravity
COMBRITFOR	Commander British Forces
COS(OPS)	Chief of Staff (Operations)
CR	Combat Ready
CRM	Crew Resource Management
CRR	Consolidated Risk Register
CTAF	Common Traffic Advisory Frequency
CVFDR	Combined Voice and Flight Data Recorder
CWP	Caution/Warning Panel (also known as Central Warning Panel)
DA	Density Altitude
DAS	Defensive Aids Suite
DASOR	Defence Air Safety Occurrence Report
DDH	Delivery Duty Holder
DE&S	Defence Equipment and Support
DHAN	Duty Holder Advice Note
DHUD	Day Head Up Display
DMS	Dynamic Mission Simulator
D-NAC(A)	Deputy-NATO Air Commander (Afghanistan)
DNVG	Display Night Vision Goggles?
DSG	Detachment Support Group
EA	Energy Attenuating
EASA	European Aviation Safety Agency
EQ	Environmental Qualification
ET.	Environmental Training
FAR	Federal Airworthiness Regulation
FLT	Flight
FM	Frequency Modulation
FOB	Flying Order Book
FOV	Field Of View
FP	Force Protection
FRC	Flight Reference Cards
Ft	Feet
FY	Financial Year




GDAS	Graphical Data Analysis System
GPMG	General Purpose Machine Gun
HF	Human Factors
HFACS	Human Factors Analysis Classification System
HKIA(N)	Hamid Karzai International Airport (North)
HKIA(S)	Hamid Karzai International Airport (South)
HLS	Helicopter Landing Site
HMD	Helmet Mounted Display
HMS	Health Monitoring System
HP	Handling Pilot
HQ	Headquarters
HQRS	Headquarters RESOLUTE SUPPORT
Hr	Hours
IECD	In Ear Communication Device
IFR	Instrument Flight Rules
ICAO	International Civil Aviation Organisation
IOC	Initial Operating Capability
JARTS	Joint Aircraft Recovery and Transportation Squadron
JHC	Joint Helicopter Command
Kg	Kilogram
Km	Kilometre
Kts	Knots (Aeronautical)
LCA	Lateral Cyclic Authority
LEP	Life Extension Programme
LHS	Left Hand Seat
LZ	Landing Zone
MAA	Military Aviation Authority
MATZ	Military Aerodrome Traffic Zone
MF700	MOD Form 700
MGBP	Main Gear Box Pressure
MIG	Materials Integrity Group
MOB	Main Operating Base
MOD	Ministry Of Defence
MRB	Main Rotor Blade
MRGB	Main Rotor Gear Box
NAS	Naval Air Squadron
NATO	North Atlantic Treaty Organisation
Nf	Power Turbine rotation speed
NHP	Non-Handling Pilot
NKC	New Kabul Compound



Nm	Nautical Mile
Nr	Main Rotor rotation speed
OCC	Operational Capability Certificate
ODH	Operating Duty Holder
PCM	Post Crash Management
PCMIO	Post Crash Management Incident Officer
PDT	Pre-Deployment Training
PJHQ	Permanent Joint Headquarters
PPR	Prior Permission Required
PT	Project Team
PTDS	Persistent Threat Detection System
PTF	Puma Training Flight
PTL	Project Team Leader
QA	Quality Assurance
RAF	Royal Air Force
RAFCAM	Royal Air Force Centre of Aviation Medicine
RHS	Right Hand Seat
RMP	Royal Military Police
RNAS	Royal Navy Air Station
ROZ	Restricted Operations Zone
RSOI	Reception, Staging, Onward Integration
RtL	Risk to Life
RTS	Release to Service
RTSA	Release to Service Authority
RW	Rotary Wing
RWAMMWAS	Rotary Wing Aircrew Moving Map Wires Alerting System
RWOETU	Rotary Wing Operational Evaluation and Training Unit
RWTES	Rotary Wing Test and Evaluation Squadron
SAS	Stability Augmentation System
SA	Situation Awareness
SOC	Soccer Field Helicopter Landing Site
SOP	Standard Operating Procedure
SQN	Squadron
SRF	Sortie Report Form
STANAG	Standardisation Agreement
STANO	Standards Officer
SUA	Special Use Airspace
TAD	TORAL Aviation Detachment
TASI	Training and Standardisation Instructions
TES	Theatre Entry Standard







TOA	Transfer of Authority
TOR	Terms of Reference
TQ	Theatre Qualification
TR	Tail Rotor
TRB	Tail Rotor Blade
TRDS	Tail Rotor Drive Shaft
TRiM	Trauma Risk Management
TTP	Training, Tactics and Procedures
UASRR	Unified Air Safety Risk Register
US	United States
USAF	United States Air Force
VAMP 27	Ventilated Aviator Moulded Plug 27dB
VFR	Visual Flight Rules
W&M	Weight and Moment
WSOP (ALM)	Weapons System Operator (Air Load Master)



#### PART 1.3 - NARRATIVE OF EVENTS

All times Local (ZULU plus 4.5 hours).

# **Synopsis**

On 11 Oct 15 at 1623 hours (hrs), a Royal Air Force Puma HC Mk2 Helicopter, tail number XW229, struck the tether of a Persistent Threat Detection System (PTDS) aerostat and crashed onto a road junction within the confines of the NATO Headquarters in Kabul, Afghanistan.

Exhibit 1 Exhibit 2

The aircraft was the subordinate element of a formation of two Puma aircraft conducting administrative tasking in support of the NATO Mission in Afghanistan.

Exhibit 3 Exhibit 4

Two crew members (Aircraft Captain and Crewman) and 3 passengers (2 1.3.3 United States (US) military and one French civilian) were killed. The third crew member (Co-pilot) and 3 additional passengers (one US military, one US civilian and one Lithuanian military) suffered various major injuries. One Turkish military bystander sustained major injuries<sup>2</sup>.

Exhibit 5 Exhibit 6

#### **Narrative**

On 11 Oct 15 two Pumas were operating as a formation with the callsign 1.3.4 in support of Operation TORAL3; lead aircraft (ZJ955) was (A21), the number 2 (XW229) was (A22). The day's tasking consisted of 4 scheduled sorties with the first launch at 09:10 hrs and the final landing planned for approximately 1625 hrs.

Exhibit 3

Exhibit 5

Exhibit 7

Exhibit 8

At around 1500 hrs, on completion of the third planned sortie, the formation arrived back at the TORAL Aviation Detachment (TAD)4, which was situated on the southern side of Hamid Karzai International Airport (HKIA)<sup>5</sup>, before shutting down for refuelling. At approximately 1510 hrs the crews received an additional task from TAD Operations to transport 2 UK military passengers from the TAD to New Kabul Compound (NKC)<sup>6</sup> in order to collect forensic evidence from a Vehicle Borne Improvised Explosive Device attack against a UK military convoy earlier that day.

Exhibit 9 Exhibit 11 Witness 3 Exhibit 12

Having completed this additional task without incident, A21 and A22 resumed their original tasking at 1617 hrs, approximately 10 mins later than planned.

Exhibit 4 Exhibit 9 Exhibit 10

1.3.7 This task was the fourth scheduled sortie of the day involving the transfer of multinational passengers (civilian and military) between numerous Helicopter Landing Sites (HLS) within Kabul. Previous sorties had each lasted approximately 50 mins and this sortie was expected to be similar in duration. Passenger embarkation was not undertaken at the normal loading point due to an on-going

Exhibit 4

Exhibit 13 Witness 5

Witness 3

<sup>2</sup> Categorised 'major' due to time in hospital.

<sup>6</sup> NKC was a NATO compound in Kabul.



<sup>&</sup>lt;sup>1</sup> The tether acted in a mooring capacity as well as providing electrical feeds to/from the aerostat.

<sup>&</sup>lt;sup>3</sup> Operation TORAL was the UK's contribution to the NATO mission in Afghanistan – Operation RESOLUTE SUPPORT.

<sup>&</sup>lt;sup>4</sup> The TAD was the operating and accommodation facility for the UK Puma detachment.

<sup>&</sup>lt;sup>5</sup> The elevation of HKIA was 5877ft Above Mean Sea Level (AMSL).

crash response exercise<sup>7</sup> on the airfield; the different embarkation point required the use of minibuses to move passengers between the HKIA North (N) terminal<sup>8</sup> and the aircraft.

1.3.8 Six passengers were loaded onto each aircraft. However, the transfer of passengers from the minibuses inadvertently resulted in a swap of the manifested passengers between aircraft.

Witness 5 Exhibit 5

1.3.9 The formation departed HKIA (N) at 1617 hrs initially following the track of Runway 29 before turning to the South East for the 2.4 nm (4.5 km)<sup>9</sup> transit towards HLS SOCCERFIELD (SOC) at Headquarters RESOLUTE SUPPORT (HQRS)<sup>10</sup>. The formation route and key locations are shown in Figure 1.3.1. The aircraft flew 'Trail Formation' which allowed A22 to operate between 2 rotor spans and 2 km from the lead aircraft; the formation transited at a height of 500 ft Above Ground Level (AGL). The reported meteorological conditions at SOC were; wind variable 4 kts, visibility 10 km or greater with no cloud reported.

Exhibit 10 Exhibit 12 Exhibit 14

Exhibit 15 Exhibit 16

Exhibit 10




Figure 1.3.1 - Formation route and key locations

<sup>&</sup>lt;sup>10</sup> Operation RESOLUTE SUPPORT was the NATO operation in Afghanistan, HQRS is the NATO HQ in Kabul.



1.3 - 2

<sup>&</sup>lt;sup>7</sup> The exercise was a Civilian Afghan Airport Authority activity not involving the TAD.

<sup>&</sup>lt;sup>8</sup> All passengers routinely departed/arrived at HKIA from a designated passenger handling facility that was located on the north side of the airfield.

Direct line distance.

1.3.10 Once in the vicinity of HQRS, A21 and A22 established themselves to the east of SOC on a downwind leg<sup>11</sup> orientated south south-west. The formation then completed a right hand turn onto a north north-east final approach path but having descended to approximately 160 ft<sup>12</sup> AGL, elected not to land due to the presence of people playing football at the northern end of the field; they then conducted a go-around.

Exhibit 10 Witness 3

Exhibit 2 Exhibit 34

1.3.11 After overflying SOC and routing to the north-east, both aircraft climbed to 500 ft AGL and turned to follow a track similar to the previous downwind leg with A22 remaining in trail formation. During their transit south for a further approach, it became apparent that the HLS was still occupied and A21 conducted a right-hand orbit at 500 ft AGL to the south-east of the HQRS compound. The south eastern corner of the HQRS compound housed the PTDS and associated infrastructure; on 11 Oct 15, the PTDS aerostat, Figure 1.3.2, was operating at a height of 2200 ft AGL.

Exhibit 10 Witness 3 Exhibit 17 Exhibit 18 Exhibit 19 Exhibit 34



Figure 1.3.2 - HQRS PTDS in the 'down' position

- 1.3.12 As the formation passed to the south of the HQRS compound, and as A21 turned through north into a holding orbit, A22 lost sight of the lead aircraft. Shortly afterwards A22 increased its Angle of Bank during a right hand turn and was seen by observers on the ground to impact the PTDS tether.
- Exhibit 10 Exhibit 20 Exhibit 21 Exhibit 34
- 1.3.13 During the orbit, A21 Crewman's attention was drawn to A22 who appeared to be overhead the eastern compound wall and conducting a 'fly by' of the HLS. A21's Crewman assumed that A22 was checking to see if the HLS was clear. Three seconds later A22 transmitted a Mayday call on the inter-aircraft frequency, until this moment, the crew of A21 were unaware that A22 had collided with the PTDS tether.
- Exhibit 10 Exhibit 34 Witness 5
- 1.3.14 A further short Mayday call was transmitted 12 seconds later by A22 followed by a transmission of "Throttles". The aircraft was witnessed losing height

Exhibit 10 Exhibit 2

<sup>&</sup>lt;sup>12</sup> A21 descended to approximately 160 ft AGL and A22 descended to approximately 175 ft AGL.



<sup>11</sup> A downwind leg is generally parallel and opposite to the landing direction.

and described as being uncontrolled; it impacted the ground within the HQRS compound.

1.3.15 A22 was observed from the ground to have struck the PTDS tether midway along the Main Rotor Blades (MRBs) on the right hand side of the aircraft. The tether parted and the PTDS aerostat drifted to the North West; the lower section of tether fell into the PTDS operating site. Eye witnesses reported that immediately prior to the impact with the ground, A22's MRBs were rotating but the Tail Rotor was stationary.

Witness 5
Exhibit 22
Witness 4
Exhibit 21
Exhibit 19
Exhibit 17
Exhibit 23

1.3.16 A22 impacted the ground between buildings within the HQRS compound. The location within HQRS is shown in Figure 1.3.3; the aircraft is pictured in Figure 1.3.4. There was no immediate post-crash fire and a considerable number of personnel on the ground assisted in the rescue of the crew and passengers, the first of which was on scene within 15 seconds. As rescue activity progressed the initial responders were joined by the HQRS Fire Service and medical personnel. Numerous hand held fire extinguishers were discharged to mitigate the risk of fire due to leaking fuel; A22 had approximately 350 kg of fuel on board at the time of the accident. Rescue activities continued for approximately 1.5 hours until all crew and passengers were extracted from the aircraft.

Exhibit 2 Exhibit 10 Exhibit 24

Exhibit 25

Exhibit 26




Figure 1.3.3 - Location of A22 crash site





Figure 1.3.4 - Aircraft post-accident

- 1.3.17 Following extraction from the aircraft, casualties were taken to the HQRS medical facility for triage. Thereafter, and dependent on the nature of their injuries, they were transferred to medical facilities at HKIA(N) or Bagram Air Base.
- 1.3.18 Post-accident, A21 remained airborne providing a confirmatory Mayday call to Kabul Air Traffic Control Tower and TAD Ops, as well as acting as a communication relay, before landing at SOC to discharge passengers.
- 1.3.19 After departure from SOC, A21 climbed to 2000 ft AGL due to concerns about the location of the untethered PTDS aerostat, and held in the overhead before being advised by TAD Ops to return to HKIA. A21 landed at the TAD at 1645 hrs.

## **Post-Crash Management**

1.3.20 Post-Crash Management activity was coordinated by a member of the HQRS staff. Once the initial emergency response had finished the site was handed over to the HQRS Base Defence Operations Centre for the ensuing cordon and control. NATO troops were used for the guard force and cordon party throughout with a permanent UK military presence on the crash site being initially provided by the Royal Military Police (RMP) and then the resident infantry battalion. Except where authorised and necessary, the wreckage remained undisturbed between the end of the emergency response and the arrival of the Defence Accident Investigation Branch (AIB) investigators on 13 Oct 15. The initial collection and preservation of evidence was coordinated by the RMP Special Investigation Branch, the Post-Crash Management Incident Officer and TAD staff.

Exhibit 6 Exhibit 27

Exhibit 10 Exhibit 28 Witness 1 Witness 3 Exhibit 28 Exhibit 29 Witness 3

Exhibit 26



# Casualties

1.3.21 The aircraft Captain and Crewman died as a result of the accident, the Copilot sustained major injuries. Three passengers were killed, 2 US Air Force (USAF) personnel and one dual nationality UK/French civilian contractor. The remaining passengers, one USAF, one US civilian contractor and one Lithuanian military all suffered various major injuries. One Turkish military bystander sustained major injuries.

Exhibit 6

1.3.22 The deceased USAF personnel were repatriated to the USA on 14 Oct 15 and the UK and French deceased to the UK on 20 Oct 15. The French national was subsequently repatriated to France. The injured USAF passenger was transferred to Ramstein Air Force Base in Germany on 12 Oct 15 and the Co-pilot to the UK on 13 Oct 15. The Lithuanian casualty was also flown to Ramstein, arriving on 15 Oct 15. The injured US contractor returned to work on the 13 Oct 15 before returning to the US.

Exhibit 27

# Salvage operations

1.3.23 A Joint Aircraft Recovery and Transportation Squadron (JARTS) team arrived on site 16 Oct 15 and carried out initial assessments of recovery actions and possible routes for movement of wreckage. On completion of Defence AIB evidence gathering on 19 Oct 15, JARTS prepared the wreckage for transportation under the guidance of Defence AIB investigators. Due to transport limitations, access to the crash site and Force Protection considerations for road movement, the wreckage was cut into sections to facilitate transportation. The wreckage was moved by road over 2 nights on 20 and 21 Oct 15 to a secure hangar at HKIA (N). It was subsequently recovered using a RAF C17 to RAF Brize Norton and moved to MOD Boscombe Down on 3 Nov 15 for detailed investigation.

Exhibit 30

## Aircraft and infrastructure damage

1.3.24 On impact with the ground the aircraft suffered extensive damage. Further significant damage occurred during the rescue response as elements of the airframe were cut away to facilitate the extraction of casualties; this secondary damage was caused by individual actions to manually move airframe structure or by HQRS Fire Service personnel using specialist cutting equipment.

Exhibit 25 Exhibit 31 Exhibit 32

1.3.25 Damage to HQRS infrastructure was limited to the MRBs striking an accommodation building's roof and an air conditioning unit. There was some contamination of the HQRS drainage system due to fuel spillage and the extensive use of fire suppressing agents during the immediate response.

Exhibit 26 Exhibit 32

