

Fire and Solar PV Systems – Investigations and Evidence

Prepared for: Penny Dunbabin, Science and Innovation, BEIS

Date: 17th July 2017

Report Number: P100874-1004 Issue 2.5



BRE National Solar Centre
Eden Project
St Blazey
Cornwall
PL24 2SG

T + 44 (0) 1726 871 830

E nsc@bre.co.uk

W www.bre.co.uk/nsc

Customer service:

+44 (0) 3333 218 811

Prepared by

Name Steve Pester, Principal Consultant, BRE National Solar Centre



Date 31st January 2017

Edited by

Name Chris Coonick, Senior Consultant, BRE National Solar Centre



Date 17th July 2017

Authorised by

Name Dr David Crowder, Head of Fire Investigation and Expert Witness Services
(Lead QA for project)

Signature 

Date 12th February 2017



Contract and use

This work has been carried out by members of the Building Research Establishment Ltd (BRE), BRE National Solar Centre (NSC) and the BRE Global Fire Safety Group, on behalf of the Department of Energy and Climate Change, Contract number TRN 1011/04/2015, agreed, 21/07/15. Since July 2016, the Department of Energy and Climate Change has been merged with the Department for Business Innovation and Skills to create a new Department for Business, Energy and Industrial Strategy (BEIS).

This report is made on behalf of BRE and may only be distributed in its entirety, without amendment, and with attribution to BRE to the extent permitted by the terms and conditions of the contract. BRE's liability in respect of this report and reliance thereupon shall be as per the terms and conditions of contract with the client and BRE shall have no liability to third parties to the extent permitted in law.

Acknowledgements

Thanks are due to researchers, investigators, technical advisers and contributors of information leading to this report:

James Acott, Fire Investigations (UK) LLC
Mike Burroughs, Fire Investigations (UK) LLC
Chris Clarke, Fire Investigations (UK) LLC
Chris Coonick, BRE National Solar Centre
David Crowder, BRE Global Fire Safety
Martin Cotterell, BRE Associate
Mike Flanagan, Fire Investigations (UK) LLC
John Galvin Fire Investigations (UK) LLC
Ciara Holland, BRE Global Fire Safety
Peter Mansi Fire Investigations (UK) LLC
Julian Parsons (Buckinghamshire Fire & Rescue Service and Chief Fire Officers Association)
Martin Shipp, BRE Global Fire Safety
Simon Smith, Prometheus
Jonny Williams, BRE National Solar Centre
Fire and Rescue Services responding



Contents

Contract and use	3
Acknowledgements	3
1 Introduction	6
1.1 Background	6
2 Project outline	8
2.1 Organisations involved	8
2.2 Programme	8
2.3 Reports	9
3 Methodology	10
3.1 Review of literature, standards and training	10
3.2 Communications	10
3.3 Establishment of the database	10
3.4 Incident investigations	11
3.4.1 Historical incident research	12
3.4.2 Site investigations	12
3.4.3 Laboratory examinations	15-14
3.4.4 Desk investigations	15
4 Mechanisms for ignition of fires on PV systems	16
4.1 Introduction	16
4.2 Electrical Arcing	16
4.3 Evidence of arcing	16
4.4 Causes of arcing	17
4.5 Other potential mechanisms	17
5 Findings	18
5.1 Overview	18
5.2 Data sources	18
5.3 Fire severity and PV involvement	18
5.4 Casualties	19
5.5 Building or site type	20
5.6 PV components implicated	20
5.7 Root cause	21
6 Interpretation of scene evidence	22



6.1	DC Isolators	22
6.2	DC connectors and cables.	25
6.3	Inverters	28
6.4	PV Modules	29
7	Fire & Rescue Services	30
7.1	Awareness	30
7.2	Issues reported by FRS	30
8	Conclusions	31
8.1	This report	31
8.2	Project overview	31
8.3	Summary of findings	32
8.4	Challenges	34
8.5	Next steps	34
	References	35
	Appendix A Database description	36
	Database fields	36
	User interface	38
	Appendix B Summary listing of records (anonymised)	48
	Appendix C Laboratory examination report - example 1	50
	Appendix D Laboratory examination report - example 2	55



1 Introduction

1.1 Background

Over the past few years, there have been a number of media reports linking photovoltaic power systems (PV) with fire. With the prevalence of PV systems now in the UK, an increase in incident reports is to be expected.

The National Statistics website¹ shows that, as of the end of November 2016, overall UK solar PV capacity stood at approximately 11 GW. Figure 1 shows the scale of the increase in deployment since 2010, when the feed-in tariff (FIT) was first introduced.

UK Solar Deployment: By Capacity (updated monthly)




Figure 1: UK PV deployment to November 2016¹

¹ www.gov.uk/government/statistics/solar-photovoltaics-deployment



At this point in time (November 2016), 48% (5,452 MW) of total installed UK solar PV capacity came from large scale installations greater than 5 MW, with 21% (2,453 MW) coming from small scale 0 to 4 kW installations, and the overall UK solar PV capacity stood at 11,429 MW across 898,029 installations (provisional figure). This is an increase of 28% (2,484 MW) compared to November 2015.

With this rapid increase in the number of installations comes an inevitable increase in the number of faults with the potential to cause fires. Whilst some incidents have been reported by the press, others have only become known through word of mouth, and it seems likely that a larger number of fire incidents have not been reported, especially where installers have been able to contain and rectify the fault without intervention from the fire services. Previously, there appears to have been no detailed follow-up investigation in order to properly understand the causes of these fires, or how the presence of PV on a building may have influenced firefighting operations.

Despite the now significant number of PV systems installed in the UK and elsewhere, PV is still a relatively young technology. Consequently, the equipment and installation standards that control the industry are still in a process of evolution. The acquisition of incident data from the field, analysis of root causes and reporting is therefore vital to ensure that standards committees have the latest information to work with, creating the conditions for the standards to remain relevant and effective.

Also, how PV systems can influence firefighting operations may be an essential input during the ongoing development of standards.

Since additional requirements within standards very often result in extra costs to be borne by the industry or consumers, understanding the likelihood of particular faults occurring and the severity of the consequences is essential for ensuring that any changes to standards are measured and properly justified.

This project has therefore been established in order to collate accurate information - both historical (pre-project start) and contemporary (reported to BRE since July 2015 for this project) – on fire incidents involving PV systems, and on relevant previous research. The aim of the project is to feed the data and conclusions into industry standards (e.g. [1], [2]) and the National Occupational Guidance system [3], which is used to disseminate information to the fire and rescue services.

To date (January 2017), the project team has completed the following work:

- a literature review
- a review of standards
- a review of training
- established a database of PV fire incidents
- conducted a series of on-site investigations and desk studies of contemporary incidents

The public project description can be found on the NSC website:

<http://www.bre.co.uk/nsc/page.jsp?id=3676>.

Please note that as far as possible, the authors have avoided reproducing any information of a personal or commercially sensitive nature in this report. The only identifiable references relate to the project team and associated fire investigation professionals.



2 Project outline

The project began in July 2015 and runs to 2018. This report is an output from work package (WP) 4,. A short outline of the project is presented below.

2.1 Organisations involved

The project team comprises the following organisations and individuals:

- BRE National Solar Centre (NSC)
- BRE Global Fire Safety Group
- Fire Investigations (UK) LLP (FI-UK)
- A representative of the Chief Fire Officer's Association (CFOA)
- A representative of Prometheus Forensic Services Ltd
- Individual PV experts

The project is owned and funded by the Department for Business, Energy and Industrial Strategy (BEIS).

2.2 Programme

Table 1 gives a brief description of the complete three year project, formed from the following work packages:

WP	Description	Status
1	Review of relevant literature. The literature review produced a total of 184 references, mainly from the PV industry, academia and fire services. The full report was submitted to BEIS 25/11/15.	Completed Nov 2015, minor modifications March 2017
2	Surveys of standards and training. Standards were mainly international (e.g. IEC), whilst training courses were mainly domestic. The full report was submitted to BEIS 25/11/15 and incorporated into the literature review report.	Completed Nov 2015
3	Survey of historical incidents in the UK – the survey involved contacting installers, building owners, the fire services and DCLGs Incident Reporting System. 37 unique historical incidents of fire involving PV systems in the UK were identified. The output was reported as part of WP5.	Completed Jan 2016



4a	Investigations of live and recent PV fire incidents in the UK. WPs 1 – 3 and 5 laid the foundations for on-going investigations into incidents, as they arise (WP4).	On-going until Feb 2018
4b	Additional Work Package introduced as a variation to the contract to enable laboratory examinations of components suspected of causing fires on PV systems to be undertaken. The data from these examinations feed into WP4 and are stored within the database.	On-going
5	Database development and initial population with historical records.	Completed Dec 2015
6	Fire and Solar PV Systems – <i>Literature Review, Including Standards and Training*</i> derived from WP1 & 2).	Completed March 2017
7	Fire and Solar PV Systems – <i>Investigations and Evidence*</i> (derived from WP3, 4 & 5).	Completed March 2017
8	Fire and Solar PV Systems – <i>Recommendations*</i> : a) <i>for PV Industry</i> (derived from WP6 & 7). This report. b) <i>for the Fire and Rescue Services</i> (derived from WP7 & 8)	Completed March 2017
9	Dissemination to BEIS and the solar and fire safety industries	Completion due February 2018

Table 1: Project work packages and status*

* Note: Following a meeting with BEIS in November 2016, the outputs from work packages 6, 7 and 8 have been recast, as shown in the table. The original work packages were as follows:

WP6: Recommendations for improving design and maintenance standards

WP7: Recommendations for improving training

WP8: Recommendations for the safety of fire-fighters in the event of fires involving PV

2.3 Reports

The following reports form the published output from the project to date. The Investigation and Evidence report (this report) will be revised and re-published in February 2018, following the collection of further data; this is also the scheduled end of the project.

- A review of relevant literature, standards and training [4]
- Fire and Solar PV Systems – *Investigations and Evidence* - this report
- Recommendations for the PV industry [5]



- Recommendations for Fire and Rescue Services [6]

3 Methodology

3.1 Review of literature, standards and training

The starting point for the project was a review of relevant literature (WP1). The literature review produced a total of 184 references, mainly from the PV industry, academia and fire services. Next, two further reviews were conducted on relevant standards and training courses.

These reviews are presented as a separate document: *Fire and Solar PV Systems – Literature Review, Including Standards and Training* [4].

3.2 Communications

Under WP3, members of the team used contacts in the fire and PV sectors to seek historical information on known fire incidents involving PV systems. The information gathered was then fed into a database, developed by the project team (described below).

Communications via the Chief Fire Officers Association (CFOA) and the Microgeneration Certification Scheme (MCS) allowed relevant organisations and individuals to be informed of the live incident investigation capability of the project (WP4) and request that any incidents involving PV systems be reported to the team in real time, or as soon as possible after the event.

A project description was also set up on the NSC website: <http://www.bre.co.uk/nsc/page.jsp?id=3676> and an approved article was published in Renewable Energy Installer magazine in December 2016. All communications carried contact details specifically set up for the project:

email: solarfire@bre.co.uk and a telephone number: 0333 0033 314.

As a result of the communications efforts, as well as regular media searches, data on live or recent incidents started to arrive. In cases where remedial measures had been completed, or evidence destroyed, the team opted not to visit the site, but to collect data by telephone and email ('desk studies').

3.3 Establishment of the database

In order to provide a secure and durable location to store data on fire incidents collected during the life of the project, a basic database with a secure web portal interface was designed, tested and implemented on a server located at BRE headquarters in Watford (WP5).

The information to be captured by the database was selected by discussion with BEIS (then DECC) and fire and PV experts at BRE.

The information necessarily contains personal data (names and addresses) and commercially sensitive data (names of products, suppliers, etc.). This is to ensure validation of information sources and to prevent duplication of incident records. Therefore, in accordance with the contract with BEIS and BRE's own procedures, the data resides only on the secure server at BRE, with only named members of the BRE team having controlled access. The database has the facility to export anonymised records only.

The diagram in Figure 2 illustrates the flow of incident data and the conceptual structure of the database.




Figure 2: Fire incident data flow and conceptual structure of database. Each record consists of some 75 data fields.

A more detailed description of the database data fields and images of the interface portal can be seen in Appendix A. An anonymised summary of the records to date is provided in Appendix B.

There are currently a total of 58 unique records of fire incidents involving PV in the database. These are made up of 33 historical incidents and 25 that have been investigated by the team, either on-site or by desk studies, as appropriate.

3.4 Incident investigations

Once the database and portal had been set up and tested, the historical incident data collected under WP3 were entered. Data from new incidents were entered as the information became available from on-site, laboratory and desk investigations. Each incident is assigned a unique identification label, of the form "PVFxxxx", where "xxxx" is a serial number. The various data collection activities are described below.

It should be noted that data on "thermal events", incidents in which overheating occurred, but did not develop into a fire, were also captured where possible. These incidents are interesting because they can provide direct evidence of potential causes of fires, with only the overheated components being



affected and the area around them being undamaged. Usually, thermal events are noticed when smoke is seen to be issuing from a component.

3.4.1 Historical incident research

The historical incident data was gathered mainly by networking with PV industry contacts and fire services.

Under WP3, members of the team used contacts in the fire and PV sectors to gather information on known historical fires involving PV systems (see details in 3.2, above). The DCLG Incident Reporting System (IRS) used by the fire services to record fires was also interrogated. However, the IRS records tend to contain little technical detail on PV-related incidents. Some members of the team were already aware of some incidents and this information was also used where possible.

A data capture form was developed to reflect the database fields, so as to record the data as consistently and completely as possible. The content of the form is virtually identical to that shown in Appendix A, User interface.

The resulting data from the above exercise were then filtered for duplications, as several reports were found to refer to incident data already captured, but with a slightly different name or description.

Data was collected on a total of 33 historical incidents: PVF0002 – PVF004, PVF0006 – PVF0028, PVF0030 – PVF0034, PVF0036 and PVF0038. (The incident numbers are not continuous because data from some earlier investigations, commissioned outside of the project, have been included, and also there was a brief period when live and historical data was arriving simultaneously).

3.4.2 Site investigations

An important feature of the project is the active, fast response, on-site forensic investigations conducted whenever the team was made aware of a suitable incident. The criteria for whether or not to send a team to site is detailed below.

There are three potential scenarios in deciding whether or not to send an investigation team to the site:

- a) Any incident where a PV system is **clearly implicated** as a possible cause of the fire, or a significant hazard for fire fighters. The team would normally seek access to the site in order to investigate. This is not always straightforward as the FRS will not give out any contact details of building owners, so we are often reliant on the FRS to pass our details to the site owner.
- b) Where a PV system is present, but **clearly not implicated** as a cause (e.g. common kitchen fire, such as that from a deep fat fryer). We enquire with the FRS to determine if the PV system caused any concerns or created extra hazards during the firefighting activities. If there were any such issues, these would be recorded, but we would not generally visit the site.
- c) Where a PV system is present, but it is **unclear whether it is implicated** as a possible cause of a fire, we will interview the relevant FRS and, based on the information received, make a decision on whether the site should be visited. In general, if a part, or parts, of the PV system appear to have been damaged, we will send a team to investigate. Where the PV system appears to be undamaged and the FRS reports no issues relating to the PV system we will not investigate further.



In general, a fast response is required so that evidence can be viewed on site prior to any further disturbance from restoration works. The team was normally able to mobilise within 24 hours if permission to access the site had been obtained.

3.4.2.1 Interactions with insurance investigators

It is important to understand that there are other parties with an interest in building fires, aside from the owner and the FRS. Generally, insurance companies will commission their own investigation into the causes of a fire, via a loss adjuster and specialist investigator.

Part of the team's process when attempting to gain access to a site is to establish and make contact with the relevant insurer, loss adjuster or investigator if possible, so as to explain the purpose of the project and give confidence that the team will not disturb evidence likely to be of interest to the insurer's investigator. Usually, if this communication is handled appropriately, the other parties are happy to have the site investigation team on site and will generally agree a time when all parties can be present and can exchange observations and thoughts. This arrangement can be of mutual benefit, allowing more pairs of expert eyes and PV and forensic knowledge to be applied to the investigation at the scene of the fire.

3.4.2.2 Site investigation team

The site investigation team is composed of PV experts and forensic fire investigators. Wherever possible, a PV expert and a fire investigator coordinate to visit the site at the same time. The site investigators underwent training in an early stage of the project in August 2015. The PV experts trained the site investigators and vice versa, with the major focus on health and safety aspects of such site visits.

At the time of writing there are 7 professional fire investigators and 4 PV experts on the site investigation team. The fire investigators are drawn from FI-UK, a company of which BRE is a partner; the PV experts are from the BRE NSC, BRE Scotland and one independent consultant.

3.4.2.3 Health, safety and communications on site

Damaged PV systems can be dangerous, so the first priority at fire scenes is health and safety. In each case a risk assessment (RA) is undertaken at BRE prior to the site visit, using what information is available. Upon arrival on site, the RA is updated with a dynamic assessment of the potential hazards. Typical risks to be assessed and controlled are as follows:

- Falls
- Trips & slips
- Electrocution
- Burns
- Collisions with objects (e.g. banging head on scaffold)

The building is only entered once the hazards have been assessed and controlled sufficiently (e.g. assessing and avoiding dangerous areas, wearing suitable PPE, etc.) to reduce the risk to an acceptable level.

At non-domestic sites, a briefing is sought in order to comply with site regulations, obtain contacts and for orientation.

Good communication with all parties is essential to ensure access to the site, avoid misunderstandings and avoid causing any extra stress to building owners. Therefore, building owners or operators, FRS, insurance investigators, trades people, installers, safety officers, site services, etc.

must be consulted, as appropriate at each scene. In general, once the research project has been explained, our experience is that most people are supportive and helpful.

3.4.2.4 Physical inspection

Since all data is entered into the database, the same data capture form that is used for the historical incident research is used on site.

After the health and safety processes have been completed, the visit normally continues with a short survey of the whole PV system (if possible) and the areas affected by the fire. If the building owner/operator or any witnesses are on hand and they are happy to share information, a conversation is initiated to help piece together the sequence of events leading to the fire incident.

If the relevant parts of the building are deemed stable (this is usually the subject of discussion with FRS operatives/investigators and fire investigators) a detailed search of the apparent seat of the fire, as determined by burn patterns and witness reports, then ensues. This can involve sifting through debris in great detail to look for clues.

Figure 3 shows an example of a domestic roof, with a PV system fitted, destroyed by fire.



Figure 3: Example burnt-out roof with parts of the PV system intact.

Some examples of evidence and its interpretation are shown in section 4.

To date, there have been a total of 12 on-site investigations (incident references PVF0001, PVF0005, PVF0039, PVF0041 and PVF0051 - PVF0058).

Of these there were 6 dwellings, 4 commercial buildings, 1 school and 1 ground-mounted system.

The sequence of reference numbers shows an increase in frequency of site visits over time, which was due to the site visits starting in winter 2015, then being more active over the summer of 2016. Occurrences of PV fires tend to start in early spring, when the first very sunny days of the year occur, and tail off in late autumn.

3.4.3 Laboratory examinations

In cases where a component is identified as the likely cause of a fire incident, the remains may be removed from the scene (with the owner's permission) and transported to a laboratory at BRE for further forensic inspection. A typical example would be a DC isolator switch (see Figure 4), which requires disassembly in a controlled environment and close inspection of small parts in order to arrive at conclusions on the probable cause.



Figure 4: Remains of a DC isolator being disassembled and inspected in the laboratory
(Photo courtesy of Fire Investigations (UK) LLP)

The bench examinations were performed by staff from FI-UK, in their dedicated laboratories at BRE.

A typical examination involves the careful and methodical disassembly of the part under scrutiny, whilst recording any observations. The operative then uses their fire investigation experience to weigh the evidence and arrive at a conclusion on the likely cause of the damage, if possible.

To date, 7 laboratory examinations of components removed from sites have taken place: (incident references PVF0005, PVF0035, PVF0039, PVF0041, PVF0047, PVF0053, PVF0058).

An example laboratory examination report (redacted) can be seen in Appendix C.

3.4.4 Desk investigations

Some incidents are reported after some time has elapsed, rather than when they are 'live' or very recent. Also, in some cases it appears that the benefits of a site visit may be marginal, for example where the evidence on site is likely to have been cleared away. In these cases, the research is limited to interviews by telephone and other desk-based activities, rather than site visits. If useful data is acquired, it is entered directly into the database.

To date, 13 desk-based investigations have taken place: incidents: PVF0035, PVF0037, PVF0040, PVF0042 – PVF0050 and PVF0059.

4 Mechanisms for ignition of fires on PV systems

4.1 Introduction

Generally, PV systems are very safe: the project has so far discovered fewer than 60 incidents and approximately 1 million systems are believed to have been installed over the past seven years (see 1.1).

However, when such incidents do occur, they can have far reaching consequences for families, businesses, and public buildings. Therefore, it is important to understand the fundamental mechanisms by which a fire may spontaneously erupt on a PV system. This section is intended to provide background information on likely mechanisms of ignition on PV systems, for reference in the findings section.

4.2 Electrical Arcing

Electrical arcing is the flow of electrical energy through an air gap by way of ionised gas molecules. Whilst air is normally regarded as a non-conducting medium, a high potential difference (voltage) between two conductors in close proximity can cause the air molecules to break down into their ionised constituents (called a 'plasma'), which can then carry a charge from one electrode to the other.

The temperature of an electrical arc depends on a number of factors, such as the level of current flow, but on a typical PV system, it is easily hot enough to melt glass, copper and aluminium, and to initiate the combustion of surrounding materials.

Arcing is not seen as a common hazard in traditional AC electrical systems. This is partly because the electrical industry standards, practices and component designs have evolved over the last 100 years or so to a point where most modern installations are very safe. PV standards, practices and components, however, are relatively young by comparison and are still evolving.

Another reason that arcing is less of an issue in AC systems is that arcs tend to self-extinguish as the voltage alternates, passing through 0 volts 100 times per second for standard grid supplies. This means that for an arc to be self-sustaining, the conditions for starting the arc have to be present continuously. DC, on the other hand, remains at a continuous voltage and, once an arc has been established, tends to support its continuation.

Thus any evidence of arcing found on sites, whilst not conclusive, points towards a possible, even probable, cause of the fire.

4.3 Evidence of arcing

Figure 5 shows a photograph of evidence of a typical arcing event affecting a DC connector, alongside a similar component that was in the same area of the fire, but without arc damage.




Figure 5: Remains of a DC connector ablated by arcing (a), and by contrast, a connector with contacts still intact and engaged, merely damaged by the surrounding fire (b). In both cases, the insulating body of the connector has been burnt off.

4.4 Causes of arcing

Other sources of heat, such as resistive heating in a corroded connection, could also be an ignition point for a fire, but the temperatures involved tend to be much lower than for an arc. However, such heating can still be a precursor to establishing an arc. For example, it is known that electrical contacts that are exposed to water and oxygen are likely to corrode. It is also known that the build-up of oxide layers on the contacts can lead to resistive heating which, over a period of time, is likely to cause the breakdown of surrounding materials. Once this has occurred, the loss of mechanical integrity of the component can then lead to a break in the circuit and, if conditions allow, the establishment of an arc.

Another potential cause of arcing is the existence of a simple poor connection. Thus the likely causes of arcing on a PV system may be summed up as follows:

- Moisture ingress degrading connections in connectors, junction boxes and switches
- Incorrectly crimped connector contacts
- The mating of incompatible plugs and sockets
- Plugs and sockets not fully engaged
- Loose screw terminals within junction boxes or isolator switches
- Poorly soldered joints within a PV module junction box or other junction box defect
- Damage to a component (e.g. broken busbar within a PV module).

4.5 Other potential mechanisms

Aside from arcing, resistive heating (alone) can be the cause of fires. However, the energy involved tends to be self-limiting: the higher resistance reduces the current in the circuit, which reduces the heating effect disproportionately ($\text{Heat} = \text{Current}^2 \times \text{Resistance}$). Therefore, it is far less likely than arcing to be the only causative mechanism, but as mentioned above, can be a precursor to arcing.



Breakdown of electronic components, such as capacitors or transformers, is possible and these are thought to be likely causes of fires in inverters. However, the statistics collected so far within this project (section 5) do not highlight inverters as a common origin of fires.

5 Findings

5.1 Overview

To date (January 2017), a total of 58 unique incidents have been investigated and incorporated into the database.

The information resulting from the research on historical incidents is less complete than that gathered during active investigations, mainly because previously such incidents have not been logged in any central information store and varying levels of detail are recoverable. However, the completeness of information improves from record PVF0039 onwards as the later records are of investigations conducted by the project team (on-site, from desk or laboratory examinations).

A summarised, anonymised listing of the database records can be seen in Appendix B.

5.2 Data sources

- 33 are historical incidents, arising before the initiation of the project
- 13 of the recorded incidents were desk investigations
- 12 records are of on-site investigations
- 7 of the above records include laboratory examinations of components

5.3 Fire severity and PV involvement

Table 2 shows a breakdown of the types of fire by severity and the relative involvement of the PV system.

Severity of fires	PV involvement			Total
	Caused by PV	Involving PV but not caused by	Cause unknown	
Serious fires	17	10	1	28
Localised fires	16	0	5	21
Thermal events	9	0	0	9
<i>Total</i>	42	10	6	58

Table 2: Summary of severity of fire and PV involvement to January 2017

Fires are classed as *Serious* if they were difficult to extinguish and spread beyond the area of origin.



Localised fires caused some damage to areas surrounding the point of origin, mainly affect PV system components, but did not spread beyond that or threaten the building.

Thermal events consist of components that over-heated, often observed to be smouldering or producing smoke, but did not develop into a fire.

5.4 Casualties

Generally, PV fires have caused damage to PV installations themselves and sometimes to the buildings on which they are mounted. Fortunately, injuries appear to be minor to date.

We have not seen any reports of fatalities resulting from fires originating within PV systems.

Table 3 shows the number of casualties recorded from all sources of information. Confidence in the numbers resulting from site visits and desk studies is high. Information from the historical incidents is less complete.

Injuries / fatalities	Fire caused by PV	Fire not caused by PV	Cause unknown	Total
Injuries / psychological trauma	8	0	0	8
Fatalities	0	1	0	1
<i>Total</i>	<i>8</i>	<i>1</i>	<i>0</i>	<i>9</i>

Table 3: Numbers of casualties recorded in all incidents

The injury types are broken down as shown in Table 4:

Types of injury	Number of people
Smoke inhalation (treated at scene)	5
Minor burn	1
Shock and anxiety	1
Minor injury to knee	1
Fatality	1
<i>Total</i>	<i>9</i>

Table 4: Break down of injury types (all incidents)



5.5 Building or site type

There is an approximately even split between domestic buildings and non-domestic buildings. The latter encompasses commercial as well as public buildings (e.g. schools).

Type of building / site	
Domestic buildings	27
Non-domestic buildings	26
Solar farms	5
<i>Total</i>	<i>58</i>

Table 5: Type of building / site affected by fire

Generally, non-domestic buildings are easier to investigate, since permission to access the site is usually easier to obtain, there may be knowledgeable facilities operative and/or maintenance records, and the incident is less emotive than for domestic premises. Also, access to flat roof areas is usually easier than to the damaged pitched roofs of typical domestic properties.

Solar farms tend to have a tightly controlled maintenance agreement with an Operation and Maintenance (O&M) company. Anecdotal evidence indicates that many solar farm incidents have occurred that have not been reported to the project, or even to the local fire services in some instances. This is because the O&M companies, usually on rapid response service level agreements, tend to deal with issues as they arise and buildings and people are often not affected.

5.6 PV components implicated

Of the incidents that are either known or likely to have been caused by the PV system, fires were recorded to have originated within particular components with the following frequency:

PV Components	Possible		<i>Total</i>
	Probable	further	
DC isolators	16	2	<i>18</i>
DC connectors	4	6	<i>10</i>
DC cables	1	3	<i>4</i>
Inverters	6	1	<i>7</i>
PV modules	1	2	<i>2</i>
Unidentified components	4		<i>4</i>
<i>Total</i>	<i>32</i>	<i>14</i>	<i>46</i>

Table 6: Frequency with which PV components were recorded as the likely cause of fire

All of the samples examined in the laboratory were DC isolators (in just one of these cases the source of the fire was attributed to a connector adjoining the isolator, rather than to the isolator itself). A description of how the above statistics were obtained from the evidence is given in section 5.7, below.



5.7 Root cause

Our analysis suggests there are three possible root causes for PV fires:

- an error in the system design,
- a faulty product (design or quality issue) or
- poor installation practice.

Whilst in some cases it has been possible to identify the root cause, it is not always possible to discern which of these caused a particular incident. However, the best interpretation we have from the information in the database is as follows:

Root cause	Probable	Possible further	<i>Total</i>
System design fault	1	1	2
Faulty product	4	1	5
Poor installation	13	2	15
Unknown	27	-	27
N/A (fire not caused by PV)	9	-	9

These figures should be treated with caution until there is more data available to increase the granularity and confidence.

6 Interpretation of scene evidence

In this report, for the sake of brevity, we do not attempt to describe how every factor and piece of evidence noted at each site or in each witness statement contributed to the interpretation of the data for each incident. However, the examples below illustrate typical evidence for the most common causes of fire attributed to PV systems.

It is suspected that where a non-specialist (e.g. building owner, site manager or FRS) has supplied the information, the terminology may not be as precise as would be used by a PV specialist. For example, 'connectors' may be referred to as 'cables'. Therefore, it is important to understand that there are inevitably uncertainties in the data caused by the variable level of PV expertise on the part of the person reporting. Where the project team has investigated on-site, this is not an issue.

6.1 DC Isolators

DC isolators were found to present the greatest fire risk within the database of incidents. Approximately 30% of the incidents recorded in this study were caused by malfunctions within this component. Often, the evidence is clear, especially where the fire is localised. An example is shown in Figure 6.




Figure 6: Localised fire in which the left hand DC isolator is completely missing, destroyed by a fire, with collateral damage to the adjacent isolator and inverter above.



In this case the evidence from the site and also the laboratory report (included in Appendix C) indicated that the isolators, which were mounted on an exposed exterior wall, were filling with water via the top-mounted cable entries. Across all the incidents reviewed, 4 incidents involved ingress of water into DC isolators, all with upward-facing cable glands.

There is also evidence of fires originating within DC isolators with poor contact design (originally being designed for AC operation and being re-designated as DC-rated by the manufacturer) and with incorrect internal wiring. An example with both of these issues is shown in Appendix D.

In 2014, prior to the start of the PV fire project, evidence of such issues submitted to BRE prompted the publication of a report on the correct selection and deployment of DC isolators on PV systems [7].

Interpreting the data, there appear to be three separate issues with DC isolators:

- 1) Poorly designed or constructed products - The contact design is particularly important for DC isolators. Models that were originally designed for AC are unlikely to be reliable over the life of a PV system. There is 1 possible instance of this (PVF0047), but there was also a pertinent installer error in that case, so the evidence to date is anecdotal and not yet conclusive.
- 2) Incorrectly specified DC isolators – there were 2 instances of this type of fault (PVF0037 and PVF0049). In both cases, the isolators were under-rated for the current or voltage of the PV strings connected.
- 3) Poor installation practice - 9 instances of poorly installed DC isolators were identified. This category therefore accounts for the majority of DC isolator failures leading to fires or thermal events.

In 4, possibly 5, cases of poor installation, the result of the error was the ingress of water into the isolator casing, subsequently causing arcing. In several cases, this was caused by multiple cables being passed through a sealing gland designed to hold one cable. This issue is most acute when the gland is mounted on the upper surface of an isolator enclosure that is exposed to weather – see Figure 7.




Figure 7: More than one cable passing through an upward-facing sealing gland on a DC isolator enclosure mounted on an outside wall.

Even where one cable of the correct size passes through an upward-facing, exposed gland, water may penetrate the enclosure – this was the case for at least 2 incidents – see Figure 8.



Figure 8: Water can be seen inside this enclosure, even though only one cable passes through each gland.

Another issue noted on 2 installations was the drilling of mounting holes through the back of enclosures designed to be weathertight (IP65). An example is shown in Figure 9. The hole on the top right-hand

corner of the enclosure is outside of the weather seal and is designed to be used for a mounting screw without compromising the sealing. However, installers sometimes view drilling through the rear of the box as an easier option, most likely because of the types of screws they have to hand.



Figure 9: Rear of isolator enclosure drilled through for mounting screws. Note that the screw on the right hand side is rusty, indicating water ingress.

In at least 1 case, loose terminal connections were found during laboratory examination.

There were 8 instances of fires most likely caused by DC isolators for which the underlying reason is unknown. In some cases, there was more than one fault.

6.2 DC connectors and cables.

The second PV component most likely to be implicated as the cause of a fire is the DC connector: in 4 cases, the connectors were most likely the source of the fire, in a further 6 cases, they may have been the source.

The DC circuits connect the PV modules together, increasing the voltage in a similar way to connecting batteries in series. Parallel strings of PV modules increase the current. The DC circuits are fed back to the inverter via a DC isolator. Figure 10 shows a simplified schematic diagram of the DC side of a typical small PV system. Larger systems have further parallel strings of PV modules and may also have fuses and junction boxes.




Figure 10: Simplified schematic diagram of DC components in a typical domestic PV system

As mentioned above, in some cases it is suspected that where a non-specialist (e.g. building owner, site manager or FRS) has supplied the information, the terminology may not be as precise as would be used by a PV specialist, and connectors are referred to as ‘cables’, adding some uncertainty to the number of fires where connectors or cables are thought to be responsible.

Figure 11 shows a typical ‘MC4’-type DC connector – these are almost universally used on UK PV installations at this point in time. The metal contacts are crimped onto the ends of the cable and latched into place inside the plastic barrels. Both halves of the connector are touch-proof, improving safety for installation and maintenance crews. Barbs on the upper right hand image lock into slots on the other half to prevent the connector from accidentally separating once the two halves have been pushed together.



Figure 11: Typical (undamaged) DC connectors, separated (top image) and coupled (bottom image)

If the evidence can be accessed at the fire scene, it is often clear if a DC connector has been subject to electrical arcing – molten beads of contact material can usually be observed, as shown in Figure 12.



Figure 12: Example of DC connector contact that has been subject to electrical arcing. The right hand end has been melted.

The finding of such evidence does not necessarily mean that the component caused the fire, since the arcing may have occurred as a result of the fire. However, the experience of the investigating teams has been that the metal contacts of DC connectors tend to remain connected by frictional forces, even when the supporting plastic body has been burnt off – see

Figure 5 ~~Figure 5~~. Therefore, any DC connectors that have been subject to arcing should be suspected as a likely source of ignition.

6.3 Inverters

Inverters form the most complex part of a PV system and they have to actively manage the power continuously flowing through them. From this perspective, it is surprising that a greater proportion of the incidents are not caused by inverter fires. However, unlike DC isolators and connectors, they are 'intelligent' devices, with sophisticated sensors and safety features, and this helps to prevent catastrophic malfunctions.

Nevertheless, in the database there are currently 6 incidents of fires logged as initiating in an inverter and a further 2 incidents that *may* have been caused by inverters.

As with the connectors and cables, it is suspected that where a non-specialist has supplied the information, the terminology may not be as precise as would be used by a PV specialist. In some cases, it is possible that an isolator mounted near to an inverter has ignited but been reported as an 'inverter fire'.

Where an inverter has caught fire, the burn patterns observed at the scene often make this clear – see Figure 13.



Figure 13: Inverter fire with clear burn patterns showing this as the source of the fire.

Further corroborating evidence may be that there were no isolators mounted nearby, or if there were, their conducting parts have not been subject to arcing or resistance heating, and no evidence of arcing at the inverter connectors.

6.4 PV Modules

Where PV modules are the source of fire, there may be evidence of arcing within the remains of one or more of the modules – an example can be seen in Figure 14.



Figure 14: Damaged part of a PV module junction box laid over an identical undamaged component, showing where material has been ablated through arcing.

7 Fire & Rescue Services

7.1 Awareness

Awareness of the project appears to be gradually building, especially amongst fire and rescue services. In most cases that the team has investigated (desk or site investigations), direct contact has been made with the relevant FRS, which have, without exception, been helpful and supportive of the project.

With ongoing assistance from our representative of CFOA, we are continuing to raise awareness of the project amongst the FRSs across the UK; a new letter to chief fire officers is currently being prepared (January 2017).

7.2 Issues reported by FRS

Issues for FRSs caused by PV systems when they were tackling fires (whether or not caused by the PV system) were reported in a total of 12 incidents.

The issues recorded are as follows:

- Potential for electrocution (6 reports)
- Fear of [roof] collapse and live cables
- Unable to isolate live PV cables. Towards the end of the incident, engineers were in attendance [not clear where engineers came from]
- Fire crews could not access the loft to isolate the PV system
- Access may have been slightly more difficult [with PV system in place]
- The roof had metal tiles and fire crews were concerned that a fault in the PV panels could result in the roof becoming live
- [The District Network Operator] knew very little about these systems and how to make them safe. There were lots of uncertainties which made safe systems of work for fire service unpredictable
- After PV system made safe by installer, no issues [delay implied]

We had some particular assistance from Devon and Somerset FRS, who held a formal incident debrief following one of the fires that the team investigated. We sent two representatives to the briefing and the key messages for the project were as follows:

- Fire crews need a method of making the PV system as safe as possible on arrival at the scene. Knowing the system remains live did not prevent the tackling of the fire, but it caused a short delay whilst a dynamic risk assessment was carried out and a suitable strategy put in place.
- Once the fire had been extinguished, the fire crews attempted to make the house as safe as possible and then hand over to the owner. However, there was concern that live DC cables were still exposed in the upper floor.

8 Conclusions

8.1 This report

This report, *Fire and Solar PV Systems – Investigations and Evidence* forms the published output from WP3 and 4 (see below). The report has been produced by building upon the information presented to BEIS in report D4, March 2016.

In the report, background information is given before describing the main work packages making up the project. The methodology is described for the reviews, communications and data collection exercises involved.

A short explanation of electrical arcing is given. This is thought to be the main mechanism of ignition in fires originating in PV systems.

The findings of the data collection exercise are then presented, with a description of the sources of data, severity of fires, numbers and types of human casualties, building types and the PV components most likely to be implicated in the initiation of the fire.

A section on the interpretation of the evidence explains how the conclusions have been arrived at and a short section on feedback from the fire services assists with an understanding of their point-of-view and the issues they face when tackling a fire involving a PV system.

8.2 Project overview

Since its inception in July 2015, the project team has conducted several strands of research on the topic of PV-related fires. We have completed and reported the following outputs:

- A literature review identifying a total of 184 relevant papers
- A review of technical standards
- A review of relevant training courses
- A review of 33 historical fire incidents involving PV systems
- The design and initial population of a database of the historical incidents
- Investigations into 25 new fire incidents involving PV systems as they occurred, incorporating the data into the database

The public description of the project can be found on the following BRE NSC web page: <http://www.bre.co.uk/nsc/page.jsp?id=3676>. We have communicated with the PV industry via targeted articles in the trade press and communications via the Microgeneration Certification Scheme (MCS).

Communications with the fire and rescue community has mainly been via CFOA. The intention is to feed into the National Occupational Guidance system, as suitable reports are produced.

Fire incidents tend to be seasonal, allowing the project team to produce a set of reports over the winter months and to prepare for the next 'season' of investigations into PV-related fires, most likely beginning in April.



The reviews of historical incidents, relevant literature, standards and training are complete and have been reported separately [4]. Therefore, going forward the project activity will consist of investigations into new incidents by desk studies and site visits, further reporting and dissemination activities.

8.3 Summary of findings

To date (January 2017), a total of 58 unique incidents have been investigated and incorporated into the database:

- 33 are historical incidents, arising before the initiation of the project
- 13 of the incidents were investigated remotely (“desk investigations”)
- 12 incidents were investigated on-site shortly after the incident had occurred
- 7 of the investigations include laboratory examinations of fire-damaged components

The severity of the fires varied. 17 of the incidents that were caused by PV systems were classified as ‘serious’ (i.e. difficult to extinguish and spreading beyond the PV system). 25 incidents were localised fires (affecting only PV components and the immediate area) or ‘thermal events’ (smoking or smouldering that did not develop into a fire).

In 10 incidents the cause was not thought to be the PV system and in 6 incidents, there was insufficient information to arrive at a reliable conclusion, so classified as ‘cause unknown’.

In general therefore, PV fires have caused damage to PV installations themselves and sometimes to the buildings on which they are mounted. Fortunately, injuries appear to be mostly minor to date: 5 cases of smoke inhalation (treated at scene), 1 minor burn, 1 case of shock and 1 minor knee injury.

There is 1 fatality recorded in the database, but the fire is known to have originated elsewhere in the house and not within the PV system.

The building types involved break down as follows:

- Domestic buildings 27 incidents
- Non-domestic buildings 26 incidents
- Solar farms 5 incidents

However, we strongly suspect a degree of under-reporting, especially amongst solar farms.



The review of international literature conducted under this project in 2015 [4], concluded that:

Where PV systems have been the cause of fires, some themes emerge. Much attention is paid to the phenomenon of electrical arcing, where a current flows across an air gap by ionising the air. High voltage arcs are extremely hot and can cause combustion of surrounding materials in less than a second. Arcing can occur where conducting parts become physically separated by mechanical movement or mis-alignment. Also, a build-up of contaminants (e.g. oxide) on electrical contacts can cause resistive heating, resulting in the breakdown of materials and subsequent arcing.

Certain components, if incorrectly specified, poorly installed or contain manufacturing faults, are typical locations of electrical arcs:

- *DC connectors*
- *DC isolators*
- *Inverters*
- *PV modules, including by-pass diodes and junction boxes*

The experience of investigating 25 recent incidents in the UK has resulted in very similar findings. The analysis of our database of incidents shows that the PV components most likely to develop faults that lead to a fire incident are as follows:

- DC Isolators 16 - 18 incidents
- DC connectors 4 - 10 incidents
- Inverters 6 - 7 incidents
- DC cables 1 - 4 incidents
- PV Modules 1 - 2 incidents

In 4 cases, the origin of the fire was not traced to any particular component.

Approximately 36% of incidents recorded that were caused by PV systems were attributed to poor installation practices. 12% were attributed to faulty products and 5% to system design errors. The causes of the remainder were unknown.

A summarised, anonymised listing of the database records can be seen in Appendix B.

There are anecdotal reports of power diverters presenting new fire and safety risks. These devices divert excess electricity generated by solar panels to a specific load, such as an immersion heater. However, within this project, we have yet to encounter a fire that appears to have been caused by one of these devices, so the results so far do not support this assertion.

Awareness of the project appears to be gradually building, especially amongst fire and rescue services and with the assistance of CFOA and MCS. This, coupled with seasonal effects, are likely to produce further PV fire incidents in the spring and summer.

Previous anecdotal evidence would seem to indicate that AC isolators re-rated for DC use can be the cause of fires. However, the evidence for this so far is insufficient to be conclusive.



8.4 Challenges

Once the team has been made aware of a live or recent incident, an assessment is made as to whether the site should be visited, based upon the apparent involvement of the PV system. In cases where a site visit is indicated, the next step is to gain permission to access the site. This can be problematic as the owner of the building may not be identified - the FRS cannot pass on contact details without permission. In some cases, this can cause a delay of days or even weeks before we can speak with the owner and seek permission to visit. However, we are in touch with the CFOA representative regarding this issue and a suggestion has been made to add PV and the project contact details to a standard form that is given to householders after a fire incident involving electrical equipment.

A second challenge can be discovering who is investigating the scene on behalf of the building owner's insurance company. In each case we make efforts to determine the identity of the relevant fire investigator in order to coordinate the site visit, support each other's investigation and, ideally, to share resulting information. Our project colleagues at Fire Investigations UK have excellent contacts and relationships with all of the main forensic investigation companies, so this is of great assistance. However, the team has been denied access to one site by the insurance company's loss adjuster, so careful handling of this situation is called for.

Responding to incidents with little notice can be a challenge. Both personal and professional plans may need to be changed. However, the team accepts this as part of the project requirements and we can normally respond within 24 hours.

The database in its current form is rather rudimentary, making it time consuming to extract data and perform analysis. Some relatively minor upgrades to the functionality of the database would allow more efficient processing and analysis of incident characteristics. We have recently introduced an anonymising print-out function that is useful for reporting.

8.5 Next steps

In the work completed up to January 2017, we have produced reviews of relevant literature, standards and training; a report on the evidence found to date (this report) and guidance for both PV industry and fire and rescue services.

In the final year of the project (2017/18), we anticipate investigating further live incidents, increasing the statistical confidence in the data.

Following this, dissemination exercises will be completed during 2017 and an updated report, inclusive of all new incidents investigated in 2017 published in February 2018.

Recommendations, based on the evidence described in this report, have been made in separate reports: [5] and [6]



References

- [1] IET, “Code of Practice for Grid Connected Solar Photovoltaic Systems,” IET Standards, London, 2015.
- [2] Microgeneration Certification Scheme, “Guide to the installation of photovoltaic systems,” Electrical Contractor's Association, London, 2012.
- [3] “National Operational Guidance Programme,” London Fire Brigade, [Online]. Available: <http://www.ukfrs.com/>. [Accessed 02 02 2017].
- [4] S. Pester and S. Woodman, “Fire and Solar PV Systems. Literature Review, Standards and Training,” BRE National Solar Centre, Watford, 2015.
- [5] S. Pester and C. Coonick, “Fire and Solar PV Systems. Recommendations for the PV industry,” BRE National Solar Centre, Watford, 2017.
- [6] S. Pester, C. Holland and C. Coonick, “Fire and Solar PV Systems. Recommendations for fire and rescue services,” BRE National Solar Centre, Watford, 2017.
- [7] S. Pester, “DC isolators for photovoltaic systems - a good practice guide,” IHS BRE Press, Bracknell, 2014.
- [8] S. Pester, “Fire and Solar PV Systems. Investigations and evidence,” BRE National Solar Centre, Watford, 2017.



Appendix A Database description

Database fields

The database consists of a set of some 73 fields per record. Each record pertains to one incident and is given a unique reference number, of the form PVFxxxx, where xxxx is a serial number.

The field headings for each incident record are as follows:

Site Owner / occupier
Address
How did you become aware of this incident?
Date of incident
Time of incident (hh:mm)
Thought to be caused by PV, or PV just present?
Type of installation (Domestic/Non-domestic/Solar farm)
Was the local FRS called?
If no, how was the fire dealt with?
Severity of incident
Type of building
No. of storeys
Type of construction (if known)
Type of roof
If Other, please specify
Age of property
Location of PV array
Location of inverter
Location of isolation switches
General conditions
Wind speed
Wind direction
Precipitation (mm rain)
Irradiance (if known)
Was the property occupied at the time of the fire?
No. of evacuations (if any)
How were the occupants alerted to the fire?
Nature, extent and number of any injuries as a result of the fire?
Extent of fire spread/damage
Any issues with building performance (e.g. collapse, issues with compartmentation, etc.)
Provisional or recorded cause of fire
If PV system, components thought to be involved
Evidence to support likely cause
Any other comments on cause
Date system commissioned
Records of any maintenance (When and type of maintenance)



Is this a BIPV (built-in PV) system

Any comments on DC connectors and cabling (e.g. condition, damage away from fire)

System components	Make	Model
Modules		
Mounting		
Inverter(s)		
DC isolator		
Remote DC switches		
DC connectors		
DC Cable		
DC overcurrent protective devices		
AC cable		
AC protective devices		
Surge protection		
Other		

Type of fire alarm system installed (if any)

Detector fitted specifically for PV system?

If yes, please select type of detector installed

Was the detector linked to the main alarm system?

Location of detector for PV system

Any other active fire protection systems installed (e.g. suppression systems)

If yes, please provide details of other fire protection systems

Remote DC switching device involved

Arc fault detection involved

Earth fault (insulation fault) alarm involved

Did any of the systems mentioned in this section operate?

If yes, please specify

Was there a Solar PV on roof label in place near the main consumer unit/distribution board?

Were the crews aware of the presence of the PV system on arrival?

Did crews notice a Solar PV on roof label near the main electrical intake?

If yes, did this change tactics for fighting the fire?

If yes, how were the tactics changed?

Did crews take any action(s) to make the PV system safe?

If yes, please specify:

Did the PV system cause any particular hazards for fire crews?

If yes, please specify:

Does your service have a Standard Operating Procedure or use any other guidance for dealing with fires involving PVs?

Did the presence of the PV system exacerbate the fire in any way?

Appendix B shows an anonymised summary of the current data set.



User interface

The first screen encountered when entering the portal is the listing. This shows a summary of all database records in short form. The screen shot below shows the listing page with sensitive data redacted.

Full name	ID	Organisation	Email address	Phone number	Date of incident	Address of incident	
Steve Pester	PVF0041	BRE National Solar Centre	steve.pester@bre.co.uk	01923 664 729	[Redacted]	[Redacted]	view
Steve Pester	PVF0040	BRE-NSC	steve.pester@bre.co.uk	01923 664 729	[Redacted]	[Redacted]	view
Steve Pester	PVF0039	BRE-NSC	steve.pester@bre.co.uk	01923 664 729	[Redacted]	[Redacted]	view
Steve Pester	PVF0038	BRE National Solar Centre	steve.pester@bre.co.uk	01923664729	[Redacted]	[Redacted]	view
Chris Coonick	PVF0037	BRE	coonickc@bre.co.uk	07890256131	[Redacted]	[Redacted]	view

Each record is automatically assigned the unique identifier (“ID” column). The ‘view’ link on the right hand side provides access to the full record for each incident.



After the listing page, the user can opt to enter a new record, the first page of which is shown in the next screen shot:

Page 1:

[List of reports](#)

[Logout](#)

Photovoltaics and Fire Safety Data Collection Form

[Back to list](#)

This form is for use by approved BRE staff, only

Please fill in the following details

Details of person completing form (BRE)

Full name	<input type="text"/>
Organisation	<input type="text"/>
Telephone number	<input type="text"/>
E-mail address	<input type="text"/>
How did you become aware of this incident?	<input style="border-bottom: 1px solid black; height: 20px; width: 100%;" type="text"/> ^ v

Incident contact or Source of information

Who from or where did information come from?

Full name	<input type="text"/>
Organisation (If media, state which and date)	<input type="text"/>
Position	<input type="text"/>
Telephone number	<input type="text"/>
E-mail address	<input type="text"/>
Person's relationship to incident (e.g building owner, fire officer, witness etc)	<input style="border-bottom: 1px solid black; height: 20px; width: 100%;" type="text"/> ^ v

[Back to list](#)



The remaining incident data is input on pages 2 and 3, as shown in the following screen shots:

List of reports

Logout

Photovoltaics and Fire Safety Data Collection Form

[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)

This form is for use by approved BRE staff, only

ID : PVF0035

Save and go to next step

Basic details of incident

Address of incident

Address line 1

Address line 2

Town

County

Postcode

Date of incident (dd/mm/yyyy)

Time of incident (hh:mm)

Please select one of the following ▼

Please select one of the following ▼

Was the local FRS called? ▼

If no, how was the fire dealt with?

Free form notes

© Building Research Establishment Ltd

Page 40 of 60

**Fire and Rescue Service intervention**FRS in attendance (Name of Fire and Rescue Service) FRS Incident No. (if known) **Details of Officer in Charge of incident (either during the incident or lead fire investigator)**Full name Role in relation to the incident **Detailed information on the incident**Type of incident (please select) **Building description (where a building is involved)**Type of building No. of storeys Height of building Type of construction (if known) Type of roof If Other, please specify Age of property Location of PV array Location of inverter Location of isolation switches



Weather at time of incident	
General conditions	<input type="text"/>
Wind speed	<input type="text" value="0.0"/> m/s
Wind direction	<input type="text"/>
Precipitation	<input type="text" value="0.0"/> mm rain
Irradiance (if known)	<input type="text" value="0.0"/> W/m ²

Description of the fire	
Was the property occupied at the time of the fire?	<input type="text" value="Select..."/> ▼
No. of evacuations (if any)	<input type="text"/>
How were the occupants alerted to the fire?	<input type="text"/>
Nature, extent and number of any injuries as a result of the fire?	<input type="text"/> ▲▼
Extent of fire spread/damage	<input type="text"/> ▲▼
Any issues with building performance (e.g. collapse, issues with compartmentation, etc.)	<input type="text"/> ▲▼

[Save and go to next step](#)[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)



[List of reports](#)

[Logout](#)

Photovoltaics and Fire Safety Data Collection Form

[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)

ID : PVF0035

Save and complete

Initial assessment of cause of fire

Provisional or recorded cause of fire

If PV system, please select components thought to be involved:

- DC isolator
- DC cables
- Module
- AC cable
- DC connectors
- Inverter
- Mounting

Evidence to support likely cause

Any other comments on cause



System description

Date system commissioned (dd/mm/yyyy)

System installer

Records of any maintenance (When and type of maintenance)

Is this a BIPV (built-in PV) system

Any comments on DC connectors and cabling (e.g. condition, damage away from fire)

System components	Make	Model
Modules	<input type="text"/>	<input type="text"/>
Mounting	<input type="text"/>	<input type="text"/>
Inverter(s)	<input type="text"/>	<input type="text"/>
DC isolator	<input type="text"/>	<input type="text"/>
Remote DC switches	<input type="text"/>	<input type="text"/>
DC connectors	<input type="text"/>	<input type="text"/>
DC Cable	<input type="text"/>	<input type="text"/>
DC overcurrent protective devices	<input type="text"/>	<input type="text"/>
AC cable	<input type="text"/>	<input type="text"/>
AC protective devices	<input type="text"/>	<input type="text"/>
Surge protection	<input type="text"/>	<input type="text"/>
Other	<input type="text"/>	<input type="text"/>



Fire protection equipment

Type of fire alarm system installed (if any)

Detector fitted specifically for PV system? -1

If yes, please select type of detector installed

Was the detector linked to the main alarm system?

Location of detector for PV system

Any other active fire protection systems installed (e.g. suppression systems)

If yes, please provide details of other fire protection systems

Were any of the following installed (please tick all that apply):

- Remote DC switching device
- Arc fault detection
- Earth fault (insulation fault) alarm

Did any of the systems mentioned in this section operate?

If yes, please specify:

Did the fire protection systems installed operate as expected/designed?

If no, please specify why:

Was there a "Solar PV on roof" label in place near the main consumer unit/distribution board?



Issues for Fire & Rescue Service

Were the crews aware of the presence of the PV system on arrival?

Did crews notice a "Solar PV on roof" label near the main electrical intake?

If yes, did this change tactics for fighting the fire?

If yes, how were the tactics changed?

Did crews take any action(s) to make the PV system safe?

If yes, please specify:

Did the PV system cause any particular hazards for fire crews?

If yes, please specify:

Does your service have a Standard Operating Procedure or use any other guidance for dealing with fires involving PVs?

Did the presence of the PV system exacerbate the fire in any way?

[Save and complete](#)[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)

After this final screen of input data, the user may also attach related documents, e.g. reports, photographs, witness statements, etc.



The screen for attaching documents is shown in the next screen shot with example documents loaded.

Photovoltaics and Fire Safety Data Collection Form

[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)

ID : PVF0056

Evidence - photos and documents

Description	Type of document	Filename		
Photo from site investigation	Image	image1.jpg	edit	delete
Photo from site investigation	Image	image2.JPG	edit	delete
Tech data sheets on components	Technical data	Section-003--Manufacturers-Literature.pdf	edit	delete

[Add document](#)

[Page 1](#) | [Page 2](#) | [Page 3](#) | [Documents](#) | [Back to list](#)

Please note that in some cases not all of the database fields can be populated since the information is not always available. However, the team attempts to gather as much information on each incident as possible.

Appendix B Summary listing of records (anonymised)

Incident Ref	Site visit	Desk study	Lab bench exam	Incident caused attributed to PV system?	Site type	Severity	If PV system, components thought to be involved	Most likely root cause: Product design fault, Designer error, Installer error, Unknown
PVF0001	Y			Y	Commercial	Serious	DC connectors, Module, Mounting	Product fault
PVF0002		Y		Y	Domestic	Localised		Unknown
PVF0003		Y		Y	Other	Localised	DC isolator	Installer error
PVF0004		Y		N	Domestic	Serious		N/A
PVF0005	Y		Y	Y	Domestic	Thermal event	DC isolator	Installer error
PVF0006		Y		Y	Commercial	Thermal event	DC isolator	Unknown
PVF0007		Y		Y	Domestic	Serious	DC isolator	Unknown
PVF0008		Y		Y	Domestic	Serious		Unknown
PVF0009		Y		Y	Commercial	Thermal event	DC isolator Inverter	Unknown
PVF0010		Y		Y	Domestic	Thermal event		Unknown
PVF0011		Y		N	Domestic	Serious		N/A
PVF0012		Y		N	Domestic	Serious		N/A
PVF0013		Y		Y	Commercial	Localised	DC isolator	Unknown
PVF0014		Y		N	Domestic	Serious		N/A
PVF0015		Y		N	Other	Serious		N/A
PVF0016		Y		N	Commercial	Serious		N/A
PVF0017		Y		Unknown	Domestic	Localised		Unknown
PVF0018		Y		Y	Solar farm	Localised		Unknown
PVF0019		Y		Y	Other	Serious		Unknown
PVF0020		Y		Unknown	Solar farm	Localised		Unknown
PVF0021		Y		Y	Domestic	Serious	DC isolator	Unknown
PVF0022		Y		Unknown	Domestic	Serious	Inverter	Unknown
PVF0023		Y		Y	Domestic	Serious		Unknown
PVF0024		Y		Unknown	Commercial	Localised		Unknown
PVF0025		Y		N	Domestic	Serious		N/A



PVF0026		Y		N	Other	Serious			N/A
PVF0027		Y		N	Domestic	Serious			N/A
PVF0028		Y		Y	Other	Localised	DC cables		Unknown
PVF0029	Record deleted								
PVF0030		Y		Y	Solar farm	Localised	Inverter		Unknown
PVF0031		Y		Y	Solar farm	Localised	Inverter		Product fault
PVF0032		Y		Y	Domestic	Serious	Inverter		Unknown
PVF0033		Y		Unknown	Commercial	Localised			Unknown
PVF0034		Y		Unknown	Domestic	Localised			Unknown
PVF0035		Y	Y	Y	Commercial	Thermal event	DC isolator		Installer error
PVF0036		Y		Y	Domestic	Serious	DC isolator		Unknown
PVF0037		Y		Y	Commercial	Localised	DC isolator		System designer error;Installer error
							DC connectors, Mounting		
PVF0038		Y		Y	Other	Serious			Unknown
PVF0039	Y		Y	Y	Commercial	Localised	DC isolator		Installer error
PVF0040		Y		Y	Commercial	Localised			Unknown
PVF0041	Y		Y	Y	Commercial	Localised	DC isolator		Installer error
							DC connectors, DC cables		
PVF0042		Y		Y	Other	Localised			Installer error
PVF0043		Y		Y	Other	Serious			N/A
							DC connectors, Inverter		
PVF0044		Y		Y	Domestic	Serious			Unknown
PVF0045		Y		Y	Other	Localised	DC isolator		Unknown
PVF0046		Y		Y	Domestic	Thermal event	Module		Product fault
PVF0047		Y	Y	Y	Domestic	Thermal event	DC isolator		Product fault;Installer error
PVF0048		Y		Y	Commercial	Thermal event	DC connectors		Installer error
PVF0049		Y		Y	Commercial	Localised	DC isolator		System designer error
PVF0050		Y		Y	Solar farm	Thermal event	DC connectors		Installer error
PVF0051	Y			Y	Domestic	Serious	DC isolator		Unknown
PVF0052	Y			Y	Domestic	Serious	Inverter		Product fault
							DC isolator, DC connectors		
PVF0053	Y		Y	Y	Commercial	Localised			Installer error
PVF0054	Y			Y	Domestic	Serious	DC connectors		Installer error
							DC connectors, DC cables		
PVF0055	Y			Y	Domestic	Serious			Installer error
PVF0056	Y			Y	Commercial	Serious	DC connectors		Installer error
							DC connectors, DC cables		
PVF0057	Y			Y	Domestic	Serious			Unknown
PVF0058	Y		Y	Y	Other	Localised	DC isolator		Installer error
PVF0059		Y		Y	Domestic	Serious	Inverter		Unknown

Appendix C Laboratory examination report - example 1

CASE No: [REDACTED]-BRE Solar Project
BRE Ref: [REDACTED]

Scene Examination Report

1. Synopsis

- 1.1. FIUK Case No. [REDACTED] BRE Solar Project – [REDACTED] – Laboratory Examination.
- 1.2. Address of fire: [REDACTED].
- 1.3. Date and time of incident: 10 February 20[REDACTED] at 10:54.
- 1.4. Date and time investigation commenced: 1 March 20[REDACTED] at 09:00.
- 1.5. Fire Investigator: [REDACTED].
- 1.6. Client: [REDACTED] BRE Solar.
- 1.7. Reason for instruction: To determine the origin and cause of a fire involving a photovoltaic installation. This report should be read in conjunction with the scene examination report.
- 1.8. Equipment description: the equipment subjected to forensic examination consisted of three DC isolators identified as RHB 1, RHB 2 (collected from the premises of the PV system installers and labelled as exhibit [REDACTED]) and LHB 1 (collected from the fire scene and labelled as exhibit [REDACTED]). A third exhibit (collected from the fire scene and labelled as [REDACTED]) consisted of DC isolator remains found on the ground below the original positions of DC isolators RHB 1 and RHB 2.
- 1.9. Summary: This report determines that the damage to the DC isolators examined is consistent with abnormal electrical activity occurring within the DC isolator enclosures generating sufficient heat energy to cause ignition of adjacent materials.
- 1.10. Photographs: Those photographs mentioned in the text of this report are enclosed in this report. Photographs were taken using a Pentax WGIII digital camera.

2. Sequence of events

- 2.1. On the 10 February 2016 at approximately 10:50, a delivery lorry was driving along the road outside the [REDACTED] site, toward the entrance, when the driver noted a fire on the outside wall of the [REDACTED]. The driver alerted members of the public who were outside the entrance to the [REDACTED] to the situation. The members of the public then notified a [REDACTED] staff member.
- 2.2. The staff member attended the scene with Carbon Dioxide and Dry Powder fire extinguishers that were used to extinguish the fire. Other members of [REDACTED] staff also attended the scene and the [REDACTED] Fire and Rescue Service ([REDACTED]) were called.

- 2.3. The [REDACTED] arrived at the scene at 11:16 and as the fire had been extinguished they carried out checks using a thermal imaging camera (TIC), established a cordon around the scene and turned all the isolators to the 'OFF' position. They also sent a message to their mobilising control reporting that the fire was due to "water ingress at the inverter isolation points".
- 2.4. The [REDACTED] staff contacted the installers of the system, [REDACTED], who attended the scene later that afternoon and removed the affected DC isolators, the inverter located above and they also cut and taped a number of DC conductors that had been attached to the affected isolators.
- 2.5. Following a visit to the installers, [REDACTED], and a scene examination at [REDACTED], a number of exhibits (detailed above) were retained for a laboratory forensic examination.

3. Laboratory examination

- 3.1. Exhibit [REDACTED]
- 3.2. This exhibit packaging contained the remains of DC isolators RHB 1 and RHB 2.
- 3.3. The remains of RHB 1 consisted of a small section of a light coloured plastic, identified as the rear of the enclosure, with a mounting screw. This particular exhibit was unremarkable.
- 3.4. An examination was carried out of RHB 2. This DC isolator had been located to the immediate right of RHB 1. The enclosure had sustained fire damage and melting of the plastic to the left hand side and top sections. The pattern of fire damage to RHB 2 was consistent with fire spread from RHB 1 (see Figures 1 & 2).
- 3.5. Exhibit [REDACTED]
- 3.6. This exhibit consisted of debris collected from the ground below the original location of DC isolators RHB 1 and RHB 2 (see Photograph 3). Within this debris, amongst the sections of burnt and melted plastic, were metal screw terminals. It was determined that these had most probably been originally associated with DC isolator RHB 1 as the enclosure of RHB 2 had retained much of its integrity.
- 3.7. The screw terminal remains examined exhibited metallic deposits in the area of the terminal screw. This is indicative of abnormal electrical activity (see Figure 4).
- 3.8. The remains of a further metallic component, possibly a terminal connection, were noted to be heavily oxidised. However consideration must be given to the fact that this item had remained exposed to the elements prior to collection (see Figure 5).
- 3.9. Other items examined from this debris included short lengths of DC conductor. One of the short lengths of conductor displayed evidence of arcing.
- 3.10. Exhibit [REDACTED] /3
- 3.11. This exhibit consisted of the fire damaged DC isolator that was responsible for the third fire event identified during the scene examination.



- 3.12. Once opened the internal surfaces of the enclosure were found severely contaminated with the products of combustion. The internal switching unit was removed for examination (see Figures 6 & 7).
- 3.13. The 'jumper links' were fitted to the top connections of L1 and L2 and of L3 and N. These connections were found tight and relatively undamaged (see Figure 8).
- 3.14. The lower connections were identified as T1 (positive out), T2 (positive in), T3 (negative in) and N (negative out).
- 3.15. The cables from the array feeding the DC isolator had entered from the bottom glands with the feed out exiting from the top to connect to the inverter.
- 3.16. Examination of the damage to the external switching unit revealed the greatest damage, causing melting and burning to the plastic, in the vicinity of T2 and T3, the permanently live conductors (see Figures 9 & 10).


4. Conclusion

- 4.1. Based on the findings of the scene examination carried out at [REDACTED] and the forensic laboratory examination of the exhibits, I am of the opinion that the three fire events, affecting the PV installation, were as a result of water ingress into the enclosure of the DC isolators.
- 4.2. Once the water has entered the enclosure a conductive path was established between the positive and negative conductor terminals causing arcing and generating heat. The heat would have degraded the plastic materials adjacent to the arcing event, which have subsequently ignited.

Report prepared by:

[REDACTED]
Fire Investigations (UK) LLP






bre

BRE
NATIONAL
SOLAR
CENTRE

bre

FIUK
Fire Investigations



Appendix D Laboratory examination report - example 2

CASE [REDACTED]

Bench Top Examination Report

1. Synopsis

- 1.1. Address of fire: [REDACTED].
- 1.2. Date and time of call: [REDACTED] shortly before 09:00.
- 1.3. Date and time investigation commenced: [REDACTED]
- 1.4. Fire Investigator: [REDACTED]
- 1.5. Information from the fire & rescue service: [REDACTED] FRS attended (three appliances). No further details have currently been provided.

2. PV Installation

- 2.1. The array was installed on [REDACTED] [REDACTED] 2011, by [REDACTED] [REDACTED] MCS Installer Certificate Ref: [REDACTED]. The array had a declared capacity of 3.42 kW comprising 18 [REDACTED] 190W [REDACTED] modules and a [REDACTED] Inverter. System details provided with my instructions show that the array was arranged with two strings, each containing nine modules.
- 2.2. Photographs provided with my instructions show that the [REDACTED] Inverter, AC Isolator, two DC Isolators and the Generation Meter were all mounted within a metal electrical cabinet that was attached to the exterior of the property (see Figures 1 and 2). The DC cables were routed on the exterior of the property within protective conduit (this appears to be metal but cannot be confirmed).
- 2.3. Photographs taken of the fire damaged installation show localised fire damage to one of the two DC Isolators, mounted in the bottom left hand corner of the cabinet. Both DC Isolators have been submitted for examination.

3. Key observations

- 3.1. The DC isolators were identified as the [REDACTED] Enclosed DC rated switch disconnecter manufactured by [REDACTED]. The two DC isolators are both rated at 16 Amps and 500 Volts DC (Model [REDACTED]) (see Figures 3 and 4). The switching mechanism is a 4-pole isolator that utilises a contact bridge mechanism. The isolator was originally manufactured for use in AC systems (identified by the terminal labelling designations namely L1, L2, L3 & N), however, it has been rated and certified for use in DC systems by the manufacturer [REDACTED] by pairing the switching contacts.
- 3.2. The array fitted was 18 [REDACTED] 190W modules arranged into two strings. Information with my instructions details that the modules had a rated output of $V_{oc (STC)}$ 45.6 Volts and an $I_{sc (STC)}$ 5.8 Amps.

Therefore, the maximum voltage and current generation can be calculated using the following formulas:

PV String Switch Disconnecter – Current Rating:

String Short-Circuit Current x 1.25

$5.8 \times 1.25 = 7.25 \text{ Amps}$

PV String Switch Disconnecter – Voltage Rating:

String Open-Circuit Voltage x 1.15

$(9 \times 45.6) \times 1.15 = 472 \text{ Volts}$

The [REDACTED] DC Isolator was operating within its design specification (16 Amps and 500 Volts).

- 3.3. The DC isolators had been installed within the electrical cabinet using the intended fixing points which did not compromise the weather proof rating of the switch enclosure.
- 3.4. The four DC cables (4mm² core diameter) were routed through a single M25x1.15 gland, secured to the top of the isolator enclosure (see Figure 5).
- 3.5. Within the enclosure 3-poles from the switch mechanism had been wired in series using two insulated link cables. The isolator had been wired so that 3-poles were used to switch the positive and 1-pole was used to switch the negative (see Figure 6). Both the fire damaged isolator (exhibit [REDACTED]) and the exemplar (exhibit [REDACTED]) were wired identically in terms of terminal configuration and gland position.
- 3.6. The fire damaged isolator enclosure (exhibit [REDACTED]) showed localised damage to the top right-hand corner, affecting the top, right-hand side and rear of the enclosure. The front of the enclosure was mostly undamaged. The four DC cables had been severed by electrical arcing activity within the enclosure. The switch mechanism showed the greatest fire damage to the bottom right-hand corner (highlighted in pink on Image 1).




Image 1: Schematic showing the configuration and terminal designation of the switch mechanism inside the DC Isolator.

- 3.7. The head of the screw terminal L4 showed metallic deposits where it had melted from erroneous electrical arcing activity that had occurred between the L3 link cable and L4 cable (see Figure 7). The terminal clamp from L4 was less damaged and showed that there had been no excess heat generated at the point of connection; there was extensive melting to the L4 terminal switch contact (see Figure 8). The contact bridge from poles three and four had not been recovered or had been destroyed due to electrical arcing activity inside the switch mechanism. There was evidence of further melting and erroneous electrical activity to terminal T4, again the damage was far more extensive to the switching contact rather than the connection between the cable and clamp (see Figure 9).
- 3.8. The second DC isolator (exhibit [REDACTED]) mounted on the right-hand side of the fire damaged isolator, showed minor fire damage to the exterior of the left-hand side of the enclosure. There was evidence of corrosion from water ingress inside the four DC cable terminals, this was most extensive in terminals L4 and T4 (see Figure 10). This may be a consequence of fire-fighting activities rather than weather exposure; it is not possible to exclude that the water ingress resulted from weather exposure, however the weatherproof enclosure and the use of conduit around the DC cables suggest this is less likely.
- 3.9. Inside the switch mechanism of exhibit [REDACTED], there was evidence of heat discolouration to both the fixed switching contacts from each terminal and the movable switching bridge contacts (see Figure 11). There was also evidence of minor scorching to the plastic bridge mechanism (see Figure 12).
- 3.10. There was also evidence of minor pitting to the contact pads on each of the switch terminals, this was consistent with the formation of a switching arc during opening and closing. The switching contact in terminal L2 appeared to show greater damage than the other neighbouring contacts. The non-movable switching terminal L2 appeared to be set slightly higher than terminals L1 and L3 this could cause this pole within the switch mechanism to make and break the full voltage fractionally before the other contacts, this could accelerate the rate of wear within the contact.

4. Conclusion

- 4.1. The fire has originated inside the switching mechanism for this DC isolator, the greatest damage has occurred within the mechanism used to switch the negative. Excessive heat has been generated at the switching contact point. The damage to the terminals is not consistent with the effects of resistive heating having occurred between the terminal connection and the DC cable. Electrical activity within the negative switching pole has likely charred the plastic casing separating the poles within the switching mechanism. Arcing between the negative and neighbouring positive pole has then occurred within the switching mechanism. As the fire has developed further arcing between positive and negative cables outside of the switching mechanism but within the DC enclosure has occurred.
- 4.2. [REDACTED] product data sheet for the [REDACTED] isolator includes a circuit diagram showing the isolator wired in a balanced configuration using two poles to switch the positive and two poles to switch the negative. The actual installation appears to differ from the manufacturer's guidance, this could have a detrimental effect on the switching capabilities of the isolator.



4.3 There was evidence of water ingress inside the exemplar switching mechanism, however it is not possible to confirm if this was present before the fire occurred. The exemplar isolator shows excess heat has been generated around each of the switching contacts this has caused discolouration to the metal terminals, scorched the plastic bridging mechanism and evidence of minor pitting to the switching contacts. This heat discolouration appears to be a consequence of general use given that the [REDACTED] isolator was appropriately rated for this array.

Report prepared by: [REDACTED]
Fire Investigations (UK) LLP

Signature: [REDACTED]



Figure 1



Figure 2



Figure 3



Figure 4



Figure 5



Figure 6

bre

BRE
NATIONAL
SOLAR
CENTRE

bre

FIQ UK
Fire Investigations

