

SYSTEM BRIEF  
DETAIL

Report detailing the testing  
of an HPL rainscreen  
cladding system tested in  
accordance with the  
requirement as described  
in British Standard 8414-1



# Ministry of Housing, Communities & Local Government

# CUSTOMER CLASSIFICATION REPORT



BR 135 (Third Edition) Classification Report

Prepared by:  
The Fire Protection Association  
London Road  
Moreton-in-Marsh  
Gloucestershire  
GL56 0RH

Prepared for:  
Ministry of Housing,  
Communities and Local  
Government  
2 Marsham Street  
London  
SW1P 4DF

Report Date(s): 17<sup>th</sup> July 2019

Report Reference: 101856.002

Version number: 2.0

This report, and the underlying work on which it is based, has been prepared and is submitted in accordance with the contract with the client and is intended solely for use by the client.

FPA warrants that the report has been prepared with all reasonable skill and care. FPA will accept liability for deficiencies in any report caused by its breach of contract or negligence. Negligence shall be as defined as in Section 1(1) of the Unfair Contract Terms Act 1977. Except in the case of death or personal injury arising from the negligence of FPA, liability of FPA for breach of contract or negligence or otherwise in relation to the preparation of the report shall in no case exceed the fee paid by the Client for the report. FPA shall in no circumstances be liable for any other loss, charges, damages, indirect or consequential loss (including loss of profit) or expenses of any kind. The Client acknowledges that all possible circumstances in which the report may have some relevance cannot be foreseen at the time the report is prepared. The Client also acknowledges that FPA would not be able to provide the Report for the agreed fee if FPA were obliged to accept all far-reaching responsibilities.

The scope of any report produced by FPA shall be limited to matters specifically identified in the Proposal or indicated in the report. Except where FPA has otherwise agreed in writing, FPA shall not be liable for any reliance placed on a report by any person other than the Client or for any reliance placed on a report which is not specified in or envisaged by the Proposal. FPA shall not be liable for any loss caused by a report where such loss arises as a result of the provision to FPA of false, misleading or incomplete information by the Client or as a result of the act or omissions of any other person.

Any report shall only be valid and may only be relied upon for the period stated in the report. FPA accepts no responsibility for the accuracy of information contained in the report after the stated period of validity. Where so indicated by FPA any report is to be regarded as expressing the opinion only of FPA and is not to be relied upon as being factually correct.



## Review

Approval	Name	Date
Author	[REDACTED]	16/07/19
Reviewed by	[REDACTED]	16/07/19
Reviewers signature	<b>[REDACTED]</b>	

## Distribution

Name	Company
[REDACTED]	Ministry of Housing, Communities and Local Government

## Document version history

Version	Date	Superseded documents/description/details
1.0	16/07/19	First issue
2.0	17/07/2019	Alteration to product description – Section 4.1

## Disclaimer

This report has been produced by the Fire Protection Association for [REDACTED].

- This report may only be distributed in its entirety, without amendment however the sponsor may redact names of those involved in the production of the report, product trade names and other material that they consider sensitive.
- Results presented relate only to the specimens tested.
- FPA takes no responsibility for the design, materials, workmanship or performance of the product tested.
- The report does not constitute an approval, certification or endorsement of the products tested.
- Any references made to this work must be accompanied by provision of the full, unabridged, report.
- The report does not imply that FPA believe the BS8414 test regime alone is appropriate for the guarantee of end-use system performance.

## Contents

1	Introduction.....	- 5 -
2	Details of the test carried out .....	- 6 -
3	Analysis of fire performance and classification.....	- 7 -
3.1	Test procedure.....	- 7 -
3.2	Thermocouple locations .....	- 8 -
3.3	System performance.....	- 9 -
	System performance is evaluated against the following criteria: .....	- 9 -
4	Test system .....	- 10 -
4.1	Description of test specimen .....	- 10 -
4.2	Installation of specimen .....	- 11 -
5	Test results.....	- 12 -
6	Mechanical performance .....	- 13 -
6.1	Post-test damage report.....	- 13 -
6.2	Post-test photographs.....	- 15 -
7	Classification and restrictions .....	- 22 -
7.1	Classification.....	- 22 -
7.2	Restrictions.....	- 22 -
8	References.....	- 23 -

## 1 Introduction

This report provides a classification of the system detailed below.

Classification is carried out in accordance with the procedures given in BR 135 – ‘Fire performance of external thermal insulation for walls of multi-storey buildings’, Third edition, 2013<sup>a</sup>.

This report should be read in conjunction with BR135 and the associated test evidence recorded in Customer Test Report Number 101856.002.

---

<sup>a</sup> Annex A for BS8414-1 test or Annex B for BS 8414-2 test

## 2 Details of the test carried out

Name of Laboratory:	Fire Protection Association Ltd
Laboratory Address:	London Road Moreton-in-Marsh Gloucestershire GL56 0RH
Test reference:	101856.002
Date of Test:	11/07/2019
Sponsor:	Ministry of Housing Communities and Local Government
Sponsor address:	2 Marsham Street London SW1P 4DF United Kingdom
Method:	Tested in accordance with BS 8414-1-2015+A1-2017
Deviations:	None

## 3 Analysis of fire performance and classification

### 3.1 Test procedure

The performance criteria and classification method are based on the recommendations of BR135 [2], which states that the primary concerns for performance criteria of these systems are the fire spread away from the initial fire source, and the rate of fire spread. The classification only applies to the system as tested.

For classification to be undertaken the system must be tested to the full test-duration requirements of BS 8414-2 [1] without any early termination of the full fire-load exposure period. Early termination shall be conducted if:

- a) Flame spread extends above the test apparatus at any time during the test duration (60 minutes after ignition of the fuel source); or
- b) There is a risk to the safety of personnel or impending damage to equipment.

If fire spreads away from the initial fire source, the rate of fire spread or tendency to collapse should not unduly hinder intervention by the emergency services.

### 3.2 Thermocouple locations

Figure 1 shows the location of thermocouples used in the test.

Fire spread is measured by type K thermocouples set at levels 1 and 2 (Figure 1). The start time for fire spread is initiated when the temperature first recorded by any external thermocouple at level 1 equals or exceeds a 200 °C temperature rise above the start temperature and remains above this value for at least 30 seconds.




Figure 1 - Location of thermocouples – dimensions in mm



### 3.3 System performance

System performance is evaluated against the following criteria:

1. External fire spread: The temperature recorded at any external thermocouple at level 2 should not exceed  $T_s$  by more than 600°C for a period of at least 30 seconds, within 15 minutes of start time  $t_s$ .
2. Internal fire spread: The temperature recorded at any internal thermocouple at level 2 should not exceed  $T_s$  by more than 600°C for a period of at least 30 seconds, within 15 minutes of start time  $t_s$ .
3. Mechanical performance: No failure criteria are set for mechanical performance. However, ongoing system combustion following extinguishing of the ignition source shall be included in the test classification reports, together with details of any system collapse, spalling, delamination, flaming debris or pool fires. The nature of the mechanical performance should be considered as part of the overall risk assessment when specifying the system.

## 4 Test system

### 4.1 Description of test specimen

#### Rainscreen:

10mm High Pressure Laminate [REDACTED] Anthracite

- Manufacturer's stated reaction to fire classification in accordance with BS EN 13501: Euroclass B-s1, d0
- Large flange stainless steel rivets 5x16mm
- 10mm gap between horizontal and vertical joints

#### Insulation:

180mm [REDACTED] Insulation Board

- Manufacturer's stated reaction to fire classification in accordance with BS EN 13501: Euroclass A1
- 70mm stainless steel pressure plates and 230mm SDKBV10x Fasteners, no washer. (6no Fixings to every board)
- Vertical & Horizontal Joints sealed with UL723 FR Grade Aluminium 50mm wide foil tape

#### 'Helping Hand' Brackets & Rainscreen Fixing Metalwork:

[REDACTED] 200mm Brackets

- Single Brackets – 2no SDF-KB-10Vx60E Fixings 32mm Long
- Double Brackets – 2no SDF-KB-10Vx60E Fixings 32mm Long

[REDACTED] T & L Bars

- Single brackets to bars -2no self-drilling stainless steel 4.2mm x 16mm, no washer
- Double brackets to bars – 4no self-drilling stainless steel 4.2mm x 16mm, no washer
- 10mm gap between T & L Bars

#### Cavity Barriers:

[REDACTED] E90 I30 Open State Cavity Barrier

- 2no galv brackets per 1200mm Barrier (300mm from ends and C/L) on verticals
- 3no galv brackets per 1200mm Barrier (200mm from ends and one in the centre) on horizontals
- 2no SDFKB10Vx60E, no washer per galv bracket
- [REDACTED] E90 I30 Solid/Fully Filled Cavity Barrier – 245mm Overall (10mm compression)
- [REDACTED] E90 I30 Open State Horizontal Cavity Barrier - 210mm overall to allow a 25mm air gap (expands an additional 44mm)

## 4.2 Installation of specimen

The specification of the materials of the cladding system were undertaken by the test sponsor. The system design, procurement and installation were undertaken on behalf of the FPA under the guidance of the test sponsor.



Figure 2 – Finished installation on the test wall

## 5 Test results

Table 1 – System performance

Test criteria	Requirement met/not met
System tested to full duration	Requirement met
External fire spread	Requirement met
Internal fire spread	Requirement met
Mechanical performance	See section 6

## 6 Mechanical performance

### 6.1 Post-test damage report

Post-test, the system was inspected to determine the amount of damage to system components. The result are as follows.

#### Rainscreen

- All panels were damaged or partially damaged. See Figure 3, Figure 4 and Figure 5.
- On the main wall the worst damaged area was directly above the combustion chamber. Approximately 50% (by area) of the panels had been consumed or become detached from the system.
- On the return wall the worst damaged areas were adjacent to and directly above the combustion chamber. Approximately 15% by area of the panels had been consumed or become detached from the system.
- On the return wall near the base, the panels had warped, resulting in the outside edge curling in towards the combustion chamber.

#### Insulation

- The insulation had smoke deposits on the front surface, but otherwise it was generally in good condition. See Figure 6.

#### Rainscreen Fixing Metalwork:

- Where the rainscreen had been consumed/fallen away from the system, the majority of exposed aluminium rails were missing. See Figure 3.
- In areas where the rainscreen was still present, the rails remained intact although slightly warped in places.

#### Helping hand brackets

- Where the rainscreen had been consumed/fallen away from the wall, the section of the helping hand brackets that extended out past the front of the insulation were melted or partially melted. Within the insulation the brackets were in generally good condition.
- In areas where the rainscreen were still present, the helping hand brackets were generally in good condition.

#### Horizontal intumescent cavity barriers

- 1<sup>st</sup> cavity barrier (directly above combustion chamber). See Figure 7 and Figure 8.
  - Above the combustion chamber, the barrier was partially detached from the wall and the intumescent strip was not present.
  - On the return wall the intumescent strip had fully activated.
- 2<sup>nd</sup> cavity barrier. See Figure 9 and Figure 10.
  - The barrier was intact.
  - On the section between the vertical cavity barriers, directly above the combustion chamber, the intumescent strip was not present.
  - Outside this area on the main wall and on the return wall the intumescent strips had fully activated.
- 3<sup>rd</sup> cavity barrier. See Figure 11 and Figure 12.
  - The barrier was intact.
  - On the section between the vertical cavity barriers, directly above the combustion chamber, the intumescent strip had fully activated.

- Outside this area on the main wall and on the return wall the intumescent strips had partially activated.
- 4<sup>th</sup> barrier (near top of wall). See Figure 13 and Figure 14.
  - The barrier was intact.
  - On the section between the vertical cavity barriers, directly above the combustion chamber, the intumescent strip had partially activated.
  - Outside this area on the main wall and on the return wall the intumescent strips had partially activated.

Vertical compression cavity barriers

- The 3 vertical barriers appeared to be in good condition. See Figure 6.

## 6.2 Post-test photographs



Figure 3 – Front face of system post test



Figure 4 – Area directly above combustion chamber post test



Figure 5 – Return wall above combustion chamber post test





Figure 6 – Insulation board and cavity barriers following removal of the rainscreen and support rails



Figure 7 – 1<sup>st</sup> cavity barrier (directly above burn chamber) from main wall following removal of the rainscreen




Figure 8 – 1<sup>st</sup> cavity barrier (directly above burn chamber) from return wall following removal of the rainscreen



Figure 9 – 2<sup>nd</sup> cavity barrier from main wall following removal of the rainscreen




Figure 10 – 2<sup>nd</sup> cavity barrier from return wall following removal of the rainscreen



Figure 11 – 3<sup>rd</sup> cavity barrier from main wall following removal of the rainscreen



Figure 12 – 3<sup>rd</sup> cavity barrier from return wall following removal of the rainscreen



Figure 13 – 4<sup>th</sup> cavity barrier (top) from main wall following removal of the rainscreen




Figure 14 – 4<sup>th</sup> cavity barrier (top) from return wall following removal of the rainscreen

## 7 Classification and restrictions

### 7.1 Classification

The system described in this report has been tested and met the performance criteria set in BR 135:2013<sup>b</sup>.

### 7.2 Restrictions

Following the at Grenfell Tower in 2017, testing, classification, regulation and recommendations surrounding the testing and use of cladding materials on high rise buildings are all being examined in the UK. As a result, the relevance of a successful BR135 classification report may expire.

It is therefore recommended that the current regulatory climate should be assessed before a successful BR135 classification report is relied upon as evidence of suitability.

The FPA test laboratory that issued the report will be able to offer assistance in this regard.

This classification is valid only for the system described herein, installed and detailed.

This classification report does not provide type approval for similar systems or for any individual component parts that were used within the system tested.

---

<sup>b</sup> Annex A for BS8414-1 test or Annex B for BS 8414-2 test

## 8 References

- [1] British Standards Institute, "BS 8414-2:2015+A1:2017, Fire performance of external cladding systems - Part 2: Test method for non-loadbearing external cladding systems fixed to supported by a structural steel frame," British Standards Institute, London, 2017.
- [2] S. Colewell and T. Baker, "BR135 Fire performance of external thermal insulation for walls of multistorey buildings, Third Edition," IHS BRE Press, Watford, 2013.