Fishing 2003 Safety Digest

Contents

Marine Accident Investigation Branch	4
CHIEF INSPECTORS FOREWORD	6
CASE 1 Near Misses Involving Fishing Vessels	7
Narrative 1	7
Narrative 2	7
The Lessons	7
CASE 2 Fatality on Board Fishing Vessel	9
Narrative	9
The Lessons	9
Footnote	10
CASE 3 For Appearances Sake	11
Narrative	11
The Lessons	12
Footnote	12
CASE 4 Take Your Lifejacket and Phone with you	13
Narrative	13
The Lessons	13
CASE 5 Poor Watchkeeping on Fishing Vessel	14
Narrative	14
The Lessons	14
CASE 6 Tiredness Can Kill	16
Narrative	16
The Lessons	16
Footnote	17
CASE 7 Grounding of a Fishing Vessel	18
Narrative	18
The Lessons	18
Footnote	19
CASE 8 Collision in the Dover Strait	20
Narrative	20

CASE 9 EPIRB Saves Two Lives	
Narrative	
The Lessons	
Footnote	
CASE 10 The Thinking Man!	
Narrative 1	
Narrative 2	
Narrative 3 The Lessons	
CASE 11 I Will if you Wont!	
Narrative	
The Lessons	
CASE 12 He Who Hesitates	
Narrative	
The Lessons	
Footnote	
CASE 13 Ideas for Tackling Flooding	
Narrative	
The Lessons	31
Footnote	32
CASE 14 Engine Room Flooding causes Another Fishing Vessel Loss	33
Narrative	33
The Lessons	33
Footnote	34
CASE 15 Fisherman Saved by Lifejacket	35
Narrative	35
The Lessons	35
CASE 16 See No Vessel, Hear No Vessel!	36
Narrative	36
The Lessons	36
CASE 17 Things that go Bump in the Night	37

Narrative	37
The Lessons	37
CASE 18 A Wooden Vessel Floods and then Sinks	39
Narrative	39
The Lessons	39
CASE 19 Look After Your Tonnage Valves	40
Narrative	40
The Lessons	40
CASE 20 Skippers Last-Minute Action Saves Lives	41
Narrative	41
The Lessons	41
CASE 21 No Redundancy!	42
Narrative	42
The Lessons	42
CASE 22 Collision Between Fishing Vessel and aGeneral Cargo Ship	43
Narrative	43
The Lessons	43
CASE 23 Fishing Vessel Capsizes with Loss of Life	44
Narrative	44
The Lessons	44
Statistics	46
Fishing Vessel Accident Statistics 1990 2002	46
CHART	48
Major Accident Locations	48
PUBLISHED REPORTS	49
List of fishing vessel accident reports published since 1999	49
SAFETY DIGEST	52
GLOSSARY of abbreviations	53
MAIB Safety Digest/Report Request Form	54
MAIB PUBLISHED REPORTS - free of charge	54

Marine Accident Investigation Branch

The Marine Accident Investigation Branch(MAIB) is an independent part of the Department for Transport, (DfT) and is completely separate from the Maritimeand Coastguard Agency (MCA). The ChiefInspector of Marine Accidents is responsible to the Secretary of State for Transport. The offices of the Branch are located at Carlton House, Carlton Place, Southampton, SO15 2DZ.

This *Safety Digest* draws the attention of the marine community to some of thelessons arising from investigations into ecent accidents. It contains facts which have been determined up to the time of issue.

This information is published to inform the fishing industry, and the public of the general circumstances of marineaccidents and to draw out the lessons to belearned. The sole purpose of the *SafetyDigest* is to prevent similar accidentshappening again. The content mustnecessarily be regarded as tentative and subject to alteration or correction if additional evidence becomes available. The articles do not assign fault or blame nor dothey determine liability. The lessons often extend beyond the events of the incidents themselves to ensure the maximum valuecan be achieved.

Extracts can be published without specific permission providing the source is dulyacknowledged.

The *Safety Digest* is only available from the Department for Transport, and can be obtained by applying to the MAIB. Other publications are available from the MAIB.

If you wish to report an accident orincident please call our 24 hourreporting line 023 8023 2527.

The telephone number for general use is 023 8039 5500.

The Branch fax number is 023 8023 2459. The e-mail address is maib@dft.gsi.gov.uk

Safety Digests are available on the Internet: www.maib.gov.uk

Extract from

The Merchant Shipping

(Accident Reporting and Investigation)

Regulations 1999

The fundamental purpose of investigating an accident under theseRegulations is to determine its circumstances and the cause with the aim of improving the safety of life at sea and the avoidance of accidents in the future. It is not the purpose to apportion liability, nor, except so far as isnecessary to achieve the fundamental purpose, to apportion blame.



CHIEF INSPECTORS FOREWORD

This digest has one simple aim: to sharewith everyone in the fishing worldsome of the key lessons that we havelearned recently from the tragicaccidents we have investigated.

Sadly, the number of accidents, anddeaths, shows no sign of reducing. In the first 2 months of this year alone, 6British fishing vessels have been lost atsea, and 4 British fishermen have died. I believe it is essential that we continue to find out why these accidents are happening, and pass the lessons on to everyone involved in the industry. Awareness of the dangers we identify may just help save other fishermen's lives.

The role of the MAIB is to get right to the bottom of what happened, not just to look at the superficial "obvious" causes. Our role is not to look at blame, fault or liability, and we most certainly do not pass on any information we have been given to the police or any other prosecution/enforcement organisations.

I have only recently taken over as thehead of the Marine AccidentInvestigation Branch (MAIB). I havespent most of the last 34 years at sea, but recognise that I have littleexperience of fishing, and so amwoefully ignorant of the pressures under which you all work. I plan tomeet as large a cross section of youas I possibly can over the next yearor so, to try to get someunderstanding of your work and its very real difficulties. My wish is for the MAIB to work with the fishing industry to find sensible and affordable ways to reduce the current rate of accidents.

I hope that you find the digestinteresting; we do try to write thearticles in a readable style. We do not now identify the names of the vesselsinvolved, which I hope will makepeople less concerned aboutreporting incidents to us. Please takea moment to think about these cases- it might just save your life.

Stephen Meyer

Chief Inspector of Marine Accidents

Near Misses Involving Fishing Vessels

Narrative 1

Having landed her catch, a fishing vesselwas returning to the fishing grounds. It wasdark, visibility was good, the sea moderate, and the wind south-south-west force 5. Onleaving harbour, she was steering 135° at aspeed of 7 knots and displaying sidelights, stern light and a masthead light.

When still within 2 miles of her port ofdeparture, the skipper detected a radarcontact 2 miles on his port bow, and shortlyafterwards sighted masthead and starboardsidelights along the same bearing. Heestimated this vessel, a general cargo ship, was on a southerly course at about 8.5knots, and that a risk of collision existed.

By the time the two vessels closed to within 1 mile, the cargo vessel had failed to take any action as the give-way vessel. This prompted the skipper to call her on VHFradio, channel 16. Unable to get a response, he altered to starboard and eventually tookall way off to prevent a collision. Radiocontact was finally established when thevessels were very close and the merchantvessels OOW felt it was too late for him to alter course or stop. The OOW, who was alone on the bridge, had been working a 6hour watch routine, and did not detect the fishing vessel by radar, or see her visually, until she was at close range.

Narrative 2

A stern trawler was south of Plymouth,towing her gear on a course of 180° atabout 3 knots. She was displaying anappropriate shape to indicate that she wasfishing. It was a clear sunny day, visibilitywas good and the sea was slight. There was little wind. A tanker was sighted about 6miles on the port beam, on a westerlycourse and making good about 13 knots. She was on a steady bearing.

As the tanker closed, the trawlers skipperbecame increasingly concerned and, whenthe range had closed to about 1 mile, triedcalling her on VHF channel 16. There wasno reply, and the skipper was forced to to maximum speed to pass aheadof the tanker, leaving it very close astern. Her OOW, who was alone on the bridge atthe time, did not recollect being in a closequarterssituation, or hearing any calls on VHF radio.

The Lessons

These two instances are representative ofmany situations which will be familiar toanyone with extensive experience ofwatchkeeping. You find yourself the stand-onvessel, and detect another vessel on your portbow or beam closing on a steady bearing. Thequestions you find yourself asking are has heseen me? and is he going to give way? Toooften we find the answer to the first questionis No because a proper lookout is not beingkept and No to the second because he isunaware of your presence.

1. Keeping a good lookout and complying with the Rules of the Road are not justgood seamanship requirements, but arealso imperative to preventing very serious accidents. Had both fishing vessel skippers not maintained a proper lookout, ormanoeuvred to prevent a collision, the MAIB would probably be investigating two serious accidents rather than near misses.

- 2. There are no new lessons aboutmaintaining a proper and effectivelookout. The requirements are well known. Watchkeepers must be alert, look out ofthe windows, use binoculars, monitor theradar on an appropriate range scale, and listen for sound signals and to the VHFradio. The factors which prevent keeping agood lookout will vary from vessel tovessel, but three reasons seem to featureover and over again. Too oftenwatchkeepers use the opportunity of ascemingly quiet period to do somethingother than keep an efficient watch. It could be anything from progressing paperwork to reading a magazine. The second reason is being distracted by something such as monitoring GMDSS, making a lengthy telephone call, or spending an unusually long time at the chart table. And the third is the tendency for either a tired or very boredwatchkeeper to fall as leep. If you are guilty of succumbing to any of these, you could be endangering peoples lives.
- 3. If you feel you are under pressure to dosomething that will prevent you keepingan efficient lookout, or you are too tiredto do it properly, tell someone. The MAIBreceives a number of reports from peoplein such a predicament, and each one istreated in total confidence. It provides the Branch with the ammunition to dosomething about it.
- 4. When the OOW is busy, a dedicated visuallookout is an invaluable safety net. Whenall is quiet, he is a second pair of eyes and ears, and helps to keep a tired OOW alert. You are required to have a dedicatedlookout at night.
- 5. VHF radio is convenient, but it relies on thewatchkeeper in the other vesselmonitoring the appropriate channel, understanding what is being said, and bothering to reply. Not surprisingly, manycalls go unanswered. But there are realdangers to using VHF when the identity of the other vessel is unknown. There are anumber of recorded incidents when either the misidentification of the other ship, ora lack of understanding, has contributed to the subsequent collision or incident.
- 6. If the situation allows, and you need tomake your presence known to the othervessel use the wake up signal by whistleor horn, and by flashing light. The signal isrequired by the Rules of the Road and, although an inattentive OOW may not seeor hear it, somebody else on board theother vessel might. Dont be shy; its inyour interest to be seen.
- 7. Navigation lights are no different to carheadlights. They accumulate grime and salt in time. An occasional wipe doeswonders to improve their effectiveness.

Fatality on Board Fishing Vessel

Narrative

After a weeks break, a beam scalloper, sailed from an east coast Scottish port in the early hours of the morning to return to the fishing grounds. Later that day, and while shooting her gear for the fourthtime, one of the deckhands moved from aposition of safety and was struck on the head by a towing bar. The sea conditions were rough, and the bar swung in board because of the vessels movement. It willnever be known why the deckhand made the move, but the blow killed him.

The deceased was an experienced fisherman, but had never sailed on this vessel before. He had only been onboard for 14 hours when he died.

Safety hats were available, but nobody onboard wore them.

The Lessons

This tragic accident will provoke a number of reactions among fishermen. Everyonewill have the deepest possible sympathy for the family of the deceased. Many will, rightly, want to know what happened and whether anything could have been done to prevent it. Others will say it was one of those things which happen from time to time in this most hazardous of occupations. The reality is that similar accidents have occurred in the past and are likely to happen again unless measures are taken to prevent them.

Much can be done once peopleunderstand that accidents are rarelycaused by a single event. It isnt just badweather, a particularly high wave, anunfortunate swing of the towing bar, orthat the victim was new to the vessel. Accidents happen through a combination of things, and it is important to learn from the lessons of this and similar accidents in the past.

- 1. No two vessels are the same. Variations in equipment, procedures, the way askipper likes things to be done or eventhe vessels motion in a seaway, willdiffer. When joining a vessel for the first time, nothing should be taken forgranted. Make sure you are aware of the various hazards and safetyprecautions in force. Pay particular attention to anything that swings from a loft such as towing bars and blocks, and make a mental note of how they can be avoided at all times. It is unlikely things will be identical to your last vessel and you must not he sitate to ask questions if you are unsure of any procedures. Doing this does not question your ability or experience; its imply highlights your commonsense.
- 2. Every year a number of fishermen areeither seriously injured, or killed, bybeing hit on the head. Someone, sooneror later, wants to know whether theconsequences could have beenprevented had the victim been wearinga safety helmet. The answer is no oneknows, but even if wearing one couldhave prevented it, most people wouldbe very reluctant to try it for a number of reasons. They are uncomfortable, getin the way, restrict vision, allow waterto drip down the back of the neck andnobody else wears one. So otherworkers have said in the past. But now, wearing safety helmets has becomesecond nature to those working onmerchant ships or in the offshore sector. It is now so much in the culture that tonot wear one feels uncomfortable. The fact remains they provide very goodprotection, reduce injury and save life. Wear a safety helmet.

- 3. When hauling or shooting, or conducting any operation on deck, keepan eye on your colleagues and do nothesitate to raise the alarm or stop aprocedure if you see somethingdangerous developing. Safety is theresponsibility of everyone on board.
- 4. When accidents happen at sea, expertmedical assistance can often be faraway, and the well-being of a casualtyis in the hands of others on board. In this case, although the injuries were severe and the efforts of the first-aidtrainedcrew were sadly unsuccessful, the need for fishermen to complete themandatory first-aid course was onceagain highlighted.

Footnote

In the past five years the MAIB hasreceived a number of reports from certainsectors of the fishing industry stating thatthe wearing of safety helmets is on theincrease. In nearly every instance, thecatalyst for change was the death of afriend and colleague through a headinjury incurred at sea. The sadness is thatit takes such an event to make peoplechange the habits of a lifetime. A farhappier solution is to do something about the before you become the victim.

This incident was the subject of a fullMAIB investigation. A comprehensive report, giving details of the causes, ananalysis, and recommendations was published in August 2001.

For Appearances Sake

Narrative

Following a 12 hour search for fish, alarge, 92.04m stern trawler, with a crewof 34 was preparing to shoot her nets in the English Channel, about 17 milessouth of the Isle of Wight.

Four of her deck crew went aft to shootthe nets under the control of the fishingskipper who was in the wheelhouse. Hewas positioned at the winch controlsoverlooking the aft working deck. Shooting began. Two of the crewattached the head line transponder andthen moved to two small pound areas atthe stern from where they were to attachtowing wires to the nets wings.

The man on the port side attached hiswire, but then noticed his colleague wasnot where he had expected to see him, inthe starboard pound. Thinking he hadgone to the toilet, he moved across tostarboard to attach the towing wire. Atalmost the same time the fishing skipperalso noticed the man was missing. Hewent aft to investigate.

When they failed to find the missingcrewman they realised he must have goneoverboard. It was dark and the wind wasforce 4 to 5.

A Pan Pan message was broadcast, andthe Solent coastguard initiated a searchand rescue operation. The vessel recoveredher nets and joined the search. Ahelicopter, a lifeboat and several merchantand fishing vessels also took part. Thecrewman was not found, but his selfinflatinglifejacket was recovered. This wasfound inflated with its light illuminated and the buckle on its harness fastened.

Nobody saw him go over the side, but the circumstances suggest he was standing in the starboard pound to connect the towing wire to the net. A feature of the pound is its proximity to the stern roller, which rotates as the nets are paid out. It is impossible to say what happened, but the possibility exists that he was somehow taken overboard by the rotating roller.

The crewman had been wearing ordinaryclothing: a hard hat and the inflatablelifejacket. Only the lifejacket was foundand recovered. Once again, it is impossible reconstruct exactly what happened, but a properly secured lifejacket should nothave become detached. The evidence suggests it was not being worn correctly, and it is likely the victim slipped thelifejacket over his head without passing the harness around his waist. When heentered the water the lifejacket slippedoff. The particularly sad feature was therelative ease with which the lifejacket was subsequently seen, but nothing was found of the man.



The Lessons

- 1. The aft boundary of the two sternpounds is the stern roller. Because this is able to rotate freely it cannot servethe same purpose as a guardrail orbulwark. Without a barrier betweenthe pound and the roller, crew can easily come into contact with the roller. If it is turning, it might then dragthem overboard. Stern rollers should beviewed in the same way as any rotating machinery. They are dangerous andmust be guarded if personnel are likely to be very close by.
- 2. The crew generally recognised theimportance of wearing a lifejacketwhile working on deck. The victim,however, apparently failed to don hisproperly, and did no more than slip itover his head. Perhaps he thought itwas unnecessary as he was onlyexpecting to be on deck for a fewminutes. To the casual onlooker itwould appear as if he was wearing one.
- 3. The value of a lifejacket is entirely dependent on it being worn properly and secured correctly. A snug fitting model is both comfortable and a life saver.

Accidents are no respecter of time. Dangers exist no matter how brief thestay on deck.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensive report, giving details of the causes, ananalysis, and recommendations was published in August 2001

•

Take Your Lifejacket and Phone with you

Narrative

A 5.8m Orkney fast liner open fishingvessel, which was powered by a 37.2kW(50HP) outboard, was being operated single handedly. The skipper was haulingcrab pots, and had twelve on board whenthe line tightened on the hauler. A pot orline had snagged on the rocky bottom in adepth of 46 metres. A northerly force 3wind was blowing, and the sea was slightwith a chop and a southerly ebbing tide.

The normal practice in such situations wasto throw the recovered pots backoverboard, and then start the recoveryfrom the opposite end of the string. Theskipper began this process, but havingpayed out 2 fathoms of rope, found it hadcaught in the outboards propeller. Moments later, the rope came bar tightand the engine cut out. The skipper triedto raise the outboard, but the load on therope prevented this.

The boat was, in effect, anchored. It was also lying with the stern so low that waterhad started to come inboard over the transom. The skipper attempted to lighten the boat by ditching some of the embarked pots, but this made little difference. He thought of diving down tocut the rope, but with the tide running, thought better of it and chose instead to contact the coastguard on VHF via a local vessel.

Meanwhile, water continued to be shippedover the stern. The skipper was wearing alifejacket and, once in the water, began torecall the advice he had received insurvival training. It served him well. About 10 minutes later he was recovered by another fishing vessel.

The Lessons

This incident could have turned out sovery differently. The skipper owes his lifeto following the advice so frequently putout by the MAIB:

- 1. Wear a lifejacket at all times.
- 2. Let people know if you are in troublebefore it is too late.
- 3. Dont make matters worse by diving in,cutting the rope and then, perhaps,watching your craft drift gently awaybefore you can re-board it.
- 4. Carry a VHF radio and make sure itworks. If battery-operated, ensure the batteries are fully charged, or are connected to a suitable power sourcesuch as the boats batteries.

When looking back on his experiences afterwards, the skipper discussed the advantages of carrying a liferaft for use insuch emergencies. As with many similar craft, there was very little room onboard as the pots took up most of the available space.

There is no doubt that when the chips aredown, and there is every prospect of yourvessel foundering, the existence of aliferaft could well make the difference between life and death. Skippers of smallcraft must make the choice. Take upcommercially useful space or give yourselfa good chance of survival. Friends, family and next-of-kin may haveuncompromising views about which choice to make. Ask them.

Poor Watchkeeping on Fishing Vessel

Narrative

A fishing vessel was on passage betweenfishing grounds and in the vicinity of theMallory gas field. Three crew were onboard. Two of the crew were carrying outvarious tasks including cooking breakfast, cutting up bait, pumping out the bilges and cleaning pump filters. They were also responsible for maintaining the watch and keeping a lookout. The third crew member, the skipper, was as leep on the deck of thew heelhouse. The vessel's planned trackpassed 0.35 miles from a rig, and the radaralarm was set on 13 of a mile. The vessel's VHF was turned off, as, in the skipper's opinion, there was too much unnecessary and distracting radio traffic.

The stand-by safety vessel on station in thearea, received a message from her sistervessel saying that she had been plottingthe track of the fishing vessel since 0600, and she had been seen to pass close to theSanta FE Monarch rig. Despite the sistervessel putting her FRC alongside the fishingvessel, nobody could be seen on the bridgeor on deck. On receipt of the message, thestand-by safety vessel also launched herFRC and intercepted the fishing vessel. Thestand-by safety vessel and her FRCparalleled the course of the fishing vesseland, despite both sounding their horns, they failed to attract any attention. Therewas no sign of life on board.

The track of the fishing vessel wasestimated to be taking her to within 0.5mile of the Mallory platform. Both theplatform and the coastguard wereinformed, and the decision was taken to tryto board the fishing vessel. The Malloryplatform went to abandon platformstations as a precautionary measure. At 0800 the stand-by safety vessels FRC wentalongside the fishing vessel, which was stillmaking way at the time, and one crewmember transferred. He went to thewheelhouse and found the skipper asleep ina sleeping bag.

The skipper was awakened and told to slowdown and steer way from the platform. Hedid so. He then protested about beingawakened, and claimed the situation wasunder control. He said he generally slept inthe wheelhouse in order to be instantly available if needed, and had two crew onwatch. Furthermore, the vessel was justarriving at her next intended fishing ground, and at no time had a 500 mexclusion zone around a rig been breached. He felt that the stand-by vessel had overreacted to the situation.

The Lessons

Readers can draw their own conclusions asto whether the stand-by vessel had overreacted this occasion, and whether thewatchkeeping arrangements in this fishing vessel were satisfactory.

- 1. Skippers should need no reminding thatthey have a paramount responsibility to ensure a proper lookout ismaintained at all times. There is nothing fundamentally wrong with askipper sleeping in the wheelhouse, provided somebody else is on watchand maintaining the lookout when heis doing so. Watchkeepers employed elsewhere on deck or below, are rarely in a position to keep a good lookout orto listen out on VHF. In some small craftit might be possible.
- 2. The Maritime and Coastguard Agency(MCA) has published MGN 84 (F)Keeping a Safe Navigational Watch on Fishing Vessels in which owners, operators, skippers and crews of fishingvessels are, among other things, reminded that:

A competent alert watchkeeper,keeping a proper all round lookout atall times is absolutely essential.

The wheelhouse must not be leftunattended at any time.

The lookout must give full attention tokeeping a proper lookout and no otherduties should be undertaken whichcould interfere with that task.

It goes without saying that thewatchkeeper cannot keep the required continuous all-round lookout at thesame time as cooking breakfast or cutting up bait.

- 3. Fishing vessels can legitimately work inthe vicinity of rigs but if they choose todo so, they should ensure they keep aconstant listening watch on Channel16 VHF. When operating in the vicinity of a gas field, VHF traffic does not fallinto the category of unnecessary.
- 4. Stand-by safety vessels carry outimportant guardship duties. If contactcannot be established with a vesselwhich is deemed to pose a potentialthreat, more direct action may benecessary to ensure the safety of allconcerned. In such circumstances, astand-by safety vessel cannot waituntil a vessel breaches the 500m zonebefore taking action.

CASE 6 Tiredness Can Kill

Narrative

After 3 days fishing off the west coast of the Shetland Islands, a fishing vessel was returning to Scalloway to land her catch. The skipper, who had only managed abouthours sleep during the time on the fishing grounds, was alone and seated in the wheelhouse. From his chair he could see and reach all key equipment, including the watch alarm, which was set at a 10-minute interval. The vessel was inautopilot and the skipper was navigating by eye. The two remaining crew weredown below; the engineer was having acoffee in the mess room, and the deckhand was in bed.

As she passed to the north of the Cheynies, at the entrance to the Middle Channel, the skipper adjusted the vesselscourse a few degrees to starboard andreset the watch alarm. He then fell asleep. Less than 5 minutes later, the vessel washard aground.

The Lessons

1. Although tiredness can kill is a wellusedcliché, its as true as it ever was. Fishing is hard work but, on thisoccasion, the combination of fishingclose inshore for 3 days, with severaltows as short as 2.5 hours, and with acrew of only three, took its toll on theskipper. Fortunately there were noinjuries, and damage was onlysuperficial.

There are no hard and fast rulesdictating how many crew a fishingvessel should carry to operate safely. Itboils down to experience: what thevessel is doing and how long it willtake, her size, the equipment fitted, and finally but, most important of all, commonsense.

2. Every wheelhouse watchkeeper hasprobably felt tired while on watch. Many, including some of the best, haveprobably fallen asleep. Fortunately, most of these have been lucky andhave got away with it. What makessomeone fall asleep is difficult to say.

Sometimes tired people want to sleepbut cant; yet at other times, peoplewho dont think they are tired doze offat the drop of a hat. Two things,however, are certain. A watchkeeperwho is alone, sitting down, and doingnothing is more likely to fall asleep thanone who is walking around thewheelhouse, getting fresh air, and using all the navigational aids available tohim. The second is that if you are very, very tired and sitting down withnothing to stimulate you, there is nothing whatsoever you can do to stopfalling asleep. It takes less than 10 seconds to do so.

- 3. With many watch alarms positionedwithin easy reach of the wheelhousechair, it would not be surprising to discover that some wheelhousewatchkeepers can literally reset a watchalarm in their sleep. Enough said. And having reset it there is nothing to prevent that person falling as leep allover again.
- 4. The effectiveness of a watch alarm towake a watchkeeper in time to preventan accident depends on the timeinterval set. The longer the interval, thelonger the opportunity for somethingto go wrong. After this grounding, awatch alarm with a 3-minute intervalwas installed. Had this alarm beenfitted before the grounding, the vesselmight have been able to land her fish asplanned. What is the interval on yourwatch alarm?
- 5. Having a second person in thewheelhouse not only provides a secondpair of eyes, but it also gives a tiredwatchkeeper somebody to chat to. Thismight prevent him from falling asleep.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensivereport, giving details of the causes, ananalysis, and recommendations waspublished in February 2002.

Grounding of a Fishing Vessel

Narrative

A fishing vessel was heading towardsCullivoe in the Shetland Islands to landher catch when she ran aground in theapproaches to the northern entrance toBluemull Sound in the early hours of themorning.

Her skipper, who had not slept for about23 hours and had recently held a mobiletelephone conversation with a friend, attempted to alter course while in the Sound. Using the joystick control, hefailed to use the correct procedure for changing from automatic to manual steering, and did not realise the vesselwas not turning as intended until immediately before the vessel grounded. By the time he did realise there was aproblem it was too late for him to do anything about it. When the tide fell, the fishing vessel was embarrassingly highand dry. She was refloated the following day. There was no pollution, and damage to the vessel was minor.



The Lessons

- 1. Everybody makes mistakes, but we aremore likely to do so when weve nothad enough sleep. Tiredness makes itdifficult to concentrate, and our abilityto remain alert to what is happeningaround us is much reduced. Simpleerrors occur that would be unthinkablein normal circumstances. Drowsiness isthe obvious symptom of fatigue. Otherindicators which affect concentration, awareness and alertness are harder toidentify, but are just as dangerous. Dont assume that just because acompetent watchkeeper is awake thathe can do the job. You only have tothink what it is like to do a simple taskat home at the end of a long day toknow how difficult it can be. It is nodifferent at sea even if you think youcan do it. People who go without sleepfor more than about 18 hours are lessable to perform routine tasks than hadthey exceeded the drink drive limit.
- 2. A second person in the wheelhousewhen in confined waters or enteringharbour, when you have been up forover about 18 hours, will do much toprevent mistakes having unfortunateconsequences. Many accidents occurbetween the hours of 0100 and 0600. This one took place at about 0330.
- 3. Problems or faults with the steering, particularly when changing from autosteering to hand steering need not bedisastrous provided they are discovered in time. An instinctive glance at therudder angle indicator each time youapply wheel, will give you early warning of a problem. If you find the rudder isnot responding, and you are trying toalter course, the time available to doanything about it is often very limited. Taking the way off is a possibility. It isfar better, however, to reduce thechances of anything going wrong byselecting and testing manual steering before you need it.
- 4. Mobile telephones have proved to bevery beneficial at sea, and are widely used for both commercial and privatereasons. As when driving a car, their useat certain times can be a

majordistraction. Many will argue that transiting confined waters when tiredat 0330 constitutes a certain time.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensive report, giving details of the causes, ananalysis, and recommendations was published in March 2002.

CASE 8 Collision in the Dover Strait

Narrative

At 0413 UTC, CNIS Dover detected a radarcontact crossing the south-west lane of the Dover Strait TSS on a heading of 010°. As the axis of the lane was 230°/050°, shewas not crossing at right angles as required By Rule 10c of the Collision Regulations. Consequently, a preliminary broadcast wasmade on VHF channel 16, followed by afurther broadcast on VHF channel 11 at 0416, warning all vessels of the contravening vessels position.

The vessel was later identified as a Frenchstern trawler which was on passage from aFrench port to the fishing grounds in the vicinity of the South Falls Bank. A 17-year-olddeckhand was alone in the wheelhouse, and had been instructed to follow the planned track of 010° across the DoverStrait at a speed of 11 knots. The vessel wasin autopilot and the watch alarm was setto a 10 minute interval. Both the skipperand the deckhand were aware that the intended track contravened Rule 10c of the Collision Regulations, but the skipperwas keen to get to the fishing groundsbefore his rivals.

CNIS Dover had previously reported this vessel five times since 1998 to the Frenchadministration for contravening Rule 10 of the Collision Regulations.

Shortly after crossing into the south-westtraffic lane, the fishing vessel deckhandsaw a radar contact about 3 miles on the starboard bow. He initially saw a vesselsport and starboard side lights, but soonafter, his vessel crossed ahead of this otherone, and only her starboard sidelightremained visible. Based on this information, and by monitoring two smallradar displays, the deckhand assessed that the vessel would pass no closer than 1 mileto starboard. He was then either distracted, or fell asleep, and paid no further attention to the situation until he saw a large ship at very close range ahead.

The ship, a product tanker on passage to West Africa, was following the south-westlane of the Dover Strait TSS at a speed of about 11 knots with three other vessels close astern. Between 0413 and 0423 UTC, the OOW fixed the ships position and annotated the deck log. Although the bridge VHF radios were set to channels 11 and 16, he did not hear the broadcastsmade by CNIS. The OOW was accompanied by a lookout, who remained at the helm formuch of this period.

After finishing his work at the chart table, the OOW checked the radar display and sawa contact 2 miles on the port bow with aCPA of 1 cable to port. He visually identified the contact as a fishing vessel, and continued to monitor it for several minutesuntil it became apparent that the vessel wason a steady bearing and was not taking anyaction to avoid a collision. At this point, the OOW applied 10° of starboard helm and sounded 5 short blasts on the ships whistle. On hearing the sound signal the master, who had been working in his cabin, came to the bridge and saw the fishing vessel about 1 cable on the port bow. He immediately ordered the helm to be increased and repeated the 5 short blasts.

At about the same time, the deckhandaboard the fishing vessel attempted to avoid a collision by turning to starboardbut, as automatic steering was selected, there was no response.

The fishing vessel collided with the shipsport bow at about 0429 causing a 6m gashin the No 1(port) tank, followed by lesserimpacts amidships and in the vicinity of theaccommodation. About 110 tonnes of oilleaked from the ruptured tank into the sea, before the contents of the tank were transferred



The Lessons

A feature of this incident is how late eachwatchkeeper detected the other vessel. Once again it reminds people howimportant it is to keep a very goodlookout, especially at night.

- 1. A fundamental purpose of a TSS is toimprove safety by requiring vessels tobehave in a predictable manner. Vesselsfollowing a traffic lane should be eitherovertaking or being overtaken, and thestatus of crossing vessels should beunambiguous. When vessels disregardthe requirements of Rule 10, thebenefits of a TSS, including those of theprecautions of radar coverage andreporting schemes, are jeopardised. Familiarity, or regular use of waters, does not carry any particular rights or exceptions from complying with the Rules at all times. They are there for allships to follow.
- 2. Maintaining an effective lookout inareas such as the Dover Strait, whichare navigationally demanding, andhave a high traffic density, is not easyand requires efficient time and bridgeresource management. Remember, thatwith a closing speed of 20 knots, it onlytakes 3 minutes for vessels to close 1 mile, and an OOW cannot afford totake his eye off the ball for longperiods. An OOW quickly checking theradar display, and looking out of thewindow between plotting a fix andwriting up the deck log, can be the difference between detecting a rapidly developing close quarters situation ingood time, and panic stations. When an OOW cannot maintain a lookouthimself, it is good practice to make the lookout aware of what he is doing and, in any event, must ensure the lookoutkeeps a good watch, particularly ahead.
- 3. Dedicated lookouts are required atnight. Keeping a lookout from the helmis not the way to meet the requirement.
- 4. When there are several vessels of different sizes in close proximity, it can be difficult to correctly associate radarechoes with the vessels sighted, particularly when there is no compassrepeater available to take bearings. Insuch situations it is essential that allvessels are continuously monitored, both visually and by radar. Be aware of remaining in the same position on the bridge or in the wheelhouse for toolong, as a vessel on a steady bearing canremain hidden behind a windowmullion from the horizon until just before it hits you.
- 5. Bridge watchkeepers are frequentlytired, but precautions can be taken tokeep them alert. These include drinkingfresh water; ensuring they are wellrested before taking over; that twopeople are always on the bridge or inthe wheelhouse; that the frequency seton the watch alarm is appropriate tothe situation and that watchkeepers are discouraged from remaining seated forlong periods.

- 6. The MAIB is aware that recreational equipment, such as CD players, feature as aids to relieve boredom in somevessels. If a master or skipper sanctions their use, so be it, but they are a major distraction in confined waters, and can prevent the OOW monitoring VHF transmissions. Switch them off, especially in the Dover Strait TSS.
- 7. A warning broadcast via VHF radio isworthless if it is not heard orunderstood. Always ensure that aproper listening watch is maintained on the VHF radio.
- 8. A competent master would prefer to becalled to arrive on the bridge to find avessel at a distance of 2 miles and closing, rather than a vessel at 1 cable with collision imminent.
- 9. Vessels transitting the Dover TSS shouldbe aware that the fishing vessel theysee crossing the lane in front of themmight well be in the charge of a 17 yearold who may be well trained, but is unlikely to have much experience.
- 10. Whether or not the belief that fishingvessels often wait until the last possiblemoment before taking action to avoid acollision is true, this should notinfluence the application of Rule 17 ofthe Collision Regulations. This ruleallows a stand-on vessel to manoeuvreas soon as it becomes apparent that thegive-way vessel is not takingappropriate action to avoid a collision. It is better to use this rule to goodeffect, and remain clear of give-wayvessels bent on maintaining their course and speed, rather than getinvolved in what could be a risky game of chicken. It is dangerous to assume another vessel is aware of your presence we might be right, but we dont want to be dead right!
- 11. When appropriate, use the wake upsignal as soon as possible and asfrequently as needed. The use of theships whistle, and any associated light, costs nothing and, if another vessel isnot aware of your presence, the soonerit is used, the more time the othervessel may have to take appropriate action.
- 12. When at close quarters, and taking avoiding action, dont nibble. By the time it is realised that more helm is needed to avoid a collision, it is often too late to be effective. The helm can always be eased once the risk of collision has passed.

Footnote

The BEAmer also investigated the accidentand cooperated with the MAIB with goodeffect.

This incident was the subject of a fullMAIB investigation. A comprehensive report, giving details of the causes, ananalysis, and recommendations was published in February 2002.

CASE 9 EPIRB Saves Two Lives

Narrative

A 15.73m-long wooden vessel wastrawling about 35 miles off the coast ofnorth Yorkshire one night in April, whenshe became fast. A crew of two was onboard. The wind was from the southeastforce 3 and the sea was slight.

While trying to release the trawl byheaving with the winch, a hydraulic pipeburst. An attempt to repair it failed, butshortly afterwards they came free. Because the winch was not working, thetrawl could not be recovered. Not wantingto lose their gear, the crew decided toleave the gear out and make for port atslow speed.

After they had been steaming for a while, the skipper told the deckhand to go belowand get some rest. When the deckhandopened the hatch to the cabin hediscovered flooding. The skipper turned onthe electric bilge pumps, but didnt thinkit necessary to contact the coastguard. After about half an hour the floodwaterdisabled the electrical supply which, inturn, stopped the electric bilge pumps. Realising the situation was becoming critical, the skipper tried to contact the coastguard using the fixed radios, butthere was no electricity supply, so wasunable to do so. The skipper did not thinkto use the portable VHF radio carried onboard.

Soon afterwards, the fishing vesselcapsized and foundered. The crew foundthemselves in the water where thetemperature was between 8°C and 9°C. The liferaft went down with the sinkingvessel, but two lifebuoys, a gas bottle andthree or four pound boards floated to the surface. The survivors managed to grabthe lifebuoys.

One further item had also broken free, the EPIRB. It started to transmit once on the surface and alerted the SAR authorities. The crew were in the sea for over an hourbefore a rescue helicopter arrived, havinghomed in on the EPIRB signal.

The crew were successfully rescued, andowe their lives to the coastguard, thehelicopter crew, many others in supportand, above all, the EPIRB.

The Lessons

- 1. This is a classic example of how the EPIRB can save lives! Fishing vesselowners often complain about the cost of safety equipment, but this demonstrates how valuable an investment the EPIRB can be
- 2. If flooding is discovered, always call the coastguard. You will not be disturbing them unnecessarily. They much prefer to be informed at an early stage, than later when things get desperate.
- 3. Fishing vessels of this size are required to have a portable VHF radio. If thecrew abandon to the liferaft, they should take the portable VHF radio with them; this is its primary purpose. The portable VHF radio can also be used if all other radios have failed.
- 4. There is little point in speculating whythe liferaft didnt float free, but thenext time you walk along the jettylooking at your fellow fishing vessels, count the number of times you seeliferafts so firmly secured that they willnever break free. Then go away andthink about it.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensivereport, giving details of the causes, ananalysis, and recommendations waspublished in February 2002.

CASE 10 The Thinking Man!

Narrative 1

A 251gt fishing vessel had recentlyundergone routine maintenance, duringwhich time the turbo charger on themain engine had been overhauled andrefitted. Once the maintenance wascomplete, the vessel prepared to return to the fishing grounds. She sailed, and had been on passage for only a short timewhen the turbo charger bearings seized, and a small fire broke out in the area of the exhaust manifold. The fire was quicklyput out and arrangements made to tow the vessel back to port.

On investigation, it was found that the turbo charger failed because of a basicerror during reassembly:

- a. The bearing oil supply pipe had beenconnected to the casing cooling waterinlet;
- b. The cooling water supply had beenconnected to the bearing oil inlet.

Narrative 2

A ro-ro ferry was on passage toPortsmouth, and the opportunity wastaken to install a new security box in theemergency generator room for the Halonrelease lever and alarm. The release wirehad been disconnected while the workwas being carried out to give easy access. With the job nearing completion, it wasdecided to re-connect the release wirebefore the final electrical connectionswere made. In doing so, the crewmanmoved the operating lever to one side, causing the release lever of the 60kghalon bottle to activate, discharging thegas into the emergency generator room.

The crewman left immediately, the spacewas ventilated, and the work wascompleted once the area was safe toenter. There were no injuries to eitherpassengers or crew.

Narrative 3

A cruise ship was in dry dock, in the USAwhen her crew were alerted to thepresence of heavy smoke in the vicinity ofthe frozen meat room. The alert wassounded, with contractors and nonessentialcrew being told to muster ashore. Preparations were made for boundarycooling, while the deck fire party enteredthe store room wearing breathing apparatus. After reporting that they hadfound smouldering wiring on the deckhead, they withdrew, leaving the second fire party from the engine room to investigate the surrounding area. This party entered the void space outside the store room, and found no evidence of the fire having spread to, or having originated in, an adjacent space.

The local fire brigade was now inattendance, and entered the store room. AClass A fire was put out. Smouldering and fire-damaged goods were removed, and the fire confirmed as being out shortly afterwards.

The cause of the fire was put down toboxes of meat being stowed in contactwith hot unprotected compressorpipework. This resulted in the cardboardcontainers drying out, heating up and smouldering to start a chain reaction. Nobody was injured.

The Lessons

A common theme links these three events. They happened in very different circumstances, and on differing types of vessel, but they each demonstrated what can happen when a course of action is not thought through to its logical conclusion. If you don't think things through YOU will probably be the one who suffers.

- 1. After any machinery overhaul, CHECKthat all connections are both made andtightened. Ideally, water and oilconnections should be either different colours, type of connections or markedin some way. ALWAYS check the work of contractors. If something is set upincorrectly, it is highly likely that YOU will be the one who eventually has tosort it out.
- 2. When undertaking work on a gasrelease mechanism, ALWAYS fit safetydevices to prevent accidental release.But remember to remove and CONFIRMthat it has been removed once the workhas been completed.
- 3. When loading stores, look at the spacefirst so that you know what accessdifficulties there are in the spaceallocated, and what problems could beencountered. If there are areas such asexposed and unprotected hot pipes, getthem insulated and protected.

No matter what vessel you are on, spendtime checking out the pitfalls that you oryour fellow seafarers are likely to meetduring the course of your job. RISKASSESSMENT, as it is now called, can saveyou a lot of time and worry.

CASE 11 I Will if you Wont!

Narrative

A fishing vessel was trawling north-westat 2.2 knots. A coaster was steamingnorth-east at 10 knots. It was daylight andthe fishing vessel was displaying anappropriate shape for a vessel engaged infishing. The weather was calm and thevisibility was good.

The fishing vessels sole watchkeepersighted the coaster when she was 4 milesaway, and determined that a closequarters situation was developing. Whenthe coasters range had closed to half amile, and she hadnt taken any action, thewatchkeeper altered course hard to portand increased to full speed.

The report is based solely on evidence provided by the fishing vessel, since the coasters evidence is that no such incident occurred.

The Lessons

There can be few fishing vessel skippers or short sea traders who do not recognise incidents such as this. There is often atendency to blame the other vessel for notdoing more to keep out of the way.

- 1. In the fishing vessel skippers experience, approaching vessels tend not to altercourse until the last minute. This has ledfishermen to delay taking action themselves until it becomes apparent that the give-way vessel has no intention of doing so. The reluctance of fishermento take action themselves is compounded by the restrictions imposed by their trawlgear. Although a stand-on vessel is not required to take action until collision cannot be avoided by the action of the give-way vessel alone, it may do so assoon as it becomes apparent that theother vessel is not giving way. In view of their restricted nature, and the reduced margin of safety in taking late action, vessels engaged in trawling should be prepared to act much earlier than they would do otherwise.
- 2. It was the coasters masters experiencethat fishing vessels tend to display afishing shape when they are not engagedin fishing. The assumption is justified, asanyone who has seen a fishing vessel in harbour can testify. The practice ofhaving shapes permanently displayeddoes undermine the value of beingrecognised as a burdened vessel, and canlead to dangerous assumptions beingmade by other, give-way vessels. Havingsaid that, it is totally wrong to assume afishing vessel showing shapes is notengaged in fishing. In this particular incident, the coaster was still the givewayvessel because she apparently hadthe fishing vessel on her own starboardside and was crossing. As a give-wayvessel, she was required to take early and substantial avoiding action.
- 3. We have here a skipper and a master who, fundamentally, do not entirely trust theother because of their past experiences. It is a sad reflection of how thetraditional manners of the sea havedeclined. Shipping must keep an eyeopen for fishermen, and must take earlyavoiding action so that trawlers andothers are not forced to manoeuvre withtheir gear still out. Fishermen, for theirpart, must realise that flouting theregulations, and having their daytimeshapes permanently rigged, underminesthe trust that other seafarers have intheir actions.
- 4. There are a couple of other points. The Collision Regulations require a vesselwhich fails to understand the intentions or actions of another, or is in doubt as towhether sufficient action is being taken by the other, to sound a warning signal of at least five short and rapid blasts. Hadthe fisherman done so in this instance, it might have alerted the coaster. Although the minimum audible range

required for avessel the size of the fishing vessel is 0.5 mile, the distance at which thewatchkeeper decided to take actionhimself, making a sound signal might, just might, be the difference between acollision and a near miss.

5. This article has focussed, in part, onshippings interpretation of fishingvessels shapes. It is an old debate, withevery prospect of continuing. The factremains that any experienced mariner inreasonable visibility can tell by looking at a fishing vessel, using binoculars ifnecessary, whether it is actually engaged in fishing. The watchkeeper glued to the adar cannot. The moral of the story: lookout of the window. Please.

CASE 12 He Who Hesitates

Narrative

A French fishing vessel collided with a UKaggregates dredger in the north-easttraffic lane of the Dover TSS. The fishingvessel was not fishing and had been thegive-way vessel under the CollisionRegulations. Both vessels suffered minordamage.

The fishing vessel had been crossing thenorth-east traffic lane on a southerlyheading making 9 knots. The dredger wassteering 050° in the traffic lane andmaking a speed of 11.7 knots. She hadbeen overhauling two vessels which were close ahead of her. The headings and speeds of both vessels had been steadyfor 10 to 12 minutes before the collision.

The second officer was on watch on the dredger. He was aware that the fishing vessel was approaching on a collision course. Experience had taught him to expect fishing vessels to leave it until the last minute before altering course. He continued to monitor the situation, but did nothing at that stage to attract the attention of the fishing vessels watchkeeper.

The fishing vessels skipper was on watch. He had seen the dredger, but did not thinkthat there was a risk of collision.

In the event, the dredger did not alter tostarboard to avoid the collision until about aminute before the collision, when the fishing vessel was at a range of a quarter of a mile or less. At about the same time, her skipper put her engine full astern. These actions proved too little, too late.

The Lessons

Anyone reading this brief narrative willbe asking what new lessons can possiblybe learned in this oldest of all situations. Two vessels are approaching one anotherin such a way that the risk of collisionexists. The one thinks he knows that theother will delay giving way until the lastminute, while the other doesnt think arisk of collision exists. Ancient marinersthe world over will be thinking Here wego again. Most will instinctively say theywould never, ever, leave things so late. These lessons are not, therefore, for thembut for that watchkeeper in a million whomight, just might, get it wrong. Theproblem is that it keeps happening, soperhaps we should never stop learning.

- 1. If a risk of collision exists, and you arethe officer of the watch in the standonvessel, never assume that the give- way vessel has seen you. Until sheshows, by positive action, that she hasthe situation under control, it is safer to assume she has not.
- 2. Rule 17 permits the stand-on vessel toact as soon as it becomes apparent toher that the vessel required to keep outof the way is not taking appropriateaction in compliance with these rules. In this case it was apparent, when therange between the two vessels was about 1 mile, that the fishing vesselwas not taking early and substantial action to keep well clear as she was obliged to do under Rule 16. At this time the dredger should have used her signalling light and whistle to alert the fishing vessel. If this did not promptimmediate action from her, the dredger should have made a broad alteration to starboard to avoid the collision. Shewas permitted to do this under Rule 17a (ii) and, it could be argued, required to do it under Rule 2.
- 3. If the fishing vessels skipper reallythought there was no risk of collision,he was demonstrably wrong. It doesntmatter who you are, or in what type ofvessel, the person in charge has

afundamental responsibility to determine whether a risk of collision exists and do something about it when it does. Radar, the compass, commonsense, seamans eye, and knowledge of the Rules are the tools available to achieve this. The oldest guidance of all is still the best. If the compass bearing of the approaching vessel does not appreciably change, then risk of collision exists.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensivereport, giving details of the causes, ananalysis, and recommendations waspublished in April 2002.

Ideas for Tackling Flooding

Narrative

A 21.9m wooden vessel fishing vessel washeading north-north-east from her homeport to pair trawl with her partner. The windwas south, force 4 and the visibility wasmoderate to good. A crew of six was onboard.

While on passage, the main enginetemperature was seen to be rising. Aninvestigation revealed the problem to be ablocked sea water inlet. The mate closed theseacock as best he could before taking thecover plate off the adjacent strum box. Onlooking inside, he saw a black plastic bagjammed in the valve. He opened it and pulled the bag out but, no sooner had he done so, when water started to pourthrough. The mate did his best to shut theseacock, but the linkage came off. Despitefrantic efforts to contain the flooding, allattempts failed. Bilge pumps were used topump out the floodwater, but couldnt keeppace. The hand pump was hardly effective.

The only power-driven bilge pump used, wasthe one fitted to the auxiliary engine. Asecond one, driven by the main engine, wasavailable but not used. The main engine drewits cooling water from the open seacock, andboth skipper and mate assumed they couldnot start the main engine because there wasno cooling available. There was a pipe from the bilge system capable of feeding seawater direct to the main engine for cooling. The mate was aware of this but, because hehad never used it before, thought it shouldnot be used as it would damage the engine. The nature of the emergency left little scopefor lateral thinking.

A coastguard helicopter flew out to thevessel with two portable salvage pumps, butbefore these could be put into action, the position on board deteriorated to the extentthat the decision to abandon ship was taken. The crew evacuated to the partner trawler, leaving the flooding vessel to sink about three hours later.

The Lessons

An incident like this demonstrates thatflooding can occur at any time, in any placeand is no respecter of a vessels age. Thelessons focus on two aspects: preventing theflooding in the first place, and containing itto prevent the vessel sinking.

It is also sobering to think that the origin of this loss was a plastic bag.

- 1. Opening up a seacock when afloat is notadvisable. Unless there is some way ofisolating an inlet safely at sea, remedialwork should only be attempted inharbour. Apart from the obvious solution of slipping the vessel to ensure there is noway for flooding to take place, it is possible to open up a seacock by berthingin a tidal harbour and waiting for the tideto go out. Once it is safe to do so, these acock can be opened up and the blockage cleared. Should there then be aproblem restoring the system to normal, there should be sufficient time to dealwith the situation.
- 2. The US coast guard trains repair teams sothat ships can be kept operational afterlimited damage. A large softwood wedge driven into an open pipe. Those doingso will confront an even greater quantity of spurting water initially, but smallersoftwood wedges are then driven inbetween the main wedge and the pipeuntil the flow is choked off. The tops of the wedges are trimmed with a saw, before a wood shore is placed between the tops of the wedges and the nearestpart of the ships

structure. The US coastguard encourages fishing vessel skippersto carry softwood wedges and shores forthis purpose. Why not do the same?

- 3. In extremes, it might just be possible tocontain the flooding by resorting to thetraditional option of fitting an emergencytingle. By lowering a weighted canvas orplastic sheet over the side in the vicinity of the inlet, it is possible it will cover thehole and substantially reduce the rate offlooding. This in turn might provide additional time for other actions to bemore effective. It might sound farfetched, but in days gone by was tried with conspicuous success.
- 4. The main engine could have been startedonce the flooding had developed. The cooling water was available and plenty offit; the floodwater inside the vessel. This would have helped to pump the vesselout since the cooling water was discharged overboard once it had been cycled through the heat exchanger. Starting the main engine would also have meant that the second bilge pump could be used.
- 5. The sea water pipe from the bilge systemcould also have been used for mainengine cooling. Seawater fed directly toan engine, rather than through a heatexchanger, can cause damage by blockingpassages with salt deposits. However, in situations such as this, the risk of anyproblems is minimal. In an emergency, it is a perfectly acceptable step to take.
- 6. Had a portable salvage pump beencarried on board, it could have helpedsave the fishing vessel. Consider it.

Footnote

The MAIB receives a number of reports offlooding incidents to fishing vessels. Thereasons are not always identified, but whatdoes become evident, is how often it seemsthat more could have been done to preventthe vessel from sinking had damage controlactions been better handled. The instinctivereaction is, invariably, to request additional pumps. This is right and proper, but far moreneeds to be done to contain, or even stop, the flooding using alternative means.

This article is largely directed at stimulating discussion on how this might be achieved. One final thought. Next time you allow inadvertently of course a plastic bagto drop overboard in harbour, dont. It could be the one to jam someones seacock. The really sobering thought is it might be yours!

This incident was the subject of a full MAIBinvestigation. A comprehensive report, giving details of the causes, an analysis, and recommendations was published in June 2002.

Engine Room Flooding causes Another Fishing Vessel Loss

Narrative

A 23.99m twin-rig steel trawler wasfishing off the Yorkshire coast when hernets became fast on the seabed.

While trying to haul back the starboardnet, a hydraulic pipe, from the winch tothe hydraulic motor burst. All three crewthen spent the next several hours on deckreplacing the burst section of pipe.

While they were on deck, the vesselsuffered substantial flooding to theengine room. The flooding was not discovered until one of the crewmen went down the engine room for a section of hydraulic hose. Because thewheelhouse was left unattended, the bilgealarm went unnoticed.

By the time the flooding was discovered, the level of floodwater was well above the engine room floor plates. With the engine room in virtual darkness, because of the failure of the 24V electrical system, it wasnot possible to locate and open the valvechest to operate the engine-driven bilgepumps.

After unsuccessful attempts were made toregain power to the 24V electrical system, and to transmit a Mayday, the crewabandoned the vessel in the liferaft. Thevessel capsized soon after.

Shortly after boarding the liferaft, thecrew managed to activate the EPIRB, which they had taken with them. Threehours later they were rescued by acoastguard helicopter.

The Lessons

- 1. The investigation of this accidentrevealed that the vessels loss was one, or a combination of, the following factors:
 - a breach in the hull plating,
 - failure of a non-return valve in anoverboard discharge resulting in backflooding, or
 - engine room seawater piping failurecaused by erosion or corrosion.
- 2. The condition of the hull plating shouldbe checked on a regular basis, inaddition to the 4-yearly ultrasonictesting required under survey. This isespecially important if the vessel hassuffered any kind of impact damage,no matter how slight.
- 3. Non-return valves should also bechecked regularly, to ensure they are functioning correctly.
- 4. The failure of engine room seawaterpiping is a common occurrence onfishing vessels, and has accounted formany flooding incidents. This has, insome cases, led to the actual loss of thevessel. In light of this, it is wise to carryout simple regular checks on allpipework, especially in the engine roomand in places which may at first appear to be inaccessible. A simple check forsigns of corrosion or weepingpipework, culminating in the repair orreplacement of the piping, may wellprevent the vessel from being lost.
- 5. While at sea, the wheelhouse shouldnever be left unattended. Had it beenmanned, the bilge alarm would have been heard, and would have given theorem sufficient time to deal with the problem and

contain the flooding. Inall probability, it would have been possible to prevent the vessel from foundering.

The ingredients of this incident are notuntypical. There have been a number of recent founderings in which the circumstances have been very similar. There is a late discovery of flooding, and the crew have insufficient time to contain it. The vessel then fills with water and sinks. The saving grace in many of themore recent incidents is that the crew has usually been rescued, thanks to the skilland dedication of the search and rescue organisations.

Yet the fact remains that in all probability, the loss was caused by a relatively smallhole, perhaps measuring no more than 5to 10cm across, through which theflooding was taking place. If it is possible to stop the water coming in at the pointwhere the pipe penetrates the hull, it isvery likely the vessel, and perhaps its crew, can be saved. The fact remains, that withforethought and the sharing of experiences, it is possible to reduce or evenstop the flooding by a number of ways, providing you know how to do it.

By adopting the oldest technique in thebook, lowering a weighted canvas sheetover the position of the engine room inletson the affected side, the rate of floodingcan be substantially reduced.

Footnote

This incident was the subject of a fullMAIB investigation. A comprehensive report, giving details of the causes, ananalysis, and recommendations was published in November 2001.

Fisherman Saved by Lifejacket

Narrative

A 4.95m GRP vessel was being used forcreeling off the coast of Northern Irelandon an April afternoon. The wind was fromthe south-west force 4, the sea and swellwere slight, and the visibility was good. She was being operated single-handedly.

While hauling creels about half a mileoffshore, the skipper heard a thump andrealised that a rope was caught aroundthe vessels propeller. He attempted to cutthe rope free and, in the process, noticedfloodwater coming up through thefloorboards.

Alarmed at how quickly his vessel wastaking on water, the skipper pulled therelease toggle to inflate his lifejacket. Lessthan five minutes later the vesseldisappeared beneath the surface. Theskipper had had no time to call for help orfire distress flares. Buoyed by his lifejacket,he slowly drifted inshore and, about anhour later, was able to stagger ashore. Hewalked home, took a hot bath and thennotified the coastguard of his experience.

The vessel was subsequently recovered. When examined, it became apparent that the rope had wrenched the propeller away, along with a section of the hull.

The Lessons

1. This skipper had a very lucky escapeindeed, especially given that the sea isextremely cold in April, and there can beno doubt that the lifejacket saved hislife. The MAIB has consistently advised fishermen to wear inflatable lifejackets when working, and this case illustrates very well that by doing so, you will greatly increase your chances of survival.

An EN 396 inflatable lifejacket can costas little as £60, a worthwhile investment. One of this type satisfies the regulatoryrequirement for vessels of less than 12min length (an inherently buoyantlifejacket is not required if a selfinflatinglifejacket is carried).

- 2. The risks multiply when sailing alone, soit is particularly important to wear aself-inflatable lifejacket when doing so. This skipper owes his life to the fact thathe took this most basic of safetyprecautions.
- 3. The skipper should have paid a little moreattention to communication. Had thedrift been offshore, the outcome mighthave been very different. Mobile phonesare not ideal; they arent waterproof and signal isnt always available offshore. Lone fishermen should always carry awaterproof portable VHF radio, the costof which is about £300. Although thismay seem a little pricey, few wouldargue that if it saves your life, it ismoney very well spent.

CASE 16 See No Vessel, Hear No Vessel!

Narrative

A potter of 10m registered length washauling a fleet of pots in thick fog. Shewas exhibiting navigation lights and wasdisplaying an appropriate shape forward. The skipper and his crew were all involved in the operation on deck and thewheelhouse was left unattended. A radarwas operating on a 0.5 mile range scale.

A 1,441gt cargo vessel was steaming atabout 7 knots. The chief officer was onwatch with operational radar and, she,too was exhibiting navigation lights.

The fishing vessels skipper first becameaware of the cargo vessel when he heardher wash in the fog; he then saw heremerge from the fog and approach his port side. He entered the wheelhouseimmediately and applied full asternpropulsion, while his crew quickly threwthe fleet of pots overboard.

The cargo vessel passed close ahead of the fishing vessel and has no record of the incident.

The Lessons

1. Neither vessel was aware of the otherin sufficient time to prevent a closequarters situation. In the prevailingfog, the cargo vessels chief officer wasreliant on radar and sound to detect the fishing vessel, and the fishingvessels skipper was reliant only onsound, since he had chosen to leave the wheelhouse unattended. It is uncertain whether or not the cargovessel sounded her whistle. What is known, however, is that the crew of the fishing vessel did not hear one. Inview of her length, the fishing vessel was not required to be fitted with awhistle. She carried a bell, but didntuse it.

In the absence of radar detection, effective sound signals are essential if close quarters situations are to be avoided.

2. Both vessels had operational radar, buteach failed to detect the other. The fishing vessel was placing much reliance on the larger vessel detectingher by radar and taking the appropriate avoiding action. She didnot. In fact, she didnot even see the smaller fishing vessel on her radar, and was totally unaware of the entire near miss situation. If you are fishing indense fog, be aware that you may not be seen.

It is uncertain why the cargo vesselschief officer did not observe the fishingvessel on radar, or sight her visually atclose range. Possible reasons include asub-standard lookout, and poor radarreturn caused by the fishing vesselsfibreglass construction and a possiblyineffective radar reflector.

The fishing vessels skipper has sincefitted a larger radar reflector to hisvessel, which will assist in his vesselbeing detected in the future. He willalso remember not to leave hiswheelhouse unattended, since by doingso he is removing his ability to detectapproaching vessels by radar.

3. Many seafarers will relate to this incident, which underlines the need for a proper lookout to be kept at all times, to maintain a full appraisal of the situation, and to enable action to betaken at an early stage. In this case, although late, the prompt emergency action taken by the skipper and his crew was effective in preventing a disaster.

Things that go Bump in the Night

Narrative

A wooden stern trawler landed her catchin Mallaig, then sailed in the early hoursof the next day to return to fishinggrounds to the south. The prawn fishingwas good and, accordingly, the workloadhigh. The watch alarm was not workingand had been landed ashore for repair, and the vessel was sailing one man short of her normal complement.

The deckhand, who was alone on watch, noted another, slower outbound vessel onthe port side. Two other vessels wereinbound, and they passed by safely. The deckhand was feeling tired, having managed only 5 hours sleep in the previous 24 hours, and having had no sleep for 17 hours. This was in addition to his having worked the previous 4 days with a similar disrupted sleep pattern. Hesat down in the wheelhouse chair.

The deckhand had known he would betaking the first watch after departureMallaig, but had, nonetheless, opted tojoin his colleagues for an evening at a barashore, rather than taking theopportunity of a well earned rest.

While ashore, he drank a moderate twopints of beer. However, given his lack ofsleep and increased workload, the alcoholprobably had a greater adverse effectthan he realised.

At around 0230, the waypoint for the nextalteration of course was reached. Owingto the close proximity of the other vesselbeing overtaken on the port side, the deckhand altered course to port onlyabout 10°. He intended altering the fullamount once the other vessel had been passed safely. The other deckhand was due to be called about 10 minutes later for his watch. Shortly after making the alteration, the deckhand fell asleep.

At 0320 he was awoken suddenly by aseries of bumps and bangs. The vessel hadgrounded.

The vessel was refloated at high waterlater that day, with the assistance of Mallaig lifeboat. She had sustained superficial hull damage, and waterdamage to the accommodation and engine room. There were no injuries or pollution as a result of the grounding.

The vessel was later repaired andre-entered service.

The Lessons

- 1. The workload was high on this trip, owing to the good fishing and the factthat the vessel sailed a man short ofher normal complement. This resulted in the skipper deciding to have only one man on watch, instead of the normal two. Having another person in the wheelhouse would have not only provided a second pair of eyes, but it would also have given the deckhand company and kept him more alert.
- 2. The deckhand had chosen to go ashorein Mallaig, rather than opting to getsome much needed rest. While ashore,he had a few drinks and, later, had satdown in a comfortable chair while onwatch and feeling very tired. This combination of circumstances resulted in him falling asleep and failing tomake the required alteration of course. The result, a very rude awakening.

The effects of drinking alcohol canoccur more quickly when tired, and bemore pronounced, than expected. Avoidalcohol if you are tired, and if tired dont take the watch!

3. Had the watch alarm been working, it is probable the deckhand would have awoken before the vessel grounded. It had been sent ashore previously and had not been returned to the vessel. The watch alarm is a fundamental piece of safety equipment, especially on a vessel with a high workload, and one that is sailing short-handed.

A Wooden Vessel Floods and then Sinks

Narrative

A 23.99m wooden fishing vessel, built in1982, was trawling about 75 miles fromher home port. The wind was from thenorth-north-east, force 5 and visibility wasmoderate to good. A crew of four wason board.

At about midday, the port net becamesnagged on a seabed obstruction. The crewspent the next few hours trying to haul thenet, sometime during which the vesselstarted to flood. Damage caused by acontact between the port trawl door andthe hull is considered to be the most likelysource of the ingress, although floodingvia the pipework cannot be ruled out.

The two main bilge pumps were electrically-driven and both were disabled when the floodwater reached the transformer box. Both pumps received electricity from the same source, which meant that if one was disabled, both pumps were lost. They should have been independently-driven, but they were not.

Although the flooding filled the engineroom, the bilge alarm didnt alert the crewbecause the audible signal was not working the time. By the time the floodwater was discovered, it was too deep for its source tobe identified.

The crew were unable to contain theflooding, so were forced to abandon thevessel. The batteries for the fixed VHF radiowere disabled by the floodwater, so theportable VHF radio was used forcommunication in the latter stage of therescue. Help arrived in the form of a fastrescue craft from an oil-rig guard ship, justseconds before the vessel sank by the stern. All crew were rescued, unhurt.

- 1. Defective bilge alarms have been a factorin the loss of many fishing vessels. TheMAIB, and others concerned with marinesafety, have repeatedly emphasised theimportance of a correctly functioningbilge alarm. Ensure that yours is workingbefore sailing, since without it, you andyour crews lives are at risk. Consider thetime it would take to repair one which isdefective often minutes the time ittook for this vessel to sink.
- 2. The electrical supply for bilge pumps should be independently-driven. This willensure that if the supply to one pump is lost, the other will continue functioning.
- 3. This article clearly demonstrates the value of the portable VHF radio. Had theskipper of this vessel lost communication with the guard ship, the rescue mighthave been delayed, leaving the crew onboard when the vessel sank.

Look After Your Tonnage Valves

Narrative

A 15.24m-long steel fishing vessel was twintrawling near an offshore platform in the North Sea at midday. The wind was force 5, the sea moderate with a 2m swell and visibility was 8 miles. An experienced crew offive was on board. The fishing operation wasto be the vessels last before she returned toher home port.

When the trawl was hauled, it became clearthere was a good catch in the nets; enough to fill the hopper up to the shelter deckhead. The full hopper caused an angle of list of about 9 degrees to starboard. While gutting the catch, the crew became alarmed at the sight offloodwater starting to build up inside the shelter. This floodwater caused the vessel to slowly capsize to starboard. She sank in 140 mdeepwater and has not been recovered.

All crew members were rescued by the fastrescue craft from a nearby stand-by vessel.

A tonnage valve had been fitted either sideof the vessels shelter, to discharge deckwater. These were freeing ports fitted with aflap, which should have allowed water toflow out, but not in. It is possible the tonnagevalve on the starboard side became jammedopen, perhaps by a piece of fish offal. Thiswould have allowed the vessels shelter toflood if her stability had been sufficientlydegraded by the weight of the fish in thehopper, high up on the starboard side.

The deckwash supplied seawater to theshelter so that the fish could be washedbefore they were stowed in the hold. Had thetonnage valve been blocked, or seized closed, it would have taken about 30 minutes forsufficient seawater to build up to capsize thevessel, if the deckwash was on. Given either of these scenarios, the tonnage valve on the starboard side malfunctioned, something surveyors find all too frequently.

- 1. If your fishing vessel is fitted withtonnage valves, inspect them regularly preferably between each trip andremember to keep the spindlelubricated so that the flap moves freely.
- 2. When fish are being gutted, thetonnage valves should be checkedregularly to ensure they have notbecome blocked by fish offal; this isespecially important when the deckwash is running. If water starts tobuild up in the shelter, check the deckwash immediately to ensure that it is turned off.
- 3. Tonnage valves should be screwed shut, unless the deckwash is on. Never wedgethem open.

Skippers Last-Minute Action Saves Lives

Narrative

An 18m-long stern trawler was trawlingin the St Georges Channel in association with four other fishing vessels when shenoticed a container vessel approaching from astern. The 116m-long container vessel was on passage between Liverpooland Portugal. It was a warm summer evening, with a light breeze and excellent visibility.

The trawler was towing a bottom trawl atabout 1.5 knots on a heading of 220°. Herskipper had first noticed the containervessel on radar at a range of about 2miles. He had monitored the approach ofthe other vessel on a collision course until the range between them had reduced to 0.5 mile.

The container vessel was making a speedof about 15 knots on a course of about 190°. The master had been alone on herbridge and had been aware of his vesselsapproach to a number of fishing vessels. The containers on deck hampered his closerange visibility from the wheelhouse. Ashe had neared the other vessels he alteredcourse to avoid them, but found that closepassing was inevitable.

The trawlers skipper considered the othervessel was not going to alter coursesufficiently, and that his vessel was at risk. He therefore immediately instructed hiscrew to come out from the cabin to the comparative safety of the deck. Theskipper released the fishing gear and, at the same time, put the helm hard tostarboard.

The container vessel passed about 6mclear on the trawlers port side.

- 1. We are all taught to drive a motorvehicle defensively, and to be prepared for the unexpected. Fishingvessel skippers are also advised to heedthis sound advice. Consider the possibility that give-way vessels justmight not have seen you, or that perhaps they have been hampered by other vessels or for a myriad of other reasons. Prepare a contingency plan, just in case the other vessel doesnttake appropriate anti-collision action.
- 2. This skipper did well, and saved the day. He is particularly commended forcalling his crew out on deck. Herealised the situation was potentially dangerous, and he addressed the issue immediately. Failing to take such action under similar circumstances has resulted in many fishermen being trapped on board their vessels, and losing their lives as a consequence.
- 3. The container vessels master had beenaware of his vessels approach to anumber of fishing vessels. He was also aware that the cargo on deck posedlimitations to his visibility. Given these conditions, he should have taken early action to keep well clear of the group of fishing vessels, or slowed his vessel and navigated with extreme caution until clear of them.

CASE 21 No Redundancy!

Narrative

A fishing vessel was leaving port. It wasdark and the weather was calm. The skipperwas alone in the wheelhouse. Once clear ofimmediate dangers, he engaged theautopilot, forgetting that it had anunresolved fault, and then studied hisfishing charts. The vessel deviated from theintended track and grounded.

The Lessons

1. The departure followed a regular routine. The skipper was alone in thewheelhouse, while his crew cleared awaythe ropes and fenders on deck. It was tobe a normal days fishing.

Having operated satisfactorily for 14 years, the autopilot had developed afault prior to arriving at the port, and although the skipper had attempted to have it repaired, the fault remained unresolved. He was aware of the wisdomof checking the autopilot against the compass heading, but apparently failed to do so on this occasion. With no obvious indication to remind him that the autopilot was not working, heen gaged it with misplaced confidence, based on its 14 years of good service.

Apart from monitoring the compass, theskipper had no means fitted to alert himto the fact that the vessel was deviating from the intended heading. Relevantand necessary check procedures should followed at all times to guard against complacency.

2. In deciding to look at his fishing charts, the skipper was unable to rely on anyoneelse to maintain a proper lookout. Asecond person on watch would have enabled the autopilot malfunction to be identified, and remedial action to be taken. With no redundancy, the skipperwas reliant on the correct operation of the navigational equipment and hisability to maintain a proper lookout. Ameasure of built-in redundancy is required in any navigational operations o as to ensure that an error by one person, or the failure of a single item of equipment, does not result in an irreversible dangerous situation.

Collision Between Fishing Vessel and aGeneral Cargo Ship

Narrative

In clear visibility, slight seas and force 4 to 5 winds, a small fishing vessel began tohaul her nets while heading into awesterly wind. She had been on the samewesterly heading for about 3 hours. Beforehauling, the skipper had seen a merchantvessel on the port side, heading in anortherly direction.

When the trawling gear reached the seasurface, the crew found it to be fouledwith a large piece of timber. The skipper, therefore, kept the vessel making waythrough the water to avoid the trawlfouling the propeller, and the timbercausing damage to the vessel.

The skipper decided to help the crew and, before leaving the wheelhouse, anticipated there would be no problem in the ship avoiding his vessel. However, while busy retrieving the gear, the skipperheard one blast from the cargo shipswhistle. The two vessels collided.

The cargo ship was on a heading of 304° and travelling at a speed of 8 knots. UsingVHF radio, the chief officer had tried invain to call the fishing vessel on his starboard bow. He then called the masterwho, on reaching the bridge, saw that the fishing vessel was on a collision course. The master reduced the ships speed and turned the helm hard to port. He then sounded the whistle, but his action failed to prevent a collision.

The fishing vessel ran along the starboardside of the cargo ship, before clearing. Theskippers first response was to call the shipon VHF radio channel 16, but he receivedno reply. He then noticed water runningacross the accommodation deck, so wentbelow to check for leaks. Water waspresent, so he moved the batteries to ahigher position.

The fishing vessel was able to reach portsafely.

- 1. The skipper thought the ship didntpose a problem, based partly on hisknowledge that it was approachingfrom his port side, and partly becausehe was fishing with the appropriatesignals displayed. An assumption thatany vessel, whether fishing ormerchant, will meet her obligation tokeep out of the way when there is riskof collision, is a dangerous one tomake. Many have made this assumption and, when avoiding action are eventually been taken, it has been too late. Some collisions in similar circumstances have resulted in loss of life, sometimes considerably so. Thene do to keep a proper lookout so as tomaintain a full appraisal of the situation is paramount.
- 2. The obligation of the chief officer wasclear under the InternationalRegulations for Preventing Collisions atSea. He had to keep out of the way ofthe fishing vessel, which was engagedin fishing. We dont know why the chiefofficer wasted time trying to contactthe fishing vessel by VHF radio, whythere was apparent doubt as to hisobligations, and why he felt it necessaryto call the master, whose subsequentactions were too late to prevent acollision.

Fishing Vessel Capsizes with Loss of Life

Narrative

A 10m-long stern trawler left port in the south coast of England, with three crewmembers on board. She headed for popular grounds off Gilkicker Point, unfamiliar to her skipper and crew. The weather was fine with a west-northwesterlywind of force 4 and goodvisibility.

During the first trawl of the day shepicked up part of a WW2 torpedo, as wellas a quantity of mud and shells. Theskipper was aware that a heavy load hadbeen caught, so he and the crew decided to try and recover it so that they could then decide how to deal with the situation. They managed to raise the netto the surface fairly easily, but when they tried to lift the cod end clear of the water, the weight was too much for the trawlwinch. As the winch struggled to lift the cod end by the gilson rope led through ablock on the A frame, at a height above the deck of about 4.8m, the vessel took anincreasing list to starboard. The loadsnagged on the starboard quarter and, with the winchs relief valve blowing, it could neither be pulled inboard, norlowered back into the water.

The situation seemed to stabilise with thevessel listed to starboard, and with freeingports on the aft starboard sideunderwater. As the crew member cut thenet to release the unwanted load, thevessel encountered the wash from apassing vessel. She rolled, took water overthe starboard bulwark and capsizedrapidly. Within minutes, she inverted and foundered.

The crew of a nearby yacht witnessed theevent. They rescued the skipper and his sonquickly from the water and raised thealarm. Other rescue craft were soon onscene. The crew member who, with theskipper, co-owned the vessel, was discovered floating face-down in thewater. He was airlifted to hospital but, despite continuous attempts to resuscitatehim, was eventually pronounced dead. Hewas believed to have been a non-swimmerand had not been wearing a lifejacket.

The Lessons

- 1. It is essential that skippers have a goodbasic understanding of ship stability sothat they can make informed decisionswhen extraordinary events occur.
- 2. Once again, we are reminded of theneed for fishermen to heed the advicethe MAIB so frequently issues: alwayswear a lifejacket when working on theopen deck even in seemingly benignweather and sea conditions.

Accidents are rarely caused by a single event. All too often, several factors combine and tragedy strikes; leaving abereaved relative grieving and leaving avessel without a valued crew member. This case was no exception. The removal of anyone of the following four situations might have averted the accident:


- Picking up part of a WW2 torpedowhile fishing. The area off GilkickerPoint is known to contain a substantial amount of ordnance. Anyone fishing there should be aware of this hazardand should make contingency plans in the event they are unlucky enough to catch more than they bargained for.
- The decision to try and lift the load ondeck using a lifting point 4.8m abovethe deck. This action raised the vesselscentre of gravity and resulted in thecapsize. Having raised the load to the surface, and having realised that it wasvery heavy, the skipper and crew should have decided on the safer option of releasing the net and buoying it for recovery by a specialist


craft. Alternatively, they could have dragged the load into shallow water for inspection at low tide.

- The snagging of the load on the fishingvessels quarter. This left the crewunable to lower the net into the waterto reduce the list and increase thestability. The MAIB is unsure exactlyhow the net became caught.
- Finally, encountering the wash from apassing vessel. This area is close to themain routes used by many ferries, highspeedcraft and merchant vessels. It is, therefore, not unusual for a vessel toencounter wash from a passing craft.

Statistics

Fishing Vessel Losses





^{*} Figures for 2002 are provisional at time of publication. (March 2003)

Fishing Vessel Accident Statistics 1990 2002


YEAR	LOSS OF LIFE					PERSONAL ACCIDENTS	
	Lost with	Fell	Involved	Onboard			

	vessel	overboard	Machinery	Accidents	Tota 1		
1990	22	4	4	0	30	128	17
1991	25	5	0	2	32	165	41
1992	7	4	3	2	16	133	32
1993	9	7	0	2	18	115	38
1994	16	5	0	5	26	155	43
1995	10	8	1	0	19	108	33
1996	9	4	1	6	20	97	26
1997	16	7	0	6	29	138	23
1998	18	5	0	3	26	112	21
1999	3	4	0	2	9	89	33
2000	21	6	2	3	32	104	40
2001	0	6	0	3	9	81	33
2002*	4	4	0	0	8	50	16
TOTAL	160	69	11	34	274	1475	396

^{*} Figures for 2002 are provisional at time of publication. (March 2003)

CHART

Major Accident Locations



PUBLISHED REPORTS

List of fishing vessel accident reports published since 1999

Alma C - report on death of Michael John Beedie a fishermanfrom the fv Alma C on Turbot Bank about 55 miles west-bysouthof Thyboron in Denmark on 25 January 2001

Amber Rose - foundering of fishing vessel with loss of onelife off the Isle of Man on 15 October 1998

Angela - capsize and foundering of fv in North Sea on 6February 2000

Annandale - flooding and foundering of fv 16 miles NNE of the Shetland Islands on 23 March 2000

Arco Arun - grounding, off Broadness Point, River Thames on 13 October 1998

Arosa - grounding and total loss of UK fv on Doonguddlerock off the west coast of Ireland with the loss of 12 crewmembers 3 October 2000

Astra II - loss of two crewmen attempting to board the vesselwhile berthed at Carbost pier, Loch Harport, Isle of Skye on 2April 2000

Atlantic Princess - man overboard incident from vessel in the English Channel on 23 November 2000

Aurelia - flooding and loss of fv Aurelia 78 miles west of StKilda 13 August 2001

Be Ready - fire on board the fishing vessel while fishing 30miles north-west of the Orkney Islands on 22 January 2000

Betty James - grounding and subsequent loss of fv off Isle ofRhum on 10 July 2000

fv Beverley Ann II - collision between vessels on 9 March1999 Cypress Pass

Blue Hooker - loss of the fishing vessel with two lives offBlackchurch Rock, North Devon on 12 November 1998

Catrina - capsize of the UK registered fishing vessel south of Newhaven on 13 October 1998

Celtic King/De Bounty - collision between UK registeredfeeder container ship Celtic King and Belgian registered fv DeBounty vessels to the south of The Smalls traffic separationscheme off the south-west coast of Wales on 19 March 2000

Charisma - capsize of the fishing vessel Charisma (OB588)with the loss of one crew member Carlingford Lough 30January 2002

Christine Nielsen - flooding and foundering of fishing vessel120 miles north-east of River Tyne on 18 March 2001

Constancy - sinking of fishing vessel on 30 July 1998 withloss of one life

Constant Faith - loss of Constant Faith about 100 milesnorth-north-east of Peterhead on 30 June 2001

Crimond II - loss of vessel 30 miles north-east of Scarborough on 24 April 2001

De Kaper - fire on board trawler off Hanstholm, Denmark on 12 February 1999

Donna M - capsize of fishing vessel off the Orkney Islandswith loss of two lives on 31 August 1999

Dunan Star - fatal accident on board fv 1.5 miles south-west of the Isle of Arran on 10 August 2000

mv Elm/mfv Suzanne - near miss incident on 11 February 1999

European Tideway and Vrouw Grietje - collision between vesselsin North Sea 16 October 2000

Fishing Vessel Safety Study 1/2002 - report on the analysis offishing vessel accident data 1992 to 2000

Fleur de Lys - explosion on board vessel which then foundered 18miles south-east of Portland Bill on 16 April 2000

Fraoch Ban - capsize of fv off coast of Shetland Islands 15 August 1999

Geeske - death of one person while fishing off Beachy Head on 9December 1998

Gemma Fidelis - fatal accident on board Gemma Fidelis 9 mileseast of the River Tees on 23 October 2001

Girl Alice - loss of skipper from vessel 1.5 miles south-east of Burnmouth 19 November 2000

Gradeley - manoverboard fatality off the west coast of the Islandof Mull on 28 October 1999

Gudermes and Saint Jacques II - collision between vessels in the Dover Strait on 23 April 2001

Harbour Lights - loss of fv off Polperro, Cornwall on 8 January 2000 with loss of one life

Horizonte Claro - grounding of fv vessel on Soyea Island, LochInver, 21 October 2000

Jasper III - foundering of vessel 90 miles north-east of Fraserburghon 10 September 1999

Lomur - grounding of Lomur in the approaches to Scalloway, Shetland Islands 14 June 2001

Lord Trenchard - explosion on board vessel in Poole Harbour on 30June 1999

Luc and Toisa Puffin - collision between the two vessels 8.5 milesdue east of the river Tyne on 13 June 1999

Lysfoss - grounding of Lysfoss in Sound of Mull, Scotland 7 May2001

Mariama K - carbon monoxide poisoning on vessel in Douarnenez, France 10 June 2000 - one fatality

Mathilda and Lady Hamilton of Helford - near miss incidentbetween Mathilda and Lady Hamilton of Helford, 7 miles eastsouth-east of Lizard Point, Cornwall on 28 June 2001

Opportune - man overboard fatality from mfv Opportune 35 mileseast of Wick on 23 February 2000

Osprey - fatal accident to a man overboard from the fishing vesselOsprey in Lochinver Harbour on 20 April 2002

Our Nicholas - grounding and loss of the crabber Our Nicholasnear the entrance to Stornoway Harbour on 24 July 2001

Our Sarah Jayne/Thelisis - collision between vessels in the ThamesEstuary 20 June 2001

Pescalanza - sinking of the fishing vessel with the loss of sixlives on 2 November 1998

Philomena - fatal accident on board vessel in the Moray Firthon 6 March 2001

Primrose - grounding of Primrose on the Island of Rhum on 15June 2001

Purbeck II - injury of crew member on board on 7 June 1999

Purdy - man overboard fatality from angling boat at ShipwashBank off Harwich, on 17July 1999

Rachel Harvey - grounding and loss of fishing vessel offPeninnis Head on 1 October 1999

Radiant - capsize and foundering of Radiant PD298 about 45miles north-west of the Isle of Lewis with the loss of one life on10 April 2002

Radiant Star III - foundering of fishing vessel 60 miles northeast of Fraserburgh on 6 August 1999

Random Harvest - flooding of fv south-west of Brighton on 3July 1999

Rebecca Kay - loss of fishing vessel Rebecca Kay on 20 April2001 off Bideford Bar Buoy

Resplendent - grounding of Resplendent in Bluemull SoundShetland Islands 13 June 2001

Ross Alcedo - fire on board vessel while underway about 32miles north-west of the Isles of Scilly on 16 January 2000

Sally Jane - capsize alongside in Shoreham Harbour on 27 July1998

mv Sand Heron and fv Celtit - collision between vessels NETraffic Lane, Dover TSS on 30 July 2001

Sharona - flooding and foundering of fishing vessel 80 milesnorth-east of Peterhead on 3 August 1999

Silvery Sea/Merkur - collision between Merkur/Silvery Seawhich then foundered about 35 miles west of Esbjerg, Denmarkwith the loss of five lives 14 June 1998

Solstice II - investigation of a fatal accident to a crew member,25 miles south-west of Rockall 13 May 2000

Sundance - capsize and foundering of Sundance off GilkickerPoint, East Solent with the loss of one life 10 September 2001

Suzanne - see Elm

Tullaghmurry Lass - sinking of fishing vessel Tullaghmurry Lasswith loss of three lives in the Irish Sea on 14 February 2002

Union Arbo/Philomena - collision between Bahamian cargoship Union Arbo and UK fv Philomena about 10 miles south of Newlyn, Cornwall on 2 September 1999

Van Dijck - loss overboard of a fisherman from fishing vesselwhile fishing 30 miles south-west of Guernsey on 16 April 2001

Vertrauen - investigation of the loss of Vertrauen about 75miles north-east of Peterhead 19 July 2001

Wakil II - investigation of an accident to skipper of fv 3.5 milessouth-west of St Bees Head on 10 April 2000

SAFETY DIGEST

MAIB Safety Digest 1/2002 - Published April 2002

MAIB Safety Digest 2/2002 - Published August 2002

MAIB Safety Digest 3/2002 - Published December 2002

Copies of the Safety Digest publication can be obtained, free of charge, on application to the Marine AccidentInvestigation Branch (Mrs J Blackbourn (023 8039 5509)).

GLOSSARY of abbreviations

BEAmer Bureau Enquêtes Accidents/mer

CNIS Channel Navigation Information Service

CPA Closest Point of Approach

EPIRB Emergency Position Indicating Radio Beacon

GMDSS Global Maritime Distress Safety System

OOW Officer of the Watch

Pan Pan Urgency Call

TSS Traffic Separation Scheme

VHF Very High Frequency

MAIB Safety Digest/Report Request Form
Name:
Address:
Please place me on your mailing list to receive the MAIB Safety Digest
Number of copies of Safety Digest you wish to receive
MAIB PUBLISHED REPORTS - free of charge
I wish to receive copies of the following reports from the list onpage 28:
Please detach and return this form to: Geoff Ball, MAIB, First Floor, Carlton House, Carlton Place, SOUTHAMPTON SO15 2DZOr e-mail us at: maib@dft.gsi.gov.uk