G-XALZ AAIB Bulletin: 10/2018 EW/G2018/06/23 ACCIDENT Aircraft Type and Registration: Rans S6S-116 Super Six Coyote II, G-XALZ No & Type of Engines: 1 Rotax 912ULS piston engine Year of Manufacture: 2010 (Serial no: PFA 204A-14378) Date & Time (UTC): 25 June 2018 at 1615 hrs Location: Fishburn Airfield, County Durham Type of Flight: Training Persons on Board: Crew - 1 Passengers - 1 Injuries: Crew - None Passengers - None Nature of Damage: Left landing gear sheared off, left wing tip rippled, two propeller blades fractured Commander's Licence: Light Aircraft Pilot's Licence Commander's Age: 75 years 594 hours (of which 40 were on type) **Commander's Flying Experience:** Last 90 days - 2 hours Last 28 days - 2 hours Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot had not flown for several weeks and was flying with a local instructor for some circuit practise. After completing several circuits, the aircraft was on short finals to Runway 08 when the right wing dropped. The pilot corrected the wing-drop and applied power, but the left wing then dropped and the aircraft sank before the pilot could take corrective action. The aircraft touched down just before the beginning of the runway. The left wheel caught on a slight rise and the left landing gear leg broke away. The aircraft continued to slide with the left wingtip on the ground before coming to rest at 90° to the runway centre line, approximately 10 m along the runway. Both occupants were uninjured.

The runway at Fishburn has a significant slope with the threshold of Runway 08 being at the top of the slope. With the wind from the east, the approach can be affected by turbulence and rotor¹ effects. Both the pilot and instructor felt that G-XALZ may have been affected by this turbulence. The pilot commented that he could have made his approach higher as this would have given him more time to react to any turbulence.

Footnote

¹ Rotor: local air mass rotating about a substantially horizontal axis.