

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Mainair Blade 912, G-BZNS	
<b>No &amp; Type of Engines:</b>	1 Rotax 912UL piston engine	
<b>Year of Manufacture:</b>	2001 (Serial no: 1263-1000-7-W1057)	
<b>Date &amp; Time (UTC):</b>	17 September 2020 at 1530 hrs	
<b>Location:</b>	Athey's Moor Airfield, Northumberland	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - None
<b>Injuries:</b>	Crew - None	Passengers - N/A
<b>Nature of Damage:</b>	Damaged beyond economic repair	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	48 years	
<b>Commander's Flying Experience:</b>	85 hours (of which 55 were on type) Last 90 days - 41 hours Last 28 days - 19 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB	

**Synopsis**

The right drag link connection failed while the aircraft was taxiing, causing the landing gear to rotate backwards and the propeller to partially sever the landing gear struts. The BMAA published an article in their December 2020 *Microlight Flying* magazine reminding owners to check drag link connections carefully during pre-flight checks.

**History of the flight**

After returning from a visit to East Fortune Airfield in Scotland, the pilot landed on Runway 14 without incident. He backtracked along the runway towards the airfield hangar. As he cleared the runway, travelling at approximately 5 mph, the right main landing gear collapsed. The landing gear rotated rearwards into the arc of the rotating propeller which partially sliced through the landing gear struts and spat (Figure 1).

Visual inspection revealed the right drag link bar ear connection to the fuselage pod had failed. Cracks were also found on the left drag link bar ear connection, (Figure 2).

The front drag link assembly is designed to allow movement of the rear suspension around the mounting bolt and to enable changes in the landing gear geometry when the trike unit is folded. Checking the security of drag links is a pre-flight check in Section 6 of the Mainair Blade 912 aircraft manual.


## Aircraft examination



**Figure 1**

G-BZNS showing collapsed right landing gear and damage caused by propeller

A BMAA article by Roger Patrick (2020) 'Now see ear', *Microlight Flying*, December 2020 briefly describes this incident and reminds owners to check the drag link connections carefully during their pre-flight checks.



**Figure 2**

Left drag link ear connection showing cracks and the failed right drag link ear connection