

**TO REPORT AN ACCIDENT OR INCIDENT  
PLEASE CALL OUR 24 HOUR REPORTING LINE**

**01252 512299**

Air Accidents Investigation Branch  
Farnborough House  
Berkshire Copse Road  
Aldershot  
Hants GU11 2HH

Tel: 01252 510300  
Fax: 01252 376999  
Press enquiries: 0207 944 3118/4292  
<http://www.aaib.gov.uk>

*AAIB investigations are conducted in accordance with Annex 13 to the ICAO Convention on International Civil Aviation, EU Regulation No 996/2010 and The Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 1996.*

*The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability.*

*Accordingly, it is inappropriate that AAIB reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.*

AAIB Bulletins and Reports are available on the Internet  
<http://www.aaib.gov.uk>

This bulletin contains facts which have been determined up to the time of compilation.

Extracts may be published without specific permission providing that the source is duly acknowledged, the material is reproduced accurately and it is not used in a derogatory manner or in a misleading context.

Published 13 October 2016

Cover picture courtesy of Stephen R Lynn  
([www.srllynphotography.co.uk](http://www.srllynphotography.co.uk))

© Crown copyright 2016

ISSN 0309-4278

Published by the Air Accidents Investigation Branch, Department for Transport  
Printed in the UK on paper containing at least 75% recycled fibre

**CONTENTS****SPECIAL BULLETINS / INTERIM REPORTS**

None

**SUMMARIES OF AIRCRAFT ACCIDENT ('FORMAL') REPORTS****Aircraft Accident Report No: 2/2016**

Saab 2000	G-LGNO	15-Dec-14	3
-----------	--------	-----------	---

**AAIB FIELD INVESTIGATIONS****COMMERCIAL AIR TRANSPORT****FIXED WING**

Beech B200 Super King Air	G-BYCP	03-Oct-15	11
Boeing 747-436	G-CIVX	30-Jan-16	44

**ROTORCRAFT**

None

**GENERAL AVIATION****FIXED WING**

None

**ROTORCRAFT**

None

**SPORT AVIATION / BALLOONS**

None

**AAIB CORRESPONDENCE INVESTIGATIONS****COMMERCIAL AIR TRANSPORT**

None

**GENERAL AVIATION**

Bell 206B Jet Ranger II	G-OAMI	10-Feb-16	51
De Havilland DH82A Tiger Moth	G-AMCK	13-May-16	52
Miles M38 Messenger 4B	G-AKVZ	19-Jul-16	53
Pioneer 300	G-VOLO	24-Apr-16	54
Piper PA-28-161 Cherokee Warrior II	G-BNXE	19-Apr-16	56

**SPORT AVIATION / BALLOONS**

EV-97 Teameurostar UK	G-SHMI	25-Jun-16	57
Ikarus C42 FB80	G-SFLA	13-May-16	58
Pegasus Quantum 15-912	G-BZYN	15-May-16	59

## CONTENTS Cont

### AAIB CORRESPONDENCE INVESTIGATIONS Cont

#### SPORT AVIATION / BALLOONS Cont

Pegasus Quik	G-CCOW	31-Jul-16	60
Pegasus Quik	G-OKEM	20-Jun-16	61
Rans S6-ESD Coyote II	G-MYGP	03-Apr-16	62
Savannah VG Jabiru(1)	G-SAVY	08-May-16	63
Tiger Cub 440	G-MMIH	05-Jun-16	66
X'air Hawk	G-CEON	10-Apr-16	68

### MISCELLANEOUS

#### ADDENDA and CORRECTIONS

None

List of recent aircraft accident reports issued by the AAIB 71

**(ALL TIMES IN THIS BULLETIN ARE UTC)**

## **Summaries of Aircraft Accident Reports**

This section contains summaries of  
Aircraft Accident ('Formal') Reports  
published since the last AAIB monthly bulletin.

The complete reports can be downloaded from  
the AAIB website ([www.aaib.gov.uk](http://www.aaib.gov.uk)).



**Aircraft Accident Report No: 2/2016**

*This report was published on 6 September 2016 and is available in full on the AAIB Website*

**Report on the serious incident to  
Saab 2000, G-LGNO  
Approximately 7 nm east of Sumburgh Airport, Shetland  
15 December 2014**

<b>Registered Owner and Operator:</b>	Loganair Ltd
<b>Aircraft Type:</b>	Saab AB Saab 2000
<b>Nationality:</b>	British
<b>Registration:</b>	G-LGNO
<b>Place of Serious Incident:</b>	Approximately 7 nm east of Sumburgh Airport, Shetland Latitude: N 59° 52' 56" Longitude: W 001° 05' 07"
<b>Date and Time:</b>	15 December 2014 at 1910 hrs All times in this report are UTC

**Summary**

The aircraft was inbound to land on Runway 27 at Sumburgh when the pilots discontinued the approach because of weather to the west of the airport. As the aircraft established on a southerly heading, it was struck by lightning. When the commander made nose-up pitch inputs the aircraft did not respond as he expected. After reaching 4,000 ft amsl the aircraft pitched to a minimum of 19° nose down and exceeded the applicable maximum operating speed ( $V_{MO}$ ) by 80 kt, with a peak descent rate of 9,500 ft/min. The aircraft started to climb after reaching a minimum height of 1,100 ft above sea level.

Recorded data showed that the autopilot had remained engaged, contrary to the pilots' understanding, and the pilots' nose-up pitch inputs were countered by the autopilot pitch trim function, which made a nose-down pitch trim input in order to regain the selected altitude.

Five Safety Recommendations are made relating to the design of the autopilot system and the certification requirements for autopilot systems.

**Conclusions**

During the approach phase of a routine flight the aircraft was struck by triggered lightning. Procedures intended to prevent flight in areas where lightning may be encountered do not protect against triggered strikes. The lightning caused only minor damage to the aircraft's radome and APU exhaust. Functional tests after the flight, and inspections of the elevator control system and autopilot system, did not reveal any faults.

Evidence from the manufacturer's simulation work indicated that the aircraft had responded as expected to the recorded control deflections.

The commander's actions following the lightning strike were to make manual inputs on the flying controls, which appear to have been instinctive and may have been based on his assumption that the autopilot would disconnect when lightning struck. However, the autopilot did not disconnect and was attempting to maintain a target altitude of 2,000 ft amsl by trimming nose-down while the commander was making nose-up pitch inputs. The control forces felt by the commander were higher than normal because the autopilot was opposing his inputs and he may have attributed this to a flight control malfunction caused by the lightning strike. He did not recall having seen or heard any of the aural or visual mistrim cautions which were a cue that the autopilot was still engaged. This was probably the result of cognitive tunnelling.

The commander applied and maintained full aft control column (nose-up elevator) input; however, the autopilot's nose-down elevator trim authority exceeded the commander's elevator nose-up authority and the aircraft pitched nose-down and descended, reaching a peak descent rate of 9,500 ft/min. The autopilot then disengaged due to an ADC fault and this allowed the commander's noseup pitch trim inputs to become effective. The aircraft started to pitch up just before reaching a minimum height of 1,100 ft above sea level.

If the autopilot system had been designed to sense pilot applied control forces and to disengage when it sensed a significant force (about 25 lbf according to FAAAC 25.1329-1C), the autopilot would have disengaged shortly after the aircraft climbed above 2,000 ft, in response to the aft column inputs applied by the commander. This would have prevented the subsequent loss of control. If the autopilot system had been designed such that operating the pitch trim switches resulted in autopilot disengagement, the autopilot would also have disengaged early in the sequence of events.

Of 22 airliner types surveyed, the Saab 2000 was the only type that had an autopilot which, when engaged, had the following three attributes:

*Applying an override force to the column will move the elevator but will not cause the autopilot to disengage*

*The autopilot can trim in the opposite direction to the pilot applied control column input*

*Pressing the main pitch trim switches has no effect and will not cause the autopilot to disengage*

The Airbus A300 and Fokker 70/100 aircraft previously had such attributes, and suffered one accident (A300) and several incidents (Fokker 70/100) due to pilots overriding the autopilot; these resulted in autopilot redesigns on both aircraft types.

In order to help prevent a similar recurrence of a loss of control due to autopilot override on the Saab 2000 and other aircraft types, five Safety Recommendations are made.



## Safety Recommendations and safety action

### *Safety Recommendations*

#### **Safety Recommendation 2016-050**

It is recommended that the European Aviation Safety Agency review the design of the Saab 2000 autopilot system and require modification to ensure that the autopilot does not create a potential hazard when the flight crew applies an override force to the flight controls.

#### **Safety Recommendation 2016-051**

It is recommended that the European Aviation Safety Agency review the autopilot system designs of aircraft certified under Part 25 or equivalent regulations and require modification if necessary to ensure that the autopilot does not create a potential hazard when the flight crew applies an override force to the flight controls.

#### **Safety Recommendation 2016-052**

It is recommended that the Federal Aviation Administration review the autopilot system designs of aeroplanes certificated to Federal Aviation Regulation Part 25 and require modification if necessary to ensure that the autopilot does not create a potential hazard when the flight crew applies an override force to the flight controls.

#### **Safety Recommendation 2016-053**

It is recommended that the Federal Aviation Administration amend Advisory Circular 25.1329-1C to ensure that requirement 25.1329(I) can only be met if the autopilot automatically disengages when the flight crew applies a significant override force to the flight controls and the auto-trim system does not oppose the flight crew's inputs.

#### **Safety Recommendation 2016-054**

It is recommended that the European Aviation Safety Agency amend the Acceptable Means of Compliance for Certification Specification 25.1329 to ensure that requirement 25.1329(I) can only be met if the autopilot automatically disengages when the flight crew applies a significant override force to the flight controls and the auto-trim system does not oppose the flight crew's inputs.

### *Safety action*

The AAIB published Special Bulletin S1/2015 on 2 March 2015 which provided the initial facts of this investigation and reported safety action taken by the aircraft manufacturer and the operator.

### Safety action by the aircraft manufacturer

On 24 February 2015 the aircraft manufacturer published Operations Newsletter No.6, informing Saab 2000 operators of the circumstances of this serious incident, and clarifying the operation of the autopilot as follows:

#### ***'Autopilot operation***

##### *Autopilot disengage:*

*Manual control inputs will not cause the autopilot to disengage and the main trim switches are disabled when the autopilot is engaged. Consequently, operation of the main pitch trim switches will not have any effect on aircraft trim nor cause the autopilot to disengage.*

*Disengaging the autopilot is normally done by pushing the disconnect button on either control wheel.*

*Manual activation of the following will also cause the autopilot to disengage:*

- Autopilot engage/disengage lever*
- Go-around button*
- The standby pitch trim switches*

*Autopilot disengage will trigger disengage warning (cavalry charge). The autopilot disengage warning is cleared by a push of the autopilot disconnect button located on the control wheel.*

##### *Autopilot mistrim*

*Conflicting manual control column inputs with the autopilot engaged will cause the autopilot trim to occur in the opposite direction of the control input, causing a mistrim situation. This will result in a "P" for pitch and/or "R" for roll appearing on the Primary Flight Display. If the situation is maintained, an AP PITCH MISTRIM or AP ROLL MISTRIM caution message will appear on the EICAS1 with associated flashing amber Master Caution light and a single aural chime. The autopilot will remain engaged.'*

### Safety action by the operator

The operator put in place a number of *'Mitigations to prevent an unsafe condition occurring when a pilot inadvertently applies an override force to the flight controls'*. It provided a description of these measures as follows:

#### *'1. Notice to Aircrew (NOTAC)*

*NOTAC 123/14 was issued to all [the operator's] SAAB 2000 pilots on 23rd December 2014 advising to ensure that the autopilot is disconnected in the event of experiencing control abnormalities:*

### *Background*

*The Saab 2000 autopilot does not disconnect when overpowered or when the control wheel pitch trim switches are operated. If the autopilot is engaged and the autopilot is overpowered it is possible to fly the aircraft and not be aware that the autopilot is engaged. However, in this situation, the autopilot pitch trim will operate to compensate for pilot input and can lead to increased control forces.*

### *Action*

*In the event that increased control forces are experienced, pilots should ensure that the autopilot is disengaged.*

### *2. Pilot Briefings*

*On the 19th December 2014 all SAAB 2000 pilots received a briefing on the incident. These briefings were either face-to-face or via telephone and included the reasons behind the NOTAC.*

### *3. Operator Conversion Training*

*Following Type Rating Training all pilots new to the SAAB 2000 undergo 8 hours of simulator conversion training on [the operator's] procedures. All pilots are now exposed to this condition in the simulator and the corrective action required.*

### *4. Triennial Training*

*All SAAB 2000 pilots are to be exposed to this condition and the corrective actions required in the simulator during recurrent training on a three yearly cycle.*

### *5. Revision to Autopilot Standard Operating Procedures (SOPs)*

*At any time the autopilot disconnects automatically or manually*

*Pilot Flying – Presses autopilot disconnect button (Even if disengagement has been automatic) and announces “Autopilot Disconnect”*

*Pilot Monitoring- Confirms autopilot has disconnected by checking autopilot engagement indication and switches/paddles and announces “Autopilot disconnect”*




## **AAIB Field Investigation Reports**

A Field Investigation is an independent investigation in which AAIB investigators collect, record and analyse evidence.

The process may include, attending the scene of the accident or serious incident; interviewing witnesses; reviewing documents, procedures and practices; examining aircraft wreckage or components; and analysing recorded data.

The investigation, which can take a number of months to complete, will conclude with a published report.



**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Beech B200 Super King Air, G-BYCP	
<b>No &amp; Type of Engines:</b>	2 Pratt & Whitney Canada PT6A-42 turboprop engines	
<b>Year of Manufacture:</b>	1981 (Serial no: BB-966)	
<b>Date &amp; Time (UTC):</b>	3 October 2015 at 0920 hrs	
<b>Location:</b>	Near Chigwell, Essex	
<b>Type of Flight:</b>	Non-commercial	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - 1 (Fatal)	Passengers - 1 (Fatal)
<b>Nature of Damage:</b>	Aircraft destroyed	
<b>Commander's Licence:</b>	Commercial Pilot's Licence	
<b>Commander's Age:</b>	40 years	
<b>Commander's Flying Experience:</b>	1,941 hours (of which 162 hours were on type) Last 90 days - 61 hours Last 28 days - 50 hours	
<b>Information Source:</b>	AAIB Field Investigation	

**Synopsis**

The aircraft was climbing through approximately 750 ft amsl after takeoff when it began to turn right. It continued to climb in the turn until it reached approximately 875 ft amsl when it began to descend. The descent continued until the aircraft struck some trees at the edge of a field, approximately 1.8 nm southwest of the aerodrome. The evidence available was consistent with a loss of aircraft control in Instrument Meteorological Conditions (IMC), but this could not be concluded unequivocally because of a lack of evidence from within the cockpit. However, it is possible the pilot became incapacitated and the additional crew member was unable to recover the aircraft in the height available.

Three Safety Recommendations are made regarding the fitment of Terrain Awareness and Warning Systems (TAWS).

**History of the flight**

G-BYCP was planned to operate a non-commercial flight from Stapleford Aerodrome to RAF Brize Norton with two company employees on board (including the pilot) to pick up two passengers for onward travel. The pilot (the aircraft commander) held a Commercial Pilot's Licence (CPL) and occupied the left seat and another pilot, who held an Airline Transport Pilot's Licence (ATPL), occupied the right. The second occupant worked for the operator of G-BYCP but his licence was valid on Bombardier Challenger 300 and Embraer ERJ 135/145 aircraft and not on the King Air.

The pilot reported for work at approximately 0715 hrs for a planned departure at 0815 hrs but he delayed the flight because of poor meteorological visibility. The general weather conditions were fog and low cloud with a calm wind. At approximately 0850 hrs the visibility was judged to be approximately 600 m, based on the known distance from the operations room to a feature on the aerodrome (Figure 1). At approximately 0915 hrs, trees were visible just beyond the end of Runway 22L, indicating that visibility was at least 1,000 m and the pilot decided that conditions were suitable for departure.



**Figure 1**

Measurement of visibility at the departure aerodrome

At 0908 hrs, the pilot called the en-route Air Navigation Service Provider (ANSP) on his mobile phone to ask for a departure clearance. He was instructed to remain clear of controlled airspace when airborne and call London Tactical Control Northeast (TCNE) on 118.825 MHz. The planned departure was to turn right after takeoff and intercept the 128° radial from Brookman's Park VOR (BPK) heading towards the beacon, and climb to a maximum altitude of 2,400 ft amsl to remain below the London TMA<sup>1</sup> which has a lower limit of 2,500 ft amsl (Figure 2). The aircraft took off at 0921 hrs and was observed climbing in a wings level attitude until it faded from view shortly after takeoff.

---

**Footnote**

<sup>1</sup> Terminal Control Area.

---





**Figure 2**

Approximate planned departure track and local airspace

After takeoff, the aircraft climbed on a track of approximately 205°M and, when passing approximately 750 ft amsl (565 ft aal), began to turn right. The aircraft continued to climb in the turn until it reached 875 ft amsl (690 ft aal) when it began to descend. The descent continued until the aircraft struck some trees at the edge of a field approximately 1.8 nm southwest of the aerodrome (Figure 3). The pilot and passenger were both fatally injured in the accident, which was not survivable.

A secondary radar return, thought to be G-BYCP, was observed briefly near Stapleford Aerodrome by London ATC but no radio transmission was received from the aircraft.

A witness was walking approximately 30 m north-east of where the aircraft struck the trees. She suddenly heard the aircraft, turned towards the sound and saw the aircraft in a nose-down attitude fly into the trees. Although she saw the aircraft only briefly, she saw clearly that the right wing was slightly low, and that the aircraft appeared to be intact and was not on fire. She also stated that the aircraft was “not falling” but flew “full pelt” into the ground.



**Figure 3**

Initial track and wreckage trail

### Recorded data

Radar data was available from four installations, at Heathrow, Debden, Stansted and Bovingdon, which provided coverage of the flight for 25 seconds. The data showed that the aircraft climbed to 875 ft amsl<sup>2</sup>, at a climb rate which averaged 1,500 ft/min. Whilst in this climb, the departure track passed a mast situated 1.5 nm from the start of Runway 22L, the elevation of which is 480 ft amsl. At this point, the aircraft was at 800 ft amsl and had started to turn right. Having reached 875 ft amsl (655 ft above ground level at the accident site<sup>3</sup>), the aircraft began to descend with an increasing rate reaching in excess of 7,000 ft/min. Two of the radar installations, at Debden and Bovingdon, showed that the aircraft's groundspeed<sup>4</sup> increased over the 15 seconds of available data, the acceleration increasing as the flightpath transitioned into a descent. A final groundspeed of 188 kt was recorded before radar coverage ended at approximately 230 ft agl.

### Footnote

<sup>2</sup> All aircraft altitudes are as reported by the aircraft's transponder, corrected to amsl using 1016 hPa as the regional pressure setting.


<sup>3</sup> In this section, aircraft heights above ground level (agl) refer to the vertical distance above the accident site.

<sup>4</sup> All aircraft groundspeeds are as reported by the aircraft's transponder and received by Mode S radar installations.

Ground tracks from the four radar installations are shown in Figure 4. Figure 5 shows the altitude and groundspeed values transmitted by the aircraft plotted against time. In the case of altitude, the values have been corrected for the regional pressure setting. In the upper half of Figure 5, the altitude trace, which shows merged altitude data from each radar installation, was used to derive the vertical speed trace.



**Figure 4**  
Ground track data



**Figure 5**  
Flight parameters

### Aircraft information

The B200 King Air is a low-wing, twin-engined aircraft with seating for up to nine passengers in a pressurised cabin. The aircraft is approved for operation by a single pilot, or by two pilots. It is powered by two turboprop engines, each driving a three-bladed, hydraulically operated constant-speed propeller with full feathering and reversing capability. G-BYCP was manufactured in 1981 and acquired by the operator in 2002. It had accumulated 14,493 flight hours and 12,222 flight cycles in service since manufacture. The aircraft was not fitted with a CVR, FDR or TAWS<sup>5</sup> equipment and was not required to be so, in accordance with relevant airworthiness and operational regulations.

### Footnote

<sup>5</sup> Terrain Awareness and Warning Systems (TAWS) are discussed in later sections.

## Accident site

The accident site was located in an area of open farmland 1.8 nm southwest of Stapleford Aerodrome, at an elevation of 220 ft amsl. The aircraft had struck a line of oak trees in a shallow pitch attitude and at high speed, causing the aircraft to break up into a large number of fragments and distributing the wreckage along a trail approximately 300 m in length, oriented on a heading of 290°M. Measurement of the angle of strikes to the tree line indicated that the aircraft had impacted with a roll attitude of approximately 12° right wing low. There was a strong smell of unburned fuel within the debris trail and scorching of wreckage lying on the field surface indicated that an intense, short-duration, fuel fire had occurred shortly after the aircraft had struck the trees. All major components of the aircraft were identified at the accident site, prior to wreckage recovery.



**Figure 6**

Aerial view of the accident site, looking south-east

A large section of the aircraft's fuselage, from the cockpit rearwards to the vertical fin, was located in a hedge line some 170 m from the initial impact point, and had been severely damaged by a post-accident fire. The only other large item of wreckage was a section of the left inboard wing, nacelle and engine which was found in the same hedge line as the fuselage, approximately 200 m from the initial impact point. This item of wreckage was also severely damaged by a prolonged post-accident fire.

The cockpit-mounted engine and propeller controls were recorded photographically in-situ at the accident site prior to the wreckage recovery, but deformation of the cockpit structure and subsequent fire damage meant that it was not possible to determine their pre-impact positions. Components from the cabin entry door were identified within the wreckage but it was not possible to establish the condition of the door at impact due to subsequent fire damage.

The right engine had been released from the aircraft at the initial impact with the trees and had subsequently broken apart. Both the left and right propellers had detached from their respective engines during the accident and were found lying on the field surface.

The left propeller had detached forward of the hub mounting flange and all three blades remained attached to the hub; the blades were bent backwards and the propeller tips had detached.

The right propeller remained attached to the right engine reduction gearbox, which had separated from the right engine. Two of the right propeller's blades remained attached to the hub and these blades were bent, one forwards and one backwards, and the tips had detached. The third blade had broken off at the root end and was located within the debris field. This blade was bent backwards and the tip had detached.

### **Wreckage examination**

The wreckage was recovered to the AAIB's facility at Farnborough. The high degree of fragmentation and fire damage to the aircraft's structure and systems prevented a complete evaluation but that which remained was subject to a detailed and prolonged examination.

#### *Engines*

Both engines were dismantled and inspected with the assistance of a technical specialist from the engine manufacturer. No evidence of a pre-impact failure was found and internal witness marks, caused by contact between the engine's rotating and static components during the accident, were consistent with both engines producing medium to high power at the moment of impact. There were no conditions observed of any of the engine components examined that would have precluded normal engine operation prior to impact.

#### *Propellers*

The aircraft's propellers were examined with the assistance of a technical specialist from the propeller manufacturer. Both propellers exhibited significant blade bending and tip fractures consistent with rotation under power at or near rated<sup>6</sup> rpm at impact. There were no discrepancies noted that would prevent or degrade normal operation prior to impact, and all observed damage was consistent with high impact forces.

#### *Flying controls*

The aircraft wreckage was examined with the assistance of a technical specialist from the aircraft manufacturer. Detailed examination of the aircraft's primary flying control systems, from the cockpit mounted yoke and rudder pedal control assemblies out to the respective flying control surfaces, did not reveal any evidence of a pre-accident flying control system failure. It was, however, not possible to eliminate the possibility of a pre-accident control restriction or jam due to the impact-related disruption of the aircraft's

---

#### **Footnote**

<sup>6</sup> The B200's PT6A-42 engines feature a propeller control system that governs the propellers to 2,000 rpm during flight.

structure. All observed discontinuities in the primary flying controls were attributable to tensile or bending overload, or to cuts made during the wreckage recovery.

The control surface trim actuators were examined, but due to the nature of the aircraft break-up and the fact that the trim systems were cable operated, it was not possible to determine accurately their positions at the moment of impact.

### *Flap system*

The flaps, two on each wing, are driven by an electric motor through a gearbox mounted on the wing rear spar at the fuselage centreline. The gearbox drives four flexible drive cables that are connected to a jackscrew actuator at each flap. A safety mechanism, consisting of a torque tube, cam and microswitch, is provided for each pair of flaps to disconnect power to the electric motor in the event of a failure that causes any flap to be approximately 3°- 6° in misalignment with its adjacent flap.

Components from the aircraft's flap drive system were recovered and examined in detail. Three of the four flap jackscrews were found to be in the flap retracted position whereas the fourth jackscrew, established by part number as the left inboard flap actuator, was found in the fully extended 100% (35°) position. The left inboard flexible flap drive cable, from the flap motor gearbox outboard, was examined, apart from a missing section approximately 8 cm in length from the outboard end which was not recovered. No mechanical defect or failure was found in the flap drive cable, or of the left inboard jackscrew itself, that could account for the difference in position to the other three flap jackscrews. Remnants of the left and right asymmetric flap protection system components were recovered from the wreckage but they were too badly damaged by fire to draw any conclusions about their pre-accident condition.

The cockpit flap position indicator, which is driven by the position of the right inboard flap, showed that the needle was pointing to a position consistent with electrical power switched off, or removed, during the aircraft break-up sequence.

### *Landing gear*

The extensions of the landing gear mechanical actuators for all three landing gear legs were consistent with the landing gear being retracted at the point of impact.

### *Instruments*

The captain's primary and standby attitude indicators were recovered from the debris field and examined. The primary attitude indicator had sustained damage, preventing electrical or functional testing. Conclusions on the pitch and roll attitude displayed at impact were based solely on a physical examination performed at the manufacturer's overhaul facility, under supervision of the AAIB. The GYRO and GS (glideslope) flags were found in their retracted positions, and the flight director command bars were not fully retracted up; these three findings indicated that the attitude indicator was electrically powered at impact and that no fault had occurred that would have caused the GYRO fail flag to display. The roll index gear, which rotates the instrument's roll indicator pointer to present roll attitude, was pinned in four places around the gear due to impact forces, with a 12° right roll attitude displayed.

Analysis of debris puncture marks through the Mylar pitch attitude tape showed that the pitch attitude displayed at impact was approximately  $-5^{\circ}$  to  $-9^{\circ}$  (nose down). Each of these pitch and roll readings was consistent with the tree strikes and wreckage distribution noted at the accident site.

The captain's standby attitude indicator was examined, but the degree of damage sustained in the accident prevented its functional testing or an assessment of the pitch and roll reading at impact. There were clear signs of scoring on the surface of the instrument's gyro rotor, indicating that the gyro was turning at high speed at impact. The attitude indicator's OFF flag was relatively un-deformed, indicating that it was probably not deployed at impact.

Components from the co-pilot's air-driven attitude indicator were identified in the wreckage but the degree of fragmentation of this instrument prevented an assessment of the attitude it displayed at impact.

### *Warning lamps*

Fourteen lamp bulb units from various cockpit annunciator panels were recovered in a sufficiently intact condition to permit examination of their bulb filaments for evidence of 'hot stretch', which can indicate if a bulb was lit at impact. Examination of these recovered light bulbs showed that two annunciators were probably lit at impact; the amber MSG and green NAV annunciators from the panel above the primary attitude indicator. The MSG annunciator was alerting the pilot to a message being displayed on one of the GNS430W GPS units fitted to the aircraft but no evidence was available to indicate what message was being displayed. The NAV annunciator indicated that the GPS was operating in VOR mode.

### **Maintenance**

The aircraft's last scheduled maintenance inspection<sup>7</sup> was carried out on 12 June 2015 at 14,289.5 hours and 12,049 flight cycles. The aircraft's Airworthiness Review Certificate was renewed on 21 January 2015 and was valid at the time of the accident. The aircraft's technical records were examined which showed that all life-limited components installed were within their permitted service lives at the time of the accident, and all Airworthiness Directives applicable to the aircraft had been complied with.

### *Technical Log entries*

The aircraft's technical log was examined and contained no deferred defects prior to the accident flight. During the course of the investigation the AAIB became aware of a post-flight '*Engineering Report*' email reporting system used by the operator to permit flight crew to communicate operational information to the operator. The '*Engineering Report*' emails also contained aircraft technical defects that were not recorded in the aircraft technical log or aircraft maintenance records.

---

### **Footnote**

<sup>7</sup> This inspection was a '*Phase 1*' inspection, one of a number of periodic inspections required by the aircraft's Approved Maintenance Programme.



The aircraft was subject to maintenance regulations as defined in EASA Part M. Part M regulation M.A.403 refers to the recording of aircraft defects:

### **M.A.403 Aircraft defects**

- (a) Any aircraft defect that hazards seriously the flight safety shall be rectified before further flight.
- (b) Only the authorised certifying staff, according to points M.A.801(b)1, M.A.801(b)2, M.A.801(c), M.A.801(d) or Annex II (Part-145) can decide, using M.A.401 maintenance data, whether an aircraft defect hazards seriously the flight safety and therefore decide when and which rectification action shall be taken before further flight and which defect rectification can be deferred. However, this does not apply when:
  - 1. the approved minimum equipment list as mandated by the competent authority is used by the pilot; or,
  - 2. aircraft defects are defined as being acceptable by the competent authority.
- (c) Any aircraft defect that would not hazard seriously the flight safety shall be rectified as soon as practicable, after the date the aircraft defect was first identified and within any limits specified in the maintenance data.
- (d) Any defect not rectified before flight shall be recorded in the M.A.305 aircraft maintenance record system or M.A.306 operator's technical log system as applicable.

The post-flight '*Engineering Report*' emails for the nine months preceding the accident were reviewed. A total of 57 defects were recorded in this period that either met the definition of M.A.403(a), or were subject to a rectification interval specified in the B200 Minimum Equipment List (MEL) as required by M.A.403(c). None of these defects were recorded in the aircraft technical log, or the aircraft maintenance records, as required by M.A.403(d). Many of the defects were repeat reports over a series of flights and related to items including inoperative fuel gauges, failed autopilot mode annunciator lights, autopilot faults, inaccurate engine oil pressure and rpm indications, reports of the left engine being slow to accelerate, and a missing stall warning strip. There were no defects reported regarding the aircraft's flying controls or flap system.

Aircraft maintenance records documenting the Phase 1 inspection carried out on 12 June 2015 referred to four '*Customer reported defects*' that had been recorded in the '*Engineering Report*' emails, but not in the technical log or aircraft maintenance records. Rectification of three of the four defects required replacement of defective components with newly overhauled parts. The B200 King Air MEL classifies one of the defects as Category B, requiring rectification within three calendar days of discovery, and the remaining three defects as Category C, requiring rectification within ten days of discovery. A review of the '*Engineering Report*' emails showed that the Category B defect had been reported 31 days prior to rectification, and the three Category C defects had been reported 156 days prior to rectification.

In the week preceding the accident flight however, the aircraft had performed six flights and the email reporting system did not contain any significant defects apart from a worn main landing gear tyre. This was correctly recorded in the technical log and the tyre was replaced prior to the next flight.

*Information provided by the aircraft manufacturer*

The aircraft manufacturer confirmed that during type certification flight testing, the B200 had been tested with the right outboard flap fully down at 100% (35°), whilst the other three flaps were fully retracted. In this condition, which is more severe than if just the right inboard flap had been fully deflected, a 27.5 lb control wheel force and 35% aileron deflection were sufficient to maintain lateral control. Aileron trim was sufficient to cancel all out-of-balance rolling moments and full stalls in this configuration were satisfactory.

The aircraft manufacturer also undertook flight performance analysis, based on the accident flight path recorded by secondary radar. The performance analysis included the effects of aircraft mass, aerodynamic drag and engine thrust. The analysis showed that, in order to achieve the recorded flight path, both engines were required to be operating at medium to high power. It was not possible to make any definitive findings regarding the engine power developed at the end of the radar coverage, as the aircraft descended below 600 ft amsl.

**Pilot information**

The pilot had flown 1,941 hours prior to the accident flight of which 1,791 hours were flown in single-engine piston aircraft. He gained a Multi-Engine Piston (MEP) Instrument Rating<sup>8</sup> in October 2009 and was an examiner for the Instrument Meteorological Conditions (IMC) Rating. He obtained his King Air type rating<sup>9</sup> on 17 June 2014 and, in the following 12 months, flew with two operators before being employed by the operator of G-BYCP.

The pilot renewed his King Air type rating on 23 May 2015 and flew approximately 67 hours in the right seat of the operator's King Air aircraft to familiarise himself with the way they were operated. He began his line training with the operator of G-BYCP on 16 August 2015 and passed his line check on 27 September 2015. The operator reported that the weather was generally good during the pilot's line training and he had not been required to fly an IMC departure from Stapleford Aerodrome.

At the time of the accident the pilot had flown 162 hours 15 minutes on type including 6 hours 40 minutes flown as the aircraft commander and 113 hours 5 minutes flown as pilot in command under the supervision of the aircraft commander.

**Medical and pathological information***The pilot*

The pilot held a Class 1 medical certificate valid until 17 December 2015 for single-pilot commercial operations carrying passengers. Medical certificates for such operations are valid for six months for pilots aged 40 and over (the pilot was 40 years old) whereas Class 1 medical certificates for other commercial operations are valid for 12 months. The increased frequency of medical examinations for pilots over 40 is an attempt to reduce the

---

**Footnote**

<sup>8</sup> Valid on multi-engine, single-pilot aircraft.

<sup>9</sup> Valid on Beech 90, 99, 100 and 200 Series aircraft, operating in a single- or multi-pilot role, with Instrument Rating.

likelihood that a pilot will become incapacitated between medical examinations as a result of an undiagnosed condition.

Electrocardiograms (ECG) are performed in aviation medical examinations with the aim of identifying heart disease at an early stage before it can pose a risk of incapacitation during flight. Following the accident a specialist in aviation cardiology reviewed the pilot's previous ECGs and assessed them all to be normal.

The post-mortem examination of the pilot found evidence of an acute dissection of a coronary artery the presence of which indicated that he might have suffered symptoms ranging from impaired consciousness to sudden death. The coronary artery dissection might have occurred spontaneously or have been the result of forces transmitted through the body during the accident sequence, and pathology alone was unable to resolve these opposing possibilities. However, the report stated that:

*'if there is no other cause identified for the crash then it is both possible and plausible that this was the precipitating factor.'*

Acute dissection of a coronary artery is a rare event which can occur spontaneously and is difficult to predict through medical examinations or ECGs.

#### *The additional crew member*

The post-mortem examination of the additional crew member revealed nothing which might have caused the accident and his injuries were consistent with the accident sequence.

The Consultant Forensic Pathologist was asked to compare the pattern of injuries to the hands of the occupants and consider the possibility that the additional crew member was holding the controls at the time of impact. He was provided with images of the control column and throttle quadrant of an aircraft similar to G-BYCP, and was made aware that the impact caused substantially more damage to the right side of the aircraft than the left.

The pathologist cautioned that he would expect the asymmetric nature of damage to the aircraft to be reflected in the injuries to the occupants. Nevertheless, even allowing for such anticipated differences, he was of the opinion that:

*'it is both possible and plausible that the right seat pilot was holding the controls at the time of impact.'*

#### **Meteorology**

The Met Office produced an 'aftercast' of the general synoptic situation at the location and time of the accident. The summary of findings stated:

*'The weather conditions across this part of southern England were generally poor ... with some widespread areas of low cloud and/or fog, with associated very poor visibilities. The top of the fog and/or cloud was generally around 1000-1500 ft [amsl], with little or no cloud above this level.'*

Stapleford Aerodrome does not report its weather conditions but conditions reported at airports nearby at 0920 hrs were:

Stansted (012° from Stapleford at 14 nm): 600 m visibility in fog with sky obscured; temperature 11°C.

Luton (304° at 24 nm): 4,500 m visibility in mist, with 5-7 eighths of cloud at 600 ft aal; temperature 11°C.

London City (203° at 10 nm): 2,100 m visibility in mist with 5-7 eighths of cloud at 200 ft aal; temperature 11°C.

## Departure procedures

### *Check of the flap system*

The operator stated that the flap system would be checked prior to the first flight of the day as follows:

- a. The flaps would be extended to 100% on battery power during the preliminary cockpit procedure and inspected visually during the pilot's 'walk-round' inspection.
- b. The flaps would be retracted before starting engines.
- c. After starting engines, the flaps would be extended to 100% and then retracted to 40% in preparation for departure.

### *Standard departure from the aerodrome*

The operator's Operations Manual Part A (OMA) stated that the minimum visibility for any takeoff in the King Air would be 500 m.

The operator's brief for the aerodrome detailed departure procedures for Runway 22L as follows:

*'Climb straight ahead at Blue Line speed<sup>10</sup> to 800 ft and then initiate a 90 degree or more left or right turn initially, to maintain clear of LCY<sup>11</sup> zone and continue climb to 2,400 ft.'*

The operator stated that pilots departing the aerodrome would call London ATC on the telephone to obtain a departure clearance when they were ready to start engines. They would turn left after takeoff onto a heading of 200°M, retract flaps at about 600 ft amsl and climb to between 700 and 1,000 ft amsl before turning right on course to their first navigation waypoint. This would ensure they remained clear of a mast, standing 480 ft amsl, lying 1 nm from the aerodrome boundary on the extended runway centreline.

---

## Footnote

<sup>10</sup> For multi-engined aircraft, Blue Line speed is the best rate of climb airspeed after failure of one engine (usually marked by a blue line on the ASI), usually called  $V_{YSE}$ .

<sup>11</sup> LCY: London City Airport.

Section 2.7.3 of the operator's Operations Manual Part B (OMB) stated that the autopilot should not normally be engaged below 1,000 ft (the minimum engagement height is 500 ft agl). The operator confirmed that, when departing from Stapleford, even in IMC, the autopilot would typically be engaged after the aircraft had turned towards its first navigation waypoint (in this case, Brookman's Park VOR) at which point the aircraft would be at about 1,700 ft amsl. Pilots would typically call the relevant ATC agency once the aircraft had turned towards its first waypoint.

## **Terrain Awareness and Warning Systems**

### *General information*

Avionic systems that protect against inadvertent flight into terrain and pre-cursors such as a loss of altitude after takeoff or an excessive descent rate are generally termed Terrain Awareness and Warning Systems (TAWS). The first generation of these systems looked at the changing terrain clearance beneath aircraft using radio altimeters and were called Ground Proximity Warning Systems (GPWS). However, these systems had no means of looking ahead of the aircraft to anticipate upcoming conflicts with the surrounding terrain, hence TAWS were developed which provided this additional functionality through use of predictive algorithms and in-built terrain databases. These second generation systems are also known as Enhanced Ground Proximity Warning Systems (EGPWS).

### *Minimum performance standards and classes of equipment*

A number of aviation regulators have defined technical standards that set out the minimum performance standard for TAWS. Under the European Aviation Safety Agency (EASA), the current applicable document is European Technical Standard Order C151b (ETSO-C151b) which is based on the equivalent FAA document in the USA, Technical Standard Order C151b. Both of these documents recognise three distinct classes of TAWS, Class A through to Class C with Class A offering the greatest protection against inadvertent flight into terrain. However, all classes must provide a Forward Looking Terrain Avoidance function, which implies that TAWS which meet these standards are second generation systems. In addition, all classes require appropriate visual and aural discrete signals to allow for the annunciation of alerts.

TAWS that meet a minimum performance standard are said to be certified against their respective Technical Standard Order.

A comparison of alerting functions, often called modes, and equipment provisions provided by Class A and Class B devices, as detailed within ETSO-C151b, is shown in Table 1. Class C devices are not included as these are generally only fitted to small General Aviation aeroplanes.

Alerting function or equipment provision	Class A	Class B
Forward Looking Terrain Avoidance	Yes	Yes
Premature Descent Alert	Yes	Yes
Excessive Rates of Descent	Yes	Yes
Excessive Closure Rate to Terrain	Yes	No
Negative Climb Rate or Altitude Loss After Take-off	Yes	Yes
Flight Into Terrain When Not in Landing Configuration	Yes	No
Excessive Downward Deviation From an ILS Glideslope	Yes	No
Voice callout "Five Hundred" when the aeroplane descends to 500 feet above the terrain or nearest runway elevation	Yes	Yes
An appropriate visual and aural discrete signal for both caution and warning alerts	Yes	Yes
Terrain information presented on a display screen	Yes	No, but shall be capable of driving a terrain display function if desired
Entitlement to a ETSO-C92c authorisation approval – For complying with mandatory GPWS carriage requirements (these were not applicable to G-BYCP)	Yes	No

**Table 1**

Alerting functions and equipment provisions provided by Class A and B TAWS


#### *Alert modelling based on recorded data from the accident flight*

To quantify the potential alerting time, as if an ETSO-C151b certified TAWS had been fitted to G-BYCP, the AAIB used radar data for ground track, altitude information from the aircraft's transponder and terrain data to assess the accident flightpath against typical TAWS protection envelopes.

This assessment was completed for the *Excessive Rates of Descent*, and *Negative Climb Rate or Altitude Loss After Take-off* functions as these protections are common to both Class A and Class B systems. In addition, *Excessive Closure Rate to Terrain*, a function of Class A equipment, was tested – Class B systems do not need a radio altimeter to be fitted so this function is not part of the standard for a Class B device.

The assessment showed that about five seconds before the last radar point, which itself was an estimated one to two seconds before ground contact, the criteria were met for issuing alerts relating to *Excessive Rates of Descent*, and *Negative Climb Rate or Altitude Loss After Take-off*. Figure 7 illustrates these cases. For the *Excessive Closure Rate to Terrain* function, alerts were generated about four seconds before the last radar point. This suggested that the first alert would have been triggered approximately six to seven seconds before ground contact.

To verify the AAIB's modelling, a manufacturer of TAWS was asked to perform its own simulation which confirmed that the *Excessive Rates of Descent*, and *Negative Climb Rate or Altitude Loss After Take-off* protections would have activated approximately four seconds before the last radar point. However, the precise timing and order of the alerts could not be specified due to the low update rate of the source data. The manufacturer also remarked that, due to the priority which some alerts have, lower priority alerts may have been suppressed in the accident sequence in favour of other higher priority alerts depending on the exact sequence of events. Additionally, the manufacturer commented that, based on G-BYCP's ground track, it was possible that *Bank Angle* alerts, typically an additional function of a Class A system, may have been generated but it was not possible to state this conclusively due to a lack of bank angle information in the radar data.




**Figure 7**  
TAWS Simulation

## Simulator trial

### Flight profile

The AAIB 'flew' a B200 King Air full-flight simulator in an attempt to match the accident flight profile derived from radar data (ground track, altitude and groundspeed) and physical evidence (the track of the wreckage trail, and the aircraft attitude at impact). The simulator was programmed to reflect the weight and balance of G-BYCP and the environmental conditions on the day of the flight. The aircraft was turned onto a heading of 205°M after takeoff and the climb was flown both manually and with the autopilot engaged. Takeoff power was set for the duration of each flight. The flight profile generated from radar and physical data, which the trial attempted to match, is shown in Figure 8. Time is set to zero at the apex of the climb for comparison purposes.



**Figure 8**  
Accident flight profile

The following simulated flight profile matched the accident data most closely:

- The flaps were retracted at 600 ft amsl.
- At 700 ft amsl, right roll input was applied without any accompanying pitch input<sup>12</sup>.
- The bank angle was increased to 55°, the nose attitude was allowed to decrease, and the aircraft was allowed to descend and accelerate.
- On passing 400 ft amsl in the descent, the bank angle was reduced rapidly towards 12° right and the pitch attitude was raised rapidly towards -5° to -9°.

---


#### Footnote

<sup>12</sup> A small aft elevator input is required during a turn to prevent an aircraft's nose attitude decreasing.

---



The flight profile from the simulated flight is shown in Figure 9 superimposed upon the accident flight profile.



**Figure 9**

Simulated and accident flight profiles

The ground impact point resulting from the simulated flight was located approximately 580 m southeast of the actual impact point. Some of this difference is probably accounted for by differences between actual and simulated values for:

- The rate at which the aircraft rolled in to the turn and the angle of bank actually achieved.
- The altitude in the descent at which the change in aircraft attitude commenced.
- The rate at which bank and pitch attitudes were changed towards the end of the flight.

On one trial run, the autopilot was engaged with a lateral mode active (heading mode) but without a vertical mode. This simulated the possibility that the pilot attempted to use the autopilot but did not engage a vertical mode. When the turn was initiated, bank angle was limited to below 30°, power was sufficient to prevent a decrease in the nose attitude and the aircraft continued to climb.

#### *TAWS alerts*

The simulator was equipped with a Honeywell Mk. VII EGPWS, a certified Class A TAWS, which provided information on the alerts that might have been generated in a flight profile similar to the accident flight. The following aural alerts were triggered during the simulated accident flight profile shown in Figure 9:

- a. "BANK ANGLE" approximately one second after the aircraft began to descend (at approximately 580 ft agl) and ten seconds before ground contact.
- b. "SINK RATE" approximately six seconds after the aircraft began to descend (at approximately 365 ft agl) and five seconds before ground contact.
- c. "PULL UP" approximately seven seconds after the aircraft began to descend (at approximately 325 ft agl) and four seconds before ground contact.

The simulated profile shown in Figure 9 was repeated and ground contact was avoided by appropriate recovery action up to and including the point where the "PULL UP" alert was triggered.

#### **Terrain awareness equipment fitted to G-BYCP**

Current EASA regulations did not require G-BYCP to be fitted with a certified TAWS but two non-certified Garmin GNS430W units were fitted. Each GNS430W unit combined the functionality of two radio transceivers, two ground-based navigation aid receivers and a GPS receiver into a single device. In addition, GNS430W units can make use of a terrain database supplied on a removable memory card, but this only provides for a non-certified terrain awareness capability. Specifically, the protections modelled by the AAIB and manufacturer which are present in a certified Class A or, to a lesser extent, a certified Class B unit (which would lack Excessive Closure Rate to Terrain or Bank Angle protections) were not available. Also, GNS430W units do not provide aural alerts or have any mechanism for external visual alerting on displays remote from the actual units themselves. Garmin offers a certified Class B solution called 'TAWS', which is an option on Garmin's 500 series units, but this option is not available on the GNS430W which, instead, incorporates Garmin's non-certified 'TERRAIN' functionality. Table 2 summarises the differences between Garmin's certified 'TAWS' solution and Garmin's non-certified 'TERRAIN' functionality. The functions of a Class B device that were modelled by the AAIB and manufacturer are highlighted in red whilst the other key differences between the certified and non-certified solutions are shown in yellow.

The terms "TAWS" and "TERRAIN" are used to identify two different configurations of 500 Series unit Main Sub-System. The "TAWS" configuration complies with the Terrain Awareness and Warning System (TAWS) requirements of TSO-C151b for Class B, whereas the "TERRAIN" configuration provides a subset of the functionality of "TAWS".

The following table identifies the high-level differences between TAWS, TERRAIN, and those units with neither (None):

Function	TAWS	TERRAIN	None
TSO-C151b Class B Certified	Yes	No	No
TAWS/TERRAIN Display ( Shows terrain elevations relative to the aircraft )	Yes	Yes	No
Visual Alerting ( Includes popup alerting )	Yes	Yes	No
Aural Alerting	Yes	No	No
External Visual Alerting Capability	Yes	No	No
Reduced Terrain Clearance (RTC) Avoidance ( Forward Looking Terrain Avoidance (FLTA) sub-function )	Yes	Yes	No
Imminent Terrain Impact Avoidance ( Forward Looking Terrain Avoidance (FLTA) sub-function )	Yes	Yes	No
Premature Descent Alert (PDA)	Yes	Yes	No
Excessive Rates of Descent Alert ( Ground Proximity Warning System (GPWS) Alerting sub-function )	Yes	No	No
Negative Climb Rate/Altitude Loss After Takeoff ( Ground Proximity Warning System (GPWS) Alerting sub-function )	Yes	No	No
"Five Hundred" Voice Callout ( Ground Proximity Warning System (GPWS) Alerting sub-function )	Yes	No	No
Inhibit Capability ( Inhibits FLTA and PDA visual and aural alerting )	Yes	Yes	No
TAWS Test System Capability	Yes	No	No
Worldwide Terrain Database	Yes	Yes	No
Airport Layer Database	Yes	Yes	No
Obstacle Database	Yes	Yes	No

500 Series TERRAIN functionality is a subset of the TAWS functionality and has been certified as a non-TSO-function. As such, a subset of the TSO-C151b specification is used as the requirement basis.

**Table 2**

Certified 'TAWS' and non-certified 'TERRAIN' functionality  
(Reproduced with permission from Garmin International, Inc.)

## **Terrain awareness equipment survey**

The AAIB asked six commercial UK King Air operators about terrain awareness equipment fitted to their aircraft, whether certified or non-certified, and, of 20 aircraft consisting mainly of King Air 200 and King Air 250 types, four were equipped with a certified solution. A further five were equipped with either Garmin GNS430, GNS530 or GTN750 series units, of which the GNS530 or GTN750 series can be upgraded to a certified TAWS. This suggested that a minimum of 11 aircraft were without any form of terrain awareness device and, if none of the GNS430, GNS530 or GTN750 series units had been upgraded, then 16 aircraft would not be equipped with a certified solution.

## **TAWS requirements and recommendations**

### *EASA*

In December 2015 the European Aviation Safety Agency (EASA) issued a Notice of Proposed Amendment (NPA), NPA2015-21, which considered the carriage of certified TAWS on turbine-powered aeroplanes. This covered those aeroplanes with a Maximum Certificated Take-off Mass (MCTOM) of 5,700 kg or less and a maximum operational passenger seating configuration (MOPSC) of between six and nine passengers. Comments on this document from interested parties were accepted by the EASA until 18 March 2016 when the consultation phase of EASA's rulemaking process finished. At the time of writing, the EASA was reviewing the comments received before publishing a final opinion. However, the EASA draft opinion calls for Class B TAWS to be fitted to turbine-powered aeroplanes with a MCTOM of 5,700 kg or less and a MOPSC of between six and nine, for which individual Certificates of Airworthiness will be first issued after 1 January 2019. This would only apply to commercial operations and affect newly built aeroplanes, and the existing fleet of aeroplanes, which would have included G-BYCP, would not be encompassed by such rulemaking nor would any such aeroplane operated privately.

### *ICAO*

The International Civil Aviation Organisation (ICAO) sets out Standards and Recommended Practices for Contracting States including the United Kingdom. ICAO Annex 6, Part 1 considers Commercial Air Transport operations by aeroplanes. In this document, a recommendation is made that all turbine-powered aeroplanes of a MCTOM of 5,700 kg or less and authorised to carry more than five but not more than nine passengers should be equipped with a Ground Proximity Warning System. This document lists the functionality such a system should provide which, in effect, denotes a Class B TAWS. A similar recommendation, in effect for Class B TAWS, is made in ICAO Annex 6, Part 2 which covers General Aviation operations by aeroplanes. These recommendations do not distinguish between newly built aeroplanes or those currently in service.

### *The USA and Canada*

In the United States, the Federal Aviation Administration (FAA) requires all turbine-powered aeroplanes able to carry between six and nine passengers to be equipped with a Class B TAWS. This applies when these aeroplanes are operated under the provisions of Federal

Aviation Regulations 14 CFR Parts 91 and 135. 14 CFR Part 135 addresses on-demand air transport whilst 14 CFR Part 91 applies to aeroplane operations not covered by another Federal Aviation Regulation Part thus including private use.

In Canada, Transport Canada (TC) under Canadian Aviation Regulations Subpart 703, requires Class B TAWS for both piston and turbine engine aeroplanes. This applies to aeroplanes involved in air taxi work with six or more passenger seats, excluding any pilot seats, unless operated under Day VFR provisions. Under the regulation applicable to commuter operations, Subpart 704, all aeroplanes with between six and nine passenger seats, excluding any pilot seats, whether piston or turbine engine powered, must be equipped with a Class B TAWS unless operating to Day VFR provisions. For private operations under Subpart 604, Subpart 605 (which covers aircraft equipment carriage) mandates Class B TAWS but only for turbine powered aeroplanes configured with between six and nine passenger seats, excluding any pilot seats.

These rules came into effect in 2001 in the USA and in 2012 in Canada. Both regulators applied these rules to aeroplanes already in service, but allowed a transition period of two and three years respectively to allow time for the necessary modifications to be made.

### **Flight Data and Voice Recorders requirements and rulemaking**

There were no requirements for G-BYCP to carry a flight data recorder or a cockpit voice recorder. EASA are rulemaking in this area and EASA rulemaking tasks RMT.0271 and RMT.0272 refer, a NPA was planned for publication in Quarter 1 of 2016.

### **Passengers on the flightdeck**

#### *CAA communication*

CAA Flight Operations Communication (FODCOM) 21/2010, *Passengers, sometimes called 'pilots' assistants*, was issued on 16 July 2010<sup>13</sup>. The FODCOM explained that persons carried on an aircraft fall into one of two categories: crew or passengers. Some aircraft certificated for single-pilot operations are fitted with a second pilot's seat and the FODCOM stated:

*'For Commercial Air Transport and Public Transport operations ... no person may be carried on the flight deck except ... an operating crew member or a passenger permitted to occupy a flight deck seat in accordance with instructions in the operator's operations manual'*

and:

*'Unless they hold an appropriate flight crew licence entitling them to act as pilot on the flight, such persons can only be passengers and may not undertake any of the pilot's duties, whether handling the controls, operating any aircraft equipment (including the radios) or completing flight documentation'*

#### **Footnote**

<sup>13</sup> CAA Flight Operations Communication 21/2010. Available: <http://publicapps.caa.co.uk/docs/33/FOD201021.pdf>

and:

*'Such passengers are not 'pilot assistants' or 'safety pilots' nor should they be permitted to contribute in any way to the operation of the aircraft.'*

Although the FODCOM pre-dated the implementation of EU 965/2012, the CAA confirmed that, in terms of regulatory requirements, the FODCOM was still valid. On 23 November 2015, the CAA issued Information Notice (IN) 2015/110, *Passengers Carried on the Flight Deck Sometimes Called 'Pilots' Assistants*<sup>14</sup>. The IN was written in substantially the same terms as the FODCOM.

The CAA stated that, because the pilot in the right seat of G-BYCP was not qualified on the B200 King Air, that person was a passenger.

#### *Operator's risk assessment*

The operator's Air Operator's Certificate permitted its King Air aircraft to be operated with either one or two qualified pilots. The OMA stated that the minimum crew requirement for the King Air would be one pilot, but that:

*'When additional Crew members are carried over and above the minimum required they must be trained to a standard proficient to perform their assigned duties'*

and:

*'All Flight Crew members must have a licence, rating, qualification ... valid for the type of aircraft, type of flight and their function within the Flight Crew.'*

In 2010, after FODCOM 21/2010 was issued, the operator undertook a risk assessment in relation to single-pilot operations. The assessment considered events that might trigger an *'Undesirable Operational State'* (UOS) which might in turn lead to a major accident. The UOS was defined with reference to single-pilot operations as a *'severe reduction in 'Spare Capacity' to deal with unforeseen circumstances'*. Risk control barriers intended to prevent the reduction in spare capacity were:

- a. Stricter regulatory medical requirements for single-pilot commercial operations.
- b. Minimum training requirements in the OMA with regards to hours and experience.
- c. Six-monthly Operational Proficiency Checks conducted in the aircraft.
- d. More restrictive flight time limitations and operational procedures, including in relation to the use of the autopilot.

---

#### **Footnote**

<sup>14</sup> CAA Information Notice IN-2015/110. Available: <https://publicapps.caa.co.uk/docs/33/InformationNotice2015110.pdf>

Barriers intended to recover the situation before the UOS could lead to an 'Accident Outcome' were: training; Crew Resource Management (CRM); and pilot experience.

The operator judged that the first set of (preventative) barriers would fail to prevent a UOS approximately once in every 100 sectors, and the second set of (recovery) barriers would fail to prevent the UOS becoming an accident once in every 10,000 occurrences. The overall risk of an accident was quantified as one in every one million sectors and the result of the assessment, according to the assessment nomenclature, was 'Improve'<sup>15</sup>.

The operator undertook the risk assessment again with an additional preventative barrier ie the use of a 'second crew member'. The operator judged that the effect of the additional crew member would be to reduce to once in every 10,000 sectors the probability that a UOS would occur. The operator made no adjustment to the effectiveness of the recovery barriers. In these circumstances, the overall risk of an accident became one in every 100 million sectors and the result of the assessment was 'Monitor'.

The output from the risk assessment was to:

*'Consider mandating the presence of [an] additional crew member or second pilot on every flight for the King Air Fleet.'*

The risk assessment is reviewed annually by the operator.

Following the risk assessment, the operator agreed with the CAA to remove from its Operations Manual all references to 'Pilot's Assistants' and replace them with 'Additional crew members'. The additional crew members would have 'no operational control of the aircraft'.

The operator stated that the duties of the additional crew member during flight were:

*'Read the checklist  
Complete the 'Plog'<sup>16</sup>  
Operate the R/T  
Adhere to [company] SOPs<sup>17</sup>  
Monitor the Captain's actions and be ready to assist if the Captain requires any assistance.  
Express his/her opinion on any action taken by the Captain that may seem abnormal or unclear.  
Follow all briefs given by the Captain.'*

---

#### Footnote

<sup>15</sup> The overall probability of the final (accident) outcome was calculated as the product of the two individual probabilities that the barriers would fail.

<sup>16</sup> Plog: Pilot's log.

<sup>17</sup> SOP: Standard Operating Procedure.

### *Crew composition in the King Air*

The operator's OMB outlined the company's 'philosophy of operation' for the King Air and stated that:

[The normal procedures] section [of OMB] assumes that a second pilot is carried. The second pilot carries out the Pilot Monitoring [PM] role. When two pilots are not carried, the Captain will complete all items.'

The SOP philosophy stated that, in two-crew operations, the PM would, among other things, monitor the flightpath and point out significant un-planned deviations. The PM would call "BANK ANGLE" should the angle of bank exceed 30° and "SINK RATE" should there be an excessive rate of descent '*according to phase of flight and altitude*'.

The duties and procedures to be used by the additional crew member were not contained in the operator's OMB.

## **Analysis**

### *Engineering*

Examination of the engines and propellers did not reveal any evidence of pre-accident defects and the observed damage was similar in nature for the left and right engines and propellers, indicating that there was no asymmetric loss of thrust. Performance analysis conducted by the aircraft manufacturer concluded that the accident flight path, as recorded by secondary radar, was only possible with both engines operating and producing medium to high power during the majority of the period of radar coverage. It was therefore concluded that the engines and propellers were probably operating normally prior to impact.

The landing gear was found in the retracted position, which was consistent with the phase of flight when the accident occurred. The engineering investigation was not able to establish the reason for the difference in flap jackscrew actuator positions between the fully extended left inboard flap actuator, and the remaining three flap actuators, which were found in a position consistent with flaps retracted. No pre-accident defect was observed for the recovered components of the left inboard flap drive system. Had a failure of this system occurred prior to takeoff on the accident flight, the degree of flap asymmetry implied by the extended left inboard flap actuator would have also required a second, independent, failure of the flap asymmetry protection system. Whilst it was therefore considered unlikely that the left inboard flap was extended during the accident flight, this possibility could not be completely discounted.

There was strong evidence that the captain's primary attitude indicator was functioning correctly during the accident flight, and physical evidence of the pitch and roll angles displayed at the moment of impact correlated closely with the tree strike geometry and wreckage distribution noted at the accident site. All discontinuities identified in the aircraft's flying control system were consistent with the impact and subsequent aircraft breakup. The possibility of a pre-accident control restriction, or jam, could not be discounted due to the high degree of fragmentation of the aircraft and subsequent fire damage. However, if



there was such a restriction or jam, it must have freed itself before impact because the late change in aircraft attitude showed that the aircraft was controllable late in the flight.

#### *Technical log entries*

The use of email '*Engineering Reports*' to record aircraft technical defects circumvented the requirements of EASA Part M regulation M.A.403 for correctly recording defects in the aircraft technical log and aircraft maintenance records. A review of the '*Engineering Report*' emails for G-BYCP, over nine months of operation immediately preceding the accident flight, revealed a high number of defects that were not recorded in the aircraft technical log, and for which rectification actions were not recorded in the aircraft's technical records. It was clear that the operator was aware of the aircraft's defect history and that it used the content of the '*Engineering Report*' emails to coordinate defect rectification during the scheduled Phase 1 maintenance inspection in June 2015. Where defects were rectified in this manner, the rectification interval was well outside MEL allowable time limits.

Despite these findings however, the investigation found no evidence that the defects recorded in the '*Engineering Reports*' directly contributed to the accident.

The following safety action was taken:

The operator has issued a Flight Crew Notice to all crews informing them of the suspension of the '*Engineering Report*' email system. The notice instructed them to follow the correct technical log procedures as set out in the operator's Operations Manual Parts A and B, and the relevant aircraft Minimum Equipment List.

#### *Flightpath*

Simulator modelling suggested that the aircraft took off and began its initial climb in accordance with standard procedures. The altitude selector was found to be reading 2,300 ft, consistent with the ATC clearance to remain clear of controlled airspace which began at 2,500 ft amsl. The simulator trial showed that, had the pilot engaged the autopilot in heading mode, but omitted to engage a vertical mode, the aircraft would have continued to climb during the turn. If he believed the autopilot to be engaged when it was not, he would have noticed his error when he commanded the turn and the heading remained constant. Given that the operator expected the departure to be flown manually, it was concluded that the autopilot was probably not engaged. Once the aircraft began to turn right, the simulated profile which matched radar and physical evidence most closely suggested that the aircraft rolled to approximately 55° angle of bank without there being a pitch input to the elevators which was required to prevent the nose attitude decreasing. Without the pitch input, the aircraft would have continued to turn but would also have begun to descend.

The apex of the departure flightpath was approximately 875 ft amsl and below the top of the cloud. It is likely, therefore, that the aircraft was in IMC at the time it began to turn right and descend. Radar data implied a rate of descent of over 7,000 fpm and a downward flightpath angle of approximately 20° as the aircraft descended through approximately 225 ft above

the accident site. Simulator trials suggested that the aircraft reached a maximum angle of bank of about 55° right. Physical evidence suggested that, by the time of impact, the downward flightpath angle had reduced to approximately 5° to 9°, and the angle of bank to approximately 12° right. The late change in aircraft attitude showed that the aircraft was controllable in roll and pitch immediately before impact. It also suggested a conscious attempt to recover the aircraft, probably because one or both of the pilots gained an appreciation of the aircraft's extreme attitude from cockpit instruments, or from external visual references which might have appeared as the aircraft descended.

### *Flap asymmetry*

During the preliminary cockpit procedure, the pilot would have extended the flaps to 100% and, had they not extended, it is unlikely that this would have been missed during the walk-round inspection. Before starting engines, the flaps would have been selected to UP and, after starting engines, they would have been selected to 100% and then 40%. If there was a failure of the flap drive system, therefore, it would have occurred either when the flaps were selected to UP before start, or to 40% after start, and the aircraft would have departed with the inboard flap section at 100% and the remaining flaps at 40%. In these circumstances, the flap position indicator in the cockpit would have indicated 40%, as expected, because it senses flap position on the right wing.

Had there been a flap asymmetry as described above, when the flaps were selected to UP after takeoff, any asymmetric aerodynamic effect already present would have increased as three of the four flap sections retracted. The flap position indicator would have indicated (as expected) that the flaps were retracted. If the flaps were retracted in accordance with standard procedures (at about 600 ft amsl), any aerodynamic effect would have been felt just as the aircraft began to turn right. Information from the manufacturer suggested that the effects would have been noticeable to the pilot but the aircraft would have been controllable in these circumstances. It was concluded that, even if there had been a flap asymmetry, its effects would not have been sufficient in isolation to cause a loss of control but they would probably have been distracting.

### *Additional crew member*

The additional crew member held an ATPL and a multi-pilot instrument rating valid on two-crew aircraft operated by the operator of G-BYCP but, because he was not type-rated on the King Air, he was a passenger on this flight. Additional crew members were used by the operator because, following a risk assessment for single-pilot operations in the King Air, it was judged that their presence would reduce the likelihood that a single pilot would experience a 'severe reduction in 'Spare Capacity' to deal with unforeseen circumstances'. The additional crew member would have 'no operational control of the aircraft' but would have duties which included: adhering to company SOPs; monitoring the captain's actions and assisting if required; and expressing an opinion on any action by the captain that appeared abnormal or unclear. Company SOPs, contained in the OMB and written assuming the aircraft would be operated by two type-rated pilots, stated that the PM would call "BANK ANGLE" should the angle of bank exceed 30° and "SINK RATE" should there be an excessive rate of descent 'according to phase of flight and altitude'.

As an experienced pilot with an instrument rating, the additional crew member was able to interpret flight instruments to gain an appreciation of aircraft attitude and performance. Therefore, it was likely that, had he been aware that the aircraft was over-banking and descending, he would have brought it to the attention of the pilot. It was probably the increasing bank angle (without a corresponding pitch input) which led to the descent, and any descent during the initial climb after takeoff could be considered excessive for that phase of flight and altitude. Each of the calls, "BANK ANGLE" and "SINK RATE", would therefore have been appropriate in the circumstances.

Data from radar and the simulator trial showed that the aircraft began to descend when it was approximately 650 ft above the accident site and after it exceeded 30° angle of bank. It was concluded that, had the "BANK ANGLE" and "SINK RATE" calls been made as soon as they became appropriate, sufficient height remained to allow the aircraft to recover to safe flight.

#### *The possibility of pilot incapacitation*

The post-mortem report raised the possibility that the pilot became incapacitated with symptoms ranging from impaired consciousness to sudden death. In these circumstances, the additional crew member would have had to recognise that the pilot was incapacitated, take control of the aircraft, assess its attitude and flightpath, and initiate recovery action. There would inevitably have been a delay between the moment control was lost and the moment incapacitation was confirmed which would have reduced the time available to assess the flightpath and recover the aircraft. If this was the scenario, it suggested that the additional crew member took recovery action but not in time to achieve climbing flight before the aircraft struck the ground.

#### *Missing evidence*

The investigation had no evidence from within the cockpit relating to the period when the aircraft began to turn and descend. In particular, there was no evidence relating to individual actions by the occupants or the interaction between them. Therefore, the investigation could not determine:

- a. Which pilot was flying the aircraft, although it was expected to have been the commander and there was no evidence to contradict this expectation.
- b. Whether the pilots noticed a flap asymmetry, if one existed, and whether it became a distraction to them both to the exclusion of maintaining a safe flightpath.
- c. Whether, or when, the non-handling pilot noticed that the aircraft attitude was outside normal parameters and brought it to the attention of the handling pilot.

## TAWS

The simulator trial and TAWS modelling suggested that, had the aircraft been fitted with a Class B TAWS, the circumstances would have satisfied system criteria to generate alerts indicating that the aircraft was descending after takeoff and, separately, had an excessive rate of descent. In a class A TAWS installation, alert criteria would most likely have been satisfied in relation to the bank angle and also for an excessive closure rate with the terrain. System logic would probably have prioritised particular alerts and suppressed others, and the radar data available was not of sufficient fidelity to establish the order of alerts that would actually have been triggered. However, it was concluded that, had either class of TAWS been fitted, the crew would probably have been alerted to the fact that the flight path was deviating from the norm at an altitude high enough to allow the aircraft to be recovered to safe flight. This conclusion was supported by the simulator trial in which terrain contact was avoided by appropriate recovery action up to and including the point where the "PULL UP" alert was triggered.

Currently, within the EU, certified TAWS are not required for this category of aeroplane used commercially, unlike the current rules for regulators such as the FAA and Transport Canada which also address privately operated aeroplanes. Further, the draft opinion within the EASA's NPA on this subject, although affecting new build aeroplanes (those issued with individual certificate of airworthiness after 1 January 2019) would exclude aeroplanes currently in service.

The AAIB survey of six commercial UK King Air operators showed that the majority of such aeroplanes were not fitted with certified TAWS, nor were any operators planning on retrofitting their fleets. Non-certified terrain awareness solutions do not offer the same level of protection or mechanisms for alerting pilots, such as aural alerts, that are required on certified units. In this accident, it is likely that a certified TAWS system would have alerted the crew to the situation in time to change the outcome. Therefore, to provide protection against inadvertent flight into terrain for this class of aeroplane, whether operated privately or commercially, the following three Safety Recommendations are made:

### **Safety Recommendation 2016-055**

It is recommended that the European Aviation Safety Agency require all in-service and future turbine aircraft with a Maximum Certificated Takeoff Mass of 5,700 kg or less and with a maximum operational passenger seating configuration of between six and nine passengers to be fitted with, as a minimum standard, a Class B Terrain Awareness and Warning System certified to ETSO-C151b.

**Safety Recommendation 2016-056**

It is recommended that the International Civil Aviation Organisation revise Annex 6 to the Convention on International Civil Aviation, Part 1 (International Commercial Air Transport – Aeroplanes) to upgrade recommendation 6.15.5 [carriage of TAWS on turbine aeroplanes with a Maximum Certificated Takeoff Mass of 5,700 kg or less and authorised to carry more than five but not more than nine passengers] to a standard.

**Safety Recommendation 2016-057**

It is recommended that the International Civil Aviation Organisation revise Annex 6 to the Convention on International Civil Aviation, Part 2 (International General Aviation – Aeroplanes) to upgrade recommendation 2.4.11.2 [carriage of TAWS on turbine aeroplanes with a Maximum Certificated Takeoff Mass of 5,700 kg or less and authorised to carry more than five but not more than nine passengers] to a standard.

*Risk control 'barriers' to prevent loss of aircraft control and terrain impact*

Risk control barriers in place to try and prevent an unintentional deviation from normal in-flight parameters include:

- a. Six-monthly medical examinations for pilots over 40 years old carrying out single-pilot commercial operations carrying passengers.
- b. Proficiency in manual handling skills
- c. Adherence to automation policy.
- d. Flight crew detect and recognise the mishandling via monitoring.
- e. Flight crew detect and recognise the mishandling via automated alerts.
- f. Flight crew correct the mishandling.
- g. Automated features limit the deviation from normal parameters.

Barrier a aimed to reduce the likelihood that a pilot operating in a single-pilot environment will become medically incapacitated at the controls by requiring that pilot to undergo more frequent medical examinations than a pilot operating in a multi-pilot environment. This barrier cannot prevent incapacitation, however, especially when some medical conditions are difficult to predict or occur spontaneously.

Barrier c required the autopilot to be engaged above 1,000 ft agl after takeoff and, because it is likely that the departure was flown manually, the automation policy did not operate as an effective barrier to loss of control during this flight.

Barriers e and g were ineffective because the aircraft was not fitted – and was not required to be fitted – with TAWS, or automated features to limit the deviation of in-flight parameters. Recommendations 2016-055 to 2016-057 are intended to make barrier e

more effective because it is likely in this case that TAWS would have alerted the pilot and/or additional crew member to the initial deviation from the expected flightpath. If the pilot was incapacitated, this might have triggered an earlier response from the additional crew member.

Barriers b, d and f relate to pilot manual handling skills and the ability to detect, recognise and correct any mishandling. These barriers were compromised either because the pilot had insufficient skill to maintain control of his aircraft or because he became incapacitated.

Risk control barriers intended to try and prevent an unintended deviation from normal in-flight parameters leading to loss of control and impact with terrain include:

- h. ATCO identifies the issue and alerts the flight crew.
- i. Automated systems assist aircraft recovery.
- j. Flight crew perform upset recovery procedure in response to monitoring and/or automated warnings.
- k. TAWS alerts flight crew to inadequate terrain separation.
- l. Flight crew carry out terrain avoidance manoeuvre in response to visual, ATCO or TAWS warning.
- m. Flight crew detect and recognise the potential conflict visually.

Barriers h, i and k were ineffective during this flight because no ATC service was provided at the aerodrome, and the aircraft was not fitted with relevant automated systems or TAWS. Barriers j and l relied upon monitoring and visual assessment because of the lack of automated warnings, ATC or TAWS. Safety Recommendations 2016-055 to 2016-057 are intended to strengthen barriers j, k and l because it was likely that TAWS alerts would have been triggered in time for the aircraft to be recovered to safe flight. It was likely that the late change in aircraft attitude was in response to the monitoring of flight instruments or a visual assessment of ground features appearing as the aircraft descended. If so, the recovery manoeuvre could not be completed in the height available and barrier m was also ineffective.

## Conclusion

Examination of the powerplants showed that they were probably producing medium to high power at impact. There was contradictory evidence as to whether or not the left inboard flap was fully extended at impact but it was concluded that the aircraft would have been controllable even if there had been a flap asymmetry. The possibility of a pre-accident control restriction could not be discounted, although the late change of aircraft attitude showed that, had there been a restriction, it cleared itself.

The evidence available suggested a loss of aircraft control while in IMC followed by an unsuccessful attempt to recover the aircraft to safe flight. It is possible that the pilot lost control through a lack of skill but this seemed highly unlikely given that he was properly

licensed and had just completed an extensive period of supervised training. Incapacitation of the pilot, followed by an attempted recovery by the additional crew member, was a possibility consistent with the evidence and supported by the post-mortem report. Without direct evidence from within the cockpit, it could not be stated unequivocally that the pilot became incapacitated. Likewise, loss of control due to a lack of skill, control restriction or distraction due to flap asymmetry could not be excluded entirely. On the balance of probabilities, however, it was likely that the pilot lost control of the aircraft due to medical incapacitation and the additional crew member was unable to recover the aircraft in the height available.

**INCIDENT**

<b>Aircraft Type and Registration:</b>	Boeing 747-436, G-CIVX	
<b>No &amp; Type of Engines:</b>	4 x Rolls-Royce RB211-524G2 turbine engines	
<b>Year of Manufacture:</b>	1998 (Serial no: 28852)	
<b>Date &amp; Time (UTC):</b>	30 January 2016 at 1712 hrs	
<b>Location:</b>	After takeoff from London Heathrow Airport	
<b>Type of Flight:</b>	Commercial Air Transport (Passenger)	
<b>Persons on Board:</b>	Crew - 17	Passengers - 293
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	None	
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence	
<b>Commander's Age:</b>	N/A	
<b>Commander's Flying Experience:</b>	N/A hours Last 90 days - N/A hours Last 28 days - N/A hours	
<b>Information Source:</b>	AAIB Field Investigation	

**Synopsis**

This was the aircraft's first flight after maintenance, during which the Landing Gear Control Module (LGCM) was replaced. After retracting the landing gear following takeoff from Heathrow, the crew were unable to move the landing gear lever from the UP to the OFF position, as it had become jammed in the UP detent. The crew elected to return to Heathrow and, in accordance with 747 Flight Crew Operations Manual Non-Normal Checklist procedures, the landing gear was lowered using the alternate extension system. The aircraft landed safely, with only the nose and body landing gear deployed.

The landing gear lever jam was attributed to a maintenance error which had resulted in incorrect rigging of the landing gear lever system during the LGCM replacement, due to the omission to insert a rig pin in the selector valve quadrant. The operator has taken safety actions intended to prevent a recurrence.

**History of the flight**

The aircraft was on its first flight after an 'A' Check scheduled maintenance input. This check included an incoming defect which involved the replacement of the LGCM, which incorporates the landing gear lever. After takeoff the crew noticed that the landing gear lever felt unusual as they moved it from the DN (down) into the UP position; they then found that it could not be moved from the UP to the OFF detents (the OFF position depressurises the landing gear hydraulic system).




The crew discussed the problem with engineering staff on the ground and decided to return to Heathrow. The nose and the two body landing gear were lowered using the alternate gear extension procedure, and the aircraft landed successfully without the two wing landing gear having deployed.

### Aircraft inspection

Inspection and function checks were carried out at the operator's main base following the incident. The LGCM was found to be mechanically jammed in the UP position. The lever could only be moved to the OFF or DN positions by the application of excessive force.

### Aircraft information


The landing gear on a Boeing 747 is mechanically commanded and hydraulically actuated. There is a three-position handle in the cockpit with the following spring-loaded detents: DN, OFF and UP. The handle must be pulled outwards against spring pressure to enable it to be moved to another position. The handle is part of the LGCM (Figure 1).



**Figure 1**

Landing Gear Control Module showing handle and control rod


The handle is connected to a control rod, which in turn is connected to a quadrant, and attached to the quadrant is a cable that runs to the wing gear selector valve quadrant located in the right hand body gear wheel well. Another cable runs from the wing gear selector valve quadrant to the nose/body gear selector valve quadrant located in the left-hand body gear wheel well (Figures 2 and 3).



**Figure 2**

Landing Gear Control Module and cable runs

The quadrant in each wheel well is connected to a selector valve by a mechanical lever. When a replacement LGCM is installed, it is a requirement in the Aircraft Maintenance Manual (AMM) to insert a rig pin in the selector valve quadrant (Figure 3).



**Figure 3**

Wing Gear Selector Valve Installation - note rig pin  
(Nose/Body Gear Selector Valve Installation similar)

### Inspection of the LGCM

The LGCM was stripped at the AAIB with a representative from the operator. There were no significant findings.

### Maintenance investigation

The maintenance conducted on the LGCM was reviewed as part of the operator's internal investigation into the incident.

The night shift had raised the task cards for the removal and re-rigging of the original LGCM; these cards included the tasks of fitting the rig pin in the selector valve quadrant, function checks and a duplicate inspection. The night shift staff removed and re-rigged the LGCM, but did not have time to complete the function checks, and the task cards were left uncertified.

The re-rigged LGCM failed the function check made by the day shift, and the day shift then fitted a replacement serviceable LGCM. The task cards raised by the day shift staff for replacing the LGCM did not contain a task for the fitment and removal of the rig pins in the

selector valve quadrants. The task cards raised by the night shift were used to certify the function checks.

Three day shift engineers were involved in the fitting of the LGCM. They had the relevant sections of the AMM and the applicable Temporary Revision (TR) to the AMM, generated by the operator to provide additional information on the task. The engineers became focused on achieving the correct adjustment and hence were using the TR (which did not specify the need to fit the rig pins). A consequence of omitting to use the rig pin was the need to use five shims to enable the LGCM to be fitted to the instrument panel; three shims are more typical for a correctly rigged system.

One of the engineers, who was positioned near the quadrant in the right-hand wheel well, noticed that the rig pin was not fitted and that the quadrant was moving (by inputs from another engineer in the cockpit). He was concerned that he might be injured, and took a planned break that was overdue. This break caused a distraction, and the fitting of the rig pin was omitted.

### **Analysis and safety actions**

The jammed landing gear lever was attributed to a rig pin not being inserted in the landing gear system during maintenance, which led to additional and unnecessary shims being used to rig the landing gear lever.

The following causal factors were identified by the operator's maintenance investigation:

- i. The distraction of the engineer when he saw the quadrant move and he took his break;
- ii. Deficiencies in the operator's task card system;
- iii. The omission of the need to fit the rig pin in the operator's TR for this task;
- iv. An inadequate handover between the night shift and the day shift.

As a result of this incident the operator has taken a number of safety actions, including:

- a. Updating the TR so that technical management are consulted if more than three rigging shims are used for this task and to include a requirement to fit rig pins and to check that the rig pins can be inserted freely once function checks are completed;
- b. Holding staff briefings to reinforce the requirements to adhere to handover procedures;
- c. Publishing a bulletin to highlight this incident, including the distraction aspect;
- d. Introduction of additional skills training in task card generation.

## **AAIB Correspondence Reports**

These are reports on accidents and incidents which were not subject to a Field Investigation.

They are wholly, or largely, based on information provided by the aircraft commander in an Aircraft Accident Report Form (AARF) and in some cases additional information from other sources.

The accuracy of the information provided cannot be assured.



**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Bell 206B Jet Ranger II, G-OAMI	
<b>No &amp; Type of Engines:</b>	1 Allison 250-C20 turboshaft engine	
<b>Year of Manufacture:</b>	1968 (Serial no: 464)	
<b>Date &amp; Time (UTC):</b>	10 February 2016 at 1620 hrs	
<b>Location:</b>	3 miles WNW of Wycombe Air Park, Buckinghamshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 3
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Collapse of the landing gear and tail boom failed	
<b>Commander's Licence:</b>	Commercial Pilot's Licence	
<b>Commander's Age:</b>	32 years	
<b>Commander's Flying Experience:</b>	757 hours (of which 77 were on type) Last 90 days - 39 hours Last 28 days - 25 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

Having departed Wycombe Air Park and in level flight, the helicopter suffered a rapid and uncommanded loss of altitude. The pilot, believing that there had been a loss of engine power, carried out an autorotation. The helicopter touched down with a high rate of descent which resulted in the failure of the tail boom and landing gear.

Data recorded by on-board systems showed that the engine operated normally throughout the event. A limited examination of the helicopter was unable to identify a defect within the engine or flying controls which might have caused the uncommanded loss of altitude.

## ACCIDENT

<b>Aircraft Type and Registration:</b>	De Havilland DH82A Tiger Moth, G-AMCK
<b>No &amp; Type of Engines:</b>	1 De Havilland Gipsy Major 1 piston engine
<b>Year of Manufacture:</b>	1941 (Serial no: 84641)
<b>Date &amp; Time (UTC):</b>	13 May 2016 at 0955 hrs
<b>Location:</b>	Field near Sidmouth, Devon
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1                      Passengers - None
<b>Injuries:</b>	Crew - 1 (Serious)      Passengers - N/A
<b>Nature of Damage:</b>	Damaged beyond economic repair
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	47 years
<b>Commander's Flying Experience:</b>	810 hours (of which 120 were on similar types) Last 90 days - 80 hours Last 28 days - 30 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

The aircraft had taken off from Branscome Airfield for a short (5-10 minute) flight to Dunkeswell. After pre-flight checks and engine warm-up, the pilot took off on Runway 10. He set course for Dunkeswell, at a height of approximately 1,300 ft (it was his custom to transit below 1,500 ft to assist Exeter Airport ATC).

After about 2 minutes, the engine experienced a loss of power which the pilot was unable to resolve and he selected a suitable field for a forced landing. Just before touchdown in the field, he had to avoid a high 'Devon hedgebank' and this resulted in a left-wing-low attitude which led to the aircraft ground looping. The aircraft was badly damaged and the pilot at first believed he had sustained only minor injuries, including being badly winded, but a hospital check showed he had at least one cracked vertebra. This required some surgery, but he reports that he has made a full recovery.

Although the pilot believes that an issue with carburation would be consistent with the power loss he experienced, he cannot be certain and reports that the engine components were too badly damaged to be tested.

---

### Bulletin Correction

The departure location was incorrectly stated as 'Farway Common Airfield' whereas the aircraft had actually taken off from 'Branscome Airfield'

The online version of this report was amended prior to publication.



**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Miles M38 Messenger 4B, G-AKVZ	
<b>No &amp; Type of Engines:</b>	1 De Havilland Gipsy Major 10 Mk 2 piston engine	
<b>Year of Manufacture:</b>	1945 (Serial no: 6352)	
<b>Date &amp; Time (UTC):</b>	19 July 2016 at 1554 hrs	
<b>Location:</b>	Biggin Hill Airport, Kent	
<b>Type of Flight:</b>	Unknown	
<b>Persons on Board:</b>	Crew - 1	Passengers - 2
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Underside of fuselage, landing gear legs and propeller	
<b>Commander's Licence:</b>	Private Pilot's Licence	
<b>Commander's Age:</b>	60 years	
<b>Commander's Flying Experience:</b>	3,675 hours (of which 365 were on type) Last 90 days - 61 hours Last 28 days - 25 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The pilot and two passengers were intending to fly to a private airstrip near Paddock Wood in Kent. The pilot stated the aircraft type has poor handling characteristics in a crosswind takeoff, which is exacerbated when the wind is from the right. He also commented that the brakes had "poor efficiency" and that the rudders provide minimal directional control until the airspeed exceeds about 28 KIAS.

The pilot stated that he was concerned about the wind direction and speed, which was reported from 140° at 10 kt. As he booked out, he requested the use of Runway 11, but this was denied as it was closed; Runway 21 was active at the time. Prior to boarding the aircraft, the pilot stated that he had convinced himself that he could not accept Runway 21 as he mistakenly believed that this would provide an excessive crosswind component from the right. As a consequence, he decided to take off in the reciprocal direction on Runway 03, which did result in a right crosswind component.

The initial takeoff run proceeded normally but, as soon as the tailwheel lifted from the ground, the aircraft entered a ground loop. The pilot attempted to regain directional control, but the aircraft departed the right side of the runway and both landing gear legs collapsed; the propeller struck the ground and the engine stopped. The aircraft came to rest and the pilot and passengers left the aircraft unaided.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Pioneer 300, G-VOLO	
<b>No &amp; Type of Engines:</b>	1 Rotax 912 ULS piston engine	
<b>Year of Manufacture:</b>	2009 (Serial no: PFA 330-14389)	
<b>Date &amp; Time (UTC):</b>	24 April 2016 at 1240 hrs	
<b>Location:</b>	Sutton Bank Airfield, Yorkshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Damage to propeller and landing gear motor, engine shock-loaded	
<b>Commander's Licence:</b>	Private Pilot's Licence	
<b>Commander's Age:</b>	52 years	
<b>Commander's Flying Experience:</b>	1,500 hours (of which 220 were on type) Last 90 days - 15 hours Last 28 days - 8 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and enquiries with the Light Aircraft Association	

**Synopsis**

The aircraft touched down normally on the mainwheels. However, shortly after the nosewheel settled, it started to collapse and the propeller struck the ground. It is suspected that the retraction/extension mechanism may have been misrigged or the rigging had changed in service.

**History of the flight**

The aircraft was on a cross-country flight from Sleep Aerodrome to Sutton Bank. The pilot made a radio call about 10 nm from Sutton Bank and was briefed to expect to land on Runway 01. On a straight-in approach at 4 nm, he selected the landing gear down and received three green lights to indicate that all three landing gear were down and locked. He selected full flap and made a gentle touchdown on the main gear, keeping the nose up as he slowed without using brakes.

Two seconds after the nose gear settled onto the runway, it started to collapse slowly and the nose and propeller contacted the runway. The aircraft slid for about 100 ft in a straight line before coming to a halt. The pilot vacated the aircraft normally.

**Additional information**

The Pioneer 300 retraction/extension system uses a single electric motor driving metal actuating rods to the nose landing gear and each main landing gear. Correct initial rigging of such systems is critical, but this may also be changed by such factors as heavy landings. In the case of G-VOLO, it is understood that the nose gear actuating rod had attempted to transfer landing loads back to the motor, which had suffered damage as a result. This showed that the leg, whilst down, was not in geometric downlock.

**Follow-up action**

The Light Aircraft Association are aware of this and other similar events and advise that they may require owners to perform annual retraction tests as part of routine maintenance.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Piper PA-28-161 Cherokee Warrior II, G-BNXE	
<b>No &amp; Type of Engines:</b>	1 Lycoming O-320-D3G piston engine	
<b>Year of Manufacture:</b>	1981 (Serial no: 28-8116034)	
<b>Date &amp; Time (UTC):</b>	19 April 2016 at 1230 hrs	
<b>Location:</b>	Sturgate Airfield, Lincolnshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 2
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Damage to front and right wheel fairings and propeller and engine shock-loaded	
<b>Commander's Licence:</b>	Light Aircraft Pilot's Licence	
<b>Commander's Age:</b>	73 years	
<b>Commander's Flying Experience:</b>	1,290 hours (of which 850 were on type) Last 90 days - 5 hours Last 28 days - 3 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The pilot was approaching to land on Runway 27 at Sturgate Airfield which had a dry asphalt surface and a length of 820 m. He described the wind as "light and variable". He had made several 'blind' radio calls to which had received no response, during which he noted that the wind strength appeared to be about 4 kt.

On final approach, the pilot felt that he was slightly high due to noise abatement procedures over local houses and selected two stages of flap. On touchdown he felt that the wind had calmed completely, causing him to float further than he would have expected, with the result that the aircraft ran off the end of the runway and into an area of ploughed land at a speed he estimated to be about 5 mph.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	EV-97 Teameurostar UK, G-SHMI	
<b>No &amp; Type of Engines:</b>	1 Rotax 912-UL piston engine	
<b>Year of Manufacture:</b>	2007 (Serial no: 3013)	
<b>Date &amp; Time (UTC):</b>	25 June 2016 at 1218 hrs	
<b>Location:</b>	Croft Farm Airfield, Defford, Worcestershire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Damage to right wing, landing gear, canopy and propeller	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	65 years	
<b>Commander's Flying Experience:</b>	129 hours (of which all were on type) Last 90 days - 9 hours Last 28 days - 1 hour	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and additional enquiries made by the AAIB	

The pilot's final approach to Runway 28 at Croft Farm was witnessed by the ground radio operator. He stated that the aircraft appeared lower than he would normally expect to see similar aircraft on finals. Subsequently, the aircraft clipped a field of crop approximately 60 ft before the runway's threshold, impacted the ground and slid a further 50 ft before coming to a halt. Both occupants were able to vacate the aircraft without difficulty or injury. The pilot attributed the accident to his misjudgement of the aircraft's height on finals.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Ikarus C42 FB80, G-SFLA	
<b>No &amp; Type of Engines:</b>	1 Rotax 912-UL piston engine	
<b>Year of Manufacture:</b>	2007 (Serial no: 0701-6867)	
<b>Date &amp; Time (UTC):</b>	13 May 2016 at 1000 hrs	
<b>Location:</b>	Lower Upham Airfield, Hampshire	
<b>Type of Flight:</b>	Training	
<b>Persons on Board:</b>	Crew - 2	Passengers - None
<b>Injuries:</b>	Crew - None	Passengers - N/A
<b>Nature of Damage:</b>	Both wings, nose gear, main gear, door and engine mounts	
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence	
<b>Commander's Age:</b>	53 years	
<b>Commander's Flying Experience:</b>	17,557 hours (of which 24 were on type) Last 90 days - 133 hours Last 28 days - 54 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The purpose of the flight was to conduct circuit training at Sandown Airfield on the Isle of Wight. A student pilot occupied the left seat, with a flying instructor in the right seat. The student flew a number of circuits to a good standard, and the instructor determined that he was ready to undertake his first solo. The aircraft returned to Lower Upham Airfield in preparation. The instructor reported that the return flight, circuit and approach to Runway 04, were uneventful. However, during the final stages of the approach, the student pilot commenced the flare somewhat high. This resulted in a very firm touchdown which caused the aircraft to bounce twice and drift to the left of the runway. The instructor took control and initiated a missed approach, applying full power and control inputs to correct the flight path. As the aircraft began to climb away, the left wingtip struck a metal stanchion embedded in a hedge to the left of the runway. This caused the aircraft to swing rapidly to the left and impact the ground. No injuries were sustained and both occupants exited the aircraft without assistance.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Pegasus Quantum 15-912, G-BZYN	
<b>No &amp; Type of Engines:</b>	1 Rotax 912-UL piston engine	
<b>Year of Manufacture:</b>	2001 (Serial no: 7835)	
<b>Date &amp; Time (UTC):</b>	15 May 2016 at 1025 hrs	
<b>Location:</b>	Sandy Airfield, Bedfordshire	
<b>Type of Flight:</b>	Training	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Damage to trike and wing	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	63 years	
<b>Commander's Flying Experience:</b>	869 hours (of which 639 were on type) Last 90 days - 58 hours Last 28 days - 12 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The aircraft was landing after a training flight with a student and an instructor on board. Towards the end of the landing roll the aircraft veered to the right, left the runway and tipped over onto its left side. The instructor's assessment was that he was unable to correct the student's inputs on the steering bar in time to prevent the accident.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Pegasus Quik Quik, G-CCOW	
<b>No &amp; Type of Engines:</b>	1 Rotax 912ULS piston engine	
<b>Year of Manufacture:</b>	2004 (Serial no: 8008)	
<b>Date &amp; Time (UTC):</b>	31 July 2016 at 1000 hrs	
<b>Location:</b>	Atheys Airfield, Northumberland	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Pod, keel, roll bracket, nose plate, front strut sleeve and spats	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	53 years	
<b>Commander's Flying Experience:</b>	62 hours (of which 62 were on type) Last 90 days - 5 hours Last 28 days - 0 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The pilot and one passenger were taking off from grass Runway 26 for a local flight. The wind direction and speed was reported as "light easterly between 10 kt and 12 kt". The pilot stated that, as the aircraft became airborne, there was a sudden change in wind direction that resulted in the wing dropping to the right and the aircraft stalling, following which it turned through approximately 230° before impacting the ground near the side of the runway. The pilot and passenger were uninjured.



**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Pegasus Quik, G-OKEM	
<b>No &amp; Type of Engines:</b>	1 Rotax 912-UL piston engine	
<b>Year of Manufacture:</b>	2004 (Serial no: 8047)	
<b>Date &amp; Time (UTC):</b>	20 June 2016 at 1600 hrs	
<b>Location:</b>	Culbokie Airfield, Ross and Cromarty	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - None
<b>Injuries:</b>	Crew - 1 (Minor)	Passengers - N/A
<b>Nature of Damage:</b>	Damage to the wing, propeller blades and cockpit area	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	39 years	
<b>Commander's Flying Experience:</b>	204 hours (of which 169 were on type) Last 90 days - 13 hours Last 28 days - 9 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and further enquiries made by the AAIB	

The pilot arrived overhead Culbokie Airfield, 7 nm NNW of Inverness, after an uneventful flight from Perth and joined the circuit for Runway 21. Whilst downwind, he observed the windsock indicating around 30° off the runway centreline, in rough agreement with the METAR and TAF obtained from Inverness Airport, and set-up for a higher speed approach to take into account the forecasted gusty conditions. The pilot stated that his approach was normal with no evidence of any strong gusting or crosswind, reporting only some buffeting as he passed 80 ft high trees on short finals. However, upon landing the aircraft bounced twice and, despite the pilot attempting a go-around on the second bounce, the left wingtip struck the ground causing the aircraft to roll onto its side. The pilot, who was wearing a helmet and three-point harness, suffered minor injury but was able to vacate the aircraft with the assistance of a passer-by. The pilot attributed the accident to having flared too high, coupled with the possibility that he may have experienced some windshear from trees abeam the runway.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Rans S6-ESD Coyote II, G-MYGP	
<b>No &amp; Type of Engines:</b>	1 Rotax 503 piston engine	
<b>Year of Manufacture:</b>	1992 (Serial no: PFA 204-12368)	
<b>Date &amp; Time (UTC):</b>	3 April 2016 at 1400 hrs	
<b>Location:</b>	North Moor Airfield, Lincolnshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Right Main Landing Gear (MLG) leg detached	
<b>Commander's Licence:</b>	Private Pilot's Licence	
<b>Commander's Age:</b>	71 years	
<b>Commander's Flying Experience:</b>	670 hours (of which 35 were on type) Last 90 days - 8 hours Last 28 days - 8 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

The aircraft was returning to North Moor Airfield after a flight of about one hour. On the downwind leg to land on Runway 09, the pilot followed his usual practice with two-stroke engines and ran the engine up to maximum rpm. Shortly after turning base leg, he reduced power but the engine stopped; he radioed to report the problem and attempted to restart but to no avail.

The pilot elected to land straight ahead into a field with a short crop. The landing was successful but, as the aircraft came to a halt, the right mainwheel slid into a rut made by a tractor, resulting in detachment of the landing gear leg. The pilot believes that carburettor icing was responsible for the engine failure and has subsequently fitted an electrical carburettor heating system with its associated switch and ammeter, plus a carburettor temperature gauge.

**SERIOUS INCIDENT**

<b>Aircraft Type and Registration:</b>	Savannah VG Jabiru(1), G-SAVY	
<b>No &amp; Type of Engines:</b>	1 Jabiru 2200A piston engine	
<b>Year of Manufacture:</b>	2009 (Serial no: BMAA/HB/499)	
<b>Date &amp; Time (UTC):</b>	8 May 2016 at 1154 hrs	
<b>Location:</b>	2 nm southwest of Mablethorpe, Lincolnshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - None
<b>Injuries:</b>	Crew - None	Passengers - N/A
<b>Nature of Damage:</b>	Elevator trim tab servo arm fractured	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	64 years	
<b>Commander's Flying Experience:</b>	345 hours (of which 141 were on type) Last 90 days - 6 hours Last 28 days - 6 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

**Synopsis**

Shortly after the aircraft entered cruising flight the trim servo actuator arm of the left elevator anti-balance trim tab fractured, resulting in severe vibration of the aircraft's pitch control circuit. The pilot carried out a successful precautionary landing in a field. Examination of the aircraft showed that excessive up elevator deflection had caused bending loads to be applied to the trim servo actuator arm, leading to its structural failure.

**History of the flight**

The pilot was flying the aircraft from North Coates Airfield in Lincolnshire to Otherton Airfield in Staffordshire. Following a normal departure from North Coates, the aircraft was cruising at 95 mph at 2,000 ft amsl when the pilot felt "a loud thump" from the rear of the aircraft. He reported that the control column was immediately "ripped" from his right hand and continued to shake violently in pitch. The pilot managed to regain hold of the control column and he reduced airspeed to 60 mph, after which the elevator vibration abruptly reduced.

The pilot retained full control in roll, yaw and over the engine but was concerned about pitch control, so he decided to make an immediate precautionary landing in a field 2 nm southwest of Mablethorpe, Lincolnshire. Following the precautionary landing, which was completed successfully, the pilot inspected the aircraft and discovered that the actuator arm of the electric trim servo, which was connected to the left elevator anti-balance tab, had fractured leaving the tab free to rotate, which had caused the severe elevator vibration.


## Elevator trim system

The Savannah VG pitch trim system consists of two anti-balance trim tabs, one fitted to the trailing edge of each elevator. Each tab is separately moved for trim by an electric trim servo mounted on the tailplane tip rib, via a system of pushrods and a lever. As the elevator rotates, the anti-balance tab gearing provides an increase in elevator forces. The neutral position of the anti-balance tab is adjusted via the trim servo to provide pitch trim. Figure 1 shows the left elevator anti-balance tab and trim system, following the precautionary landing, with the elevator tip fairing removed for clarity. The electric trim actuator arm, manufactured from a toughened thermoplastic material, had fractured in downward bending overload and there was no evidence of fatigue or progressive failure (Figure 2).



**Figure 1**

Fractured elevator anti-balance trim tab servo arm



**Figure 2**

Bending failure of the trim tab servo arm

The pilot reported that this was the second such failure of a trim servo actuator arm on the aircraft, following fracture of the right elevator trim servo arm in 2015. The BMAA had no records of any similar trim actuator arm failures on other UK-registered Savannah aircraft.

### **Examination of the aircraft**

The aircraft was examined by a member of the BMAA Technical Office<sup>1</sup>. The range of elevator deflection was found to exceed the allowable limits for the aircraft. When the elevator was fully up, the anti-balance tab gearing could cause the tab deflection to go over-centre, producing a bending load in the servo trim actuator arm. This tendency was exacerbated with additional nose-down trim input from the trim servo. The pilot stated that it was his normal practice after landing to hold the nose of the aircraft up for aerodynamic braking, by using full up elevator. This could have induced bending loads on the servo actuator arm.

### **Safety action**

The BMAA is currently surveying other UK-registered Savannah aircraft to determine whether any other examples exhibit the excessive elevator deflections found on G-SAVY, and will notify UK owners of their findings.

---

### **Footnote**

<sup>1</sup> G-SAVY is a BMAA amateur-built aircraft and the BMAA is responsible for its continued airworthiness

---

## ACCIDENT

<b>Aircraft Type and Registration:</b>	Tiger Cub 440, G-MMIH	
<b>No &amp; Type of Engines:</b>	1 Fuji-Robin EC-44-PM piston engine	
<b>Year of Manufacture:</b>	1984 (Serial no: SO130)	
<b>Date &amp; Time (UTC):</b>	5 June 2016 at 1300 hrs	
<b>Location:</b>	Crosland Heath Golf Club, Huddersfield, West Yorkshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - None
<b>Injuries:</b>	Crew - 1 (Serious)	Passengers - N/A
<b>Nature of Damage:</b>	Substantial damage to the landing gear, forward fuselage and wings	
<b>Commander's Licence:</b>	Private Pilot's Licence	
<b>Commander's Age:</b>	55 years	
<b>Commander's Flying Experience:</b>	326 hours (of which 4 were on type) Last 90 days - 1 hour Last 28 days - 1 hour	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

## Synopsis

After taking off with the intention of conducting a few circuits, the pilot had turned the aircraft onto the downwind leg when the engine began to lose power. Eventually it would run at no more than 2,500 rpm, compared with a normal maximum of 5,200. The pilot was forced to land on a golf course adjacent to the airfield, but the presence of golfers on the landing area caused him to alter course so that the aircraft landed heavily on rough ground. The pilot, who sustained a back injury, assessed the symptoms of the power loss to be indicative of carburettor icing.

## History of the flight

The pilot arrived at the airfield at around noon with the intention of mending a puncture before taking the aircraft for what would be its first flight of the year. Having attended to the puncture he then spent another hour checking the aircraft, including the flying controls, engine and fuel system. The aircraft was then pulled out of its hangar, refuelled with fresh fuel and, after setting the parking brake and priming the carburettors, the pilot started the engine by hand-swinging the propeller. The engine was subsequently run up to its normal operating temperature and power checks carried out, with satisfactory results. The pilot then taxied the aircraft to the flying club caravan, shut down the engine and went for a cup of tea.

A short time later he returned to the aircraft, conducted another walk-around check and started the engine. He taxied towards the in-use runway, running the engine up to full throttle in short bursts, confirming that full power was available. The takeoff run was normal, with the aircraft becoming airborne at 35 kt, subsequently climbing at 500 ft/min with an indicated airspeed of 40 kt. The pilot intended to conduct a few circuits and, at 500 ft, he began to turn the aircraft through 180° onto the downwind leg. After the turn was completed the engine started to lose power, with the maximum achievable rpm down from 5,200 to around 2,500. The pilot considered that the engine fuel pump may have failed and gave a few squeezes on the 'rubber bulb' back-up pump located under the seat (this is mainly used for priming the carburettors prior to starting the engine). This had no effect and moving the throttle back and forth similarly achieved no result other than changing the rpm between tick-over and 2,500.

By now the aircraft was down to around 400 ft and the pilot was aware he needed to find a landing site. He considered that he had insufficient height to land back on the airfield; an influencing factor here was the presence of a quarry adjacent to the runway, in which the aircraft may have ended up in the event he failed to reach the airfield. Crosland Heath Golf Club was immediately below and the pilot lined up on one of the fairways. He was aware that this would entail a downwind landing but considered that this was acceptable as the aircraft was too low to turn into wind, which was light at only around 5 kt. At a height of about 200 ft the pilot became aware of golfers on his intended landing area and altered course to land on some rough ground to the side of the fairway. The aircraft landed heavily and rotated to the left before coming to rest. The pilot climbed out of the aircraft, by which time a number of golfers had arrived to provide assistance. The pilot then became aware of a sharp pain in his back and lay down on the grass to await the arrival of the ambulance.

### **The investigation**

The pilot's subsequent examination of the wreckage included the engine and accessories such the fuel pump and the gascolator. No evidence of a failure or malfunction was found. It is the pilot's conviction that the nature of the power reduction was indicative of carburettor icing. The weather on the day was described as "approximately 12°C and humid". The engine on this aircraft type has no provision for carburettor heat.

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	X'air Hawk, G-CEON	
<b>No &amp; Type of Engines:</b>	1 Jabiru 2200A piston engine	
<b>Year of Manufacture:</b>	2008 (Serial no: PFA 340-14673)	
<b>Date &amp; Time (UTC):</b>	10 April 2016 at 1545 hrs	
<b>Location:</b>	Strathaven Airfield, Lanarkshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - 1
<b>Injuries:</b>	Crew - None	Passengers - None
<b>Nature of Damage:</b>	Propeller, nosewheel and cockpit screen damage	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	56 years	
<b>Commander's Flying Experience:</b>	151 hours (of which 101 were on type) Last 90 days - 2 hours Last 28 days - 2 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

While back-tracking along grass Runway 09, the pilot noticed a "soggy patch" in the centre of the runway which he made a mental note to avoid during takeoff. He reached the end of the runway, turned and positioned the aircraft on the left-hand side and commenced the takeoff. The aircraft accelerated to approximately 40 mph, after which the pilot reported a deceleration coincident with another area of "soggy" runway. This deceleration caused the nose to dip, the nosewheel to detach and the propeller to contact the ground. The aircraft inverted and came to rest facing the opposite direction on its back.

The pilot and passenger, who were both wearing full harnesses, escaped uninjured. The pilot commented that, despite other aircraft taking off on the same runway, walking the runway to assess its condition prior to takeoff might have been wise.



## **Miscellaneous**

This section contains Addenda, Corrections and a list of the ten most recent Aircraft Accident ('Formal') Reports published by the AAIB.

The complete reports can be downloaded from the AAIB website ([www.aaib.gov.uk](http://www.aaib.gov.uk)).



## **TEN MOST RECENTLY PUBLISHED FORMAL REPORTS ISSUED BY THE AIR ACCIDENTS INVESTIGATION BRANCH**

- |  |   |
|--|---|
| 1/2011 Eurocopter EC225 LP Super Puma, G-REDU near the Eastern Trough Area Project Central Production Facility Platform in the North Sea on 18 February 2009.<br>Published September 2011.           | 1/2015 Airbus A319-131, G-EUOE London Heathrow Airport on 24 May 2013.<br>Published July 2015.                                  |
| 2/2011 Aerospatiale (Eurocopter) AS332 L2 Super Puma, G-REDL 11 nm NE of Peterhead, Scotland on 1 April 2009.<br>Published November 2011.  | 2/2015 Boeing B787-8, ET-AOP London Heathrow Airport on 12 July 2013.<br>Published August 2015.                                 |
| 1/2014 Airbus A330-343, G-VSXY at London Gatwick Airport on 16 April 2012.<br>Published February 2014.   | 3/2015 Eurocopter (Deutschland) EC135 T2+, G-SPAO Glasgow City Centre, Scotland on 29 November 2013.<br>Published October 2015. |
| 2/2014 Eurocopter EC225 LP Super Puma G-REDW, 34 nm east of Aberdeen, Scotland on 10 May 2012 and G-CHCN, 32 nm south-west of Sumburgh, Shetland Islands on 22 October 2012.<br>Published June 2014. | 1/2016 AS332 L2 Super Puma, G-WNSB on approach to Sumburgh Airport on 23 August 2013.<br>Published March 2016.                  |
| 3/2014 Agusta A109E, G-CRST Near Vauxhall Bridge, Central London on 16 January 2013.<br>Published September 2014.  | 2/2016 Saab 2000, G-LGNO approximately 7 nm east of Sumburgh Airport, Shetland on 15 December 2014<br>Published September 2016. |

Unabridged versions of all AAIB Formal Reports, published back to and including 1971, are available in full on the AAIB Website

<http://www.aaib.gov.uk>



---

## GLOSSARY OF ABBREVIATIONS

aal	above airfield level	lb	pound(s)
ACAS	Airborne Collision Avoidance System	LP	low pressure
ACARS	Automatic Communications And Reporting System	LAA	Light Aircraft Association
ADF	Automatic Direction Finding equipment	LDA	Landing Distance Available
AFIS(O)	Aerodrome Flight Information Service (Officer)	LPC	Licence Proficiency Check
agl	above ground level	m	metre(s)
AIC	Aeronautical Information Circular	mb	millibar(s)
amsl	above mean sea level	MDA	Minimum Descent Altitude
AOM	Aerodrome Operating Minima	METAR	a timed aerodrome meteorological report
APU	Auxiliary Power Unit	min	minutes
ASI	airspeed indicator	mm	millimetre(s)
ATC(C)(O)	Air Traffic Control (Centre)( Officer)	mph	miles per hour
ATIS	Automatic Terminal Information System	MTWA	Maximum Total Weight Authorised
ATPL	Airline Transport Pilot's Licence	N	Newtons
BMAA	British Microlight Aircraft Association	$N_R$	Main rotor rotation speed (rotorcraft)
BGA	British Gliding Association	$N_g$	Gas generator rotation speed (rotorcraft)
BBAC	British Balloon and Airship Club	$N_i$	engine fan or LP compressor speed
BHPA	British Hang Gliding & Paragliding Association	NDB	Non-Directional radio Beacon
CAA	Civil Aviation Authority	nm	nautical mile(s)
CAVOK	Ceiling And Visibility OK (for VFR flight)	NOTAM	Notice to Airmen
CAS	calibrated airspeed	OAT	Outside Air Temperature
cc	cubic centimetres	OPC	Operator Proficiency Check
CG	Centre of Gravity	PAPI	Precision Approach Path Indicator
cm	centimetre(s)	PF	Pilot Flying
CPL	Commercial Pilot's Licence	PIC	Pilot in Command
°C,F,M,T	Celsius, Fahrenheit, magnetic, true	PNF	Pilot Not Flying
CVR	Cockpit Voice Recorder	POH	Pilot's Operating Handbook
DME	Distance Measuring Equipment	PPL	Private Pilot's Licence
EAS	equivalent airspeed	psi	pounds per square inch
EASA	European Aviation Safety Agency	QFE	altimeter pressure setting to indicate height above aerodrome
ECAM	Electronic Centralised Aircraft Monitoring	QNH	altimeter pressure setting to indicate elevation amsl
EGPWS	Enhanced GPWS	RA	Resolution Advisory
EGT	Exhaust Gas Temperature	RFFS	Rescue and Fire Fighting Service
EICAS	Engine Indication and Crew Alerting System	rpm	revolutions per minute
EPR	Engine Pressure Ratio	RTF	radiotelephony
ETA	Estimated Time of Arrival	RVR	Runway Visual Range
ETD	Estimated Time of Departure	SAR	Search and Rescue
FAA	Federal Aviation Administration (USA)	SB	Service Bulletin
FDR	Flight Data Recorder	SSR	Secondary Surveillance Radar
FIR	Flight Information Region	TA	Traffic Advisory
FL	Flight Level	TAF	Terminal Aerodrome Forecast
ft	feet	TAS	true airspeed
ft/min	feet per minute	TAWS	Terrain Awareness and Warning System
g	acceleration due to Earth's gravity	TCAS	Traffic Collision Avoidance System
GPS	Global Positioning System	TGT	Turbine Gas Temperature
GPWS	Ground Proximity Warning System	TODA	Takeoff Distance Available
hrs	hours (clock time as in 1200 hrs)	UHF	Ultra High Frequency
HP	high pressure	USG	US gallons
hPa	hectopascal (equivalent unit to mb)	UTC	Co-ordinated Universal Time (GMT)
IAS	indicated airspeed	V	Volt(s)
IFR	Instrument Flight Rules	$V_1$	Takeoff decision speed
ILS	Instrument Landing System	$V_2$	Takeoff safety speed
IMC	Instrument Meteorological Conditions	$V_R$	Rotation speed
IP	Intermediate Pressure	$V_{REF}$	Reference airspeed (approach)
IR	Instrument Rating	$V_{NE}$	Never Exceed airspeed
ISA	International Standard Atmosphere	VASI	Visual Approach Slope Indicator
kg	kilogram(s)	VFR	Visual Flight Rules
KCAS	knots calibrated airspeed	VHF	Very High Frequency
KIAS	knots indicated airspeed	VMC	Visual Meteorological Conditions
KTAS	knots true airspeed	VOR	VHF Omnidirectional radio Range
km	kilometre(s)		
kt	knot(s)		

---

