

AAIB Bulletin

9/2025



**TO REPORT AN ACCIDENT OR INCIDENT
PLEASE CALL OUR 24 HOUR REPORTING LINE**

01252 512299

Air Accidents Investigation Branch
Farnborough House
Berkshire Copse Road
Aldershot
Hampshire
GU11 2HH
United Kingdom

Tel: 01252 510300

Media enquiries: 01932 440015 (office hours) / 0300 777 7878 (out of hours)

www.aaib.gov.uk

AAIB investigations are conducted in accordance with Annex 13 to the ICAO Convention on International Civil Aviation, assimilated EU Regulation No 996/2010 (as amended) and The Civil Aviation (Investigation of Air Accidents and Incidents) Regulations 2018.

The sole objective of the investigation of an accident or incident under these Regulations is the prevention of future accidents and incidents. It is not the purpose of such an investigation to apportion blame or liability.

Accordingly, it is inappropriate that AAIB reports should be used to assign fault or blame or determine liability, since neither the investigation nor the reporting process has been undertaken for that purpose.

AAIB Bulletins and Reports are available on the Internet
www.aaib.gov.uk

This bulletin contains facts which have been determined up to the time of compilation.

Extracts may be published without specific permission providing that the source is duly acknowledged, the material is reproduced accurately and it is not used in a derogatory manner or in a misleading context.

Published: 11 September 2025.

Cover picture courtesy of Niall Robertson

© Crown copyright 2025

ISSN 0309-4278

Published by the Air Accidents Investigation Branch, Department for Transport

CONTENTS

SPECIAL BULLETINS / INTERIM REPORTS

None

SUMMARIES OF AIRCRAFT ACCIDENT ('FORMAL') REPORTS

None

AAIB FIELD INVESTIGATIONS

COMMERCIAL AIR TRANSPORT

FIXED WING

None

ROTORCRAFT

None

GENERAL AVIATION

FIXED WING

None

ROTORCRAFT

None

SPORT AVIATION / BALLOONS

None

UNMANNED AIRCRAFT SYSTEMS

None

AAIB CORRESPONDENCE INVESTIGATIONS

COMMERCIAL AIR TRANSPORT

None

GENERAL AVIATION

Druine D.62B Condor	G-AXGV	20-Mar-25	3
Piper PA 46-350P	N3117J	18-May-25	4
Robinson R22 Beta	G-KKRN	3-Feb-25	9

CONTENTS Cont

AAIB CORRESPONDENCE INVESTIGATIONS Cont

SPORT AVIATION / BALLOONS

Pegasus Quik	G-CDOP	11-May-25	12
--------------	--------	-----------	----

UNMANNED AIRCRAFT SYSTEMS

Uvify IFO	n/a	29-Mar-25	14
-----------	-----	-----------	----

RECORD-ONLY INVESTIGATIONS

Record-Only UAS Investigations reviewed	June / July 2025	15
---	------------------	----

MISCELLANEOUS

ADDENDA and CORRECTIONS

None

List of recent aircraft accident reports issued by the AAIB	21
---	----

(ALL TIMES IN THIS BULLETIN ARE UTC)

AAIB Correspondence Reports

These are reports on accidents and incidents which were not subject to a Field Investigation.

They are wholly, or largely, based on information provided by the aircraft commander in an Aircraft Accident Report Form (AARF) and in some cases additional information from other sources.

The accuracy of the information provided cannot be assured.

Accident

Aircraft Type and Registration:	Druine D.62B Condor, G-AXGV	
No & Type of Engines:	1 Continental Motors Corp O-200-A piston engine	
Year of Manufacture:	1970 (Serial no: RAE/641)	
Date & Time (UTC):	20 March 2025 at 1148 hrs	
Location:	Croft Airfield, North Yorkshire	
Type of Flight:	Private (Training)	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - 1 (Serious)	Passengers - 1 (Serious)
Nature of Damage:	Aircraft destroyed	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	66 years	
Commander's Flying Experience:	1,288 hours (of which 1 were on type) Last 90 days - 2 hours Last 28 days - 1 hour	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The accident occurred on the approach to land during a biennial revalidation flight for the pilot flying, who was unfamiliar with the aircraft and the farm strip. The instructor was experienced with both the aircraft type and the farm strip.

After completing some general handling, the aircraft was flown back to the strip for a touch-and-go on Runway 27 with a forecast 5-10 kt crosswind from the left. The approach was made from a right hand circuit. The pilot was used to flying a biplane, so he decided to fly a curved tailwheel approach. As the aircraft descended below the tops of trees on the left of the approach to the runway, it started to drift toward the trees. The pilot flying turned the aircraft away from the trees, but one of the wings stalled, which rolled and pitched the aircraft nose-down. The stalled wing hit the ground, followed by the nose, before the aircraft came to rest upside down. The pilot recalled hitting his head twice on the canopy during this period.

Once the aircraft was made as safe as possible, they released themselves from their full harnesses. The pilot flying crawled out of the aircraft via the rear left window and lifted the left wing sufficiently for the instructor to exit the aircraft. They then called for assistance from the emergency services.

Although an initial assessment suggested they had sustained only minor injuries, further assessment at hospital found that both had suffered a neck vertebra fracture.

Accident

Aircraft Type and Registration:	Piper PA 46-350P, N3117J	
No & Type of Engines:	1 Pratt and Whitney PT6A-35 engine	
Year of Manufacture:	2005	
Date & Time (UTC):	18 May 2025 at 1730 hrs	
Location:	Kilkeel (Greencastle) Airfield, County Down	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 3
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Substantial damage to wing and parts of fuselage	
Commander's Licence:	Commercial Pilot's Licence	
Commander's Age:	44 years	
Commander's Flying Experience:	2,512 hours (of which 656 were on type) Last 90 days - 33 hours Last 28 days - 20 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Synopsis

The pilot lost sight of the runway centreline on rotation, with the aircraft drifting to the left and the wheels entering long grass next to the mown runway strip. He was unable to recover directional control and the aircraft hit an adjacent hedge and earth bank causing considerable damage. There were no injuries.

History of the flight

The pilot, together with three passengers, had planned to fly from Kilkeel Airfield in Northern Ireland to Fairoaks Airport near London, where the aircraft was based. Kilkeel Airfield has a single grass runway, which the airfield's website states is 750 m long and 5 m wide. The pilot reported the grass on either side of the runway strip as being very long. He described a dashed line down the runway to delineate the centreline, but no markings along the edge of the strip. The mown area opened out approximately halfway along the length of the runway to allow access to aircraft for parking and refuelling.

The pilot stated he had started his take off run from Runway 19 with the aircraft performing as expected. He commenced rotation just prior to the start of the wider mown area and believes the aircraft had then yawed slightly to the left. The aircraft had just become airborne when the strip narrowed again, with the left main gear wheel entering the long grass along the edge. This caused the aircraft to decelerate and yaw rapidly to the left, with

all three wheels contacting the ground again. The aircraft continued to yaw to the left, despite the pilot applying right rudder, and decelerated as it passed through the long grass. The pilot was unable to prevent the aircraft from hitting an adjacent hedge and earth bank, which broke off part of the wing and caused substantial damage to the fuselage. The passenger compartment, however remained intact and the pilot and passengers were able to exit, unaided and uninjured, through the main exit.

The pilot commented that on rotation the long nose of the aircraft obstructed his view forwards, and this coincided with the loss of peripheral guidance caused by the strip widening out into the parking area. This made it an increasing challenge to maintain directional control in an aircraft which produced significant torque on takeoff. He stated that, in hindsight, he should have rotated later to maintain better visual awareness of his position relative to the centreline. Despite being experienced at flying to grass runways, the pilot also stated he would restrict his flying to those with wider cleared strips in the future.

Accident

Aircraft Type and Registration:	Robinson R22 Beta, G-KKRN	
No & Type of Engines:	1 Lycoming O-320-B2C piston engine	
Year of Manufacture:	1989 (Serial no: 1201)	
Date & Time (UTC):	3 February 2025 at 1700 hrs	
Location:	Near Wokingham, Berkshire	
Type of Flight:	Training	
Persons on Board:	Crew - 2	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Empennage detached, significant damage to fuselage and rotors	
Commander's Licence:	Commercial Pilot's Licence	
Commander's Age:	54 years	
Commander's Flying Experience:	1,580 hours Last 90 days - 97 hours Last 28 days - 27 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Synopsis

At approximately 800 ft agl while approaching White Waltham, the trainee pilot inadvertently moved the fuel mixture control to the LEAN position instead of selecting the carburettor heating (carb heat) ON. The selection of LEAN caused the engine to stop. After immediately taking control, the instructor established the helicopter in autorotation but did not have sufficient time and height available to initiate an engine restart. While the helicopter experienced a partial rollover on landing, neither pilot was injured in the accident.

The risk of misidentification of the mixture control when selecting carburettor heating in the Robinson R22 Beta (R22) was first formally documented by the manufacturer in January 1981. The instructor was aware of the mis-selection risk and had briefed his student on the correct operation of the controls before the accident flight.

This accident is a reminder that, while risks can be identified and mitigated, the limitations of human performance mean lapses leading to risks maturing cannot be completely eradicated.

History of flight

The accident occurred on an R22 conversion course for a pilot who was already qualified on the Guimbal Cabri G2 (G2) helicopter type¹. On the morning of 3 February the trainee satisfactorily completed a general handling/familiarisation flight in G-KKRN.

The syllabus for the second flight included simulated emergency handling, engine out training and practice autorotations. Before flight the instructor briefed the trainee on all aspects of the exercises to be undertaken, including the risk of carburettor icing and the appropriate use of carburettor heating. On both flights, the trainee occupied the right seat and carried out the full start sequence, including checking the correct operation of the carburettor heating system.

The flight progressed as planned until the aircraft was being positioned to rejoin the circuit at White Waltham. Shortly after passing visual reporting point Sierra (M4 Junction 10) the instructor asked the trainee to descend to circuit joining height. He initially began descending without selecting carburettor heating ON so the instructor asked him to level off and reminded him of the need to select carburettor heating before entering a descent. The trainee was then instructed to continue the approach and descend. At this point, the trainee reached down and pulled what he thought was the carb heat control but was actually the mixture control. Realising his mistake, he called that he had “pulled the fuel” at which point the engine rpm was dropping rapidly. The instructor immediately took control and entered autorotation from approximately 800 ft agl.

Once autorotation had been established the instructor asked the trainee to push the mixture control back down to the fully rich position, the intent being to try an engine restart if time allowed. Having established the autorotation as his immediate priority, the instructor then focused on field selection. With the M4 motorway to his right, and trees and powerlines to his left, the only viable option was the ploughed field ahead. At this stage there was not enough height left to consider a restart, therefore the instructor concentrated on executing an engine-off landing at the slowest possible forward airspeed. He assessed that the helicopter was travelling at less than 5 kt when he levelled the skids just prior to ground contact. As the skids touched down, they dug into the soil and the helicopter tipped forward onto its nose before “gently” rolling to the right. During the period immediately after ground contact the main rotors struck the rear empennage, which detached from the helicopter and was thrown forward of the wreckage.

Neither pilot was injured in the accident, and both were able to self-evacuate through the left door (Figure 1).

Footnote

¹ He held a PPL(H) and had completed approximately 106 hours flying on the G2.



Figure 1

G-KKRN after the accident (image courtesy Thames Valley Police)


Aircraft description

G-KKRN is an R22 Beta, powered by the Lycoming O-320, a normally aspirated engine with manually operated carburettor heating². The carburettor heating control is located on the centre console aft and right of the cyclic stick boot (Figure 2).

The mixture control is positioned directly forward of the carb heat control, close to the bottom of the lower instrument panel and to the right of the PULL RT TRIM control (Figure 2). It is coloured red rather than black and has a different physical shape to the carburettor heating control. On top of the mixture control is a friction release button which, when pressed, allows the control to be moved. During the before start checks the mixture control is set to the FULL RICH position (fully down) and a plastic tubular guard is placed around the stem of the control. In normal operation, the mixture remains at FULL RICH until the after-landing shutdown checks when it is pulled upwards to the OFF position to stop the engine.

Footnote

² The R22 Beta II variant is powered by the Lycoming O-360 engine which has an automatically operated carb heat system. The G2 is also equipped with the O-360 engine featuring automatic carb heat operation.

**Figure 2**

Centre console controls

The mixture guard is a tactile physical barrier intended to reduce the risk of inadvertent mixture operation during flight. It is common practice for pilots to remove the guard when intentionally operating the mixture control. Some pilots temporarily stow it over the adjacent trim selector (Figure 3 (left)) before returning it to the mixture control on completion of the selection. It is possible to dislodge the guard with the control in the FULL RICH position if a pilot slides their index and middle finger under the mixture control and applies upward pressure (Figure 3 (right)).




Figure 3

Mixture control guard removed and stowed (left) and dislodged (right)

Inadvertent operation of the mixture control has been an identified risk for the R22 type for many years and was the subject of the manufacturer's Safety Notice SN-1, first published in January 1981 (Figure 4). This safety notice is further reproduced in Section 10 of the official R22 pilot's operating handbook published online³. The manufacturer's Operational Suitability Data document (OSD)⁴ 'provides the requirements for pilot training, checking, and currency specific to the R22 type rating.' Section 5.7 of the OSD lists 'Training Areas of special emphasis (TASE)' which training providers are required to comply with. The manufacturer explained that including the inadvertent actuation of the mixture control in the TASE had previously been considered and rejected. After a further review following this accident, they explained that:


'From a review of accident reports, the frequency of occurrence of accidents caused by inadvertent actuation of the mixture control is still relatively low compared to other accident causes also addressed in the Robinson Safety Notices and not included in the TASE. Furthermore, each additional TASE item dilutes the level of emphasis for existing items. Consequently, a revision to the TASE to include inadvertent actuation of the mixture control does not appear to be justified at this time.'

While not specifically referring to the potential for inadvertent mixture selection, the TASE states that it 'should be read in conjunction with the R22 POH, Robinson Safety Notices and the Robinson Maneuver [sic] Manual found with the R22/R44 Flight Training Guide.'

Footnote

³ Available at [R22 Pilot's Operating Handbook](#) [accessed 15 May 2025].

⁴ Operational Suitability Data (OSD) Flight Crew R22 RTR 165 December 2024. Available at [RTR 165 Operational Suitability Data - Flight Crew, Rev. 2](#) [accessed 15 May 2025].

**Figure 4**

Manufacturer's Safety Notice SN-1

Analysis

This accident resulted from the misidentification of a critical control by a qualified pilot who was inexperienced on type. The risk of misidentification was first formally documented by the manufacturer in January 1981. The instructor was aware of the mis-selection risk and had briefed his student on the correct operation of the controls before the accident flight. Nonetheless, the student's instinctive action, to operate the carburettor heating without first visually identifying the control, managed to overcome the safety barrier of the mixture guard and resulted in an unintended engine shutdown. With little time and height available to restart the engine, the instructor focused on establishing safe autorotation parameters. The instructor considered that, had the available touchdown location been on firmer ground the landing would have been completed without damage.

AAIB observation

This accident is a reminder that, while risks can be identified and mitigated, the limitations of human performance mean lapses leading to risks maturing cannot be completely eradicated. Faced with a challenging, unexpected and time-critical situation, the instructor appropriately prioritised establishing and flying the helicopter in autorotation ahead of attempting a restart.

Accident

Aircraft Type and Registration:	Pegasus Quik, G-CDOP	
No & Type of Engines:	1 Rotax 912ULS piston engine	
Year of Manufacture:	2005 (Serial no: 8129)	
Date & Time (UTC):	11 May 2025 at 0930 hrs	
Location:	Perth Airport	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Torn section of the trailing edge of the right side of the wing	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	67 years	
Commander's Flying Experience:	299 hours (of which 299 were on type) Last 90 days - 10 hours Last 28 days - 3 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Synopsis

The pilot was returning to Perth Airport after a local flight and reported the aircraft pitching and becoming difficult to control. On landing, he discovered damage to the right trailing edge of the wing. No other damage was reported to the aircraft and the pilot considered he may have collided with a UAV. It was noted that neither the pilot nor his passenger was wearing their diagonal seat harnesses.

History of the flight

The pilot was returning to Runway 09 at Perth Airport after a local flight with a passenger. He was at about 2,000 ft agl in the vicinity of Perth Racecourse, approximately 3 nm west of the airport and described how the aircraft suddenly "pitched to the right" as if he had "hit a deep pothole whilst driving". He reported the aircraft was difficult to handle and that when he tried to reduce speed it became unstable and shook. He stated it was also difficult to keep the aircraft straight whilst on the approach, although the pilot managed to carry out a successful landing. When taxiing after landing, the pilot noticed that there was damage to a section of the trailing edge on the right wing, with some tears in the material.

The aircraft was later inspected but no other damage was found, and it was reported that the damage to the wing was not considered to be due to an object coming off the aircraft or a strike by the aircraft's propeller. Without an obvious cause it was suggested that the

aircraft may have collided with a UAV. The pilot noted that the accident happened in the vicinity of a local event over which someone may have been flying a UAV, although there was no evidence that this was the case. There were black strike marks on the material adjacent to the tear on the wing, suggesting contact with a manmade object, rather than a bird. The pilot commented that he would in future avoid flying in the vicinity of outdoor events to avoid any UAVs which may be present.

Survivability

In providing information to the AAIB about the accident, it became apparent that neither the pilot nor his passenger had been wearing the diagonal restraint strap, relying instead on only the lap strap. The pilot was open in discussing this and stated that whilst he knew the passenger seat was fitted with a diagonal strap, he had not been aware that the pilot's seat was also fitted with such a strap. He stated that he had never worn a diagonal restraint strap during over 12 years of flying microlights despite having attended safety evenings where the importance of wearing such a restraint had been mentioned. In the pilot's opinion, wearing one would constrain full movement on the control bar. He had never been taught to wear one during his training and, in his experience, most microlight pilots did not wear one. He could not explain, however, why the passenger was not wearing their diagonal restraint when they did not need to operate the controls.

The importance of using upper body restraint whilst flying a microlight is explained in depth in an AAIB report concerning a fatal accident involving a Pegasus Quik registration G-CCPC on 1 June 2022¹. It appears that despite such accidents and an effort to raise awareness amongst the pilot community, there remains the need to break an existing culture that sees their use as a restriction.

Footnote

¹ https://assets.publishing.service.gov.uk/media/656707c7d6ad75001302fc6b/Pegasus_Quik_G-CCPC_01-24.pdf [accessed July 2025].

Serious Incident

Aircraft Type and Registration:	UAS Uvify IFO multirotor	
No & Type of Engines:	4 Uvify brushless electric motors	
Year of Manufacture:	2020 (Serial no: 203382IFOD0150100085)	
Date & Time (UTC):	29 March 2025 at 1926 hrs	
Location:	Durham	
Type of Flight:	Commercial Operations (UAS)	
Persons on Board:	Crew - None	Passengers - None
Injuries:	Crew - N/A	Passengers - N/A
Nature of Damage:	None	
Commander's Licence:	Other	
Commander's Age:	38 years	
Commander's Flying Experience:	52 hours (of which 51 were on type) Last 90 days - 6 hours Last 28 days - 0 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The unmanned aircraft (UA) was one of a swarm of 540 being flown within an area, about 50 m in diameter. A sterile flight area extended a further 60 m out in all directions.

During the flight, the UA began to climb, deviating from its intended flightpath to a height of 196 m, which was outside of the defined geofence. At this point, the motors automatically cut, and the UA fell to the ground, landing in a hedge 50 m beyond the sterile flight area boundary.

Investigations by the operator, UA control software developers and the UA manufacturer agreed that vibrations on the z-axis, possibly due a worn motor, led to incorrect GNSS and altitude estimations. The UA erroneously believed it was descending and so applied thrust to climb, resulting in it climbing out of formation with the other UAs.

Safety actions identified by the operator were to:

1. Inspect the motors on all of their UAs for signs of wear, and replace where necessary.
2. Collaborate with the hardware and software manufacturers to develop a fix that stops GNSS errors from causing the UA to go outside the geofence.
3. Increase the size of the sterile flight area until the above measures have been completed.

AAIB Record-Only Investigations

This section provides details of accidents and incidents which were not subject to a Field or full Correspondence Investigation.

They are wholly, or largely, based on information provided by the aircraft commander at the time of reporting and in some cases additional information from other sources.

The accuracy of the information provided cannot be assured.

Record-only UAS investigations reviewed: June - July 2025**22 May 2025 MA Freewing MiG-29 Fulcrum** Swanley, Kent

A scale model of a MIG 29, powered by an electric motor and ducted fan, suffered a battery disconnect in-flight due to a faulty connector. This caused the model to descend in an uncontrolled glide. It hit the ground on the far side of the M25 motorway from the model flying club field. The model flying club has strict procedures to avoid the motorway and this was the first occurrence in its 46 year history. The club has issued advice to all members warning about the faulty connector.

10 Jun 2025 Prototype Quad Copter Ashbourne, Derbyshire

The custom-built quad copter UA was being operated in a rural area for testing purposes, when it experienced a loss of power. The UA fell approximately 30 to 40 m, before striking the ground and incurring substantial damage. The operator is undertaking an investigation to determine the reason for the power loss.

18 Jun 2025 DJI Mavic 3T Near Hackney, Middlesex

While photographing a building, the UA struck the building and fell to the ground within a cordoned area. One propeller detached and the UA body and camera housing were damaged.

1 Aug 2025 DJI Phantom 4 RTK North Thoresby, Grimsby

The UA took off normally under the control of a remote pilot. As it reached its starting height, it began to transition across the site and began "barrelling forward". The UA did not respond to manual inputs or to a command to return automatically to the start point. It then fell from the sky and struck a van.

Miscellaneous

This section contains Addenda, Corrections
and a list of the ten most recent
Aircraft Accident ('Formal') Reports published
by the AAIB.

The complete reports can be downloaded from
the AAIB website (www.aaib.gov.uk).

TEN MOST RECENTLY PUBLISHED FORMAL REPORTS ISSUED BY THE AIR ACCIDENTS INVESTIGATION BRANCH

3/2015	Eurocopter (Deutschland) EC135 T2+, G-SPAO Glasgow City Centre, Scotland on 29 November 2013. Published October 2015.	2/2018	Boeing 737-86J, C-FWGH Belfast International Airport on 21 July 2017. Published November 2018.
1/2016	AS332 L2 Super Puma, G-WNSB on approach to Sumburgh Airport on 23 August 2013. Published March 2016.	1/2020	Piper PA-46-310P Malibu, N264DB 22 nm north-north-west of Guernsey on 21 January 2019. Published March 2020.
2/2016	Saab 2000, G-LGNO approximately 7 nm east of Sumburgh Airport, Shetland on 15 December 2014. Published September 2016.	1/2021	Airbus A321-211, G-POWN London Gatwick Airport on 26 February 2020. Published May 2021.
1/2017	Hawker Hunter T7, G-BXFI near Shoreham Airport on 22 August 2015. Published March 2017.	1/2023	Leonardo AW169, G-VSKP King Power Stadium, Leicester on 27 October 2018. Published September 2023.
1/2018	Sikorsky S-92A, G-WNSR West Franklin wellhead platform, North Sea on 28 December 2016. Published March 2018.	2/2023	Sikorsky S-92A, G-MCGY Derriford Hospital, Plymouth, Devon on 4 March 2022. Published November 2023.

Unabridged versions of all AAIB Formal Reports, published back to and including 1971,
are available in full on the AAIB Website

<http://www.aaib.gov.uk>

GLOSSARY OF ABBREVIATIONS

aal	above airfield level	kt	knot(s)
ACAS	Airborne Collision Avoidance System	lb	pound(s)
ACARS	Automatic Communications And Reporting System	LP	low pressure
ADF	Automatic Direction Finding equipment	LAA	Light Aircraft Association
AFIS(O)	Aerodrome Flight Information Service (Officer)	LDA	Landing Distance Available
agl	above ground level	LPC	Licence Proficiency Check
AIC	Aeronautical Information Circular	m	metre(s)
amsl	above mean sea level	mb	millibar(s)
AOM	Aerodrome Operating Minima	MDA	Minimum Descent Altitude
APU	Auxiliary Power Unit	METAR	a timed aerodrome meteorological report
ASI	airspeed indicator	min	minutes
ATC(C)(O)	Air Traffic Control (Centre)(Officer)	mm	millimetre(s)
ATIS	Automatic Terminal Information Service	mph	miles per hour
ATPL	Airline Transport Pilot's Licence	MTWA	Maximum Total Weight Authorised
BMAA	British Microlight Aircraft Association	N	Newtons
BGA	British Gliding Association	N _R	Main rotor rotation speed (rotorcraft)
BBAC	British Balloon and Airship Club	N _g	Gas generator rotation speed (rotorcraft)
BHPA	British Hang Gliding & Paragliding Association	N _i	engine fan or LP compressor speed
CAA	Civil Aviation Authority	NDB	Non-Directional radio Beacon
CAVOK	Ceiling And Visibility OK (for VFR flight)	nm	nautical mile(s)
CAS	calibrated airspeed	NOTAM	Notice to Airmen
cc	cubic centimetres	OAT	Outside Air Temperature
CG	Centre of Gravity	OPC	Operator Proficiency Check
cm	centimetre(s)	PAPI	Precision Approach Path Indicator
CPL	Commercial Pilot's Licence	PF	Pilot Flying
°C,F,M,T	Celsius, Fahrenheit, magnetic, true	PIC	Pilot in Command
CVR	Cockpit Voice Recorder	PM	Pilot Monitoring
DME	Distance Measuring Equipment	POH	Pilot's Operating Handbook
EAS	equivalent airspeed	PPL	Private Pilot's Licence
EASA	European Union Aviation Safety Agency	psi	pounds per square inch
ECAM	Electronic Centralised Aircraft Monitoring	QFE	altimeter pressure setting to indicate height above aerodrome
EGPWS	Enhanced GPWS	QNH	altimeter pressure setting to indicate elevation amsl
EGT	Exhaust Gas Temperature	RA	Resolution Advisory
EICAS	Engine Indication and Crew Alerting System	RFFS	Rescue and Fire Fighting Service
EPR	Engine Pressure Ratio	rpm	revolutions per minute
ETA	Estimated Time of Arrival	RTF	radiotelephony
ETD	Estimated Time of Departure	RVR	Runway Visual Range
FAA	Federal Aviation Administration (USA)	SAR	Search and Rescue
FDR	Flight Data Recorder	SB	Service Bulletin
FIR	Flight Information Region	SSR	Secondary Surveillance Radar
FL	Flight Level	TA	Traffic Advisory
ft	feet	TAF	Terminal Aerodrome Forecast
ft/min	feet per minute	TAS	true airspeed
g	acceleration due to Earth's gravity	TAWS	Terrain Awareness and Warning System
GNSS	Global Navigation Satellite System	TCAS	Traffic Collision Avoidance System
GPS	Global Positioning System	TODA	Takeoff Distance Available
GPWS	Ground Proximity Warning System	UA	Unmanned Aircraft
hrs	hours (clock time as in 1200 hrs)	UAS	Unmanned Aircraft System
HP	high pressure	USG	US gallons
hPa	hectopascal (equivalent unit to mb)	UTC	Co-ordinated Universal Time (GMT)
IAS	indicated airspeed	V	Volt(s)
IFR	Instrument Flight Rules	V ₁	Takeoff decision speed
ILS	Instrument Landing System	V ₂	Takeoff safety speed
IMC	Instrument Meteorological Conditions	V _R	Rotation speed
IP	Intermediate Pressure	V _{REF}	Reference airspeed (approach)
IR	Instrument Rating	V _{NE}	Never Exceed airspeed
ISA	International Standard Atmosphere	VASI	Visual Approach Slope Indicator
kg	kilogram(s)	VFR	Visual Flight Rules
KCAS	knots calibrated airspeed	VHF	Very High Frequency
KIAS	knots indicated airspeed	VMC	Visual Meteorological Conditions
KTAS	knots true airspeed	VOR	VHF Omnidirectional radio Range
km	kilometre(s)		



AAIB
Air Accidents Investigation Branch