

REPORT  
ON THE WRECK OF THE  
SS RICHARD MONTGOMERY

Maritime and Coastguard Agency  
Spring Place  
105 Commercial Road  
Southampton  
SO15 1EG

March 2000

## CONTENTS

EXECUTIVE SUMMARY.....	Page 3
------------------------	--------

### PART 1 HISTORY OF THE WRECK

Background.....	Page 5
Responsibility for the Wreck .....	Page 5
The Committee on Hazardous Wrecks .....	Page 5
The Explosives On Board .....	Page 6
Condition of the Explosives .....	Page 6
Risk of an Explosion.....	Page 6
The KEILCE Explosion .....	Page 7
Measures taken to Contain the Danger .....	Page 7

### PART 2 THE 1999 SURVEY OF THE WRECK OF THE SS RICHARD MONTGOMERY

Introduction.....	Page 8
Conduct of the Survey .....	Page 8
Scope of Work.....	Page 8
Technical Details of the Survey.....	Page 8
Analysis of the Survey Data.....	Page 9
Comparison with Previous Sonar Data .....	Page 10
Survey Conclusions .....	Page 11

### PART 3 CONSIDERATIONS FOR THE FUTURE

Introduction....	Page 12
Risks.....	Page 12
Effects.....	Page 14
Solutions.....	Page 15
Conclusions for the Way Forward .....	Page 18

### PART 4 RECOMMENDATIONS

Masts and Derricks .....	Page 19
Continual observation of the Wreck .....	Page 19
Survey of the Wreck.....	Page 19
Assessment of Risk .....	Page 19
Policy of Openness.....	Page 20

APPENDIX 1 MUNITIONS REMAINING ABOARD SS RICHARD MONTGOMERY	Page 21
---	---------

APPENDIX 2 THE KIELCE EXPLOSION.....	Page 22
--------------------------------------	---------

APPENDIX 3 MONOCHROMATIC GRADIENT PLOTS .....	Page 24
---	---------

1998 .....	Page 24
1999 .....	Page 25



## EXECUTIVE SUMMARY

1. The SS RICHARD MONTGOMERY grounded and split in two off Sheerness in 1944 whilst carrying a cargo of bombs. A large part of the cargo was successfully recovered at the time. No explosions occurred when the ship grounded or during the subsequent salvage operation, and none have occurred since.
2. It is probable that some of the munitions remaining on board are still capable of detonation but the likelihood of a major explosion is remote. Experts have consistently advised that the best way to keep the risk to an absolute minimum is to leave the wreck alone. The site is therefore designated a prohibited area under the Protection of Wrecks Act 1973.
3. Whilst the risk of a major explosion is remote, it is considered prudent to monitor regularly the condition of the wreck. Therefore routine surveys have been undertaken to assess the condition of the wreck and to check for any new signs of possible danger.
4. Until 1984 surveys were carried out by Ministry of Defence (MOD) salvage divers. More recently the surveys have been undertaken by commercial diving contractors, working under MOD supervision. Following the 1993 survey, in view of the limitations placed on such methods by the poor visibility under water at the site, and on the recommendation of the MOD Salvage Organisation, it was decided that full advantage should be taken of the major advances in sonar technology, in preference to the use of diving surveys. This policy has been followed for the last 5 years.
5. This survey, in 1999, was conducted on behalf of the Maritime and Coastguard Agency (an executive agency of the Department of Environment, Transport and the Regions) by Sonar Research and Development (SRD) Ltd of Beverley. It was completed in July 1999 under the supervision of the MOD's Salvage Organisation.
6. The survey of the wreck shows that there has been only minor changes in the structure of the wreck below surface. There have also been minor changes in the surrounding seabed topography.
7. The blocks and other debris associated with the masts and derricks were successfully removed during remedial work carried out by Medway Ports on behalf of the MCA in October 1999.
8. The future of the wreck is considered, pulling together the available knowledge from several reports. The risks associated with the wreck are identified as; collision by another vessel, capsize or significant movement of the wreck and the wreck breaking up. The effects of these risks are judged to be either a mass detonation of the remaining munitions or the distribution of munitions, with the possibility of some washing ashore.
9. Five basic scenarios to solve the problems are discussed; do nothing, monitor with non-intervention, containment, entombment and removal. A feasibility study is currently being undertaken by BMT Reliability Consultants (BMT) under contract to the MCA, to further assess the risks involved in these options.

10. The methods considered for the future management of the wreck are detailed below.

**1. Masts and Derricks**

That the masts, derricks and warning notices remain in situ, subject to ongoing inspection.

**2. Continual Observation of the Wreck**

That the continual close observation of the wreck is maintained in the foreseeable future.

**3. Survey of the Wreck**

That annual surveys should continue to be undertaken.

**4. Assessment of Risk**

A risk assessment study is currently being undertaken to cover the following points:

- The effects of a mass detonation of the remaining munitions under a variety of wind and tide conditions
- The conditions required for a mass detonation to occur
- The likelihood of those conditions occurring
- The possibility of the wreck breaking up
- The likely distribution of any escaped munitions
- Feasibility of a containment or entombment solution
- Feasibility of removing ordnance
- Feasibility of totally sanitising the wreck site

**5. Policy of Openness**

That information about the wreck be placed in the public domain, and that the results of the risk assessment are published to form part of a consultation exercise regarding the way forward in the long term.

## PART 1

### THE HISTORY OF THE WRECK

#### Background

1. The SS RICHARD MONTGOMERY was a Liberty ship, 441' 6" long and 7146 gross tons, of a mass-produced design not necessarily intended for more than a single voyage. She was built in 1943 by St John's River Ship Building Company, Jacksonville, Florida. The ship sailed from the USA to the UK as part of the convoy HX-301 in summer 1944 with a cargo of some 7000 tons of munitions. On arrival in the Thames Estuary the vessel was directed to anchor in the Great Nore Anchorage, off Sheerness. On almost the next tide, however, the ship's anchor dragged and it drifted on to a bank running east from the Isle of Grain (at 51° 78' 57" N 00° 47' 12" E) about 250 metres north of the Medway Approach Channel. The ship grounded amidships on the crest of the bank and - this being a weak spot in this design - shortly afterwards broke its back. The wreck now lies in some 15 metres of water, with the masts protruding at all states of the tide.
2. The wreck lies about one and a half miles from Sheerness and the Isle of Grain and five miles from Southend. It lies on a bank across the tide.
3. The wreck is not an obstruction to navigation - indeed, it serves to mark, for other shipping, the bank on which it grounded.
4. Intensive efforts were made after the grounding to unload the cargo and about half was removed. The two stern holds were probably emptied. The other holds were less accessible. When the wreck flooded, the salvage operation had to be abandoned. An investigation by the Southend Chamber of Trade<sup>1</sup> concluded that all of the fused bombs (situated in number 2 tween deck) had been cleared during the salvage operation. This information is considered inconclusive. The remaining cargo represents some 1400 tonnes of explosive material; the balance being the heavy bomb casings etc. The table at appendix 1 shows the best estimate of the disposition of the remaining explosives.

#### Responsibility for the wreck

5. The UK Government has assumed de facto responsibility for monitoring the wreck - firstly through the Board of Trade and, since 1983, through the Department of Transport (now DETR). It has relied upon expert advice provided by a Committee on hazardous wrecks comprising various experts from the Ministry of Defence, the Home Office and the Health & Safety Executive, together with the Port of London Authority and the Medway Ports. The Committee sought advice from US experts on

---

<sup>1</sup> E G WHITEBREAD, *SS Richard Montgomery*, 23 March 1973

the contents of the wreck, the design of the munitions carried, and the nature of the hazards they posed. The Committee is now formally disbanded, but the Department still has access to the experts if needed.

### **The Committee on Hazardous Wrecks**

6. The Committee's consistently firm advice was that no attempt should be made to disturb the site. In the Committee's opinion, any such action would increase the likelihood of the very explosion that must be avoided if at all possible.

### **The Explosives on Board<sup>2</sup>**

7. The Committee's advice was based on the most exhaustive information available about the types of explosives involved, and the likely effect upon them of age and/or contact with sea water. The bombs thought to be on board are of three types. The bulk are standard, un-fused TNT bombs. In addition, some 800 fused cluster bombs are believed to remain. These bombs were loaded with TNT. They could be transported fused because the design included a propeller mechanism at the front which only screwed the fuse into position as the bombs fell from an aircraft. These two types of bombs could therefore be handled - with care - when the accident occurred. There are also some smoke bombs on board (paragraph 10 below).

### **Condition of the explosives**

8. TNT does not react with water and is extremely stable, particularly if stored at a steady, low temperature. As it has been contained in metal bomb cases there has probably been little change in its chemical or explosive properties as a result of the long period of immersion.
9. When the condition of the munitions was first assessed there was considerable concern over the possibility of the formation of very sensitive copper compounds from reaction between the lead azide in the detonators with the brass components of the fuses of the cluster bombs. This would have been a possibility whilst the fuses contained significant amounts of air, however, as the fuses will probably all have been flooded for many years, and the sensitive compounds referred to are all soluble in water, this is no longer considered to be a significant hazard.
10. Following the 1996 survey a review was made by the Defence Evaluation and Research Agency, based on the information available, as to the probable condition of the munitions still remaining in the wreck. The review concluded that the munitions would retain their explosive power but would be no more sensitive than in their normal state. Any fuses present in the wreck would have deteriorated to the extent that they were no longer functional. The white phosphorus filling of the smoke bombs is stable under water but is capable of spontaneous ignition if exposed to the air.

### **Risk of an explosion**

11. The break in the ship has already exposed the contents of No 3 hold/tween deck, without an explosion occurring. There are two reasons why a cluster bomb fuse in an

---

<sup>2</sup> See Appendix 1

unstable condition could explode without even setting off the cluster bomb to which it is attached. 1) The fuse is not screwed into the main charge. 2) The main charge might now be wet or non-explosive. The same reasons make it still less likely that such a fuse could detonate the main cargo.

12. It is believed that, left to itself, the wreck will break up gradually. There is a good prospect that all the ordnance will get wet in this process and will become neutralised. Even if the water has not already rendered them inert, a small explosion at any distance from the wreck will not set off the bulk of the cargo. The risk would significantly increase, however, if the wreck were to be disturbed by moving it or attempting to unload it. It is hoped that the feasibility study will quantify this probability.
13. The risk of a major explosion is believed to be remote and is probably becoming even less likely with the passage of time. It may eventually pass altogether, but this is not likely to be for some considerable time. It would probably be very dangerous to try to find out the true situation within the wreck, particularly if this involved significant interference.

### **KEILCE explosion<sup>3</sup>**

14. The explosion of the munitions aboard the wreck of the KEILCE in 1967, reinforced the decision of the Committee on Hazardous Wrecks to recommend a policy of non-interference. The mass detonation of the cargo occurred after explosive cutting charges were fired during an attempt to clear the wreck. Appendix 2 gives fuller details of the incident.

### **Measures taken to contain the danger**

15. The site is the only one designated as a dangerous wreck under the Protection of Wrecks Act 1973. It is an offence to interfere with it in any way. This augments measures taken in the 1960s which included additional buoys and a Notice to Mariners designating the site as a "foul area" where trespassers would be liable to prosecution. Medway Ports at the Port of Sheerness keep a close watch on the site by sight and by Radar, and maintain the buoys and warning notices under contract to the Maritime and Coastguard Agency.

---

<sup>3</sup> See Appendix 2

## PART 2

### THE 1999 SURVEY OF THE WRECK OF THE SS RICHARD MONTGOMERY

#### INTRODUCTION

1. From time to time over some 25 years, and on the recommendation of the Committee on Hazardous Wrecks<sup>4</sup>, surveys of the wreck have been arranged in order to monitor conditions. The most recent survey was conducted in July 1999 by Sonar Research and Development (SRD) Limited under contract to the Secretary of State for the Environment, Transport and the Regions (DETR). The survey was organised by the Maritime and Coastguard Agency (MCA)<sup>5</sup> and was supervised by the Chief Salvage Officer to the Ministry of Defence (Navy). The survey made use of a high resolution electronic scanning sonar system developed by the contractor and linked to a microprocessor system to produce a detailed survey of the seabed, over a wide area in the vicinity of the wreck. Both the MOD and MCA were satisfied that the survey was properly and competently carried out in compliance with the contract.

#### CONDUCT OF THE SURVEY

2. A vessel owned by Associated British Ports (ABP) was used for the survey, which was conducted on 25 and 26 July 1999. The survey was carried out during a period of good weather. The survey area was in the lee of the Isle of Sheppey and sea conditions remained calm throughout the duration of the survey.
3. The survey area lies at the eastern extremity of Sheerness Middle Sand and is to the south of the Great Nore Anchorage and north of the Medway Approach Channel.

#### SCOPE OF WORK

4. SRD was contracted to survey the wreck of SS RICHARD MONTGOMERY and an area of 400 metres around the wreck. The company was required to locate, identify and map any loose wreckage and munitions on the seabed. The full work scope was completed.

#### TECHNICAL DETAILS OF THE 1999 SURVEY

##### Methodology of survey

5. The 1999 survey was undertaken on 25th & 26th July 1999, using SRD's Seabed Visualisation System. This system provides a continuous electronic scan of the seabed, fitted with 3 transducers using high and standard resolution. A sound velocity of 1519 ms<sup>-1</sup> was used. Data positions were established at 10 cm accuracy for high resolution data, and at 20 cm accuracy for standard resolution. Vertical positioning was to a resolution of 1 cm.

---

<sup>4</sup> The Committee on Hazardous Wrecks comprised experts from the Ministry of Defence, the Home Office and the Health & Safety Executive, together with the Port of London Authority and the Medway Ports

<sup>5</sup> MCA was formed on 1/4/98 by the merger of The Coastguard Agency and Marine Safety Agency

6. The survey was conducted using pre-set north/south run lines. Lines were run at 15 metre intervals and then 10 metre intervals generating a total of 56 lines to cover the whole survey area. Twelve shorter lines, run at 10 metre intervals were generated to cover the immediate vicinity of the wreck.

### **Reference points**

7. The Kinematic GPS base station was established at Sheerness, and primary positioning was provided by an Ashtech Z-Sensor RTK DGPS system, consisting of 1 base station and 1 rover station, with a VHF radio link.
8. Chart datum at Sheerness, 2.90 metres below Ordnance datum Newlyn was used as the sounding datum.
9. Tide readings were obtained using a portable SRD tide gauge with datum referenced to Sheerness. The data was compared with the permanent tide gauge at Sheerness, and a good agreement was obtained. The tidal direction was not measured, but was observed to be running strongly approximately east/west.

### **Data processing**

10. The data, once obtained using the Seabed Visualisation System, was processed using computer technology. The data was filtered to cut out 'noise', tides added, and a model was created by aligning adjacent swathes. Plans based on this information can be found amongst the graphics included here.

### **ANALYSIS OF THE SURVEY DATA**

11. The presence of the wreck on Sheerness Middle Sand has caused localised changes in the seabed topography. The wreck was examined in detail and appears stable although showed some minor, but possibly significant changes to the structure and surrounding seabed. Slight changes in the scouring, and the development of 2 holes in the seabed nearby were also noticed. An area of small contacts in the break of the wreck was again detected. The most noticeable change was an object which had fallen from the superstructure, possibly indicating decay.
12. Hydrographic surveys have shown, in general, that sand banks are at their shallowest over neap tide periods. This survey took place over the spring tide period to ensure that the survey vessel could pass over the wreck in safety at high water. Therefore the depths obtained over the shallowest parts of the banks might not necessarily be the least depths.
13. The monochromatic gradient plots in Appendix 3 reveal details of the ship's structure. These plots also reveal details of small seabed topographical features such as sand ripples over the area.
14. The following features within the survey area might be observed from the solid contour plot at Appendix 4:
  - **The Wreck Site**  
The wreck site occupies the central part of the survey area. It is the area enclosed by the 9-metre contour and may be considered to be the area of seabed topography most influenced by the presence of the wreck.

- **The Medway Dredged Channel**  
The Medway dredged channel occupies the southern part of the survey area, which is orientated in the region of 072°/252° and is bounded by the southernmost 9-metre contour in the survey area.
  - **The Sheerness Middle Sand**  
The Sheerness Middle Sand occupies the central part of the survey area. This sand bank is most extensive in the western part of the survey area. It is broken by the wreck site and continues to the east of the wreck site. The 6-metre contour of this feature is continuous to the north, and to the south this feature is continuous along the 8-metre contour.
  - **The Great Nore Anchorage**  
The Great Nore Anchorage forms a north eastern boundary to the survey area.
15. The survey shows that the 15-metre contour is more extensive than shown on the published chart. This contour now extends some 10 to 30 metres from the east side of the wreck into two elongations to the west side of the wreck. On the east side, the contour is at its maximum distance from the wreck opposite the centre part of each section. The elongation at the bow of the vessel extends some 80 metres on a bearing of 238° and at the stern, the elongation is shorter at only 25 metres to the south west. From the colour contour plot at Appendix 4 it can be seen that the shallowest parts of the wreck are at a similar depth to the shallow parts of the Sheerness Middle Sand.
16. When compared with the 1998 survey, which was also carried out at Spring tides, it can be seen that the scouring process which has effectively "sunk" the wreck over the last 55 years appears to be ceasing.

## COMPARISON WITH PREVIOUS SONAR DATA

### Seabed Terrain

17. The detailed differences between this survey and those conducted in 1996, 1997 and 1998 are as follows:
- The average depth for the survey area has remained almost constant between the 1998 and 1999 surveys. The majority of differences of depth of the seabed were within 0.20 metres. There was an average depth decrease of 0.10 metres within a 200 metre area of the wreck.
  - Material has continued to deposit on the west face of the sand bar to the east of the wreck. The maximum thickness of the deposited material is 1.2 metres. Material has also continued to be removed from the east face of the sand bar to the west of the wreck. Maximum thickness of removed material is 1 metre.
  - Two holes have developed in the seabed on the west side of the aft section. The maximum change in depth is 1.8 metres, and the area covered is 20 x 10 metres. The area between the holes is flat.
  - All of the features visible in the last two surveys have been found again during the 1998 survey.

- The object 2 metres across, situated 190 metres from the wreck at a bearing of 347° has been identified as an artefact of the wreck but is not clearly identifiable. This object is exposed but does not give rise to concern. It is too large to be an item of ordnance and appears to be a part of the vessel's structure, probably from the above decks superstructure.
- There has been a decrease of seabed support for both sections of the wreck. This is approximately 1% of the forward section and 2.5% for the aft section.

### Differences at the Wreck

18. No significant changes in position or orientation of the wreck were observed. The following points were noted:
- The crack in the starboard side of the forward section has again been detected. The crack in the port side of the forward section, detected in earlier surveys was not found although its presence could not be eliminated
  - Eight items of overhanging debris have been detected, These have been provisionally identified as derricks from forward and aft masts, and life-boat davits.
  - The debris located at the break in the wreck covered an area approximately 8 metres by 4 metres with a maximum height of 2 metres above the surrounding seabed. This was the same as in the 1996, 1997 and 1998 surveys. Debris has now been detected towards the starboard side of the break in the wreck. This has the dimension of approximately 2 metres x 2 metres, with a maximum height of 1.5 metres above the seabed. This appears to have fallen from the wreck's superstructure.
  - The objects situated to the west of the aft section are visible on the gradient chart. Inspection of the raw survey data has again revealed that the objects are not exposed but are affecting the surrounding seabed.

### SURVEY CONCLUSIONS

19. The inspection of the wreck shows that there has been no significant change in the structure below surface. An object has fallen from the superstructure on to the seabed, and 2 large holes have been observed on the seabed to the west of the aft section of the wreck.
20. The 1998 survey has indicated that the scouring of the seabed in the vicinity of the wreck is continuing as it has for the past 55 years. Between the 1996 and 1997 surveys, scouring occurred at the bow, the break, and at the stern of the wreck with accumulation in other areas. Further light scouring in the immediate vicinity of the wreck has occurred between the 1997 and 1998 surveys. Between the 1998 and 1999 surveys further slight scouring has occurred in the immediate vicinity of the wreck.
21. As a result of the four surveys, the following findings can be stated:
- The minor changes such as fallen superstructure observed in the 1999 survey may indicate deterioration of the structure. The localised changes in the seabed from

scouring and the development of new depressions show that the wreck remains a significant influence on the seabed topography in the survey area.

## PART 3

### CONSIDERATIONS FOR THE FUTURE

#### INTRODUCTION

22. This part of the report considers the future. It pulls together the available knowledge from several reports. The underlying problem lies with the munitions which remain aboard the wreck, their present condition, and what may happen to them in the future. It is fortunate in many ways that the SS RICHARD MONTGOMERY is a unique problem - a wreck containing a quantity of munitions close to a populated area. However, this uniqueness means there is no direct comparison to judge the possible effects of a mass explosion.
23. The MCA has commissioned a risk assessment on the long term future of the Richard Montgomery from BMT Reliability Consultants Ltd (BMT). This is in progress and will clarify the following options when it is completed. The study is intended to be complete within the current year.

#### RISKS

24. The risks associated with the wreck of the SS RICHARD MONTGOMERY can be divided into three broad areas associated with collision, capsize and breaking up of the wreck.

#### Collision

25. Another vessel colliding with the wreck could sufficiently disturb the munitions aboard to produce the conditions necessary for a mass explosion. The wreck is situated in two parts in a "hollow" in a sand spit and does not obstruct normal navigation. The cargo from the after part of the wreck, situated nearest the Medway Channel, is believed to have been salvaged in 1944. There are no records of near misses since the wreck occurred in 1944.
26. The Medway Approach Channel runs approximately 200 metres to the south of the wreck. During 1998 the Port of Sheerness logged 5,173 vessels inwards, excluding pleasure craft.
27. There are 5 designated anchorage positions in the Great Nore Anchorage. The centre of the closest anchorage "N1" is approximately 650 metres from the wreck and has a depth below chart datum of 13 metres variable. Anchorages 'N1' and 'N2' are virtually unused.

28. The Thames Estuary is a popular area for pleasure craft, with many small vessels using the Medway. Although small, those vessels with a shallow draft could pass over the wreck at high water, at low water there is the possibility of collision.
29. The present arrangements to avoid collisions include:
- designating the wreck as dangerous under the Protection of Wrecks Act 1973 and having an exclusion zone around the wreck.
  - marking this area by four navigational buoys with lights, with additional smaller buoys in between.
  - publicising the condition of the wreck by notices on charts and in Pilot books.
  - The masts are visible at all states of the tide; they form a vivid visual indication of the wreck's position and give a distinctive radar return. Loose debris and cargo blocks were removed by Medway Ports under contract to the MCA in October 1999, with the aim of extending the life-span of the masts.
  - Medway Ports have a Vessel Traffic Service (VTS) which uses radar to monitor vessel traffic in the Medway Approach Channel. It is under contract to MCA to provide radar coverage of the wreck site and warn vessels approaching the exclusion zone. Vessels requiring to use one of the Great Nore designated anchorages would do so as directed by the Medway Navigation Service (MNS).

#### **Capsize or Significant Movement of the Wreck**

30. The erosion of the seabed around the wreck could cause the capsize or significant movement of the vessel. This could have two effects; a mass detonation of the munitions, or the munitions could escape and be swept away by the tide.
31. The scouring in the vicinity of the wreck continues as it has for the past 55 years. In the last three years there has been some scouring at the bow, the break, and at the stern of the wreck with accumulation in other areas. The insignificant changes in depth between previous surveys indicates that the seabed surrounding the wreck is stable. It is probable the wreck is sitting on London clay which is the underlying bottom of the Thames Estuary. The surveys also find that there has been a slight increase in the seabed support for the hull (5% between 1995 and 1998). The 1999 survey reveals a very slight decrease in seabed support (1% at forward section and 2.5% at aft section). A reduction in seabed for support increases the risk of the wreck moving.
32. During the last 55 years there has been little change in the angle at which the vessel is lying on the sea bed, although scouring has occurred resulting in the apparent sinking of the vessel.
33. There are no physical measures presently taken to reduce the risk of capsize or movement of the wreck.

#### **Break Up**

34. The wreck has been subject to 55 years of deterioration. This has resulted in the loss of the vessel's superstructure. The results of the deterioration increase the risk that at some stage the wreck will lose its structural integrity and start to break up.
35. The structural failings which may occur are:
- loss of masts/derricks
  - a large crack in the hull
  - the loss of individual hull plates
  - the failure or collapse of a deck
36. There have been no studies into the forces being exerted on the vessel by the remaining cargo and the surrounding seabed. This is because there is insufficient knowledge of the disposition of the remaining cargo. The interior condition of the wreck does not allow for an internal investigation.
37. Should the vessel start to break up there is some risk that some, or all of, the munitions contained within the hull would be free to be swept away by the tides. This could result in individual munitions being washed ashore on beaches. This reduces the effect of a mass explosion from the remaining munitions, however, a new risk of individual munitions exploding or burning on beaches is created.
38. What munitions are free to move depends on what part of the wreck has broken up. There are two basic types of munitions which raise the most concern. The fused fragmentation bombs, which are the most likely to spontaneously detonate, are believed to be stowed in number 2 tween deck. The 100 lb. phosphorous bombs are stowed in the deep tanks in number 1 hold.
39. Number 2 hold is situated in the centre of the forward section of the wreck and will be prone to the greatest bending moments should the wreck move. There is a crack in the starboard side of number 2 lower hold and a similar crack in the port side, although not detected, cannot be ruled out.
40. The deep tanks situated in number 1 hold are constructionally some of the strongest parts of the vessel. It is probable that this part of the vessel will be the last to break up.
41. There are no physical measures presently taken to reduce the risks caused by the wreck breaking up apart from the recent trimming of the cargo blocks from the masts.

## EFFECTS

42. There are two effects which could result from disturbance of the wreck; a mass explosion of the munitions aboard, or the explosion or burning of isolated munitions. These are discussed below.

### Mass Explosion

43. The Defence Evaluation and Research Agency (DERA) have reviewed the information<sup>6</sup> available on the wreck and found that there have been a number of studies of the likely effects of a mass detonation of the munitions remaining in the wreck (equivalent to 1500 tonnes of TNT) either as the consequence of an accident or as the result of a planned disposal operation<sup>7</sup>.
44. The reports which estimated the effects of a mass explosion of the remaining cargo were both written some time ago. As there have been significant developments in computer programmes capable of modelling events of this type, it may now be possible to obtain a better risk assessment of the effect of a mass explosion under a variety of wind and tidal conditions than was previously available. This is currently being undertaken by BMT under contract to the MCA.
45. Whilst there is little data available that can be directly related to the particular situation with the Richard Montgomery, it has always been accepted that a mass explosion would put property and the local population at risk.

### Distribution of Munitions

46. The River Medway and approaches contain a great number of munitions from many sources. Recent dredging operations have produced a wide range of ordnance of both age and type, from cannon balls to a variety of shells, both real and practice. No ordnance which could be definitely identified as originating from the "Richard Montgomery" has been recovered. No modelling of the effects of the free movement of escaped munitions has been undertaken.
47. If escaped munitions wash ashore they will be prone to drying out. For the TNT or RDX explosives in the majority of the bombs the drying out of the explosives after a long period of immersion may render them more unstable. When phosphorus dries out it will spontaneously combust.

### SOLUTIONS

48. Five basic scenarios to solve the problem of the wreck ranging from "do nothing" through to the sanitising of the wreck site are identified.

#### Do Nothing

49. This option involves the ceasing of the present monitoring and the saving of the monitoring budget of £50k per annum. For this solution to work, the wreck would need to be assessed as having no risk of explosion. If this was accepted the wreck would no longer be designated as dangerous under the 1973 Protection of Wrecks Act.
50. Although having no cost, this option has the risk that compensation may have to be paid in the event of a mass detonation. There would be a cost associated with the neutralising of any munitions washed ashore following the break up of the wreck.

---

<sup>6</sup> DERA, *WSS/WX4/CR97625/1.0*, July 1997

<sup>7</sup> SLADE A C T, *Effects of detonation in the wreck SS Richard Montgomery*, WAE/121/06, 15 May 1970

TATE F E G, *The Richard Montgomery*, XB 243/1/3. 4 December 1975.

51. The assessment of the munitions aboard indicate that there is still a residual risk of explosion. This option has therefore to be discounted.

### Monitor With Non Intervention

52. This is the status quo option in which there is no intervention or measures taken to reduce risks; the wreck and surrounding seabed are regularly surveyed. This option has a regular and manageable cost, however, there is still the risk that compensation may have to be paid in the event of a mass detonation. There would be a cost associated with the neutralising of any munitions washed ashore following the break up of the wreck.
53. Although the seabed appears stable there is no guarantee that the annual surveys presently undertaken would give sufficient notice of movements caused by severe weather conditions. This solution has been used successfully for the past 55 years, but ultimately it cannot be the final solution.

### Containment

54. Under this option there are many possibilities depending on the desired achievement. These range from the use of placing a rigid structure around the wreck to the use of spoil from dredging operations.
55. There is a risk associated with any works on or near the wreck and this would need to be quantified before any approval could be given for work to proceed. The risk of causing a mass detonation by the works needs to be reduced to the same or smaller level than that existing at present.
56. Medway Ports are presently in the process of undertaking a feasibility study into dredging the approach channel to 12.5 metres depth. This will result in the Port Authority having to dispose of quantities of spoil from the dredging. It is their intention to use the spoil in a beneficial manner.
57. The use of a quantity of London clay to form a bund around the wreck site is a consideration under this option. London clay is classified as a rock due to its age and the fact that it has undergone compression through burial. It is described as a stiff silty clay not prone to erosion and would be a good material to form a long term natural barrier. The filling of the area between the bund and the wreck's hull with sand could also be considered. This would have the effect of supporting the structure of the wreck, while the partial burial and re-instatement of the Sheerness Middle Sand Bank would add protection against collision.
58. A 1971 report<sup>8</sup> stated:

---

<sup>8</sup> *Wreck of the SS Richard Montgomery off Sheerness. An investigation into the proposed schemes for protecting the wreck.* Hydraulics Research Station, Wallingford, Report number EX508.

“A protecting barrier around the wreck is feasible from a hydraulic standpoint although great care will have to be taken both in the design and in the construction of such a structure.”

59. The cost of undertaking this type of work has not been quantified. The specific nature of the solution, the underlying seabed condition and the effects of tides in the area of the wreck area are all being studied in the risk assessment.
60. The risks associated with the capsize of the vessel and the dispersing of munitions following a break up are reduced. There is the possibility, if using dredging spoil, that the work may need remedial action after a period of time. The monitoring of the seabed around the wreck would therefore need to be continued. This option would also require the consent and a licence under the Food and Environmental Protection Act (FEPA) from the Ministry of Agriculture Fisheries and Food (MAFF).

### **Entombment**

61. Essentially this is a deluxe version of containment, with a structure designed to completely enclose the wreck. To achieve complete entombment some form of rigid structure would be required.
62. There would probably be a greater risk with constructing and maintaining such a structure than with the containment option. Additionally as with any permanent structure there is the problem of how to proceed when it reaches the end of its design life. There is the possibility that further erosion of the seabed around the structure could occur. The monitoring of the seabed would therefore need to be continued. This option also has implication for changes in current flow around the structure as well as changes to environmental habitats.
63. The risk of mass detonation during the construction would be considerable, however, once completed, entombment would eliminate the risk of escaping munitions during the effective life-span of the structure.
64. The greater complexity of the structure and its “end of design life” problems mean that this solution may well prove not to be cost effective.

### **Removal**

65. The sanitising of the site is the most attractive environmental solution. This can be achieved in two ways; the removal of the remaining munitions or the complete removal of the wreck. Both these solutions would involve a high one-off investment with no ongoing costs after completion of the project.
66. There would be risks involved in the removal of the wreck. The possibility of mass detonation should be considered, although this is thought to be remote. There would be potential danger to contractors during procedures and total removal would take several years to complete. This is the only option which completely removes the problem and would involve no further cost.

## CONCLUSIONS FOR THE WAY FORWARD

67. There are three broad areas of risk associated with the wreck; another vessel colliding with the wreck, the wreck capsizing or moving significantly, and the breaking up of the wreck.
68. The risk of collision varies with the number of vessels passing close to the wreck. This will fluctuate with the success of the operations associated with the Medway Ports and with the number of pleasure craft. The various measures which have been in place for the past 55 years have contained this risk.
69. Erosion of the seabed around the wreck could cause capsize or significant movement. During the past 55 years there has been little change in the angle at which the wreck is lying, although scouring has resulted in the apparent sinking of the wreck. No physical measures have, or are being, taken to reduce this risk.
70. The wreck has been subject to 55 years of deterioration. At some stage structural failure will occur. This may consist of large cracks in the hull, the loss of individual plates, the failure or collapse of a deck. This risk will increase with time. Apart from the recent remedial work to trim the cargo blocks from the masts no measures have been taken to prevent the break-up of the wreck.
71. DERA have concluded it is probable that some of the munitions remaining on board are still capable of detonation but the likelihood of a major explosion is remote. Experts have consistently advised that the best way to keep the risk to an absolute minimum is to leave the wreck alone. However, the balance of risk between a mass

detonation and between individual munitions becoming free is slowly shifting with the latter becoming the more likely due to break up.

72. Five basic scenarios to solve the problem of the wreck ranging from “do nothing” through to the sanitising of the wreck site have been identified.
73. The feasibility study currently being undertaken by BMT on behalf of the MCA will consider all these options and possible associated effects, to ensure that all information is available before any intervention options are seriously considered.

## **PART 4**

### **RECOMMENDATIONS**

#### **MASTS AND DERRICKS**

74. The 1993 survey stated that the condition of the masts and derricks was such that serious consideration should be given to removing them in an attempt to stabilise the surrounding deck areas. Recent inspections of the masts found, however, that they remained sufficiently robust to leave largely undisturbed. As a consequence it was clear that the existing warning notices placed on the wreck should also remain in place. The 1997 survey indicated that minor “trimming” of the fixings to the masts (cargo blocks) might be necessary. This would have the effect of reducing the effects of wind and tide on the masts and help to preserve their integrity. The remedial work was effected by Medway Ports under contract to the MCA during October 1999. The existing warning signs were renewed in October 1999.

#### **RECOMMENDATION 1**

That the masts, derricks and warning notices remain in situ, subject to ongoing inspection.

#### **CONTINUAL OBSERVATION OF THE WRECK**

75. The wreck remains under close observation under a contract let by the Secretary of State for the Environment, Transport and the Regions to Medway Ports to provide for the continual 24-hour guarding of the wreck. The Company are well placed and equipped to undertake this role and the contract has been operating to the satisfaction of the Secretary of State.

#### **RECOMMENDATION 2**

That the continual close observation of the wreck is maintained in the foreseeable future.

#### **SURVEY OF THE WRECK**

76. The sonar surveys of recent years have produced repeatable data. They have identified some movement in the debris overhanging the vessel's sides. This indicates that any survey requiring manual intervention would be extremely dangerous. Although the seabed surrounding the wreck appears to be in a stable condition, some scouring and other structural changes do occur.

#### **RECOMMENDATION 3**

To monitor the seabed around the wreck an annual survey should continue for the foreseeable future.

#### **ASSESSMENT OF RISK**

77. There is no up-to-date assessment either of the risks associated with the present policy of not disturbing the wreck, or what effects a long term intervention may have. Without a quantified risk assessment it has not been possible to recommend a way forward that is based on sound principles. The risk assessment will need to consider cost, environmental impact and risks to stakeholders in the event of explosion.

#### **RECOMMENDATION 4**

The findings of the risk assessment are used as a basis for deciding on the long-term management of the wreck.

#### **POLICY OF OPENNESS**

67. In the past there has been a veil of secrecy surrounding the wreck and the risks involved. The public has not always been aware of the true facts and this led to scare articles appearing in the media. The MCA (and The Coastguard Agency before) have made available the results of the annual surveys, with copies being placed in the libraries of both Houses of Parliament and copies sent to Local Authorities.

#### **RECOMMENDATION 5**

That information about the wreck be placed in the public domain, and that the results of the risk assessment are published to form part of a consultation exercise regarding the way forward in the long term.



## MUNITIONS REMAINING ABOARD SS RICHARD MONTGOMERY

DERA in their summary report have listed the best estimates of the munitions which remain aboard the SS Richard Montgomery. The weights given in the table below are those of the explosive content of the cargo and not the shipped weight.

LOCATION	TYPE OF MUNITIONS	EXPLOSIVE WEIGHTS (TONNES)
<b>HOLD NO1</b>		
Deep tanks Aft	79 cases signals	3 (pyrotechnics)
	1429 cases wp 100lb smoke bombs	65 (white phosphorus)
Deep tanks Forward	30 Boxes boosters	31 (pyrotechnics)
	786 boxes signals	
Lower hold/tween deck	1407 500lb bombs TNT AN M64A1	167
	850 1000lb bombs TNT AN M65	208
	1500 250lb bombs TNT AN M57	84
<b>HOLD NO 2</b>		
Lower hold	1068 1000lb SAP bombs TNT AW-M59	140
	574 500lb SAP bombs AN M58	41
	286 2000lb GP TNT AN-M66	144
	588 1000lb AN M65	140
Tween deck	521-580 B260lb fragmentation bombs AN M81	9
	2297 cases of fragmentation bomb clusters	9
	AN M1A1 (6 x 20lb fused)	
	and/or AN M4A1 (3 x 23lb unfused)	
	and/or AN-M81 B260lb	
<b>HOLD NO 3</b>		
Lower hold/tween deck	1170 SAP 1000lb bombs	163
	406 GP 1000lb bombs	99
	1351 SAP 500lb bombs	97
	<b>TOTAL</b>	<b>1400 tonnes</b>

## THE KIELCE EXPLOSION

### BACKGROUND

1. In 1946 the Kielce, a ship of Polish origin, built in 1944, was on charter to the US forces, sailing from Southampton to Bremerhaven, when it was in collision and sank in the English Channel off Folkestone. The ship was of 1896 gross tonnage, 250 ft long, 41 ft berth and drawing just over 20 ft. It had a "full cargo of bombs and ammunition" although no cargo manifest has ever been traced.
2. In the early 1950s an unknown wreck was chartered at 51°02'20" N, 01° 13'33" E, and it was not until ten years later, when Trinity House awarded several contracts for the removal of wrecks in the Channel, that this was identified as the Kielce and confirmed to contain ammunition.
3. In 1966 the Folkestone Salvage Company was given a contract to clear the wreck, to give 50 ft clearance at MLWST, and part of the contract called for the dispersal of the explosive stores. During their preliminary work to clear collapsed hull plating, the Salvage Company fired two cutting charges on the hull without serious effect. On firing the third, however, at 1159 hours BST on 22 July 1967, a large explosion occurred which "brought panic to Folkestone's town and chaos to the beaches".

### THE EFFECTS OF THE EXPLOSION

4. At the time the Press and the local Police, were made aware of significant damage to various properties. Chimneys were damaged, slates dislodged and ceilings were cracked, but no case of personal injury was reported.
5. Meanwhile, the seismic effects of the explosion had been recorded by at least 25 observatories, throughout Europe and America, out to a distance of nearly 5000 miles from Folkestone, and from these records, using techniques which were developed for cataloguing the severity of earthquakes and other seismic disturbances, a magnitude of  $4\frac{1}{2} \pm \frac{1}{2}$  was allocated to the explosion.
6. By subsequent survey, the sea-bed crater formed by the explosion was found to be roughly elliptical with major and minor axes 153 and 67 ft respectively, the maximum depth 20 ft and with the "lips" rising to between 5 and 11 ft proud of the general level of the sea bed<sup>9</sup>.
7. The wreck had been lying in approximately 90 ft of water, on a sea bed of silt, when the explosion occurred. An acoustic signal was received at one station in the UK, whose amplitude was approximately one-thirtieth of that which would have been expected from a surface explosion of the magnitude from the seismic records. In other words, by far the larger proportion of the energy released was transmitted seismically

---

<sup>9</sup> The size of this crater is consistent with the figures predicted, as a result of US experience, for sea-bed craters formed by explosions with a yield of 2 kton.


(this was confirmed by the general absence of shattered windows, except those which were broken by the movement of the frames).

8. Two members of the staff of the Folkestone Salvage Company were in a small boat some 400 yds from the wreck when the explosion occurred, and they reported "a small ripple and some spray" - certainly not a large plume of water. However, there were a few reports of a "tidal wave" hitting the Folkestone beaches, resulting in a small number of successful claims for property damage on these beaches, although it has been computed that the amplitude of the resulting sea wave caused by the explosion would not have been greater than about 2 ft.

## THE YIELD

9. A magnitude of  $4\frac{1}{2}$  indicates a yield of 2000 tons of TNT, when fully contained in water or in a dense rock. The Kielce explosion was not fully contained although, as indicated above, a small proportion of the total energy release was propagated acoustically. Hence, although the total energy released may have been higher than expected from 2000 tons of TNT, the proportion of the energy propagated through the water and the sea-bed will have been equivalent to that released by that weight of explosive "fully contained".

MONOCHROMATIC GRADIENT PLOT 1998



# MONOCHROMATIC GRADIENT PLOT 1999

