



collided with the boundary hedge at approximately 15 mph. The total time from take-off to the accident was 35 minutes.

Approximately 3 flying hours prior to the accident one of the engine's cylinders had been replaced but detailed post-accident examination of the engine did not reveal any explanation for the juddering or reluctance to produce power.