

No: 10/89

Ref: EW/G89/08/05

Category: 1c

Aircraft Type and Registration: Isaacs Fury 2, G-PFAR

No & Type of Engines: 1 Continental Motors Corp O-200-A piston engine

Year of Manufacture: 1985

Date and Time (UTC): 8 August 1989 at 1200 hrs

Location: Hayrish Farm, South Taunton, Somerset

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Damage to wings, fuselage, propeller and engine mounting

Commander's Licence: Private Pilot's Licence

Commander's Age: 41 years

Commander's Total Flying Experience: 160 hours (of which 57 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was landing in good weather in a light wind on a grass runway. Very soon after touchdown the aircraft ran over a slight bump, which caused it to swing to the left. The pilot applied power and full right rudder but was unable to prevent the aircraft leaving the runway and colliding with a hedge.