



RECONSTRUCTION DRAWING SHOWING MAJOR PARTS WHICH BECAME DETACHED IN THE AIR




The parts shaded became detached in the air.

FIG. 1.




*Left Wing Showing Compression Collapse Of Spar (Download)*

*Fig 2.*




*Right Hand Wing Lower Spar Showing Compression Buckle And Fracture*




*Elevator Centre Hinge Bracket Showing Rearwards Twist  
And Elongation Of Bolt Holes.*

*Fig 4.*




*Left Hand Hole.*



*Right Hand Hole.*

*Enlarged View Of Bolt Holes Showing Wear And Elongation.*

*Fig 5.*



*Showing Sheared Bolts Tail-Fin Attachments.*