



Fig. 1




Showing differences in heads of valves




Showing fractured anchorage lug and incorrect routing of locking wire

Fig 2.

Fig 3.



Fuel filter bowl assembly showing fractured anchorage lug and incorrect wire locking



(Example)  
Correct single  
sealing washer  
2 mm thick  
when new

Disassembled filter bowl showing two thin and damaged cork sealing washers

Fig 4.