



The cause of the power failure has not been determined, but the pilot considers that fuel starvation was the most likely cause. The Southend METAR at 1220 hrs included haze and a temperature of 05°C with a dewpoint of 04°C. These conditions are conducive to serious carburettor icing at any power.