Spitfire IXT, G-LFIX

AAIB Bulletin No: 6/2000 Ref:EW/G2000/03/21 Category:1.2

Aircraft Type and Registration: No & Type of Engines: Year of Manufacture: Date & Time (UTC): Location: Type of Flight:	Spitfire IXT, G-LFIX 1 Rolls-Royce Merlin 25 piston engine 1944 31 March 2000 at 1256 hrs Duxford Airfield Private
Persons on Board:	Crew 1 - Passengers - None
Injuries:	Crew None - Passengers - N/A
Nature of Damage:	Damage to three of the Spitfires propeller blades and a
Commander's Licence: Commander's Age: Commander's Flying Experience:	portion of the nosecone. Substantial damage to the helicopters left side Private Pilots Licence 48 years 703 hours (of which 285 were on type) Last 90 days - 10 hours
	Last 28 days - 9 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot. Visit to Duxford Airfield by an AAIB Inspector

TheSpitfire pilot planned a practice display flight at Duxford Airfield,Cambridgeshire in preparation for the coming summer display season. Whilst the Spitfire was taxiing for take offa Bell 206 helicopter arrived at the airfield and was parked on the H on thegrass between the paved taxiway and the grass runway in front of the tower.

Afterthe display the Spitfire landed on grass Runway 24 and taxied on the grassbehind a number of parked aircraft toward a parking place at the north-east of theairfield. The Spitfire pilot usednormal tailwheel taxiing technique, weaving the aircraft from side to side inorder to clear the area ahead. Butafter passing the last of the parked aircraft to its left side the Spitfirestruck the Bell 206 helicopter almost head-on. The collision caused damage to three of the Spitfires propeller bladesand a portion of the nosecone, and substantial damage to the helicopters leftside.

TheH parking position at Duxford has been in use for many years and is located approximately one third of the distance between the paved taxiway and the grassrunway, at the southern edge of the area as a grass taxiway parallel to Runway24. Since the accident Duxford AirfieldManagement are to consider means by which increased separation can be achieved between helicopter parking and the grass taxiway.