



torque link were extremely stiff and appeared to lack adequate lubrication. The complete landing gear assembly was returned to the manufacturer for further examination.