

BAe 146, HB-IVY

AAIB Bulletin No: 8/99 Ref: EW/G99/05/40 Category: 1.1

Aircraft Type and Registration: BAe 146, HB-IVY

No & Type of Engines: 4 Lycoming ALF-502 turbofan engines

Year of Manufacture: N/A

Date & Time (UTC): 27 May 1999 at 2050 hrs

Location: London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Crew - N/A - Passengers - N/A

Injuries: Crew - None - Passengers - None

Nature of Damage: Aft fuselage punctured

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: N/A

Commander's Flying Experience: N/A

Information Source: Report submitted by Airfield Operations Safety Unit

An electric tug was bringing bags to the rear hold of the aircraft but on attempting to brake the driver's foot slipped off the brake pedal and the tug continued forward and struck the fuselage.