


ACCIDENT SITE PHOTOGRAPHS



1. Main Wreckage



2. Tail Rotor Assembly



POWER TRAIN SYSTEM

LONG DRIVE SHAFT FAILURES

