## MD 87, VP-BOP

AAIB Bulletin No: 12/99 Ref: EW/G99/09/15 Category: 1.1

Aircraft Type and Registration: MD 87, VP-BOP

**No & Type of Engines:** 2 JT8D-219 turbofan engines

Year of Manufacture: 1988

Date & Time (UTC): 10 September 1999 at 1525 hrs

**Location:** Stansted Airport, Essex

**Type of Flight:** Public Transport

**Persons on Board:** Crew - 5 - Passengers - 62

**Injuries:** Crew - None - Passengers - None

**Nature of Damage:** Severe buckling of the skin and window belt panel in the area

of the right side service door

**Commander's Licence:** Airline Transport Pilot's Licence

**Commander's Age:** 51 years

**Commander's Flying** 

**Experience:** 

9,100 hours (of which 2,100 were on type)

Last 90 days - 120 hours

Last 28 days - 35 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft had parked on Stand 504 at London Stansted Airport and the passengers were disembarking. A catering vehicle approached the aircraft from the right side at the service door location and struck the aircraft with some force. The vehicle driver had taken his foot of the clutch with the vehicle still in gear allowing it to lurch forward. Following advice from the repair organisation the aircraft was flown to Shannon for repair.