

ACCIDENT

Aircraft Type and Registration:	Jabiru UL-450, G-BYYT	
No & Type of Engines:	1 Jabiru Aircraft PTY 2200A piston engine	
Year of Manufacture:	1999	
Date & Time (UTC):	13 June 2009 at 1805 hrs	
Location:	Hayward Private Airstrip, Herefordshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Nose gear, left wingtip and propeller damaged	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	59 years	
Commander's Flying Experience:	397 hours (of which 75 were on type) Last 90 days - 8 hours Last 28 days - 4 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The pilot was making an approach to Runway 22 in a light south-westerly wind. As the aircraft touched down on the grass runway, a gust of wind took it off the centreline. The pilot attempted to regain the centreline and to slow the aircraft with the brakes. The right brake

proved more effective than the left, causing the aircraft to enter a skid, during which the nose gear detached and the left wingtip contacted the ground. The aircraft then departed the right side of the runway and collided with tree saplings; the pilot was uninjured.