INCIDENT

Aircraft Type and Registration: Airbus A310, F-OJHH

No & Type of Engines: 2 General Electric CF6-80 C2A2 turbofan engines

Year of Manufacture: 1991

Date & Time (UTC): 24 November 2006 at 2043 hrs

Location: On approach to Birmingham Airport

Type of Flight: Public Transport (Passenger)

Persons on Board: Crew - 11 Passengers - 84

Injuries: Crew - None Passengers - None

Nature of Damage: None

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 59 years

Commander's Flying Experience: 9,748 hours (of which 2,950 were on type)

Last 90 days - 278 hours Last 28 days - 91 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

Synopsis

The aircraft was being radar vectored for an ILS approach to Runway 15 at Birmingham Airport. The radar controller had cleared the crew to descend to an altitude of 2,500 ft, but noticed that the aircraft continued to descend below the cleared altitude. He instructed the crew to climb and repeated the QNH, which the crew had not set. With the correct QNH set the aircraft climbed and levelled at 2,000 ft, as instructed by the controller. Having intercepted the localiser they were cleared to descend with the ILS and a normal landing was completed.

History of the flight

The aircraft was on a scheduled flight from Tehran to Birmingham Airport. The commander was the Pilot Flying (PF) and the co-pilot was the Pilot Not Flying (PNF). The crew contacted the Radar controller at 2037 hrs as they were approaching FL80. They confirmed that they had received the ATIS and repeated the QNH of 982 hPa. They were instructed to maintain FL80 and their present heading.

The controller intended to provide radar vectors for the aircraft to intercept the localiser for Runway 15 at a distance of 9 nm. At 2038 hrs he cleared the aircraft to descend to an altitude of 4,000 ft on the QNH of 982 hPa, which the PNF acknowledged correctly. During this descent, the aircraft was cleared to descend further to an altitude of 2,500 ft and this was again acknowledged correctly by the PNF.

© Crown copyright 2007

At 2043 hrs the crew were instructed to turn right onto a heading of 060° and to reduce speed to 180 kt; the aircraft turned onto the base leg and continued its descent. The controller, who was also controlling several other aircraft, saw F-OJHH descend through 2,500 ft. He transmitted "5020 CLEARED ALTITUDE TWO THOUSAND FIVE HUNDRED FEET SAY AGAIN TWO THOUSAND FIVE HUNDRED FEET". PNF responded, "TWO FIVE HUNDRED 5020 TWO THOUSAND FIVE HUNDRED". Seeing the aircraft still descending the controller transmitted "YES IF YOU COULD CLIMB BACK UP TO TWO THOUSAND FIVE HUNDRED PLEASE AND TURN RIGHT NOW ONTO ONE TWO ZERO DEGREES". The PNF responded to the instruction after a short pause. Seeing the aircraft still descending, the controller repeated, "5020 YOU ARE STILL DESCENDING CLIMB TWO THOUSAND FIVE HUNDRED FEET ACKNOWLEDGE". This was acknowledged again by the PNF but the aircraft still continued to descend. The controller instructed the crew that there was a mast 4 nm due east of their position which was 1,358 ft amsl, and that they should climb immediately. The PNF acknowledged this instruction.

Suspecting that the crew had not set the QNH, the controller transmitted "5020 QNH 982 CONFIRM YOU ARE INDICATING ONE THOUSAND FIVE HUNDRED FEET". At this point the crew realised that the altimeters were still set to the standard pressure setting of 1013 hPa and not the Birmingham QNH of 982 hPa. The PF initiated a climb and he and the PNF set the Birmingham QNH and crosschecked the altimeters. The PNF informed the controller "JUST GOT IT NOW AND CLIMBING READING 2,000 FEET". The controller responded "YOU CAN LEVEL OFF AT TWO THOUSAND FEET PLEASE TO INTERCEPT THE GLIDEPATH AT NINE MILES YOU ARE NOW CLEAR OF THE TV MAST". The PNF acknowledged the

instruction and they were then cleared to descend on the ILS. The crew continued with the approach and landed without further incident.

Weather

The synoptic situation at 2100 hrs on the day of the incident showed a low pressure system (969 hPa) centred near Eire. A broad warm sector was covering the southern half of the British Isles with a light to moderate south-south-westerly flow over the Midlands and Southern England. Weather conditions over the Midlands were cloudy with outbreaks of rain, mainly in the West Midlands. The surface visibility was generally 25 km but locally 10 to 15 km in rain. The mean sea level pressure in the Birmingham area was 982 hPa with the Barnsley Regional Pressure Setting, valid from 2000 hrs to 2100 hrs, of 974 hPa.

The 2020 hrs weather report at Birmingham Airport recorded a surface wind from 160° at 10 kt, with the visibility greater than 10 km in light rain, few cloud at 1,600 ft with scattered cloud at 2,200 ft, the temperature was 12°C, the dew point was 11°C and the QNH was 982 hPa.

Altimeter setting

The Standard Operating Procedure (SOP) for altimeter setting in the descent was set out by the operator in the descent checklist of the normal procedures. This requires both the PF and PNF to set the QNH when cleared by ATC to descend from a flight level to an altitude.

Analysis

The crew had not changed the altimeter setting from the standard setting of 1013 hPa to the Birmingham QNH of 982 hPa when first cleared to descend from a flight level to an altitude. Based on an average height of 30 ft per hPa, a height difference of 930 ft existed between the

© Crown copyright 2007

aircraft actual altitude and that indicated on the altimeters. Consequently, thus when the altimeters were indicating 2,500 ft the aircraft had actually descended to 1,570 ft. As the aircraft continued its descent below its cleared level of 2,500 ft the radar controller notified the crew and warned them of the mast ahead. Having realised that the altimeter sub scale setting was incorrect the crew

initiated an immediate climb, re-set the altimeters to the correct QNH and followed the controller's instructions.

The crew could not recall any distractions or unusual flight deck activity at the point at which they would normally have adjusted the altimeter sub-scales.

© Crown copyright 2007