

Corrigendum to Bulletin 1/86

G-BEUX Page 8

Last Line should read:—

“It has not been determined why it was not possible to lower the starboard flap (which is directly driven by the motor) after failure of the port flap drive cable.”