

Fokker F100-650, G-BVJC, 3 August 1996

AAIB Bulletin No: 12/1996

Ref: EW/G96/08/02 Category: 1.1

Aircraft Type and Registration:	Fokker F100-650, G-BVJC
No & Type of Engines:	2 Rolls Royce Tay 650-15 turbofan engines
Year of Manufacture:	1994
Date & Time (UTC):	3 August 1996 at 1900 hrs
Location:	Stand B2, Terminal 1, London Heathrow Airport
Type of Flight:	Public Transport
Persons on Board:	Crew - 6 - Passengers - 106
Injuries:	Crew - None - Passengers - None
Nature of Damage:	Damage to lower left corner of forward service door
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	53 years
Commander's Flying Experience:	13,900 hours (of which 1,200 were on type) Last 90 days - 126 hours Last 28 days - 37 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and information from the Metropolitan Police Heathrow

The aircraft was being prepared for a scheduled service flight to Glasgow. The loading platform of a catering high-lift vehicle came into contact with the lower left corner of the service door causing slight bending of the door. The aircraft was taken out of service for repair.