Recommendation(s) Status: Station over-run at Haywards Heath

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

Key to Recommendation Status

| Implemented: | All actions to deliver the recommendation have been completed. | |
|----------------------------|--|--|
| | | |
| Implemented by alternative | | |
| means: | during the investigation. | |
| | | |
| Implementation ongoing: | Work to deliver the intent of the recommendation has been agreed and is in the process of being delivered. | |
| | | |
| In-progress: | The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is in place to implement the recommendation; and work is in progress to provide this. | |
| | | |
| Non-implementation: | Regulation 12(2)(b)(iii) = recommendation considered and no implementation action to be taken. | |
| Awaiting response: | Awaiting initial report from the relevant safety authority or public body on the status of the recommendation. | |


RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following.



The red triangle shows recommendations where the RAIB has concerns that no actions have been taken in response to a recommendation.



The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.



Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

| Number/ Date/ Report No/ Inv Title / Current Status | | Safety Recommendation | Summary of current status (based on latest report from the relevant safety authority or public body) |
|--|---|--|---|
| | 12/01/2006 10/2006 wer-run at Haywards Heath nplemented | First Capital Connect (formerly Thameslink) and Southern should arrange for an inspection mirror to be used when examining the interior of the drum switch. This recommendation has already been implemented (paragraphs 31, 32, 34 and 35). | First Capital Connect has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate. |
| 2 | 12/01/2006 10/2006 | Alstom to review procedures, processes and equipment in order to identify aneffective means of preventing loose material from | Alstrom has reported that it has taken actions in response to this |
| Station over-run at Haywards Heath | | interfering with the operation of the drum switch (paragraphs 24, 25 and 31). | recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate. |
| Status: In | nplemented | • | · |

02 November 2015 Page 2 of 2