

## Recommendation(s) Status: Collision near Burton on Trent




This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

### Key to Recommendation Status

<b>Implemented:</b>	All actions to deliver the recommendation have been completed.
<b>Implemented by alternative means:</b>	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB during the investigation.
<b>Implementation ongoing:</b>	Work to deliver the intent of the recommendation has been agreed and is in the process of being delivered.
<b>In-progress:</b>	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is in place to implement the recommendation; and work is in progress to provide this.
<b>Non-implementation:</b>	Regulation 12(2)(b)(iii) = recommendation considered and no implementation action to be taken.
<b>Awaiting response:</b>	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following:

-  The red triangle shows recommendations where the RAIB has concerns that no actions have been taken in response to a recommendation.
-  The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.
-  The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

Number/ Date/ Report No/ Inv Title / Current Status	Safety Recommendation	Summary of current status (based on latest report from the relevant safety authority or public body)
1            01/08/2007    01/2008 Collision near Burton on Trent  Status: Implemented	EWS should put in place a system to assure itself that damaged stanchions are detected and replaced by its load examiners (paragraph 64b).	EWS has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
2            01/08/2007    01/2008 Collision near Burton on Trent  Status: Implemented	EWS should revise its manual and procedures to require the detection and replacement of damaged stanchions, where possible by those responsible for loading and unloading wagons, and by train preparers before every despatch (paragraph 65a).	EWS Network Rail has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
3            01/08/2007    01/2008 Collision near Burton on Trent  Status: Implemented	EWS should revise its manual and procedures so they define the type of damage that would require a stanchion to be replaced using pass/fail criteria, diagrams or photographs (paragraph 65b).	EWS has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
4            01/08/2007    01/2008 Collision near Burton on Trent  Status: Implemented	EWS should evaluate the practicability of using stanchions similar in height to their associated loads and, if practicable, revise its manual, procedures and stanchion specifications accordingly so that the relevant members of staff are able to select stanchions appropriate in height to their loads (paragraph 65c).	EWS has carried out a review in response to this recommendation. EWS proposes no further action. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate. ORR has closed the recommendation.