

ACCIDENT

Aircraft Type and Registration:	SLA 80 Executive, G-CEII	
No & Type of Engines:	1 Rotax 912-UL piston engine	
Year of Manufacture:	2007 (Serial no: 10107)	
Date & Time (UTC):	28 January 2016 at 1330 hrs	
Location:	Brighton Aerodrome, North Yorkshire	
Type of Flight:	Private	
Persons on Board:	Crew - 2	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Left landing gear	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	31 years	
Commander's Flying Experience:	1,541 hours (of which 15 were on type) Last 90 days - 59 hours Last 28 days - 26 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The aircraft was landing on grass Runway 28 at Brighton Aerodrome; the wind was from 230° at 10 kt. The pilot, who was accompanied by an instructor, reported that "low-level windshear" had resulted in the aircraft touching down heavily before bouncing. The instructor took control and flew a go-around before positioning to land. During the subsequent landing the left main gear collapsed.