ACCIDENT

Aircraft Type and Registration: Socata TB10 Tobago, G-HELA

No & Type of Engines: 1 Lycoming O-360-A1AD piston engine

Year of Manufacture: 1980 (Serial no: 135)

Date & Time (UTC): 25 September 2016 at 1400 hrs

Location: Breighton Aerodrome, Yorkshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Right wing and navigation light, upper and

lower right wing skin surfaces and aileron

Commander's Licence: Private Pilot's Licence

Commander's Age: 52 years

Commander's Flying Experience: 311 hours (of which 198 were on type)

Last 90 days - 24 hours Last 28 days - 7 hours

Information Source: Aircraft Accident Report Form submitted by the

pilot

After landing at Breighton Aerodrome, and while manoeuvring the aircraft to park on the grass parking area, the right wingtip contacted a wooden fence. The pilot reported that he had misjudged the proximity of the fence. The aircraft sustained damage to the right wing but the pilot was uninjured.

© Crown copyright 2016 72