ACCIDENT

Aircraft Type and Registration: Skyranger 912(2) Skyranger, G-INCE

No & Type of Engines: 1 Rotax 912-UL piston engine

Year of Manufacture: 2003 (Serial no: BMAA/HB/270)

Date & Time (UTC): 26 August 2016 at 1630 hrs

Location: Hackford, Wymondham

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Fuselage, landing gear and right wing damage,

engine shock-loaded

Commander's Licence: National Private Pilot's Licence

Commander's Age: 44 years

Commander's Flying Experience: 126 hours (of which 70 were on type)

Last 90 days - 10 hours Last 28 days - 6 hours

Information Source: Aircraft Accident Report Form submitted by the

pilot

The aircraft approached the airfield to land in a southerly direction in weather reported as fine with wind from 220° at 3.5 kt. As the aircraft approached the runway, the pilot reported that a gust of wind from the right pushed him towards a tree on the left side of the runway. The aircraft clipped this tree with its left wingtip.

Despite applying full power and commanding right roll and rudder, the aircraft continued to bank left. As the aircraft was then approaching power lines, the pilot elected to reduce power and land the aircraft in a field of maize. The pilot, who was wearing a full harness, escaped with minor injuries.

© Crown copyright 2017 65