ACCIDENT

Aircraft Type and Registration: Silence Twister, G-TWSS

No & Type of Engines: 1 Jabiru 2200A piston engine

Year of Manufacture: 2008 (Serial no: PFA 329-14608)

Date & Time (UTC): 5 June 2016 at 1800 hrs

Location: Wing Farm Airstrip, Warminster, Wiltshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Fire damage to engine and engine bay

Commander's Licence: Private Pilot's Licence

Commander's Age: 53 years

Commander's Flying Experience: 2,250 hours (of which 42 were on type)

Last 90 days - 43 hours Last 28 days - 14 hours

Information Source: Aircraft Accident Report Form submitted by the

pilot

During an attempt to start the engine, and after about 5 seconds of cranking, smoke appeared above the engine cowling. The pilot turned off the fuel and fuel pump while continuing to crank. He then turned off the electrics and ran to a hangar to get a fire extinguisher. He returned to the aircraft about 20 seconds later and was able to extinguish the fire (Figure 1). The fault was traced to a sticking float inside the carburettor.



Figure 1
G-TWSS after the fire was extinguished

© Crown copyright 2017 56