

ACCIDENT

Aircraft Type and Registration:	Aircreation Flexwing BioniX Tanarg 912ES, SP-MTKI	
No & Type of Engines:	Rotax 912S	
Year of Manufacture:	2010	
Date & Time (UTC):	23 August 2016 at 1145hrs	
Location:	Popham Airfield, Hampshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Extensive	
Commander's Licence:	Other	
Commander's Age:	41 years	
Commander's Flying Experience:	500 hours (of which 420 were on type) Last 90 days - 75 hours Last 28 days - 15 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The pilot was landing on Runway 21 at Popham Airfield with the wind from his left. The pilot reported that it was a very hot day and, with a height above ground of less than a metre, he experienced violent air movement which rotated the aircraft to the right. After loss of directional control the aircraft landed sideways and rolled over. The pilot was unharmed but the aircraft sustained wing and propeller damage.