

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: Order By: Navigator

View Asset

Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe					SQ M		

Summary Print

Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Depth (mm):

Defect Type: Area (m2): Roadstud Type:

Defect Desc: Length (m): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Repair Desc:

Treatment: Date Repair Due: Work Status:

Total Cost: Date Instructed: Work Order:

BOQ Uplift Item: Target Complete: Work Sheet:

WOL Uplift Item: Date Completed: Check Batch:

Check Date: Check Result:

Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Paved Areas - MRP Insp - Flexible Carriageway Depth (mm):

Defect Type: Pothole Area (m2): Roadstud Type:

Defect Desc: Length (m): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Repair Desc: Date Repair Due: Work Status:

Treatment: REPAIR Date Instructed: Work Order:

Total Cost: Target Complete: Work Sheet:

BOQ Uplift Item: Date Completed: Check Batch:

WOL Uplift Item: Check Date: Check Result:

Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
700_14_01	Pavement - Patch Repair Pothole De					SQ M		

Summary Create WO

Defects - MAJ3806 - AAMEY08DW@lamisprd.DPPRDEKDB01 MAIv4.7 0.3

Defect Id: 3465586 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/275 XSP: [Empty] Start Chain: 325 Inspector: NP8 Inspection Batch: 24148

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3826788

Location: F&F M1 J14 J15 MP 86/4 POTHOLE Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded?: N By: [Empty]

Activity: P3 Paved Areas - MRP Insp - Flexible Carriageway Depth (mm): [Empty] Roadstud Type: [Empty]

Defect Type: POTH Pothole Area (m2): [Empty] Co-ords X: 485437.5

Defect Desc: POTHOLE FIXED ON SAT NIGHT SUNDAY MORNING BY ISU Length (m): [Empty] Y: 244095.5

Defect Status: COMPLETED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 09-MAR-2015 10:35 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 09-MAR-2015 10:37 Notice Id: [Empty]

Repair

Category: Permanent Perm Imm Temp Date Repair Due: 06-APR-2015 Work Status: ACTIONED

Repair Desc: POTHOLE FOUND AND FIXED Date Instructed: 09-MAR-2015 10:37 Work Order: A08/2450

Treatment: / REPAIR Target Complete: 06-APR-2015 10:35 Work Sheet: [Empty]

Total Cost: [Empty] Date Completed: 12-MAR-2015 07:10 Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: 3454876 Order By: Defect Id (Desc) Navigator

View Asset

Asset

Road Section: 0400M1/275 XSP Start Chain: 560 Inspector: EMB Inspection Batch: 22607

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3818827

Location: M1 NB 85/0 PARALEL TO THE LAKES Priority: SFTY SISS: ALL

Special Instr: Superseded? N By: Roadstud Type:

Activity: P3 Paved Areas - MRP Insp - Flexible Carriageway Depth (mm): Area (m2): Co-ords X: 485323.1

Defect Type: POTH Pothole Length (m): Y: 244300.8

Defect Desc: M1 NB 85/0 PARALEL TO THE LAKES Asset Modification:

Defect Status: COMPLETED Date Inspected: 28-FEB-2015 23:48 Notice Printed:

Recharge: Date Recorded: 28-FEB-2015 23:49 Notice Id:

Notify: Date Repair Due: 28-MAR-2015 Work Status: ACTIONED

Repair

Category: Permanent Perm Imm Temp Date Instructed: 28-FEB-2015 23:50 Work Order: A08/2391

Repair Desc: M1 NB 85/0 PARALEL TO THE LAKES Target Complete: 28-MAR-2015 23:48 Work Sheet:

Treatment: / REPAIR Date Completed: 08-MAR-2015 08:14 Check Batch:

Total Cost: Check Date: Check Result:

BOQ Uplift Item: Date Paid: Payment Id:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
700_14_01	Pavement - Patch Repair Pothole De					SQ M		

Summary Print

Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEKDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe	1.00			1.00	SQ M	1.00	1.00

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: 3464126 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/275 XSP: [Empty] Start Chain: 1483 Inspector: JCB Inspection Batch: 21613

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3812387

Location: M1 J14-15 MP86/5A Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded?: N By: [Empty]

Activity: P1 Paved Areas - Maintenance Insp Depth (mm): [Empty] Roadstud Type: [Empty]

Defect Type: POTH Pothole Diameter(mm): [Empty] Co-ords X: 484814.7

Defect Desc: M1 J14-15 MP86/5A POTHOLE Step Chg(mm): [Empty] Y: 245071.0

Defect Status: INSTRUCTED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 20-FEB-2015 17:11 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 20-FEB-2015 17:13 Notice Id: [Empty]

Repair

Category: Permanent Perm Imm Temp Date Repair Due: 20-MAR-2015 Work Status: INSTRUCTED

Repair Desc: M1 J14-15 MP86/5A POTHOLE Date Instructed: 20-FEB-2015 17:13 Work Order: A08/2301

Treatment: / REPAIR Target Complete: 20-MAR-2015 17:11 Work Sheet: [Empty]

Total Cost: 1.00 Date Completed: [Empty] Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole	1.00			1.00	SQ M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Paved Areas - MRP Insp - Flexible Carriageway Depth (mm):

Defect Type: Pothole Area (m2): Roadstud Type:

Defect Desc: Length (m): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
700_14_01	Pavement - Patch Repair Pothole De					SQ.M		

Summary Create WO

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: 8460637 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/275 XSP: 4 Start Chain: 660 Inspector: RH8 Inspection Batch: 17197

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3780779

Location: MP 86/4 N/B L1 P1 POTH Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded?: N By: [Empty]

Activity: P1 Paved Areas - Maintenance Insp Depth (mm): [Empty] Roadstud Type: [Empty]

Defect Type: POTH Pothole Diameter(mm): [Empty] Co-ords X: 485284.0

Defect Desc: 1XPOTHOLE Step Chg(mm): [Empty] Y: 244394.0

Defect Status: INSTRUCTED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 14-JAN-2015 09:39 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 14-JAN-2015 14:57 Notice Id: [Empty]

Repair

Category: Temporary Perm Imm Temp Date Repair Due: 15-JAN-2015 Work Status: INSTRUCTED

Repair Desc: MAKE SAFE Date Instructed: 14-JAN-2015 14:57 Work Order: A08/1991

Treatment: MS MAKE SAFE Target Complete: 15-JAN-2015 09:39 Work Sheet: [Empty]

Total Cost: 1.00 Date Completed: [Empty] Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe	1.00			1.00	SQ M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@lamisprd.OPPRDEXDB01 MAI v4.7.0.3

Defect Id: 5459973 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/275 XSP 4 Start Chain 816 Inspector: RH8 Inspection Batch: 16776

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3776723

Location: M1 MP 86/4+80 L1 N/B P1 POTH Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded?: N By: [Empty]

Activity: P1 Paved Areas - Maintenance Insp Depth (mm): [Empty] Roadstud Type: [Empty]

Defect Type: POTH Pothole Diameter(mm): [Empty] Co-ords X: 485197.0

Defect Desc: POTHOLE Step Chg(mm): [Empty] Y: 244524.0

Defect Status: COMPLETED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 07-JAN-2015 09:35 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 07-JAN-2015 16:27 Notice Id: [Empty]

Repair

Category: Temporary Perm Imm Temp Date Repair Due: 08-JAN-2015 Work Status: [Empty]

Repair Desc: MAKE SAFE Date Instructed: [Empty] Work Order: [Empty]

Treatment: MS MAKE SAFE Target Complete: [Empty] Work Sheet: [Empty]

Total Cost: [Empty] Date Completed: 07-JAN-2015 00:00 Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe					SQ M		

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Paved Areas - MRP Insp - Flexible Carriageway Depth (mm):

Defect Type: Pothole Area (m2): Roadstud Type:

Defect Desc: Length (m): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
700_14_01	Pavement - Patch Repair Pothole De					SQ M		

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole	1.00			1.00	SQ M	1.00	1.00

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Superseded? By:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole	1.00			1.00	SQ M	1.00	1.00

Summary Create WO

Defects - MAI3806 - AAMEY08DW@iamisprd.DPFRDEXDB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Paved Areas - Maintenance Insp Depth (mm):

Defect Type: Pothole Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole	1.00			1.00	SQ M	1.00	1.00

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Superseded? By:

Activity: Depth (mm):

Defect Type: Diameter(mm): Co-ords X:

Defect Desc: Step Chg(mm): Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe					SQ M		

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: 8454379 Order By: Defect Id (Desc) Navigator

Asset: [View Asset]

Road Section: 0400M1/275 XSP: [] Start Chain: 228 Inspector: NP8 Inspection Batch: 10883

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3726130

Location: M1 M/P 85/3+60 J14 - J15 Priority: NSFM SISS: ALL

Special Instr: 300012812 Superseded? N By: []

Activity: V1 VRS - Maintenance Insp Length: [] Roadstud Type: []

Defect Type: ACCD Accident damage Height: [] Co-ords X: 485483.4

Defect Desc: 4 X TCB POSTS AND 4 X SOCKETED POSTS OLD SPEC Y: 244010.0

Defect Status: INSTRUCTED Asset Modification: []

Recharge: [] Date Inspected: 12-NOV-2014 01:16 Notice Printed: []

Notify: [] Date Recorded: 12-NOV-2014 01:17 Notice Id: []

Repair

Category: Permanent Perm Imm Temp Date Repair Due: 10-DEC-2014 Work Status: INSTRUCTED

Repair Desc: [] Date Instructed: 12-NOV-2014 01:18 Work Order: A08/1654

Treatment: / REPAIR Target Complete: 10-DEC-2014 01:16 Work Sheet: []

Total Cost: 1.00 Date Completed: [] Check Batch: []

BOQ Uplift Item: [] Check Date: [] Check Result: []

WOL Uplift Item: [] Date Paid: [] Payment Id: []

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
VRS_RE_00C	Vehicle Restraint System - Repair (d	1.00			1.00	LIN M	1.00	1.00

Summary Print Create WO Edit Defect

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Roadstud Type:

Defect Type: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed:

Treatment: Target Complete:

Total Cost: Date Completed: Work Order:

BOQ Uplift Item: Check Date: Work Sheet:

WOL Uplift Item: Date Paid: Check Batch:

Check Result: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
SGPO_RE00	Sign Post - Repair					ITEM		

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7 0.3

Defect Id: 3449161 Order By: Defect Id (Desc) Navigator

View Asset

Asset

Road Section: 0400M1/275 XSP Start Chain: 780 Inspector: RCB Inspection Batch: 7690

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3672295

Location: M1 N/B 85/B+40 C/RES VRS DAMAGE Priority: NSFH SISS: ALL

Special Instr: 300011732 Superseded?: N By: []

Activity: V1 VRS - Maintenance Insp Length: [] Roadstud Type: []

Defect Type: ACCD Accident damage Height: [] Co-ords X: 485216.7

Defect Desc: M1 N/B 85/B+40 C/RES VRS DAMAGE, 1X SURFACE MOUNT Y: 244493.9

Defect Status: INSTRUCTED Asset Modification: []

Recharge: [] Date Inspected: 25-AUG-2014 10:43 Notice Printed: []

Notify: [] Date Recorded: 25-AUG-2014 10:45 Notice Id: []

Repair

Category: Permanent Perm Imm Temp Date Repair Due: 08-SEP-2014 Work Status: INSTRUCTED

Repair Desc: M1 N/B 85/B+40 C/RES VRS DAMAGE, 1X SURFACE MOUNT Date Instructed: 25-AUG-2014 10:45 Work Order: A08/1317

Treatment: / REPAIR Target Complete: 08-SEP-2014 10:43 Work Sheet: []

Total Cost: 1.00 Date Completed: [] Check Batch: []

BOQ Uplift Item: [] Check Date: [] Check Result: []

WOL Uplift Item: [] Date Paid: [] Payment Id: []

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
VRS_RE_000	Vehicle Restraint System - Repair (d	1.00			1.00	LIN M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAJ3806 - AAMEY08DW@iamisprd.DPPRDEXDB01 MAIV4.7 0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: VRS - Maintenance Insp Length: Roadstud Type:

Defect Type: Accident damage Height: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
VRS_RE_000	Vehicle Restraint System - Repair (d	1.00			1.00	LIN M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Paved Areas - Maintenance Insp

Depth (mm):

Roadstud Type:

Defect Type: Pothole

Diameter(mm):

Co-ords X:

Defect Desc: Step Chg(mm):

Y:

Defect Status: Asset Modification:

Recharge:

Date Inspected: Notice Printed:

Notify:

Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc:

Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost:

Date Completed: Check Batch:

BOQ Uplift Item:

Check Date:

Check Result:

WOL Uplift Item:

Date Paid:

Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MALV4 7.0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Length: Roadstud Type:

Defect Type: Height: Co-ords X:

Defect Desc: Asset Modification:

Defect Status: Date Inspected: Notice Printed:

Recharge: Date Recorded: Notice Id:

Notify:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
VRS_RE_000	Vehicle Restraint System - Repair (d					LIN M		

Summary Create WO

Defects - MAJ3806 - AAMEY08DW@lamisprd.DPPRDEXDB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: VRS - Maintenance Insp Length: Roadstud Type:

Defect Type: Accident damage Height: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
400_10_02	VRS - Repair					LIN M		

Summary Print Create WO Edit Defect

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Length: Roadstud Type:

Defect Type: Height: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed:

Treatment: Target Complete:

Total Cost: Date Completed: Work Order:

BOQ Uplift Item: Check Date: Work Sheet:

WOL Uplift Item: Date Paid: Check Batch:

Check Result:

Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEADB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset View Asset

Road Section: XSP Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Paved Areas - MRP Insp - Flexible Carriageway

Defect Type: Pothole

Defect Desc: Depth (mm):

Defect Status: Area (m2): Roadstud Type:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Co-ords X: Y:

Asset Modification:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
700_14_01	Pavement - Patch Repair Pothole De					SQ M		

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@iamisprd.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: Order By: Defect Id (Desc) Navigator

Asset: View Asset

Road Section: 0400M1/275 XSP Start Chain: 474 Inspector: MC1 Inspection Batch: 3275

Road Desc: END SERV ENTRANCE SLIP TO CENTRE OF BRIDGE Initiation Type: MRP Inspection Id: 3593134

Location: M1 N/B 85/5+50 LEFT VERGE Priority: SFTY SISS: ALL

Special Instr: 300009374 Superseded? N By:

Activity: V1 VRS - Maintenance Insp Length: Roadstud Type:

Defect Type: ACCD Accident damage Height: Co-ords X: 485366.8

Defect Desc: M1 N/B 85/5+50 LEFT VERGE BARRIER DAMAGE, 1x 4.8 OBE Y: 244227.2

Defect Status: COMPLETED Asset Modification:

Recharge: Date Inspected: 23-APR-2014 14:05 Notice Printed:

Notify: Date Recorded: 23-APR-2014 14:09 Notice Id:

Repair

Category: Permanent Perm Imm Temp Date Repair Due: 30-APR-2014 Work Status: ACTIONED

Repair Desc: M1 N/B 85/5+50 LEFT VERGE BARRIER DAMAGE, 1x 4.8 OBE Date Instructed: 23-APR-2014 23:55 Work Order: A08/163

Treatment: / REPAIR Target Complete: 30-APR-2014 14:05 Work Sheet:

Total Cost: Date Completed: 29-MAY-2014 05:06 Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
400_10_02	VRS - Repair					LIN M		

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprtd.PPRDEXDB01 MAI.V4.7.0.3

Defect Id: Order By:

Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Length: Roadstud Type:

Defect Type: Height: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
400_10_02	VRS - Repair					LIN.M		