

Event List | Event List - AOR
EMIT Failure recorded during routine maintenance. [redacted] system shutdown [redacted] 1 of 1+

Menu [dropdown] Home [dropdown] Details [dropdown] Create Case [dropdown] Query

Event Summary: * EMIT Failure recorded during routine maintenance. [redacted] system shutdown	Event Status: Closed [dropdown]	Case Name: [text]
Event Number: * 1-1UV2OE Location - Project: * [redacted]	Date Occurred: 20/05/2013 09:57:4 [calendar]	Investigator: [text]
Originator: [redacted] Precede Location: [redacted]	Date Reported: 20/05/2013 09:57:4 [calendar]	Case Status: [text]
Owner: [redacted] Security / Sensitive: * Normal [dropdown]	Event Closed: 31/05/2013 09:09:3 [calendar]	OSHA Code: [dropdown]
Assistance Called: [text] Injury: [checkbox]	INES Code: [dropdown]	OSHA Description: [text]
Company Involved: AWE	ESH Status Code: [dropdown]	
Function: [text] Sub Function: [text]	Business Team: [text]	

Originators Description
During Step 4.3 of MI EDMS3/800CFDE1/B/ES9003?MI008, a failure was recorded during testing. The test requires the [redacted] to be shutdown via the [redacted] in the [redacted] control room. On operation of the [redacted] system should stop the [redacted] system and continue to run the [redacted] system. Once the [redacted] has completely stopped the [redacted] system should then shutdown.

Further Details
This is a known and unintentional feature of the system when running across [redacted]. This will be covered as part of the [redacted] replacement under rekit, (WP19). There is no additional action that can be done before this apart from avoiding cross [redacted] running

During Step 4.3 of MI EDMS3/800CFDE1/B/ES9003?MI008, a failure was recorded during testing. The test requires the [redacted] to be shutdown via the [redacted] in the [redacted] control room. On operation of the [redacted] system should stop the [redacted] system and continue to run the [redacted] system. Once the [redacted] has completely stopped the [redacted] system should then shutdown.

This failure was found on PM work order 8651449

Due to the [redacted] system currently running 'Cross [redacted] 1&4) there is a known issue that on operation of this button the system does not wait for the [redacted] to shutdown before stopping the [redacted]. On activation of the [redacted] BOTH the [redacted] and [redacted] systems stop simultaneously. This is not how the system should function. This AE has been raised to highlight this issue and to cover the failure of the EMIT test.

OK Cancel

Menu [dropdown] Home [dropdown] Query

Event Details

CONTAINMENT: Via notification
Immediate actions to stop escalation of Event:
CONTROL: To be investigated
Short term actions to prevent immediate recurrence:
PREVENTION: None. There is nothing that can be done on this until rekit project replaces the [redacted] under WP 19.
Actions completed to prevent recurrence:

FOR@cton R25.01 - Windows Internet Explorer

File Edit View Favorites Tools Help

ORACLE

Event: Saved Queries: []

Home Cases Events Issues Actions My BIP Reports

Event List | EventList - ACR

Information

Originators Plant/Equipment Description: [] System []

Comments: This is a known unintentional feature of the system when running across [] and will be covered as part of the [] replacement under relt. (WP19)

Process Documentation References: []

AWE Programme Performance affected: []

Immediate Distribution List: []

Contacts Menu Add New Query No Records []

Last Name	First Name	Manager	Phone	Building	Function	Sub Function	Employee Type	Supplier	Event Relationship

Plant & Equipment Menu New Query No Records []

Type	AMS Ref	UIN	Location	Precise Location	Comments

Done Local intranet 100%