

Asbestos Status	Priority Code	When and What	Last Inspection Date	Surveyor	Survey Type	Diagram Reference	Photo Reference	Internal /			Frequency	Re-Inspection Date	New Asbestos	Approximate Cost	Target Completion Date	Responsible Party (C-E /)	SPEC024_Code
								Sealed	Damage	External							
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey	P2454		-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON082
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON082
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2456		-1	-1	External	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON072
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2463		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON072
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2462		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON072
No Action	0		01/05/2015	Brian McCafferty	Management Survey	P2412	Photos\ABSUIDRMCRxx\2405606-Roof Trusses.Jpg	-1	-1	Internal	0		No	0		C-E	RMCR00CON008
No Action	0		01/05/2015	Brian McCafferty	Management Survey	P2477		-1	-1	Internal	0		No	0		C-E	RMCR00CON008
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID711422\2405576-Adhesive on Vinyl Floor Tiles.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON008
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697761\2405504-Ventilation Pipe.Jpg	-1	-1	External	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2803		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697804\2405540-Roof Covering.Jpg	-1	-1	External	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey	P2478		-1	-1	External	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697761\2405506-Cistern Within Walls.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405549-Adhesive on Rear of Blue Vinyl.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405548-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405546-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405551-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405545-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697808\2405550-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON011
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey	P2475		-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON010
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2476		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON010
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON021
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2469		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON021
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2472		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON049
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON142
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2455		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON142
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2455		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON141
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON141
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON141
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON141
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697705\2405439-Debris on Flat Roof.Jpg	-1	-1	External	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON146
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID691755\2405411-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON191
Restrict Access	2	Restrict Access	01/05/2015	Brian McCafferty	Management Survey	P2481		-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON183
Restrict Access	2	Restrict Access	01/05/2015	Brian McCafferty	Management Survey	P2483		-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON183
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697705\2405437-Roof Covering.Jpg	-1	-1	External	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON183
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697705\2405438-Soffit.Jpg	-1	-1	External	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00CON183
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID691755\2405415-Adhesive to Floor Covering.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON183
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2451		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON183
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID691755\2405413-Gaskets Throughout Pipework.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON222
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2453		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON068
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey	P2457		-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON068
Monitor	4	Monitor	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID697761\2405503-Cistern Within Walls.Jpg	-1	-1	Internal	12	01/05/2016	No	0	01/11/2019	C-E	RMCR00CON012
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey			-1	-1	Internal	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00Ground
Remove	3	Remove	01/05/2015	Brian McCafferty	Management Survey		Photos\ABSUID691754\2405404-Live Electrics.Jpg	-1	-1	External	12	01/05/2016	No	0	30/04/2016	C-E	RMCR00Ground