

ANNEX B RNAD BEITH

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_RE F	ROOM_DES C	PRESE NT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RI SK	RISK_RATIN G	RECOMM ENDATIO NS	REMEDIAL_ACTIO N	RISK_MITIG ATION	COST	COMMENTS	OLD_MA XIMO_N UM	LASTC OMPD ATE	NEX TDA TE	PMNUM	PRIORI TISATI ON	REMOVALDAT E	STATU S
ADBE	1808	ADBE01000	NEWS BUILDING	Internal	Ground	Boiler Room	Boiler 3 gaske	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N							No trace of debris, removal date assumed as inspection date	4380					18-JUN-09	OPERAT
ADBE	1809	ADBE01000	NEWS BUILDING	Internal	Boiler Room	Floor area	Gasket debris	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N							No trace of gaskets, condition high damage when sampled, removal date assumed as insection date.	4381					18-JUN-09	OPERAT
ADBE	1810	ADBE01001	MOTOR TRANSPORT GARAGE	Internal	Toilet	Floor coverin	Tile adhesive	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4376					08-FEB-10	OPERAT
ADBE	1811	ADBE01001	MOTOR TRANSPORT GARAGE	Internal	Toilet	Floor coverin	Grey floor tiles	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4377					08-FEB-10	OPERAT
ADBE	1812	ADBE01001	MOTOR TRANSPORT GARAGE	Internal	Toilet	Floor	Aqua floor tiles	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4378					08-FEB-10	OPERAT
ADBE	1813	ADBE01001	MDP MAIN GATE	External	Tank Store Roof	External	Roof lining pa	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			No access to roof, condition assumed as previous inspection.	4379	17-JUN-14			Low		OPERAT
ADBE	1814	ADBE01001	CONTRACTS OFFICE	External	Porch	Roof	Roof covering	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	<10m² or <10m pipe run	Chrysotile	Removed	N							Building demolished.	4382					24-JUN-10	OPERAT
ADBE	1815	ADBE01001	CONTRACTS OFFICE	Internal	Kitchen	Sink unit	Sink pad	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	Small amounts	Presumed Crocidolite	Removed	N							Building demolished. Notification of required amendment received 13/01/2011	7545					01-MAR-10	OPERAT
ADBE	1816	ADBE01001	MAIN ADMINISTRATION BUILDING	External	External	Roof	Roof mounted	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Presumed Crocidolite	Medium Damage - Significant Damage/Visible Fibres	Y	8 - Medium Ris	16	Inspect	Annual condition inspection to be carried out by Competent Person			Re-surveyed on 12/12/2013, Condition reported good	4383	17-JUN-14			High		OPERAT
ADBE	18250	ADBE01001	MAIN ADMINISTRATION BUILDING	Internal	Roof	Tank Room	Ducting joints	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	11	Inspect	Annual condition inspection to be carried out by Competent Person			Survey c/o 12/12/2013, Permit to climb required, no access, condition presumed as prevoius inspection.		17-JUN-14			Medium		OPERAT
ADBE	1817	ADBE01001	EXP ENTRANCE PAU	External	Roof	External	Roof covering	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building removed, NORA required, removal date assumed as inspection date.	4389					18-JUN-14	OPERAT
ADBE	1818	ADBE01001	INCIDENT CONTROL POST	Internal	Ceiling Void	Internal	Roof purlins (r	No	Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished, inspection date assumed as removal date.	4390					13-JUN-12	OPERAT
ADBE	18251	ADBE01001	EMPTY WORKSHOP	Internal	Roof	Internal ceilin	Purlins	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Surveyed on 12/12/2013 after storm damage to one purlin at roof peak						09-MAR-14	OPERAT

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTDATE	NEXTDATE	PMNUM	PRIORITY	REMOVALDATE	STATUS
ADBE	18490	ADBE01001	APPRENTICE MACHINE SHOP	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm extent and condition.	300	No access, purlins and cladding rails located behind and above lining panels.					Low		OPERATIONAL
ADBE	18491	ADBE01001	EMPTY WORKSHOP	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm extent and condition.	300	No access, purlins and cladding rails located behind and above lining panels.					Low		OPERATIONAL
ADBE	18492	ADBE01001	STORE (Previously CONTAINER REPAIR FACILITY/ FLT CHARGING)	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm extent and condition.	300	Currently used as a fitness suite. No access, purlins and cladding rails located behind and above lining panels.					Low		OPERATIONAL
ADBE	18493	ADBE01001	MAINTENANCE WORKSHOP	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm the extent and condition.	300	No access, purlins and cladding rails located behind and above lining panels.					Low		OPERATIONAL
ADBE	18494	ADBE01001	PAINT SHOP	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm extent and condition.	300	No access, purlins and cladding rails located behind and above lining panels.					Low		OPERATIONAL
ADBE	1819	ADBE01001	SPRAYPAINT FACILITY	External	Bin storage area	Door	External door	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	<10m² or <10m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4391				12-FEB-10	OPERATIONAL	
ADBE	1820	ADBE01001	SPRAYPAINT FACILITY	Internal	Bin storage area	Door	Internal door	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	<10m² or <10m pipe run	Amosite (Amphibole asbestos excluding crocidolite)	Removed	N							Notification of required amendment received 13/01/2011	4392				12-FEB-10	OPERATIONAL	
ADBE	1821	ADBE01001	SPRAYPAINT FACILITY	Internal	Bin storage area	Walls	Wall panels	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4393				12-FEB-10	OPERATIONAL	
ADBE	1822	ADBE01001	SPRAYPAINT FACILITY	External	Bin storage area	Roof	Purlins	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							No trace of material, condition good when sampled. Removal date assumed as inspection date	4394				18-JUN-09	OPERATIONAL	
ADBE	18495	ADBE01001	SPRAYPAINT FACILITY	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Sample	Undertake analysis to confirm presence of ACMs	Arrange for management survey to confirm extent and condition.	300	No access, purlins and cladding rails located behind and above lining panels.					Low	22-JUN-11	OPERATIONAL
ADBE	1823	ADBE01002	HAZARDOUS STOREROOM (CAT C)	External	Walls	External	Wall panels	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	10	Inspect	Annual condition inspection to be carried out by Competent Person				4338				Medium	17-JUN-14	OPERATIONAL
ADBE	1824	ADBE01002	HAZARDOUS STOREROOM (CAT C)	Internal	Roof and Walls	Internal	Purlins & Cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person				4339				Low	17-JUN-14	OPERATIONAL
ADBE	1825	ADBE01002	STORE BUILDING	Internal	Roof and Walls	Internal	Purlins & Cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person				4340				Low	17-JUN-14	OPERATIONAL

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTDATE	NEXTDATE	PMNUM	PRIORITY	REMOVALDATE	STATUS
ADBE	1826	ADBE01002	HAZARDOUS STOREROOM (CAT C)	External	Roof	External	Felt roof cover	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			4341	18-JUN-14				Low		OPERATIONAL
ADBE	1827	ADBE01002	HAZARDOUS STOREROOM (CAT C)	Internal	Internal	Roof support	Purlins	Yes	Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.	10-50m² or 10-50m pipe run	Presumed Crocidolite	Medium Damage - Significant Damage/Visible Fibres	Y	11 - High Risk	19	Inspect	Annual condition inspection to be carried out by Competent Person			4342	17-JUN-14				High		OPERATIONAL
ADBE	18474	ADBE01002	STORE BUILDING	External	Demolished building adjacent to building10	Existing floor	Floor tiles	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)		Chrysotile	High Damage - Visible Debris	Y	4 - Insignificant		Remove	Arrange for ACM to be removed	Remove and dispose of at a licenced site	1000	Identified during asbestos demolition survey ASB/13/EK/S/0332 dated 12/12/2013							OPERATIONAL
ADBE	1828	ADBE01002	STORE BUILDING	Internal	Roof and Walls	Internal	Purlins & Clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4343	17-JUN-14				Low		OPERATIONAL
ADBE	1829	ADBE01002	STORE BUILDING	Internal	Roof and Walls	Internal	Purlins and clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4344	17-JUN-14				Low		OPERATIONAL
ADBE	1830	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4345	18-JUN-14				Low		OPERATIONAL
ADBE	1831	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Roof and walls	Internal	Purlins and clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4346	17-JUN-14				Low		OPERATIONAL
ADBE	1832	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4347	17-JUN-14				Low		OPERATIONAL
ADBE	1833	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and clad	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4348	17-JUN-14				Low		OPERATIONAL
ADBE	1834	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Roof and walls	Internal	Purlins and clad	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							No evidence of asbestos, removal date assumed as inspection date.	4349					18-JUN-09	OPERATIONAL
ADBE	1835	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4350	18-JUN-14				Low		OPERATIONAL
ADBE	1836	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Medium Damage - Significant Damage/Visible Fibres	Y	7 - Medium Risk	12	Remove	Arrange for ACM to be removed	Remove and dispose of damaged cladding rail at licenced site.	500	No trace during inspection on 23-06-2014, presumed removed, NORA awaited.	4351	17-JUN-14			Medium		OPERATIONAL
ADBE	1837	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			Add	17-JUN-14				Low		OPERATIONAL
ADBE	1838	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4352	17-JUN-14				Low		OPERATIONAL

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTCOMPLIANCE	NEXTDATE	PMNUM	PRIORITY	REMOVALDATE	STATUS	
ADBE	1839	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			Add		17-JUN-14			Low		OPERATIONAL	
ADBE	1840	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4353		18-JUN-14			Low		OPERATIONAL	
ADBE	1841	ADBE01002	HAZARDOUS STORE - (CAT C)	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4354		18-JUN-14			Low		OPERATIONAL	
ADBE	1842	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4355		17-JUN-14			Low		OPERATIONAL	
ADBE	1843	ADBE01002	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4356		17-JUN-14			Low		OPERATIONAL	
ADBE	1844	ADBE01002	HAZARDOUS STORE - (CAT C)	External	Roof and walls	External	Roof and wall	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			4357		17-JUN-14			Low		OPERATIONAL	
ADBE	1845	ADBE01002	TOILET	External	External	Soil pipe	Buried soil pipe	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Removal confirmed on 19/09/2013	4412					26-FEB-13	OPERATIONAL	
ADBE	1846	ADBE01002	TOILET	External	Roof	External	Sheeting	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	9	Inspect	Annual condition inspection to be carried out by Competent Person			Building programmed for demolition.	4413		17-JUN-14			Medium		OPERATIONAL
ADBE	1847	ADBE01002	TOILET	External	Wall	External	Wall mounted	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N						No trace of waste pipe, removal date assumed as inspection date	4414						18-JUN-13	OPERATIONAL	
ADBE	1848	ADBE01003	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4358		17-JUN-14			Low		OPERATIONAL	
ADBE	1849	ADBE01003	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			4359		17-JUN-14			Low		OPERATIONAL	
ADBE	1850	ADBE01003	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			Access key missing, condition assumed as previous inspection.	4360		18-JUN-14			Low		OPERATIONAL
ADBE	1851	ADBE01003	STORE BUILDING	External	Door	External	Door lining	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	<10m² or <10m pipe run	Amosite (Amphibole asbestos excluding crocidolite)	Removed	N						Removal date assumed as inspection date.	4361						18-JUN-09	OPERATIONAL	

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTCOMPLETED	NEXTDATE	PMNUM	PRIORITY	REMOVALDATE	STATUS
ADBE	1852	ADBE01003	STORE BUILDING	Internal	Roof	Internal	Purlins	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, suspended ceiling fitted, condition good when sampled	4362	17-JUN-14			Low		OPERATIONAL
ADBE	1853	ADBE01003	HAZARDOUS STORE - (CAT C)	Internal	Roof	Internal	Purlins	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4363	17-JUN-14			Low		OPERATIONAL
ADBE	1854	ADBE01003	HAZARDOUS STORE - (CAT C)	Internal	Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person				Add	17-JUN-14			Low		OPERATIONAL
ADBE	1855	ADBE01003	FUEL WASTE STORAGE	Internal	Roof and Walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	7	Inspect	Annual condition inspection to be carried out by Competent Person				4364	17-JUN-14			Low		OPERATIONAL
ADBE	1856	ADBE01003	FUEL WASTE STORAGE	Internal	Equipment	Services equipment	Pipe fittings	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	<10m² or <10m pipe run	Chrysotile	Removed	N							No trace of material, condition high damage when sampled, removal date assumed as inspection date.	4365					18-JUN-09	OPERATIONAL
ADBE	1857	ADBE01003	HAZARDOUS STORE - (CAT C)	External	Roof	External	Roofing felt	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4366	18-JUN-14			Low		OPERATIONAL
ADBE	1858	ADBE01003	FLT BATTERY CHARGE FACILITY	Internal	Generator Room Walls	Internal	Cladding rails	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			No access, cladding rails located behind lining panels.	4367	23-JUN-14			Low		OPERATIONAL
ADBE	1859	ADBE01003	FLT BATTERY CHARGE FACILITY	Internal	Generator Room Roof	Internal	Purlins	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			No access, purlins located above lining panels.	4368	23-JUN-14			Low		OPERATIONAL
ADBE	1860	ADBE01003	STORE BUILDING	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4369	17-JUN-14			Low		OPERATIONAL
ADBE	1861	ADBE01003	STORE BUILDING	Internal	Roof and Walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4370	17-JUN-14			Low		OPERATIONAL
ADBE	1862	ADBE01004	HAZARDOUS STORE - (CAT C)	Internal	Roof and walls.	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, located above / behind lining, condition good when sampled	4371	17-JUN-14			Low		OPERATIONAL
ADBE	1863	ADBE01004	HAZARDOUS STORE - (CAT C)	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, located above / behind lining, condition good when sampled	4372	17-JUN-14			Low		OPERATIONAL
ADBE	1864	ADBE01004	HAZARDOUS STORE - (CAT C)	External	Roof and walls	Internal and External	Roof sheeting	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)	10-50m² or 10-50m pipe run	Presumed Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4373	17-JUN-14			Low		OPERATIONAL

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTCOMPLETED	NEXTDATE	PMNUM	PRIORITY	REMOVALDATE	STATUS
ADBE	1865	ADBE01004	HAZARDOUS STORE (CAT C)	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person				4374	23-JUN-14			Low		OPERATIONAL
ADBE	1866	ADBE01004	HAZARDOUS STORE (CAT C)	Internal	Roof and walls	Internal	Purlins and cladding	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Presumed Crocidolite	Removed	N							Building demolished, inspection date assumed as removal date.	4375					13-JUN-12	OPERATIONAL
ADBE	1867	ADBE01004	HAZARDOUS STORE (CAT C)	Internal	Roof and walls	Internal	Purlins and cladding	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished, removal date assumed as inspection date.	Add					13-JUN-12	OPERATIONAL
ADBE	1868	ADBE01004	FLT BATTERY CHARGE FACILITY	Internal	Roof	Internal	Purlins	Yes	Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.	10-50m² or 10-50m pipe run	Chrysotile	Medium Damage - Significant Damage/Visible Fibres	Y	9 - Medium Risk	17	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, located above suspended ceiling, condition medium damage when inspected.	4396	23-JUN-14			High		OPERATIONAL
ADBE	1869	ADBE01004	STORE	Internal	Roof and walls	Internal	Purlins and cladding	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	3 - Insignificant	11	Inspect	Annual condition inspection to be carried out by Competent Person				4397	17-JUN-14			Medium		OPERATIONAL
ADBE	1870	ADBE01004	LOCOMOTIVE SHED	Internal	Roof	Internal	Purlins and cladding	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished. Notification of required amendment received 13/01/2011	4398					20-MAR-10	OPERATIONAL
ADBE	1871	ADBE01004	TOILET	External	Walls	External	Wall mounted	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	<10m² or <10m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	11	Inspect	Annual condition inspection to be carried out by Competent Person			Building programmed for demolition.	4410	18-JUN-14			Medium		OPERATIONAL
ADBE	1872	ADBE01004	TOILET	External	Roof	External	Sheeting	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	12	Inspect	Annual condition inspection to be carried out by Competent Person			Building programmed for demolition.	4411	18-JUN-14			Medium		OPERATIONAL
ADBE	1873	ADBE01005	AAGW EXAMINATION	Internal	Building Annex	Walls	Internal wall boards	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Amosite (Amphibole asbestos excluding crocidolite)	Medium Damage - Significant Damage/Visible Fibres	Y	7 - Medium Risk	15	Inspect	Annual condition inspection to be carried out by Competent Person			IOM certificate of analysis A26748 January 2013.	4399	18-JUN-14			High		OPERATIONAL
ADBE	1874	ADBE01005	BOOSTER MAINTENANCE	External	Roof and walls	External	Roof and wall	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	11	Inspect	Annual condition inspection to be carried out by Competent Person				4400	18-JUN-14			Medium		OPERATIONAL
ADBE	1875	ADBE01005	BOOSTER MAINTENANCE	Internal	Floor	Floor area	Debris on floor	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	Small amounts	Chrysotile	Removed	N							No trace of debris, condition high damage when sampled. Removal date assumed as inspection date.	4401					18-JUN-09	OPERATIONAL
ADBE	17810	ADBE01005	BOOSTER MAINTENANCE	Internal	Booster Maintenance Extension	Internal	Wall boards	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.		Chrysotile	Low Damage - A few scratches/broken edges/etc	Y			Inspect	Annual condition inspection to be carried out by Competent Person			IOM certificate of analysis A26750 January 2013.		18-JUN-14					OPERATIONAL
ADBE	1876	ADBE01005	STORE	Internal	Roof and walls	Internal	Purlins and cladding	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished. Notification of required amendment received 13/01/2011	4402					10-MAR-10	OPERATIONAL
ADBE	1877	ADBE01006	DISTRIBUTION SUB STATION A	External	Roof	External	Sheeting	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4395					30-MAR-10	OPERATIONAL

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_REF	ROOM_DESC	PRESENT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RISK	RISK_RATING	RECOMMENDATIONS	REMEDIAL_ACTION	RISK_MITIGATION	COST	COMMENTS	OLD_MAXIMUM	LASTDATE	NEXTDATE	PRIORITY	REMOVALDATE	STATUS	
ADBE	1878	ADBE01006	BRIDGE GATE	External	Roof	External	Roofing felt	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished. Notification of required amendment received 13/01/2011	4415				20-MAR-10	OPERATIONAL	
ADBE	1879	ADBE01006	BRIDGE GATE	Internal	Floor	Internal	Floor tile adhesive	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Building demolished. Notification of required amendment received 13/01/2011	4416				20-MAR-10	OPERATIONAL	
ADBE	1880	ADBE01006	GM POLICE GATEHOUSE	Internal	Floor	Store room	Brown floor tiles	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	<10m² or <10m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4417				08-FEB-10	OPERATIONAL	
ADBE	1881	ADBE01006	GM POLICE GATEHOUSE	Internal	Gas meter house Floor	Internal	Brown floor tiles	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Removal confirmed on 19/09/2013	4418				26-FEB-13	OPERATIONAL	
ADBE	1882	ADBE01006	DVR FACILITY	External	Roof	External	Roofing felt	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4419				27-MAR-10	OPERATIONAL	
ADBE	1883	ADBE01006	MTHW BOILER HOUSE SERVING 804 & 816	Internal	Floor	Boiler House	Gasket debris	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N								No trace of debris, removal date assumed as inspection date	4420				18-JUN-09	OPERATIONAL
ADBE	1884	ADBE01008	LEAK TEST/PROCESSING FACILITY	Internal	Plant room Roof and walls	Internal	Insulating board	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	10	Inspect	Annual condition inspection to be carried out by Competent Person				Inaccessible, located between roof and wall skins, condition low damage when inspected.	4405	18-JUN-14		Medium		OPERATIONAL
ADBE	1885	ADBE01008	LEAK TEST/PROCESSING FACILITY	Internal	Roof and walls	Internal	Roof and walls	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	4 - Insignificant	12	Inspect	Annual condition inspection to be carried out by Competent Person				Inaccessible, located between roof and wall skins, condition good when inspected.	4406	18-JUN-14		Medium		OPERATIONAL
ADBE	1886	ADBE01008	LEAK TEST/PROCESSING FACILITY	Internal	Plant room Walls and roof	Internal	Insulating board	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Chrysotile	Low Damage - A few scratches/broken edges/etc	Y	4 - Insignificant	12	Inspect	Annual condition inspection to be carried out by Competent Person				Inaccessible, located between roof and wall skins, condition low damage when inspected.	4407	18-JUN-14		Medium		OPERATIONAL
ADBE	1887	ADBE01008	FUELLING & LTDF MTHW BOILER HOUSE DIST SUB-STN N	External	Ground	External	Gasket debris	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N								No trace of debris, condition high damage when sampled, removal date assumed as inspection date	4408				18-JUN-09	OPERATIONAL
ADBE	1888	ADBE01008	FUELLING & LTDF MTHW BOILER HOUSE DIST SUB-STN N	Internal	Boiler house Blower unit	Internal	3 No gaskets	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N								No trace of gaskets, removal date assumed as inspection date. Boilers replaced 2011.	4409				20-JUN-13	OPERATIONAL
ADBE	1889	ADBE01009	IWC 6 ADMINISTRATION	Internal	Calorifier room	Internal	PLANT ROOM	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Good - No Visible Damage	Y	5 - Low Risk	12	Inspect	Annual condition inspection to be carried out by Competent Person				No access during survey, condition presumed as previous inspection.	4403	18-JUN-14		Medium		OPERATIONAL
ADBE	1890	ADBE01009	IWC 6 PLANT ROOM 1/4	Internal			Gasket debris	No	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	Small amounts	Chrysotile	Removed	N								No trace of debris, removal date assumed as inspection date	4404				18-JUN-09	OPERATIONAL

LINK	ID	LOCATION	DESCRIPTION	INTERNAL EXTERNAL	FLOOR	ROOM_RE F	ROOM_DES C	PRESE NT	COMPONENT	EXTENT	TYPE	CONDITION	ACTIVE	MATERIAL_RI SK	RISK_RATIN G	RECOMM ENDATIO NS	REMEDIAL_ACTIO N	RISK_MITIG ATION	COST	COMMENTS	OLD_MA XIMO_N UM	LASTC OMPD ATE	NEX TDA TE	PMNUM	PRIORI TISATI ON	REMOVALDAT E	STATU S
ADBE	1891	ADBE01012	ADMIN OFFICES	Internal	Gents toilet room 14	Internal	Floor tile adhe	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	2 - Insignificant	9	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, floor overlaid with vinyl, condition good when sampled.	4384	17-JUN-14			Medium		OPERAT
ADBE	1892	ADBE01012	ADMIN OFFICES	Internal	Office 2 Room G7	Floor coverin	Brown floor tile	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Removed	N							Notification of required amendment received 13/01/2011	4385				12-FEB-10	OPERAT	
ADBE	1893	ADBE01012	ADMIN OFFICES	Internal	Gents toilet room 14	Internal	Red floor tiles	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	2 - Insignificant	11	Inspect	Annual condition inspection to be carried out by Competent Person			Inaccessible, floor overlaid with vinyl, condition good when sampled	4386	17-JUN-14			Medium		OPERAT
ADBE	1894	ADBE01012	ADMIN OFFICES	Internal	Office 2 Room G7	Office floor	Floor tile adhe	Yes	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).	10-50m² or 10-50m pipe run	Chrysotile	Good - No Visible Damage	Y	2 - Insignificant	8	Inspect	Annual condition inspection to be carried out by Competent Person			Adhesive encapsulated under floor covering, Notification of required amendment received 27/08/2013	4387	17-JUN-14			Low		OPERAT
ADBE	1895	ADBE01012	ADMIN OFFICES	Internal	Emergency exit corridor	Internal	Wall panels	Yes	Asbestos insulating board, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.	10-50m² or 10-50m pipe run	Amosite (Amphibole asbestos excluding crocidolite)	Good - No Visible Damage	Y	5 - Low Risk	13	Inspect	Annual condition inspection to be carried out by Competent Person			Wall panels encapsulated with paint protection system.	4388	17-JUN-14			Medium		OPERAT
ADBE	18473	ADBE01012	ADMIN OFFICES	External	Roof	Gable	Gable undercl	No	Asbestos-reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc).		Chrysotile	Removed	N							Sampled by ENVIRAS Surveys Ltd on 7/11/2013					27-MAR-14	OPERAT	