

Path Head – Cell 3 Capping Works – July 2016



Restoration soils being dozed across the capping material (black material)

Geomembrane drainage material being placed





**Geomembrane material
(close up)**

