

Secretariat
Defence Infrastructure Organisation
Kingston Road
Sutton Coldfield
B75 7RL

E-mail: diosec-parli@mod.uk www.gov.uk/DIO

19 May 2016

Ref. FOI 2016/04562

Dear

Thank you for your email of 20 April 2016 requesting the following information:

"I would also like to request the asbestos records for the property including what is used on the annual inspection please."

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD) and I can confirm that all of the information in scope of your request is held.

The information you have requested can be found enclosed at annex A the asbestos records for

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, 2<sup>nd</sup> Floor, Zone N, MOD Main Building, Whitehall, SW1A 2HB (e-mail <u>CIO-FOI-IR@mod.uk</u>). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <a href="http://www.ico.org.uk">http://www.ico.org.uk</a>.

Yours sincerely,

**DIO Secretariat** 

N/A	0	not recorded		External	17	External	1880263	2129795
N/A	0	not recorded		Bedroom	10	First	1880244	2129795
N/A	0	not recorded		Stores	8	First	1880241	2129795
N/A	0	not recorded		Stores	5	Ground To First	1880238	2129795
N/A	0	not recorded		Roof Void	15	Roof Void	1880252	2129795
N/A	0	not recorded		Bedroom	9	First	1880243	2129795
N/A	0	not recorded		Bedroom	11	Ground To First	1880246	2129795
N/A	0	not recorded		Toilet	4	Ground To First	1880236	2129795
N/A	0	not recorded		Garage	13	<b>Ground To First</b>	1880250	2129795
N/A	0	not recorded		Landing	7	First	1880240	2129795
N/A	0	not recorded		Lounge	2	Ground To First	1880228	2129795
N/A	0	not recorded		Bedroom	12	Ground To First	1880248	2129795
N/A	0	Bituminous Product	Sinks	Kitchen	ω	Ground To First	1880231	2129795
N/A	0	not recorded		Shed	14	Ground To First	1880251	2129795
N/A	0	not recorded		Stores	6	<b>Ground To First</b>	1880239	2129795
Unit of Measure	Approximate Amount of Material	Material Description	Elements	Room Description	Room ID	Floor	Record ID	<b>G</b> ILUS <b>G</b>

TRUE	No sample required TRUE No suspect material seen.		No sample required FALSE Not accessed. No key available.	No sample required FALSE Not accessed.	No sample required TRUE No suspect material seen.	TRUE	TRUE	No sample required FALSE Not accessed. No key available.	TRUE	No sample required TRUE No suspect material seen. No access Understairs Cupboard	No sample required TRUE No suspect material seen. No access Understairs Cupboard	room.	No Asbestos Detected TRUE quantity in the room but this indicates that there is ACM in the	the surveying contractor was incorrect where they had indicated	NO sample required FALSE NOT accessed. NO key available.	TA 60	No sample required FALSE Not accessed. No key available.	Asbestos Type Access Made Comments
						s Cupboard	s Cupboard			s Cupboard	s Cupboard		re is ACM in the	ley had indicated a	data annidad bu			
0	0	0	0	0	0	0	0	0	0	0	0		0		c	<b>S</b>	0	Materials Sco
0	0	0	0	0	0	0	. 0	0	0	0	0		0		c	>	0	Extenet of Damage Score
0	0	0	0	0	0	0	0	0	0	0	0 .		0		c	>	0	Surface Treatment Score

444444444	ω	1 1 8
	0	-1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -
Internal	Internal	Internal / External Internal Internal
0000000000	<b>O</b>	Frequency
		Re-Inspection Date
NO 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	N <sub>O</sub>	New Asbestos No
	0.00	Approximate Cost
		Target Completion Date
MHS	MHS	Responsibility (C-E / DE) MHS MHS

## SPEC024\_Code

LARKTGPSP11 9JN LARKTGPSP11 9JN

LARKTGPSP11 9JN

LARKTGPSP11 9JN LARKTGPSP11 9JN LARKTGPSP11 9JN

LARKTGPSP11 9JN LARKTGPSP11 9JN LARKTGPSP11 9JN

LARKTGPSP11 9JN LARKTGPSP11 9JN

LARKTGPSP11 9JN LARKTGPSP11 9JN

LARKTGPSP11 9JN LARKTGPSP11 9JN

000000000	Asbestos Type Score 0
000000000	Occupant Score Occupant Score 0 0 0 0 0
000000000	Disturbance pre Location Score 0 0
0000000000	Accessibility e Score 0
0000000000	Extent / Amount Score 0
0000000000	No Of Occupants O O O
0000000000	Frequency of Use Score 0
000000000	Average Time of Use Score

Type of Maintenance Score	Frequency of Maintenance Activity Score	Asbestos Status Priority Code	Priority Code	When and What	Last Inspection Date	Surveyor	Survey Type	Diagram Reference
00	0 0	No Action No Action	00		02/01/1900 02/01/1900		TYPE 2 TYPE 2	10 10
0	0	No Action	0		02/01/1900		TYPE 2	2
0	0	No Action	0		02/01/1900		TYPE	2
0	0	No Action	0		02/01/1900		TYPE	2
0	0	No Action	0		02/01/1900		TYPE	2
0	0	No Action	0		02/01/1900		ΤΥΡΕ	2
0	0	No Action	0		02/01/1900		TYPE	2
0	0	No Action	0		02/01/1900		TYP	E 2
0	0	No Action	0		02/01/1900		Τγp	E 2
0	0	No Action	0		02/01/1900		TγP	E 2
0	0	No Action	0		02/01/1900		Τγp	E 2
0	0	No Action	0		02/01/1900		ΤΥP	E 2
0	0	No Action	0		02/01/1900		ΤγP	E 2
0	0	No Action	0		02/01/1900		Τ¥Ρ	Σ 2