

E-mail: diosec-parli@mod.uk www.gov.uk/DIO

17 August 2017

Ref. FOI2017/07856

Dear

Thank you for your letter of 18 July 2017 to HMS Collingwood, Newgate Lane, Fareham, and Hampshire, PO14 1AS requesting the following information:

'We are writing to you to make a request under the Freedom of Information Act 2000 ("FOI") for the following information in relation to work carried out at HMS Collingwood in 1987.

- 1. Any contracts between Avon Lippiatt Hobbs and the Ministry of Defence for work carried
- 2. All documents related to all refurbishment works carried out at HMS Collingwood in 1987;
- 3. Any asbestos surveys carried out of HMS Collingwood."

This request for information has been passed to the Ministry of Defence (MOD) to respond to. I am treating your correspondence as a request for information under the Freedom of Information

A search for the information has now been completed within the MOD and I can confirm that some information in scope of your request is held.

I can confirm that we do not hold any information in relation to point one and two of your request. The information you have requested at point three can be found attached at annex A.

Under Section 16 of the Act (Advice and Assistance) you may find it helpful to note in regards to point one of your request the Defence Infrastructure Organisation are not aware of any work carried out by Avon Lippiatt Hobbs. In regards to point two of your request there are no records for the year specified. In regards to point three of your request, the Department holds a rolling asbestos register which is updated annually if asbestos is found or it is has been removed; the annex shows the most recent asbestos record dated April 2017.

If you have any queries regarding the content of this letter, please contact this office in the first

If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk).

Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <a href="https://ico.org.uk/">https://ico.org.uk/</a>.

Yours sincerely,

**DIO Secretariat** 

Infr	ence astructure	8		al Primo		ract Central		carillion	amey
Criteria:		EAT	ĺ	Location		M - SDA 29 - Portsm	outh		
Establishme	ent: H	IMS COLLINGWOOD		Buildin	ıg: A				
Spec024:				Option	: A	l			
Item UID	Floor	Room Description	Room ID	Access Made	Position	Asbestos Analysis Result	Asbestos Status	Total Risk Identified Risk Score	Approx Amount
HMS COLLING	WOOD - 110	7 TRAINER - 1742077 - COLW01SB0772				•	•		•
2487453	Ground	Simulator	1	Yes	Throughor Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - 2 SC	QUASH COURTS - 708052 - COLW0100062	3			I			
2489539	Ground	Squash Courts - Entrance Hall	1	Yes	Throughou	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489540	Ground	Squash Courts - Lobby stairs 4	1	Yes	Throughou	nt No Asbestos Detected	No Action	0 No Risk	0 N/A
2489541	Ground	Squash Courts - Court 1	1	Yes	Throughou	nt No Asbestos Detected	No Action	0 No Risk	0 N/A
2489542	Ground	Squash Courts - Court 2	1	Yes	Throughou	nt No Asbestos Detected	No Action	0 No Risk	0 N/A
2489543	Ground	Squash Courts - Gallery Court 1	1	Yes	Throughou	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489544	Ground	Squash Courts - Gallery Court 2	1	Yes	Throughou	nt No Asbestos Detected	No Action	0 No Risk	0 N/A
2489545	Ground	Squash Courts - Stairs	1	Yes	Throughou	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489546	Roof	Squash Courts - Roof	1	Yes	Roof Slate	s Presumed Asbestos Content	Monitor	6 Low	0 N/A
HMS COLLING	WOOD - ACC	COMMODATION BLOCK (LOWE) - 1183306	- COLW0100	0766					
2487467	Ground	Junior Ranks Accommodation (Lowe)	1	Yes	Throughou Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - ACC	COMMODATION BLOCK (NIVEN) - 1183307	- COLW0100	0777	<u>.i                                      </u>	!	-		
2487447	Ground	Junior Ranks Accommodation	1	Yes	Throughou Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - AGE	RICULTURAL STORE - 708054 - COLW0100	0647		•	•	•		
2487245	Ground	Gardeners Store - Workshop 1	1	Yes	Throughou	It No Asbestos Detected	No Action	0 No Risk	0 N/A
2487246	Ground	Gardeners Store - Workshop 2	1	Yes	Throughou	It No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - AMA	ATEUR RADIO CLUB AND CWO - 708028 -	COLW010005	12	-	<u> </u>		<del> </del>	
2489022	Ground	Welfare / Radio Club - Corridor	1	Yes	Throughou	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489023	Ground	Welfare / Radio Club - Office 1	1	Yes	Throughou	nt No Asbestos Detected	No Action	0 No Risk	0 N/A
2489024	Ground	Welfare / Radio Club - Office 2	1	Yes	Throughou	No Asbestos Detected	No Action	0 No Risk	0 N/A
<u>i l</u>								1	

Run Date: 05/04/2017 08:42:40

	fence	R	•						
Infi	rastructure ganisation				osReais			carillion	amey
2489025	Ground	Welfare / Radio Club - Office 3	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2489026	Ground	Welfare / Radio Club - Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489027	Ground	Welfare / Radio Club - Office 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489028	Ground	Welfare / Radio Club - Office 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489029	Ground	Welfare / Radio Club - Admin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489030	Ground	Welfare / Radio Club - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489031	Ground	Welfare / Radio Club - Lobby Entrance	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489032	Ground	Welfare / Radio Club - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489033	Ground	Welfare / Radio Club - WC Lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489034	Ground	Welfare / Radio Club - Female WC	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489035	Ground	Welfare / Radio Club - Male WC	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489036	Ground	Welfare / Radio Club - Radio Club Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489037	Ground	Welfare / Radio Club - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489038	External	Welfare / Radio Club - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - ARMOU	JRY / CLASSROOM / DRILL SHED - 7080	39 - COLW0	1000625		<u> </u>		<u> </u>	
2490654	Ground	Drill Shed - Toilet East	1	Yes	Panels to	Amosite	Monitor	6 Low	0 N/A
2490655	Ground	Drill Shed - Classroom (east)	1	No	AC Ducts		No Action	0 No Risk	0 N/A
2490656	Ground	Drill Shed - Small Arms Trainer	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490657	Ground	Drill Shed - Small Arms Trainer (roof/loft)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490658	Ground	Drill Shed - Corridor East	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490659	Ground	Drill Shed - Entrance North Lobby	1	Yes	Panels	Amosite	Monitor	6 Low	0 N/A
2490660	Ground	Drill Shed - Corridor West	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490661	Ground	Drill Shed - Tea Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490662	Ground	Drill Shed - WC West Hall	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490663	Ground	Drill Shed - Shower Room (west)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 2 of 420

		ence astructure	F	Regional Prime Contract Central							
( The second sec		anisation			<b>Asbest</b>	osReais	ster		carillion	ı amey 🥒	
2	2490664	Ground	Drill Shed - Female Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490665	Ground	Drill Shed - State CEM Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490666	Ground	Drill Shed - CEM Training Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490667	Ground	Drill Shed - Electrical Plant (cupboard)	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A	
2	2490668	Ground	Drill Shed - Armoury Workshop	1	Yes	Main Fire Doors	Presumed Asbestos Content	Monitor	5 Low	0 N/A	
2	2490669	Ground	Drill Shed - Gun room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490670	Ground	Drill Shed - Office (main)	1	No	AC Ducts		No Action	0 No Risk	0 N/A	
2	2490671	Ground	Drill Shed - Store room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490672	Ground	Drill Shed - Store room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490673	Ground	Drill Shed - Drill Shed	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
HMS C	COLLING	I VOOD - ASUAT	11 - CONISTON CLASSROOM 8 - 17420	76 - COLW0	1SB0771						
2	2487454	Ground	Classroom - Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487455	Ground	Classroom - Exercise Control Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487456	Ground	Classroom - OPS Room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487457	Ground	Classroom - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487458	Ground	Classroom - Sonar Control Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487459	Ground	Classroom - OPS Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2487460	External	Classroom - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
HMS C	COLLING	<u> </u> VOOD - ATLAN	<u> </u> TIC BUILDING - 711070 - COLW0100063	3							
2	2490793	Second	Atlantic Block - S28	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490794	Second	Atlantic Block - S31	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490795	Second	Atlantic Block - S30	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490796	Second	Atlantic Block - S33	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2490797	Second	Atlantic Block - S32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

Ш,		ence		Regiona	al Prime	e Contra	act Central		carillionamey	
20000		astructure anisation			Asbest	osRegis	ster		carillion	amey
	2490798	Second	Atlantic Block - S33	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490799	Second	Atlantic Block - S34	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490800	Second	Atlantic Block - Stairs 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490801	Second	Atlantic Block - Stairs 3 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490802	Second	Atlantic Block - DOE Room 1a	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490803	Second	Atlantic Block - DOE Room 1	1	Yes	Flexible Gaiter to	No Asbestos Detected	No Action	0 No Risk	2 No.
	2490804	Second	Atlantic Block - Kitchen 2 (opp stairs 3)	1	Yes	ceiling panels	Amosite	Monitor	6 Low	0 N/A
	2490805	Second	Atlantic Block - Roof Access	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490806	Second	Atlantic Block - S40	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490807	Second	Atlantic Block - S41	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490808	Second	Atlantic Block - S42	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490809	Second	Atlantic Block - S43	1	Yes	panels lining	Amosite	Monitor	6 Low	0 N/A
	2490810	Second	Atlantic Block - S44	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490811	Second	Atlantic Block - Kitchen 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490812	Second	Atlantic Block - S39 Drawing Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490813	Second	Atlantic Block - S39	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490814	Second	Atlantic Block - Stairs 4 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490815	Second	Atlantic Block - Stairs 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490816	Second	Atlantic Block - Female WC2	1	Yes	ceiling		No Action	0 No Risk	0 N/A
H	2490817	Second	Atlantic Block - Male WC3	1	Yes	ceiling	1	No Action	0 No Risk	0 N/A
#	2490818	Second	Atlantic Block - S36	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490819	Second	Atlantic Block - S35	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490820	Second	Atlantic Block - S35	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490821	Second	Atlantic Block - S38	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence astructure	F	Region	ct Central		carillion			
2585	Orga	anisation			<u>Asbest</u>	osReais	ster		carillion	amey
	2490822	Second	Atlantic Block - Lobby 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490823	Ground	Atlantic Block - Loft Roof space	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490824	Ground	Atlantic Block - Loft Tank Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490825	First	Atlantic Block - Stairs 4	1	Yes	Staircase	Chrysotile	Monitor	3 Very Low	0 N/A
	2490826	First	Atlantic Block - Stairs 4 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490827	First	Atlantic Block - Male WC 1 Lobby	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2490828	First	Atlantic Block - Male WC 1	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2490829	First	Atlantic Block - Female WC 1 Lobby	1	Yes	ceiling panels		No Action	0 No Risk	0 N/A
	2490830	First	Atlantic Block - Female w/c 1	1	Yes	ceiling		No Action	0 No Risk	0 N/A
	2490831	First	Atlantic Block - Cleaning Cupboard 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490832	First	Atlantic Block - Kitchen 1	1	Yes	Sink		No Action	0 No Risk	0 N/A
	2490833	First	Atlantic Block - F41	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490834	First	Atlantic Block - Male WC 1 Cupboard (DOE)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490835	First	Atlantic Block - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490836	First	Atlantic Block - F43	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490837	First	Atlantic Block - F44	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490838	First	Atlantic Block - F45	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490839	First	Atlantic Block - F46	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490840	First	Atlantic Block - F46	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490841	First	Atlantic Block - F47A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490842	First	Atlantic Block - F47	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
+	2490843	First	Atlantic Block - F47	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
$\parallel$	2490844	First	Atlantic Block - F48	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2490845	First	Atlantic Block - corridor 2	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2490846	First	Atlantic Block - F51	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490847	First	Atlantic Block - F49	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 5 of 420

		ence	R	egiona	al Prim	e Contra	act Central			
denta	Infra	astructure anisation				osRegis			carillion	amey
	2490848	First	Atlantic Block - F50	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490849	First	Atlantic Block - F52	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490850	First	Atlantic Block - F53	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490851	First	Atlantic Block - F53	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
	2490852	First	Atlantic Block - Lobby F53	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
	2490853	First	Atlantic Block - Lobby F53	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490854	First	Atlantic Block - Lobby F54	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490763	Second	Atlantic Block - Female WC 1 (next to room S15)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490764	Second	Atlantic Block - Female WC 1 lobby	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490765	Second	Atlantic Block - Femalw WC 1 Hatch	1	Yes	lining to ceiling void	Amosite	Monitor	6 Low	0 N/A
	2490766	Second	Atlantic Block - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490767	Second	Atlantic Block - Cleaning Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490768	Second	Atlantic Block - DOE	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490769	Second	Atlantic Block - No2 Conference Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490770	Second	Atlantic Block - Kitchen 1 (adj room S18)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490771	Second	Atlantic Block - Kitchen 1 (adj room S18)	1	Yes	lining to ceiling void	Amosite	Monitor	6 Low	0 N/A
	2490772	Second	Atlantic Block - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490773	Second	Atlantic Block - S18 IG Project Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490774	Second	Atlantic Block - S19 IG Project Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490775	Second	Atlantic Block - S20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490776	Second	Atlantic Block - Male WC 2 (opp S19 & S20)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490777	Second	Atlantic Block - Male WC 2 (opp S19 & S20)	1	Yes	lining to air con duct x 2	Amosite	Monitor	6 Low	0 N/A
	2490778	Second	Atlantic Block - Male WC 1 (opp S19 & S20)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490779	Second	Atlantic Block - Male WC 1 (opp S19 & S20)	1	Yes	lining to air con duct x 2	Amosite	Monitor	6 Low	0 N/A

Page:

6 of 420

Run By:

	Defence Infrastructu			Regiona	al Prime	e Contra	act Central	•	carillionamey	
	Infra Orga	structure anisation			Asbesto	osReais	ter		carillion	amey
	2490780	Second	Atlantic Block - Male WC 1 & 2 Lobby (opp S19 & S	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490781	Second	Atlantic Block - Stairs 2 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490782	Second	Atlantic Block - Stairs 2	1	Yes	panels to	Amosite	Monitor	6 Low	0 N/A
	2490783	Second	Atlantic Block - stairs 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490784	Second	Atlantic Block - S21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490785	Second	Atlantic Block - S24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490786	Second	Atlantic Block - S22	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490787	Second	Atlantic Block - S23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490788	Second	Atlantic Block - S26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490789	Second	Atlantic Block - S29	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490790	Second	Atlantic Block - S25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490791	Second	Atlantic Block - S27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490792	Second	Atlantic Block - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490744	Second	Atlantic Block - Stairs 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490745	Second	Atlantic Block - Stairs 1 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490746	Second	Atlantic Block - S1 Civillian Personnel MG	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490747	Second	Atlantic Block - S1 Civilian Personnel MG	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490748	Second	Atlantic Block - S2 Civilian Personnel Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490749	Second	Atlantic Block - S2 Civillian Personnel Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490750	Second	Atlantic Block - S2 -S1 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490751	Second	Atlantic Block - S4 IS (flash IP)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490752	Second	Atlantic Block - S3 Info System	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2490753	Second	Atlantic Block - S5 Data Preparation	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$   \uparrow \uparrow  $	2490754	Second	Atlantic Block - S6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

4	Defence Infrastructure Organisation			Regiona		carillionamey				
	Infra Orga	astructure anisation				osRegis			carillior	amey
	2490755	Second	Atlantic Block - S7/8 Server Room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490756	Second	Atlantic Block - S9 Training Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490757	Second	Atlantic Block - S10 Stores	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490758	Second	Atlantic Block - S11 IS Software CONS	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490759	Second	Atlantic Block - S13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490760	Second	Atlantic Block - S12 File Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490761	Second	Atlantic Block - S16 STR	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2490762	Second	Atlantic Block - S15 PVA	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H +	2491028	Ground	Atlantic Block - Male WC 3 Lobby	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
H +	2491029	Ground	Atlantic Block - Male WC 3	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2491030	Ground	Atlantic Block - Female WC 2	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2491031	Ground	Atlantic Block - North Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491032	Ground	Atlantic Block - Stairs 4	1	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491033	Ground	Atlantic Block - Stairs 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491034	Ground	Atlantic Block - External Loading Bay	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491035	Ground	Atlantic Block - Book Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491036	Ground	Atlantic Block - G33	1	Yes	panels to	Amosite	Monitor	6 Low	0 N/A
	2491037	Ground	Atlantic Block - G32	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2491038	Ground	Atlantic Block - G31	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491039	Ground	Atlantic Block - G36	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491040	Ground	Atlantic Block - Corridor 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491041	Ground	Atlantic Block - G34	1	Yes	ceiling slats	Amosite	Monitor	6 Low	0 N/A
	2491042	Ground	Atlantic Block - G34B	1	Yes	ceiling slats	Amosite	Monitor	6 Low	0 N/A
	2491043	Ground	Atlantic Block - G34	1	Yes	bulk heads	Amosite	Monitor	6 Low	0 N/A
$  \uparrow \uparrow  $	2491044	Ground	Atlantic Block - G34A Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491045	Ground	Atlantic Block - G34B	1	Yes	bulk heads	Amosite	Monitor	6 Low	0 N/A
шШ		1								

Defe	ence astructure	F				act Central		carillion	A
Orga	anisation			Asbest	osRegis	ster		carillion	amey 🦳
2491046	Ground	Atlantic Block - electrical Intake Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491047	Ground	Atlantic Block - Plant Room	1	Yes	Pipework	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2491048	First	Atlantic Block - Plant Room	1	Yes	Air- Conditioning	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2491049	Ground	Atlantic Block - Viewing Platform	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491050	Ground	Atlantic Block - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490997	Ground	Atlantic Block - G24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490998	Ground	Atlantic Block - G22	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490999	Ground	Atlantic Block - G23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491000	Ground	Atlantic Block - G20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491001	Ground	Atlantic Block - G19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491002	Ground	Atlantic Block - G18	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491003	Ground	Atlantic Block - G17	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491004	Ground	Atlantic Block - G15	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491005	Ground	Atlantic Block - G16	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491006	Ground	Atlantic Block - Bond Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491007	Ground	Atlantic Block - CELL1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491008	Ground	Atlantic Block - CELL2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491009	Ground	Atlantic Block - CELL3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491010	Ground	Atlantic Block - CELL4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491011	Ground	Atlantic Block - Wash Room CELL	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491012	Ground	Atlantic Block - CELL Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491013	Ground	Atlantic Block - External Outside Link	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491014	Ground	Atlantic Block - Wash Room (G14A)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A

**Page:** 9 of 420

	Defe		F	Regiona	al Prime	e Contra	ct Central		carillionamey	
	Orga	structure anisation			Asbest	osReais	ster		carillion	amey
	2491015	Ground	Atlantic Block - UIP Entrance Lobby	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491016	Ground	Atlantic Block - UIP Reception	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491017	Ground	Atlantic Block - Stairs 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491018	Ground	Atlantic Block - G26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491019	Ground	Atlantic Block - Corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491020	Ground	Atlantic Block - Print Room	1	Yes	Sink		No Action	0 No Risk	0 N/A
	2491021	Ground	Atlantic Block - G29	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2491022	Ground	Atlantic Block - G28	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2491023	Ground	Atlantic Block - RU Store	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491024	Ground	Atlantic Block - DIC 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491025	Ground	Atlantic Block - DIC 2	1	Yes	Underneath of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491026	Ground	Atlantic Block - G30	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491027	Ground	Atlantic Block - Rest Room	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490886	First	Atlantic Block - F33 Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490887	First	Atlantic Block - F30	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490888	First	Atlantic Block - Straircase 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490889	First	Atlantic Block - Lobby to Staircase 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490890	First	Atlantic Block - F30 Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490891	First	Atlantic Block - F29	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490892	First	Atlantic Block - MWC (near room F60)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490893	First	Atlantic Block - F32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2490894	First	Atlantic Block - F32	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490895	First	Atlantic Block - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel \parallel$	2490896	First	Atlantic Block - F31	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	fence rastructure	F	Regiona	al Prime	e Contra	act Central		carillion	A
Org	ganisation			Asbest	osRegis	ster		carillion	1 amey 🥟
2490897	First	Atlantic Block - F28 Registry	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2490898	First	Atlantic Block - F27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490899	First	Atlantic Block - F26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490900	First	Atlantic Block - F25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490901	First	Atlantic Block - F24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490902	First	Atlantic Block - F23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490903	First	Atlantic Block - F22 Training	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490904	First	Atlantic Block - F21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490905	First	Atlantic Block - F20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490906	First	Atlantic Block - staircase 2	1	Yes	Under Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
2490907	First	Atlantic Block - Staircase 2 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490908	First	Atlantic Block - Staircase 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490909	First	Atlantic Block - Male WC F19A (near staircase 2)	1	Yes	ceiling panels / tiles	Amosite	Monitor	6 Low	0 N/A
2490910	First	Atlantic Block - Male WC F19A Lobby	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2490911	First	Atlantic Block - Male WC F19A Urinal	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2490912	First	Atlantic Block - Cleaners Cupboard (near staircase	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490913	First	Atlantic Block - F19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490914	First	Atlantic Block - F18	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490915	First	Atlantic Block - Wash Up F17A (next to F18)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2490916	First	Atlantic Block - F17	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490917	First	Atlantic Block - F16 No2 Conference Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490918	First	Atlantic Block - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490919	First	Atlantic Block - Reg Store	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
2490920	First	Atlantic Block - DOE	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence	F	Regiona	al Prime	e Contra	act Central	•	<u>**</u>	
	Infrastructure Organisation			Asbest	osReais	ster		carillion	ı amey 🥍
24909		Atlantic Block - Drying Room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	922 First	Atlantic Block - Riser in Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	923 First	Atlantic Block - Ladies WC3 (near staircase 2) F15	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
24909	924 First	Atlantic Block - Ladies WC4 (near staircase 2) F15	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
24909	925 First	Atlantic Block - F15	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	926 First	Atlantic Block - F13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	927 First	Atlantic Block - F12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	928 First	Atlantic Block - F14 Planning Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	929 First	Atlantic Block - F11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	930 First	Atlantic Block - ERB	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	931 First	Atlantic Block - F10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	932 First	Atlantic Block - F7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	933 First	Atlantic Block - F9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	934 First	Atlantic Block - F8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	935 First	Atlantic Block - F6 STMA Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	936 First	Atlantic Block - F5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	937 First	Atlantic Block - F4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	938 First	Atlantic Block - Staircase 1	1	Yes	Under Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
24909	939 First	Atlantic Block - Staircase 1 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	940 First	Atlantic Block - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	941 First	Atlantic Block - Staircase 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	942 First	Atlantic Block - Staircase 6	1	Yes	Floor (Light Brown Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24909	943 First	Atlantic Block - Staircase 6	1	Yes	Side of	Chrysotile	Monitor	3 Very Low	0 N/A
24909	944 First	Atlantic Block - Staircase 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence		Regiona	al Prim	e Contra	act Central	•	**	A
Org	astructure anisation			Asbest	osReais	ster		carillio	ı amey 🥍
2490945	First	Atlantic Block - F2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490946	First	Atlantic Block - F3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490947	First	Atlantic Block - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490855	First	Atlantic Block - Lobby F55	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490856	First	Atlantic Block - F56	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490857	First	Atlantic Block - F56	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2490858	First	Atlantic Block - F57	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490859	First	Atlantic Block - F54	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490860	First	Atlantic Block - F56 Lobby	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490861	First	Atlantic Block - F56 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490862	First	Atlantic Block - F59	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2490863	First	Atlantic Block - F59	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490864	First	Atlantic Block - F59	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490865	First	Atlantic Block - Stairs 5 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490866	First	Atlantic Block - F58 Lobby	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490867	First	Atlantic Block - Stairs 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490868	First	Atlantic Block - Stairs 5	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
2490869	First	Atlantic Block - F58	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490870	First	Atlantic Block - F58	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490871	First	Atlantic Block - F58 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490872	First	Atlantic Block - F60	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490873	First	Atlantic Block - F60	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
2490874	First	Atlantic Block - F41 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490875	First	Atlantic Block - F40	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490876	First	Atlantic Block - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490877	First	Atlantic Block - F38	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490878	First	Atlantic Block - F42	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defence Infrastructur Organisation 2490879 First			Regiona	al Prime	e Contra	act Central			
Infra Orga	structure anisation				osReais			carillion	amey
		Atlantic Block - F34	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2490880	First	Atlantic Block - F37	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490881	First	Atlantic Block - F36	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490882	First	Atlantic Block - F35	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490883	First	Atlantic Block - F35 Utility Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490884	First	Atlantic Block - F34	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490885	First	Atlantic Block - F33	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490948	First	Atlantic Block - F1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490949	First	Atlantic Block - Corridor 5	1	Yes	panels to		No Action	0 No Risk	0 N/A
2490950	First	Atlantic Block - Toilet Lobby	1	Yes	panels to		No Action	0 No Risk	0 N/A
2490951	First	Atlantic Block - Toilet Lobby	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
2490952	First	Atlantic Block - Male WC	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
2490953	First	Atlantic Block - WC	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
2490954	First	Atlantic Block - Female WC 1 Lobby	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
2490955	Ground	Atlantic Block - Stairs 6	1	Yes	Floor (Light	Chrysotile	Monitor	3 Very Low	0 N/A
2490956	Ground	Atlantic Block - Stairs 6	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490957	Ground	Atlantic Block - Stairs 6	1	No	Above Fixed		No Action	0 No Risk	0 N/A
2490958	Ground	Atlantic Block - G1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490959	Ground	Atlantic Block - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490960	Ground	Atlantic Block - WC G1C Lobby (opp HQ1)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2490961	Ground	Atlantic Block - Male WC G1C (opp HQ1)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2490962	Ground	Atlantic Block - G2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490963	Ground	Atlantic Block - G3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490964	Ground	Atlantic Block - Equipment Room G4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490965	Ground	Atlantic Block - G5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490966	Ground	Atlantic Block - Store Dup Keys	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
2490966	Ground	Atlantic Block - Store Dup Keys	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	

	Defe			Regiona	al Prime	e Contra	act Central			
	Orga	structure			Asbest	osReais	ster		carillion	amey
	2490967	Ground	Atlantic Block - DOE	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490968	Ground	Atlantic Block - G6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490969	Ground	Atlantic Block - Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2490970	Ground	Atlantic Block - Corridor 1	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2490971	Ground	Atlantic Block - Stair 1	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2490972	Ground	Atlantic Block - Stair 1	1	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490973	Ground	Atlantic Block - South Lobby Entrance	1	Yes	Floor (Brown /	Chrysotile	Monitor	3 Very Low	0 N/A
П	2490974	Ground	Atlantic Block - Cycle Rack	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490975	Ground	Atlantic Block - Bin Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490976	Ground	Atlantic Block - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490977	Ground	Atlantic Block - G7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490978	Ground	Atlantic Block - G9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490979	Ground	Atlantic Block - G10B	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490980	Ground	Atlantic Block - G8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490981	Ground	Atlantic Block - G11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490982	Ground	Atlantic Block - G12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490983	Ground	Atlantic Block - G13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490984	Ground	Atlantic Block - G14	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490985	Ground	Atlantic Block - Wash Up	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490986	Ground	Atlantic Block - G10A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490987	Ground	Atlantic Block - G10C	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490988	Ground	Atlantic Block - DOE 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490989	Ground	Atlantic Block - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490990	Ground	Atlantic Block - Male WC 2 Lobby (G14C)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A

Run By:

CD\\svc\_ProRepuser

	Defe	ence istructure	F	Regiona	l Prime	e Contra	act Central		***	A
		anisation		-	Asbest	osRegis	ster		carillio	n amey 🦳
	2490991	Ground	Atlantic Block - Male WC 2 (G14C)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
2	2490992	Ground	Atlantic Block - Female WC 1 Lobby (G14D)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490993	Ground	Atlantic Block - Female WC 1 (G14D)	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2490994	Ground	Atlantic Block - Stairs 2	1	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490995	Ground	Atlantic Block - G25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490996	Ground	Atlantic Block - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS (	COLLINGW	OOD - BAND I	ROOM / RUGBY CLUB BAR - 708002 - Co	OLW0100028						
	2488925	Ground	Corporals Club - Beer Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488926	Ground	Corporals Club - Gents WC	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488927	Ground	Corporals Club - Ladies WC	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488928	Ground	Corporals Club - Main Bar / Dance Area	1	Yes	panel on doors		No Action	0 No Risk	0 N/A
2	2488929	Ground	Corporals Club - Foyer	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
1	2488930	Ground	Corporals Club - Cleaning Cupboard	1	Yes	Floor (Brown		No Action	0 No Risk	0 N/A
2	2488931	Ground	Corporals Club - Band Practice Area	1	Yes	panel on doors		No Action	0 No Risk	0 N/A
	2488932	Ground	Corporals Club - Corridor	1	Yes	panel on		No Action	0 No Risk	0 N/A
	2488933	Ground	Corporals Club - Store 3 (beer store)	1	Yes	high level conduit near	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488934	Ground	Corporals Club - Store 4	1	Yes	Ceiling Void (Lagging	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488935	Ground	Corporals Club - Store 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
1	2488936	Ground	Corporals Club - Crew Room	1	Yes	panel on		No Action	0 No Risk	0 N/A
	2488937	Ground	Corporals Club - Store 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488938	Ground	Corporals Club - Office Next to Crew Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488939	Ground	Corporals Club - Foyer 2 north end of bldg adjacen	1	Yes	panel on door		No Action	0 No Risk	0 N/A
1 2	2488940	Ground	Corporals Club - Crew Room	1	Yes	Loft / Ceiling		No Action	0 No Risk	0 N/A
	2488941	Ground	Corporals Club - Crew Room	1	Yes	Ceiling Void		No Action	0 No Risk	0 N/A
	2488942	Ground	Corporals Club - Crew Room	1	Yes	Pipes in		No Action	0 No Risk	0 N/A
	2488943	Ground	Corporals Club - Corridor	1	Yes	Floor		No Action	0 No Risk	0 N/A

	Defence	F	Regiona	al Prim	e Contra	act Central	•	**	
	Infrastructure Organisation			Asbest	osReais	ster		carillio	n amey 🥍
2488	3944 Ground	Corporals Club - crew room	1	Yes	Pipes	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3945 Roof	Corporals Club - external roof	1	Yes	roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3946 External	Corporals Club - external west side of building	1	Yes	box cover to piping		No Action	0 No Risk	0 N/A
2488	3947 External	Corporals Club - external west side of building	1	Yes	Pipeing / Flue		No Action	0 No Risk	0 N/A
2488	3948 Ground	Corporals Club - east main entrance	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3949 Ground	Corporals Club - Store 2 (at main entrance)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3950 Ground	Corporals Club - Office Next	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3951 Ground	Corporals Club - Store 1	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3923 Ground	Corporals Club - Main Bar Area	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	3924 Ground	Corporals Club - Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
IMS COL	<u> </u>								
2488	3662 Ground	Other Liquid Storage - SR Beer Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
IMS COL	LINGWOOD - BOILI	L ER HOUSE STORE / TOILET - 707981 - CO	LW0100020	3		1			
2487	7164 Ground	Store House - Wash Room	1	Yes	Cable		No Action	0 No Risk	0 N/A
2487	7165 Ground	Store House - Wash Room	1	Yes	Cable Cover		No Action	0 No Risk	0 N/A
2487	7166 Ground	Store House - Wash Room	1	Yes	Cable Cover		No Action	0 No Risk	0 N/A
2487	7167 Ground	Store House - Wash Room	1	Yes	Cable Cover		No Action	0 No Risk	0 N/A
2487	7168 Ground	Store House - Wash Room	1	Yes	Ceiling Tiles		No Action	0 No Risk	0 N/A
2487	7169 Ground	Store House - Toilet	1	Yes	Ceiling Tiles		No Action	0 No Risk	0 N/A
2487	7170 Ground	Store House - Chemical Store	1	Yes	Ceiling Tiles		No Action	0 No Risk	0 N/A
2487	7171 Ground	Store House - Acid Store	1	Yes	Ceiling Tiles		No Action	0 No Risk	0 N/A
2487	7172 Ground	Store House - Acid Store	1	Yes	ceiling vent		No Action	0 No Risk	0 N/A
IMS COL	LINGWOOD - BRYS	SON 701 JR SLA - 708100 - COLW0100070	1						
2487	7473 Ground	Accommodation Block - g/f Cleaners Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	7474 Ground	Accommodation Block - g/f Telephone Box	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	7475 Ground	Accommodation Block - g/f Stairwell adjacent to ma	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	7476 Ground	Accommodation Block - g/f electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central			
) Infra	structure anisation				osReais			carillior	amey
	Ground	Accommodation Block - g/f Flat 1A - cupboard	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2487478	Ground	Accommodation Block - g/f Flat 1A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487479	Ground	Accommodation Block - g/f Flat 1A - Locker room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487480	Ground	Accommodation Block - g/f Flat 1A - ladies toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487481	Ground	Accommodation Block - g/f Flat 1A - mens toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487482	Ground	Accommodation Block - g/f Flat 1A - lecture room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487483	Ground	Accommodation Block - g/f Flat 1A - main office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487484	Ground	Accommodation Block - g/f Flat 2A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487485	Ground	Accommodation Block - g/f Flat 2A - pipe riser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487486	Ground	Accommodation Block - g/f Flat 2A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487487	Ground	Accommodation Block - g/f Flat 2A - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487488	Ground	Accommodation Block - g/f Flat 2A - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487489	Ground	Accommodation Block - g/f Flat 2A - office 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487490	Ground	Accommodation Block - g/f Flat 2A - office 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487491	Ground	Accommodation Block - g/f Flat 2A - AS office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487492	Ground	Accommodation Block - g/f Flat 2A - OC PTTG	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487493	Ground	Accommodation Block - g/f Flat 2A - SO2 room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487494	Ground	Accommodation Block - g/f Flat 3A - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487495	Ground	Accommodation Block - g/f Flat 3A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487496	Ground	Accommodation Block - g/f Flat 3A - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487497	Ground	Accommodation Block - g/f Flat 3A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487498	Ground	Accommodation Block - g/f Flat 3A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487499	Ground	Accommodation Block - g/f Flat 3A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation			Regiona	•	carillionamey				
	Infra Orga	structure anisation				osReais			carillion	amey
	2487500	Ground	Accommodation Block - g/f Flat 3A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487501	Ground	Accommodation Block - g/f Flat 3A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487502	Ground	Accommodation Block - g/f Flat 4A - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487503	Ground	Accommodation Block - g/f Flat 4A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487504	Ground	Accommodation Block - g/f Flat 4A - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487505	Ground	Accommodation Block - g/f Flat 4A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487506	Ground	Accommodation Block - g/f Flat 4A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487507	Ground	Accommodation Block - g/f Flat 4A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487508	Ground	Accommodation Block - g/f cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487509	Ground	Accommodation Block - g/f outside cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487510	First	Accommodation Block - f/f stairwell	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
П	2487511	First	Accommodation Block - f/f Flat 1B - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487512	First	Accommodation Block - f/f Flat 1B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487513	First	Accommodation Block - f/f Flat 1B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487514	First	Accommodation Block - f/f Flat 1B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487515	First	Accommodation Block - f/f Flat 1B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487516	First	Accommodation Block - f/f Flat 1B - main room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487517	First	Accommodation Block - f/f Flat 2B - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487518	First	Accommodation Block - f/f Flat 2B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487519	First	Accommodation Block - f/f Flat 2B - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487520	First	Accommodation Block - f/f Flat 2B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487521	First	Accommodation Block - f/f Flat 2B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487522	First	Accommodation Block - f/f Flat 2B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	<b>Contra</b>	act Central	•	carillion	
		structure anisation			Asbesto	osReais	ter		carillion	amey
24		First	Accommodation Block - f/f Flat 3B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187524	First	Accommodation Block - f/f Flat 3B - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187525	First	Accommodation Block - f/f Flat 3B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187526	First	Accommodation Block - f/f Flat 3B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187527	First	Accommodation Block - f/f Flat 3B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187528	First	Accommodation Block - f/f Flat 3B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187529	First	Accommodation Block - f/f Flat 3B - main room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187530	Second	Accommodation Block - s/f stairwell	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
24	187531	Second	Accommodation Block - s/f Flat 1C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187532	Second	Accommodation Block - s/f Flat 1C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187533	Second	Accommodation Block - s/f Flat 1C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187534	Second	Accommodation Block - s/f Flat 1C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187535	Second	Accommodation Block - s/f Flat 1C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187536	Second	Accommodation Block - s/f Flat 1C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187537	Second	Accommodation Block - s/f Flat 2C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187538	Second	Accommodation Block - s/f Flat 2C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187539	Second	Accommodation Block - s/f Flat 2C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187540	Second	Accommodation Block - s/f Flat 2C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187541	Second	Accommodation Block - s/f Flat 2C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187542	Second	Accommodation Block - s/f Flat 2C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187543	Second	Accommodation Block - s/f Flat 3C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187544	Second	Accommodation Block - s/f Flat 3C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	187545	Second	Accommodation Block - s/f Flat 3C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		R	Regiona		<u>**</u>				
			- 4	Asbest	osReais	ter		carillior	amey
2487546	Second	Accommodation Block - s/f Flat 3C - drying cupboar	1	Yes			No Action	0 No Risk	0 N/A
2487547	Second	Accommodation Block - s/f Flat 3C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487548	Second	Accommodation Block - s/f flat 3C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487549	Second	Accommodation Block - s/f Flat 3C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487550	Second	Accommodation Block - s/f Flat 4C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487551	Second	Accommodation Block - s/f Flat 4C -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487552	Second	Accommodation Block - s/f Flat 4 C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487553	Second	Accommodation Block - s/f Flat 4C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487554	Second	Accommodation Block - s/f Flat 4C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487555	Second	Accommodation Block - s/f Flat 4C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487556	Second	Accommodation Block - s/f Flat 4C -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487557	Second	Accommodation Block - s/f Flat 4C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
S COLLINGW	VOOD - BRYSO	N 702 JR SLA - 711075 - COLW0100070	2					L L	
2487558	Ground	external outside cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487559	Ground	Accommodation Block - g/f telephone	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487560	Ground	Accommodation Block - g/f stairwell	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487561	Ground	Accommodation Block - g/f sitting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487562	Ground	Accommodation Block - g/f stairwell	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487563	Ground	Accommodation Block - g/f Flat 7A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487564	Ground	Accommodation Block - g/f Flat 7A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487565	Ground	Accommodation Block - g/f Flat 7A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487566	Ground	Accommodation Block - g/f Flat 7A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487567	Ground	Accommodation Block - g/f Flat 7A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487568	Ground	Accommodation Block - g/f Flat 7A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487546  2487547  2487548  2487549  2487550  2487551  2487552  2487553  2487554  2487555  2487556  2487556  2487557  S COLLINGW  2487558  2487560  2487561  2487562  2487563  2487564  2487565  2487565	2487547       Second         2487548       Second         2487549       Second         2487550       Second         2487551       Second         2487552       Second         2487553       Second         2487554       Second         2487555       Second         2487556       Second         2487557       Second         2487558       Ground         2487559       Ground         2487560       Ground         2487561       Ground         2487562       Ground         2487563       Ground         2487565       Ground         2487566       Ground         2487567       Ground	Commodation Block - s/f Flat 3C - drying cupboar	2487546   Second	Asbest   Second   Accommodation Block - s/f Flat 3C -   1   Yes   drying cupboar   2487547   Second   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 3C -   1   Yes   Accommodation Block - s/f Flat 4C -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block - s/f Flat 7A -   1   Yes   Accommodation Block -	AsbestosRedis   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Accommodation Block - s/f Flat 3C -   1   Yes   Throughout   Corridor   Accommodation Block - s/f Flat 4C -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Accommodation Block - s/f Flat 7A -   1   Yes   Throughout   Acco	AsbestosRedister   Cardina   Cardi	### Ashestos Register  2487546   Second   Accommodation Block - sf Flat 3C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487547   Second   Accommodation Block - sf Flat 3C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487548   Second   Accommodation Block - sf Flat 3C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487549   Second   Accommodation Block - sf Flat 3C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487549   Second   Accommodation Block - sf Flat 3C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487550   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487551   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487552   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487553   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487554   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487555   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487555   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487555   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487557   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487558   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487559   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487559   Second   Accommodation Block - sf Flat 4C -   1   Yes   Throughout   No Asbestos Detected   No Action    2487559   Ground   Accommodation Block - sf Flat 4C -   1   Yes   Th	Aspestos Register

	Defence Infrastructure Organisation			Regiona						
1	Infra Orga	structure				osReais			carillion	amey
	2487569	Ground	Accommodation Block - g/f Flat 7A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487570	Ground	Accommodation Block - g/f exterior cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487571	Ground	Accommodation Block - g/f exterior cupboard 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487572	Ground	Accommodation Block - g/f Flat 8A - cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487573	Ground	Accommodation Block - g/f Flat 8A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487574	Ground	Accommodation Block - g/f Flat 8A - ladies toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487575	Ground	Accommodation Block - g/f Flat 8A - mens toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487576	Ground	Accommodation Block - g/f Flat 8A - electrical cup	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487577	Ground	Accommodation Block - g/f Flat 9A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487578	Ground	Accommodation Block - g/f Flat 9A - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487579	Ground	Accommodation Block - g/f Flat 9A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487580	Ground	Accommodation Block - g/f Flat 9A - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2487581	Ground	Accommodation Block - g/f Flat 9A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487582	Ground	Accommodation Block - g/f Flat 9A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487583	Ground	Accommodation Block - g/f Flat 9A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487584	Ground	Accommodation Block - g/f Flat 11A - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487585	Ground	Accommodation Block - g/f Flat 11A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487586	Ground	Accommodation Block - g/f Flat 11A - storage room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487587	Ground	Accommodation Block - g/f Flat 10A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487588	Ground	Accommodation Block - g/f Flat 10A - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487589	Ground	Accommodation Block - g/f Flat 10A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487590	Ground	Accommodation Block - g/f Flat 10A - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487591	Ground	Accommodation Block - g/f Flat 10A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central			
Infra	structure				osRegis			carillion	amey
2487592	Ground	Accommodation Block - g/f Flat 10a - right cabin	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2487593	Ground	Accommodation Block - g/f Flat 10A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487594	Ground	Accommodation Block - g/f flat 10A - mens toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487595	Ground	Accommodation Block - g/f Flat 10A - ladies toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487596	Ground	Accommodation Block - g/f sitting room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487597	Ground	stairwell - ground to 2nd floors	1	Yes	Side of Stairs and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487598	First	Accommodation Block - f/f Flat 7B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487599	First	Accommodation Block - f/f Flat 7B - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487600	First	Accommodation Block - f/f Flat 7B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487601	First	Accommodation Block - f/f Flat 7B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487602	First	Accommodation Block - f/f Flat 7B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487603	First	Accommodation Block - f/f Flat 7B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487604	First	Accommodation Block - f/f Flat 7B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487605	First	Accommodation Block - f/f Flat 8B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487606	First	Accommodation Block - f/f Flat 8B - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487607	First	Accommodation Block - f/f Flat 8B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487608	First	Accommodation Block - f/f Flat 8B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487609	First	Accommodation Block - f/f Flat 8B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487638	Second	Accommodation Block - s/f Flat 7C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487639	Second	Accommodation Block - s/f Flat 7C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487640	Second	Accommodation Block - s/f flat 8C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487641	Second	Accommodation Block - s/f Flat 8C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487642	Second	Accommodation Block - s/f Flat 8C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central			
Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey
2487643	Second	Accommodation Block - s/f Flat 8C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487644	Second	Accommodation Block - s/f Flat 8C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487645	Second	Accommodation Block - s/f Flat 8C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487646	Second	Accommodation Block - s/f Flat 8C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487647	Second	Accommodation Block - s/f Flat 9C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487648	Second	Accommodation Block - s/f Flat 9C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487649	Second	Accommodation Block - s/f Flat 9C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487650	Second	Accommodation Block - s/f Flat 9C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487651	Second	Accommodation Block - s/f Flat 9C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487652	Second	Accommodation Block - s/f Flat 9C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487653	Second	Accommodation Block - s/f Flat 9C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487654	Second	Accommodation Block - s/f Flat 10C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487655	Second	Accommodation Block - s/f Flat 10C - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487656	Second	Accommodation Block - s/f Flat 10C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487657	Second	Accommodation Block - s/f Flat 10C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487658	Second	Accommodation Block - s/f Flat 10C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487659	Second	Accommodation Block - s/f Flat 10C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487660	Second	Accommodation Block - s/f Flat 10C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487661	Second	Accommodation Block - s/f Flat 11C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487662	Second	Accommodation Block - s/f Flat 11C - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487663	Second	Accommodation Block - s/f Flat 11C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487664	Second	Accommodation Block - s/f Flat 11C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487665	Second	Accommodation Block - s/f Flat 11C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central		carillionamey		
	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey	
	2487610	First	Accommodation Block - f/f Flat 8B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487611	First	Accommodation Block - f/f Flat 8B main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487612	First	Accommodation Block - f/f Flat 9B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2487613	First	Accommodation Block - f/f Flat 9B - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487614	First	Accommodation Block - f/f Flat 9B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487615	First	Accommodation Block - f/f Flat 9B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487616	First	Accommodation Block - f/f Flat 9B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487617	First	Accommodation Block - f/f Flat 9B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2487618	First	Accommodation Block - f/f Flat 9B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2487619	First	Accommodation Block - f/f Flat 10B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487620	First	Accommodation Block - f/f Flat 10B - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487621	First	Accommodation Block - f/f Flat 10B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487622	First	Accommodation Block - f/f Flat 10B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2487623	First	Accommodation Block - f/f Flat 10B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2487624	First	Accommodation Block - f/f Flat 10B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487625	First	Accommodation Block - f/f Flat 10B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487626	First	Accommodation Block - f/f Flat 11B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487627	First	Accommodation Block - f/f Flat 11B - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487628	First	Accommodation Block - f/f Flat 11B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
$\prod$	2487629	First	Accommodation Block - f/f Flat 11B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487630	First	Accommodation Block - f/f Flat 11B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487631	First	Accommodation Block - f/f Flat 11B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2487632	First	Accommodation Block - f/f Flat 11B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	fence	R	egiona	al Prim	e Contra	act Central			A	
Or	rastructure ganisation				osReais			carillionamey		
2487633	Second	Accommodation Block - s/f Flat 7C - corridor	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487634	Second	Accommodation Block - s/f Flat 7C - drying cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487635	Second	Accommodation Block - s/f Flat 7C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487636	Second	Accommodation Block - s/f Flat 7C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487637	Second	Accommodation Block - s/f Flat 7C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487666	Second	Accommodation Block - s/f Flat 11C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487667	Second	Accommodation Block - s/f Flat 11C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
HMS COLLING	GWOOD - BRYSC	ON 703 JR SLA - 708113 - COLW01000703				I	- I			
2487668	Ground	Accommodation Block - g/f cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487669	Ground	Accommodation Block - g/f electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487670	Ground	Accommodation Block - g/f accommodation office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487671	Ground	Accommodation Block - g/f bedding store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487672	Ground	Accommodation Block - g/f main toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487673	Ground	Accommodation Block - g/f toilet & shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487674	Ground	Accommodation Block - g/f 13A office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487675	Ground	Accommodation Block - g/f store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487676	Ground	Accommodation Block - g/f WO office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487677	Ground	Accommodation Block - g/f Flat 12A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487678	Ground	Accommodation Block - g/f Flat 12A - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487679	Ground	Accommodation Block - g/f Flat 12A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487680	Ground	Accommodation Block - g/f Flat 12A - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487681	Ground	Accommodation Block - g/f Flat 12A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487682	Ground	Accommodation Block - g/f Flat 12A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2487683	Ground	Accommodation Block - g/f Flat 12A - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	Defence Infrastructure		Regiona	al Prime	e Contra	act Central		carillionamey		
	Orga	astructure anisation			Ashest	osReais	ter		carillion	amey
	2487684	Ground to Second	Accommodation Block - Stairwell	1	Yes	Side of Stairs and	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487685	First	Accommodation Block - f/f Flat 12B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487686	First	Accommodation Block - f/f Flat 12B - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487687	First	Accommodation Block - f/f Flat 12B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487688	First	Accommodation Block - f/f Flat 12B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487689	First	Accommodation Block - f/f Flat 12B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487690	First	Accommodation Block - f/f Flat 12B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487691	First	Accommodation Block - f/f Flat 12B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487692	First	Accommodation Block - f/f Flat 13B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487693	First	Accommodation Block - f/f Flat 13B - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487694	First	Accommodation Block - f/f Flat 13B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487695	First	Accommodation Block - f/f Flat 13B - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487696	First	Accommodation Block - f/f Flat 13B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487697	First	Accommodation Block - f/f Flat 13B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487698	First	Accommodation Block - f/f Flat 13B - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487699	Second	Accommodation Block - s/f Flat 12C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487700	Second	Accommodation Block - s/f Flat 12C - drying cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487701	Second	Accommodation Block - s/f Flat 12C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487702	Second	Accommodation Block - s/f Flat 12C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487703	Second	Accommodation Block - s/f Flat 12C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487704	Second	Accommodation Block - s/f Flat 12C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487705	Second	Accommodation Block - s/f Flat 12C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487706	Second	Accommodation Block - s/f Flat 13C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence	F	Regiona	al Prime	e Contra	act Central			
	Infrastructure Organisation				osReais			carillion	n amev
248	7707 Second	Accommodation Block - s/f Flat 13C - drying cupboa	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7708 Second	Accommodation Block - s/f Flat 13C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7709 Second	Accommodation Block - s/f Flat 13C - heads	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7710 Second	Accommodation Block - s/f Flat 13C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7711 Second	Accommodation Block - s/f Flat 13C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7712 Second	Accommodation Block - s/f Flat 13C - main bedroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COI	LINGWOOD - BUCK	(LEY HALL - 708108 - COLW01000708		1		l		<u>'</u>	
248	8302 Ground	Accommodation Block - g/f Flat 39A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8303 Ground	Accommodation Block - g/f Flat 39A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8304 Ground	Accommodation Block - g/f Flat 39A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8305 First	Accommodation Block - f/f Flat 35B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8306 First	Accommodation Block - f/f Flat 35B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8307 First	Accommodation Block - f/f Flat 35B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8308 First	Accommodation Block - f/f Flat 35B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8309 First	Accommodation Block - f/f Flat 35B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8310 First	Accommodation Block - f/f Flat 35B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8311 First	Accommodation Block - f/f Flat 35B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8312 First	Accommodation Block - f/f Flat 36B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8313 First	Accommodation Block - f/f Flat 36B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8314 First	Accommodation Block - f/f Flat 36B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8315 First	Accommodation Block - f/f Flat 36B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8316 First	Accommodation Block - f/f Flat 36B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8317 First	Accommodation Block - f/f Flat 36B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	8318 First	Accommodation Block - f/f Flat 36B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•	carillionamey		
8	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey	
	2488319	First	Accommodation Block - f/f Flat 37B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488320	First	Accommodation Block - f/f Flat 37B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488321	First	Accommodation Block - f/f Flat 37B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488322	First	Accommodation Block - f/f Flat 37B - Drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488323	First	Accommodation Block - f/f Flat 37B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488324	First	Accommodation Block - f/f Flat 37B - All cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488325	First	Accommodation Block - f/f Flat 37B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488326	First	Accommodation Block - f/f Flat 38B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488327	First	Accommodation Block - f/f Flat 38B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488328	First	Accommodation Block - f/f Flat 38B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488329	First	Accommodation Block - f/f Flat 38B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488330	First	Accommodation Block - f/f Flat 38B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488331	First	Accommodation Block - f/f Flat 38B - all cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488332	First	Accommodation Block - f/f Flat 38B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488333	First	Accommodation Block - f/f Flat 39B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488334	First	Accommodation Block - f/f Flat 39B - Electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488335	First	Accommodation Block - f/f Flat 39B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488336	First	Accommodation Block - f/f Flat 39B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488337	First	Accommodation Block - f/f Flat 39B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488338	First	Accommodation Block - f/f Flat 39B - All cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488339	First	Accommodation Block - f/f Flat 39B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488340	First	Accommodation Block - f/f Flat 39C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488341	First	Accommodation Block - f/f Flat 39C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	Defe		F	Regiona	al Prime	<b>Contra</b>	act Central		carillion	
		astructure anisation			Asbesto	osReais	ter		carillion	mey
24	488342	First	Accommodation Block - f/f Flat 39C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488343	First	Accommodation Block - f/f Flat 39C - Drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488344	First	Accommodation Block - f/f Flat 39C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488345	First	Accommodation Block - f/f Flat 39C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488346	First	Accommodation Block - f/f Flat 39C - storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488347	Ground	Accommodation Block - Cupboard x 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488348	Ground	Accommodation Block - Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488349	Ground	Accommodation Block - Stairwells 1 & 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488350	Second	Accommodation Block - s/f Flat 35C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488351	Second	Accommodation Block - s/f Flat 35C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488352	Second	Accommodation Block - s/f Flat 35C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488353	Second	Accommodation Block - s/f Flat 35C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488354	Second	Accommodation Block - s/f Flat 35C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488355	Second	Accommodation Block - s/f Flat 35C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488356	Second	Accommodation Block - s/f Flat 35C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488357	Second	Accommodation Block - s/f Flat 36C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488358	Second	Accommodation Block - s/f Flat 36c - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488359	Second	Accommodation Block - s/f Flat 36C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488261	Ground	Accommodation Block - Block 35 - 36 Side of Stairs	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488262	Ground	Accommodation Block - Cupboard x 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488263	Ground	Accommodation Block - Stairwell 1 & 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488264	Ground	Accommodation Block - g/f Flat 35A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488265	Ground	Accommodation Block - g/f Flat 35A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Page:

30 of 420

Defe			Regiona	al Prime	e Contra	act Central		carillionamey		
Orga	structure anisation			Ashest	osReais	ter		carillion	amey	
2488266	Ground	Accommodation Block - g/f Flat 35A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488267	Ground	Accommodation Block - g/f Flat 35A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488268	Ground	Accommodation Block - g/f Flat 35A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488269	Ground	Accommodation Block - g/f Flat 35A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488270	Ground	Accommodation Block - g/f Flat 35A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488271	Ground	Accommodation Block - g/f Flat 36A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488272	Ground	Accommodation Block - g/f Flat 36A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488273	Ground	Accommodation Block - g/f Flat 36A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488274	Ground	Accommodation Block - g/f Flat 36A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488275	Ground	Accommodation Block - g/f Flat 36A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488276	Ground	Accommodation Block - g/f Flat 36A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488277	Ground	Accommodation Block - g/f Flat 36A Storage Cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488278	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488279	Ground	Accommodation Block - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488280	Ground	Accommodation Block - g/f 38A - Main Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488281	Ground	Accommodation Block - g/f 38A - Sitting Room Study	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488282	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488283	Ground	Accommodation Block - g/f Flat 37A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488284	Ground	Accommodation Block - g/f Flat 37A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488285	Ground	Accommodation Block - g/f Flat 37A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488286	Ground	Accommodation Block - g/f Flat 37A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488287	Ground	Accommodation Block - g/f Flat 37A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488288	Ground	Accommodation Block - g/f Flat 37A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	Defe			Regiona	al Prime	e Contra	act Central	•	carillionamey		
	Infra Orga	structure anisation			Ashesto	osReais	ter		carillion	amey	
		Ground	Accommodation Block - g/f Flat 37A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488290	Ground	Accommodation Block - Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488291	Ground	Accommodation Block - Payphone	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488292	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488293	Ground	Accommodation Block - g/f 38A - Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488294	Ground	Accommodation Block - g/f 38A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
Ш	2488295	Ground	Accommodation Block - g/f 38A - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
Ш	2488296	Ground	Accommodation Block - g/f 38A - Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488297	Ground	Accommodation Block - g/f 38A - Storage Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488298	Ground	Accommodation Block - g/f Flat 39A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488299	Ground	Accommodation Block - g/f Flat 39A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
П	2488300	Ground	Accommodation Block - g/f Flat 39A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488301	Ground	Accommodation Block - g/f Flat 39A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488360	Second	Accommodation Block - s/f Flat 36C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488361	Second	Accommodation Block - s/f Flat 36C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488362	Second	Accommodation Block - s/f Flat 36C - All cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488363	Second	Accommodation Block - s/f Flat 36C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
Ш	2488364	Second	Accommodation Block - s/f Flat 37C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488365	Second	Accommodation Block - s/f Flat 37C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488366	Second	Accommodation Block - s/f Flat 37C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488367	Second	Accommodation Block - s/f Flat 37C - Drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488368	Second	Accommodation Block - s/f Flat 37C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2488369	Second	Accommodation Block - s/f Flat 37C - all Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	ence astructure	F				act Central		carillion	
Org	anisation			Sbest	osReais			carillion	ıamey⊅
2488370	Second	Accommodation Block - s/f Flat 37C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
IS COLLING		IFIER ROOM - 707982 - COLW01000202	<u>.</u>						
2487158	Ground	Calorifier Room	1	Yes	Ceiling		No Action	0 No Risk	0 N/A
2487159	Ground	Calorifier Room	1	Yes	Pipe Flanges	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2487160	Ground	Calorifier Room	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
IS COLLING\	WOOD - CARLES	SS VC JR SLA - 1029879 - COLW010007	767		-			· ·	
2487468	Ground	Junior Ranks Accommodation (Careless)	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
IS COLLING\	WOOD - CERES	NAVAL STORES - 708058 - COLW0100	0641			•	•	•	
2488846	Ground	Ceres Stores - SW Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488847	Ground	Ceres Stores - Utilities Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488848	Ground	Ceres Stores - Computer Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488849	Ground	Ceres Stores - Main Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488850	Ground	Ceres Stores - NE Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488851	Ground	Ceres Stores - Restroom / Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488852	Ground	Ceres Stores - Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488853	Ground	Ceres Stores - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488854	Ground	Ceres Stores - Corridor to Office / Warehouse	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488855	Ground	Ceres Stores - Bale Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488856	Ground	Ceres Stores - Main Warehouse	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488857	Ground	Ceres Stores - R&D	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488858	Ground	Ceres Stores - Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488859	Ground	Ceres Stores - Office adj Warehouse	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488860	Ground	Ceres Stores - Laundry Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488861	First	Ceres Stores - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488862	External	Ceres Stores - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//

Run Date: 05/04/2017 08:42:40

	ence astructure			_		act Central	•	carillio	
Org	ganisation			Asbest	osReais	<u>ster</u>		Carillio	namey /
2491993	Ground	Changing Rooms	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - CHAN	 NGING ROOMS - 711062 - COLW0400021	11		<u> </u>	1			I
2491994	Ground	Changing Rooms	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - CHUR	RCH - CHURCH OF ENGLAND - 707945 -	COLW010001	63			•		<u> </u>
2487136	Ground	Church of England - Chaplaincy	1	Yes	Panel to wal	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487137	Ground	Church of England - Vestry	1	Yes	Panel to wal	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487138	Roof	Church of England - Roof	1	Yes	Roof Sheeting	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - CHUF	RCH OF SCOTLAND / OFFICE - 711077 -	COLW010016	0B					
2487131	Ground	Religious Buildings - CSFC Chapel	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487132	Ground	Religious Buildings - St Andrews Chapel	1	Yes	Panels in ceiling void	Amosite	Monitor	7 Low	0 N/A
2487133	Ground	Religious Buildings - Store Vestry	1	Yes	Panels in	Amosite	Monitor	7 Low	0 N/A
2487134	Roof	Religious Buildings - Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487135	External	Religious Buildings - External	1	Yes	Floor		No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - CLAS	SROOM / TOILETS - 708142 - COLW010	0160D						
2488908	Ground	Religious Study Block - Church of England chaplain	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488909	Ground	Religious Study Block - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488910	Loft	Religious Study Block - Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488911	Ground	Religious Study Block - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488912	Ground	Religious Study Block - Smoking Room	1	Yes	high level pipe void		No Action	0 No Risk	0 N/A
2488913	Ground	Religious Study Block - Lobby	1	Yes	panels to fire break in	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488914	Ground	Religious Study Block - Lobby	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488915	Ground	Religious Study Block - Female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488916	Ground	Religious Study Block - Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488917	Ground	Religious Study Block - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488918	Ground	Religious Study Block - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence		Regiona	al Prim	e Contra	act Central			
	astructure anisation			Asbest	osReais	ster		carillion	(amey
2488919	Roof	Religious Study Block - Church of	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
		England Chapel r							
2488920	Ground	Religious Study Block - G01 -	1	Yes	ceiling	Chrysotile	Monitor	6 Low	0 N/A
		Conference Room			panels				
2488921	External	Religious Study Block - external wall	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
					Switchgear	Content			
2488922	External	Religious Study Block - external	1	Yes	Drainage	Crocidolite	Monitor	6 Low	2 No.
		ground			Pipe				
MS COLLING	NOOD - CLUB -	711065 - COLW01000289							
2487173	Ground	Motorcycle Club - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487174	Ground	Motorcycle Club - Locker Rooms	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487175	Ground	Motorcycle Club - Tool Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487176	Ground	Motorcycle Club - Workshop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487177	Ground	Motorcycle Club - Plant Room	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N//
MS COLLING	NOOD - CMU SI	HIPWRIGHTS WORKSHOP - 708057 - C	OLW0100064	2					
2488865	Ground	Workshop - Room 03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488866	Ground	Workshop - Room 04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488867	Ground	Workshop - Room 05	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488868	Ground	Workshop - Room 06	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488869	Ground	Workshop - Room 07	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488870	External	Workshop - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488863	Ground	Workshop - Room 01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488864	Ground	Workshop - Room 02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLING	NOOD - CMU SI	HIPWRIGHTS WORKSHOP ANNEX - 70	8156 - COLW	0100642A					
2487220	External	Store House - External	1	Yes	Walls (DPC)	No Asbestos Detected	No Action	0 No Risk	0 N//
MS COLLING	NOOD - COLLIN	IGWOOD MAINTENANCE UNIT - 70804	9 - COLW010	00614				•	<u> </u>
2489100	Ground	Offices - Tech. Serv. KC Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2 700 100		Chiese Foon. Golv. No Ollice	'	103	Timougnout	1.10 / lobosido Delecida	110 / (011011	O TAO TAISK	0 14/7
2489101	Ground	Offices - TSS office 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2400101		Sinos 135 onios 1	'	103	Timougnout	1.10 / lobosios Deleoida	110 / (0(10))	O NO NISK	0 14/7
2489102	Ground	Offices - Tea bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
_ 100102	3.53.13		·		ougilout		. 10 / 10 11011		0.14//
					1			1	1

		ence		Regiona	al Prime	e Contra	act Central			
1000	Infra Org	astructure anisation				osReais			carillion	amey
	2489103	Ground	Offices - WC 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2489104	Ground	Offices - TSS office 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489105	Ground	Offices - Flagship Tech Serv HQ	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489106	Ground	Offices - Flagship store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489107	Ground	Offices - Flagship store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489108	Ground	Offices - FTL office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489109	Ground	Offices - Conference room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489110	Ground	Offices - TE and FM office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489111	Ground	Offices - Battery room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489112	Ground	Offices - WC 2	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489113	Ground	Offices - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489114	Ground	Offices - Conference room 2 lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489115	Ground	Offices - Conference room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489116	Ground	Offices - Head office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489117	Ground	Offices - Store / workshop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489118	Ground	Offices - Electrical room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489119	Ground	Offices - EWC office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489120	Ground	Offices - URS Defence	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489121	Ground	Offices - Tech Service	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489122	Ground	Offices - Copy room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489123	Ground	Offices - Tech Service finance office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489124	Ground	Offices - WC 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2489125	Ground	Offices - WC 3 rest room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prim	e Contra	act Central	T	*	
	Orga	structure			Asbest	osReais	ster		carilli	onamey
	2489126	Ground	Offices - DOE room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489096	Ground	Offices - Calorifier room	1	Yes	Pipework	Amosite	Control Access	12 Medium	0 N/A
	2489097	Ground	Offices - Calorifier room	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2489098	Ground	Offices - Corridor	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489099	Ground	Offices - North entrance	1	Yes	Over Entrance	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLINGW	OOD - CONTR	ACTORS STORE - 708066 - COLW0100	00631	•	•	•	•		
	2489554	Ground	Engraving Workshop - Main Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489555	Ground	Engraving Workshop - Small Front Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
НМ	COLLINGW	/OOD - CREW	REST FACILITY - 707949 - COLW01000	159	<u>I</u>		1			
$\dagger T$	2487122	Ground	Crew Rest Facility	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLINGW	L /OOD - CYCLE	SHELTERS - 2542633 - COLW01XWP0	<u> </u>   02	<u> </u>	Dallaling				
+		Ground	Bus Shelter / Cycle Shed	1	Yes			No Action	0 No Risk	0 N/A
нмя	COLLINGW	OOD - DAIS - 7	708162 - COLW0100633A			•				
	2489556	Ground	DIAS - Viewing Platform	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489557	Ground	DIAS - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLINGW	/OOD - DISTRII	BUTION SUB STATION DSS B - 254248	6 - COLW01)	(ED002		<u> </u>	<u> </u>	-	
+	2491973	Ground	Distribution Substation DSS B	1	Yes			No Action	0 No Risk	0 N/A
HMS	COLLINGW	I /OOD - DISTRII	<u> </u>	<u> </u>   7 - COLW01	<u> </u> (ED003					
	2491974	Ground	Distribution Substation DSS C	1	Yes			No Action	0 No Risk	0 N/A
HMS			BUTION SUB STATION DSS CHP - 2542	<u> </u> 2564 - COLW						
+		Ground	Distribution Substation DSS C	1	Yes	T	1	No Action	0 No Risk	0 N/A
шмс			BUTION SUB STATION DSS D - 254248	8 - COL W01)				TVO 7 TOLIGITI	O I TO THISK	014/74
IIIVI		Ground	Distribution Substation DSS D	1	Yes			No Action	0 No Risk	0 N/A
HMS	COLLINGW	<u>I</u> /OOD - DISTRII	 BUTION SUB STATION DSS E - 254248	<u> </u> 9 - COLW01X	(ED005			<u> </u>		
		Ground	Distribution Substation DSS E	1	Yes			No Action	0 No Risk	0 N/A
HMS			BUTION SUB STATION DSS F - 254249	 						•
1 1		Ground	Distribution Substation DSS F	1 1	Yes	1	1	No Action	0 No Risk	0 N/A
LINAS			BUTION SUB STATION DSS G - 707959	COLWO1VI				NO ACTION	0 140 17137	0 14/A
ITIVIS		•	Distribution Substation DSS G	- COLVVUIAI		<del>                                     </del>	1	No Action	0 No Risk	0 N/A
11546		Ground		4 001 14/04	Yes			INO ACTION	U INU KISK	U IN/A
HIVIS			BUTION SUB STATION DSS H - 254249	T - COLWU1)		_	1	Tal. A. d	l alu se e	1
	2491978	Ground	Distribution Substation DSS H	<u> </u>	Yes			No Action	0 No Risk	0 N/A

15	ence		Regiona	al Prim	e Contra	act Central	•		A
Org	astructure janisation			<u>Asbest</u>	<u>osReais</u>	ster		———carillion	amey
HMS COLLING	WOOD - DISTR	BIBUTION SUB STATION DSS J - 254249	2 - COLW01X	ED008					
2491979	Ground	Distribution Substation DSS J	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	BIBUTION SUB STATION DSS K - 254252	8 - COLW01X	(ED018					
2491987	Ground	Distribution Substation DSS K	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	IBUTION SUB STATION DSS L - 254249	3 - COLW01X	ED009		•	•	•	•
2491980	Ground	Distribution Substation DSS L	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	RIBUTION SUB STATION DSS M - 254249	94 - COLW01)	KED010			•	·	
2491981	Ground	Distribution Substation DSS M	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	RIBUTION SUB STATION DSS M - 254252	29 - COLW01)	KED019	•	•	•	•	
2491988	Ground	Distribution Substation DSS M	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	BIBUTION SUB STATION DSS N - 708098	- COLW01XE	D011	I	•	•		•
2488663	Ground	Distribution Substation DSS N	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	<u> </u>	LIBUTION SUB STATION DSS P - 254249	<u> </u>  5 - COLW01X	<u> </u> (ED012					
2491982	Ground	Distribution Substation DSS P	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	BIBUTION SUB STATION DSS R - 254250	6 - COLW01X	(ED013		<u> </u>		L L	
2491983	Ground	Distribution Substation DSS R	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	RIBUTION SUB STATION DSS S - 254252	5 - COLW01X	ED014		<u> </u>			
2491984	Ground	Distribution Substation DSS S	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DISTR	RIBUTION SUB STATION DSS T - 254252	6 - COLW01X	ED015		<u> </u>		L L	
2491985	Ground	Distribution Substation DSS T	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - DREA	DNOUGHT FITNESS CENTRE - 1029883	- COLW0100	0775		<u> </u>			
2487445	Ground	Sports Hall	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
					Building				
<u> </u>		TRA BUILDING SHORT TERM ACCOMM	ODATION - 7			_			
2491997	Ground	Electra Block - Calorifier Room	1	Yes	Walls (Lagging	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489355	Ground	Electra Block - NE Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489356	Ground	Electra Block - NE Corridor	1	Yes	Ceiling void	Amosite	Monitor	6 Low	0 N/A
2489357	Ground	Electra Block - G23 Shower	1	Yes	to slab	Presumed Asbestos	Monitor	6 Low	0 N/A
0.400050					running into		N. A.C	o N. Bi I	0.01/4
2489358	Ground	Electra Block - G23 Cleaner Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489359	Ground	Electra Block - NE Corridor	1	Yes	to slab	Presumed Asbestos	Monitor	6 Low	0 N/A
2489360	Ground	Electra Block - G25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489361	Ground	Electra Block - G24 Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	efence	R	egiona	l Prim	e Contra	act Central		carillion 0 No Risk	
	nfrastructure Organisation				osReais			carillion	amey
248936		Electra Block - G24 Cleaners Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	3 Ground	Electra Block - NE Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	4 Ground	Electra Block - G26 Laundry	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	5 Ground	Electra Block - G22 TV Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	6 Ground	Electra Block - Main entrance porch	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	7 Ground	Electra Block - Main entrance porch	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	8 Ground	Electra Block - G21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248936	9 Ground	Electra Block - G27 WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	0 Ground	Electra Block - G28	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	1 Ground	Electra Block - G29	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	2 Ground	Electra Block - G30	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	3 Ground	Electra Block - G33	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	4 Ground	Electra Block - NE Electrical	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	5 Ground	Electra Block - G32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	6 Ground	Electra Block - G31 Linen	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
248937	7 Ground	Electra Block - South Corridor Electrical Cupboard	1	Yes	Electrical Switchgear	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	8 Ground	Electra Block - SE Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248937	9 Ground	Electra Block - G04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248938	0 Ground	Electra Block - G03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248938	1 Ground	Electra Block - G02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248939	5 Ground	Electra Block - G17 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248939	6 Ground	Electra Block - G16 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248939	7 Ground	Electra Block - G14 and Ensuite	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248939	8 Ground	Electra Block - South Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation			Regiona	al Prime	e Contra	act Central		carillion aney  Very Low 0 N/A	
	Infra Orga	structure				osReais			carilliona	mey
		Ground	Electra Block - Calorifier Room	1	Yes	Pipework	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
П	2489400	First	Electra Block - Electrical F22	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489401	First	Electra Block - Electrical F05	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489402	Ground	Electra Block - SW Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489403	Ground	Electra Block - SW Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489404	First	Electra Block - F10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489405	First	Electra Block - F11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489406	First	Electra Block - F12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489407	First	Electra Block - F13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489408	First	Electra Block - F14	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489409	First	Electra Block - F09	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489410	First	Electra Block - F16 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489411	First	Electra Block - F08	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489412	First	Electra Block - F17 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489413	First	Electra Block - F07	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489414	First	Electra Block - F18 Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489415	First	Electra Block - F06	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489416	First	Electra Block - F19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489417	First	Electra Block - F05 (now room F18)	1	Yes	boxing in NE	Presumed Asbestos Content	Monitor	6 Low	0 N/A
$\prod$	2489418	First	Electra Block - F20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489419	Ground	Electra Block - SE Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489420	First	Electra Block - F01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489421	First	Electra Block - F20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	R	egiona	I Prim	e Contra	act Central		carillior 0 No Risk	
	Infra Org	astructure anisation		_	_	osReais			carillior	amey
	2489422	First	Electra Block - F03	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489382	Ground	Electra Block - G01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489383	Ground	Electra Block - G05	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489384	Ground	Electra Block - G06	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489385	Ground	Electra Block - G07	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489386	Ground	Electra Block - G08	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489387	Ground	Electra Block - G09	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489388	Ground	Electra Block - G10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489389	Ground	Electra Block - G11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489390	Ground	Electra Block - G12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489391	Ground	Electra Block - G13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489392	Ground	Electra Block - SW Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489393	Ground	Electra Block - G19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489394	Ground	Electra Block - G18	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489479	Second	Electra Block - S13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489480	Ground	Electra Block - SW Stair	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489481	Second	Electra Block - Electrical S20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489482	Loft	Electra Block - South Loft Space	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489483	Loft	Electra Block - North East Loft Space	1	No			No Action	0 No Risk	0 N/A
H	2489484	Roof Space	Electra Block - 3 storey wing roof space	1	Yes	Flue Pipes	Amosite	Monitor	5 Low	0 N/A
$\prod$	2489485	Roof Space	Electra Block - 3 storey wing roof space	1	Yes	Water Tank Flanges	Chrysotile	Monitor	4 Very Low	0 N/A
	2489486	Roof Space	Electra Block - 3 storey wing roof space	1	Yes	Strip below roof plate	Chrysotile	Monitor	4 Very Low	0 N/A
	2489487	Roof Space	Electra Block - 2 storey wing roof space	1	Yes	Strip below roof plate	Chrysotile	Monitor	4 Very Low	0 N/A
	2489488	Second	Electra Block - 3 storey wing S14	1	Yes	Under	Chrysotile	Remove	5 Low	0 N/A

4	Defe			Regiona	I Prime	e Contra	act Central		carillion	
The state of the s	Infra Orga	astructure anisation				osReais			carillion	amey
	2489489	First	Electra Block - 3 storey wing F14	1	Yes	Under	Chrysotile	Remove	5 Low	0 N/A
	2489490	Ground	Electra Block - 3 storey wing G14	1	Yes	Under	Chrysotile	Remove	5 Low	0 N/A
П	2489491	First	Electra Block - 2 storey wing Room F23	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2489451	First	Electra Block - F41	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489452	Ground	Electra Block - NE Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489453	First	Electra Block - F42	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489454	First	Electra Block - F44	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489455	First	Electra Block - F43 WC & Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489456	First	Electra Block - F42 / F44 Cleaners Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489457	First	Electra Block - F44 / F43 Cleaners Store	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2489458	First	Electra Block - F21 Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489459	Ground	Electra Block - NE Stair	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489460	Ground	Electra Block - SE Stair	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489461	Ground	Electra Block - SE Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489462	Second	Electra Block - S01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489463	Second	Electra Block - S02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489464	Second	Electra Block - S03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489465	Second	Electra Block - S04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489466	Second	Electra Block - S05 (now room S06)	1	Yes	boxing in NE corner	Amosite	Monitor	6 Low	0 N/A
	2489467	Second	Electra Block - S19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489468	Second	Electra Block - S18 Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489469	Second	Electra Block - S17 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489470	Second	Electra Block - S16 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489471	Second	Electra Block - S14 Ensuite	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	R	eaiona	al Prim	e Contra	act Central			A
		astructure anisation		1	Asbest	osReais	ster		carillion	amey
	2489472	Second	Electra Block - S09	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489473	Second	Electra Block - S08	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489474	Second	Electra Block - S07	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489475	Ground	Electra Block - South Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489476	Second	Electra Block - S10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489477	Second	Electra Block - S11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489478	Second	Electra Block - S12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489423	First	Electra Block - F04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489424	Ground	Electra Block - Electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489425	Ground	Electra Block - South Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489426	Ground	Electra Block - SE Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489427	Ground	Electra Block - Loft W Walkway	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489428	Ground	Electra Block - NE Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489429	Ground	Electra Block - NE Walkway	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489430	First	Electra Block - F25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489431	First	Electra Block - F24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489432	First	Electra Block - F23 Store	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2489433	First	Electra Block - F21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489434	First	Electra Block - F22 Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489435	Ground	Electra Block - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489436	First	Electra Block - F26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489437	First	Electra Block - F27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489438	First	Electra Block - F28	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489439	First	Electra Block - F29	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation		F	Regiona	al Prim	e Contra	act Central		carillionamey	
					Ashest	osReais	ter		carillion	amey
	2489440	First	Electra Block - F30	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
H +	2489441	First	Electra Block - F31	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489442	First	Electra Block - F32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489443	First	Electra Block - F33	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel \uparrow \parallel$	2489444	First	Electra Block - F34	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489445	First	Electra Block - F35	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489446	First	Electra Block - F36	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489447	First	Electra Block - F37	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489448	First	Electra Block - F38	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489449	First	Electra Block - F39	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489450	First	Electra Block - F40	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLING	<u>I</u> VOOD - ENDEA	_lI VOUR BUILDING - 745948 - COLW01000	0757						
	2488656	Ground	Endeavour Classroom	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLING	 VOOD - FISHER	L R JR ACCOMMODATION - 708109 - COL	W01000707		Dallaling				
	2488148	Ground	Accommodation Block - Stairs - Ground, 1st & 2nd F	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488149	Ground	Accommodation Block - g/f Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2488150	Ground	Accommodation Block - g/f Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488151	Ground	Accommodation Block - stairwells 1 &	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488152	Ground	Accommodation Block - g/f Flat 30A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488153	Ground	Accommodation Block - g/f Flat 30A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488154	Ground	Accommodation Block - g/f Flat 30A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2488155	Ground	Accommodation Block - g/f Flat 30A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2488156	Ground	Accommodation Block - g/f Flat 30A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488157	Ground	Accommodation Block - g/f Flat 30A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe		F	Regiona	al Prime	e Contra	ct Central		<u>*</u>	
Infra Orga	structure anisation				osReais			carillion	amey
2488158	Ground	Accommodation Block - g/f Flat 30A - Storage Cupbo	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2488159	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488160	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488217	First	Accommodation Block - f/f Flat 33B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488218	First	Accommodation Block - f/f Flat 33B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488219	First	Accommodation Block - f/f Flat 34B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488220	First	Accommodation Block - f/f Flat 34B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488221	First	Accommodation Block - f/f Flat 34B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488222	First	Accommodation Block - f/f Flat 34B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488223	First	Accommodation Block - f/f Flat 34B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488224	First	Accommodation Block - f/f Flat 34B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488225	First	Accommodation Block - f/f Flat 34B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488226	Second	Accommodation Block - s/f Flat 30C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488227	Second	Accommodation Block - s/f Flat 30C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488228	Second	Accommodation Block - s/f Flat 30C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488229	Second	Accommodation Block - s/f Flat 30C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488230	Second	Accommodation Block - s/f Flat 30c - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488231	Second	Accommodation Block - s/f Flat 30C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488232	Second	Accommodation Block - s/f Flat 30C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488233	Second	Accommodation Block - s/f Flat 31C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488234	Second	Accommodation Block - s/f Flat 31C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488235	Second	Accommodation Block - s/f Flat 31C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488236	Second	Accommodation Block - s/f Flat 31C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
1	Infra Orga	structure anisation				osReais			carillion	amey
	2488237	Second	Accommodation Block - s/f Flat 31C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488238	Second	Accommodation Block - s/f Flat 31C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488239	Second	Accommodation Block - s/f Flat 31C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488240	Second	Accommodation Block - s/f Flat 32C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488241	Second	Accommodation Block - s/f Flat 32C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488242	Second	Accommodation Block - s/f Flat 32C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488243	Second	Accommodation Block - s/f Flat 32C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488244	Second	Accommodation Block - s/f Flat 32C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488161	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488162	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488163	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488164	Ground	Accommodation Block - g/f Junior Rates Admin Offic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488165	Ground	Accommodation Block - g/f Flat 32A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488166	Ground	Accommodation Block - g/f Flat 32A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488167	Ground	Accommodation Block - g/f Flat 32A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488168	Ground	Accommodation Block - g/f Flat 32A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488169	Ground	Accommodation Block - g/f Flat 32A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488170	Ground	Accommodation Block - g/f Flat 32A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488171	Ground	Accommodation Block - g/f Flat 32A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488172	Ground	Accommodation Block - Telephone booth	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488173	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488174	Ground	Accommodation Block - g/f 34A Office - Electrical	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488175	Ground	Accommodation Block - g/f 34A Office - Cleaning St	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central	•		
Infra Orga	structure anisation				osReais			carillion	amey
	Ground	Accommodation Block - g/f 34A Office - Ladies Toil	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488177	Ground	Accommodation Block - g/f 34A Office · Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488178	Ground	Accommodation Block - g/f 34A Office - Bedding & F	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488179	Ground	Accommodation Block - g/f 34A Office Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488180	Ground	Accommodation Block - g/f 34A Office - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488181	Ground	Accommodation Block - g/f 34A Office - Electrical	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488182	Ground	Accommodation Block - Block 34 - Bike Shed	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488183	Ground	Accommodation Block - Block 34 - Bin shed	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488184	Ground	Accommodation Block - g/f Flat 33A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488185	Ground	Accommodation Block - g/f Flat 33A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488186	Ground	Accommodation Block - g/f Flat 33A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488187	Ground	Accommodation Block - g/f Flat 33A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488188	Ground	Accommodation Block - g/f Flat 33A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488189	Ground	Accommodation Block - g/f Flat 33A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488190	Ground	Accommodation Block - g/f Flat 33A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488191	First	Accommodation Block - f/f Flat 30B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488192	First	Accommodation Block - f/f Flat 30B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488193	First	Accommodation Block - f/f Flat 30B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488194	First	Accommodation Block - f/f Flat 30B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488195	First	Accommodation Block - f/f Flat 30B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488196	First	Accommodation Block - f/f Flat 30B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488197	First	Accommodation Block - f/f Flat 30B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488198	First	Accommodation Block - f/f Flat 31B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey
	2488199	First	Accommodation Block - f/f Flat 31B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488200	First	Accommodation Block - f/f Flat 31B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488201	First	Accommodation Block - f/f Flat 31B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488202	First	Accommodation Block - f/f Flat 31B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488203	First	Accommodation Block - f/f Flat 31B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488204	First	Accommodation Block - f/f Flat 31B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488205	First	Accommodation Block - f/f Flat 32B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488206	First	Accommodation Block - f/f Flat 32B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488207	First	Accommodation Block - f/f Flat 32B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488208	First	Accommodation Block - f/f Flat 32B Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488209	First	Accommodation Block - f/f Flat 32B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2488210	First	Accommodation Block - f/f Flat 32B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488211	First	Accommodation Block - f/f Flat 32B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488212	First	Accommodation Block - f/f Flat 33B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488213	First	Accommodation Block - f/f Flat 33B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488214	First	Accommodation Block - f/f Flat 33B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488215	First	Accommodation Block - f/f Flat 33B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488216	First	Accommodation Block - f/f Flat 33B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488245	Second	Accommodation Block - s/f Flat 32C - all Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488246	Second	Accommodation Block - s/f Flat 32C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488247	Second	Accommodation Block - s/f Flat 33C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488248	Second	Accommodation Block - s/f Flat 33C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488249	Second	Accommodation Block - s/f Flat 33C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence astructure	F				ct Central		.,,,	
2200	Org	anisation			Asbest	osRegis	ster		<u>Carillion</u>	amey 🦳
	2488250	Second	Accommodation Block - s/f Flat 33C - Drying Room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488251	Second	Accommodation Block - s/f Flat 33C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488252	Second	Accommodation Block - s/f Flat 33C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488253	Second	Accommodation Block - s/f Flat 33C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488254	Second	Accommodation Block - s/f Flat 34C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488255	Second	Accommodation Block - s/f Flat 34C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488256	Second	Accommodation Block - s/f Flat 34C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488257	Second	Accommodation Block - s/f Flat 34C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488258	Second	Accommodation Block - s/f Flat 34C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488259	Second	Accommodation Block - s/f Flat 34C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488260	Second	Accommodation Block - s/f Flat 34C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Н	MS COLLING	VOOD - FISHGU	JARD TRAINING - 708022 - COLW01000	531		•	•	•		•
	2489059	Ground	Fishguard Classroom Block - stores G16	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489060	Ground	Fishguard Classroom Block - workshop G12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489061	Ground	Fishguard Classroom Block - engraving G12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489062	Ground	Fishguard Classroom Block - G11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489063	Ground	Fishguard Classroom Block - G10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489064	Ground	Fishguard Classroom Block - G18	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489065	Ground	Fishguard Classroom Block - south corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489066	Ground	Fishguard Classroom Block - north corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489067	Ground	Fishguard Classroom Block - west corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489068	Ground	Fishguard Classroom Block - east corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489069	Ground	Fishguard Classroom Block - ladies wash room G5	1	Yes	Sadia Water Heater		No Action	0 No Risk	1 No.
$\parallel$	2489070	Ground	Fishguard Classroom Block - mens wash room G6	1	Yes	Toilet Cistern		No Action	0 No Risk	2 No.

		ence		Regiona	al Prim	e Contra	act Central			
The state of the s	Infra Orga	astructure anisation				osRegis			carillion	amey
	2489071	Ground	Fishguard Classroom Block - G4	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489072	Ground	Fishguard Classroom Block - G7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489073	Ground	Fishguard Classroom Block - G3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489074	Ground	Fishguard Classroom Block - G9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489075	Ground	Fishguard Classroom Block - G13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489076	Ground	Fishguard Classroom Block - G14	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489077	Ground	Fishguard Classroom Block - north stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489078	Ground	Fishguard Classroom Block - smoking room G7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489079	First	Fishguard Classroom Block - F6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489080	First	Fishguard Classroom Block - F5A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489081	First	Fishguard Classroom Block - F8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489082	First	Fishguard Classroom Block - F5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489083	First	Fishguard Classroom Block - male wash room	1	Yes	Sadia Water Heater		No Action	0 No Risk	0 N/A
	2489084	First	Fishguard Classroom Block - F2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489085	First	Fishguard Classroom Block - F4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489086	First	Fishguard Classroom Block - F1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489087	First	Fishguard Classroom Block - F10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489088	First	Fishguard Classroom Block - F9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489089	First	Fishguard Classroom Block - F11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489090	First	Fishguard Classroom Block - F12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489091	First	Fishguard Classroom Block - F13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489092	First	Fishguard Classroom Block - F13A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489093	First	Fishguard Classroom Block - welding G19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	F	Regiona	al Prim	e Contra	act Central			
1		astructure anisation				osReais			carillion	amey
	2489094	Loft	Fishguard Classroom Block - Loft	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489095	Loft	Fishguard Classroom Block - Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\dagger \dagger$	2489055	Ground	Fishguard Classroom Block - office G1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
+	2489056	Ground	Fishguard Classroom Block - cleaning cupboards (x2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489057	Ground	Fishguard Classroom Block - office G2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489058	Ground	Fishguard Classroom Block - office G17	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
НМ	COLLING	VOOD - FURNIT	URE STORE - 708024 - COLW01000527	7		L	•	•	1	
	2487212	Ground	Store House - Main Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
T	2487213	Ground	Store House - Storage Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLING	VOOD - GALLE	Y / CYCLE STORE - 708148 - COLW010	0623A			L	L		
	2489534	Ground	Sullage Area - Cycle and Sullage Store	1	Yes	Roof Sheets	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489535	Ground	Sullage Area - MTNL Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLING	VOOD - GAS ME		5				<u> </u>		
	2487252	Ground	Gas Meter House	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLING	VOOD - GAS ME	ETER HOUSE / CYCLE / GRIT / STORE -	- 708103 - CC	LW0100071		1			
	2488580	Ground	Gas Meter House / Cycle / Grit Store - Gas Intake	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488581	External	Gas Meter House / Cycle / Grit Store - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLING	VOOD - GATEH	OUSE PORTAKABIN - 1742079 - COLW	01PB0778			L	L		
	2487448	Ground	Gate House Portacabin	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLING	VOOD - GOULD	VC SR SLA - 745942 - COLW01000750			<u> </u>	L	L		
	2488652	Ground	Gould Accommodation Block	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	COLLING	VOOD - GUARD	ROOM - 708104 - COLW01000718				1		'	
	2488569	Ground	Guard Room - Pass Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\dagger \dagger$	2488570	Ground	Guard Room - Locker Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\dagger \dagger$	2488571	Ground	Guard Room - Mens WC & Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488572	Ground	Guard Room - Womens WC & Showers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence astructure	R				act Central		carillio	
Org	anisation			\sbest	<u>osReais</u>			carillio	namey⊅
2488573	Ground	Guard Room - Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488574	Ground	Guard Room - Control Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488575	Ground	Guard Room - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488576	Ground	Guard Room - Arms Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488577	Ground	Guard Room - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488578	Ground	Guard Room - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488579	External	Guard Room - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
 MS COLLINGV	 VOOD - GWS 30	TEST HUT - 707985 - COLW01000198							
2487162	Ground	Test Mast Hut	1	Yes	Ceiling Sheets	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487163	Roof	Test Mast Hut - Roof	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLINGV	VOOD - GWS25	TEST HUT - 708082 - COLW01000658	L			1			I
2487255	Ground	Test Mast Hut	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLING	VOOD - HEAT T	RANSFER STATION - 708095 - COLW010	000687			•	•		•
2488666	Ground	Heat Transfer Station - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLINGV	VOOD - HOOD E	BUILDING - 1011639 - COLW01000769				l	_ L		l .
2487462	Ground	Medical and Dental Centre Combined	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLINGV	VOOD - HYDRA	ULIC EQUIPMENT TRAINING - 708051 - (	COLW01000	629	<u> </u>	<u> </u>			
2489547	Ground	Hydraulic Workshop - Services Annex	1	Yes	Floor (Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489548	Ground	Hydraulic Workshop - Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489549	Ground	Hydraulic Workshop - Main Equipment Room	1	Yes	Floor (Brown	Chrysotile	Monitor	3 Very Low	0 N/A
2489550	Ground	Hydraulic Workshop - Tornedo Body Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489551	Ground	Hydraulic Workshop - Flight Deck / Classroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489552	First	Hydraulic Workshop - Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489553	Ground	Hydraulic Workshop - Torpedo Mounting Deck	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central	•		
Orga	structure anisation				osReais			carillion	amey
2487906	Ground	Accommodation Block - g/f Flat 24A Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487907	Ground	Accommodation Block - g/f Flat 24A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487908	Ground	Accommodation Block - g/f Flat 24A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487909	Ground	Accommodation Block - g/f Flat 24A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487910	Ground	Accommodation Block - g/f Flat 24A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487911	Ground	Accommodation Block - g/f Flat 24A - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487912	Ground	Accommodation Block - g/f Flat 24A Masin Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487913	Ground	Accommodation Block - g/f Flat 24A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487914	Ground	Accommodation Block - g/f Flat 24A Cleaning Cupboa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487915	Ground	Accommodation Block - g/f Flat 25B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487916	Ground	Accommodation Block - g/f Flat 25B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487917	Ground	Accommodation Block - g/f Flat 25B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487918	Ground	Accommodation Block - g/f Flat 25B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487919	Ground	Accommodation Block - g/f Flat 25B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487920	Ground	Accommodation Block - g/f Flat 25B - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487921	Ground	Accommodation Block - g/f Flat 25B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487922	Ground	Accommodation Block - g/f Flat 25B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487923	Ground	Accommodation Block - g/f Flat 25B - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487924	Ground	Accommodation Block - Blocks 18 & 19 - Ground, 1s	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487925	First	Accommodation Block - f/f Flat 18B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487926	First	Accommodation Block - f/f Flat 18B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487927	First	Accommodation Block - f/f Flat 18B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487928	First	Accommodation Block - f/f Flat 18B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
1	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey
	2487929	First	Accommodation Block - f/f Flat 18B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487930	First	Accommodation Block - f/f Flat 18B - Right Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487931	First	Accommodation Block - f/f Flat 18B - Left Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487932	First	Accommodation Block - f/f Flat 18B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487933	First	Accommodation Block - f/f Flat 18B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487934	First	Accommodation Block - f/f Flat 18B - cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487935	First	Accommodation Block - f/f Flat 19B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487936	First	Accommodation Block - f/f Flat 19B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487937	First	Accommodation Block - f/f Flat 19B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487938	First	Accommodation Block - f/f Flat 19B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487939	First	Accommodation Block - f/f Flat 19B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487940	First	Accommodation Block - f/f Flat 19B - Right Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487941	First	Accommodation Block - f/f Flat 19B - Left Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487942	First	Accommodation Block - f/f Flat 19B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487943	First	Accommodation Block - f/f Flat 19B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487944	First	Accommodation Block - f/f Flat 19B - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487945	First	Accommodation Block - f/f Flat 21B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487946	First	Accommodation Block - f/f Flat 21B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487947	First	Accommodation Block - f/f Flat 21B - Duty Phase II	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487948	First	Accommodation Block - f/f Flat 21B - WO Office Lef	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487949	First	Accommodation Block - f/f Flat 20B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487950	First	Accommodation Block - f/f Flat 20B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487951	Ground	Accommodation Block - flf Flat 20B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		F	Regiona	al Primo	e Contra	act Central		*	
	Infra Orga	astructure anisation				osReais			carillion	amey
	2487952	First	Accommodation Block - f/f Flat 20B -	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш			Electrical Cu							
	2487953	First	Accommodation Block - f/f Flat 20B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487954	First	Accommodation Block - f/f Flat 20B - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2487955	First	Accommodation Block - f/f Flat 20B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2487956	First	Accommodation Block - f/f Flat 20B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487957	First	Accommodation Block - f/f Flat 20b - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487958	First	Accommodation Block - f/f Flat 22B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487959	First	Accommodation Block - f/f Flat 22B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487879	Ground	Accommodation Block - g/f Flat 22A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487880	Ground	Accommodation Block - g/f Flat 22A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487881	Ground	Accommodation Block - g/f Flat 22A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487882	Ground	Accommodation Block - g/f Flat 22A - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487883	Ground	Accommodation Block - g/f Flat 22A - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487884	Ground	Accommodation Block - g/f Flat 22A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487885	Ground	Accommodation Block - g/f Flat 22A - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487886	Ground	Accommodation Block - g/f Flat 23A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487887	Ground	Accommodation Block - g/f Flat 23A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487888	Ground	Accommodation Block - g/f Flat 23A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487889	Ground	Accommodation Block - g/f Flat 23A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487890	Ground	Accommodation Block - g/f Flat 23A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487891	Ground	Accommodation Block - g/f Flat 23A - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487892	Ground	Accommodation Block - g/f Flat 23A - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487893	Ground	Accommodation Block - g/f Flat 23A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2487894	Ground	Accommodation Block - g/f Flat 23A - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487895	Ground	Accommodation Block - g/f Payphone	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487896	Ground	Accommodation Block - g/f Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487897	Ground	Accommodation Block - g/f Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487898	Ground	Accommodation Block - g/f 25A Store Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487899	Ground	Accommodation Block - g/f 25A - Baggage Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487900	Ground	Accommodation Block - g/f Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487901	Ground	Accommodation Block - g/f mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487902	Ground	Accommodation Block - g/f 25A - Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487903	Ground	Accommodation Block - g/f 25A - Study Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487904	Ground	Accommodation Block - g/f Flat 24A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487905	Ground	Accommodation Block - g/f Flat 24A - pipe Riser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487835	Ground	Accommodation Block - g/f Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487836	Ground	Accommodation Block - g/f Flat 19A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487837	Ground	Accommodation Block - g/f Flat 19A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487838	Ground	Accommodation Block - g/f Flat 19A - drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487839	Ground	Accommodation Block - g/f Flat 19A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487840	Ground	Accommodation Block - g/f Flat 19A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487841	Ground	Accommodation Block - g/f Flat 19A - Right Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2487842	Ground	Accommodation Block - g/f Flat 19A - Left Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487843	Ground	Accommodation Block - g/f Flat 19A - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487844	Ground	Accommodation Block - g/f Flat 19A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487845	Ground	Accommodation Block - g/f Flat 19A - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	i i	Regiona	al Prime	e Contra	act Central	•	<u>*</u>	
	Infra Orga	structure anisation				osReais			carillion	ımey
	2487846	Ground	Accommodation Block - g/f Ladies	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
			Toilet							
	2487847	Ground	Accommodation Block - g/f Storage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	0407040	C ray ya d	Room	4	Vaa	There works a vit	No Ashastas Datastad	No Action	O No Diale	O NI/A
	2487848	Ground	Accommodation Block - g/f Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
++	2487849	Ground	Accommodation Block - g/f Staff	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2107010	O. Garra	Kitchen			Imaagnaat				
	2487850	Ground	Accommodation Block - g/f Pipe Riser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487851	Ground	Accommodation Block - g/f Flat 20A - Bathroom,	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487852	Ground	Accommodation Block - g/f Flat 20A - Daily Staff C	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487853	Ground	Accommodation Block - g/f Flat 20A - WOIE Cabin Ri	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487854	Ground	Accommodation Block - g/f Flat 20A - WO Office Lef	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487855	Ground	Accommodation Block - g/f WO Office Right x 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487856	Ground	Accommodation Block - g/f Stationary Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487857	Ground	Accommodation Block - g/f Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487858	Ground	Accommodation Block - g/f Cleaning Store Outside 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487859	Ground	Accommodation Block - g/f Flat 21A - Office Corrid	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487860	Ground	Accommodation Block - g/f Flat 21A - Service Polic	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487861	Ground	Accommodation Block - g/f Flat 21A - Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487862	Ground	Accommodation Block - g/f Flat 21A - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487863	Ground	Accommodation Block - g/f Flat 21A - Main Admin Of	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487864	Ground	Accommodation Block - g/f Flat 21A - Admin Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487865	Ground	Accommodation Block - g/f Flat 21A - Phase II Trai	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487866	Ground	Accommodation Block - g/f Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487867	Ground	Accommodation Block - g/f Electrical Cupboard x 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487868	Ground	Accommodation Block - g/f Flat 21C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central			
Orga	astructure anisation				osReais			carillion	amey
2487869	Ground	Accommodation Block - g/f Flat 21C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487870	Ground	Accommodation Block - g/f Flat 21C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487871	Ground	Accommodation Block - g/f Flat 21C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487872	Ground	Accommodation Block - g/f Flat 21C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487873	Ground	Accommodation Block - g/f Flat 21C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487874	Ground	Accommodation Block - g/f Flat 21C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487875	Ground	Accommodation Block - g/f Flat 21C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487876	Ground	Accommodation Block - g/f Flat 21C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487877	Ground	Accommodation Block - g/f Flat 22A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487878	Ground	Accommodation Block - g/f Flat 22A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487960	First	Accommodation Block - f/f Flat 22B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487961	First	Accommodation Block - f/f Flat 22B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487962	First	Accommodation Block - f/f Flat 22B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487963	First	Accommodation Block - f/f Flat 22B - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487964	First	Accommodation Block - f/f Flat 22B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487965	First	Accommodation Block - f/f Flat 22B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487966	First	Accommodation Block - f/f Flat 22B - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487967	First	Accommodation Block - f/f Flat 23B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487968	First	Accommodation Block - f/f Flat 23B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487969	First	Accommodation Block - f/f Flat 23B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487970	First	Accommodation Block - f/f Flat 23B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487971	First	Accommodation Block - f/f Flat 23B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487972	First	Accommodation Block - f/f Flat 23B - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defence Infrastructure Organisation		F	Regiona	al Prime	e Contra	act Central	•	<u>**</u>	
Infra Orga	structure				osReais			carillior	amey
	First	Accommodation Block - f/f Flat 23B - Main Cabin	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2487974	First	Accommodation Block - f/f Flat 23B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487975	First	Accommodation Block - f/f Flat 23B - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487976	First	Accommodation Block - f/f Flat 24B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487977	First	Accommodation Block - f/f Flat 24B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487978	First	Accommodation Block - f/f Flat 24B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487979	First	Accommodation Block - f/f Flat 24B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487980	First	Accommodation Block - f/f Flat 24B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487981	First	Accommodation Block - f/f Flat 24B - Left and Righ	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487982	First	Accommodation Block - f/f Flat 24B - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487983	First	Accommodation Block - f/f Flat 24B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487984	First	Accommodation Block - f/f Flat 24B - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487985	First	Accommodation Block - f/f Flat 24C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487986	First	Accommodation Block - f/f Flat 24C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487987	First	Accommodation Block - f/f Flat 24C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487988	First	Accommodation Block - f/f Flat 24C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487989	First	Accommodation Block - f/f Flat 24C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487990	First	Accommodation Block - f/f Flat 24C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487991	First	Accommodation Block - f/f Flat 24C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487992	First	Accommodation Block - f/f Flat 24C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487993	First	Accommodation Block - f/f Flat 24C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487994	Second	Accommodation Block - s/f Flat 18C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487995	Second	Accommodation Block - s/f Flat 18C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence		Regiona	al Prime	e Contra	act Central			
Infra Orga	astructure anisation				osReais			carillion	mey
2487996	Second	Accommodation Block - s/f Flat 18C - Drying room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2487997	Second	Accommodation Block - s/f Flat 18C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487998	Second	Accommodation Block - s/f Flat 18C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487999	Second	Accommodation Block - s/f Flat 18C - Right Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488000	Second	Accommodation Block - s/f Flat 18C - Left Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488001	Second	Accommodation Block - s/f Flat 18c - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488002	Second	Accommodation Block - s/f Flat 18C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488003	Second	Accommodation Block - s/f Flat 18c - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488004	Second	Accommodation Block - s/f Flat 19C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488005	Second	Accommodation Block - s/f Flat 19C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488006	Second	Accommodation Block - s/f Flat 19C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488007	Second	Accommodation Block - s/f Flat 19C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488008	Second	Accommodation Block - s/f Flat 19C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488009	Second	Accommodation Block - s/f Flat 19C - Right Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488010	Second	Accommodation Block - s/f Flat 19C - Left Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488011	Second	Accommodation Block - s/f Flat 19C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488012	Second	Accommodation Block - s/f Flat 19C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488013	Second	Accommodation Block - s/f Flat 19C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488014	Second	Accommodation Block - s/f Flat 20C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488015	Second	Accommodation Block - s/f Flat 20C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488016	Second	Accommodation Block - s/f Flat 20C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488017	Second	Accommodation Block - s/f Flat 20C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488018	Second	Accommodation Block - s/f Flat 20C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
	Infra Orga	structure anisation				osReais			carillion	amey
	2488019	Second	Accommodation Block - s/f Flat 20C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488020	Second	Accommodation Block - s/f Flat 20C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488021	Second	Accommodation Block - s/f Flat 20C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488022	Second	Accommodation Block - s/f Flat 20c - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488023	Second	Accommodation Block - s/f Flat 21C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488024	Second	Accommodation Block - s/f Flat 21C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488025	Second	Accommodation Block - s/f Flat 21C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488026	Second	Accommodation Block - s/f Flat 21C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488027	Second	Accommodation Block - s/f Flat 21C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488028	Second	Accommodation Block - s/f Flat 21C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488029	Second	Accommodation Block - s/f Flat 21C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488030	Second	Accommodation Block - s/f Flat 21C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488031	Second	Accommodation Block - s/f Flat 21C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488032	Second	Accommodation Block - s/f Flat 22C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488033	Second	Accommodation Block - s/f Flat 22C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488034	Second	Accommodation Block - s/f Flat 22C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488035	Second	Accommodation Block - s/f Flat 22C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488036	Second	Accommodation Block - s/f Flat 22C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488037	Second	Accommodation Block - s/f Flat 22C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488038	Second	Accommodation Block - s/f Flat 22C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488039	Second	Accommodation Block - s/f Flat 22C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488040	Second	Accommodation Block - s/f Flat 22C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488041	Second	Accommodation Block - s/f Flat 23C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence	F	Regiona	al Prime	e Contra	act Central		*	
	Infrastructur Organisation	re			osReais			carillion	amey
24	88042 Second	Accommodation Block - s/f Flat 23C - Kitchen	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88043 Second	Accommodation Block - s/f Flat 23C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88044 Second	Accommodation Block - s/f Flat 23C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88045 Second	Accommodation Block - s/f Flat 23C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88046 Second	Accommodation Block - s/f Flat 23C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88047 Second	Accommodation Block - s/f Flat 23C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88048 Second	Accommodation Block - s/f Flat 23C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88049 Second	Accommodation Block - s/f Flat 23C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88050 Second	Accommodation Block - s/f Flat 25C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88051 Second	Accommodation Block - s/f Flat 25C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88052 Second	Accommodation Block - s/f Flat 25C Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88053 Second	Accommodation Block - s/f Flat 25C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88054 Second	Accommodation Block - s/f Flat 25C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88055 Second	Accommodation Block - s/f Flat 25C - Left & Right	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88056 Second	Accommodation Block - s/f Flat 25C - Main Cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88057 Second	Accommodation Block - s/f Flat 25C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88058 Second	Accommodation Block - s/f Flat 25C - Cleaning Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS CC	OLLINGWOOD - IN	TAKE SUB STATION ISS A - 2542475 - COLV	/01XED001		1			<u> </u>	
	91972 Ground	Intake Substation ISS A	1	Yes			No Action	0 No Risk	0 N/A
		CKSON BUILDING WO AND SR MESS - 7080	043 - COLW0				_		
	90369 Ground	WO and Sergeants Mess (Catering) - NW Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90370 Ground	WO and Sergeants Mess (Catering) - Foyer Entrance	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90371 Ground	WO and Sergeants Mess (Catering) - Hall Porter	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90372 Ground	WO and Sergeants Mess (Catering) - Phone Booth Are	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence		Regiona	al Prime	e Contra	act Central			A
(T)	Infra Orga	structure anisation				osReais			carillion	amey
	2490373	Ground	WO and Sergeants Mess (Catering) - Store / Rear of	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490374	Ground	WO and Sergeants Mess (Catering) - Cloak Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490375	Ground	WO and Sergeants Mess (Catering) - Store 1	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490376	Ground	WO and Sergeants Mess (Catering) - Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490377	Ground	WO and Sergeants Mess (Catering) - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490378	Ground	WO and Sergeants Mess (Catering) - Ladies WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490379	Ground	WO and Sergeants Mess (Catering) - Store 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490380	Ground	WO and Sergeants Mess (Catering) - Corridor to Sto	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490381	Ground	WO and Sergeants Mess (Catering) - Male Wc	1	Yes	Flue Pipe and Cuff in	Chrysotile	Monitor	4 Very Low	0 N/A
	2490382	Ground	WO and Sergeants Mess (Catering) - disabled toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490383	Ground	WO and Sergeants Mess (Catering) - Store 5	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2490384	Ground	WO and Sergeants Mess (Catering) - Store 5	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490385	Ground	WO and Sergeants Mess (Catering) - Store 5	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2490386	Ground	WO and Sergeants Mess (Catering) - Store 5	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2490387	Ground	WO and Sergeants Mess (Catering) - Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490388	Ground	WO and Sergeants Mess (Catering) - Store 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490389	Ground	WO and Sergeants Mess (Catering) - WC & Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490390	Ground	WO and Sergeants Mess (Catering) - Bar Area	1	Yes	Above bar in the ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2490391	Ground	WO and Sergeants Mess (Catering) - Dance Floor	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490392	Ground	WO and Sergeants Mess (Catering) - Seating Area at	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2490393	Ground	WO and Sergeants Mess (Catering) - Stage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490394	Ground	WO and Sergeants Mess (Catering) - Backstage Store	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490395	Ground	WO and Sergeants Mess (Catering) - Backstage Store	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

Defence Infrastructure	F	Regional Prime Contract Central									
Infra Orga	structure				osReais			carillion	mey		
2490396	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		Backstage									
2490397	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A		
		Backstage									
2490398	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A		
	ļ	Backstage Store		.,					0.21/0		
2490399	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A		
2490400	Ground	Backstage Store WO and Sergeants Mess (Catering) -	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A		
2490400	Ground	Dining Room	'	168	FIOOI	No Aspesios Defected	NO ACTION	U INO KISK	U IN/A		
2490401	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Floor (Green	No Asbestos Detected	No Action	0 No Risk	0 N/A		
2100101	Orouna	Cupboard NE Cor	,	100	Tiles)	The Alabedies Beledies	140 7 (01/01)	o No raisk	014//		
2490402	Ground	WO and Sergeants Mess (Catering) -	1	No	Ceiling Void		No Action	0 No Risk	0 N/A		
		Dining Room									
2490403	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A		
		SW Bar Seating									
2490404	Ground	WO and Sergeants Mess (Catering) -	1	Yes	redundunt		No Action	0 No Risk	0 N/A		
		SW Bar - Cellar			flue within						
2490405	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
0.400.400	0	SW Bar - Dance	4	\/	Theresees	NI- A-bt D-tt	NI- A-C	ON- Pi-li	O N1/A		
2490406	Ground	WO and Sergeants Mess (Catering) - Entrance to Col	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
2490407	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
2490407	Ground	SW Corridor	'	163	Tilloughout	No Aspesios Defected	NO ACTION	O NO KISK	O IN/A		
2490408	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		TV Room 1			l ag a						
2490409	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		TV Room 2 & Sto									
2490410	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		Switch room Adj									
2490411	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Walls	Chrysotile	Monitor	3 Very Low	0 N/A		
0.400.440		Snooker Room			T		NI A C	ON DIL	0.11/4		
2490412	Ground	WO and Sergeants Mess (Catering) - Atrium	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
2490413	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Packing	Chrysotile	Monitor	4 Very Low	0 N/A		
2490413	Ground	Mess Treasurers	ı	168	between rsj	Chrysothe	IVIOTIILOI	4 Very Low	U IN/A		
2490414	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		Mess Treasurers		. •••	l cagcar						
2490415	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		Mess Treasurere									
2490416	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
		Treasurers Plan							<u> </u>		
2490417	Ground	WO and Sergeants Mess (Catering) -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A		
0.400.440		Mess Managers O			1			0 11 51 1	0.11/2		
2490418	Ground	WO and Sergeants Mess (Catering) -	1	Yes	redundant		No Action	0 No Risk	0 N/A		
		Small SW Bar (J			flue pipe						

	Defe			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2490419	Ground	WO and Sergeants Mess (Catering) - Jays Bar Lounge	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490420	Ground	WO and Sergeants Mess (Catering) - SW Male Wc	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490421	Ground	WO and Sergeants Mess (Catering) - SW Womens WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490422	Ground	WO and Sergeants Mess (Catering) - Mountbatten Sui	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490423	Ground	WO and Sergeants Mess (Catering) - Mountbatten Toi	1	Yes	Redundant flue pipe	Chrysotile	Monitor	4 Very Low	0 N/A
	2490424	Ground	WO and Sergeants Mess (Catering) - Mountbatten Cor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490425	Ground	WO and Sergeants Mess (Catering) - Servery	1	Yes	Panels to skylights	Amosite	Monitor	6 Low	0 N/A
Ш	2490426	Ground	WO and Sergeants Mess (Catering) - SW Pantry	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490427	Ground	WO and Sergeants Mess (Catering) - Sink Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490428	Ground	WO and Sergeants Mess (Catering) - West Servery	1	Yes	Panels to skylights	Amosite	Monitor	6 Low	0 N/A
Ш	2490429	Ground	WO and Sergeants Mess (Catering) - West Pantry	1	Yes	High level boxing to	Amosite	Monitor	6 Low	0 N/A
	2490430	Ground	WO and Sergeants Mess (Catering) - West Servery	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490431	Ground	WO and Sergeants Mess (Catering) - Crockery store	1	Yes	Cupboard Ceiling	Amosite	Monitor	6 Low	0 N/A
Ш	2490432	Ground	WO and Sergeants Mess (Catering) - Coffee Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490433	Ground	WO and Sergeants Mess (Catering) - Store B (SE)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490434	Ground	WO and Sergeants Mess (Catering) - Store 14	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490435	Ground	WO and Sergeants Mess (Catering) - Ladies WC 1 (no	1	Yes	Flue Pipe and Cuff in	Presumed Asbestos Content	Encapsulate/Repair	4 Very Low	0 N/A
$\prod$	2490436	Ground	WO and Sergeants Mess (Catering) - Ladies WC 1 (no	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
$\prod$	2490437	Ground	WO and Sergeants Mess (Catering) - Ladies WC 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490438	Ground	WO and Sergeants Mess (Catering) - Ladies Wc 2	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
$\prod$	2490439	Ground	WO and Sergeants Mess (Catering) - Ladies WC 1 (no	1	Yes	Small loose panel on		No Action	0 No Risk	0 N/A
$\prod$	2490440	Ground	WO and Sergeants Mess (Catering) - Ladies WC 1 (no	1	Yes	Bunny Burner		No Action	0 No Risk	0 N/A
$\prod$	2490441	Ground	WO and Sergeants Mess (Catering) - Catering Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
	) Infra Orga	structure anisation			Asbest	osReais	ter		carillion	amey
2	2490442	Ground	WO and Sergeants Mess (Catering) - Catering Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490443	Ground	WO and Sergeants Mess (Catering) - Catering Office	1	Yes	Bunny Burner		No Action	0 No Risk	0 N/A
2	2490444	Ground	WO and Sergeants Mess (Catering) - Catering Office	1	Yes	Flue pipe and ceiling		No Action	0 No Risk	0 N/A
2	2490445	Ground	WO and Sergeants Mess (Catering) - Store 7 (pantry	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490446	Ground	WO and Sergeants Mess (Catering) - SE Corridor	1	No			No Action	0 No Risk	0 N/A
2	2490447	Ground	WO and Sergeants Mess (Catering) - SE Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490448	Ground	WO and Sergeants Mess (Catering) - SE Male Restroo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490449	Ground	WO and Sergeants Mess (Catering) - SE Male WC acce	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490450	Ground	WO and Sergeants Mess (Catering) - SE Male TV Room	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490451	Ground	WO and Sergeants Mess (Catering) - COSHH	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490452	Ground	WO and Sergeants Mess (Catering) - Pastry Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490453	Ground	WO and Sergeants Mess (Catering) - Cold Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490454	Ground	WO and Sergeants Mess (Catering) - Cold Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490455	Ground	WO and Sergeants Mess (Catering) - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490456	Ground	WO and Sergeants Mess (Catering) - Cookery Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490457	Ground	WO and Sergeants Mess (Catering) - Servery (N)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490458	Ground	WO and Sergeants Mess (Catering) - Pantry (N)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490459	Ground	WO and Sergeants Mess (Catering) - Store 13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490460	Ground	WO and Sergeants Mess (Catering) - Male Changing R	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490515	Ground	WO and Sergeants Mess (Catering) - SE Plant room	1	Yes	Pipework	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2490488	Ground	WO and Sergeants Mess (Catering) - Dry Room	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490489	Ground	WO and Sergeants Mess (Catering) - Misc Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490490	Ground	WO and Sergeants Mess (Catering) - TV Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Page:

66 of 420

Run By:

	Defe		F	Regiona	al Primo	e Contra	act Central		*	
	) Infra	structure	•			osReais			carillion	amey
		Ground	WO and Sergeants Mess (Catering) - RA"s Locker Roo	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490492	Ground	WO and Sergeants Mess (Catering) - Snooker Locker	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490493	Ground	WO and Sergeants Mess (Catering) - Snooker Room No	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490494	Ground	WO and Sergeants Mess (Catering) - North Stair	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490495	Ground	WO and Sergeants Mess (Catering) - First Floor Cor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490496	Ground	WO and Sergeants Mess (Catering) - North Showers	1	No	ceiling void vent units		No Action	0 No Risk	0 N/A
	2490497	Ground	WO and Sergeants Mess (Catering) - North Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490498	Ground	WO and Sergeants Mess (Catering) - Snooker Room (s	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
	2490499	Ground	WO and Sergeants Mess (Catering) - Male WC & Showe	1	Yes	Flue Cap Riser	Chrysotile	Monitor	4 Very Low	0 N/A
	2490500	Ground	WO and Sergeants Mess (Catering) - South Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490501	Ground	WO and Sergeants Mess (Catering) - Snooker Room (S	1	No	Riser in SW corner		No Action	0 No Risk	0 N/A
	2490502	Ground	WO and Sergeants Mess (Catering) - Tank Room (2nd	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490503	Ground	WO and Sergeants Mess (Catering) - Central Plant R	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490504	Ground	WO and Sergeants Mess (Catering) - Central Plant R	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490505	Ground	WO and Sergeants Mess (Catering) - Central Plant R	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490506	Ground	WO and Sergeants Mess (Catering) - SW Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490507	Ground	WO and Sergeants Mess (Catering) - External South	1	Yes	Flue Cap	Chrysotile	Monitor	4 Very Low	0 N/A
2	2490508	Ground	WO and Sergeants Mess (Catering) - External South	1	Yes	Flue Cap	Chrysotile	Monitor	4 Very Low	0 N/A
2	2490509	Ground	WO and Sergeants Mess (Catering) - External South	1	Yes	Flue Cap	Chrysotile	Monitor	4 Very Low	0 N/A
	2490510	Ground	WO and Sergeants Mess (Catering) - External South	1	Yes	Flue Cap	Chrysotile	Monitor	4 Very Low	0 N/A
	2490511	Ground	WO and Sergeants Mess (Catering) - North	1	Yes	Flue Cap	Chrysotile	Monitor	4 Very Low	0 N/A
	2490512	Ground	WO and Sergeants Mess (Catering) - Store Room 1	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
2	2490513	Ground	WO and Sergeants Mess (Catering) - Store Room 2	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A

	Defe		F	Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure				osReais			carillion	amey
	2490514	Ground	WO and Sergeants Mess (Catering) - NW Plant room	1	Yes	Pipework	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2490461	Ground	WO and Sergeants Mess (Catering) - Female Changing	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490462	Ground	WO and Sergeants Mess (Catering) - E Rest room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490463	Ground	WO and Sergeants Mess (Catering) - E Servery	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490464	Ground	WO and Sergeants Mess (Catering) - Male WC (E)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490465	Ground	WO and Sergeants Mess (Catering) - Female WC (E)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490466	Ground	WO and Sergeants Mess (Catering) - East Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490467	Ground	WO and Sergeants Mess (Catering) - East Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490468	Ground	WO and Sergeants Mess (Catering) - Electrical Cont	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490469	Ground	WO and Sergeants Mess (Catering) - Dry Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490470	Ground	WO and Sergeants Mess (Catering) - Vegetable Prepa	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490471	Ground	WO and Sergeants Mess (Catering) - East Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490472	Ground	WO and Sergeants Mess (Catering) - Raw Meat Prepar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490473	Ground	WO and Sergeants Mess (Catering) - Deep Freeze	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490474	Ground	WO and Sergeants Mess (Catering) - Chefs Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490475	Ground	WO and Sergeants Mess (Catering) - COSHH Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490476	Ground	WO and Sergeants Mess (Catering) - Dry Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490477	Ground	WO and Sergeants Mess (Catering) - Furniture Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490478	Ground	WO and Sergeants Mess (Catering) - Furniture Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490479	Ground	WO and Sergeants Mess (Catering) - Furniture Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490480	Ground	WO and Sergeants Mess (Catering) - Head Chefs Stor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490481	Ground	WO and Sergeants Mess (Catering) - Lay Apart Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490482	Ground	WO and Sergeants Mess (Catering) - Mess President	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence		Regiona	al Prim	e Contra	act Central			
Org	astructure anisation		4	Asbest	osRegis	ster		carillion	namey
2490483	Ground	WO and Sergeants Mess (Catering) - Warrant Officer	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2490484	Ground	WO and Sergeants Mess (Catering) - Dining Room Sup	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490485	Ground	WO and Sergeants Mess (Catering) - N Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490486	Ground	WO and Sergeants Mess (Catering) - S Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490487	Ground	WO and Sergeants Mess (Catering) - Sky TV Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - JUNIOI	R RATES DINING HALL - 1430656 - COL	W01000781			<u> </u>		<u> </u>	<u> </u>
2487451	Ground	Canteen	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - LEWIN	- 708084 - COLW01000674			<u> </u>				
2491968	Ground	Classroom Block - 078 Classroom (E11A)	1	Yes	Fibreboard Expansion	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - LEWIN	- 708099 - COLW01000676				•	-		•
2491970	Ground	Classroom Block	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - LEWIN	- 711074 - COLW01000675			_!	<u>l</u>	<u> </u>		<u> </u>
2491969	Ground	Classroom Block	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - LEYDE	NE BUILDING - 760097 - COLW0100065	0						
2491965	Ground	Offices	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - LIVERF	POOL ROAD GATEHOUSE - 708060 - CO	LW01000639	)		•	-		
2488871	External	Guard Room - External Front	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488872	Ground	Guard Room - G1 Officer of the Day	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488873	Ground	Guard Room - G2 Security Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488874	Ground	Guard Room - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488875	Ground	Guard Room - G3 Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488876	Ground	Guard Room - G4 Cleaner Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488877	Ground	Guard Room - G5 Male Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488878	Ground	Guard Room - G6 Female Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488879	Ground	Guard Room - G7 Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488880	Ground	Guard Room - G7.1 Kitchen Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence		Regiona	L Prim	e Contra	act Central			
Infra Org	astructure anisation				osReais			carillion	namey
2488881	Ground	Guard Room - Rear Compound	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2488882	Loft	Guard Room - Loft Space	1	No			No Action	0 No Risk	0 N/A
HMS COLLING	NOOD - LOWE I	BUILDING PUMP HOUSE - 1887714 - C	OLW01000776			<u> </u>	<u> </u>	L L	I
2487446	Ground	Plant Building	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	NOOD - MAGAZ	ZINE - 708038 - COLW01000626	!		<u> </u>	<u>I</u>			<u>I</u>
2489536	Ground	Armoury - Store 01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489537	Ground	Armoury - Store 02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489538	Ground	Armoury - External Sump	1	No	Sump		No Action	0 No Risk	0 N/A
HMS COLLING	VOOD - MAIN B	OILER HOUSE - 708050 - COLW01000	612		<u> </u>	<u> </u>		<u>'</u>	I
2491999	External	Plant Building - External	1	Yes	Wall	Chrysotile	Monitor	5 Low	0 N/A
2487217	Ground	Plant Building - Boiler House	1	Yes	Panel to	Chrysotile	Monitor	5 Low	0 N/A
2487218	Roof	Plant Building - Gas Bottle Store	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	 VOOD - MARLB	I BOROUGH COVERED STREET - 708093	3 - COLW01000	690		1		L L	
2488670	Ground	Classroom - Covered walkway	1	No	Floor Ducts		No Action	0 No Risk	0 N/A
2488671	Ground	Classroom - Covered walkway	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488672	Ground	Classroom - Covered walkway	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
2488673	Roof	Classroom - Roof	1	Yes	Roof Covering	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488674	External	Classroom - External	1	Yes	Seals to	Chrysotile	Monitor	4 Very Low	0 N/A
2488675	External	Classroom - External	1	Yes	Plant and Machinery	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2488676	Roof	Classroom - Roof	1	Yes	Fascia	Chrysotile	Monitor	4 Very Low	0 N/A
2488677	External	Classroom - External	1	Yes	Fascia	Chrysotile	Monitor	4 Very Low	0 N/A
2488678	External	Classroom - External	1	Yes	Concrete Canopies	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	VOOD - MARLB	BOROUGH LIBRARY - 708071 - COLWO	1000671		1	<u>I</u>	1	L L	
2488713	Ground	Library - g/f 003	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488714	First	Library - f/f 101 stairs and landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	VOOD - MARLB	BOROUGH TRAINING - 3002154 - COLW	/01000665		<u> </u>	<u> </u>		<u>'</u>	<u> </u>
2487410	First	Marlborough Block - f/f 104 F114	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2487411	First	Marlborough Block - f/f 110 F115	1	Yes	Sink	Chrysotile	Monitor	5 Low	0 N/A
2487412	First	Marlborough Block - f/f 111 lobby & landing	1	Yes	Pipework	Presumed Asbestos Content	Monitor	6 Low	0 N/A

		ence		Regiona	l Prime	e Contra	act Central			
Tanada .	Org	astructure anisation				osRegis			carillion	namey >
	2487413	Ground	Marlborough Block - g/f 020 corridor	1	Yes	Pipework	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2487414	First	Marlborough Block - f/f 111 lobby & landing	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487415	First	Marlborough Block - f/f 111 lobby & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487416	First	Marlborough Block - f/f 100 corridor	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487417	Ground	Marlborough Block - g/f 012 lobby	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487418	Ground	Marlborough Block - g/f 012 lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487419	Ground	Marlborough Block - g/f 020 corridor	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
HN	IS COLLINGV	VOOD - MARLE	BOROUGH TRAINING - 708072 - COLWO	1000670			•	•		<u>'</u>
Ш	2489599	First	Marlborough Block - 118 F14	1	No	Void Within		No Action	0 No Risk	0 N/A
	2489600	Ground	Marlborough Block - 104 G13	1	Yes	Pipe Valves	Chrysotile	Remove	5 Low	0 N/A
	2489601	Ground	Marlborough Block - 014 G13	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	5 Low	0 N/A
	2489602	First	Marlborough Block - 106 stairwell	1	Yes	Windows (Seals)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489603	First	Marlborough Block - 106 stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489604	Ground	Marlborough Block - 003 stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489605	Ground	Marlborough Block - 009	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489606	Ground	Marlborough Block - 014 G13	1	Yes	panels either side	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489607	Ground	Marlborough Block - 014 G13	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489608	Ground	Marlborough Block - 015 G14	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
HN	IS COLLINGV	VOOD - MARLE	BOROUGH TRAINING - 708073 - COLWO	1000669			•	•		•
	2487444	Ground	Classroom - g/f 018 G188	1	Yes	Vent Panel to Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487434	First	Classroom - f/f 110 F192B	1	No	No Access		No Action	0 No Risk	0 N/A
$  \uparrow \uparrow \uparrow  $	2487435	First	Classroom - f/f 123 stairwell	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
	2487436	First	Classroom - f/f 124 corridor	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
Ш	2487437	Ground	Classroom - g/f 123 corridor	1	Yes	High Level Pipework	Presumed Asbestos Content	Monitor	6 Low	0 N/A
$\prod$	2487438	First	Classroom - f/f 118 F197	1	Yes	Panels to wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2487439	Ground	Classroom - g/f 001 G175	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence			Regiona	l Prime	e Contra	ct Central			A
	Infrastruct Organisati	on			_	osReais			carillio	n amey 🥍
248	7440 First		lassroom - f/f 123 stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7441 First	С	lassroom - f/f 124 corridor	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7442 Ground	C	lassroom - g/f 018 G188	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7443 Ground	C	lassroom - g/f 018 G188	1	Yes	Panel above Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COI	LLINGWOOD - I	MARLBOR	OUGH TRAINING - 708074 - COLWO	1000668						l
248	7425 Ground	С	lassroom - g/f 018 G173A	1	No	Lift	1	No Action	0 No Risk	0 N/A
248	7426 Ground	C	lassroom - g/f 019 668/4 lift motor	1	Yes	Electrics	Presumed Asbestos	Monitor	6 Low	0 N/A
248	7427 First		lassroom - g/f & Classroom - f/f lobby	1	No	and Lift Dumb Waiter	Content	No Action	0 No Risk	0 N/A
248	7428 Ground	C	lassroom - g/f 025 lobby	1	Yes	Pipework	Presumed Asbestos Content	Monitor	6 Low	0 N/A
248	7429 First	C	lassroom - f/f 115 landing & stairs	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7430 First	С	lassroom - f/f 115 landing & stairs	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7431 First	С	lassroom - f/f 125 landing	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7432 Ground	C	lassroom - g/f 012 Corridor	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7433 Ground	C	lassroom - g/f 025 lobby	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	7420 First	С	lassroom - f/f 115 stairs & landing	1	Yes	Pipework	Presumed Asbestos Content	Monitor	6 Low	0 N/A
248	7421 First	C	lassroom - f/f 116 F183	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
248	7422 First	С	lassroom - f/f 117 F183 B lift	1	No	Lift		No Action	0 No Risk	0 N/A
248	7423 Ground	С	lassroom - g/f 016 G173	1	No			No Action	0 No Risk	0 N/A
248	7424 Ground	C	lassroom - g/f 017 G173	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
HMS COI	LLINGWOOD - I	MARLBOR	OUGH TRAINING - 708075 - COLWO	1000667		•		•		
249	1349 Ground	С	lassroom Block - 034 K6B	1	Yes	column cladding by	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	1350 Ground	С	lassroom Block - 035 K7	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	1351 Ground	C	lassroom Block - 036 K8	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	1352 Ground	C	lassroom Block - 037 L9	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	1353 Ground	C	lassroom Block - 038 L8	1	Yes	cladding to 2no	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		R	<u>Regiona</u>	al Primo	e Contra	act Central	•		
	Infra Orga	structure anisation				osReais			carillion	amey
2	2491354	Ground	Classroom Block - 039 L6 & L7	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491355	Ground	Classroom Block - 040 L4	1	Yes	cladding to 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491356	Ground	Classroom Block - 041 L5	1	Yes	cladding to 1no column	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491357	Ground	Classroom Block - 042 K6A	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491358	Ground	Classroom Block - 043 L3	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491359	Ground	Classroom Block - 045 L1	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491360	Ground	Classroom Block - 048 L11	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491361	Ground	Classroom Block - 049 L12	1	Yes	cladding to 4no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491362	Ground	Classroom Block - 050 L13	1	Yes	cladding to 1no column	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491363	Ground	Classroom Block - 051 L10A	1	Yes	cladding to 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491364	Ground	Classroom Block - 052 L10B	1	Yes	cladding to columns	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491365	Ground	Classroom Block - 053 L14	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491366	Ground	Classroom Block - 055 L15	1	Yes	cladding to 2no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491367	Ground	Classroom Block - 056 L16	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491368	Ground	Classroom Block - 057 computer room	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491369	Ground	Classroom Block - 058 office	1	Yes	boxing to 2no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491370	Ground	Classroom Block - 059 M5	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491371	Ground	Classroom Block - 062 M4	1	Yes	Beams	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491372	Ground	Classroom Block - 062 M4	1	Yes	Pump 09 Pipe	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491373	Ground	Classroom Block - 062 M4	1	Yes	wall panels behind sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491374	First	Classroom Block - 111 M4	1	Yes	Beams	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491375	First	Classroom Block - 111 M4	1	Yes	Pump 07	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491376	First	Classroom Block - 112 redundant cooling room	1	Yes	Beams	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	R	egiona	al Prime	e Contra	act Central			
R		astructure anisation				osReais			carillion	amey
	2491377	First	Classroom Block - 112 redundant cooling room	1	Yes	Floor (Debris)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491378	Second	Classroom Block - 201 M4 Tank room	1	Yes	Columns	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491379	Ground	Classroom Block - 064 M1	1	Yes	panels to wall at vent	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491380	Ground	Classroom Block - 064 M1	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491381	First	Classroom Block - 118 stairs	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491382	Second	Classroom Block - 201 M4 Tank room	1	Yes	fire break between	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491383	External	Classroom Block - External	1	Yes	External Cladding	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491320	Roof	Classroom Block - Roof	1	No	Radar		No Action	0 No Risk	0 N/A
	2491321	First	Classroom Block - 101 H16	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491322	First	Classroom Block - 103 H15	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491323	First	Classroom Block - 106 H17	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491324	First	Classroom Block - 107 H19	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491325	First	Classroom Block - 108 H18	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491326	First	Classroom Block - 109 corridor	1	Yes	panels to suspended	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491327	First	Classroom Block - 109 corridor	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491328	First	Classroom Block - 110 stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491329	Ground	Classroom Block - 002 H12	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491330	Ground	Classroom Block - 004 H13	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491331	Ground	Classroom Block - 005 H13 cupboard	1	Yes	firebreak at each end of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491332	Ground	Classroom Block - 011 J6	1	Yes	panels to walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491333	Ground	Classroom Block - 012 J5	1	Yes	cladding to colums &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491334	Ground	Classroom Block - 014 H6 & H6A	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491335	Ground	Classroom Block - 015 J4	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491336	Ground	Classroom Block - 016 J3	1	Yes	cladding to 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		F	Regiona	al Prime	e Contra	act Central			
	Orga	structure				osReais			carillion	amey
	2491337	Ground	Classroom Block - 017 J2	1	Yes	cladding to columns	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491338	Ground	Classroom Block - 018 H5	1	Yes	panels to walls,	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491339	Ground	Classroom Block - 019 H4 & H3	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491340	Ground	Classroom Block - 020 J1	1	Yes	cladding to columns	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491341	Ground	Classroom Block - 025 J8, J9 & J10	1	Yes	panels to walls and	No Asbestos Detected	No Action	0 No Risk	0 N/A
1 2	2491342	Ground	Classroom Block - 026 J7	1	Yes	ceiling around vent	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491343	Ground	Classroom Block - 027 K1	1	Yes	cladding to 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491344	Ground	Classroom Block - 028 K2	1	Yes	cladding to 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491345	Ground	Classroom Block - 029 K3	1	Yes	panels to walls & 2no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491346	Ground	Classroom Block - 030 K4	1	Yes	panels to walls &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491347	Ground	Classroom Block - 032 K5	1	Yes	cladding to 4no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491348	Ground	Classroom Block - 033 Lab 1 & 2	1	Yes	cladding by door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491303	First	Classroom Block - 106 H17	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
1	2491304	Ground	Classroom Block - 001 H8	1	Yes	Water Pipes	Chrysotile	Monitor	4 Very Low	0 N/A
2	2491305	Ground	Classroom Block - 009 H6C	1	Yes	High Level Pipes	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2491306	Ground	Classroom Block - 015 J4	1	Yes	Spray	Chrysotile	Monitor	4 Very Low	0 N/A
2	2491307	Ground	Classroom Block - 024 corridor	1	No	Floor Ducts		No Action	0 No Risk	0 N/A
2	2491308	Ground	Classroom Block - 050 L13	1	Yes	High Level Pipes	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2491309	Ground	Classroom Block - 060 M3A	1	No	Throughout		No Action	0 No Risk	0 N/A
2	2491310	Ground	Classroom Block - 062 M4	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491311	Ground	Classroom Block - 062 M4	1	No	Undercroft		No Action	0 No Risk	0 N/A
1	2491312	First	Classroom Block - 111 M4	1	Yes	Small	Chrysotile	Monitor	4 Very Low	0 N/A
	2491313	Second	Classroom Block - 201 M4 Tank room	1	Yes	High Level Pipes	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491314	Ground	Classroom Block - 063 corridors	1	No	Floor Ducts		No Action	0 No Risk	0 N/A
	2491315	First	Classroom Block - 117 corridor	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491316	First	Classroom Block - 118 stairs	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491317	Ground	Classroom Block - 066 Substation M	1	Yes	HV Electrics	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A

	Defence Infrastructure	R	egiona	l Prim	e Contra	act Central		***	
	Organisation		-	Asbest	osReais	ster		carillion	amey 🥍
24913		Classroom Block - 201 M4 Tank room	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
24913	Roof	Classroom Block - Upper Roof	1	No	Throughout		No Action	0 No Risk	0 N/A
HMS COLL	INGWOOD - MARL	BOROUGH TRAINING - 708076 - COLW010	000666		•	•	•		•
24897	742 Ground	Classroom - 101 F124	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24897	743 Ground	Classroom - 112 landing & stairwell	1	Yes	Pipework Above	Chrysotile	Monitor	4 Very Low	0 N/A
24897	744 Ground	Classroom - 014 G129	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
24897	745 Ground	Classroom - 020 corridor	1	Yes	Pipework Above	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24897	746 First	Classroom - 107 F130	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	747 First	Classroom - 112 landing & stairwell	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	748 First	Classroom - 112 landing & stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	749 First	Classroom - 120 landing	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	750 Ground	Classroom - 011 lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	751 Ground	Classroom - 011 lobby	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	752 Ground	Classroom - 014 G129	1	Yes	Panel Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	753 Ground	Classroom - 020 common room	1	Yes	Beading to Windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLL	INGWOOD - MARL	BOROUGH TRAINING - 708078 - COLW010	000664						
24913	384 Ground	Classroom Block - 001 A1 - A3	1	Yes	brake lining to hoist	Presumed Asbestos Content	Monitor	5 Low	0 N/A
24913	385 Ground	Classroom Block - 001 A1 - A3	1	Yes	electrical equipment	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24913	386 Ground	Classroom Block - 001 A1 - A3	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
24913	387 Ground	Classroom Block - 002 A5 high level	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
24913	388 Ground	Classroom Block - 006 A7-A8 high level	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
24913	389 Ground	Classroom Block - 006 A7-A8	1	Yes	electrical equipment	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24913	390 Ground	Classroom Block - 006 A7-A8	1	Yes	high level heater	Presumed Asbestos Content	Monitor	5 Low	0 N/A
24913	391 Ground	Classroom Block - 008 B7	1	Yes	electrical switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24913	392 Ground	Classroom Block - 010 B5 office, corridor & locker	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A

		ence	R	eaiona	al Prime	e Contra	ct Central			lion amey
		astructure anisation				osReais			caril	lion amey 🧪
	2491393	Ground	Classroom Block - 011 B5 workshop	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
	2491394	Ground	Classroom Block - 012 B4 booths	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491395	Ground	Classroom Block - 015 B4 test bays	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
	2491396	Ground	Classroom Block - 016 B4 corridor	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491397	Ground	Classroom Block - 017 B4 workshop	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
	2491398	Ground	Classroom Block - 018 B1 cleaners	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2491399	Ground	Classroom Block - 022 B2 café	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2491400	Ground	Classroom Block - 023 corridor	1	No	Floor Ducts		No Action	0 No Risk	0 N/A
	2491401	Ground	Classroom Block - 027 C5 radar room	1	Yes	panels to high level	Chrysotile	Monitor	4 Very Low	0 N/A
	2491402	Ground	Classroom Block - 028 C6 computer room	1	Yes	panels to high level	Chrysotile	Monitor	4 Very Low	0 N/A
	2491403	Ground	Classroom Block - A01 Duct room above C3	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
	2491404	Ground	Classroom Block - 035 C4.2 radar room	1	Yes	panels to walls	Chrysotile	Monitor	5 Low	0 N/A
	2491405	Ground	Classroom Block - 035 C4.2 radar room	1	Yes	panel above door	Chrysotile	Monitor	5 Low	0 N/A
	2491406	Ground	Classroom Block - 038 corridor	1	Yes	panel above	Chrysotile	Monitor	4 Very Low	0 N/A
	2491407	Ground	Classroom Block - 038 corridor	1	Yes	Door to top of metal	Presumed Asbestos Content	Monitor	5 Low	0 N/A
	2491408	Ground	Classroom Block - 044 C8.3	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491409	Ground	Classroom Block - 046 C10	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2491410	Ground	Classroom Block - 047 corridor	1	Yes	panel above	Chrysotile	Monitor	4 Very Low	0 N/A
HT	2491411	Ground	Classroom Block - 049 D1	1	Yes	Electrical	Chrysotile	Remove	4 Very Low	0 N/A
	2491412	Ground	Classroom Block - 049 D1	1	Yes	Door on mezzanine	Presumed Asbestos Content	Monitor	5 Low	0 N/A
	2491413	Ground	Classroom Block - 051 D4	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491414	Ground	Classroom Block - 052 D3 main room	1	Yes	panels to ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2491415	Ground	Classroom Block - 053 D3 side room	1	Yes	panels to ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2491416	Ground	Classroom Block - 054 D3 store	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
$\sqcap \uparrow$	2491417	Ground	Classroom Block - 055 D8	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491418	Ground	Classroom Block - 055 D8	1	Yes	Pump Machinery	Presumed Asbestos Content	Monitor	5 Low	0 N/A
	2491419	Ground	Classroom Block - 056 D6	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
	2491420	Ground	Classroom Block - 061 E3 training room	1	Yes	panels to high level	Chrysotile	Monitor	5 Low	0 N/A

	Defe		R	egiona	l Prime	<b>Contra</b>	act Central			<u> </u>
	) Infra Orga	structure		- 4	Asbesto	osReais	ster		carillion	amey
2	491421	Ground	Classroom Block - 063 E2B	1	Yes	panels to	Chrysotile	Monitor	5 Low	0 N/A
2	491422	Ground	Classroom Block - 066 E1 plant room	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
2	491423	Ground	Classroom Block - 002 A5	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
2	491424	External	Classroom Block - External	1	Yes	External	Chrysotile	Monitor	3 Very Low	0 N/A
2	491425	Ground	Classroom Block - 002 door surround	1	Yes	dividing wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	491426	Ground	Classroom Block - 029 C3 workshop	1	Yes	beading to glass in fire	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	491427	Ground	Classroom Block - A02 duct room above C3	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	491428	Ground	Classroom Block - 034 C4	1	Yes	beading to glass in fire	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	491429	Ground	Classroom Block - 049 D1	1	Yes	fire break to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	491430	Ground	Classroom Block - 066 E1 plant room	1	Yes	Debris within floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS C	OLLINGW	OOD - MARLB	OROUGH TRAINING - 708079 - COLW010	000662						
2	491134	First	Classroom Block - 101 F50	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491135	First	Classroom Block - 101 F50	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491136	First	Classroom Block - 102 F52	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491137	First	Classroom Block - 102 F52	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491138	First	Classroom Block - 102 F52	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2	491139	First	Classroom Block - 103 F54	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491140	First	Classroom Block - 103 F54	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491141	First	Classroom Block - 103 F54	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2	491142	First	Classroom Block - 104 F56	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491143	First	Classroom Block - 104 F56	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491144	First	Classroom Block - 104 F56	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2	491145	First	Classroom Block - 106 stairwell & landing	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491146	First	Classroom Block - 108 F59A electrical cupboard	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	491147	First	Classroom Block - 110 F61	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	491148	First	Classroom Block - 110 F61	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491149	First	Classroom Block - 110 F61	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2	491150	First	Classroom Block - 111 F62	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491151	First	Classroom Block - 111 F62	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2	491152	First	Classroom Block - 111 F63	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
2	491153	First	Classroom Block - 113 F63	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	Defe		R	egiona	l Prime	<b>Contra</b>	ct Central			
Tana de	Infra Orga	structure anisation				sReais			carillion	amey
		First	Classroom Block - 113 F64	1		Wall Panels		Monitor	4 Very Low	0 N/A
	2491155	First	Classroom Block - 114 585 lift & shaft	1	No	Lift and Shaft		No Action	0 No Risk	0 N/A
	2491156	First	Classroom Block - 118 F55	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491157	First	Classroom Block - 118 F55	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491158	First	Classroom Block - 119 F53	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491159	First	Classroom Block - 119 F53	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491160	First	Classroom Block - 119 F53	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491161	First	Classroom Block - 120 F51	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491162	First	Classroom Block - 120 F51	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491163	First	Classroom Block - 121 F49	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491164	First	Classroom Block - 121 F49	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491165	First	Classroom Block - 121 F49	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491166	Ground	Classroom Block - 002 G38	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491167	Ground	Classroom Block - 003 G39	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491168	Ground	Classroom Block - 003 G39	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491169	Ground	Classroom Block - 003 G39	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491170	Ground	Classroom Block - 004 G41	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491171	Ground	Classroom Block - 004 G41	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491172	Ground	Classroom Block - 004 G41	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491173	Ground	Classroom Block - 005 G43	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491174	Ground	Classroom Block - 005/G43	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491175	Ground	Classroom Block - 005 G43	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491176	Ground	Classroom Block - 006 G45	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491177	Ground	Classroom Block - 006 G45	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491178	Ground	Classroom Block - 006 G45	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491179	Ground	Classroom Block - 007 G44	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491180	Ground	Classroom Block - 007 G44	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491181	Ground	Classroom Block - 007 G44	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
П	2491182	Ground	Classroom Block - 009 G42	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2491183	Ground	Classroom Block - 009 G42	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491184	Ground	Classroom Block - 009 G42	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491185	Ground	Classroom Block - 010 G40	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491186	Ground	Classroom Block - 010 G40	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491187	Ground	Classroom Block - 010 G40	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A

**Page:** 79 of 420

	Defe		R	egiona	l Prime	e Contra	ct Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2491188	Ground	Classroom Block - 012 G49 switch room	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
HT	2491189	Ground	Classroom Block - 013 G50	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
HT	2491190	Ground	Classroom Block - 013 G50	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
HT	2491191	Ground	Classroom Block - 013 G50	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
HT	2491192	Ground	Classroom Block - 014 G51	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
HT	2491193	Ground	Classroom Block - 014 G51	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
HT	2491194	Ground	Classroom Block - 014 G51	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
$\Pi$	2491195	Ground	Classroom Block - 017 G47A	1	No	Lift and		No Action	0 No Risk	0 N/A
$\Pi$	2491196	Ground	Classroom Block - 018 G52	1	No	Lift Gear		No Action	0 No Risk	0 N/A
	2491197	Ground	Classroom Block - 019 G53	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491198	Ground	Classroom Block - 019 G53	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491199	Ground	Classroom Block - 021 G55	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
$\Pi$	2491200	Ground	Classroom Block - 021 G55	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491201	Ground	Classroom Block - 021 G55	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491202	Roof	Classroom Block - Roof Tank Room	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491203	Roof	Classroom Block - Roof Tank Room	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
	2491204	External	Classroom Block - External	1	Yes	Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491205	First	Classroom Block - 105 corridor	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	10 No.
	2491206	First	Classroom Block - 106 stairwell & landing	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491207	First	Classroom Block - 106 stairwell & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491208	First	Classroom Block - 107 WC	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491209	First	Classroom Block - 108 F59A electrical cupboard	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491210	First	Classroom Block - 111 F62	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491211	First	Classroom Block - 112 F64	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491212	First	Classroom Block - 116 F57	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491213	First	Classroom Block - 117 corridor	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	3 No.
	2491214	Ground	Classroom Block - 001 corridor	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	9 No.
	2491215	Ground	Classroom Block - 002 G38	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

Above Door   Abo		fence	F	Regiona	al Prime	<b>Contra</b>	act Central			
2491217   Ground   Classroom Block - 011 C48 WC   1 Yes   Pamels   No Abbestos Detected   No Action   0 No Risk   0	Inf Or	rastructure ganisation							caril	lionamey
2491218   Ground   Classroom Block - 015 G47   Yes   Dehns in No Asbestras Detected   No Action   O No Risk   O			Classroom Block - 008 lobby & link	1		Panels		No Action	0 No Risk	0 N/A
Address   Addr	2491217	Ground	Classroom Block - 011 G48 WC	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
Above Door   Abo	2491218	Ground	Classroom Block - 015 G47	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
Above Dor   Aph   Above Dor   Abov	2491219	Ground	Classroom Block - 017B G46	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
Above	2491220	Ground	Classroom Block - 019 G33	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2491086   First	2491221	Ground	Classroom Block - 022 lobby	1	Yes		No Asbestos Detected	No Action	0 No Risk	2 No.
2491096   First   Classroom Block - 102 F42   1   Yes   Packers to   Chrysotile   Encapsulate/Repair   4   Very Low   0	HMS COLLING	WOOD - MARLE	BOROUGH TRAINING - 708080 - COLWO	1000661					1	I
2491097   First	2491095	First	Classroom Block - 102 F42	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
Switchgear   Content   Classroom Block - 102 F42   1 Yes   Wall Panels   Chrysotile   Monitor   3 /ery Low   0	2491096	First	Classroom Block - 102 F42	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2491098   First   Classroom Block - 102 F42   1   Yes   Wall Panels   Chrysotile   Monitor   3   Yery Low   0	2491097	First	Classroom Block - 102 F42	1	Yes			Monitor	4 Very Low	0 N/A
2491100   First   Classroom Block - 103 F43   1   Yes   Wall Panels   Chrysotile   Monitor   3   Very Low   0	2491098	First	Classroom Block - 102 F42	1	Yes			Monitor	3 Very Low	0 N/A
2491101   First	2491099	First	Classroom Block - 103 F43	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491102         First         Classroom Block - 104 F44         1         Yes         Ceiling         Chrysotile         Monitor         3         Very Low         0           2491103         First         Classroom Block - 104 F44         1         Yes         Wall Panels         Chrysotile         Monitor         3         Very Low         0           2491104         First         Classroom Block - 105 F45         1         Yes         Ceiling         Chrysotile         Monitor         3         Very Low         0           2491105         First         Classroom Block - 105 F45         1         Yes         Wall Panels         Chrysotile         Monitor         3         Very Low         0           2491106         First         Classroom Block - 105 F45         1         Yes         Packers to Chrysotile         Encapsulate/Repair         4         Vory Low         0           2491107         First         Classroom Block - 106 F46         1         Yes         Ceiling         Chrysotile         Monitor         3         Very Low         0           2491109         First         Classroom Block - 106 F46         1         Yes         Packers to Chrysotile         Monitor         3         Very Low         0	2491100	First	Classroom Block - 103 F43	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
2491103         First         Classroom Block · 104 F44         1         Yes         Wall Panels         Chrysotile         Monitor         3         Yery Low         0           2491104         First         Classroom Block · 105 F45         1         Yes         Ceiling         Chrysotile         Monitor         3         Yery Low         0           2491105         First         Classroom Block · 105 F45         1         Yes         Wall Panels         Chrysotile         Monitor         3         Yery Low         0           2491106         First         Classroom Block · 106 F45         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4         Yery Low         0           2491107         First         Classroom Block · 106 F46         1         Yes         Chrysotile         Monitor         3         Yery Low         0           2491108         First         Classroom Block · 106 F46         1         Yes         Packers to         Chrysotile         Monitor         3         Yery Low         0           2491110         First         Classroom Block · 106 F46         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4         Yery Low         0 </td <td>2491101</td> <td>First</td> <td>Classroom Block - 103 F43</td> <td>1</td> <td>Yes</td> <td>Packers to</td> <td>Chrysotile</td> <td>Encapsulate/Repair</td> <td>4 Very Low</td> <td>0 N/A</td>	2491101	First	Classroom Block - 103 F43	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2491104         First         Classroom Block - 105 F45         1         Yes         Ceiling         Chrysotile         Monitor         3         Very Low         0           2491105         First         Classroom Block - 105 F45         1         Yes         Wall Panels         Chrysotile         Monitor         3         Very Low         0           2491106         First         Classroom Block - 105 F45         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4         Very Low         0           2491107         First         Classroom Block - 106 F46         1         Yes         Ceiling         Chrysotile         Monitor         3         Very Low         0           2491109         First         Classroom Block - 106 F46         1         Yes         Packers to         Chrysotile         Monitor         3         Very Low         0           2491110         First         Classroom Block - 108 electrical cupboard         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4         Very Low         0           2491111         First         Classroom Block - 11 stainwell         1         Yes         Ceiling         Chrysotile         Monitor         3	2491102	First	Classroom Block - 104 F44	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491105 First Classroom Block - 105 F45 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491106 First Classroom Block - 105 F45 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491107 First Classroom Block - 106 F46 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491108 First Classroom Block - 106 F46 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491109 First Classroom Block - 106 F46 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491110 First Classroom Block - 108 electrical 1 Yes Panel above door Classroom Block - 108 electrical 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491111 First Classroom Block - 11 stairwell 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491112 Ground Classroom Block - 002 G31A 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491113 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491115 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0	2491103	First	Classroom Block - 104 F44	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
2491106   First   Classroom Block - 105 F45   1   Yes   Packers to   Chrysotile   Encapsulate/Repair   4   Very Low   0	2491104	First	Classroom Block - 105 F45	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491107 First Classroom Block - 106 F46 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491108 First Classroom Block - 106 F46 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0  2491109 First Classroom Block - 106 F46 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0  2491110 First Classroom Block - 108 electrical cupboard 1 Yes Ceiling Chrysotile Monitor 5 Low 0  2491111 First Classroom Block - 11 stairwell 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491112 Ground Classroom Block - 002 G31A 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491113 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0  2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Encapsulate/Repair 4 Very Low 0  2491115 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491116 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0  2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Encapsulate/Repair 4 Very Low 0	2491105	First	Classroom Block - 105 F45	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
2491108         First         Classroom Block - 106 F46         1         Yes         Wall Panels         Chrysotile         Monitor         3 Very Low         0           2491109         First         Classroom Block - 106 F46         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4 Very Low         0           2491110         First         Classroom Block - 108 electrical cupboard         1         Yes         Panel above Amosite door         Monitor         6 Low         0           2491111         First         Classroom Block - 11 stairwell         1         Yes         Ceiling         Chrysotile         Monitor         3 Very Low         0           2491112         Ground         Classroom Block - 002 G31A         1         Yes         Ceiling         Chrysotile         Monitor         3 Very Low         0           2491113         Ground         Classroom Block - 002 G31A         1         Yes         Packers to         Chrysotile         Encapsulate/Repair         4 Very Low         0           2491114         Ground         Classroom Block - 003 G31         1         Yes         Ceiling         Chrysotile         Monitor         3 Very Low         0           2491115         Ground         Classro	2491106	First	Classroom Block - 105 F45	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2491109 First Classroom Block - 106 F46 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0  2491110 First Classroom Block - 108 electrical cupboard 1 Yes Panel above Amosite door 1  2491111 First Classroom Block - 11 stairwell 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491112 Ground Classroom Block - 002 G31A 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491113 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0  2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491115 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491116 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0  2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0  2491117 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0  2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0	2491107	First	Classroom Block - 106 F46	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491110 First Classroom Block - 108 electrical cupboard 1 Yes Panel above door 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491111 First Classroom Block - 002 G31A 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491112 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491115 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Monitor 3 Very Low 0	2491108	First	Classroom Block - 106 F46	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
cupboard door door door door door door door	2491109	First	Classroom Block - 106 F46	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2491112 Ground Classroom Block - 002 G31A 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491113 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491115 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Monitor 3 Very Low 0	2491110	First		1	Yes		Amosite	Monitor	6 Low	0 N/A
2491113 Ground Classroom Block - 002 G31A 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0 2491114 Ground Classroom Block - 003 G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491115 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0	2491111	First	Classroom Block - 11 stairwell	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491114GroundClassroom Block - 003 G311YesCeilingChrysotileMonitor3Very Low02491115GroundClassroom Block - 004 G321YesCeilingChrysotileMonitor3Very Low02491116GroundClassroom Block - 004 G321YesWall PanelsChrysotileMonitor3Very Low02491117GroundClassroom Block - 004 G321YesPackers toChrysotileEncapsulate/Repair4Very Low0	2491112	Ground	Classroom Block - 002 G31A	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491115 Ground Classroom Block - 004 G32 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0 2491116 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0	2491113	Ground	Classroom Block - 002 G31A	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
2491116 Ground Classroom Block - 004 G32 1 Yes Wall Panels Chrysotile Monitor 3 Very Low 0 2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0	2491114	Ground	Classroom Block - 003 G31	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491117 Ground Classroom Block - 004 G32 1 Yes Packers to Chrysotile Encapsulate/Repair 4 Very Low 0	2491115	Ground	Classroom Block - 004 G32	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491116	Ground	Classroom Block - 004 G32	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
2491118 Ground Classroom Block - 005 G33 & G31 1 Yes Ceiling Chrysotile Monitor 3 Very Low 0	2491117	Ground	Classroom Block - 004 G32	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
, , , , , , , , , , , , , , , , , , ,	2491118	Ground	Classroom Block - 005 G33 & G31	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	Defe			Regiona	al Prime	e Contra	ct Central			
		structure anisation			Ashest	osReais	ter		carillion	mey
	2491119	Ground	Classroom Block - 005 G33 & G31	1	Yes	Wall Panels		Monitor	3 Very Low	0 N/A
	2491120	Ground	Classroom Block - 005 G33 & G31	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491121	Ground	Classroom Block - 006 G34	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491122	Ground	Classroom Block - 006 G34	1	Yes	Wall Panels	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2491123	Ground	Classroom Block - 00 G35	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2491124	Ground	Classroom Block - 009 corridor	1	Yes	Panels	Amosite	Monitor	6 Low	0 N/A
	2491125	First	Classroom Block - 101 corridor	1	Yes	Panels above the	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491126	First	Classroom Block - 107 F47	1	Yes	Panels above the	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491127	First	Classroom Block - 209 WC 488	1	Yes	Panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491128	First	Classroom Block - 110 corridor	1	Yes	doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491129	First	Classroom Block - 111 stairwell	1	Yes	doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491130	First	Classroom Block - 111 stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491131	Ground	Classroom Block - 001 corridor	1	Yes	Panels above doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491132	Ground	Classroom Block - 008 WC G36	1	Yes	Panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491133	Ground	Classroom Block - 009 corridor	1	Yes	Panels above doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
HM	IS COLLINGW	VOOD - MARLB	OROUGH TRAINING - 708081 - COLWO	1000660						
	2487256	Ground	Office Block - A2 - sonar 2093 main winch	1	Yes	Pulley Sheave	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2487257	First	Office Block - f/f Room 106 F3	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
П	2487258	First	Office Block - f/f room 108 F6	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487259	First	Office Block - f/f room 109 F7	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487260	First	Office Block - f/f room 112 F8	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487261	First	Office Block - f/f room 113 F9	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487262	First	Office Block - f/f room 114 F10	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487263	First	Office Block - f/f room 117 F15	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487264	First	Office Block - f/f 118 stairwell, landing & link	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487265	First	Office Block - f/f room 120 F16	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487266	First	Office Block - f/f room 122 F17	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487267	First	Office Block - f/f room 123 F18	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487268	First	Office Block - f/f room 124 F19	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487269	First	Office Block - f/f room 125 F20	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A

	Defe		R	egiona	l Prime	e Contra	ct Central			
		structure anisation		-	Asbest	osRegis	ter		carillion	amey
	2487270	First	Office Block - f/f room 126 F21	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487271	First	Office Block - f/f room 124 F19	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487272	First	Office Block - f/f room 127 F22	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487273	First	Office Block - f/f room 127 F22	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487274	First	Office Block - f/f room 128 F23	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487275	First	Office Block - f/f room 128 F23	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487276	First	Office Block - f/f room 129 F24	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
П	2487277	First	Office Block - f/f room 130 F25	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487278	First	Office Block - f/f room 131 F26	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487279	First	Office Block - f/f room 132 F27	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487280	First	Office Block - f/f room 133 F28	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487281	First	Office Block - f/f 133 F28	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487282	First	Office Block - f/f room 134 F29	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487283	First	Office Block - f/f room 135 F30	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487284	First	Office Block - f/f room 136 F31	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487285	First	Office Block - f/f room 136 F31	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487286	First	Office Block - f/f room 139 F32 & F33	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487287	First	Office Block - f/f room 144 F37	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487288	First	Office Block - f/f room 144 F37	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487289	First	Office Block - f/f room 145 F37a	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487290	First	Office Block - f/f room 145 F37a	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487291	First	Office Block - f/f room 146 F38	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487292	First	Office Block - f/f room 146 F38	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
	2487293	First	Office Block - f/f room 147 F39	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
П	2487294	First	Office Block - f/f room 147 F39	1	Yes	Wall Panels	Chrysotile	Monitor	6 Low	0 N/A
П	2487295	First	Office Block - f/f room 148 F40	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
	2487296	First	Office Block - f/f room 149 F41	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
П	2487297	First	Office Block - f/f room 192 F151	1	Yes	Electrical Distribution	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2487298	Ground	Office Block - g/f 001 MACC 05	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2487299	Ground	Office Block - g/f 003 MACC 8	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2487300	Ground	Office Block - g/f 004 Hall	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2487301	Ground	Office Block - g/f 011 MACC 04	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2487338	Ground	Office Block - g/f 026 G13	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
$\prod$	2487339	Ground	Office Block - g/f 029 G16	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A

	Defence Infrastructure Organisation	F	Regiona	al Prime	e Contra	act Central		carillion 0 No Risk		
	Infra Orga	astructure anisation				osReais			carillion	amey
24		Roof	Office Block - roof tank room	1	No	Throughout		No Action	0 No Risk	0 N/A
24	87341	Roof	Office Block - roof tank room	1	Yes	Water Tank Pipework	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24	87342	External	Office Block - external door (adj office G30)	1	Yes	Panel above external	Chrysotile	Monitor	4 Very Low	0 N/A
24	87343	First	Office Block - f/f 101 stairs & landing	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87344	First	Office Block - f/f 101 stairs & landing	1	Yes	panels above doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87345	First	Office Block - f/f 101 stairs & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87346	First	Office Block - f/f 102 room F1	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87347	First	Office Block - f/f 103 room F2	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87348	First	Office Block - f/f 104 corridor	1	Yes	panels above 5no	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87349	First	Office Block - f/f 105 corridor	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87350	First	Office Block - f/f 105 corridor	1	Yes	panels above 8no	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87351	First	Office Block - f/f 107 F5 WC	1	Yes	panels above inner	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87352	First	Office Block - f/f 110 corridor	1	Yes	panels above 8no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	87353	First	Office Block - f/f 118 stairwell, landing & link	1	Yes	panels above 7no	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87354	First	Office Block - f/f 118 stairwell, landing & link	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87355	First	Office Block - f/f 119 F14	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87356	First	Office Block - f/f 121 corridor	1	Yes	panel above 15no doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	87357	First	Office Block - f/f 137 stairwell & landing	1	Yes	panels above 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	87358	First	Office Block - f/f 137 stairwell & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87359	First	Office Block - f/f 138 F34	1	Yes	panels above inner	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87360	First	Office Block - f/f 138 F34	1	Yes	debris within inspection	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87361	First	Office Block - f/f 140 link	1	Yes	panels above 4no	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87362	First	Office Block - f/f 141 corridor	1	Yes	panels above 10no	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87363	First	Office Block - f/f 160 link, stairwell & landing	1	Yes	beading to windows	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	Rea	ional P	rime	Contra	ct Central		•		n amey
	Infra Orga	astructure anisation				sReais				carillio	n amey 🧪
	2487364	First	Office Block - f/f 160 link, stairwell & landing		Yes S		No Asbestos Detected	No Action	0	No Risk	0 N/A
	2487365	First	Office Block - f/f 178 stairwell, landing & link	1		beading to windows	No Asbestos Detected	No Action	0	No Risk	0 N/A
	2487366	First	Office Block - f/f 178 stairwell, landing & link	1 `		fire break above	No Asbestos Detected	No Action	0	No Risk	0 N/A
	2487302	Ground	Office Block - g/f 012 Corridor	1 `	Yes ۱	Wall Panels	Chrysotile	Monitor	6	Low	0 N/A
П	2487303	Ground	Office Block - g/f 013 G1	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487304	Ground	Office Block - g/f 014 G2	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487305	Ground	Office Block - g/f 015 G3	1 `	Yes \	Wall Panels	Chrysotile	Monitor	6	Low	0 N/A
	2487306	Ground	Office Block - g/f 015 G6	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487307	Ground	Office Block - g/f 016 G7	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487308	First	Office Block - f/f room 127 F22	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487309	First	Office Block - f/f room 128 F23	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487310	First	Office Block - f/f room 136 F31	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487311	Ground	Office Block - g/f 025 G12	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487312	Ground	Office Block - g/f 027 G14	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
Ш	2487313	Ground	Office Block - g/f 029 G16	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487314	Ground	Office Block - g/f 032 G19	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487315	Ground	Office Block - g/f 033 G20	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487316	Ground	Office Block - g/f 034 G21	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487317	Ground	Office Block - g/f 035 G22	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487318	Ground	Office Block - g/f 035 G22	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487319	Ground	Office Block - g/f 040 G26	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487320	Ground	Office Block - g/f 041 G28	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487321	Ground	Office Block - g/f 041 G28	1 `	Yes F	Packers to	Chrysotile	Encapsulate/Repair	6	Low	0 N/A
	2487322	Ground	Office Block - g/f 042 G29	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487323	Ground	Office Block - g/f 043 G30	1 `	Yes (	Ceiling	Chrysotile	Monitor	5	Low	0 N/A
	2487324	Ground	Office Block - g/f 095 G147	1	No (	G147S Vault		No Action	0	No Risk	0 N/A
	2487325	Ground	Office Block - g/f 0111 G25a	1 `	Yes f	fire break	Amosite	Monitor	8	Low	0 N/A
	2487326	First	Office Block - f/f stairwell 101	1 `	Yes S	Seals to	Chrysotile	Monitor	6	Low	0 N/A
	2487327	First	Office Block - f/f stairwell & link corridor 118	1		Seals to Windows	Chrysotile	Monitor	6	Low	0 N/A
	2487328	First	Office Block - f/f stairwell & link corridor 137	1		Seals to Windows	Chrysotile	Monitor	6	Low	0 N/A
	2487329	First	Office Block - f/f stairwell & link corridor 160	1		Seals to Windows	Chrysotile	Monitor	6	Low	0 N/A
	2487330	First	Office Block - f/f stairwell & link corridor 178	1 `		Seals to Windows	Chrysotile	Monitor	6	Low	0 N/A

	efence	Re	aiona	L Prime	e Contra	ct Central			
	nfrastructure Organisation		_	_	osReais			carillion	amey
248733		Office Block - g/f link lobby 036	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
248733	32 Ground	Office Block - g/f link lobby 020	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
248733	33 Ground	Office Block - g/f 001 MACC 05	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
248733	34 First	Office Block - f/f stairwell 1113	1	Yes	Seals to	Chrysotile	Monitor	6 Low	0 N/A
248733	35 Ground	Office Block - g/f 001 MACC5	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
248733	6 Ground	Office Block - g/f 015 G3	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
248733	37 Ground	Office Block - g/f 023 G11	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
248739	96 Ground	Office Block - g/f 035 G22	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248739	97 Ground	Office Block - g/f 036 link	1	Yes	panels above 3no	No Asbestos Detected	No Action	0 No Risk	0 N/A
248739	98 Ground	Office Block - g/f 037 G23	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
248739	99 Ground	Office Block - g/f 037 G23	1	Yes	panel to ceiling in	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	00 Ground	Office Block - g/f 044 corridor	1	Yes	panels above 8no	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	Of Ground	Office Block - g/f 045 G27	1	Yes	pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	02 Ground	Office Block - g/f 054 hall, link & lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	03 Ground	Office Block - g/f 073 hall, link & lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	94 Ground	Office Block - g/f 089 hall, link & lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	95 Ground	Office Block - g/f 089 hall, link & lobby	1	Yes	fire break above	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	06 Ground	Office Block - g/f 0105 G153a	1	Yes	fire break above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	7 Ground	Office Block - g/f 0112 G3a	1	Yes	fire break above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	08 Ground	Office Block - g/f 101 stairs 7 landing	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
248740	9 Ground	Office Block - g/f 030 G17	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
248736	First	Office Block - f/f 178 stairwell, landing & link	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248736	68 First	Office Block - f/f 195 stairwell, link & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248736	69 First	Office Block - f/f 213 stairwell & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248737	70 First	Office Block - f/f 1118 F94a	1	Yes	fire break	No Asbestos Detected	No Action	0 No Risk	0 N/A
248737	'1 First	Office Block - f/f 119 F38a	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
100000	Orga	structure anisation			Asbest	osReais	ter		carillion	amey
	2487372	First	Office Block - f/f 21120 F8b	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487373	Ground	Office Block - g/f 001 MACC 05	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487374	Ground	Office Block - g/f 001 MACC 05	1	Yes	panels above 4no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487375	Ground	Office Block - g/f 004 hall	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487376	Ground	Office Block - g/f 007 link	1	Yes	panels above 5no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487377	Ground	Office Block - g/f 008 Mall 10	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487378	Ground	Office Block - g/f 008 Mall 10	1	Yes	Toilet Cistern	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487379	Ground	Office Block - g/f 009 MACC 11	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487380	Ground	Office Block - g/f 010 MACC 12	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487381	Ground	Office Block - g/f 012 Corridor	1	Yes	panels above 10no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487382	Ground	Office Block - g/f 015 G3	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487383	Ground	Office Block - g/f 020 hall link	1	Yes	panels above 5no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487384	Ground	Office Block - g/f 021 G10	1	Yes	panel above inner door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487385	Ground	Office Block - g/f 022 corridor	1	Yes	panels above 15no	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487386	Ground	Office Block - g/f 023 G11	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487387	Ground	Office Block - g/f 024 G11a	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487388	Ground	Office Block - g/f 026 G13	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487389	Ground	Office Block - g/f 027 G14	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487390	Ground	Office Block - g/f 028 G15	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487391	Ground	Office Block - g/f 029 G16	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487392	Ground	Office Block - g/f 029 G16	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487393	Ground	Office Block - g/f 030 G17	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487394	Ground	Office Block - g/f 031 G18	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

Inf	fence rastructure					act Central		-	carillio	namey
2487395	Ground	Office Block - g/f 032 G19		ASDESTO Yes	osReais	No Asbestos Detected	No Action		No Risk	0 N/A
			ı	163	Wall I allels	No Aspesios Delected	NO ACION	J	NO INISK	014/74
S COLLING	WOOD - MARLE	BOROUGH TRAINING - 711071 - COLV	V01000663							
2491222	First	Classroom Block - 102 F65	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/A
2491223	First	Classroom Block - 102 F65	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491224	First	Classroom Block - 103 F66	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/A
2491225	First	Classroom Block - 103 F66	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/A
2491226	First	Classroom Block - 103 F66	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491227	First	Classroom Block - 104 F68	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/A
2491228	First	Classroom Block - 104 F68	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/A
2491229	First	Classroom Block - 104 F68	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491230	First	Classroom Block - 105 F70	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/A
2491231	First	Classroom Block - 105 F70	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/A
2491232	First	Classroom Block - 105 F70	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491233	First	Classroom Block - 106 F72	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N//
2491234	First	Classroom Block - 106 F72	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N//
2491235	First	Classroom Block - 106 F72	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N//
2491236	First	Classroom Block - 107 F71	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/A
2491237	First	Classroom Block - 107 F71	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/A
2491238	First	Classroom Block - 107 F71	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491300	Ground	Classroom Block - 013 G67	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0	No Risk	0 N//
2491301	Ground	Classroom Block - 016 G69	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0	No Risk	0 N/
2491302	Ground	Classroom Block - 019 lobby	1	Yes	Panels Above	No Asbestos Detected	No Action	0	No Risk	0 N/A
2491270	Ground	Classroom Block - 006 G63	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N//
2491271	Ground	Classroom Block - 006 G63	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/A
2491272	Ground	Classroom Block - 007 G62	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N//
2491273	Ground	Classroom Block - 007 G62	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/
2491274	Ground	Classroom Block - 007 G62	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/
2491275	Ground	Classroom Block - 008 G60	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/
2491276	Ground	Classroom Block - 008 G60	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N//
2491277	Ground	Classroom Block - 008 G60	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N//
2491278	Ground	Classroom Block - 009 G58	1	Yes	Ceiling	Chrysotile	Monitor	3	Very Low	0 N/
2491279	Ground	Classroom Block - 009 G58	1	Yes	Wall Panels	Chrysotile	Monitor	4	Very Low	0 N/
2491280	Ground	Classroom Block - 009 G58	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4	Very Low	0 N/

	Defence Infrastructure Organisation 2491281 Ground		R	egiona	al Prime	e Contra	ct Central			
Tando	Infra	astructure anisation				osReais			carillion	mey
			Classroom Block - 013 G67	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491282	Ground	Classroom Block - 013 G67	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491283	Ground	Classroom Block - 015 G69	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491284	Ground	Classroom Block - 015 G69	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491285	Ground	Classroom Block - 015 G69	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491286	Ground	Classroom Block - 017 G70	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491287	Ground	Classroom Block - 018 G71 & G72	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491288	Ground	Classroom Block - 018 G71 & G72	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491289	External	Classroom Block - External door (adj office G62)	1	Yes	Panel Above Door	Chrysotile	Monitor	4 Very Low	0 N/A
	2491290	First	Classroom Block - 101 corridor	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491291	First	Classroom Block - 110 link & landing	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491292	First	Classroom Block - 110 link & landing	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491293	First	Classroom Block - 111 F77 WC	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491294	First	Classroom Block - 112 F77B electric cupboard	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491295	First	Classroom Block - 118 F75	1	Yes	Panels Above Door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491296	First	Classroom Block - 120 landing	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	4 No.
	2491297	Ground	Classroom Block - 001 corridor	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	9 No.
	2491298	Ground	Classroom Block - 005 G61	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491299	Ground	Classroom Block - 010 lobby link	1	Yes	Panels Above	No Asbestos Detected	No Action	0 No Risk	2 No.
П	2491239	First	Classroom Block - 108 F69	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491240	First	Classroom Block - 108 F69	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491241	First	Classroom Block - 108 F69	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491242	First	Classroom Block - 109 F67	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
П	2491243	First	Classroom Block - 109 F67	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
	2491244	First	Classroom Block - 109 F67	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
	2491245	First	Classroom Block - 110 Link & corridor	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491246	First	Classroom Block - 112 F77B electric cupboard	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491247	First	Classroom Block - 114 F79	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	Defence		F	Regiona	al Prime	e Contra	ct Central			
	Infrastru Organis				_	osRegis			carillion	mey
249	1248 Firs		Classroom Block - 114 F79	1	Yes	Wall Panels		Monitor	4 Very Low	0 N/A
249	1249 Firs	t	Classroom Block - 114 F79	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1250 Firs	t	Classroom Block - 115 F80	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1251 Firs	t	Classroom Block - 115 F80	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1252 Firs	t	Classroom Block - 115 F80	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1253 Firs	t	Classroom Block - 118 F75	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1254 Firs	t	Classroom Block - 118 F75	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1255 Firs	t	Classroom Block - 119 F76	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1256 Firs	t	Classroom Block - 119 F76	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1257 Firs	t	Classroom Block - 119 F76	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1258 Gro	und	Classroom Block - 002 G56	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1259 Gro	und	Classroom Block - 002 G56	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1260 Gro	und	Classroom Block - 002 G56	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1261 Gro	und	Classroom Block - 003 G57	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1262 Gro	und	Classroom Block - 003 G57	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1263 Gro	und	Classroom Block - 003 G57	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1264 Gro	und	Classroom Block - 004 G59	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
249	1265 Gro	und	Classroom Block - 004 G59	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1266 Gro	und	Classroom Block - 004 G59	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1267 Gro	und	Classroom Block - 005 G61	1	Yes	Wall Panels	Chrysotile	Monitor	4 Very Low	0 N/A
249	1268 Gro	und	Classroom Block - 005 G61	1	Yes	Packers to	Chrysotile	Encapsulate/Repair	4 Very Low	0 N/A
249	1269 Gro	und	Classroom Block - 006 G63	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
HMS COL	LINGWOOL	D - MERCU	RY TRAINING - 708069 - COLW0100067	'3		<u>.</u>				
249	1967 Gro	und	Classroom Block	1	Yes			No Action	0 No Risk	0 N/A
HMS COL	LINGWOOL	D - MERCU	RY TRAINING - 708070 - COLW0100067	<b>'2</b>				•	•	
249	1966 Gro	und	Classroom Block	1	Yes			No Action	0 No Risk	0 N/A
HMS COL	LINGWOOL	D - MIDDLE	TON HALL - SLA BLOCK - 708110 - CO	LW01000706	3			•	•	
2488	8090 Gro	und	Accommodation Block - g/f Flat 29A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	8091 Gro	und	Accommodation Block - g/f Flat 29A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	8092 Firs	t	Accommodation Block - f/f Flat 26B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	8093 Firs	t	Accommodation Block - f/f Flat 26B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488	8094 Firs	t	Accommodation Block - f/f Flat 26B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
The state of the s	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey
	2488095	First	Accommodation Block - f/f Flat 26B - drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488096	First	Accommodation Block - f/f Flat 26B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488097	First	Accommodation Block - f/f Flat 26B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488098	First	Accommodation Block - f/f Flat 26B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488099	First	Accommodation Block - f/f Flat 27B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488100	First	Accommodation Block - f/f Flat 27B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488101	First	Accommodation Block - f/f Flat 27B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488102	First	Accommodation Block - f/f Flat 27B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488103	First	Accommodation Block - f/f Flat 27B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488104	First	Accommodation Block - f/f Flat 27B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488105	First	Accommodation Block - f/f Flat 27B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488106	First	Accommodation Block - f/f Flat 28B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488134	Second	Accommodation Block - s/f Flat 28C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488135	Second	Accommodation Block - s/f Flat 28C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488136	Second	Accommodation Block - s/f Flat 28C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488137	Second	Accommodation Block - s/f Flat 28C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488138	Second	Accommodation Block - s/f Flat 28c - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488139	Second	Accommodation Block - s/f Flat 28C - all Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488140	Second	Accommodation Block - s/f Flat 28C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488141	Second	Accommodation Block - s/f Flat 29C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488142	Second	Accommodation Block - s/f Flat 29C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488143	Second	Accommodation Block - s/f Flat 29C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488144	Second	Accommodation Block - s/f Flat 29C Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Page:

91 of 420

Run By:

-	Defe			Regiona	al Prime	e Contra	act Central	•		
1	Infra Orga	structure anisation				osReais			carillion	amey
	2488145	Second	Accommodation Block - s/f Flat 29C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488146	Second	Accommodation Block - s/f Flat 29C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488147	Second	Accommodation Block - s/f Flat 29C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488107	First	Accommodation Block - f/f Flat 28B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488108	First	Accommodation Block - f/f Flat 28B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488109	First	Accommodation Block - f/f Flat 28B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488110	First	Accommodation Block - f/f Flat 28B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488111	First	Accommodation Block - f/f Flat 28B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488112	First	Accommodation Block - f/f Flat 28B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488113	First	Accommodation Block - f/f Flat 29B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488114	First	Accommodation Block - f/f Flat 29B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488115	First	Accommodation Block - f/f Flat 29B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488116	First	Accommodation Block - f/f Flat 29B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488117	First	Accommodation Block - f/f Flat 29b - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488118	First	Accommodation Block - f/f Flat 29B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488119	First	Accommodation Block - f/f Flat 29B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488120	Second	Accommodation Block - s/f Flat 26C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488121	Second	Accommodation Block - s/f Flat 26C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488122	Second	Accommodation Block - s/f Flat 26C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488123	Second	Accommodation Block - s/f Flat 26C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488124	Second	Accommodation Block - s/f Flat 26C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488125	Second	Accommodation Block - s/f Flat 26C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488126	Second	Accommodation Block - s/f Flat 26C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central		carillion	
	) Infra Orga	structure			Asbesto	osReais	ter		carillion	amey
24	488127	Second	Accommodation Block - s/f Flat 27C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488128	Second	Accommodation Block - s/f Flat 27C - electrical C	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488129	Second	Accommodation Block - s/f Flat 27C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488130	Second	Accommodation Block - s/f Flat 27C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488131	Second	Accommodation Block - s/f Flat 27C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488132	Second	Accommodation Block - s/f Flat 27C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488133	Second	Accommodation Block - s/f Flat 27C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488059	Ground	Accommodation Block - Bike Shed	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488060	Ground	Accommodation Block - Bin Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488061	Ground	Accommodation Block - g/f 26A - Sitting Room Corri	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488062	Ground	Accommodation Block - g/f 26A - Sitting Room Elec	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488063	Ground	Accommodation Block - g/f 26A - Sitting Room Stora	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188064	Ground	Accommodation Block - g/f 26a - Sitting Room Elect	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488065	Ground	Accommodation Block - g/f 26A - Main Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488066	Ground	Accommodation Block - g/f 26A - Sitting Room Study	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488067	Ground	Accommodation Block - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488068	Ground	Accommodation Block - g/f Flat 27A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488069	Ground	Accommodation Block - g/f Flat 27A Electrical Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488070	Ground	Accommodation Block - g/f Flat 27A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488071	Ground	Accommodation Block - g/f Flat 27A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488072	Ground	Accommodation Block - g/f Flat 27A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488073	Ground	Accommodation Block - g/f Flat 27A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	488074	Ground	Accommodation Block - g/f Flat 27A Storage Cupboar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 93 of 420

	fence rastructure	R	Regiona	al Prim	e Contra	act Central		***	A
Or	ganisation			<b>Asbest</b>	osReais	ster		carillion	amey
2488075	Ground	Accommodation Block - Block 26 & 27 - ground, 1st	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488076	Ground	Accommodation Block - Telephone booth	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488077	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488078	Ground	Accommodation Block - Stairwell g/f Flat 28A - Cor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488079	Ground	Accommodation Block - g/f Flat 28A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488080	Ground	Accommodation Block - g/f Flat 28A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488081	Ground	Accommodation Block - g/f Flat 28A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488082	Ground	Accommodation Block - g/f Flat 28A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488083	Ground	Accommodation Block - g/f Flat 28A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488084	Ground	Accommodation Block - g/f Flat 28A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488085	Ground	Accommodation Block - g/f Flat 29A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488086	Ground	Accommodation Block - g/f Flat 29A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488087	Ground	Accommodation Block - g/f Flat 29A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488088	Ground	Accommodation Block - g/f Flat 29A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488089	Ground	Accommodation Block - g/f Flat 29A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - MILLEI	NIUM HALL - 708055 - COLW01000646				-	-1		•
2487234	Ground	Cinema - Stage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487235	Ground	Cinema - Small Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487236	Ground	Cinema - Chair Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487237	Ground	Cinema - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487238	Ground	Cinema - Auditorium Stage (High Level)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487239	Ground	Cinema - Auditorium	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487240	Ground	Cinema - Central Booth	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487241	Ground	Cinema - Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Infr	ence astructure	F				act Central		carillio	namey
<b>Org</b> 2487242	Ground	Cinema - Lobby to B634	1	ASDESTO Yes	osReais Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
		,	ı		Tilloughout	No Assestos Betesteu	No Action	O NO TAISK	
	•	OLICE DOG HANDLERS QUARTERS - 70	08018 - COL	W01000406			_		
2487183	Ground	Hobbies Club - WC Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2487184	Ground	Hobbies Club - Kitchen	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	5 Low	0 N
2487185	Ground	Hobbies Club - Locker Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487186	Ground	Hobbies Club - Office (classroom 1)	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	5 Low	0 N
2487187	Ground	Hobbies Club - Dog Food Prep Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487188	Ground	Hobbies Club - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487189	Ground	Hobbies Club - Drying Room Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487190	Ground	Hobbies Club - Main Office (entrance area)	1	Yes	Ceiling Under Stairs	Presumed Asbestos Content	Monitor	5 Low	0 N
2487191	First	Hobbies Club - First Floor Office	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	5 Low	0 N
2487192	External	Hobbies Club - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	۸ 0
2487178	Ground	Hobbies Club - Scuba Kit Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487179	Ground	Hobbies Club - Shower Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487180	Ground	Hobbies Club - Ladies WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487181	Loft	Hobbies Club - Loft	1	Yes	Fibreglass Insulation	Presumed Asbestos Content	Monitor	7 Low	0 N
2487182	Ground	Hobbies Club - Gents WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
COLLING	WOOD - MUSEU	IM - 708029 - COLW01000511			1	<u> </u>		l l	
2487203	Roof	Museum - Roof	1	Yes	Roof Sheeting	Crocidolite and Chrysotile	Monitor	6 Low	0 N
2487204	Ground	Museum - Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487205	Ground	Museum - Entrance lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487206	Ground	Museum - South West Exit	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487207	Ground	Museum - Museum	1	Yes	Premier		No Action	0 No Risk	0 N
2487208	Ground	Museum - North Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2487209	Mezzanine	Museum - Valve Room	1	Yes	Door Panels	Chrysotile	Monitor	6 Low	0 N

Page:

95 of 420

Run By:

	Defence Infrastructure Organisation 2487210 Ground		R	egiona	al Prim	e Contra	act Central			
	Org	astructure				osRegis			carillion	n amey 🦳
	-		Museum - North East Exit	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487211	Mezzanine	Museum - Valve Room	1	Yes	Museum		No Action	0 No Risk	0 N/A
н	MS COLLING	VOOD - MUSEL	JM DISPLAY - 708036 - COLW01000478			1-1.1.4	•	•		<u> </u>
	2487193	Ground	Library	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
ни	MS COLLING	VOOD - NAAFI	GARAGES - 708053 - COLW01000653				!	-!		<u></u>
	2487247	Ground	SLA and SFA Garages - Garage 03	1	Yes	Roof and Gulley	Chrysotile	Monitor	6 Low	0 N/A
	2487248	Ground	SLA and SFA Garages - Garage 02	1	Yes	Roof and Gulley	Chrysotile	Monitor	6 Low	0 N/A
	2487249	Ground	SLA and SFA Garages - Garage 01	1	Yes	Roof and Gulley	Chrysotile	Monitor	6 Low	0 N/A
	2487250	Ground	SLA and SFA Garages - Garage 03	1	Yes	Downpipe	Presumed Asbestos Content	Monitor	8 Low	0 N/A
ни	MS COLLING	VOOD - NAAFI	STAFF ACCOMMODATION - 708063 - CO	LW0100063	6		•	•		
	2489558	Ground	MOD Civilian Accomm - External Gas Meter lobby	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489559	Ground	MOD Civilian Accomm - G07 Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489560	Ground	MOD Civilian Accomm - Gas Meter cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489561	Ground	MOD Civilian Accomm - G08 living Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489562	Ground	MOD Civilian Accomm - G06 Kitchenette	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489563	Ground	MOD Civilian Accomm - G05	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489564	Ground	MOD Civilian Accomm - Bathroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489565	Ground	MOD Civilian Accomm - Stairs & Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489566	Ground	MOD Civilian Accomm - West Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489567	Ground	MOD Civilian Accomm - G04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489568	Ground	MOD Civilian Accomm - G03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489569	Ground	MOD Civilian Accomm - Bathroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489570	Ground	MOD Civilian Accomm - G02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489571	Ground	MOD Civilian Accomm - G01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489572	Ground	MOD Civilian Accomm - Linen Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence		Regiona	al Prim	e Contra	act Central			An
	Orga	astructure anisation			<b>Ashest</b>	osReais	ter		carillion	amey
2	2489573	Ground	MOD Civilian Accomm - Electrical cupboard	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489574	Ground	MOD Civilian Accomm - Entrance Porch	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489575	Ground	MOD Civilian Accomm - Boiler Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489576	First	MOD Civilian Accomm - F05	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489577	First	MOD Civilian Accomm - F06	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489578	First	MOD Civilian Accomm - F07	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489579	First	MOD Civilian Accomm - F08	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489580	First	MOD Civilian Accomm - F05-F09 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489581	First	MOD Civilian Accomm - Bathroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489582	First	MOD Civilian Accomm - F09 Utility Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489583	First	MOD Civilian Accomm - Stairs & Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489584	First	MOD Civilian Accomm - F01-F04 Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489585	First	MOD Civilian Accomm - F04	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489586	First	MOD Civilian Accomm - F03	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489587	First	MOD Civilian Accomm - F02	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489588	First	MOD Civilian Accomm - F01	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489589	First	MOD Civilian Accomm - Bathroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489590	First	MOD Civilian Accomm - Linen Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489591	First	MOD Civilian Accomm - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489592	Loft	MOD Civilian Accomm - Loft Space	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS (	COLLINGV	VOOD - NETWO	DRK RAIL DINING HALL - 1742078 - COI	 _W01000779	L		1	1	1	
2	2487449	Ground	Canteen	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS (	COLLINGV	VOOD - NURSE	RY EXTENSION NO 1 - 745949 - COLW	01000758		<u>.</u>	•	-	· · · · ·	•
	2488657	Ground	Wooden Tots Crèche Extension - Wet Area	1	Yes	Sink Unit	No Asbestos Detected	No Action	0 No Risk	0 N/A

Infra	ence astructure	Re				act Central		carillio	namov
Org	anisation	Wooden Tate Online Fritageling			<u>osReais</u>		No Astion	- Carmio	runey
2488658	Ground	Wooden Tots Crèche Extension	1	Yes	Inroughout	No Asbestos Detected	No Action	0 No Risk	0 N
	WOOD - NURSE	RY EXTENSION NO 2 - 745950 - COLW010	00759						
2488659	Ground	Wooden Tots Crèche Extension	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
COLLING	WOOD - OFFICE	ERS MESS - 708040 - COLW01000623			1	<u> </u>	<b>_</b>	<b>I</b>	
2490549	First	Officers Mess (Catering) - Pantry	1	Yes	Panels to Lift Shaft	Presumed Asbestos Content	Monitor	6 Low	0 N
2490550	First	Officers Mess (Catering) - Trafalger Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490551	First	Officers Mess (Catering) - Male Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490552	First	Officers Mess (Catering) - Female Toilet 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490553	First	Officers Mess (Catering) - Conservatory	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490554	First	Officers Mess (Catering) - TV Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490555	First	Officers Mess (Catering) - TV Room 2 & Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490556	First	Officers Mess (Catering) - Mercury Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490557	First	Officers Mess (Catering) - Mercury Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490558	First	Officers Mess (Catering) - Mercury Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490559	First	Officers Mess (Catering) - Lift Machinery Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490560	First	Officers Mess (Catering) - Dining Room Gallery	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490561	First	Officers Mess (Catering) - West Stairs	1	No	Ceiling Void		No Action	0 No Risk	0 N
2490562	First	Officers Mess (Catering) - Buzz Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490563	First	Officers Mess (Catering) - Buzz Bar Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490564	First	Officers Mess (Catering) - Buzz Bar Wine Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490565	First	Officers Mess (Catering) - reception Gallery and S	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490566	First	Officers Mess (Catering) - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490567	First	Officers Mess (Catering) - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
2490568	First	Officers Mess (Catering) - Store 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N

	Defence Infrastructure Organisation		F	Regiona	al Prime	e Contra	act Central	-	carillionamey	
dendo	Infra Orga	astructure anisation				osReais			carillion	amey
	2490569	First	Officers Mess (Catering) - Store 5	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490570	First	Officers Mess (Catering) - Store 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490571	First	Officers Mess (Catering) - Male Locker Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490572	First	Officers Mess (Catering) - Male Changing Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490573	First	Officers Mess (Catering) - Electrical Cupboard 1 (	1	Yes	Ceiling	Amosite	Monitor	6 Low	0 N/A
	2490574	First	Officers Mess (Catering) - East Stairs	1	Yes	Tiles to ceiling and	Amosite	Monitor	6 Low	0 N/A
	2490575	First	Officers Mess (Catering) - Male Changing Room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490576	First	Officers Mess (Catering) - Male Toilet 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490577	First	Officers Mess (Catering) - Male Toilet 3	1	Yes	Ceiling Void	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490578	First	Officers Mess (Catering) - Mercury Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490579	First	Officers Mess (Catering) - Billiards Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490580	First	Officers Mess (Catering) - Electrical Cupboard to	1	Yes	Ceiling Panels		No Action	0 No Risk	0 N/A
	2490581	First	Officers Mess (Catering) - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490582	Ground	Officers Mess (Catering) - Cloakroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490583	Ground	Officers Mess (Catering) - Cloakroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490584	Ground	Officers Mess (Catering) - Male Toilet 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490585	Ground	Officers Mess (Catering) - Male Toilet 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490586	Ground	Officers Mess (Catering) - Corridor 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490587	Ground	Officers Mess (Catering) - Ladies Toilet 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490588	Ground	Officers Mess (Catering) - Hairdresser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2490589	Ground	Officers Mess (Catering) - Main Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490590	Ground	Officers Mess (Catering) - External service Yard	1	Yes	Panel above entrance	Amosite	Monitor	6 Low	0 N/A
	2490591	Ground	Officers Mess (Catering) - External Store 2 - Yard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 99 of 420

	Defence Infrastructure Organisation			Regiona	al Prime	e Contra	act Central		carillionamey	
decido	Infra Orga	structure anisation				osReais			carillion	amey
	2490592	Ground	Officers Mess (Catering) - External Store 3 - Yard	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490593	Ground	Officers Mess (Catering) - Bar WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490594	Ground	Officers Mess (Catering) - Spirit Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490595	Ground	Officers Mess (Catering) - Wine Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490596	Ground	Officers Mess (Catering) - Port Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490597	Ground	Officers Mess (Catering) - Beer Cellar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490598	Ground	Officers Mess (Catering) - Bar Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490599	Ground	Officers Mess (Catering) - Bar Manager Office and	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490600	Ground	Officers Mess (Catering) - Dining Room	1	Yes	Tiles in ceiling void	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2490601	Ground	Officers Mess (Catering) - Collingwood Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490602	Ground	Officers Mess (Catering) - Pantry 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490603	Ground	Officers Mess (Catering) - Vincent Bar Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490634	Ground	Officers Mess (Catering) - Office 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490635	Ground	Officers Mess (Catering) - Silver Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490636	Ground	Officers Mess (Catering) - Restroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490637	Ground	Officers Mess (Catering) - Store 9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490638	Ground	Officers Mess (Catering) - COSHH Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490639	Ground	Officers Mess (Catering) - Reception	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490640	Ground	Officers Mess (Catering) - Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490641	Ground	Officers Mess (Catering) - West Stairs (bar)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490642	Roof	Officers Mess (Catering) - External Roof to Plant	1	Yes	Cladding to Steel Joists		No Action	0 No Risk	7 No.
	2490643	Ground	Officers Mess (Catering) - Mess Sec	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490644	Ground	Officers Mess (Catering) - Mess Managers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 100 of 420

Run By:

CD\\svc\_ProRepuser

	Defence Infrastructure		Regiona	e Contra	act Central		carillion amey  0 No Risk 0 N/A			
		astructure anisation				osRegis			carillion	amey
2.	490645	Ground	Officers Mess (Catering) - Porters Counter	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2.	490646	Ground	Officers Mess (Catering) - Porters Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2.	490647	Ground	Officers Mess (Catering) - Porters Restroom Cupboa	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2.	490648	Ground	Officers Mess (Catering) - Main Electrical Intake	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2.	490649	First	Officers Mess (Catering) - electrical cupboard	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
2.	490650	First	Officers Mess (Catering) - electrical cupboard	1	Yes	Ceiling Panels		No Action	0 No Risk	0 N/A
2.	490651	First	Officers Mess (Catering) - electrical cupboard	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	490652	First	Officers Mess (Catering) - electrical cupboard	1	Yes	Top of electrical	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490653	First	Officers Mess (Catering) - electrical cupboard	1	Yes	Redundant panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490604	Ground	Officers Mess (Catering) - Store 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490605	Ground	Officers Mess (Catering) - Vincent Bar	1	Yes	Redundant ceiling to bar	Chrysotile	Monitor	3 Very Low	0 N/A
2,	490606	Ground	Officers Mess (Catering) - Store 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	490607	Ground	Officers Mess (Catering) - Games Machine	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	490608	Ground	Officers Mess (Catering) - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490609	Ground	Officers Mess (Catering) - Preparation Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	490610	Ground	Officers Mess (Catering) - Lift Shaft	1	Yes	Panels to Lift Shaft	Presumed Asbestos Content	Monitor	6 Low	0 N/A
24	490611	Ground	Officers Mess (Catering) - Servery	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490612	Ground	Officers Mess (Catering) - Mess Trap Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490613	Ground	Officers Mess (Catering) - Store 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	490614	Ground	Officers Mess (Catering) - Kitchen	1	No	Above Fixed		No Action	0 No Risk	0 N/A
2	490615	Ground	Officers Mess (Catering) - Raw Veg Store	1	Yes	Chiller Units (Lining)	Presumed Asbestos Content	Monitor	5 Low	0 N/A
2.	490616	Ground	Officers Mess (Catering) - Office 1	1	No	Above Fixed Ceiling Tiles		No Action	0 No Risk	0 N/A
2	490617	Ground	Officers Mess (Catering) - Pastry Room	1	No	Above Fixed Ceiling Tiles		No Action	0 No Risk	0 N/A
2	490618	Ground	Officers Mess (Catering) - Cold Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence astructure	Re	egiona		carillion				
	Org	anisation			<u> Asbest</u>	<u>osReais</u>			carillion	amey
	2490619	Ground	Officers Mess (Catering) - Cold Room store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490620	Ground	Officers Mess (Catering) - Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490621	Ground	Officers Mess (Catering) - electrical Intake Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490622	Ground	Officers Mess (Catering) - Fore Exit Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490623	Ground	Officers Mess (Catering) - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490624	Ground	Officers Mess (Catering) - Food Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490625	Ground	Officers Mess (Catering) - Electrical Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490626	Ground	Officers Mess (Catering) - Female Cloakroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490627	Ground	Officers Mess (Catering) - Male Cloakroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490628	Ground	Officers Mess (Catering) - North Fire Exit	1	Yes	Panel above door	Amosite	Monitor	6 Low	0 N/A
	2490629	Ground	Officers Mess (Catering) - Store 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490630	Ground	Officers Mess (Catering) - Restroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490631	Ground	Officers Mess (Catering) - Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490632	Ground	Officers Mess (Catering) - Female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490633	Ground	Officers Mess (Catering) - Store 8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Н	MS COLLING	WOOD - PASCO	HALL - SLA BLOCK - 708112 - COLW010	00704	l	1		<u> </u>		
	2487769	First	Accommodation Block - f/f Flat 15B - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487770	First	Accommodation Block - f/f Flat 15B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487771	First	Accommodation Block - f/f Flat 15B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2487772	First	Accommodation Block - f/f Flat 15B - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2487773	First	Accommodation Block - f/f Flat 15B - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2487774	First	Accommodation Block - f/f Flat 15B - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2487775	First	Accommodation Block - f/f Flat 16B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2487776	First	Accommodation Block - f/f Flat 16B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Щ_	Į	1	<u> </u>		<u> </u>		<u> </u>		<u> </u>	

	Defe			Regiona	al Prime	<b>Contra</b>	act Central		carillion	
		structure anisation			Asbesto	osReais	ter		carillion	amey
24	487777	First	Accommodation Block - f/f Flat 16B - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487778	First	Accommodation Block - f/f Flat 16B - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487779	First	Accommodation Block - f/f Flat 16B - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487780	First	Accommodation Block - f/f Flat 16B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487781	First	Accommodation Block - f/f Flat 16B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487782	First	Accommodation Block - f/f Flat 16B - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487783	First	Accommodation Block - f/f Flat 16B - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487784	First	Accommodation Block - f/f Flat 16B - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487785	First	Accommodation Block - f/f Flat 17B - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487786	First	Accommodation Block - f/f Flat 17B - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487787	First	Accommodation Block - f/f Flat 17B - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487788	First	Accommodation Block - f/f Flat 17B - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487789	First	Accommodation Block - f/f Flat 17B - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487790	First	Accommodation Block - f/f Flat 17B - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487791	First	Accommodation Block - f/f Flat 17B - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487792	First	Accommodation Block - f/f Flat 17B - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487793	First	Accommodation Block - f/f Flat 17B - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487794	First	Accommodation Block - f/f Flat 17B - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487795	Second	Accommodation Block - s/f Flat 14C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487796	Second	Accommodation Block - s/f Flat 14C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487825	Second	Accommodation Block - s/f Flat 17C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487826	Second	Accommodation Block - s/f flat 17C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	487827	Second	Accommodation Block - s/f flat 17c - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence		Regiona	al Prime	e Contra	act Central		carillion	
	Infrastructure Organisation			Asbest	osReais	ter		carillion	amey
2487		Accommodation Block - s/f Flat 17C - electrical cu	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	829 Second	Accommodation Block - s/f Flat 17C - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	830 Second	Accommodation Block - s/f Flat 17C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	831 Second	Accommodation Block - s/f Flat 17C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	832 Second	Accommodation Block - s/f Flat 17C - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	833 Second	Accommodation Block - s/f Flat 17c - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	834 Second	Accommodation Block - s/f Flat 17C - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	797 Second	Accommodation Block - s/f Flat 14C - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	798 Second	Accommodation Block - s/f Flat 14C - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	799 Second	Accommodation Block - s/f Flat 14C - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	800 Second	Accommodation Block - s/f Flat 14C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	801 Second	Accommodation Block - s/f Flat 14C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	802 Second	Accommodation Block - s/f Flat 14C - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	803 Second	Accommodation Block - s/f Flat 14C - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	804 Second	Accommodation Block - s/f Flat 14C - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	805 Second	Accommodation Block - s/f Flat 15C - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	806 Second	Accommodation Block - s/f Flat 15c - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	807 Second	Accommodation Block - s/f Flat 15C - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	808 Second	Accommodation Block - s/f Flat 15C - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	809 Second	Accommodation Block - s/f Flat 15C - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	810 Second	Accommodation Block - s/f Flat 15C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	811 Second	Accommodation Block - s/f Flat 15C - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487	812 Second	Accommodation Block - s/f Flat 15C - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation	ence		Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure	•			osReais			carillion	amey
	2487813	Second	Accommodation Block - s/f Flat 15C -	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
			storage cupbo							
	2487814	Second	Accommodation Block - s/f Flat 15c - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487815	Second	Accommodation Block - s/f Flat 16c - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487816	Second	Accommodation Block - s/f Flat 16C - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487817	Second	Accommodation Block - s/f Flat 16C - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487818	Second	Accommodation Block - s/f Flat 16c - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
7	2487819	Second	Accommodation Block - s/f Flat 16c - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487820	Second	Accommodation Block - s/f Flat 16C - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
:	2487821	Second	Accommodation Block - s/f Flat 16c - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
:	2487822	Second	Accommodation Block - s/f Flat 16c - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
;	2487823	Second	Accommodation Block - s/f Flat 16c - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487824	Second	Accommodation Block - s/f Flat 16C - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487767	First	Accommodation Block - f/f Flat 15B - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487768	First	Accommodation Block - f/f Flat 15B - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487722	Ground	Accommodation Block - g/f storage cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487723	Ground	Accommodation Block - g/f cleaning cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487724	Ground	Accommodation Block - Stairwell 1 & 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487725	Ground	Accommodation Block - g/f Flat 15A - main sitting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487726	Ground	Accommodation Block - g/f mens toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487727	Ground	Accommodation Block - g/f ladies toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487728	Ground	Accommodation Block - g/f study room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487729	Ground	Accommodation Block - g/f kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487730	Ground	Accommodation Block - g/f cleaning cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
1	Infra Orga	structure anisation				osReais			carillion	amey
	2487731	Loft	Accommodation Block - loft space	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487732	Ground	Accommodation Block - g/f cleaners cupboard x 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487733	Ground to Second	Accommodation Block - stairwell	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487734	Ground to Second	Accommodation Block - stairwells	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487735	Ground	Accommodation Block - g/f Flat 16A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487736	Ground	Accommodation Block - g/f Flat 16A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487737	Ground	Accommodation Block - g/f Flat 16A - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487738	Ground	Accommodation Block - g/f Flat 16A - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487739	Ground	Accommodation Block - g/f Flat 16A - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487740	Ground	Accommodation Block - g/f Flat 16A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487741	Ground	Accommodation Block - g/f Flat 16A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487742	Ground	Accommodation Block - g/f Flat 16A - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487743	Ground	Accommodation Block - g/f Flat 16A - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487744	Ground	Accommodation Block - g/f Flat 16A - cleaning cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487745	Ground	Accommodation Block - g/f Flat 17A - corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487746	Ground	Accommodation Block - g/f Flat 17A - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487747	Ground	Accommodation Block - g/f Flat 17a - drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487748	Ground	Accommodation Block - g/f Flat 17A - electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487749	Ground	Accommodation Block - g/f Flat 17A - bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487750	Ground	Accommodation Block - g/f Flat 17A - left cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487751	Ground	Accommodation Block - g/f Flat 17A - right cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487752	Ground	Accommodation Block - g/f Flat 17A - main cabin	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487753	Ground	Accommodation Block - g/f Flat 17A - storage cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

arillion amey
isk 0 N/
isk 0 N/
0 N/
isk 0 N/
isk 0 N/
cisk 0 N/
isk 0 N/
isk 0 N/
cisk 0 N
isk 0 N
isk 0 N
isk 0 N/

		ence								
10000	Infra Orga	astructure anisation				osReais			carillion	amey
	2488680	Ground	Offices - g/f room 34	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488681	Ground	Offices - g/f room 35	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488682	Ground	Offices - g/f room 36	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488683	Ground	Offices - g/f room 32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488684	Ground	Offices - g/f room 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488685	Ground	Offices - Porch	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488686	Ground	Offices - g/f room 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488687	Ground	Offices - g/f room 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488688	Ground	Offices - g/f room 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488689	Ground	Offices - g/f room 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488690	Ground	Offices - g/f room 8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488691	Ground	Offices - g/f room 9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488692	Ground	Offices - g/f room 10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488693	Ground	Offices - g/f room 11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488694	Ground	Offices - g/f room 12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488695	Ground	Offices - g/f room 13 ladies wc	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488696	Ground	Offices - g/f room 14 cleaners cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488697	Ground	Offices - g/f room 18 disabled toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488698	Ground	Offices - g/f room 19 gents wc	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2488699	Ground	Offices - g/f room 23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488700	Ground	Offices - g/f room 24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488701	Ground	Offices - g/f room 25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2488702	Ground	Offices - g/f room 26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Infr	ence astructure	R	Corillian	carillionamey						
Org	anisation	Asbestos Register  Asbestos Register					The same	Carillion	carmionamey	
2488703	Ground	Offices - g/f room 27 wash up	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488704	Ground	Offices - g/f room 28	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488705	Ground	Offices - g/f room 29	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488706	Ground	Offices - g/f room 30	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488707	Ground	Offices - g/f room 31	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488708	Ground	Offices - g/f corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2488709	Loft	Offices - Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
IS COLLING	<u> </u> WOOD - PLANT									
2488954	Ground	Plant Building / Car Club - EEM Switch Room	1	Yes	Three Pipe System		No Action	0 No Risk	0 N//	
2488955	Ground	Plant Building / Car Club - EEM Switch Room	1	Yes	Floor		No Action	0 No Risk	0 N//	
2488956	Ground	Plant Building / Car Club - EEM Switch Room	1	Yes	Electric Cupboard		No Action	0 No Risk	0 N/.	
2488957	Ground	Plant Building / Car Club - EEM Switch Room	1	Yes	Floor Void		No Action	0 No Risk	0 N/	
2488958	Ground	Plant Building / Car Club - Club Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/	
2488959	Ground	Plant Building / Car Club - Club Garage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/	
2488952	Ground	Plant Building / Car Club - Main Room	1	Yes	Floor (Debris)	No Asbestos Detected	No Action	0 No Risk	0 N/	
2488953	Ground	Plant Building / Car Club - EEM Switch Room	1	Yes	Pipes and Wall	No Asbestos Detected	No Action	0 No Risk	0 N//	
IS COLLING	WOOD - PORTA	KABIN MUSEUM DISPLAY - 708136 - CC	LW0100511	A	111000	1		I		
2487202	Ground	Museum Portacabin	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/	
IS COLLING	NOOD - PORTA	KABIN REST ROOM - 708153 - COLW01	00646A		9	1	<u> </u>			
2487243	Ground	Crew Rest Facility - Internal	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/	
2487244	External	Crew Rest Facility - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/.	
IS COLLING	NOOD - PROMS	STORE - 708037 - COLW01000532				!	1	<del>- !</del>		
2488883	Ground	Store House - Store	1	Yes	Floor (Red / Yellow Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/	
2488884	External	Store House - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/	

Infr	ence astructure	Re	_	_		act Central		carillio	n amou
Org	anisation		<i>_</i>		<u>osReais</u>			Carino	nαmey /
2487464	Ground	Prowse Accommodation	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
		NDS ACCOMMODATION BLOCK - 708019	- COLW01						
2488960	Ground	Redlands Accommodation - Understairs cupboard	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
2488961	Ground	Redlands Accommodation - Understairs cupboard	1	Yes	electrical switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488962	Ground	Redlands Accommodation - corridor	1	Yes	ceiling	Chrysotile	Monitor	5 Low	0 N/A
2488963	Ground	Redlands Accommodation - lobby	1	Yes	fascia	Chrysotile	Monitor	6 Low	0 N/A
2488964	External	Redlands Accommodation - External	1	Yes	fascia panel to entrance	Chrysotile	Monitor	4 Very Low	0 N/A
2488965	Roof	Redlands Accommodation - Roof	1	Yes	Undercloaki ng	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488966	Roof	Redlands Accommodation - Roof	1	Yes	Roof Tiles	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488967	Roof Space	Redlands Accommodation - roof space	1	Yes	fire break panel	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488968	First	Redlands Accommodation - Kitchen 110	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488969	Ground	Redlands Accommodation - Understairs cupboard & st	1	Yes	panels to both sides	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488970	Ground	Redlands Accommodation - bathroom / shower room RF	1	Yes	wall panels behind tiles	No Asbestos Detected	No Action	0 No Risk	0 N/A
MS COLLING	 WOOD - RELIGI	OUS BUILDINGS - 707948 - COLW0100016	0		201	1	<u> </u>		<u> </u>
2491962	Ground	Religious Building	1	Yes			No Action	0 No Risk	0 N/A
MS COLLING	WOOD - ROMAN	N CATHOLIC CHURCH / OFFICE - 708143 -	COLW010	0160A		<u> </u>	<u> </u>		
2487123	Ground	Religious Buildings - RC Chapel	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487124	Ground	Religious Buildings - Conference Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487125	Ground	Religious Buildings - St Peters Chapel	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487126	Roof	Religious Buildings - Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487127	Ground	Religious Buildings - G07 Cupboard	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
2487128	Ground	Religious Buildings - G08 Presentation Room	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
2487129	External	Religious Buildings - External	1	Yes	Floor		No Action	0 No Risk	0 N/A
2487130	External	Religious Buildings - External	1	Yes	Floor		No Action	0 No Risk	0 N/A
		VC OFFICER ACCOMMODATION - 101053	33 - COI W	01000765	101.	<u>I</u>			
2487466	Ground	Roope Accommodation	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date: 05/04/2017 08:42:40

575 P	
	Defence
	Infrastructure
	Organisation

## Regional Prime Contract Central AsbestosRegister



COLLING	NOOD - ROY	AL ARTHUR BUILDING - 745944 - COLW01	000753						
			4	Vaa	The many such as set	No Ashastas Datastad	No Astion	OlNa Diak	0.1
2488654	Ground	Royal Arthur Offices	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N
COLLING	WOOD - SAR	C NAAFI VENDING AREA AND CLUB - 7080	064 - COLW0	1000634					
2489705	Ground	SARC Club - TV Room Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N
		(cleaners room)			J				
2489706	Ground	SARC Club - TB Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	4 O
_,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					i i i i gi i i i i				
2489736	Ground	SARC Club - Laundry Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0.0
2100100	Ground	State class Education (2000)	·	. 00	i i i i dagi i dat	110710000000	, to / tolio		
2489737	Ground	SARC Club - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2100707	Cround	Ortico clab Cloanoro Capacara	'	100	Timoagnoat	110 / loboolog Boloolog	7 (61161)		
2489738	Ground	SARC Club - Actual Bar Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2403730	Oround	OANO Olab - Actual Bal Alca	•	103	Tilloughout	No Asbesios Delected	NO ACTION	O NO NISK	
2489739	Ground	SARC Club - Weights Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2409139	Giodila	SARC Club - Weights Room	'	168	Throughout	NO Aspesios Defected	No Action	O NO KISK	01
2489740	Ground	CARC Club - Weight Store Room /	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2409740	Ground	SARC Club - Weight Store Room / Office	ı	168	Throughout	INO ASpesios Delected	No Action	UNO RISK	0 1
0400744	0		4	V	The second second	N. A. J t D. t t J	NI- Astisus	ON- Pist	0.1
2489741	Ground	SARC Club - Boxing Gym	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
0400707	O no un d	CADC Club Tou Chara	4	Vaa	Thereseeds a cut	No Ashastas Datastad	NIA Action	O No Diale	0.1
2489707	Ground	SARC Club - Toy Store	ı	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
0400700	0	OADO Olub. Olub Fatasasa Labbas	4	V	The second second	N. A. J t D. t t J.	NI - A - 4'	O No Diele	0.1
2489708	Ground	SARC Club - Club Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
0.400700		2470 01 1 14 1 140		\/	0 11 71			ON BU	
2489709	Ground	SARC Club - Male WC	1	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	10
				.,					
2489710	Ground	SARC Club - Female WC	1	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	10
2489711	Ground	SARC Club - Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489712	Ground	SARC Club - Automat	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489713	Ground	SARC Club - Automat Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489714	Ground	SARC Club - Switch Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489715	Ground	SARC Club - Lift	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489716	Ground	SARC Club - Bar Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489717	Ground	SARC Club - WC next to Bar Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
			·	- <del>-</del>	1 3 3 3 3 4				
2489718	Ground	SARC Club - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
_ 1007 10	0.50110	January Contract of	•	100	III.ougilout		1.10 / 1011011	- CITO KIOK	
2/20740	Ground	SARC Club - Beer Store	4	Voc	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2489719	Giodila	SANG Ciub - Deel Stole	'	Yes	Throughout	INO Wangaroa Derected	INO ACTION	U INU KISK	01

	Defence Infrastructure			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2489720	Ground	SARC Club - Office Next to Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489721	Ground	SARC Club - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489722	Ground	SARC Club - Kitchen store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489723	Ground	SARC Club - Billiards Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489724	Ground	SARC Club - DOE	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489725	Ground	SARC Club - NAAFI Shop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489726	Ground	SARC Club - Office Next to NAAFI Shop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489727	Ground	SARC Club - Staff Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489728	Ground	SARC Club - NE Stairs	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2489729	Ground / First	SARC Club - Ground and First NW Stairs	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2489730	Ground	SARC Club - SE Stairs	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2489731	Ground	SARC Club - SW Stairs	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2489732	Ground	SARC Club - Fire Exit Stairs N	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489733	Ground	SARC Club - Equipment Storage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489734	Ground	SARC Club - NE Stairs Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489735	Ground	SARC Club - Medical Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489609	Second	SARC Club - North West Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489610	Second	SARC Club - Squash Court 1 Upper	1	Yes	Panels at high level of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489611	Second	SARC Club - Upper Balcony 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489612	Second	SARC Club - Upper Balcony 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489613	Second	SARC Club - Squash Court 2 Upper	1	Yes	Panels at high level of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489614	Second	SARC Club - Squash Court 3 Upper	1	Yes	Panels at high level of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489615	Second	SARC Club - Viewing Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489616	Second	SARC Club - Pool Area	1	Yes	Sprayed Coating	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure		Regiona	al Prime	e Contra	act Central	•			
	Infra Orga	structure anisation			Ashesto	osReais	ter		carillion	amey
	2489617	Second	SARC Club - Lift Motor Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489618	Second	SARC Club - Tanks	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489619	Second	SARC Club - Plant Room west	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489620	Second	SARC Club - Plant Room Stairs West	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489621	Second	SARC Club - Sun Bed Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489622	Second	SARC Club - NE Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489623	Second	SARC Club - Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489624	Second	SARC Club - Female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489625	Second	SARC Club - Family Viewing Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489626	Second	SARC Club - Plant Room East	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489627	Second	SARC Club - PT Upper Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489628	Second	SARC Club - SE Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489629	Second	SARC Club - RM Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489630	Second	SARC Club - SE Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489631	Second	SARC Club - SE Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489632	Second	SARC Club - Viewing Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489633	Second	SARC Club - Upper Sports Hall	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489634	Second	SARC Club - Upper Pool Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489635	Second	SARC Club - DOE in Lounge Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489636	Second	SARC Club - Lounge Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489637	Second	SARC Club - Balcony (next to recreational managers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489638	Ground	SARC Club - Swimming Pool Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489639	Ground	SARC Club - Store in Swimming Pool Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastru	estructure					act Central				
<b>(3</b>	Orga	anisation			Ashest	osReais	ster		Carillion amey		
2	2489640	Ground	SARC Club - Launderette	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489641	Ground	SARC Club - Switch Room (next to swimming pool pla	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489642	Ground	SARC Club - Carboy Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489643	Ground	SARC Club - Bulk Store (toxic store)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489644	First	SARC Club - Social Activity Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489645	First	SARC Club - Dance Floor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489646	First	SARC Club - Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489647	First	SARC Club - Male WC (Collingwood club)	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A	
2	2489648	First	SARC Club - Female WC (Collingwood club)	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A	
2	2489649	First	SARC Club - Cloakroom (Collingwood club)	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A	
2	2489650	First	SARC Club - Stage (dance floor)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489651	First	SARC Club - Dressing Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489652	First	SARC Club - Dressing room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489682	Ground	SARC Club - Sports Hall	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489683	Ground	SARC Club - Sports Kit Loan Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489684	Ground	SARC Club - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2489685	Ground	SARC Club - Entrance Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489686	Ground	SARC Club - DOE (next to sports hall)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489687	Ground	SARC Club - Main administration Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489688	Ground	SARC Club - Office 2 )in main admin office)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489689	Ground	SARC Club - Waiting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
2	2489690	Ground	SARC Club - Small Kit Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2489691	Ground	SARC Club - Gun Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	

	Defence Infrastructure	R	egiona	al Prime	e Contra	ct Central			
	nfrastructure Organisation				sReais			<u>Carillion</u>	amey
24896		SARC Club - PT Changing Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	93 Ground	SARC Club - Male Changing Room	1	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	94 Ground	SARC Club - Male WC	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
24896	95 Ground	SARC Club - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	96 Ground	SARC Club - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	97 Ground	SARC Club - Female Changing Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	98 Ground	SARC Club - Activity Area 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	99 Ground	SARC Club - Activity Store (near activity area 1)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	00 Ground	SARC Club - Activity Area 2 C.V. Suite Gym	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	01 Ground	SARC Club - Activity Area 1 Weights Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	02 Ground	SARC Club - Physio (all weather pitch changing roo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	03 Ground	SARC Club - Tavern Bar	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24897	04 Ground	SARC Club - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	53 First	SARC Club - Dressing Room 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	54 First	SARC Club - Store (next to dressing room 2)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	55 First	SARC Club - Store (next to dressing room 1)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	56 First	SARC Club - WC in dressing rooms	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	57 First	SARC Club - Ticket Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	58 First	SARC Club - Club Chairmans Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	59 First	SARC Club - Store (next to club chairmans office)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	60 First	SARC Club - External Balcony	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	61 First	SARC Club - Stage Stairs North	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	62 First	SARC Club - Stage Stairs South	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24896	63 First	SARC Club - Small Store Room by Cloakroom	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	Defe	ence astructure	F	Regiona	al Prime	<b>Contra</b>	act Central		.,,,	
( Constant	Orga	anisation			Asbesto	osRegis	ster		carillion	amey
2	489664	First	SARC Club - Lounge Bar Office	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489665	First	SARC Club - Balcony Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489666	First	SARC Club - SW Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489667	First	SARC Club - NW Stairs	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	489668	First	SARC Club - DOE (next to NE stairs)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489669	First	SARC Club - Sun Bed Lounge	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489670	First	SARC Club - Male Changing Room	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	489671	First	SARC Club - Female Changing Room	1	Yes	Ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	489672	First	SARC Club - Pool entrance	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489673	First	SARC Club - Pool Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489674	First	SARC Club - Pool equipment Store / Staff Changing	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489675	First	SARC Club - Lobby to Balcony	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489676	First	SARC Club - SE stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489677	First	SARC Club - Squash Court 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489678	First	SARC Club - Squash Court 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489679	First	SARC Club - Squash court 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489680	First	SARC Club - Viewing Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489681	First	SARC Club - Swimming Pool	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS C	OLLINGW	VOOD - SAVAG	E VC JR SLA - 1029880 - COLW0100076	68			<u> </u>		I	
2	487469	Ground	Junior Ranks Accommodation (Savage)	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS C	OLLINGW	VOOD - SCOTIA	BUILDING RT TRAINING EQUIPMENT	BUILDING -	711066 - CO	LW01000421	•	•	· · · · · · · · · · · · · · · · · · ·	
2	489008	Ground	Scotia Classroom Block - corridor 2	1	Yes	panel over door to room	Amosite	Monitor	8 Low	0 N/A
2	489009	Ground	Scotia Classroom Block - room F	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489010	Ground	Scotia Classroom Block - room D	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489011	Ground	Scotia Classroom Block - cleaners cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489011	Ground		1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N

	Defence Infrastructure	R	egiona	l Prim	e Contra	act Central				
1		astructure anisation				osReais			carillion	amey
	2489012	Ground	Scotia Classroom Block - WC1	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2489013	Ground	Scotia Classroom Block - corridor 1	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
	2489014	External	Scotia Classroom Block - External porch	1	Yes	ceiling tiles	Amosite	Monitor	6 Low	0 N/A
	2489015	Ground	Scotia Classroom Block - NW stairs	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489016	Ground	Scotia Classroom Block - W office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489017	Ground	Scotia Classroom Block - electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489018	Ground	Scotia Classroom Block - corridor	1	Yes	panels		No Action	0 No Risk	0 N/A
	2489019	Ground	Scotia Classroom Block - room E	1	Yes	debris on		No Action	0 No Risk	0 N/A
HT	2489020	External	Scotia Classroom Block - External	1	Yes	Cladding	Chrysotile	Monitor	4 Very Low	0 N/A
	2489021	Ground	Scotia Classroom Block - Whole Building	1	No	Ducting		No Action	0 No Risk	0 N/A
	2488982	First	Scotia Classroom Block - corridor 2	1	Yes	above door to corridor 1	Amosite	Monitor	8 Low	0 N/A
	2488983	First	Scotia Classroom Block - corridor 1 ceiling void	1	Yes	Ceiling Void (Debris)		No Action	0 No Risk	0 N/A
	2488984	First	Scotia Classroom Block - Classroom L	1	Yes	ceiling tiles	Amosite	Monitor	8 Low	0 N/A
	2488985	First	Scotia Classroom Block - Classroom K	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488986	First	Scotia Classroom Block - Classroom S	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488987	First	Scotia Classroom Block - ICS 2 (Classroom R)	1	Yes	ceiling and skylights	Amosite	Monitor	8 Low	0 N/A
	2488988	First	Scotia Classroom Block - central stairs	1	Yes	ceiling and skylight		No Action	0 No Risk	0 N/A
	2488989	First	Scotia Classroom Block - Classroom Q (radio comms)	1	Yes	ceiling and skylights		No Action	0 No Risk	0 N/A
	2488990	First	Scotia Classroom Block - classroom M	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488991	First	Scotia Classroom Block - Classroom P	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488992	First	Scotia Classroom Block - Classroom P annex	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488993	Ground	Scotia Classroom Block - Strong room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488994	Ground	Scotia Classroom Block - Central Stairs	1	Yes	ceiling		No Action	0 No Risk	0 N/A
	2488995	Ground	Scotia Classroom Block - corridor 1	1	Yes	panel above door to	Amosite	Monitor	8 Low	0 N/A
	2488996	Ground	Scotia Classroom Block - corridor 2	1	Yes	panel above door to	Amosite	Encapsulate/Repair	8 Low	0 N/A

	fence	F	Regiona	al Prime	e Contra	act Central			
Infr	rastructure ganisation				osReais			carillion	amev
2488997	Ground	Scotia Classroom Block - room E	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488998	Ground	Scotia Classroom Block - SCOT 1	1	Yes	panels to wall &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488999	Ground	Scotia Classroom Block - SCOT 2	1	Yes	panels to wall &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489000	Ground	Scotia Classroom Block - SCOT 3	1	Yes	panels to wall &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489001	Ground	Scotia Classroom Block - SCOT Lobby	1	Yes	panels to wall &	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489002	Ground	Scotia Classroom Block - room D	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489003	Ground	Scotia Classroom Block - room D annex	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489004	Ground	Scotia Classroom Block - room B	1	Yes	ceiling	Amosite	Monitor	8 Low	0 N/A
2489005	Ground	Scotia Classroom Block - room A	1	Yes	panels to ceilings and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489006	Ground	Scotia Classroom Block - room G	1	Yes	Floor (Mustard	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489007	Ground	Scotia Classroom Block - room G	1	Yes	Floor (Orange	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488971	Ground	Scotia Classroom Block - Whole Building	1	Yes	Electrical Plant and	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488972	First	Scotia Classroom Block - NW Stairs	1	Yes	Floor (Brown /	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488973	First	Scotia Classroom Block - Corridor 1	1	Yes	Floor (Beige Tiles)	Chrysotile	Monitor	5 Low	0 N/A
2488974	First	Scotia Classroom Block - Corridor 1	1	Yes	ceiling tiles		No Action	0 No Risk	0 N/A
2488975	First	Scotia Classroom Block - cleaners cupboard	1	Yes	ceiling tiles	Amosite	Monitor	8 Low	0 N/A
2488976	First	Scotia Classroom Block - IO Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488977	First	Scotia Classroom Block - female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488978	First	Scotia Classroom Block - male staff WC	1	Yes	ceiling tiles	Amosite	Monitor	8 Low	0 N/A
2488979	First	Scotia Classroom Block - male rates WC	1	Yes	ceiling tiles and skylight	Amosite	Monitor	8 Low	0 N/A
2488980	First	Scotia Classroom Block - corridor 1	1	Yes	above door to corridor 2	Amosite	Monitor	8 Low	0 N/A
2488981	First	Scotia Classroom Block - male rates WC	1	Yes	Toilet Cistern	Amosite	Monitor	6 Low	0 N/A
HMS COLLING	WOOD - SEAWO	DLF DATUM MAST EQUIPMENT BUILDIN	NG - 707984	- COLW0100	0199	•	•		
2487156	Ground	Test Mast Hut	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	F	Regiona	l Prim	e Contra	act Central		**	
The state of the s	Infra Orga	astructure anisation				osReais			carillion	amey
ни			RITY HUT - 1742075 - COLW01PB0761		<u> </u>	CONTOGIC				
	2487470	Ground	Guard Room - Room 01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487471	Ground	Guard Room - Room 02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487472	Ground	Guard Room - Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
НИ	IS COLLINGV	VOOD - SEPHT	ON VC SR SLA - 745943 - COLW010007	51					<u> </u>	
	2488653	Ground	Sephton Accommodation Block	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HN	IS COLLINGV	VOOD - SHERE	BROOKE VC OFFICER ACCOMMODATION	N - 1010532	- COLW010			<u> </u>		
	2487465	Ground	Sherbrook Accommodation	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
ни	IS COLLINGV	VOOD - Site W	ide Assets - COLWxx - COLWXXSITEWII	DE		1			L L	
	2487219	Ground	COLW0100641A - Chemical Store	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491496	Ground	COLW01000621 / 622 - Store 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491497	Ground	COLW01000621 / 622 - Bathroom 16	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491498	Ground	COLW01000621 / 622 - 28 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491499	Ground	COLW01000621 / 622 - 28 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491500	Ground	COLW01000621 / 622 - 28 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491501	Ground	COLW01000621 / 622 - 29 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491502	Ground	COLW01000621 / 622 - 29 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491503	Ground	COLW01000621 / 622 - DOE 1	1	Yes	Floor (Beige	Chrysotile	Monitor	3 Very Low	0 N/A
	2491504	Ground	COLW01000621 / 622 - Pelican Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491505	Ground	COLW01000621 / 622 - Pelican Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491506	Ground	COLW01000621 / 622 - Pelican WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491507	Ground	COLW01000621 / 622 - Hornet Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491508	Ground	COLW01000621 / 622 - Hornet Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491509	Ground	COLW01000621 / 622 - Hornet Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491510	Ground	COLW01000621 / 622 - Corridor 5	1	Yes	panels above fire	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation 2491511 Ground			Regiona	l Prime	e Contra	act Central			
1	Orga	structure				osReais			carillion	amey
		·	COLW01000621 / 622 - 42 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491512	Ground	COLW01000621 / 622 - 42 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491513	Ground	COLW01000621 / 622 - 42 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491514	Ground	COLW01000621 / 622 - 43 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491515	Ground	COLW01000621 / 622 - 43 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491516	Ground	COLW01000621 / 622 - 43 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491517	Ground	COLW01000621 / 622 - 40 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2491518	Ground	COLW01000621 / 622 - 40 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491519	Ground	COLW01000621 / 622 - 41 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491520	Ground	COLW01000621 / 622 - 41 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491521	Ground	COLW01000621 / 622 - 41 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491522	Ground	COLW01000621 / 622 - 39 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491523	Ground	COLW01000621 / 622 - 39 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491524	Ground	COLW01000621 / 622 - 39 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491525	Ground	COLW01000621 / 622 - 38 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491731	Ground	COLW01000621 / 622 - Corridor 6	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
	2491732	Ground	COLW01000621 / 622 - Stairs 3	1	Yes	panel above	Amosite	Monitor	6 Low	0 N/A
	2491733	Ground	COLW01000621 / 622 - Stairs 3	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
	2491734	Ground	COLW01000621 / 622 - Stairs 3	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491735	Ground	COLW01000621 / 622 - Corridor 7	1	Yes	panel above		No Action	0 No Risk	0 N/A
	2491736	Ground	COLW01000621 / 622 - Corridor 7	1	Yes	panel above		No Action	0 No Risk	0 N/A
	2491737	Ground	COLW01000621 / 622 - Stairs 3 Fire Exit Door to Ce	1	Yes	panel above door	Amosite	Monitor	6 Low	0 N/A
$   \uparrow   $	2491738	Ground	COLW01000621 / 622 - Soffits - Courtyard 1 (extern	1	Yes	panels to underside of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491739	Ground	COLW01000621 / 622 - Soffits - Courtyard 2	1	Yes	panels adjacent to	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491740	Ground	COLW01000621 / 622 - Stairs 4	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		F	Regiona	al Prime	e Contra	act Central			
( The second sec	Orga	structure anisation			Asbest	osReais	ster		carillion	namey 🚩
2	2491741	Ground	COLW01000621 / 622 - Bin store	1	Yes	2no loose boards - free	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491742	Ground	COLW01000621 / 622 - Bin Store	1	Yes	panel / tiles	Amosite	Monitor	6 Low	0 N/A
2	2491743	Ground	COLW01000621 / 622 - Bike Shed	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491744	Ground	COLW01000621 / 622 - Cabin 45	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491745	Ground	COLW01000621 / 622 - Cabin 45 Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491746	Ground	COLW01000621 / 622 - Cabin 143	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491747	Ground	COLW01000621 / 622 - Cabin 143 Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491748	Ground	COLW01000621 / 622 - Cabin 142	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491749	Ground	COLW01000621 / 622 - Cabin 142 Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491750	Ground	COLW01000621 / 622 - Cabin 144	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491751	Ground	COLW01000621 / 622 - Cabin 144 Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491752	Ground	COLW01000621 / 622 - Cabin 8	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491753	Ground	COLW01000621 / 622 - Cabin 9	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491754	Ground	COLW01000621 / 622 - Cabin 9	1	No	Riser		No Action	0 No Risk	0 N/A
2	2491755	Ground	COLW01000621 / 622 - Cabin 10	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491756	Ground	COLW01000621 / 622 - Cabin 11	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491757	Ground	COLW01000621 / 622 - Pipe Riser to WC G	1	No	Pipe Riser		No Action	0 No Risk	0 N/A
2	2491758	Ground	COLW01000621 / 622 - WC G	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491759	Ground	COLW01000621 / 622 - Utility 7	1	Yes	panel in	Amosite	Monitor	6 Low	0 N/A
2	2491526	Ground	COLW01000621 / 622 - 38 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491527	Ground	COLW01000621 / 622 - 38 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491528	Ground	COLW01000621 / 622 - 37 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491529	Ground	COLW01000621 / 622 - 37 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491530	Ground	COLW01000621 / 622 - 37 Shower & WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		Re	aiona	l Prime	<b>Contra</b>	ct Central			
R	Infra Orga	structure				sRegis			carillion	amey
	2491531	Ground	COLW01000621 / 622 - 36 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491532	Ground	COLW01000621 / 622 - 36 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491533	Ground	COLW01000621 / 622 - 36 Shower & WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491534	Ground	COLW01000621 / 622 - Stairs 2	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2491535	Ground	COLW01000621 / 622 - Corridor 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491536	Ground	COLW01000621 / 622 - Utility Room 15	1	Yes	panel in cupboard	Amosite and Chrysotile	Monitor	6 Low	0 N/A
	2491537	Ground	COLW01000621 / 622 - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491538	Ground	COLW01000621 / 622 - Store 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491539	Ground	COLW01000621 / 622 - Link 623	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
H +	2491540	First	COLW01000621 / 622 - DOE 2	1	Yes	Floor (Beige	Chrysotile	Monitor	3 Very Low	0 N/A
	2491541	Ground	COLW01000621 / 622 - Stairs 1	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2491542	Ground	COLW01000621 / 622 - Store 8	1	Yes	Floor (Beige	Chrysotile	Monitor	3 Very Low	0 N/A
	2491543	Ground	COLW01000621 / 622 - Store 9	1	Yes	Floor (Beige	Chrysotile	Monitor	3 Very Low	0 N/A
	2491544	Ground	COLW01000621 / 622 - Bathroom 12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491545	Ground	COLW01000621 / 622 - Bathroom 21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491546	Ground	COLW01000621 / 622 - Riser Cupboard Bathroom 21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491547	Ground	COLW01000621 / 622 - Bathroom 22	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491548	Ground	COLW01000621 / 622 - Bathroom 22 Riser Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491549	Ground	COLW01000621 / 622 - A19 Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491550	Ground	COLW01000621 / 622 - Bathroom 10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491551	Ground	COLW01000621 / 622 - Baggage Store A15	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491552	Ground	COLW01000621 / 622 - Cleaner Store A16	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491553	Second	COLW01000621 / 622 - Bathroom 30 (adjacent to room	1	Yes	in recess of pipe riser	Amosite and Chrysotile	Monitor	6 Low	0 N/A
HT	2491554	Ground	COLW01000621 / 622 - Stair 2	1	Yes	coating to	Chrysotile	Monitor	3 Very Low	0 N/A
	2491555	Ground	COLW01000621 / 622 - Landing of Stairwell 2 (above	1	Yes	panels above doors	Amosite	Monitor	6 Low	0 N/A

	Defe		F	Regiona	al Prime	e Contra	act Central			
dado	Orga	structure anisation			Asbest	osReais	ter		carillion	amey
	2491466	Ground	COLW01000621 / 622 - Store A17	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491467	Ground	COLW01000621 / 622 - Corridor 2	1	Yes	panel above fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491468	Ground	COLW01000621 / 622 - Lobby 1	1	Yes	above fire doors onto	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491469	Ground	COLW01000621 / 622 - Stairs 3	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491470	Ground	COLW01000621 / 622 - Corridor 3	1	Yes	panels above fire	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491471	Ground	COLW01000621 / 622 - Cabin 78	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491472	Ground	COLW01000621 / 622 - Cabin 79	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491473	Ground	COLW01000621 / 622 - Cabin 80	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491474	Ground	COLW01000621 / 622 - Cabin 81	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491475	Ground	COLW01000621 / 622 - Lobby 2	1	Yes	panels to 3 fire doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491476	Ground	COLW01000621 / 622 - Stairs 4	1	Yes	stairs and landing	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491477	Ground	COLW01000621 / 622 - 35 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491478	Ground	COLW01000621 / 622 - 35 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491479	Ground	COLW01000621 / 622 - 35 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491480	Ground	COLW01000621 / 622 - Bathroom 18	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491481	Ground	COLW01000621 / 622 - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491482	Ground	COLW01000621 / 622 - Store 4	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2491483	Ground	COLW01000621 / 622 - 33 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2491484	Ground	COLW01000621 / 622 - 33 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2491485	Ground	COLW01000621 / 622 - 33 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491486	Ground	COLW01000621 / 622 - 32 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491487	Ground	COLW01000621 / 622 - 32 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491488	Ground	COLW01000621 / 622 - 32 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	Re	aiona	al Prime	e Contra	act Central	-		
( To )		astructure anisation			Asbest	osReais	ster		carillion	amey
2	2491489	Ground	COLW01000621 / 622 - 31 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491490	Ground	COLW01000621 / 622 - 31 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491491	Ground	COLW01000621 / 622 - 31 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491492	Ground	COLW01000621 / 622 - 30 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491493	Ground	COLW01000621 / 622 - 30 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491494	Ground	COLW01000621 / 622 - 30 WC & Shower	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491495	Ground	COLW01000621 / 622 - Store 5	1	Yes	Floor (Beige	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491431	Ground	COLW01000621 / 622 - Cabin 59	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491432	Ground	COLW01000621 / 622 - Corridor 1	1	Yes	panel above door	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491433	Ground	COLW01000621 / 622 - Utility Room 23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491434	Ground	COLW01000621 / 622 - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491435	Ground	COLW01000621 / 622 - Cabin 58	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491703	Ground	COLW01000621 / 622 - Corridor 2	1	Yes	ceiling void	Amosite	Monitor	6 Low	0 N/A
2	2491704	Ground	COLW01000621 / 622 - Corridor 2	1	Yes	panel above	Amosite	Monitor	6 Low	0 N/A
2	2491705	Ground	COLW01000621 / 622 - Cupboard 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491706	Ground	COLW01000621 / 622 - Corridor 2	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
2	2491707	Ground	COLW01000621 / 622 - Fire Exit stairs 4	1	Yes	panel above door to	Amosite	Monitor	6 Low	0 N/A
2	2491708	Ground	COLW01000621 / 622 - Lobby stairs 4	1	Yes	fire break in ceiling void	Amosite	Monitor	6 Low	0 N/A
2	2491709	Ground	COLW01000621 / 622 - Lobby stairs 4	1	Yes	above door to corridor 3		No Action	0 No Risk	0 N/A
2	2491710	Ground	COLW01000621 / 622 - Stairs 4 Lobby	1	Yes	fire break in ceiling void		Monitor	6 Low	0 N/A
2	2491711	Ground	COLW01000621 / 622 - Covered Walkway (central)	1	Yes	panels to ceiling of	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491712	Ground	COLW01000621 / 622 - Corridor 3	1	Yes	panel above		No Action	0 No Risk	0 N/A
2	2491713	Ground	COLW01000621 / 622 - Corridor 3 (stairs 4 lobby)	1	Yes	fire break in ceiling void	Amosite	Monitor	6 Low	0 N/A
2	2491714	Ground	COLW01000621 / 622 - Corridor 3	1	Yes	panel above		No Action	0 No Risk	0 N/A
2	2491715	Ground	COLW01000621 / 622 - SE Fire Exit	1	Yes	tiles to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491716	Ground	COLW01000621 / 622 - Corridor 3	1	Yes		Amosite	Monitor	6 Low	0 N/A

Run By:

CD\\svc\_ProRepuser

	Defence Infrastructure Organisation 2491717 Ground			Regiona	l Prime	e Contra	ct Central			
	Infra Org	astructure anisation				osReais			carillion	amey
			COLW01000621 / 622 - Corridor 4	1	Yes	panel	Amosite	Monitor	6 Low	0 N/A
П	2491718	Ground	COLW01000621 / 622 - Corridor 4	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
	2491719	Ground	COLW01000621 / 622 - Staff Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491720	Ground	COLW01000621 / 622 - Corridor 4	1	Yes	above door	Amosite	Monitor	6 Low	0 N/A
IT	2491721	Ground	COLW01000621 / 622 - Corridor 4	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
	2491722	Ground	COLW01000621 / 622 - Stairs 6 Lobby	1	Yes	panel above both doors	Amosite	Monitor	6 Low	0 N/A
	2491723	Ground	COLW01000621 / 622 - Stairs & Lobby 6	1	Yes	fire break in ceiling void	Amosite	Monitor	6 Low	0 N/A
	2491724	Ground	COLW01000621 / 622 - Stairs 6 Lobby	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491725	Ground	COLW01000621 / 622 - Corridor 5	1	Yes	panel above	Amosite	Monitor	6 Low	0 N/A
П	2491726	Ground	COLW01000621 / 622 - Corridor 5	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
П	2491727	Ground	COLW01000621 / 622 - Stairs 5	1	Yes	panel above	Amosite	Monitor	6 Low	0 N/A
П	2491728	Ground	COLW01000621 / 622 - Stairs 5	1	Yes	fire break in	Amosite	Monitor	6 Low	0 N/A
	2491729	Ground	COLW01000621 / 622 - Stairs 5	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491730	Ground	COLW01000621 / 622 - Corridor 6	1	Yes	panel above	Amosite	Monitor	6 Low	0 N/A
	2491436	Ground	COLW01000621 / 622 - Cabin 57	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491437	Ground	COLW01000621 / 622 - Corridor 1	1	Yes	strip above doors in	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491438	Ground	COLW01000621 / 622 - Stairs 6	1	Yes	stairs and landing	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491439	Ground	COLW01000621 / 622 - Cabin 60	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491440	Ground	COLW01000621 / 622 - Cabin 61	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491441	Ground	COLW01000621 / 622 - Cabin 62	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491442	Ground	COLW01000621 / 622 - WC 24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491443	Ground	COLW01000621 / 622 - Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491444	Ground	COLW01000621 / 622 - Cabin 63	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491445	Ground	COLW01000621 / 622 - Stairs 2-5	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491446	Ground	COLW01000621 / 622 - Utility Room 25	1	Yes	panel to cupboard	Amosite and Chrysotile	Monitor	6 Low	0 N/A
	2491447	Ground	COLW01000621 / 622 - Drying Room 25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 125 of 420

	Defe			Regiona	al Prime	<b>Contra</b>	act Central			
Transfer of the Park	Infra Orga	structure anisation			Asbesto	sRegis	ter		carillion	amey
		First	COLW01000621 / 622 - electrical cupboard	1	Yes	Floor (Beige Tiles)		Monitor	3 Very Low	0 N/A
	2491449	Ground	COLW01000621 / 622 - WC 26	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491450	Ground	COLW01000621 / 622 - WC 27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491451	Ground	COLW01000621 / 622 - Cabin 64	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491452	Ground	COLW01000621 / 622 - Cabin 65	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491453	Ground	COLW01000621 / 622 - Cabin 66	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491454	Ground	COLW01000621 / 622 - Cabin 67	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491455	Ground	COLW01000621 / 622 - Cabin 68	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491456	Ground	COLW01000621 / 622 - Cabin 69	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491457	Ground	COLW01000621 / 622 - Cabin 70	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491458	Ground	COLW01000621 / 622 - Cabin 71	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491459	Ground	COLW01000621 / 622 - Cabin 72	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491460	Ground	COLW01000621 / 622 - Cabin 73	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491461	Ground	COLW01000621 / 622 - Cabin 74	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491462	Ground	COLW01000621 / 622 - Cabin 75	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491463	Ground	COLW01000621 / 622 - Cabin 76	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491464	Ground	COLW01000621 / 622 - Cabin 77	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491465	Ground	COLW01000621 / 622 - Store A18	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487157	Ground	COLW01000201 - Small Arms Range	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487154	Ground	COLW01000193 - Substation G	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487161	Ground	COLW01000206 - Incinerator Compound	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487452	Ground	COLW01000782 - Cunningham Block	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491673	Ground	COLW01000621 / 622 - Cabin 2 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation 2491674 Ground		R	egiona	al Prime	e Contra	ct Central		•	
	Infra	structure	1			osReais			carillior	amev
			COLW01000621 / 622 - Cabin 2	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bedroom			J				
	2491675	Ground	COLW01000621 / 622 - Cabin 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bathroom							
	2491676	Ground	COLW01000621 / 622 - Cabin 3	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Lounge							
	2491677	Ground	COLW01000621 / 622 - Cabin 3	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	0.404.070		Bedroom		\ <u>'</u>	T		N. A. C	ON BU	0.01/4
	2491678	Ground	COLW01000621 / 622 - Cabin 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HH	2491679	Ground	Bathroom COLW01000621 / 622 - Cabin 4	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491079	Ground	Lounge	ı	168	Cening	No Aspesios Defected	NO ACTION	O NO KISK	U IN/A
	2491680	Ground	COLW01000621 / 622 - Cabin 4	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2101000	Oroana	Bedroom		100	ooming	No riobooled Bolodida	71071011		01477
HH	2491681	Ground	COLW01000621 / 622 - Cabin 5	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Lounge							
	2491682	Ground	COLW01000621 / 622 - Cabin 5	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bedroom							
	2491683	Ground	COLW01000621 / 622 - Cabin 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bathroom							
	2491684	Ground	COLW01000621 / 622 - Cabin 6	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	0.404.005		Lounge		\ <u>/</u>	.,.		N. A. C	ON BU	0.11/4
	2491685	Ground	COLW01000621 / 622 - Cabin 6 Bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491686	Ground	COLW01000621 / 622 - Cabin 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491000	Ground	Bathroom	ı	165	Tilloughout	NO Aspesios Defected	NO ACTION	O NO KISK	U IN/A
	2491687	Ground	COLW01000621 / 622 - Cabin 7	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Lounge	•		9				
	2491688	Ground	COLW01000621 / 622 - Cabin 7	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bedroom							
	2491689	Ground	COLW01000621 / 622 - Cabin 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bathroom							
	2491690	Ground	COLW01000621 / 622 - Bathroom 2	1	Yes	behind riser	Presumed Asbestos	Monitor	6 Low	0 N/A
HH		<u></u>					Content			
	2491691	Ground	COLW01000621 / 622 - Utility Room 1	1	Yes	panel to		No Action	0 No Risk	0 N/A
	2404602	Craund	COLW04000634 / 633 LHility Doom 4		Vaa	cupboard	No Ashastas Datastad	No Action	O No Diek	0 N/A
	2491692	Ground	COLW01000621 / 622 - Utility Room 1 Store room	I	Yes	throughout	No Asbestos Detected	NO ACTION	0 No Risk	U N/A
	2491693	Ground	COLW01000621 / 622 - Utility Room 1	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2431033	Ground	GOEWO10000217 022 - Otility Room 1	'	103	Ollik	Onlysothe	Worldon	S Very Low	O N/A
	2491694	Ground	COLW01000621 / 622 - DOE Room 1	1	Yes	switch gear	Presumed Asbestos	Monitor	4 Very Low	0 N/A
						9	Content			2 47 7
	2491695	Ground	COLW01000621 / 622 - DOE Room 1	1	Yes	panel to	Amosite	Monitor	6 Low	0 N/A
						ceiling				
	2491696	Ground	COLW01000621 / 622 - Cabin 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bathroom							

-	Defe		R	Regiona	l Prime	e Contra	act Central			
	Infra Orga	astructure anisation				osReais			carillion	amey
	2491697	Ground	COLW01000621 / 622 - Cleaner 1	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2491698	Ground	COLW01000621 / 622 - Corridor 2	1	Yes	tiles above	Amosite	Monitor	6 Low	0 N/A
	2491699	Ground	COLW01000621 / 622 - WC 3	1	No	Riser		No Action	0 No Risk	0 N/A
	2491700	Ground	COLW01000621 / 622 - Cleaner store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491701	Ground	COLW01000621 / 622 - Laundry Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491702	Ground	COLW01000621 / 622 - Bathroom 5	1	No	Riser		No Action	0 No Risk	0 N/A
	2491643	Ground	COLW01000621 / 622 - WC 38 off corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491644	Ground	COLW01000621 / 622 - cleaning cupboard next to WC3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491645	Ground	COLW01000621 / 622 - Room 137	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491646	Ground	COLW01000621 / 622 - Room 092	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491647	Ground	COLW01000621 / 622 - Room 093	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491648	Ground	COLW01000621 / 622 - Bathroom 28	1	Yes	panel and debris within	Amosite	Monitor	6 Low	0 N/A
	2491649	Ground	COLW01000621 / 622 - DOE Room (off corridor 2)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491650	Ground	COLW01000621 / 622 - Room 094	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491651	Ground	COLW01000621 / 622 - Room 095	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491652	Ground	COLW01000621 / 622 - Room 096	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491653	Ground	COLW01000621 / 622 - Room 097	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491654	Ground	COLW01000621 / 622 - DOE Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491655	Ground	COLW01000621 / 622 - No Entry Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491656	Ground	COLW01000621 / 622 - Room 098	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491657	Ground	COLW01000621 / 622 - Room 099	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491658	Ground	COLW01000621 / 622 - Baggage Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491659	Ground	COLW01000621 / 622 - Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491660	Ground	COLW01000621 / 622 - Staircase 1	1	Yes	side of stairs	Chrysotile	Monitor	3 Very Low	0 N/A
	2491661	Ground	COLW01000621 / 622 - Room 100	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491662	Ground	COLW01000621 / 622 - Room 101	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
$\prod$	2491663	Ground	COLW01000621 / 622 - Corridor 6	1	Yes	Above door	Amosite	Monitor	6 Low	0 N/A
	2491664	Ground	COLW01000621 / 622 - Cleaners Cupboard D	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defe			Regiona	al Prime	e Contra	act Central		carillion	
Infra Orga	structure anisation				osReais			carillion	amey
2491665	Ground	COLW01000621 / 622 - Covered external walkway (nor	1	Yes	panels to external	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491666	Ground	COLW01000621 / 622 - NW Entrance Lobby	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491667	Ground	COLW01000621 / 622 - Corridor 1	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491668	Ground	COLW01000621 / 622 - Calorifier Lobby	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491669	Ground	COLW01000621 / 622 - Calorifier Lobby	1	No	throughout		No Action	0 No Risk	0 N/A
2491670	Ground	COLW01000621 / 622 - Cabin 1 Lounge	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491671	Ground	COLW01000621 / 622 - Cabin 1 bedroom	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491672	Ground	COLW01000621 / 622 - Cabin 1 Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487140	Ground	COLW0100187A - Greenhouse	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487141	Ground	COLW0100187B - Greenhouse	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2492000	Ground	COLW01000621 / 622 - Electrical Cupboard (Corridor	1	Yes	Flooring	Chrysotile	Monitor	6 Low	2 m2
2492001	Ground	COLW01000621 / 622 - Stairs 4 Lobby	1	Yes	Ceiling Void Anti	-Chrysotile	Monitor	6 Low	1 m2
2492002	First	COLW01000621 / 622 - Lobby (Between 35 and 46)	1	Yes	Ceiling Void Shuttering to	1	Monitor	6 Low	1 m2
2492003	Second	COLW01000621 / 622 - Stairs 1	1	Yes	Door Header	Amosite and Chrysotile	Monitor	9 Medium	1 m2
2492004	Second	COLW01000621 / 622 - Lobby (Between Corridor 04 an	1	Yes	Above Ceiling -	Chrysotile	Monitor	5 Low	1 m2
2487253	Ground	COLW01000656 - Fuel Storage Bund	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487254	Ground	COLW01000657 - Fuel Storage Bund	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487251	Ground	COLW01000654 - Gas Meter House	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491556	Ground	COLW01000621 / 622 - Landing of Stairwell 2 (above	1	Yes	panels above doors	Amosite	Monitor	6 Low	0 N/A
2491557	Ground	COLW01000621 / 622 - Corridor 6 above door leading	1	Yes	panels above door	Amosite	Monitor	6 Low	0 N/A
2491558	Ground	COLW01000621 / 622 - D.O.E. Room on Corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491559	Ground	COLW01000621 / 622 - Sitting Room	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491560	Ground	COLW01000621 / 622 - Baggage Room on Corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 129 of 420

		ence	R	egiona	al Prime	e Contra	ct Central			
	) Infra Orga	structure				osReais			carillion	ımey
2	2491561	Ground	COLW01000621 / 622 - Utility Room 34	1	Yes	panels/tiles in cuipboard	Amosite and Chrysotile	Monitor	6 Low	0 N/A
2	2491562	Ground	COLW01000621 / 622 - WC 35 (on corridor 5)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491563	Ground	COLW01000621 / 622 - WC/Bathroom on Corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491564	Ground	COLW01000621 / 622 - Room 082	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491565	Ground	COLW01000621 / 622 - Room 083	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491566	Ground	COLW01000621 / 622 - Room 084	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491567	Ground	COLW01000621 / 622 - Room 085	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491568	Ground	COLW01000621 / 622 - Room 086	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2	2491569	Ground	COLW01000621 / 622 - Room 087	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491570	Ground	COLW01000621 / 622 - Room 088	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491571	Ground	COLW01000621 / 622 - Room 089	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491572	Ground	COLW01000621 / 622 - WC (37)	<u>'</u> 1	Yes	ceiling	om yours	No Action	0 No Risk	0 N/A
	2491573	Ground	COLW01000621 / 622 - Room 090	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
				1		, ,	_			
	2491574	Ground	COLW01000621 / 622 - Room 091	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491575	Ground	COLW01000621 / 622 - Corridor 6 above door leading	1	Yes	above door in ceiling	Amosite	Monitor	6 Low	0 N/A
2	2491576	Ground	COLW01000621 / 622 - Corridor 6 above door leading	1	Yes	above door in ceiling	Amosite	Monitor	6 Low	0 N/A
2	2491577	Ground	COLW01000621 / 622 - Landing at top of Stairwell 2	1	Yes	in ceiling void above	Amosite	Monitor	6 Low	0 N/A
2	2491578	Ground	COLW01000621 / 622 - Landing at top of Stairwell 2	1	Yes	in ceiling void above	Amosite	Monitor	6 Low	0 N/A
2	2491579	Ground	COLW01000621 / 622 - Cleaners Cupboard on Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491580	Ground	COLW01000621 / 622 - Utility Room	1	Yes	panels/tiles in cuipboard	Amosite	Monitor	6 Low	0 N/A
2	2491581	Ground	COLW01000621 / 622 - WC 37 in corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491582	Ground	COLW01000621 / 622 - Cleaners Cupboard next to WC3	1	Yes	board in recess	Amosite	Monitor	6 Low	0 N/A
2	2491583	Ground	COLW01000621 / 622 - Outdoor Patio (opposite WC37)	1	Yes	quarry tiles	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2491584	Ground	COLW01000621 / 622 - Baggage Store (corridor 4) (A	1	Yes	Fuse holders lying		No Action	0 No Risk	0 N/A
2	2491850	Ground	COLW01000672 / 673 - corridor 064	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491851	Ground	COLW01000672 / 673 - B8 074	1	Yes	panels to wall above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2491852	Ground	COLW01000672 / 673 - B8B 075	1	Yes	panels to wall above	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Primo	e Contra	act Central			
1000	Infra Orga	structure anisation				osReais			carillion	amey
П	2491853	Ground	COLW01000672 / 673 - B4B 076	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491854	Ground	COLW01000672 / 673 - B55 077	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491855	Ground	COLW01000672 / 673 - B5B 078	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491856	Ground	COLW01000672 / 673 - B11 080	1	Yes	Perforated Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491857	Ground	COLW01000672 / 673 - corridor 082	1	Yes	3 x panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491858	Ground	COLW01000672 / 673 - corridor 082	1	Yes	panels around	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491859	Ground	COLW01000672 / 673 - corridor 082	1	Yes	panels above 2 x	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2491860	Ground	COLW01000672 / 673 - C1A 083	1	Yes	panel to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491861	Ground	COLW01000672 / 673 - C1B 084	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491862	Ground	COLW01000672 / 673 - B6A 059	1	Yes	boxing to beam	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491863	Ground	COLW01000672 / 673 - A1 049	1	Yes	upstand panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491864	Ground	COLW01000672 / 673 - A1 049	1	Yes	wall by door way	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2491865	Ground	COLW01000672 / 673 - A2 050	1	Yes	wall by doorway	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491866	Ground	COLW01000672 / 673 - corridor 064	1	Yes	wall riser	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491867	Ground	COLW01000672 / 673 - C2A	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491868	Ground	COLW01000672 / 673 - C2B 086	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491869	Ground	COLW01000672 / 673 - C2C 087	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491870	Ground	COLW01000672 / 673 - C3A 088	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491871	Ground	COLW01000672 / 673 - C3B 089	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491872	Ground	COLW01000672 / 673 - C3C 090	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491873	Ground	COLW01000672 / 673 - C3A 091	1	Yes	panels to doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491874	Ground	COLW01000672 / 673 - corridor 092	1	Yes	panels around	No Asbestos Detected	No Action	0 No Risk	0 N/A
T	2491875	Ground	COLW01000672 / 673 - C7 095	1	Yes	Walls and Bulkhead	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence astructure	R				ct Central		.111	4
The state of the s	Org	anisation			Asbest	osReais	ter		carillion	amey 🦳
	2491876	Ground	COLW01000672 / 673 - D9 100	1	Yes	Walls and Bulkhead	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491877	Ground	COLW01000672 / 673 - corridor 110	1	Yes	fire break	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491878	Ground	COLW01000672 / 673 - corridor 110	1	Yes	panels to 2 x	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491790	Ground	COLW01000621 / 622 - Calorifier 2	1	Yes	panels above door	Amosite	Monitor	6 Low	0 N/A
	2491791	Ground	COLW01000621 / 622 - Calorifier 1	1	Yes	panels above door	Amosite	Monitor	6 Low	0 N/A
	2491792	Ground	COLW01000621 / 622 - Sarah Blackett Suite Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491793	Ground	COLW01000621 / 622 - Breaker Room	1	No	throughout		No Action	0 No Risk	0 N/A
	2491794	Ground	COLW01000621 / 622 - Stairs 1	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491795	Ground	COLW01000621 / 622 - Stairs 1	1	Yes	panel to	Amosite	Monitor	6 Low	0 N/A
	2491796	Ground	COLW01000621 / 622 - Sarah Blackett Building	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491797	Ground	COLW01000621 / 622 - Sarah Blackett Lounge	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491798	Ground	COLW01000621 / 622 - A 35	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491799	Ground	COLW01000621 / 622 - A 34	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491800	Ground	COLW01000621 / 622 - Calorifier Room 3	1	No	throughout		No Action	0 No Risk	0 N/A
	2491801	Ground	COLW01000621 / 622 - room 001 - utility room	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2491802	Ground	COLW01000621 / 622 - room 004 - store	1	Yes	Floor	Chrysotile	Monitor	3 Very Low	0 N/A
	2491803	Ground	COLW01000621 / 622 - A01, loft area above baggage	1	Yes	old sarking felt	Chrysotile	Monitor	3 Very Low	0 N/A
	2491804	Ground	COLW01000621 / 622 - A02, loft above baggage store	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
	2491805	Ground	COLW01000621 / 622 - A02, loft above baggage store	1	Yes	old sarking felt	Chrysotile	Monitor	3 Very Low	0 N/A
	2491806	Ground	COLW01000621 / 622 - A02 loft area	1	No	throughout		No Action	0 No Risk	0 N/A
	2491807	Ground	COLW01000621 / 622 - room 008 - calorifier room 1	1	Yes	fire break panel above	Amosite	Monitor	6 Low	0 N/A
	2491808	Ground	COLW01000621 / 622 - room 008 - calorifier room 1	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491809	Ground	COLW01000621 / 622 - cabin 12	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491810	Ground	COLW01000621 / 622 - cabin 13	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	R	egiona	al Primo	e Contra	act Central			
(3	Infra Orga	structure anisation				osReais			carillion	amey
	2491811	Ground	COLW01000621 / 622 - cabin 27	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2491812	Ground	COLW01000621 / 622 - glass store	1	Yes	Floo	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491813	Ground	COLW01000621 / 622 - A01 - loft area	1	Yes	Roof Slate Debris	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491814	Ground	COLW01000621 / 622 - A02 loft area	1	Yes	Roof Slate Debris	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491815	Ground	COLW01000621 / 622 - Calorifier room	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491816	First	COLW01000672 / 673 - electrical cupboard F5A 103	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491817	First	COLW01000672 / 673 - stairwell 107	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491818	First	COLW01000672 / 673 - stairwell 127	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491819	Ground	COLW01000672 / 673 - corridor 008	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491820	Ground	COLW01000672 / 673 - A2 050	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491821	Ground	COLW01000672 / 673 - A4 056	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491822	Ground	COLW01000672 / 673 - B10 057	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491823	Ground	COLW01000672 / 673 - A34 054	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491824	Ground	COLW01000672 / 673 - B11 080	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491825	Ground	COLW01000672 / 673 - C9 081	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491826	Ground	COLW01000672 / 673 - corridor 082	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491827	Ground	COLW01000672 / 673 - corridor 082	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
	2491828	Ground	COLW01000672 / 673 - A1 049	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491829	Ground	COLW01000672 / 673 - C8 096	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491830	Ground	COLW01000672 / 673 - C8 096	1	Yes	Pipework Within	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491831	Ground	COLW01000672 / 673 - D12 097	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491832	Ground	COLW01000672 / 673 - D11 098	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
Ш	2491833	Ground	COLW01000672 / 673 - D8 101	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
HT	2491834	Ground	COLW01000672 / 673 - lobby 104	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
$H^{\dagger}$	2491835	Ground	COLW01000672 / 673 - D10 099	1	No	Throughout		No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2491836	External	COLW01000672 / 673 - External	1	Yes	Panels above main	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2491837	First	COLW01000672 / 673 - access to roof 132	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491838	First	COLW01000672 / 673 - stairwell 107	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		Re	egiona	l Prime	e Contra	ct Central			
8	Infra Orga	structure				osReais			carillion	amey
		First	COLW01000672 / 673 - stairwell 131	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491840	Ground	COLW01000672 / 673 - corridor 008	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491841	Ground	COLW01000672 / 673 - lobby 033	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491842	Ground	COLW01000672 / 673 - electrical cupboard C3A 004	1	Yes	under the wooden	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491843	Ground	COLW01000672 / 673 - A2 050	1	Yes	up stand panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491844	Ground	COLW01000672 / 673 - lobby 051	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491845	Ground	COLW01000672 / 673 - electrical cupboard A1 052	1	Yes	fire break panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491846	Ground	COLW01000672 / 673 - electrical cupboard H2 053	1	Yes	fire break panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491847	Ground	COLW01000672 / 673 - A1 060	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491848	Ground	COLW01000672 / 673 - A4A 061	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491849	Ground	COLW01000672 / 673 - B2 062	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491615	Ground	COLW01000621 / 622 - Staircase 3 - top of landing	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491616	Ground	COLW01000621 / 622 - Cleaners cupboard next to WC4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491617	Ground	COLW01000621 / 622 - Utility Room 43 (off corridor	1	Yes	panel to ceiling in	Amosite and Chrysotile	Monitor	6 Low	0 N/A
	2491618	Ground	COLW01000621 / 622 - Drying Room (off corridor 2)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491619	Ground	COLW01000621 / 622 - DOE Room (off corridor 2)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491620	Ground	COLW01000621 / 622 - Cleaners Cupboard (next to WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491621	Ground	COLW01000621 / 622 - Room 120	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491622	Ground	COLW01000621 / 622 - Room 121	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491623	Ground	COLW01000621 / 622 - Room 122	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491624	Ground	COLW01000621 / 622 - Room 123	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491625	Ground	COLW01000621 / 622 - WC 44 off corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491626	Ground	COLW01000621 / 622 - Room 124	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491627	Ground	COLW01000621 / 622 - Room 125	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
$  \uparrow \uparrow \uparrow  $	2491628	Ground	COLW01000621 / 622 - Room 126	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
$\Box$	2491629	Ground	COLW01000621 / 622 - Room 127	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	Defe			Regiona	al Prime	Contra	ct Central			
The state of the s	Infra Orga	structure anisation				sRegis			carillion	mey
	2491630	Ground	COLW01000621 / 622 - Room 128	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
H	2491631	Ground	COLW01000621 / 622 - Room 129	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2491632	Ground	COLW01000621 / 622 - Room 130	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2491633	Ground	COLW01000621 / 622 - Room 131	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491634	Ground	COLW01000621 / 622 - Room 132	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
П	2491635	Ground	COLW01000621 / 622 - Room 133	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491636	Ground	COLW01000621 / 622 - WC 45 off corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491637	Ground	COLW01000621 / 622 - Baggage store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491638	Ground	COLW01000621 / 622 - Cleaners Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491639	Ground	COLW01000621 / 622 - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491640	Ground	COLW01000621 / 622 - Room 134	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491641	Ground	COLW01000621 / 622 - Room 135	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491642	Ground	COLW01000621 / 622 - Room 136	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
	2491760	Ground	COLW01000621 / 622 - Drying Room - Utility 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491761	Ground	COLW01000621 / 622 - Electrical Switch Cupboard	1	No	throughout		No Action	0 No Risk	0 N/A
	2491762	Ground	COLW01000621 / 622 - Cabin 14	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491763	Ground	COLW01000621 / 622 - Cabin 15	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491764	Ground	COLW01000621 / 622 - Cabin 16	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491765	Ground	COLW01000621 / 622 - Cabin 17	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491766	Ground	COLW01000621 / 622 - Cleaner Cupboard	1		board in recess in	Amosite	Monitor	6 Low	0 N/A
	2491767	Ground	COLW01000621 / 622 - Cabin 19	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491768	Ground	COLW01000621 / 622 - Cabin 18	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491769	Ground	COLW01000621 / 622 - Cabin 20	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491770	Ground	COLW01000621 / 622 - Cabin 21	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491771	Ground	COLW01000621 / 622 - Cabin 23	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491772	Ground	COLW01000621 / 622 - Cabin 22	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence	Re	egiona	al Primo	e Contra	act Central			
	astructure anisation				osReais			carillion	amey
2491773	Ground	COLW01000621 / 622 - Cabin 25	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491774	Ground	COLW01000621 / 622 - Cabin 24	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491775	Ground	COLW01000621 / 622 - Cabin 26	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491776	Ground	COLW01000621 / 622 - Store (A10)	1	No	Pipe Void		No Action	0 No Risk	0 N/A
2491777	Ground	COLW01000621 / 622 - WC 9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491778	Ground	COLW01000621 / 622 - Cabin 27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491779	Ground	COLW01000621 / 622 - Glass Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491780	Ground	COLW01000621 / 622 - A 32	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491781	Ground	COLW01000621 / 622 - Cabin 139	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491782	Ground	COLW01000621 / 622 - Cabin 139 WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491783	Ground	COLW01000621 / 622 - Cabin 138	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491784	Ground	COLW01000621 / 622 - Cabin 138 WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491785	Ground	COLW01000621 / 622 - A 33	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491786	Ground	COLW01000621 / 622 - Cabin 140	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491787	Ground	COLW01000621 / 622 - Cabin 140 WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491788	Ground	COLW01000621 / 622 - Cabin 141	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491789	Ground	COLW01000621 / 622 - Cabin 141 WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491585	Ground	COLW01000621 / 622 - Refuse Room	1	Yes	flue to refuse	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2491586	Ground	COLW01000621 / 622 - Cleaners Cupboard next to WC3	1	Yes	panel in recess	Amosite and Chrysotile	Monitor	6 Low	0 N/A
2491587	Ground	COLW01000621 / 622 - Loft - access through baggage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491588	Ground	COLW01000621 / 622 - Cleaners Cupboard (next to WC	1	Yes	panel in recess	Amosite and Chrysotile	Monitor	6 Low	0 N/A
2491589	Ground	COLW01000621 / 622 - External Roof Link	1	Yes	Roof Slates	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491590	Ground	COLW01000621 / 622 - WC 39 on Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491591	Ground	COLW01000621 / 622 - Room 102	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A

	ence	F	Regiona	al Prime	e Contra	ct Central			
Infra Orga	structure				osReais			carilliona	mey
2491592	Ground	COLW01000621 / 622 - Room 103	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491593	Ground	COLW01000621 / 622 - Room 104	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491594	Ground	COLW01000621 / 622 - Room 105	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491595	Ground	COLW01000621 / 622 - Room 106	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491596	Ground	COLW01000621 / 622 - Room 107	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491597	Ground	COLW01000621 / 622 - Room 108	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491598	Ground	COLW01000621 / 622 - Room 109	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491599	Ground	COLW01000621 / 622 - Room 110	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491600	Ground	COLW01000621 / 622 - Room 111	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491601	Ground	COLW01000621 / 622 - Room 112	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491602	Ground	COLW01000621 / 622 - Room 113	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491603	Ground	COLW01000621 / 622 - Room 114	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491604	Ground	COLW01000621 / 622 - Room 115	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491605	Ground	COLW01000621 / 622 - WC 40	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491606	Ground	COLW01000621 / 622 - Utility Room 41 (off corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491607	Ground	COLW01000621 / 622 - Corridor 4	1	Yes	ceiling		No Action	0 No Risk	0 N/A
2491608	Ground	COLW01000621 / 622 - Staircase 6 - Top of Landing	1	Yes	side of stairs at top of	Chrysotile	Monitor	3 Very Low	0 N/A
2491609	Ground	COLW01000621 / 622 - Staircase 4 - top of landing	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491610	Ground	COLW01000621 / 622 - Room 116	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491611	Ground	COLW01000621 / 622 - Room 117	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491612	Ground	COLW01000621 / 622 - WC 42	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491613	Ground	COLW01000621 / 622 - Room 118	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2491614	Ground	COLW01000621 / 622 - Room 119	1	Yes	ceiling	Chrysotile	Monitor	3 Very Low	0 N/A
2488649	Ground	COLW01000725 - Outdoor Building Area of Pitch	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488660	Ground	COLW01000697 - VSF Hut	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488661	Ground	COLW01000698 - VSF Hut	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488664	Ground	COLW01000677 - Chilled Water Section	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488665	Ground	COLW01000685 - Gas House	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488667	Ground	COLW01000688 - Pipe Intake (Internal)	1	Yes	Pipe Near Door	Chrysotile	Monitor	6 Low	0 N/A

	Defe		R	egiona	al Prime	e Contra	act Central	•		
The state of the s	Orga	structure anisation			Ashesto	osReais	ter		carillion	amey
	2488668	Ground	COLW01000688 - Pipe Intake (Internal)	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488669	Ground	COLW01000689 - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489754	Ground	COLW01000666 / 667 - Undercroft / Duct	1	Yes	Expansion Bellows	Chrysotile	Monitor	4 Very Low	0 N/A
	2489755	Ground	COLW01000666 / 667 - Undercroft / Duct	1	Yes	Pipework Flanges	Chrysotile	Monitor	4 Very Low	0 N/A
	2489756	Ground	COLW01000666 / 667 - Undercroft / Duct	1	Yes	Pipework Under	Presumed Asbestos Content	Control Access	12 Medium	0 N/A
	2489757	Ground	COLW01000666 / 667 - Undercroft / Duct	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489758	Ground	COLW01000666 / 667 - Undercroft / Duct 101A	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489759	Ground	COLW01000666 / 667 - Undercroft / Duct 101A	1	Yes	Duct Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489760	Ground	COLW01000666 / 667 - Undercroft / Duct 101B	1	Yes	Duct Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489761	Ground	COLW01000666 / 667 - Undercroft / Duct 101B	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488648	Ground	COLW01000725 - Mini Indoor Football Pitch	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491938	Ground	COLW01000674 / 675 / 676 - S15A 033	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491939	Ground	COLW01000674 / 675 / 676 - S15A 033	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491940	Ground	COLW01000674 / 675 / 676 - S18 036	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491941	Ground	COLW01000674 / 675 / 676 - S18 036	1	Yes	window reveal and	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491942	Ground	COLW01000674 / 675 / 676 - S16 035	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491943	Ground	COLW01000674 / 675 / 676 - S16 035	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491944	Ground	COLW01000674 / 675 / 676 - S15B 034	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491945	Ground	COLW01000674 / 675 / 676 - S15B 034	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2491946	Ground	COLW01000674 / 675 / 676 - S17C 049	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2491947	Ground	COLW01000674 / 675 / 676 - S17B 050	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2491948	Ground	COLW01000674 / 675 / 676 - S17A 051	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491949	Ground	COLW01000674 / 675 / 676 - S17E 052	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		F	Regiona	l Prime	e Contra	ct Central	•		
ALIEN .	Orga	structure anisation			Asbest	osReais	ter		carillion	amey
	2491950	Ground	COLW01000674 / 675 / 676 - S17D 053	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491951	Ground	COLW01000674 / 675 / 676 - S17 054	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491952	Ground	COLW01000674 / 675 / 676 - E4 055	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491953	Ground	COLW01000674 / 675 / 676 - corridor 079	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491954	Ground	COLW01000674 / 675 / 676 - E8A 080	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491955	Ground	COLW01000674 / 675 / 676 - E12A 068	1	Yes	panels to windows	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491956	Ground	COLW01000674 / 675 / 676 - S19 037	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491957	Ground	COLW01000674 / 675 / 676 - corridor 083	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491958	Ground	COLW01000674 / 675 / 676 - corridor 083	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491959	Ground	COLW01000674 / 675 / 676 - corridor 084	1	Yes	Pipework in Ceiling Void	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491960	Ground	COLW01000674 / 675 / 676 - porch 085	1	Yes	Firebreaks	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491961	External	COLW01000674 / 675 / 676 - External	1	Yes	Canopies	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488582	Ground	COLW01000720 - Barrier Control Hut	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488583	External	COLW01000720 - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488584	Ground	COLW01000721 - Sentry Box	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491879	Ground	COLW01000672 / 673 - B3A 071	1	Yes	panels to door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491880	Ground	COLW01000672 / 673 - G47A 112	1	Yes	panels to ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491881	Ground	COLW01000672 / 673 - G47A 112	1	Yes	Debris below	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491882	Ground	COLW01000672 / 673 - D10A 111	1	Yes	fire break	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491883	External	COLW01000672 / 673 - External	1	Yes	Canopies	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491884	First	COLW01000674 / 675 / 676 - stairs 105	1	No	Skylight		No Action	0 No Risk	0 N/A
	2491885	First	COLW01000674 / 675 / 676 - corridor windows 118	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491886	First	COLW01000674 / 675 / 676 - stairs windows 119	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A

		ence	F	Regiona	al Primo	e Contra	act Central		<u>*</u>	
	Infra Orga	astructure anisation				osReais			carillio	n amev
	2491887	First	COLW01000674 / 675 / 676 - stairs	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
			windows 125			(Seals)				
	2491888	Ground	COLW01000674 / 675 / 676 - hall	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
			windows 001			(Seals)				
	2491889	Ground	COLW01000674 / 675 / 676 -	1	Yes	Amplifier	Presumed Asbestos	Monitor	4 Very Low	0 N/A
	0.404.000		G13/G14 005	4		Units	Content	14 %	4 1/4 1	0.11/4
	2491890	Ground	COLW01000674 / 675 / 676 - lobby windows 009	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
+++	2491891	Ground	COLW01000674 / 675 / 676 - G10 008	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
	2431031	Ground	COEW010000747 0737 070 - G10 000	ı	163	Switchgear	Content	IVIOTITO	4 Very Low	U IV/A
HH	2491892	Ground	COLW01000674 / 675 / 676 - S9 029	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2101002	O. Garra	00211010000117 0707 070 00 020	·		(Seals)		le.		011,71
	2491893	Ground	COLW01000674 / 675 / 676 - S10 030	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
						(Seals)				
	2491894	Ground	COLW01000674 / 675 / 676 -	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
			S11/S11A 031			(Seals)				
	2491895	Ground	COLW01000674 / 675 / 676 - S14 032	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
HH	0.404.000		001740400024 / 075 / 070 0454		\ <u>'</u>	(Seals)	01 (1)	14 1	4 1/4	0.11/4
	2491896	Ground	COLW01000674 / 675 / 676 - S15A 033	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
+++	2491897	Ground	COLW01000674 / 675 / 676 - S18 036	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2491097	Ground	COEW010000747 0737 070 - 318 030		163	(Seals)	Crirysotile	IVIOTITO	4 Very Low	U IV/A
	2491898	Ground	COLW01000674 / 675 / 676 - S16 035	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
				·		(Seals)				
	2491899	Ground	COLW01000674 / 675 / 676 - S15B	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
			034			(Seals)				
	2491900	Ground	COLW01000674 / 675 / 676 - E2 058	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
						(Seals)				
	2491901	Ground	COLW01000674 / 675 / 676 - E1 057	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
HH	0404000	Cravinad	COLWO4000074 / 075 / 070		Vaa	(Seals)	Characa tila	Manitan	4)/2711711	O N1/A
	2491902	Ground	COLW01000674 / 675 / 676 - E7 061	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
+++	2491903	Ground	COLW01000674 / 675 / 676 - E8 062	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2401000	Ground	002707070707070707070707070707070707070		103	(Seals)	Ornysome	Widthio	Very Low	014//(
HH	2491904	Ground	COLW01000674 / 675 / 676 - E13 063	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
						(Seals)				
	2491905	Ground	COLW01000674 / 675 / 676 - E14 064	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
						(Seals)				
	2491906	Ground	COLW01000674 / 675 / 676 - E15 066	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
						(Seals)				
	2491907	Ground	COLW01000674 / 675 / 676 - E17 071	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
	2404000	Cround	COLW04000674 / 675 / 670 - 500 674		V	Ciple	Chrygotile	Monitor	2 Mary Law	O N1/A
	2491908	Ground	COLW01000674 / 675 / 676 - E20 074	1	Yes	Sink	Chrysotile	Monitor	3 Very Low	0 N/A
++	2491909	Ground	COLW01000674 / 675 / 676 - E24 059	1	Yes	Windows	Chrysotile	Monitor	4 Very Low	0 N/A
	2101000		552.75.75357.17.6757.676	'		(Seals)			l ory Low	J 14// (
					1	, ,	1			

		ence	R	egiona	al Prime	e Contra	act Central			
diame	Infra Orga	astructure anisation				osReais			carillion	amey
	2491910	Ground	COLW01000674 / 675 / 676 - E25 060	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491911	Ground	COLW01000674 / 675 / 676 - E16 082	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491912	Ground	COLW01000674 / 675 / 676 - porch 085	1	Yes	Pipework	Chrysotile	Monitor	4 Very Low	0 N/A
П	2491913	Ground	COLW01000674 / 675 / 676 - porch 085	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2491914	First	COLW01000674 / 675 / 676 - F15 101	1	Yes	fire break over doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491915	First	COLW01000674 / 675 / 676 - F14 102	1	Yes	fire break over doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491916	First	COLW01000674 / 675 / 676 - stairs 105	1	Yes	Ceiling and High Level	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491917	First	COLW01000674 / 675 / 676 - F10 114	1	Yes	fire break over doors	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491918	First	COLW01000674 / 675 / 676 - corridor 118	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491919	First	COLW01000674 / 675 / 676 - stairs 119	1	Yes	Ceiling and High Level	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491920	First	COLW01000674 / 675 / 676 - stairs 119	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491921	First	COLW01000674 / 675 / 676 - stairs 125	1	Yes	Ceiling and High Level	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491922	First	COLW01000674 / 675 / 676 - F11 115	1	Yes	Hatch	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491923	Ground	COLW01000674 / 675 / 676 - hall 001	1	Yes	Ceiling, Beams and	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491924	Ground	COLW01000674 / 675 / 676 - stairs 119	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491925	Ground	COLW01000674 / 675 / 676 - G13/G14 005	1	Yes	Wall Tiles	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491926	Ground	COLW01000674 / 675 / 676 - lobby 009	1	Yes	Ceiling and firebreak	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491927	Ground	COLW01000674 / 675 / 676 - G1A 021	1	Yes	Ceiling and firebreak	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491928	Ground	COLW01000674 / 675 / 676 - stairs 119	1	Yes	beading to fire door	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491929	Ground	COLW01000674 / 675 / 676 - corridor 028	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491930	Ground	COLW01000674 / 675 / 676 - S9 029	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491931	Ground	COLW01000674 / 675 / 676 - S9 029	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491932	Ground	COLW01000674 / 675 / 676 - S10 030	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation		Regional Prime Contract Central AsbestosRegister							
									carillion	carillionamey
24	91933	Ground	COLW01000674 / 675 / 676 - S10 030	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	91934	Ground	COLW01000674 / 675 / 676 - S11/S11A 031	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	91935	Ground	COLW01000674 / 675 / 676 - S11/S11A 031	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	91936	Ground	COLW01000674 / 675 / 676 - S14 032	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	91937	Ground	COLW01000674 / 675 / 676 - S14 032	1	Yes	window reveal	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88710	Ground	COLW01000693 - Liverpool Road Sentry Box	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88711	Ground	COLW01000695 - Liverpool Road Search Kiosk	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88712	Ground	COLW01000696 - MTHW Valve Pit 25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88568	Ground	COLW01000717 - Dog Kennels	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
IMS CC	DLLINGW	I OOD - SLA AN	ID SFA GARAGES - 707964 - COLW0100	0184		<u> </u>	1			
24	87139	Ground	SLA and SFA Garages	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
IMS CC	DLLINGW	OOD - SMALL	ARMS RANGE 30 METRES - 707983 - C	OLW01XSA	001		•	•	-	
249	91990	Ground	Outdoor Range	1	Yes			No Action	0 No Risk	0 N/A
IMS CC	DLLINGW	OOD - SONAR	BUILDING TRAINING TYPE 22 PLATFO	RM WEAPO	N EN - 7080	D23 - COLW010	000529	<u> </u>	<u> </u>	I
24	87214	Ground	Offices - Toilet	1	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
						Cladding				
24	87215	Ground	Offices - Plant Room	1	Yes	Cables	Presumed Asbestos	Monitor	6 Low	0 N/A
24	87216	First	Offices - Room 20	1	Yes	(Wraps) Electrical	Content Presumed Asbestos	Monitor	6 Low	0 N/A
240	0/210	FIISt	Offices - Rooffi 20	I	162	Switchgear	Content	Monitor	Low	U N/A
IMS CC	DLLINGW	OOD - SOUTH	ERN CLUB JUNIOR RANKS / SHOPPING	G ARCADE -	708044 - C				<u> </u>	
248	89305	Ground	Coasters Club - Stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89306	Ground	Coasters Club - West Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89307	Ground	Coasters Club - Stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89308	Ground	Coasters Club - East Stairwell	1	Yes	Panels to	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89309	Ground	Coasters Club - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89310	Ground	Coasters Club - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	89311	Ground	Coasters Club - Laundrette	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

1	Defe			Regiona	al Prime	e Contra	act Central			
	Orga	structure anisation			\shest	osReais	ter		carillion	amev
	2489312	Ground	Coasters Club - Hair Salon	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489313	Ground	Coasters Club - Store Inside Hair Salon	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489314	Ground	Coasters Club - Spar Shop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489315	Ground	Coasters Club - Post Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489316	Ground	Coasters Club - Spar Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489317	Ground	Coasters Club - Spar Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489318	Ground	Coasters Club - Spar Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489319	Ground	Coasters Club - Spar Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489320	Ground	Coasters Club - Shop 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489321	Ground	Coasters Club - Shop 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489322	Ground	Coasters Club - Service Duct	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489323	Ground	Coasters Club - Shop 4 and Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489324	Ground	Coasters Club - Shop 3 and Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489325	Ground	Coasters Club - Launderette Duct 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489326	Ground	Coasters Club - Launderette Duct 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489327	Ground	Coasters Club - Store Next To Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489328	Ground	Coasters Club - Plant Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489329	Ground	Coasters Club - Shop 4 - Cafe Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2489330	Ground	Coasters Club - Game Zone	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489331	Ground	Coasters Club - Main Canteen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489332	Ground	Coasters Club - Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489333	Ground	Coasters Club - Foyer	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489334	Ground	Coasters Club - West Stairs	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		R	egiona	d Prime	e Contra	ct Central			
	) Infra Orga	structure				osReais			carillion	amey
2	489335	Ground	Coasters Club - Cleaners Cupboard at Top of Stairs	1	Yes	panel to inside wall		No Action	0 No Risk	0 N/A
2	489336	Loft	Coasters Club - Loft Tank Room above West Stairwel	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489337	Ground	Coasters Club - West Foyer	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489338	Ground	Coasters Club - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489339	Ground	Coasters Club - Internet Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489340	Ground	Coasters Club - TV Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489341	Ground	Coasters Club - Snooker Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489342	Ground	Coasters Club - East Foyer	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489343	Ground	Coasters Club - Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489344	Ground	Coasters Club - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489345	Ground	Coasters Club - East Stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489346	Ground	Coasters Club - Mini Office (CCTV)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489347	Ground	Coasters Club - Jack Snacks - Shop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489348	Ground	Coasters Club - Jack Snacks - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489349	Ground	Coasters Club - Jack Snacks - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489350	Ground	Coasters Club - Jack Snacks - Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489351	Ground	Coasters Club - Jack Snacks - Store room	1	Yes	Floor (Red Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
2	489352	Ground	Coasters Club - Jack Snacks - Pipe Risers	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	489353	Ground	Coasters Club - Jack Snacks - Service Lift Next to	1	Yes	Panel to top of service lift	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2	489354	Loft	Coasters Club - Jack Snacks - loft area Above Kitc	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS C	OLLINGW	<u> </u>  OOD - SPORT	S CHANGING ROOMS NO3 - PORTAKABI	IN - 708116	- COLW010	<u> </u>	<u> </u>			
		Ground	Archery Club / Changing Room - Main Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	488586	Ground	Archery Club / Changing Room - Gents Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	488587	Ground	Archery Club / Changing Room - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	Re	giona	I Prim	e Contra	act Central			A
1	Org	astructure anisation				tosReais			carillion	1 amey
	2488588	Ground	Archery Club / Changing Room - Archery Store	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488589	Roof	Archery Club / Changing Room - Roof	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмя	S COLLING	WOOD - SPORT	S HALL - 1249001 - COLW04000780	<u> </u>			<u> </u>			
	2487450	Ground	Sports Pavilion	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	S COLLING	WOOD - STORE	- 708003 - COLW01000285	•			•	•	•	•
	2488835	Ground	Fisher Gymnasium - Corridor	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488836	Ground	Fisher Gymnasium - Store 1 & 2 roof void	1	Yes	Roof Sheets	Presumed Asbestos Content	Monitor	8 Low	0 N/A
	2488837	Ground	Fisher Gymnasium - corridor 1 roof void	1	Yes	Roof Sheets	Presumed Asbestos Content	Monitor	8 Low	0 N/A
	2488838	Ground	Fisher Gymnasium - shower room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488839	Ground	Fisher Gymnasium - main Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488840	Roof	Fisher Gymnasium - External Roof	1	Yes	Roof Sheets	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2488841	Ground	Fisher Gymnasium - Store 2	1	Yes	Floor (Grey Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488842	Ground	Fisher Gymnasium - Archery Club	1	Yes	Floor (Orange	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488843	Ground	Fisher Gymnasium - Archery Club	1	Yes	Floor (Yellow	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488844	Ground	Fisher Gymnasium - Store 3	1	Yes	Floor (Grey Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488845	Ground	Fisher Gymnasium - Store 4	1	Yes	Floor (Grey Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488832	Ground	Fisher Gymnasium - Foyer	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488833	Ground	Fisher Gymnasium - Toilets	1	Yes	toilet cistern	Chrysotile	Monitor	5 Low	0 N/A
	2488834	Ground	Fisher Gymnasium - Store 1	1	Yes	Floor (Dark Brown Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
нмѕ	S COLLING	WOOD - STORE	- 745947 - COLW01000756				•	-	•	<u> </u>
	2488655	Ground	RNSLA Shed	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS	COLLING	WOOD - STORE	(BM) - 711068 - COLW01000496						<u> </u>	
	2487194	Ground	Store House - Toilet	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
	2487195	Ground	Store House - Store	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
	2487196	Ground	Store House - Entrance Lobby	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
	2487197	Ground	Store House - Kitchen	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure				osReais			carillion	amey
		Ground	Store House - Rest Room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2487199	Ground	Store House - Workshop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487200	Ground	Store House - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2487201	External	Store House - External	1	Yes	Electrical		No Action	0 No Risk	0 N/A
НМ	S COLLINGW	OOD - STORE	HOUSE - NON SPECIALISED MATERIE	L - 707947 - 0	COLW010001	161				
	2491998	Ground	The Green Room - Boiler Room	1	Yes	Floor	Chrysotile	Remove	8 Low	1 m2
	2488737	Ground	The Green Room - Lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488738	Ground	The Green Room - Green Room	1	Yes	Ceiling Panels	Presumed Asbestos Content	Monitor	8 Low	0 N/A
	2488739	Ground	The Green Room - Green Room	1	Yes	Roof Void	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488740	Ground	The Green Room - Bar	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488741	Ground	The Green Room - Bar	1	Yes	Roof Void	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488742	Ground	The Green Room - Boiler Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488743	Ground	The Green Room - Boiler Room	1	Yes	Strips/panel s to roof and	Presumed Asbestos Content	Monitor	8 Low	0 N/A
	2488744	Ground	The Green Room - Switch Room	1	Yes	firebreak at high level	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488745	Ground	The Green Room - Switch Room	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	6 Low	0 N/A
	2488746	Roof	The Green Room - Roof	1	Yes	roof sheeting	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488747	Roof	The Green Room - Roof	1	Yes	roof sheeting	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488748	Ground	The Green Room - Boiler Room	1	Yes	high level fire break	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488749	Ground	The Green Room - Boiler Room	1	Yes	roof lining		No Action	0 No Risk	0 N/A
	2488750	Loft	The Green Room - A01 Loft Area	1	Yes	Rafters & top of walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488751	Loft	The Green Room - A01 Loft Area	1	Yes	loft partition wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488752	Loft	The Green Room - A02 Loft Area	1	Yes	roof space partition wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488753	Ground	The Green Room - Switch Room	1	No	Floor Ducts		No Action	0 No Risk	0 N/A
HMS	S COLLINGW	OOD - SUBST	ATION A - 707963 - COLW01000188							
	2488715	Ground	Substation A - Distribution 415 VAC	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
	Infra Orga	structure				osRegis			carillio	n amey 🔪
24		Ground	Substation A - Rectifier Room	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
24	88717	Ground	Substation A - Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88718	Ground	Substation A - Transformer Room	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
24	88719	Ground	Substation A - Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88720	Ground	Substation A - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88721	Ground	Substation A - Intake A	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	88722	Ground	Substation A - Transformer supply	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	88723	Ground	Substation A - Substation Main Intake (60hrz)	1	Yes	Ceiling	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	88724	Ground	Substation A - Substation Main Intake (60hrz)	1	Yes	vertical panels to	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	88725	Ground	Substation A - Distribution 415 VAC	1	No	Floor Voids		No Action	0 No Risk	0 N/A
24	88726	Ground	Substation A - Rectifier Room	1	No	Floor Voids		No Action	0 No Risk	0 N/A
		Ground	Substation A - Transformer Room	1	No	Floor Voids		No Action	0 No Risk	0 N/A
HMS CC	DLLINGW	OOD - SUBST	ATION B - 707962 - COLW01000189							
24	87142	Ground	Substation B - LV Bay	1	Yes	Ceiling Tiles	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	87143	Ground	Substation B - HV Bay	1	Yes	Ceiling Tiles	Presumed Asbestos Content	Monitor	8 Low	0 N/A
24	87144	Ground	Substation B - External Transformer	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	87145	Ground	Substation B - LV and HV Bays	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
24	87146	Ground	Substation B - LV and HV Bays	1	No	Floor Voids		No Action	0 No Risk	0 N/A
HMS CC	DLLINGW	OOD - SUBST	ATION C - 708031 - COLW01000502				ı	1		<u>I</u>
24	88903	Ground	Substation C - Gas intake room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88904	Ground	Substation C - rear compound (external AC compound	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88905	Ground	Substation C - LV room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88906	Ground	Substation C - HV room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	88907	Ground	Substation C - Adjacent to LV	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS CC	DLLINGW	OOD - SUBST	ATION D - 708106 - COLW01000716		<u> </u>	l	1	<u> </u>	<u> </u>	

	ence		Regiona	al Prime	e Contra	act Central		<u>**</u>	
Org	astructure janisation			Asbest	osReais	ster		carillion	ı amey 🥍
2488566	Ground	Substation D - HV Bay	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488567	Ground	Substation D - LV Bay	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
HMS COLLING	WOOD - SUBST	ATION E - 707961 - COLW01000191				l .			
2487147	Ground	Substation E - 415 V-AC	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2487148	Ground	Substation E - 415 V-AC	1	Yes	Ceiling Tiles	Amosite	Monitor	8 Low	0 N/A
2487149	Ground	Substation E - 11,000 V-AC	1	Yes	Ceiling Tiles	Amosite	Monitor	8 Low	0 N/A
2487150	Ground	Substation E - 11,000 V-AC	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2487151	Roof	Substation E - Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487152	Ground	Substation E - 415 V-AC	1	No	Floor Voids		No Action	0 No Risk	0 N/A
2487153	Ground	Substation E - 11,000 V-AC	1	No	Floor Voids		No Action	0 No Risk	0 N/A
HMS COLLING	<u> </u>	L ATION F - 707960 - COLW01000192			1	<u> </u>		<u> </u>	
2488736	Ground	Substation F - Bay 1	1	No	Floor Voids		No Action	0 No Risk	0 N/A
2488728	Ground	Substation F - Bay 1	1	Yes	Ceiling Tiles	Amosite	Monitor	8 Low	0 N/A
2488729	Ground	Substation F - Bay 1	1	Yes	Ceiling	Amosite	Monitor	8 Low	0 N/A
2488730	Ground	Substation F - Bay 1	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488731	Ground	Substation F - Bay 2	1	Yes	Ceiling Tiles	Amosite	Monitor	8 Low	0 N/A
2488732	Ground	Substation F - Bay 2	1	Yes	Ceiling	Amosite	Monitor	8 Low	0 N/A
2488733	Ground	Substation F - Bay 2	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2488734	Roof	Substation F - Roof	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488735	Ground	Substation F - Bay 2	1	No	Floor Voids		No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - SUBST	ATION H - 707974 - COLW01000194							
2487155	Ground	Substation H	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	WOOD - SUBST	ATION J - 708062 - COLW01000637		I		•			
2489593	Ground	Substation J - MV Room	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2489594	Ground	Substation J - HV Room	1	No	Floor Voids		No Action	0 No Risk	0 N/A
2489595	Ground	Substation J - External Transformer 1	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2489596	Ground	Substation J - External Transformer 2	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
HMS COLLING	WOOD - SUBST	ATION L - 708061 - COLW01000638			•	•	•		
2489597	Ground	Substation L - HV Bay	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
				l .		1			

	ence astructure	F				act Central			A
Org	anisation	<u> </u>			<u>osReais</u>		_	———carillion	ıamey⊁
2489598	Ground	Substation L - LV Bay	1	Yes	Electrical Plant	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
MS COLLING	WOOD - TELEPI	HONE EXCHANGE - 708046 - COLW0100	00617						
2489297	Ground	Telephone Exchange - Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489298	Ground	Telephone Exchange - Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489299	Ground	Telephone Exchange - Main Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489300	Ground	Telephone Exchange - Entrance	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489301	Ground	Telephone Exchange - Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489302	Ground	Telephone Exchange - Screened Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489303	Ground	Telephone Exchange - External Compound	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489304	Ground	Telephone Exchange - Electrical Distribution Equip	1	Yes	Arc Shields		No Action	0 No Risk	0 N/A
MS COLLING	WOOD - THEAT	RE STORE - 708130 - COLW01000726					<u> </u>		l
2488650	Ground	Theatre Store - Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488651	Roof	Theatre Store - Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
I VIS COLLING	WOOD - TRANS		COLW0100	0645		1			
2487221	Ground	Offices - Kitchen	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487222	Ground	Offices - East Locker Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487223	Ground	Offices - South Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487224	Ground	Offices - Corridor	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
2487225	Ground	Offices - Gentlemans Toilet	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
2487226	Ground	Offices - Gentlemans Toilet	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
2487227	Ground	Offices - Ladies Toilet	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
2487228	Ground	Offices - Ladies toilet	1	Yes	Ceiling	Chrysotile	Monitor	5 Low	0 N/A
2487229	Ground	Offices - Middle Office	1	Yes	Ceiling Void		Monitor	5 Low	0 N/A
2487230	Ground	Offices - Rest Room	1	Yes	Ceiling Void	Chrysotile	Monitor	5 Low	0 N/A
2487231	Ground	Offices - Standby Room	1	Yes	Ceiling Void	Chrysotile	Monitor	5 Low	0 N/A
2487232	Loft	Offices - North Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2487233	Loft	Offices - South Loft	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date: 05/04/2017 08:42:40



## Regional Prime Contract Central AsbestosRegister



Run By:

S COLLINGWO	OOD - VALKYR	IE TRAINING - 708067 - COLW01000630		TORGOG	OSITEMIS				
2490733 F	irst	Valkyrie Block - YSM riser 116	1	Yes	Panel Above	Amosite	Monitor	6 Low	0 N
2490734 F	irst	Valkyrie Block - mezzanine M01 103	1	Yes	Ceiling Tiles	Amosite	Monitor	6 Low	0 N
2490735 F	First	Valkyrie Block - room 103	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N
2490736 F	irst	Valkyrie Block - room 103	1	Yes	Fuses found		Remove	4 Very Low	0 N
2490737 F	First	Valkyrie Block - riser 111	1	Yes	Door Frame	Chrysotile	Monitor	3 Very Low	0 N
2490738 G	Ground	Valkyrie Block - YSM power room 015	1	Yes	Pipework Flanges and	No Asbestos Detected	No Action	0 No Risk	0 N
2490739 G	Ground	Valkyrie Block - YSM riser 016	1	Yes	Pipework Flanges	No Asbestos Detected	No Action	0 No Risk	0 0
2490740 F	irst	Valkyrie Block - lobby 101 into corridor 102	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N
	First	Valkyrie Block - room 113	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	10
2490742 F	First	Valkyrie Block - store 118	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	10
2490743 F	First	Valkyrie Block - mezzanine M01	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10
2490704 F	First	Valkyrie Block - YSM Services	1	Yes	Panel Above	Amosite	Monitor	6 Low	10
2490705 F	First	Valkyrie Block - 1.11 Cleaners Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2490706 F	First	Valkyrie Block - 1.11 VQ Centre Records Room	1	Yes	Insulating Board	No Asbestos Detected	No Action	0 No Risk	10
2490707 F	irst	Valkyrie Block - 1.10	1	Yes	Column in	Amosite	Monitor	6 Low	10
2490708 F	First	Valkyrie Block - 1.06 Seawolf Tracker	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2490709 F	First	Valkyrie Block - 1.06 Protected Compartment	1	Yes	Wall Panels Beneath	Amosite	Monitor	6 Low	0.0
2490710 F	First	Valkyrie Block - 1.06 Protected Compartment Mezani	1	Yes	Walls and Ceiling	Amosite	Monitor	6 Low	10
2490711 F	irst	Valkyrie Block - Mens Toilets (trainees)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2490712 F	irst	Valkyrie Block - Womens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2490713 F	First	Valkyrie Block - Compressed Air Red Valve	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10
2490714 F	First	Valkyrie Block - 105 Classroom	1	Yes	Firebreak	Amosite	Monitor	6 Low	10
	Ground / First	Valkyrie Block - South Stairwell 1st & g/f	1	Yes	Panels Above Door	Amosite	Monitor	6 Low	10
2490716 F	irst	Valkyrie Block - Corridor - Door to South Stairwel	1	Yes	Panel Above Door	Amosite	Monitor	6 Low	10
2490717 F	First	Valkyrie Block - Electrical Intake Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10

Page:

	Defe		F	Regiona	al Prime	e Contra	act Central	•	<u>**</u>	
	Orga	structure anisation			Asbesto	osReais	ster		carillion	amey 🥍
249	90718	Ground	Valkyrie Block - DOE Power Room	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90719	First	Valkyrie Block - room 106 & Mezzanine	1	Yes	wall & boxing	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90720	Ground	Valkyrie Block - Room G07 CACS Suite	1	Yes	wall & boxing	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90721	First	Valkyrie Block - room 106 & Mezzanine	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
249	90722	First	Valkyrie Block - compressed airred valve duct	1	Yes	Door Frame (Packer)	Chrysotile	Monitor	3 Very Low	0 N/A
249	90723	Ground	Valkyrie Block - lobby/stairwell 001	1	Yes	Firebreak Panel Above	Amosite	Monitor	6 Low	0 N/A
249	90724	Ground	Valkyrie Block - corridor 002	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90725	Ground	Valkyrie Block - DOE power room 014	1	Yes	Pipework Flanges and	Chrysotile	Monitor	4 Very Low	0 N/A
249	90726	Ground	Valkyrie Block - YSM power room 015	1	Yes	Panel Above Door Within		Monitor	6 Low	0 N/A
249	90727	Ground	Valkyrie Block - YSM power room 015	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
249	90728	First	Valkyrie Block - winch lobby 101	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90729	First	Valkyrie Block - corridor 102	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90730	Roof	Valkyrie Block - Roof Plant Room R01	1	No			No Action	0 No Risk	0 N/A
249	90731	Roof	Valkyrie Block - Roof R02	1	Yes	Promenade	Chrysotile	Monitor	4 Very Low	0 N/A
249	90732	First	Valkyrie Block - room 115	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
249	90674	Ground	Valkyrie Block - Reception	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90675	Ground	Valkyrie Block - Reception	1	Yes	Pipe Riser	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90676	Ground	Valkyrie Block - Electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90677	Ground	Valkyrie Block - Office G02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90678	Ground	Valkyrie Block - office G01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90679	Ground	Valkyrie Block - Office G03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
249	90680	Ground	Valkyrie Block - Office G04	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90681	Ground	Valkyrie Block - Office G05	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90682	Ground	Valkyrie Block - Office G06	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90683	Ground	Valkyrie Block - Corridor	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
249	90684	Ground	Valkyrie Block - Corridor to Kitchen	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	F	Regiona	al Prim	e Contra	ct Central			
	Infra Orga	astructure anisation	-			osReais			carillion	mey
	2490685	Ground	Valkyrie Block - Kitchen	1	Yes	Sink	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
	2490686	Ground	Valkyrie Block - Mens Toilet adjacent to Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490687	Ground	Valkyrie Block - Kitchen	1	Yes	Pipe Riser (Off Kitchen)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490688	Ground	Valkyrie Block - G07 - CACS Suite	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490689	Ground	Valkyrie Block - East Reception near Stairs	1	Yes	Firebreak Panel Above	Amosite	Monitor	6 Low	0 N/A
	2490690	Ground	Valkyrie Block - YSM Services	1	Yes	wall panel flue above	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490691	Ground	Valkyrie Block - YSM Services	1	Yes	Panel Above	Amosite	Monitor	6 Low	0 N/A
	2490692	Ground	Valkyrie Block - G08 - Power Room	1	Yes	Panel Above Door	Amosite	Monitor	6 Low	0 N/A
	2490693	Ground	Valkyrie Block - G10 - Seawolf Launch	1	Yes	Firebreak Panel Above	Amosite	Monitor	6 Low	0 N/A
	2490694	First	Valkyrie Block - East Stairs / lobby	1	Yes	Firebreak	Amosite	Monitor	6 Low	0 N/A
	2490695	First	Valkyrie Block - Corridor at Top of Stairs	1	Yes	Floor (Beige Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490696	First	Valkyrie Block - Block & Tackle Room	1	Yes	Floor (Beige Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490697	First	Valkyrie Block - Block & Tackle Room	1	Yes	Firebreak Panel Above	Amosite	Monitor	6 Low	0 N/A
	2490698	First	Valkyrie Block - 1.12 Seawolf	1	Yes	Ceiling Tiles	Amosite	Monitor	6 Low	0 N/A
$\prod$	2490699	First	Valkyrie Block - 1.12 Mezanine	1	Yes	Ceiling and Steelwork	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
	2490700	First	Valkyrie Block - 112	1	Yes	Wall Panel	Amosite	Monitor	6 Low	0 N/A
$\prod$	2490701	First	Valkyrie Block - 1.10 Seawolf Surveillance	1	Yes	Panel Between	Amosite	Monitor	6 Low	0 N/A
	2490702	First	Valkyrie Block - 107 Operations Room	1	Yes	Panel Between	Amosite	Monitor	6 Low	0 N/A
	2490703	First	Valkyrie Block - 108 Type 22 Operations Room	1	Yes	Wall Panel Behind	Amosite	Monitor	6 Low	0 N/A
HMS	COLLING	VOOD - VERNO	N BUILDING - 708065 - COLW01000632				•	•		
Ш	2490516	First	Vernon Link Building - Corridor	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490517	First	Vernon Link Building - Room 1.09	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490518	First	Vernon Link Building - Room 1.10	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel \uparrow \parallel$	2490519	First	Vernon Link Building - Room 1.11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$   \uparrow \uparrow  $	2490520	First	Vernon Link Building - Room 1.12	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	•		
	Infra Orga	structure anisation				osReais			carillion	amey
24		First	Vernon Link Building - Room 1.13	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90522	First	Vernon Link Building - Room 1.07	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90523	First	Vernon Link Building - Room 1.06 Wash Up	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90524	First	Vernon Link Building - Room 1.08 Coms	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90525	First	Vernon Link Building - Stairwell	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
24	90526	First	Vernon Link Building - Room 1.05 Female WC	1	Yes	Toilet Cistern		No Action	0 No Risk	0 N/A
24	90527	First	Vernon Link Building - Room 1.04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90528	First	Vernon Link Building - Room 1.03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90529	First	Vernon Link Building - Room 1.02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90530	First	Vernon Link Building - Room 1.01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90531	First	Vernon Link Building - Corridor - Steps to 615 Exi	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
24	90532	Roof	Vernon Link Building - Tank room in Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90533	Ground	Vernon Link Building - Stairs	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
24	90534	Ground	Vernon Link Building - Stairs	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90535	Ground	Vernon Link Building - G.04 Wash Up	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90536	Ground	Vernon Link Building - North Exit	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90537	Ground	Vernon Link Building - North Exit	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
24	90538	Ground	Vernon Link Building - G.02 NRTA	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90539	Ground	Vernon Link Building - G.01 Key Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90540	Ground	Vernon Link Building - G.05 ACS	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90541	Ground	Vernon Link Building - 615 Link Lobby External	1	Yes	Ceiling Panels	Amosite	Monitor	6 Low	0 N/A
24	90542	Ground	Vernon Link Building - G.06 Wash Up	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90543	Ground	Vernon Link Building - G.08	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	90544	Ground	Vernon Link Building - G.09	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
Trans.	Infra Orga	structure				osReais			carillion	amey
	The state of the s	Ground	Vernon Link Building - External Links to Bldg 615	1	Yes	Ceiling Panels	Amosite	Monitor	6 Low	0 N/A
	2490546	First	Vernon Link Building - Link corridor to Bldg 615	1	Yes	Windows (Seals)	Chrysotile	Monitor	4 Very Low	0 N/A
	2490547	First	Vernon Link Building - Store F04	1	No	Ceiling Void		No Action	0 No Risk	0 N/A
	2490548	First	Vernon Link Building - Stairs	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
HN	IS COLLINGW	OOD - VERNO	N TRAINING - 708048 - COLW01000615			<u>'</u>			•	
Н	2492005	External	Vernon Block - External	1	Yes	Floor	Chrysotile	Remove	7 Low	1 m2
Ш	2492006	Ground	Vernon Block - Calorifier Room G09 (Electrical Int	1	Yes	Redundant Flash	Chrysotile	Remove	5 Low	1 m2
	2492007	Ground	Vernon Block - Calorifier Room G09	1	Yes	Rope Gasket to	Chrysotile	Monitor	6 Low	1 LM
	2492008	Ground	Vernon Block - Calorifier Room G09	1	Yes	Redundant Gasket	Chrysotile	Remove	5 Low	1 m2
	2489280	Ground	Vernon Block - classroom G06A 032	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489281	Ground	Vernon Block - classroom G06A 032	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489282	Ground	Vernon Block - calorifier & chilled plant room	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489283	Ground	Vernon Block - calorifier & chilled plant room	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489284	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489285	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489286	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489287	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489288	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489289	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489290	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489291	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489292	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489293	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489294	Ground	Vernon Block - chilled plant room 026	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A

154 of 420

	Defe		F	Regiona	al Prime	e Contra	act Central		carillion	
( The second sec		structure anisation				osRegis			carillion	amey
2	2489295	Ground	Vernon Block - chilled plant room 026	1	Yes	Duct	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489296	First	Vernon Block - radar corridor 112	1	No	Secure		No Action	0 No Risk	0 N/A
2	2489250	Ground	Vernon Block - comms room 019	1	Yes	Electrical Plant and	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2489251	Ground	Vernon Block - entrance lobby 020	1	Yes	wooden frame above	Amosite	Monitor	7 Low	0 N/A
2	2489252	Ground	Vernon Block - lobby 020	1	Yes	Floor	Amosite	Monitor	4 Very Low	0 N/A
2	2489253	Ground	Vernon Block - classroom 021	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2489254	Ground	Vernon Block - training room 022	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2489255	Ground	Vernon Block - passage 023	1	Yes	Ceiling Tiles	Amosite	Monitor	6 Low	0 N/A
2	2489256	Ground	Vernon Block - comms 024	1	Yes	Ceiling Tiles	Amosite	Monitor	6 Low	0 N/A
2	2489257	Ground	Vernon Block - comms 024	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2489258	Ground	Vernon Block - comms 024	1	Yes	High Level Heaters	Presumed Asbestos Content	Monitor	5 Low	0 N/A
2	2489259	Ground	Vernon Block - compressor room 025	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
2	2489260	Ground	Vernon Block - 026	1	No			No Action	0 No Risk	0 N/A
2	2489261	Ground	Vernon Block - 027	1	No			No Action	0 No Risk	0 N/A
2	2489262	Ground	Vernon Block - Substation G 028	1	No			No Action	0 No Risk	0 N/A
2	2489263	Ground	Vernon Block - chilled plant room 026	1	Yes	Black Pipe	Amosite	Remove	6 Low	0 N/A
2	2489264	Ground	Vernon Block - chilled plant room 026	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	5 Low	0 N/A
2	2489265	Ground	Vernon Block - chilled plant room 026	1	Yes	Plant Equipment	Presumed Asbestos Content	Monitor	5 Low	0 N/A
2	2489266	First	Vernon Block - utility room 102	1	Yes	timber frame above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489267	First	Vernon Block - WC 103	1	Yes	timber frame above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489268	First	Vernon Block - office 105	1	Yes	timber frame above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489269	First	Vernon Block - store 115	1	Yes	floor, cabinets and	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489270	First	Vernon Block - lobby 001	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489271	Ground	Vernon Block - corridor 017	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489272	Ground	Vernon Block - comms room 019	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489273	Ground	Vernon Block - lobby 020	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defence		Regiona	al Prime	e Contra	act Central		carillion	A-
	nfrastructure Organisation			Asbest	osReais	ster		carillior	amey
24892		Vernon Block - lobby G06B 029	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24892	75 Ground	Vernon Block - lobby G06B 029	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24892	76 Ground	Vernon Block - classroom G06C 030	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24892	77 Ground	Vernon Block - classroom G06C 030	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24892	78 Ground	Vernon Block - lobby G06 031	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24892	79 Ground	Vernon Block - lobby G06 031	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	30 Ground	Vernon Block - DAH Computer Room G08	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	31 Ground	Vernon Block - Display Room G07	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	32 Ground	Vernon Block - Seadart Computer Room G06	1	Yes	Floor (Green Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
24891	33 Ground	Vernon Block - Seadart Display Room	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	34 Ground	Vernon Block - Seadart Housing	1	Yes	Top of Accumulator	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	35 Ground	Vernon Block - Calorifier Room G09	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
24891	36 Ground	Vernon Block - Ikara Instrument Room G05	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	37 Ground	Vernon Block - Ikara Equipment G04	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	38 Ground	Vernon Block - Radar Maintenance Room G03	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	39 Ground	Vernon Block - Seadart Missile Room G02	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	40 Ground	Vernon Block - DAH Electrical Cupboard	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	41 Ground	Vernon Block - Corridor 1	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	42 Ground	Vernon Block - Corridor 1	1	Yes	Floor (Maroon /	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	43 Ground	Vernon Block - Hydraulic Room G27	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	44 Ground	Vernon Block - Ikara Missle Room G01	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	45 Ground	Vernon Block - Launcher G26	1	Yes	Ceiling	Amosite	Monitor	7 Low	0 N/A
24891	46 Ground / First	Vernon Block - South west stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24891	47 Ground	Vernon Block - Passage Way Leading to G01	1	Yes	Ceiling panels / tiles	Amosite	Monitor	7 Low	0 N/A

	Defence Infrastructur Organisation 2489148 Ground		Re	egiona	al Prim	e Contra	act Central			
	Orga	astructure anisation				osReais			carillion	amey
			Vernon Block - Air Conditioning G12	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489149	Ground	Vernon Block - Pump Annex	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489150	Ground	Vernon Block - Annex G11	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489151	Ground	Vernon Block - Chilled Water Plant	1	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489152	Ground	Vernon Block - Seadart Equipment Room G14	1	Yes	Air conditioning	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489153	Ground	Vernon Block - Changing Room G16	1	Yes	Panels Above Door	Amosite	Monitor	7 Low	0 N/A
	2489154	Ground	Vernon Block - G17	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489155	Ground	Vernon Block - G20	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489156	Ground	Vernon Block - G19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489157	Ground	Vernon Block - G25	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489158	Ground	Vernon Block - G22	1	Yes	Air conditioning	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489159	Ground	Vernon Block - G23	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489160	Ground	Vernon Block - G21	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489161	Ground	Vernon Block - G24	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489162	Ground	Vernon Block - Store G15	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HH	2489163	Ground	Vernon Block - Male WC G101	1	Yes	Toilet	Amosite	Monitor	4 Very Low	2 No.
H +	2489164	Ground	Vernon Block - Classroom 102	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
HH	2489165	Ground	Vernon Block - Classroom 103	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
HH	2489166	Ground	Vernon Block - Classroom 103A	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
H +	2489167	Ground	Vernon Block - Classroom 104	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
HH	2489168	Ground	Vernon Block - Classroom 104A	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
HH	2489169	Ground	Vernon Block - Classroom 105	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
	2489170	Ground	Vernon Block - Female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2489171	Ground	Vernon Block - Cleaner 123	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
HH	2489172	Ground	Vernon Block - Classroom 118	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
	2489173	Ground	Vernon Block - Office & Classroom 119	1	Yes	Floor (Green Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
H +	2489174	Ground	Vernon Block - Common Room 116	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A

	efence	Rec	giona	I Prime	e Contra	act Central	•		
In O	frastructure rganisation		_	_	osReais			carillion	amey
248917		Vernon Block - Radar Classroom 117	1	Yes	Floor (Green Tiles)		Monitor	3 Very Low	0 N/A
2489170	6 Ground	Vernon Block - Radar 115	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248917	7 Ground	Vernon Block - Secure Book Store 113	1	Yes	Floor (Green Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
2489178	3 Ground	Vernon Block - Classroom 114	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489179	9 Ground	Vernon Block - Corridor 1	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489180	) Ground	Vernon Block - Corridor 1 (near link to Bldg 632)	1	Yes	Floor (Dark Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
248918	1 Ground	Vernon Block - Equipment Room 112	1	Yes	Floor (Green Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
2489182	2 Ground	Vernon Block - Store 111	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489183	3 Ground	Vernon Block - Store 109	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489184	4 Ground	Vernon Block - Classroom 110	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
248918	5 Ground	Vernon Block - Classroom 108	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489180	6 Ground	Vernon Block - Classroom 107	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
248918	7 Ground	Vernon Block - Gun Mounting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248918	3 Ground	Vernon Block - Sight Housing	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489189	9 Ground	Vernon Block - Corridor 2 (west) leading to room 1	1	Yes	Floor (Green Tiles)	Chrysotile	Monitor	3 Very Low	0 N/A
2489190	) Ground	Vernon Block - Roof & Roof Tank Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248919	1 Ground	Vernon Block - GWS Tracking and 909 radar 120	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489192	2 Ground	Vernon Block - Lobby 122	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248919	3 Ground	Vernon Block - Corridor 2 (east)	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
2489194	4 Ground	Vernon Block - Corridor 3	1	Yes	Floor (Green	Chrysotile	Monitor	3 Very Low	0 N/A
248919	5 Ground	Vernon Block - NW Stairs (ground to 1st floor)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489190	6 Ground	Vernon Block - NE Stairs	1	Yes	Ceiling Tiles	Amosite	Monitor	7 Low	0 N/A
248919	7 Ground	Vernon Block - External Walkway	1	Yes	Underside of	Amosite	Monitor	7 Low	0 N/A
2489198	3 Ground	Vernon Block - Actual Gun Housing	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489199	9 Ground	Vernon Block - Store G19	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248920	) Ground	Vernon Block - North Exit to G32	1	Yes	Above Door	Amosite	Monitor	7 Low	0 N/A
248920	1 Ground	Vernon Block - External Limit to G32	1	Yes	Ceiling Tiles	Amosite	Monitor	7 Low	0 N/A

	Defence Infrastructure Organisation  2489202 Ground		Re	aiona	I Prime	e Contra	ct Central	•		
dende				_	_	osReais			carillion	amey
			Vernon Block - computer room G06	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489203	Ground	Vernon Block - Display room G06	1	Yes	Wall Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489204	First	Vernon Block - classroom 1.18	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489205	First	Vernon Block - stairwell	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489206	First	Vernon Block - classroom 106	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489207	First	Vernon Block - store 107	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489208	First	Vernon Block - store 107	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489209	First	Vernon Block - store 109	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489210	First	Vernon Block - commercial office 110	1	Yes	wooden frame above	Amosite	Monitor	7 Low	0 N/A
	2489211	First	Vernon Block - office 111 1.04A	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489212	First	Vernon Block - radar corridor 112	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489213	First	Vernon Block - radar corridor 112	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489214	First	Vernon Block - corridor 113	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489215	First	Vernon Block - corridor 113	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489216	First	Vernon Block - office 114	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489217	First	Vernon Block - store 115	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489218	First	Vernon Block - radar room 108	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489219	First	Vernon Block - radar corridor 108	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489127	Ground	Vernon Block - Throughout Building	1	Yes	Electrical Equipment	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489128	Ground	Vernon Block - Front Porch	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489129	Ground	Vernon Block - Front Lobby	1	Yes	Floor (Grey Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489220	First	Vernon Block - office 116 1.03	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489221	First	Vernon Block - office 117 1.07	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489222	First	Vernon Block - copier room 118	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489223	First	Vernon Block - Offce 120 1.08	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
$\sqcap$	2489224	First	Vernon Block - room 121 1.10	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
$\sqcap$	2489225	First	Vernon Block - meeting room 122	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
$\top$	2489226	First	Vernon Block - gents wc 123	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
$\dagger \dagger$	2489227	First	Vernon Block - corridor 124	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
$\top$	2489228	First	Vernon Block - corridor 124	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489229	First	Vernon Block - stairwell 125	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A

	Defe		F	Regiona	l Prime	e Contra	ct Central			
4880		structure		-	Asbest	osReais	ter		carillion	amey
	2489230	Ground	Vernon Block - lobby 001	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489231	Ground	Vernon Block - 002 G.02	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489232	Ground	Vernon Block - 003 G.03	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489233	Ground	Vernon Block - classroom 005	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
$\perp$	0.40000.4		N. B. I. I. I.			Switchgear	Content	10.0		0.11/4
$\perp$	2489234	Ground	Vernon Block - cupboard 006	1	Yes	Panel Above		Monitor	7 Low	0 N/A
Ш	2489235	Ground	Vernon Block - stairwell 008	1	Yes	Ceiling Tiles		Monitor	7 Low	0 N/A
	2489236	Ground	Vernon Block - workshop 009	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
+	2489237	Ground	Vernon Block - 011 G22	1	Yes	Switchgear Electrical	Content Presumed Asbestos	Monitor	4 Very Low	0 N/A
	2400201	Cround	Vernon Blook OTT G22		103	Switchgear	Content	World	T Very Low	014//(
	2489238	Ground	Vernon Block - switch room 014	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
$\perp$	0.400000		V 81 1 315			Switchgear	Content	NA 11		0.01/0
	2489239	Ground	Vernon Block - switch room 015	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
H	2489240	Ground	Vernon Block - plant room 016	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
			·			Switchgear	Content			
	2489241	Ground	Vernon Block - plant room 016	1	Yes	Pipework	Chrysotile	Monitor	5 Low	0 N/A
П	2489242	Ground	Vernon Block - corridor 017	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
П	2489243	Ground	Vernon Block - corridor 017	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
	2489244	Ground	Vernon Block - corridor 017	1	Yes	Electrical Switchgear	Presumed Asbestos Content	Monitor	4 Very Low	0 N/A
	2489245	Ground	Vernon Block - 018 G.08	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
H	2489246	Ground	Vernon Block - 018 G.08	1	Yes	Wall Panels	Amosite	Monitor	7 Low	0 N/A
H	2489247	Ground	Vernon Block - 018 G.08	1	Yes	Door Panels	Amosite	Monitor	7 Low	0 N/A
H	2489248	Ground	Vernon Block - 018 G.08	1	Yes	Electrical	Presumed Asbestos	Monitor	4 Very Low	0 N/A
						Switchgear	Content			
	2489249	Ground	Vernon Block - Comms room 019	1	Yes	wooden	Amosite	Monitor	7 Low	0 N/A
Н	MS COLLINGV	OOD - VIVIAN	BLOCK - 708047 - COLW01000616							
	2490059	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490060	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490061	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490062	Ground	WO and Sergeants Mess - Room 407	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
$\parallel$	2490063	Ground	WO and Sergeants Mess - Room 408	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490064	Ground	WO and Sergeants Mess - Room 407	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490065	Ground	WO and Sergeants Mess - Room 409	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prim	e Contra	act Central			
10000	Infra Orga	structure anisation				osReais			carillion	amey
П	2490066	Ground	WO and Sergeants Mess - Room 410	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490067	Ground	WO and Sergeants Mess - Room 411	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490068	Ground	WO and Sergeants Mess - Room 412	1	Yes	panel on ceiling		No Action	0 No Risk	0 N/A
	2490069	Ground	WO and Sergeants Mess - Room 412	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
	2490070	Ground	WO and Sergeants Mess - Room 413	1	Yes	panel above door to both		No Action	0 No Risk	0 N/A
	2490071	Ground	WO and Sergeants Mess - Electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490072	Ground	WO and Sergeants Mess - Room 501	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490073	Ground	WO and Sergeants Mess - Room 502	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490074	Ground	WO and Sergeants Mess - Room 503	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490075	Ground	WO and Sergeants Mess - Room 504	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490076	Ground	WO and Sergeants Mess - Room 505	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490077	Ground	WO and Sergeants Mess - Room 506	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490078	Ground	WO and Sergeants Mess - Room 507	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490079	Ground	WO and Sergeants Mess - Room 508	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490080	Ground	WO and Sergeants Mess - Room 509	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490081	Ground	WO and Sergeants Mess - Room 510	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490082	Ground	WO and Sergeants Mess - Room 511	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490083	Ground	WO and Sergeants Mess - Room 512	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490084	Ground	WO and Sergeants Mess - Room 513	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490085	Ground	WO and Sergeants Mess - Room 514	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490086	Ground	WO and Sergeants Mess - Room 515	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490087	Ground	WO and Sergeants Mess - Room 516	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490088	Ground	WO and Sergeants Mess - Room 517	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

161 of 420

-	Defe			Regiona	al Prime	Contra	act Central			
danie	Infra Orga	structure anisation				sRegis			carillion	amey
	2490089	Ground	WO and Sergeants Mess - Room 518	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490028	Ground	WO and Sergeants Mess - Room 328	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490029	Ground	WO and Sergeants Mess - Room 329	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490030	Ground	WO and Sergeants Mess - Room 330	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490031	Ground	WO and Sergeants Mess - Room 331	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490032	Ground	WO and Sergeants Mess - Room 332	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490033	Ground	WO and Sergeants Mess - Room 333	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490034	Ground	WO and Sergeants Mess - Room 334	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490035	Ground	WO and Sergeants Mess - Room 335	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490036	Ground	WO and Sergeants Mess - Room 336	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490037	Ground	WO and Sergeants Mess - Room 337	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490038	Ground	WO and Sergeants Mess - Room 338	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490039	Ground	WO and Sergeants Mess - Room 339	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490040	Ground	WO and Sergeants Mess - Room 340	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490041	Ground	WO and Sergeants Mess - Room 340	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
Ш	2490042	Ground	WO and Sergeants Mess - Room 341	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490043	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2490044	Ground	WO and Sergeants Mess - NW Sttairwell	1		Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490045	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490046	Ground	WO and Sergeants Mess - NW Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490047	Ground	WO and Sergeants Mess - NW Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2490048	Ground	WO and Sergeants Mess - Room 400	1	Yes	panels above door		No Action	0 No Risk	0 N/A
	2490049	Ground	WO and Sergeants Mess - Room 401	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A

	Defence Infrastructur Organisation 2490050 Ground			Regiona	al Prime	e Contra	ct Central		carillionamey	
CHIEFE.	Orga	structure			Asbesto	osReais	ter		carillion	amey
		T	WO and Sergeants Mess - Room 401	1	Yes	panels to ceiling		No Action	0 No Risk	0 N/A
	2490051	Ground	WO and Sergeants Mess - Room 402	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490052	Ground	WO and Sergeants Mess - Room 403	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490053	Ground	WO and Sergeants Mess - Room 404	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490054	Ground	WO and Sergeants Mess - Room 405	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490055	Ground	WO and Sergeants Mess - Room 406	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490056	Ground	WO and Sergeants Mess - Room 406	1	Yes	panels to ceiling		No Action	0 No Risk	0 N/A
	2490057	Ground	WO and Sergeants Mess - North Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490058	Ground	WO and Sergeants Mess - North Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490351	Ground	WO and Sergeants Mess - Corridor 11	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
	2490352	Ground	WO and Sergeants Mess - Corridor 12	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
	2490353	Ground	WO and Sergeants Mess - Room 613	1	Yes	panel above door		No Action	0 No Risk	0 N/A
	2490354	Ground	WO and Sergeants Mess - Tank room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490355	Ground	WO and Sergeants Mess - Tank room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490356	Ground	WO and Sergeants Mess - Tank room 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490357	Ground	WO and Sergeants Mess - Tank room 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490358	Ground	WO and Sergeants Mess - Tank room 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490359	Ground	WO and Sergeants Mess - Tank room 6	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490360	Ground	WO and Sergeants Mess - Tank room 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490361	Ground	WO and Sergeants Mess - Tank room 8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490362	Ground	WO and Sergeants Mess - Tank room 9	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490363	Ground	WO and Sergeants Mess - South Calorifier	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490364	Ground	WO and Sergeants Mess - North Calorifier	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	efence	R	<u>eaion</u> a	al Prime	e Contra	act Central	•		
	frastructure rganisation			Asbest	osReais	ster		carillion	amey
2490365		WO and Sergeants Mess - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490366	6 External	WO and Sergeants Mess - External	1	Yes	panels to the canopy	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490367	External	WO and Sergeants Mess - External	1	Yes	panels to the	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490368	External	WO and Sergeants Mess - External	1	Yes	panels to the	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491995	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2491996	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Stairs (Nosings)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490090	Ground	WO and Sergeants Mess - Room 519	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
2490091	Ground	WO and Sergeants Mess - Room 520	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
2490092	Ground	WO and Sergeants Mess - Lounge (central)	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490093	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490094	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
2490095	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
2490096	Ground	WO and Sergeants Mess - Lounge	1	Yes	panel above		No Action	0 No Risk	0 N/A
2490097	Ground	WO and Sergeants Mess - Room 522	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490098	Ground	WO and Sergeants Mess - Room 523	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490099	Ground	WO and Sergeants Mess - Room 524	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490100	Ground	WO and Sergeants Mess - Room 525	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490101	Ground	WO and Sergeants Mess - Room 526	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490102	? Ground	WO and Sergeants Mess - Room 527	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490103	Ground	WO and Sergeants Mess - Room 528	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490104	Ground	WO and Sergeants Mess - Room 529	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490105	Ground	WO and Sergeants Mess - Room 530	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490106	Ground Ground	WO and Sergeants Mess - Room 531	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490107	Ground	WO and Sergeants Mess - Room 532	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		F	Regiona	al Prime	e Contra	ct Central			
.455554	Infra Orga	structure anisation				osRegis			carillion	amey
	2490108	Ground	WO and Sergeants Mess - Room 533	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490109	Ground	WO and Sergeants Mess - Room 534	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490110	Ground	WO and Sergeants Mess - Room 535	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490111	Ground	WO and Sergeants Mess - Room 536	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490112	Ground	WO and Sergeants Mess - Room 537	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490113	Ground	WO and Sergeants Mess - Room 538	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490114	Ground	WO and Sergeants Mess - Room 539	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490115	Ground	WO and Sergeants Mess - Room 540	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490116	Ground	WO and Sergeants Mess - Room 541	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490117	Ground	WO and Sergeants Mess - Room 600	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
	2490118	Ground	WO and Sergeants Mess - Room 601	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
	2490119	Ground	WO and Sergeants Mess - Room 602	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490120	Ground	WO and Sergeants Mess - Room 603	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490152	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490153	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490154	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490155	Ground	WO and Sergeants Mess - East Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490156	Ground	WO and Sergeants Mess - SE Bathroom	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2490157	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490158	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490159	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490160	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2490161	Ground	WO and Sergeants Mess - SE Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	F	Regiona	al Prime	e Contra	ct Central		<u>**</u>	
100000	Infra Orga	structure				osReais			carillion	ımey
	2490162	Ground	WO and Sergeants Mess - South	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
			Bathroom							
	2490163	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490164	Ground	WO and Sergeants Mess - South	1	Yes	Stairs	Chrysotile	Monitor	3 Very Low	0 N/A
			Stairwell			(Nosings)			·	
	2490165	Ground	WO and Sergeants Mess - South	1	Yes	panel above		No Action	0 No Risk	0 N/A
			Stairwell			radiator				
	2490166	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2490167	Ground	WO and Sergeants Mess - South Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490168	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490169	Ground	WO and Sergeants Mess - SW Bathroom	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
H	2490170	Ground	WO and Sergeants Mess - SW	1	Yes		Chrysotile	Monitor	3 Very Low	0 N/A
			Stairwell		. • •	(Nosings)			, , , , , , , , , , , , , , , , , , ,	0.07.
	2490171	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2490172	Ground	WO and Sergeants Mess - SW Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490173	Ground	WO and Sergeants Mess - West Bathroom	1	Yes	panel above door		No Action	0 No Risk	0 N/A
	2490174	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490175	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490176	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490177	Ground	WO and Sergeants Mess - West Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490178	Ground	WO and Sergeants Mess - NW Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490179	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490180	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490181	Ground	WO and Sergeants Mess - North Bathroom	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
I	2490121	Ground	WO and Sergeants Mess - Room 604	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490122	Ground	WO and Sergeants Mess - Room 605	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490123	Ground	WO and Sergeants Mess - Room 606	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence		Regiona	d Prim	e Contra	act Central			
The state of the s		astructure anisation				osReais			carillion	amey
	2490124	Ground	WO and Sergeants Mess - Room 607	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490125	Ground	WO and Sergeants Mess - Room 607	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490126	Ground	WO and Sergeants Mess - Room 608	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490127	Ground	WO and Sergeants Mess - Room 609	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490128	Ground	WO and Sergeants Mess - Room 610	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490129	Ground	WO and Sergeants Mess - Room 611	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490130	Ground	WO and Sergeants Mess - Room 612	1	Yes	panel above door in		No Action	0 No Risk	0 N/A
П	2490131	Ground	WO and Sergeants Mess - Room 612	1	Yes	panels to ceiling		No Action	0 No Risk	0 N/A
	2490132	Ground	WO and Sergeants Mess - Room 613	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490133	Ground	WO and Sergeants Mess - Room 600	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
П	2490134	Ground	WO and Sergeants Mess - Corridor 01	1	Yes	panels above door		No Action	0 No Risk	0 N/A
	2490135	Ground	WO and Sergeants Mess - Corridor 2	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
	2490136	Ground	WO and Sergeants Mess - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490137	Ground	WO and Sergeants Mess - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490138	Ground	WO and Sergeants Mess - Corridor 5	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490139	Ground	WO and Sergeants Mess - Corridor 6	1	Yes	panel above door to SW		No Action	0 No Risk	0 N/A
Ш	2490140	Ground	WO and Sergeants Mess - Corridor 7	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490141	Ground	WO and Sergeants Mess - Corridor 8	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\ $	2490142	Ground	WO and Sergeants Mess - Corridor 9 - above doors t	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
$\ $	2490143	Ground	WO and Sergeants Mess - Corridor 10	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
$\ $	2490144	Ground	WO and Sergeants Mess - Corridor 11	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
Ш	2490145	Ground	WO and Sergeants Mess - Corridor 12	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
Ш	2490146	Ground	WO and Sergeants Mess - NE Bathroom	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A

167 of 420

		ence	R	egiona	al Primo	e Contra	act Central			
	Infra Org	astructure anisation				osReais			carillion	amey
	2490147	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490148	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490149	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490150	Ground	WO and Sergeants Mess - NE Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2490151	Ground	WO and Sergeants Mess - East Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489885	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	panel above the radiator		No Action	0 No Risk	0 N/A
П	2489886	Ground	WO and Sergeants Mess - NE Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489887	Ground	WO and Sergeants Mess - NW Pipestove	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489888	Ground	WO and Sergeants Mess - Room 400 Utility Room	1	Yes	infill panel on far wall		No Action	0 No Risk	0 N/A
П	2489889	Ground	WO and Sergeants Mess - Room 401 Cleaners Cupboard	1	Yes	panel above door and to		No Action	0 No Risk	0 N/A
П	2489890	Ground	WO and Sergeants Mess - Room 402	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489891	Ground	WO and Sergeants Mess - Room 403	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489892	Ground	WO and Sergeants Mess - Room 404	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489893	Ground	WO and Sergeants Mess - Room 405	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489894	Ground	WO and Sergeants Mess - Room 406	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
П	2489895	Ground	WO and Sergeants Mess - Room 407 Store	1	Yes	panel above door on both		No Action	0 No Risk	0 N/A
П	2489896	Ground	WO and Sergeants Mess - North Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489897	Ground	WO and Sergeants Mess - North Pipe Riser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489898	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489899	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489900	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	panel above radiator on		No Action	0 No Risk	0 N/A
	2489901	Ground	WO and Sergeants Mess - Room 500	1	Yes	panel on far wall near		No Action	0 No Risk	0 N/A
	2489902	Ground	WO and Sergeants Mess - Room 501	1	Yes	Floor		No Action	0 No Risk	0 N/A

	ence		Regiona	al Prim	e Contra	act Central	•		
Infra Orga	astructure anisation				osReais			carillion	amey
2489903	Ground	WO and Sergeants Mess - Room 502	1	Yes	Floor		No Action	0 No Risk	0 N/A
2489904	Ground	WO and Sergeants Mess - Room 503 - Linen Store	1	Yes	Floor		No Action	0 No Risk	0 N/A
2489905	Ground	WO and Sergeants Mess - Room 504 - Toilet	1	Yes	panels over door		No Action	0 No Risk	0 N/A
2489906	Ground	WO and Sergeants Mess - Room 504 - Toilet	1	Yes	Floor		No Action	0 No Risk	0 N/A
2489907	Ground	WO and Sergeants Mess - Room 505	1	Yes	panel on far wall near		No Action	0 No Risk	0 N/A
2489908	Ground	WO and Sergeants Mess - Central Staircase	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489909	Ground	WO and Sergeants Mess - Central Staircase	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
2489910	Ground	WO and Sergeants Mess - Central Staircase	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
2489911	Ground	WO and Sergeants Mess - Room 606	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
2489912	Ground	WO and Sergeants Mess - Room 605	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489913	Ground	WO and Sergeants Mess - Room 604	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489914	Ground	WO and Sergeants Mess - Room 603	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489915	Ground	WO and Sergeants Mess - Room 602	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489916	Ground	WO and Sergeants Mess - Room 601 Cleaners Room	1	Yes	panels on ceiling		No Action	0 No Risk	0 N/A
2489917	Ground	WO and Sergeants Mess - Room 600	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489918	Ground	WO and Sergeants Mess - Room 601 Cleaners Room	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
2489919	Ground	WO and Sergeants Mess - Room 612	1	Yes	panels on ceiling and		No Action	0 No Risk	0 N/A
2489920	Ground	WO and Sergeants Mess - Electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489921	Ground	WO and Sergeants Mess - Corridor 01	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
2489922	Ground	WO and Sergeants Mess - Corridor 2	1	Yes	Ceiling Void		No Action	0 No Risk	0 N/A
2489923	Ground	WO and Sergeants Mess - Corridor 3	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
2489924	Ground	WO and Sergeants Mess - Corridor 4	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
2489925	Ground	WO and Sergeants Mess - Corridor 5	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A

	Defe		R	Regiona	al Prime	e Contra	act Central			
	Orga	structure anisation			Asbest	osReais	ter		carillion	amey
	2489926	Ground	WO and Sergeants Mess - Corridor 6	1	Yes	Ceiling Void		No Action	0 No Risk	0 N/A
$\prod$	2489927	Ground	WO and Sergeants Mess - Corridor 7	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2489928	Ground	WO and Sergeants Mess - Corridor 8	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2489929	Ground	WO and Sergeants Mess - F101	1	Yes	panel on r/h side near	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489930	Ground	WO and Sergeants Mess - F102	1	Yes	panel on		No Action	0 No Risk	0 N/A
	2489931	Ground	WO and Sergeants Mess - F103	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489932	Ground	WO and Sergeants Mess - F104	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489933	Ground	WO and Sergeants Mess - F105	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489934	Ground	WO and Sergeants Mess - F106	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489935	Ground	WO and Sergeants Mess - F107	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489936	Ground	WO and Sergeants Mess - F108	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489937	Ground	WO and Sergeants Mess - F109	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489938	Ground	WO and Sergeants Mess - F110	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489939	Ground	WO and Sergeants Mess - F111	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489940	Ground	WO and Sergeants Mess - F112	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489941	Ground	WO and Sergeants Mess - F113	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489942	Ground	WO and Sergeants Mess - F114	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489943	Ground	WO and Sergeants Mess - F115	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489944	Ground	WO and Sergeants Mess - F116	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489945	Ground	WO and Sergeants Mess - F117	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489946	Ground	WO and Sergeants Mess - F118	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
H +	2489947	Ground	WO and Sergeants Mess - F119	1	Yes	panel on		No Action	0 No Risk	0 N/A
	2489948	Ground	WO and Sergeants Mess - F120	1	Yes	panel on		No Action	0 No Risk	0 N/A
	2489949	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A

\$ S	Defe		R	Regiona	l Prime	e Contra	act Central		carilliona	
		structure anisation				osReais			carillion	mey
	2489950	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489951	Ground	WO and Sergeants Mess - NE Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489952	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489953	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489954	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489955	Ground	WO and Sergeants Mess - E Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489956	Ground	WO and Sergeants Mess - East Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489957	Ground	WO and Sergeants Mess - Room 124	1	Yes	panel on wall (l/h		No Action	0 No Risk	0 N/A
	2489958	Ground	WO and Sergeants Mess - Room 124	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489959	Ground	WO and Sergeants Mess - Room 125	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489960	Ground	WO and Sergeants Mess - Room 125	1	Yes	panel on wall (r/h		No Action	0 No Risk	0 N/A
	2489961	Ground	WO and Sergeants Mess - Room 126	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489962	Ground	WO and Sergeants Mess - Room 127	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489963	Ground	WO and Sergeants Mess - Room 132	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489964	Ground	WO and Sergeants Mess - Room 133	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489965	Ground	WO and Sergeants Mess - Room 140	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489966	Ground	WO and Sergeants Mess - Room 141	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489967	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489968	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489969	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489970	Ground	WO and Sergeants Mess - SE Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489971	Ground	WO and Sergeants Mess - Room 134	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489972	Ground	WO and Sergeants Mess - Room 135	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

W	Defe			Regiona	al Prime	e Contra	ct Central			
1	Infra Orga	structure anisation				osReais			carillion	amey
	2489973	Ground	WO and Sergeants Mess - Room 140	1	Yes	panel to wall on r/h side		No Action	0 No Risk	0 N/A
	2489974	Ground	WO and Sergeants Mess - Room 141	1	Yes	panel on wall I/h side		No Action	0 No Risk	0 N/A
	2489975	Ground	WO and Sergeants Mess - SE Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489976	Ground	WO and Sergeants Mess - SE Pipe Riser	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489977	Ground	WO and Sergeants Mess - Room 200 Utility & Drying	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489978	Ground	WO and Sergeants Mess - Room 201 Store Room	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A
	2489979	Ground	WO and Sergeants Mess - Room 202	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489980	Ground	WO and Sergeants Mess - Room 203	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489981	Ground	WO and Sergeants Mess - Room 204	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489982	Ground	WO and Sergeants Mess - Room 205	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489983	Ground	WO and Sergeants Mess - Room 206	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
	2489984	Ground	WO and Sergeants Mess - Room 206	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489985	Ground	WO and Sergeants Mess - S Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489986	Ground	WO and Sergeants Mess - S Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489987	Ground	WO and Sergeants Mess - S Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489988	Ground	WO and Sergeants Mess - South Bathroom	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A
	2489989	Ground	WO and Sergeants Mess - South Electrrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489990	Ground	WO and Sergeants Mess - Room 207	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
	2489991	Ground	WO and Sergeants Mess - Room 208	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489992	Ground	WO and Sergeants Mess - Room 209	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489993	Ground	WO and Sergeants Mess - Room 210	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489994	Ground	WO and Sergeants Mess - Room 211	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489995	Ground	WO and Sergeants Mess - Room 212	1	Yes	panels on ceiling		No Action	0 No Risk	0 N/A

	Defe			Regiona	al Primo	e Contra	ct Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2489996	Ground	WO and Sergeants Mess - Room 213	1	Yes	panel above door each		No Action	0 No Risk	0 N/A
П	2489997	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2489998	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489999	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	panel above door to		No Action	0 No Risk	0 N/A
	2490000	Ground	WO and Sergeants Mess - SE Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490001	Ground	WO and Sergeants Mess - Room 212	1	Yes	panel above door both		No Action	0 No Risk	0 N/A
П	2490002	Ground	WO and Sergeants Mess - Room 301	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490003	Ground	WO and Sergeants Mess - Room 302	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
	2490004	Ground	WO and Sergeants Mess - Room 307	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490005	Ground	WO and Sergeants Mess - Room 308	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490006	Ground	WO and Sergeants Mess - Room 309	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490007	Ground	WO and Sergeants Mess - Room 310	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490008	Ground	WO and Sergeants Mess - Room 315	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490009	Ground	WO and Sergeants Mess - Room 316	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490010	Ground	WO and Sergeants Mess - Room 317	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
	2490011	Ground	WO and Sergeants Mess - Room 317	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490012	Ground	WO and Sergeants Mess - Room 318	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490013	Ground	WO and Sergeants Mess - Room 318	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490014	Ground	WO and Sergeants Mess - West Bathroom	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A
$\parallel$	2490015	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490016	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
$\parallel$	2490017	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490018	Ground	WO and Sergeants Mess - Room 213	1	Yes	Ironing Board		No Action	0 No Risk	0 N/A

		ence	R	Regiona	al Prime	e Contra	act Central			A.
R	Infra Orga	structure anisation			Asbest	osReais	ster		carillion	amey
	2490019	Ground	WO and Sergeants Mess - Room 213	1	Yes	panels near box pipes in		No Action	0 No Risk	0 N/A
	2490020	Ground	WO and Sergeants Mess - Room 322	1	Yes	panel on wall (I/h		No Action	0 No Risk	0 N/A
	2490021	Ground	WO and Sergeants Mess - Room 322	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490022	Ground	WO and Sergeants Mess - Room 323	1	Yes	panel on wall r/h side		No Action	0 No Risk	0 N/A
	2490023	Ground	WO and Sergeants Mess - Room 323	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490024	Ground	WO and Sergeants Mess - Room 324	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490025	Ground	WO and Sergeants Mess - Room 325	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490026	Ground	WO and Sergeants Mess - Room 326	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490027	Ground	WO and Sergeants Mess - Room 327	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489884	Ground	WO and Sergeants Mess - NW Sttairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490304	Ground	WO and Sergeants Mess - Room 520	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490305	Ground	WO and Sergeants Mess - Coffee Room	1	Yes	panel above double		No Action	0 No Risk	0 N/A
	2490306	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490307	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490308	Ground	WO and Sergeants Mess - Central Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2490309	Ground	WO and Sergeants Mess - Room 522	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490310	Ground	WO and Sergeants Mess - Room 523	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490311	Ground	WO and Sergeants Mess - Room 524	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490312	Ground	WO and Sergeants Mess - Room 525	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
HT	2490313	Ground	WO and Sergeants Mess - Room 526	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490314	Ground	WO and Sergeants Mess - Room 527	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$H = \frac{1}{2}$	2490315	Ground	WO and Sergeants Mess - Room 528	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490316	Ground	WO and Sergeants Mess - Room 529	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

174 of 420

		ence	F	Regiona	al Prime	e Contra	act Central	•		
The state of the s	Infra	astructure anisation	_			osReais			carillion	amey
	2490317	Ground	WO and Sergeants Mess - Room 530	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490318	Ground	WO and Sergeants Mess - Room 531	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490319	Ground	WO and Sergeants Mess - Room 532	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490320	Ground	WO and Sergeants Mess - Room 533	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490321	Ground	WO and Sergeants Mess - Room 534	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490322	Ground	WO and Sergeants Mess - Room 535	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490323	Ground	WO and Sergeants Mess - Room 536	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490324	Ground	WO and Sergeants Mess - Room 537	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490325	Ground	WO and Sergeants Mess - Room 538	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490326	Ground	WO and Sergeants Mess - Room 539	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490327	Ground	WO and Sergeants Mess - Room 540	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490328	Ground	WO and Sergeants Mess - Room 541	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490329	Ground	WO and Sergeants Mess - Room 600	1	Yes	above door to dry store		No Action	0 No Risk	0 N/A
	2490330	Ground	WO and Sergeants Mess - Room 601 store	1	Yes	above door to dry store		No Action	0 No Risk	0 N/A
	2490331	Ground	WO and Sergeants Mess - Room 601 store	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
	2490332	Ground	WO and Sergeants Mess - Room 601	1	Yes	panels on ceiling		No Action	0 No Risk	0 N/A
	2490333	Ground	WO and Sergeants Mess - Room 602	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490273	Ground	WO and Sergeants Mess - Room 404	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490274	Ground	WO and Sergeants Mess - Room 405	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490275	Ground	WO and Sergeants Mess - Room 406	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490276	Ground	WO and Sergeants Mess - Room 407	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490277	Ground	WO and Sergeants Mess - Room 408	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490278	Ground	WO and Sergeants Mess - Room 409	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

175 of 420

	Defe		F	Regiona	al Prime	e Contra	act Central			
	Orga	structure anisation			Asbesto	osReais	ster		carillion	amey
	2490279	Ground	WO and Sergeants Mess - Room 410	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
IT	2490280	Ground	WO and Sergeants Mess - Room 411	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490281	Ground	WO and Sergeants Mess - Room 413	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490282	Ground	WO and Sergeants Mess - Room 412	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490283	Ground	WO and Sergeants Mess - Room 412	1	Yes	panels to ceiling and		No Action	0 No Risk	0 N/A
	2490284	Ground	WO and Sergeants Mess - Room 412	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
	2490285	Ground	WO and Sergeants Mess - Room 501	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490286	Ground	WO and Sergeants Mess - Room 502	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490287	Ground	WO and Sergeants Mess - Room 503	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490288	Ground	WO and Sergeants Mess - Room 504	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490289	Ground	WO and Sergeants Mess - Room 505	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490290	Ground	WO and Sergeants Mess - Room 506	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490291	Ground	WO and Sergeants Mess - Room 507	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490292	Ground	WO and Sergeants Mess - Room 508	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490293	Ground	WO and Sergeants Mess - Room 509	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490294	Ground	WO and Sergeants Mess - Room 510	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490295	Ground	WO and Sergeants Mess - Room 511	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490296	Ground	WO and Sergeants Mess - Room 512	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490297	Ground	WO and Sergeants Mess - Room 513	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490298	Ground	WO and Sergeants Mess - Room 514	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490299	Ground	WO and Sergeants Mess - Room 515	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
H	2490300	Ground	WO and Sergeants Mess - Room 516	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ħ	2490301	Ground	WO and Sergeants Mess - Room 517	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	Contra	ct Central	•		
denta	Infra Orga	structure anisation				sReais			carillion	amey
	2490302	Ground	WO and Sergeants Mess - Room 518	1		Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490303	Ground	WO and Sergeants Mess - Room 519	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490334	Ground	WO and Sergeants Mess - Room 603	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490335	Ground	WO and Sergeants Mess - Room 604	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490336	Ground	WO and Sergeants Mess - Room 605	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490337	Ground	WO and Sergeants Mess - Room 606	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490338	Ground	WO and Sergeants Mess - Room 607	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490339	Ground	WO and Sergeants Mess - Room 608	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490340	Ground	WO and Sergeants Mess - Room 609	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490341	Ground	WO and Sergeants Mess - Corridor 01	1	Yes	panels above doors		No Action	0 No Risk	0 N/A
	2490342	Ground	WO and Sergeants Mess - Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490343	Ground	WO and Sergeants Mess - Corridor 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490344	Ground	WO and Sergeants Mess - Corridor 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490345	Ground	WO and Sergeants Mess - Corridor 5	1		above door to corridor 7		No Action	0 No Risk	0 N/A
	2490346	Ground	WO and Sergeants Mess - Corridor 6	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
	2490347	Ground	WO and Sergeants Mess - Corridor 7	1	Yes	panel above door to room		No Action	0 No Risk	0 N/A
	2490348	Ground	WO and Sergeants Mess - Corridor 8	1	Yes	panel above door to SW		No Action	0 No Risk	0 N/A
	2490349	Ground	WO and Sergeants Mess - Corridor 9	1	Yes	panel above door to SW		No Action	0 No Risk	0 N/A
	2490350	Ground	WO and Sergeants Mess - Corridor 10	1	Yes	panel above door to SW		No Action	0 No Risk	0 N/A
	2490182	Ground	WO and Sergeants Mess - North Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490183	Ground	WO and Sergeants Mess - North Stairwell	1		Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2490184	Ground	WO and Sergeants Mess - North Stairwell	1		panel above radiator		No Action	0 No Risk	0 N/A
	2490185	Ground	WO and Sergeants Mess - Room 101	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 177 of 420

Defence Infrastructure Organisation 2490186 Ground		R	Regiona		carillionamey				
Infra Orga	structure anisation				osReai			**carillion	amey
	1	WO and Sergeants Mess - Room 102	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490187	Ground	WO and Sergeants Mess - Room 103	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490188	Ground	WO and Sergeants Mess - Room 104	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490189	Ground	WO and Sergeants Mess - Room 105	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490190	Ground	WO and Sergeants Mess - Room 106	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490191	Ground	WO and Sergeants Mess - Room 107	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490192	Ground	WO and Sergeants Mess - Room 108	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490193	Ground	WO and Sergeants Mess - Room 109	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490194	Ground	WO and Sergeants Mess - Room 110	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490195	Ground	WO and Sergeants Mess - Room 111	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490196	Ground	WO and Sergeants Mess - Room 112	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490197	Ground	WO and Sergeants Mess - Room 113	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490198	Ground	WO and Sergeants Mess - Room 114	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490199	Ground	WO and Sergeants Mess - Room 115	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490200	Ground	WO and Sergeants Mess - Room 116	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490201	Ground	WO and Sergeants Mess - Room 117	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490202	Ground	WO and Sergeants Mess - Room 118	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490203	Ground	WO and Sergeants Mess - Room 119	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490204	Ground	WO and Sergeants Mess - Room 124	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490205	Ground	WO and Sergeants Mess - Room 119	1	Yes	panel on wall		No Action	0 No Risk	0 N/A
2490206	Ground	WO and Sergeants Mess - Room 123	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490207	Ground	WO and Sergeants Mess - Room 126	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2490208	Ground	WO and Sergeants Mess - Room 127	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	Contra	ct Central			A.
	Orga	structure anisation			Ashesto	sRegis	ter		carillion	amey
П	2490209	Ground	WO and Sergeants Mess - Room 132	1		Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ħ	2490210	Ground	WO and Sergeants Mess - Room 133	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
IT	2490211	Ground	WO and Sergeants Mess - Room 134	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ħ	2490212	Ground	WO and Sergeants Mess - Room 135	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490213	Ground	WO and Sergeants Mess - Room 140	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490214	Ground	WO and Sergeants Mess - Room 141	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490215	Ground	WO and Sergeants Mess - Room 200	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490216	Ground	WO and Sergeants Mess - Room 201 Store	1	Yes	panel above door and on		No Action	0 No Risk	0 N/A
	2490217	Ground	WO and Sergeants Mess - Room 201	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A
	2490218	Ground	WO and Sergeants Mess - Room 202	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490219	Ground	WO and Sergeants Mess - Room 203	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
IT	2490220	Ground	WO and Sergeants Mess - Room 206	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
IT	2490221	Ground	WO and Sergeants Mess - Room 207	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
IT	2490222	Ground	WO and Sergeants Mess - Room 212 cleaners	1	Yes	ceiling		No Action	0 No Risk	0 N/A
	2490223	Ground	WO and Sergeants Mess - Room 213	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490224	Ground	WO and Sergeants Mess - Room 210	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490225	Ground	WO and Sergeants Mess - Room 211	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490226	Ground	WO and Sergeants Mess - Room 301	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2490227	Ground	WO and Sergeants Mess - Room 302	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490228	Ground	WO and Sergeants Mess - Room 303	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490229	Ground	WO and Sergeants Mess - Room 304	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490230	Ground	WO and Sergeants Mess - Room 305	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2490231	Ground	WO and Sergeants Mess - Room 306	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

**Page:** 179 of 420

		ence	F	Regiona	l Prim	e Cont	ract Central			A.
	Orga	astructure anisation			Ashest	osRea	ister		carillion	amey
2	2490232	Ground	WO and Sergeants Mess - Room 307	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490233	Ground	WO and Sergeants Mess - Room 308	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490234	Ground	WO and Sergeants Mess - Room 309	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490235	Ground	WO and Sergeants Mess - Room 310	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490236	Ground	WO and Sergeants Mess - Room 311	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490237	Ground	WO and Sergeants Mess - Room 312	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490238	Ground	WO and Sergeants Mess - Room 313	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490239	Ground	WO and Sergeants Mess - Room 314	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490240	Ground	WO and Sergeants Mess - Room 319	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490241	Ground	WO and Sergeants Mess - All Accomm Rooms on Second	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490242	Ground	WO and Sergeants Mess - Room 315	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490243	Ground	WO and Sergeants Mess - Room 316	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490244	Ground	WO and Sergeants Mess - Room 317	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490245	Ground	WO and Sergeants Mess - Room 318	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490246	Ground	WO and Sergeants Mess - Room 320	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490247	Ground	WO and Sergeants Mess - Room 322	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490248	Ground	WO and Sergeants Mess - Room 323	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490249	Ground	WO and Sergeants Mess - Room 324	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490250	Ground	WO and Sergeants Mess - Room 325	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490251	Ground	WO and Sergeants Mess - Room 326	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490252	Ground	WO and Sergeants Mess - Room 327	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490253	Ground	WO and Sergeants Mess - Room 328	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2490254	Ground	WO and Sergeants Mess - Room 329	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			_
dail	Infra Orga	structure anisation			Asbesto	osReais	ster		carillion	amey
	2490255	Ground	WO and Sergeants Mess - Room 330	1		Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490256	Ground	WO and Sergeants Mess - Room 331	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490257	Ground	WO and Sergeants Mess - Room 332	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490258	Ground	WO and Sergeants Mess - Room 333	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490259	Ground	WO and Sergeants Mess - Room 334	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490260	Ground	WO and Sergeants Mess - Room 335	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490261	Ground	WO and Sergeants Mess - Room 336	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490262	Ground	WO and Sergeants Mess - Room 337	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490263	Ground	WO and Sergeants Mess - Room 338	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490264	Ground	WO and Sergeants Mess - Room 339	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490265	Ground	WO and Sergeants Mess - Room 340	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490266	Ground	WO and Sergeants Mess - Room 400 Utility Room	1	Yes	panel box work		No Action	0 No Risk	0 N/A
	2490267	Ground	WO and Sergeants Mess - Room 401	1	Yes	panels on ceiling		No Action	0 No Risk	0 N/A
	2490268	Ground	WO and Sergeants Mess - Room 400	1	Yes	panels above door		No Action	0 No Risk	0 N/A
	2490269	Ground	WO and Sergeants Mess - Room 401	1	Yes	panels above door		No Action	0 No Risk	0 N/A
	2490270	Ground	WO and Sergeants Mess - Room 341	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490271	Ground	WO and Sergeants Mess - Room 402	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2490272	Ground	WO and Sergeants Mess - Room 403	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489855	Ground	WO and Sergeants Mess - Room 318	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489856	Ground	WO and Sergeants Mess - Room 319 Store	1	Yes	Floor		No Action	0 No Risk	0 N/A
	2489857	Ground	WO and Sergeants Mess - Room 320	1	Yes	panel on far wall near		No Action	0 No Risk	0 N/A
	2489858	Ground	WO and Sergeants Mess - Room 321 West Bathroom	1	Yes	panel above door (facing		No Action	0 No Risk	0 N/A
	2489859	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		R	Regiona	al Prime	e Contra	act Central		carilliono	
		structure anisation				osReais			carillion	mey
2	2489860	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
2	2489861	Ground	WO and Sergeants Mess - West Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
2	2489862	Ground	WO and Sergeants Mess - Room 322	1	Yes	infill panel on far wall		No Action	0 No Risk	0 N/A
2	2489863	Ground	WO and Sergeants Mess - Room 323	1	Yes	infill panel on far wall		No Action	0 No Risk	0 N/A
2	2489864	Ground	WO and Sergeants Mess - Room 324	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489865	Ground	WO and Sergeants Mess - Room 325	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489866	Ground	WO and Sergeants Mess - Room 326	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489867	Ground	WO and Sergeants Mess - Room 327	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489868	Ground	WO and Sergeants Mess - Room 328	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489869	Ground	WO and Sergeants Mess - Room 329	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489870	Ground	WO and Sergeants Mess - Room 330	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489871	Ground	WO and Sergeants Mess - Room 331	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489872	Ground	WO and Sergeants Mess - Room 332	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489873	Ground	WO and Sergeants Mess - Room 333	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489874	Ground	WO and Sergeants Mess - Room 334	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489875	Ground	WO and Sergeants Mess - Room 335	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489876	Ground	WO and Sergeants Mess - Room 336	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489877	Ground	WO and Sergeants Mess - Room 337	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489878	Ground	WO and Sergeants Mess - Room 338	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489879	Ground	WO and Sergeants Mess - Room 339	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489880	Ground	WO and Sergeants Mess - Room 340	1	Yes	panel on far wall near		No Action	0 No Risk	0 N/A
2	2489881	Ground	WO and Sergeants Mess - Room 341	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2489882	Ground	WO and Sergeants Mess - NW Bathroom	1	Yes	panel above door facing		No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central			
danie	Infra Orga	structure anisation			Asbesto	osReais	ter		carillion	amey
	2489883	Ground	WO and Sergeants Mess - NW Sttairwell	1		Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489795	Ground	WO and Sergeants Mess - Room 125	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489796	Ground	WO and Sergeants Mess - Room 126	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489797	Ground	WO and Sergeants Mess - Room 127	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489798	Ground	WO and Sergeants Mess - Room 128	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489799	Ground	WO and Sergeants Mess - Room 129	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489800	Ground	WO and Sergeants Mess - Room 130	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489801	Ground	WO and Sergeants Mess - Room 131	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489802	Ground	WO and Sergeants Mess - Room 132	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489803	Ground	WO and Sergeants Mess - Room 133	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489804	Ground	WO and Sergeants Mess - Room 134	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489805	Ground	WO and Sergeants Mess - Room 135	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489806	Ground	WO and Sergeants Mess - Room 136	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489807	Ground	WO and Sergeants Mess - Room 137	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489808	Ground	WO and Sergeants Mess - Room 139	1	Yes	panel in far corner		No Action	0 No Risk	0 N/A
	2489809	Ground	WO and Sergeants Mess - Room 140	1	Yes	panel above door		No Action	0 No Risk	0 N/A
	2489810	Ground	WO and Sergeants Mess - East corridor adjacent to	1	Yes	on wooden beams	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489811	Ground	WO and Sergeants Mess - Room 138	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489812	Ground	WO and Sergeants Mess - Room 139	1	Yes	far wall near window and		No Action	0 No Risk	0 N/A
	2489813	Ground	WO and Sergeants Mess - Room 140	1	Yes	panel on wall near		No Action	0 No Risk	0 N/A
	2489814	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489815	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	Black strip to edge of	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2489816	Ground	WO and Sergeants Mess - SE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A

	Defe	ence	R	Regiona	al Prime	e Contra	ct Central		<u>**</u>	
	Infra	structure anisation				osReais			carillion	amey
		Ground	WO and Sergeants Mess - Room 141 - Female Toilets	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489818	Ground	WO and Sergeants Mess - Room 200 Store	1	Yes	panel above door		No Action	0 No Risk	0 N/A
	2489819	Ground	WO and Sergeants Mess - Room 200 Store	1	Yes	Floor	Presumed Asbestos Content	Monitor	3 Very Low	0 N/A
$\prod$	2489820	External	WO and Sergeants Mess - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489821	Ground	WO and Sergeants Mess - Internal Cupboard Near Sou	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489822	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489823	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489824	Ground	WO and Sergeants Mess - South Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489825	Ground	WO and Sergeants Mess - Room 201	1	Yes	panel in left hand corner		No Action	0 No Risk	0 N/A
	2489826	Ground	WO and Sergeants Mess - Room 202	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489827	Ground	WO and Sergeants Mess - Room 203	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489828	Ground	WO and Sergeants Mess - Room 204	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489829	Ground	WO and Sergeants Mess - Room 205	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489830	Ground	WO and Sergeants Mess - Room 206 Store	1	Yes	panel to ceiling and		No Action	0 No Risk	0 N/A
	2489831	Ground	WO and Sergeants Mess - Room 207 Utility Room	1	Yes	panel above door		No Action	0 No Risk	0 N/A
	2489832	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489833	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
	2489834	Ground	WO and Sergeants Mess - SW Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
	2489835	Ground	WO and Sergeants Mess - Room 207 - Utility Room	1	Yes	panel on far r/h side wall		No Action	0 No Risk	0 N/A
	2489836	Ground	WO and Sergeants Mess - Corridor 8 (south corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489837	Ground	WO and Sergeants Mess - SW Bathroom	1	Yes	panel above the door in		No Action	0 No Risk	0 N/A
	2489838	Ground	WO and Sergeants Mess - Room 301	1	Yes	panels on end of wall		No Action	0 No Risk	0 N/A
	2489839	Ground	WO and Sergeants Mess - Room 302	1	Yes	panels on end of wall	No Asbestos Detected	No Action	0 No Risk	0 N/A

age of	Defe			Regiona	al Prime	<b>Contra</b>	act Central	•		
	Infra Orga	structure anisation				sReais			carillion	amey
	2489840	Ground	WO and Sergeants Mess - Room 303	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489841	Ground	WO and Sergeants Mess - Room 304	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489842	Ground	WO and Sergeants Mess - Room 305	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489843	Ground	WO and Sergeants Mess - Room 306	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489844	Ground	WO and Sergeants Mess - Room 307	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489845	Ground	WO and Sergeants Mess - Room 308	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489846	Ground	WO and Sergeants Mess - Room 309	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489847	Ground	WO and Sergeants Mess - Room 310	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489848	Ground	WO and Sergeants Mess - Room 311	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489849	Ground	WO and Sergeants Mess - Room 312	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ħŧ	2489850	Ground	WO and Sergeants Mess - Room 313	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489851	Ground	WO and Sergeants Mess - Room 314	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489852	Ground	WO and Sergeants Mess - Room 315	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489853	Ground	WO and Sergeants Mess - Room 316	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489854	Ground	WO and Sergeants Mess - Room 317	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489765	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Stairs (Nosings)	Chrysotile	Monitor	3 Very Low	0 N/A
Ш	2489766	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	panel above radiator		No Action	0 No Risk	0 N/A
$   \uparrow \uparrow  $	2489767	Ground	WO and Sergeants Mess - Bathroom	1	Yes	residue on redundant	No Asbestos Detected	No Action	0 No Risk	0 N/A
$   \uparrow \uparrow   $	2489768	Ground	WO and Sergeants Mess - Bathroom (adj Room 101)	1	Yes	false ceiling void (Debris)		No Action	0 No Risk	0 N/A
$   \uparrow   $	2489769	Ground	WO and Sergeants Mess - Bathroom (adj Room 101)	1	Yes	on ceiling tile near	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489770	Ground	WO and Sergeants Mess - Room 101	1	Yes	panel in corner of	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489771	Ground	WO and Sergeants Mess - Room 103	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489772	Ground	WO and Sergeants Mess - Room 105	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central		•	
	Infra Orga	structure anisation				osReais			carillion	amey
	2489773	Ground	WO and Sergeants Mess - Room 106	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489774	Ground	WO and Sergeants Mess - Room 107	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489775	Ground	WO and Sergeants Mess - Room 108	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489776	Ground	WO and Sergeants Mess - Room 109	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489777	Ground	WO and Sergeants Mess - Room 110	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489778	Ground	WO and Sergeants Mess - Room 111	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489779	Ground	WO and Sergeants Mess - Room 112	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489780	Ground	WO and Sergeants Mess - Room 113	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489781	Ground	WO and Sergeants Mess - Room 115	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489782	Ground	WO and Sergeants Mess - Room 116	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489783	Ground	WO and Sergeants Mess - Room 117	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489784	Ground	WO and Sergeants Mess - Room 118	1	Yes	panels in far corner next		No Action	0 No Risk	0 N/A
	2489785	Ground	WO and Sergeants Mess - Room 119	1	Yes	panels in far		No Action	0 No Risk	0 N/A
	2489786	Ground	WO and Sergeants Mess - Room 118	1	Yes	panels above door		No Action	0 No Risk	0 N/A
	2489787	Ground	WO and Sergeants Mess - East Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489788	Ground	WO and Sergeants Mess - East Stairwell	1	Yes	Black strip to edge of	Chrysotile	Monitor	3 Very Low	0 N/A
$\prod$	2489789	Ground	WO and Sergeants Mess - East Stairwell	1	Yes	panel above the radiator		No Action	0 No Risk	0 N/A
	2489790	Ground	WO and Sergeants Mess - Unisex Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489791	Ground	WO and Sergeants Mess - Room 121	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489792	Ground	WO and Sergeants Mess - Room 122	1	Yes	panels in far corner near		No Action	0 No Risk	0 N/A
	2489793	Ground	WO and Sergeants Mess - Room 123	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489794	Ground	WO and Sergeants Mess - Room 124	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489762	Ground	WO and Sergeants Mess - Main entrance porch	1	Yes	ceiling panels	No Asbestos Detected	No Action	0 No Risk	0 N/A

		ence	F	Regiona	al Prim	e Contra	act Central			
	Orga	astructure anisation				osReais			carillion	amey
	2489763	Ground	WO and Sergeants Mess - Main Accommodation Office	1	Yes	wall panels near window		No Action	0 No Risk	0 N/A
	2489764	Ground	WO and Sergeants Mess - NE Stairwell	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
НМ	S COLLINGV	VOOD - VOCAT	IONAL QALIFICATION CENTRE - 17890	15 - COLW01	000783				•	
	2491971	Ground	Classroom Block	1	Yes			No Action	0 No Risk	0 N/A
НМ	S COLLINGV	VOOD - VOLUN	ITEER CADET CORPS - 711064 - COLW	01000284						
	2488754	Ground	Buffers Store - Buffers Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488755	Ground	Buffers Store - Buffers Office Store	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488756	Ground	Buffers Store - Front Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488757	Roof	Buffers Store - Roof	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488758	Ground	Buffers Store - Paper Store	1	Yes	Floor (Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2488759	Ground	Buffers Store - Entrance Lobby	1	Yes	Floor (Red Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488760	Ground	Buffers Store - CBM1	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488761	Ground	Buffers Store - CBM Store Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488762	Ground	Buffers Store - CBM Workshop 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488763	Ground	Buffers Store - CBM Workshop 2	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488764	Ground	Buffers Store - CBM Staff Rest Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488765	Ground	Buffers Store - CBM Lobby (towards rear of bldg by	1	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488766	Ground	Buffers Store - CBM Toilet	1	Yes	Toilet	Amosite	Monitor	6 Low	0 N/A
	2488767	Ground	Buffers Store - CBM Toilet	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2488768	Ground	Buffers Store - RA Locker Rm, Shower Rm & Toilets	1	Yes	Roof Space	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488769	Ground	Buffers Store - RA Locker Rm Pipe Void	1	No	Pipe Void		No Action	0 No Risk	0 N/A
$\prod$	2488770	Ground	Buffers Store - RA Locker Room Porch Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488771	Ground	Buffers Store - Voluntary Cadet Corp Uniform Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488772	Ground	Buffers Store - Voluntary Cadet Corp Main Hall	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488773	Ground	Buffers Store - Voluntary Cadet Corp Office 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

No.	Defe			Regiona	al Prime	e Contra	ct Central			
	Infra Orga	structure anisation				osReais			carillion	amey
	2488774	Ground	Buffers Store - Voluntary Cadet Corp Office Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488775	Ground	Buffers Store - Voluntary Cadet Corp Office 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488776	Ground	Buffers Store - Voluntary Cadet Corp Office 2 - Fi	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488777	Ground	Buffers Store - Voluntary Cadet Corp Office 2 Cupb	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488778	Ground	Buffers Store - Girl Head Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488779	Ground	Buffers Store - Boys Head Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488780	Ground	Buffers Store - Voluntary Cadet Corp Classroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488781	Ground	Buffers Store - Voluntary Cadet Corp Classroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488782	Ground	Buffers Store - Voluntary Cadet Corp Classroom 3	1	Yes	Floor	Chrysotile	Monitor	5 Low	0 N/A
	2488783	Ground	Buffers Store - Voluntary Cadet Corp Classroom 4	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488784	Ground	Buffers Store - Voluntary Cadet Corp Store 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488785	Ground	Buffers Store - Voluntary Cadet Corp Store 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488786	Ground	Buffers Store - Voluntary Cadet Corps Rm 10	1	Yes	internal boxing to	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488787	Ground	Buffers Store - Voluntary Cadet Corps Rm 10	1	Yes	internal boxing to	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488788	Ground	Buffers Store - 007 toilets	1	Yes	Toilet	Amosite	Monitor	6 Low	0 N/A
	2488789	Ground	Buffers Store - 013 room	1	Yes	Floor (Green	Chrysotile	Monitor	5 Low	0 N/A
Ш	2488790	Ground	Buffers Store - 019 VCC classroom	1	Yes	Floor (Beige Tiles)	Chrysotile	Monitor	5 Low	0 N/A
	2488791	Ground	Buffers Store - external porch	1	Yes	Canopy	Amosite	Monitor	8 Low	0 N/A
	2488792	Ground	Buffers Store - store 2 003	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488793	Ground	Buffers Store - small store 004	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488794	Ground	Buffers Store - small store 004	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488795	Ground	Buffers Store - lobby to wc 006	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
$  \uparrow \uparrow  $	2488796	Ground	Buffers Store - 007 wc	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
$   \uparrow \uparrow   $	2488797	Ground	Buffers Store - 007 wc	1	Yes	ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central		carillion o	
	) Infra Orga	structure				osReais			carillion	amey
2	488798	Ground	Buffers Store - 007 wc	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488799	Ground	Buffers Store - 006 lobby to wc	1	Yes	Floor (Light Grey Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488800	Ground	Buffers Store - 008 store 3	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488801	Ground	Buffers Store - 009 locker room	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488802	Ground	Buffers Store - 012 office	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488803	Ground	Buffers Store - 013 office	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488804	Ground	Buffers Store - 001 room	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488805	Ground	Buffers Store - 001 room	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488806	Ground	Buffers Store - 002 store 1	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488807	Ground	Buffers Store - 003 store 2	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488808	Ground	Buffers Store - 014 ladies locker	1	Yes	panels to sloping side	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488809	Ground	Buffers Store - 015 wc shower	1	Yes	panels above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488810	Ground	Buffers Store - 015 wc shower	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488811	Ground	Buffers Store - 016 plant room	1	Yes	panels to sloping	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	488812	Ground	Buffers Store - 017 shower	1	Yes	panels above	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488813	Ground	Buffers Store - 017 shower	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488814	Ground	Buffers Store - 018 locker room	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488815	Ground	Buffers Store - 018 locker room	1	Yes	Floor (Beige Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488816	Ground	Buffers Store - 020 room	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488817	Ground	Buffers Store - 020 room	1	Yes	Floor (Brown /	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488818	Ground	Buffers Store - 021 one star training	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488819	Ground	Buffers Store - 021 one star training	1	Yes	Floor (Beige Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2	2488820	Ground	Buffers Store - 022 main room	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe		R	egiona	al Prim	e Contra	act Central			
		structure nisation				osReais			carillion	amey
248		Ground	Buffers Store - 022 main room	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88822	Ground	Buffers Store - 023 store	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88823	Ground	Buffers Store - 023 store	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88824	Ground	Buffers Store - 024 able cadet	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88825	Ground	Buffers Store - 024 able cadet	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88826	Ground	Buffers Store - 025 heads	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88827	Ground	Buffers Store - 025 heads	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88828	Ground	Buffers Store - 026 store	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88829	Ground	Buffers Store - 026 store	1	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88830	Ground	Buffers Store - 027 store	1	Yes	Ceiling Panels	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88831	Loft	Buffers Store - loft area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS CO	LLINGW	OOD - WALKE	R - 708021 - COLW01000477		I.		1		<u> </u>	
248	88895	Ground	Walker Conference Centre - administration office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	38896	Ground	Walker Conference Centre - corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88897	Ground	Walker Conference Centre - store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88898	Ground	Walker Conference Centre - head office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88899	Ground	Walker Conference Centre - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88900	Ground	Walker Conference Centre - Rest room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88901	Ground	Walker Conference Centre - plant room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88902	Roof	Walker Conference Centre - Roof	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88885	Ground	Walker Conference Centre - entrance lobby	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88886	Ground	Walker Conference Centre - electrical cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88887	Ground	Walker Conference Centre - cloakroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248	88888	Ground	Walker Conference Centre - male Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	ence	F	Regiona	l Prim	e Contra	act Central			
Infr Ord	astructure anisation				osReais			carillion	amey
2488889	Ground	Walker Conference Centre - copy	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		room							
2488890	Ground	Walker Conference Centre - ladies	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Toilet							
2488891	Ground	Walker Conference Centre - corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488892	Ground	Walker Conference Centre -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		classroom 1							
2488893	Ground	Walker Conference Centre - classroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488894	Ground	Walker Conference Centre -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		classroom 3							
HMS COLLING	NOOD - WARBU	JRTON-LEE VC SR SLA - 858096 - COLV	V01000762						
2487463	Ground	Warburton Lea Accommodation	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
HMS COLLING	NOOD - WARDF	ROOM ACCN 621 - 708042 - COLW01000	621		Dananig	1			
2491963	Ground	Officers Mess Accommodation	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLING	<u> </u>		1622						
2491964	Ground		1	Yes	<u> </u>	1	No Action	0 No Risk	0 N/A
		Officers Mess Accommodation		res			NO ACTION	UNO RISK	U IN/A
HMS COLLING	NOOD - WARDE	ROOM ACCN 724 - 708114 - COLW01000	724						
2488590	Ground	Wardroom Annexe Block - g/f Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488591	Ground	Wardroom Annexe Block - g/f Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488592	Ground	Wardroom Annexe Block - g/f Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488593	Ground	Wardroom Annexe Block - g/f Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
0.40050.4	0	3	4	\/	Th	No Ashastas Datastas	NI- A-G	ON- Dist	0.01/4
2488594	Ground	Wardroom Annexe Block - g/f Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488595	Ground	Wardroom Annexe Block - g/f Bathroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488596	Ground	Wardroom Annexe Block - g/f Bathroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488597	Ground	Wardroom Annexe Block - Room 156	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488598	Ground	Wardroom Annexe Block - Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488599	Ground	156A Wardroom Annexe Block - Room 155	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488600	Ground	Wardroom Annexe Block - Room	4	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2400000	Ground	155A	I	1 es	Throughout	NO Aspesios Defected	INO ACIIOII		
2488601	Ground	Wardroom Annexe Block - Room 157	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	1				1			i	

**Page:** 191 of 420

		ence	F	Regiona	al Prime	<b>Contra</b>	act Central		carillion	
1	Orga	astructure anisation				sReais			carillion	amey
	2488602	Ground	Wardroom Annexe Block - Room 157A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488603	Ground	Wardroom Annexe Block - Room 154	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488604	Ground	Wardroom Annexe Block - Room 154A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488605	Ground	Wardroom Annexe Block - Room 158	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488606	Ground	Wardroom Annexe Block - Room 158A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488607	Ground	Wardroom Annexe Block - Room 153	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488608	Ground	Wardroom Annexe Block - Room 153A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488609	Ground	Wardroom Annexe Block - Room 159	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488610	Ground	Wardroom Annexe Block - Room 159A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488611	Ground	Wardroom Annexe Block - Room 152	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488612	Ground	Wardroom Annexe Block - Room 152A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488613	Ground	Wardroom Annexe Block - Room 160	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488614	Ground	Wardroom Annexe Block - Room 160A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488615	Ground	Wardroom Annexe Block - Room 151	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488616	Ground	Wardroom Annexe Block - Room 151A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488617	Ground	Wardroom Annexe Block - g/f Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488618	First	Wardroom Annexe Block - f/f Stairs	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488619	First	Wardroom Annexe Block - f/f Baggage Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488620	First	Wardroom Annexe Block - f/f Cleaners	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488621	First	Wardroom Annexe Block - f/f Bathroom 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488622	First	Wardroom Annexe Block - f/f Bathroom 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488623	Ground	Wardroom Annexe Block - Room 166	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488624	Ground	Wardroom Annexe Block - Room 166A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Page:

192 of 420

Defence Infrastructure	Re	Regional Prime Contract Central									
Infr Org	astructure janisation				osReais			Carillion 0 No Risk	namey		
2488625	Ground	Wardroom Annexe Block - Room 165	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N		
2488626	Ground	Wardroom Annexe Block - Room 165A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488627	Ground	Wardroom Annexe Block - Room 167	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488628	Ground	Wardroom Annexe Block - Room 167A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488629	Ground	Wardroom Annexe Block - Room 164	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488630	Ground	Wardroom Annexe Block - Room 164A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488631	Ground	Wardroom Annexe Block - Room 168	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488632	Ground	Wardroom Annexe Block - Room 168A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488633	Ground	Wardroom Annexe Block - Room 163	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488634	Ground	Wardroom Annexe Block - Room 163A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488635	Ground	Wardroom Annexe Block - Room 169	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488636	Ground	Wardroom Annexe Block - Room 169A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488637	Ground	Wardroom Annexe Block - Room 162	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488638	Ground	Wardroom Annexe Block - Room 162A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488639	Ground	Wardroom Annexe Block - Room 170	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488640	Ground	Wardroom Annexe Block - Room 170A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488641	Ground	Wardroom Annexe Block - Room 161	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488642	Ground	Wardroom Annexe Block - Room 161A	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		
2488643	First	Wardroom Annexe Block - f/f Laundry Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 0		
2488644	First	Wardroom Annexe Block - f/f Utility Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	10		
2488645	First	Wardroom Annexe Block - f/f Corridor 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 0		
2488646	First	Wardroom Annexe Block - f/f Corridor 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 0		
2488647	First	Wardroom Annexe Block - f/f Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N		

Infr	ence astructure	F	_	_		act Central		carillion	ameri
Org	anisation				<u>osReais</u>		_	Carinion	1amey/
2487461	Ground	Classroom (Warspite)	1	Yes	Throughout Building	No Asbestos Detected	No Action	0 No Risk	0 N/A
15 COLLING		ON JR ACCOMMODATION - 708107 - CO	LW01000709						
2488534	Second	Accommodation Block - s/f Flat 44C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488535	Second	Accommodation Block - s/f Flat 44C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488536	Second	Accommodation Block - s/f Flat 44C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488537	Second	Accommodation Block - s/f Flat 44C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488538	Second	Accommodation Block - s/f Flat 44C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488539	Second	Accommodation Block - s/f Flat 45C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488540	Second	Accommodation Block - s/f Flat 45C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488541	Second	Accommodation Block - s/f flat 45C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488542	Second	Accommodation Block - s/f Flat 45C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488543	Second	Accommodation Block - s/f Flat 45C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488544	Second	Accommodation Block - s/f Flat 45C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488545	Second	Accommodation Block - s/f Flat 46C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2488546	Second	Accommodation Block - s/f Flat 46C - electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488547	Second	Accommodation Block - s/f Flat 46C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488548	Second	Accommodation Block - s/f Flat 46C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488549	Second	Accommodation Block - s/f Flat 46C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2488550	Second	Accommodation Block - s/f Flat 46C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2488551	Second	Accommodation Block - s/f Flat 46C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2488552	Second	Accommodation Block - s/f Flat 47C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2488553	Second	Accommodation Block - s/f Flat 47C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//
2488554	Second	Accommodation Block - s/f Flat 47C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/
2488555	Second	Accommodation Block - s/f Flat 47C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N//

	Defe			Regiona	al Prime	e Contra	act Central	-		
	Infra Orga	structure anisation				osReais			carillion	amey
	2488556	Second	Accommodation Block - s/f Flat 47C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488557	Second	Accommodation Block - s/f Flat 47C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488558	Second	Accommodation Block - s/f Flat 47C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488559	Second	Accommodation Block - s/f Flat 48C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488560	Second	Accommodation Block - s/f Flat 48C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488561	Second	Accommodation Block - s/f Flat 48C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488506	Second	Accommodation Block - s/f Flat 40C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488507	Second	Accommodation Block - s/f Flat 40C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488508	Second	Accommodation Block - s/f Flat 40C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488509	Second	Accommodation Block - s/f Flat 40C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488510	Second	Accommodation Block - s/f Flat 40C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488511	Second	Accommodation Block - s/f Flat 41C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488512	Second	Accommodation Block - s/f Flat 41C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488513	Second	Accommodation Block - s/f Flat 41C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488514	Second	Accommodation Block - s/f Flat 41C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488515	Second	Accommodation Block - s/f Flat 41C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488516	Second	Accommodation Block - s/f Flat 41C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488517	Second	Accommodation Block - s/f Flat 41C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488518	Second	Accommodation Block - s/f Flat 42C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488519	Second	Accommodation Block - s/f Flat 42C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488520	Second	Accommodation Block - s/f Flat 42C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2488521	Second	Accommodation Block - s/f Flat 42C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488522	Second	Accommodation Block - s/f Flat 42C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

STATE OF THE PARTY	Defence Infrastructure Organisation			Regiona	•	carillionamey				
8	Infra Orga	structure				osReais			carillion	amey
	2488523	Second	Accommodation Block - s/f Flat 42C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488524	Second	Accommodation Block - s/f Flat 42C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488525	Second	Accommodation Block - s/f Flat 43C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488526	Second	Accommodation Block - s/f Flat 43C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488527	Second	Accommodation Block - s/f Flat 43C - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488528	Second	Accommodation Block - s/f Flat 43C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488529	Second	Accommodation Block - s/f Flat 43C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488530	Second	Accommodation Block - s/f Flat 43C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488531	Second	Accommodation Block - s/f Flat 43C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488532	Second	Accommodation Block - s/f Flat 44C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488533	Second	Accommodation Block - s/f Flat 44C - Electrical cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488450	First	Accommodation Block - f/f Flat 40B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488451	First	Accommodation Block - f/f Flat 40B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488452	First	Accommodation Block - f/f Flat 40B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488453	First	Accommodation Block - f/f Flat 40B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488454	First	Accommodation Block - f/f F/at 40B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488455	First	Accommodation Block - f/f Flat 40B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488456	First	Accommodation Block - f/f Flat 41B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488457	First	Accommodation Block - f/f Flat 41B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488458	First	Accommodation Block - f/f Flat 41B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488459	First	Accommodation Block - f/f Flat 41B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488460	First	Accommodation Block - f/f Flat 41B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488461	First	Accommodation Block - f/f Flat 41B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

200	Defe			Regiona	al Prime	e Contra	act Central	-		
	Infra Orga	structure anisation				osReais			carillion	amey
		First	Accommodation Block - f/f Flat 41B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488463	First	Accommodation Block - f/f Flat 42B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488464	First	Accommodation Block - f/f Flat 42B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488465	First	Accommodation Block - f/f Flat 42B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488466	First	Accommodation Block - f/f Flat 42B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488467	First	Accommodation Block - f/f Flat 42B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488468	First	Accommodation Block - f/f Flat 42B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488469	First	Accommodation Block - f/f Flat 42B - storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488470	First	Accommodation Block - f/f Flat 44B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488471	First	Accommodation Block - f/f Flat 44B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488472	First	Accommodation Block - f/f Flat 44B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488473	First	Accommodation Block - f/f Flat 44B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488474	First	Accommodation Block - f/f Flat 44B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488475	First	Accommodation Block - f/f Flat 44B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488476	First	Accommodation Block - f/f Flat 44B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488477	First	Accommodation Block - f/f Flat 45B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488478	First	Accommodation Block - f/f Flat 45B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488479	First	Accommodation Block - f/f Flat 45B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488480	First	Accommodation Block - f/f Flat 45B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488481	First	Accommodation Block - f/f Flat 45B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488482	First	Accommodation Block - f/f Flat 45B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488483	First	Accommodation Block - f/f Flat 45B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488484	First	Accommodation Block - f/f Flat 46B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

200	Defe			Regiona	al Prime	e Contra	act Central	-		
	Orga	structure anisation			Ashest	osReais	ter		carillion	amey
	2488485	First	Accommodation Block - f/f Flat 46B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488486	First	Accommodation Block - f/f Flat 46B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488487	First	Accommodation Block - f/f Flat 46B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488488	First	Accommodation Block - f/f Flat 46B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488489	First	Accommodation Block - f/f Flat 46B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488490	First	Accommodation Block - f/f Flat 46B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488491	First	Accommodation Block - f/f Flat 47B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488492	First	Accommodation Block - f/f Flat 47B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488493	First	Accommodation Block - f/f Flat 47B - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488494	First	Accommodation Block - f/f Flat 47B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488495	First	Accommodation Block - f/f Flat 47B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488496	First	Accommodation Block - f/f Flat 47B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488497	First	Accommodation Block - f/f Flat 47B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488498	First	Accommodation Block - f/f Flat 48B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488499	First	Accommodation Block - f/f Flat 48B - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488500	First	Accommodation Block - f/f Flat 48B - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488501	First	Accommodation Block - f/f Flat 48B - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488502	First	Accommodation Block - f/f Flat 48B - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488503	First	Accommodation Block - f/f Flat 48B - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2488504	Second	Accommodation Block - s/f F/at 40C - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488505	Second	Accommodation Block - s/f Flat 40C - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488422	Ground	Accommodation Block - g/f Flat 44A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488423	Ground	Accommodation Block - g/f Flat 46A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

4	Defe			Regiona	al Prime	e Contra	act Central	•		
8	Infra Orga	structure anisation			Ashest	osReais	ter		carillion	amey
	2488424	Ground	Accommodation Block - g/f Flat 46A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488425	Ground	Accommodation Block - g/f Flat 46A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488426	Ground	Accommodation Block - g/f Flat 46a - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488427	Ground	Accommodation Block - g/f Flat 46A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488428	Ground	Accommodation Block - g/f Flat 46A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488429	Ground	Accommodation Block - g/f Flat 46A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488430	Ground	Accommodation Block - g/f Flat 47A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488431	Ground	Accommodation Block - g/f Flat 47a - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488432	Ground	Accommodation Block - g/f Flat 47A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488433	Ground	Accommodation Block - g/f Flat 47A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488434	Ground	Accommodation Block - g/f Flat 47A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488435	Ground	Accommodation Block - g/f Flat 47A - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488436	Ground	Accommodation Block - g/f Flat 47A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488437	Ground	Accommodation Block - Block 48 Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488438	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488439	Ground	Accommodation Block - Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488440	Ground	Accommodation Block - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488441	Ground	Accommodation Block - 1/2 Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488442	Ground	Accommodation Block - 48a - sitting room corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488443	Ground	Accommodation Block - 48a - Main Sitting room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488444	Ground	Accommodation Block - 48a - Study room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488445	Ground	Accommodation Block - 48a - Electrical cupboard /	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488446	Ground	Accommodation Block - 48a - Mens toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central		carillion	
	Infra Orga	structure			Asbesto	osReais	ter		carillion	amey
24		Ground	Accommodation Block - 48a - Ladies Toilet	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188448	Ground	Accommodation Block - 48a - Staff Cleaning office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188449	First	Accommodation Block - f/f Flat 40B - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188413	Ground	Accommodation Block - Electrical cupboard / Pipe R	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188414	Ground	Accommodation Block - g/f Flat 43A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188415	Ground	Accommodation Block - g/f Flat 43A - electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188416	Ground	Accommodation Block - g/f Flat 44A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188417	Ground	Accommodation Block - g/f Flat 44A - electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188418	Ground	Accommodation Block - g/f Flat 44A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188419	Ground	Accommodation Block - g/f Flat 44A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188420	Ground	Accommodation Block - g/f Flat 44a - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188421	Ground	Accommodation Block - g/f Flat 44a - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188562	Second	Accommodation Block - s/f Flat 48C - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188563	Second	Accommodation Block - s/f Flat 48C - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188564	Second	Accommodation Block - s/f Flat 48C - All Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188565	Second	Accommodation Block - s/f Flat 48C - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188371	Ground	Accommodation Block - Stairwell - Ground , 1st 7 2	1	Yes	Side of Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188372	Ground	Accommodation Block - g/f Flat 40A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188373	Ground	Accommodation Block - g/f Flat 40A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188374	Ground	Accommodation Block - g/f Flat 40A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188375	Ground	Accommodation Block - g/f Flat 40A - Drying room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188376	Ground	Accommodation Block - g/f Flat 40A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
24	188377	Ground	Accommodation Block - g/f Flat 40A - all Cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	Defe			Regiona	al Prime	e Contra	act Central	-		
danie	Infra Orga	structure anisation			Ashesto	osReais	ter		carillion	amey
	2488378	Ground	Accommodation Block - g/f Flat 40A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488379	Ground	Accommodation Block - g/f Flat 41A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488380	Ground	Accommodation Block - g/f Flat 41A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488381	Ground	Accommodation Block - g/f Flat 41A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488382	Ground	Accommodation Block - g/f Flat 41A - Drying Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488383	Ground	Accommodation Block - g/f Flat 41A - Bathroom	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488384	Ground	Accommodation Block - g/f Flat 41A - All cabins	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488385	Ground	Accommodation Block - g/f Flat 41A - Storage Cupbo	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488386	Ground	Accommodation Block - Payphone	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488387	Ground	Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488388	Ground	Accommodation Block - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488389	Ground	Accommodation Block - 1/2 Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488390	Ground	Accommodation Block - Electrical Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488391	Ground	Accommodation Block - g/f Flat 42A - sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488392	Ground	Accommodation Block - g/f Flat 42A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488393	Ground	Accommodation Block - g/f Flat 42A - Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488394	Ground	Accommodation Block - g/f Flat 42A - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488395	Ground	Accommodation Block - g/f Flat 42A - Storage Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488396	Ground	Accommodation Block - g/f Flat 42a - Main Sitting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488397	Ground	Accommodation Block - g/f Flat 42A - Sitting Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2488398	Ground	Accommodation Block - g/f Flat 43A - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2488399	Ground	Accommodation Block - g/f Flat 43A - Electrical Cu	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2488400	Ground	Accommodation Block - g/f Flat 43A - Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

	efence	F	Regiona	al Prim	e Contra	act Central			<b>A</b>
In O	frastructure organisation			Asbest	osReais	ster		carillion	amey
248840		Accommodation Block - g/f Flat 43A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Drying Room							
2488402	2 Ground	Accommodation Block - g/f Flat 43A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Bathroom							
248840	3 Ground	Accommodation Block - g/f Flat 43A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
0.400.40	4 0	All cabins			<u> </u>		AL A d	ON BU	0.11/4
2488404	4 Ground	Accommodation Block - g/f Flat 43A -	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
248840	5 Ground	Storage Cupbo  Accommodation Block - Cupboard	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
240040	Giodila	Accommodation Block - Cupboard	'	165	Triloughout	NO Aspesios Defected	NO ACTION	U INO RISK	U IN/A
248840	6 Ground	Accommodation Block - Electrical	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2400400	Olouna	Cupboard	'	100	Trilloughout	140 / lobesies Delected	140 7100011	o No Kisk	014//
248840	7 Ground	Accommodation Block - Main Sitting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Room	_						
248840	8 Ground	Accommodation Block - Study Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		,							
2488409	9 Ground	Accommodation Block - 45a Sitting	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Room							
2488410	0 Ground	Accommodation Block - 45a - Ladies	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Toilet							
248841	1 Ground	Accommodation Block - 45a - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	_								
2488412	2 Ground	Accommodation Block - 45a Storage	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	10141000 141545	Room	001 14/04 1/1/	VD004					
HMS COLLIN	IGWOOD - WEAT	HER PROTECTION SHELTER - 2542632	- COLW01XV	VP001					
249199	1 Ground	Weather Protection Shelter	1	Yes			No Action	0 No Risk	0 N/A
HMS COLLIN	IGWOOD - WOOD	ENTOTS NURSERY - 708026 - COLW010	000525			•	•		•
2489513	3 Roof Space	Crèche / Childcare Facility - ceiling	1	Yes	Throughout		No Action	0 No Risk	0 N/A
	Troor opaco	void and roo	•	100	Imougnout		7 (01/01/		014//
2489514	4 Roof Space	Crèche / Childcare Facility - roof	1	Yes	Roof Space	No Asbestos Detected	No Action	0 No Risk	0 N/A
		space			Beams				
248951	5 Ground	Crèche / Childcare Facility - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		,							
248951	6 Ground	Crèche / Childcare Facility - Work	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		room / Dining							
248951	7 Ground	Crèche / Childcare Facility - Main	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Room / Play are							
2489518	8 Ground	Crèche / Childcare Facility - Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489519	9 Ground	Crèche / Childcare Facility - Staff	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Room				-			
2489520	0 Ground	Crèche / Childcare Facility - Arts &	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
0.2222		Crafts			 	 	IN A C		0.111
248952	1 Ground	Crèche / Childcare Facility - Covered	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
		Limit							

	Defe	ence astructure	F	carillionamey						
The state of the s	Orga	anisation		<i></i>	Asbest	osReais	ster		carillion	amey
	2489522	Ground	Crèche / Childcare Facility - General Store	1	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489523	Ground	Crèche / Childcare Facility - Electrical Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489524	Ground	Crèche / Childcare Facility - Calorifier Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489525	Ground	Crèche / Childcare Facility - Baby Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489526	Ground	Crèche / Childcare Facility - WC / Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489527	Ground	Crèche / Childcare Facility - Sleep Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489528	Ground	Crèche / Childcare Facility - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489529	Ground	Crèche / Childcare Facility - Staff WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489530	Ground	Crèche / Childcare Facility - Feed Prep	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2489531	Ground	Crèche / Childcare Facility - Baby Change Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489532	Ground	Crèche / Childcare Facility - Baby Room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489533	External	Crèche / Childcare Facility - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
HN	IS COLLINGY	VOOD - WOODI	ENTOTS NURSERY - 708030 - COLW010	00503		•	<b>.</b>	•		
	2489507	Ground	Crèche / Childcare Facility - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489508	Ground	Crèche / Childcare Facility - Staff WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2489509	Ground	Crèche / Childcare Facility - Feed Prep	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489510	Ground	Crèche / Childcare Facility - Baby Change Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\prod$	2489511	Ground	Crèche / Childcare Facility - Baby Room 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489512	External	Crèche / Childcare Facility - External	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489492	Roof Space	Crèche / Childcare Facility - ceiling void and roo	1	Yes	Throughout		No Action	0 No Risk	0 N/A
	2489493	Roof Space	Crèche / Childcare Facility - roof space	1	Yes	Roof Space Beams	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489494	Ground	Crèche / Childcare Facility - kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
$\parallel$	2489495	Ground	Crèche / Childcare Facility - Work room / Dining	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2489496	Ground	Crèche / Childcare Facility - Main Room / Play are	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Page:

203 of 420

Run By:

Defence Infrastructure		R	Carillian amou						
Orga	anisation			<u>Asbeste</u>				carillioi	1 amey /
2489497	Ground	Crèche / Childcare Facility - Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489498	Ground	Crèche / Childcare Facility - Staff Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489499	Ground	Crèche / Childcare Facility - Arts & Crafts	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489500	Ground	Crèche / Childcare Facility - Covered Limit	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489501	Ground	Crèche / Childcare Facility - General Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489502	Ground	Crèche / Childcare Facility - Electrical Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489503	Ground	Crèche / Childcare Facility - Calorifier Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489504	Ground	Crèche / Childcare Facility - Baby Room 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489505	Ground	Crèche / Childcare Facility - WC / Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489506	Ground	Crèche / Childcare Facility - Sleep Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
S COLLINGW	VOOD - WORKS	SHOP - 708027 - COLW01000514						1	
			1	Voc	Throughout	No Ashastas Datastad	No Action	O No Pick	0 N/A
2409039	Ground	Jet Ski Store / Workshop - Office	ı	165	Throughout	No Aspesios Defected	No Action	O INO KISK	
2489040	Ground	Jet Ski Store / Workshop - File 1	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489041	Ground	Jet Ski Store / Workshop - File 2	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489042	Ground	Jet Ski Store / Workshop - File 3	1	Yes	Floor (Brown	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489043	Ground	Jet Ski Store / Workshop - File 3	1	Yes	Floor (Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489044	Ground	Jet Ski Store / Workshop - File 4	1	Yes	Roof	Presumed Asbestos Content	Monitor	8 Low	0 N/A
2489045	Ground	Jet Ski Store / Workshop - Library	1	Yes	Floor (Green Tiles)	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489046	Ground	Jet Ski Store / Workshop - Internal Workshop	1	Yes	Ceiling / Roof	Presumed Asbestos Content	Monitor	8 Low	0 N/A
2489047	Ground	Jet Ski Store / Workshop - Male WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489048	Ground	Jet Ski Store / Workshop - Rest Room	1	Yes	Roof	Presumed Asbestos Content	Monitor	8 Low	0 N/A
2489049	Ground	Jet Ski Store / Workshop - Female WC	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
2489050	Roof	Jet Ski Store / Workshop - Roof	1	Yes	Roof / Plant Room Roof	Presumed Asbestos Content	Monitor	6 Low	0 N/A
2489051	Ground	Jet Ski Store / Workshop - Boiler House	1	Yes	Boiler (Residue)	Amosite and Chrysotile	Control Access	12 Medium	0 N/A
	2489497 2489498 2489499 2489500 2489501 2489502 2489503 2489504 2489505 2489506 S COLLINGV 2489039 2489040 2489041 2489042 2489042 2489045 2489045 2489046 2489047 2489048 2489049	Infrastructure	Crèche / Childcare Facility - Office	Crèche / Childcare Facility - Office	Crèche / Childcare Facility - Office	AsbestosRedia   2489497   Ground   Crèche / Childcare Facility - Office   1   Yes   Throughout   2489498   Ground   Crèche / Childcare Facility - Staff   1   Yes   Throughout   2489499   Ground   Crèche / Childcare Facility - Arns & 1   Yes   Throughout   2489500   Ground   Crèche / Childcare Facility - Covered   1   Yes   Throughout   2489501   Ground   Crèche / Childcare Facility - Covered   1   Yes   Throughout   Limit   Yes   Throughout   2489501   Ground   Crèche / Childcare Facility - General   1   Yes   Throughout   Store   2489502   Ground   Crèche / Childcare Facility - Electrical   1   Yes   Throughout   Store   2489503   Ground   Crèche / Childcare Facility - Baby   1   Yes   Throughout   Store   2489504   Ground   Crèche / Childcare Facility - Baby   1   Yes   Throughout   Store   2489505   Ground   Crèche / Childcare Facility - Baby   1   Yes   Throughout   Store   2489505   Ground   Crèche / Childcare Facility - Steep   1   Yes   Throughout   Store   2489506   Ground   Crèche / Childcare Facility - Steep   1   Yes   Throughout   Store   2489506   Ground   Crèche / Childcare Facility - Steep   1   Yes   Throughout   Store   SCOLLINGWOOD - WORKSHOP - 708027 - COLW01000514   2489040   Ground   Jet Ski Store / Workshop - File 1   1   Yes   Throughout   2489040   Ground   Jet Ski Store / Workshop - File 2   1   Yes   Throughout   2489041   Ground   Jet Ski Store / Workshop - File 3   1   Yes   Floor (Brown   2489042   Ground   Jet Ski Store / Workshop - File 3   1   Yes   Floor (Brown   2489044   Ground   Jet Ski Store / Workshop - File 3   1   Yes   Floor (Brown   2489045   Ground   Jet Ski Store / Workshop - File 4   1   Yes   Floor (Green   Tiles)   2489046   Ground   Jet Ski Store / Workshop - File 4   1   Yes   Floor (Green   Tiles)   2489046   Ground   Jet Ski Store / Workshop - File 4   1   Yes   Floor (Green   Tiles)   2489046   Ground   Jet Ski Store / Workshop - File 4   1   Yes   Floor (Green   Tiles)   2489048   Ground   Jet Ski Store / Workshop - File 4   1   Yes   Throughout   2489049	Asbestos Reaister   Crèche / Childcare Facility - Office   1 Yes   Throughout   No Asbestos Detected   Room   Crèche / Childcare Facility - Staff   Room   Throughout   No Asbestos Detected   Room   Crèche / Childcare Facility - Arts & Crafts   Throughout   No Asbestos Detected   Room   Crèche / Childcare Facility - Arts & Crafts   Throughout   No Asbestos Detected   Creche / Childcare Facility - Covered   Throughout   No Asbestos Detected   Limit   Crèche / Childcare Facility - Covered   Throughout   No Asbestos Detected   Limit   Yes   Throughout   No Asbestos Detected   Limit   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - General   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - Electrical   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - Calorifler   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - Calorifler   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - WC / Store   Yes   Throughout   No Asbestos Detected   Store   Crèche / Childcare Facility - WC / Store   Yes   Throughout   No Asbestos Detected   Yes   Throughout   No Asbestos Detected   Store   Yes   Throughout   No Asbestos Detected   Store   Yes   Throughout   No Asbestos Detected   Yes   Throughout   Yes   Throughout   No Asbes	Asbesto   Realiston   Créche / Childcare Facility - Office   1   Yes   Throughout   No Asbestos Detected   No Action   No Ac	Asbestos Realister Cartillion Stores (Cartillion Cartellion (Cartellion Cartellion Cartellion Cartellion (Cartellion Cartellion Cartellion Cartellion (Cartellion Cartellion Cartellion Cartellion Cartellion (Cartellion Cartellion Cartellion Cartellion Cartellion Cartellion Cartellion (Cartellion Cartellion Ca

Page:

204 of 420

Run By:

	Defence			Regiona	al Prime	e Contra	act Central		carillionamey		
dental	Orga	structure anisation				osReais			carillio	n amey >	
	2489052	Ground	Jet Ski Store / Workshop - Boiler House	1	Yes	Flue to boiler	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2489053	Ground	Jet Ski Store / Workshop - Boiler House	1	Yes	Front of Boiler	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2489054	Ground	Jet Ski Store / Workshop - Boiler House	1	Yes	Back of Boiler	Chrysotile	Monitor	5 Low	0 N/A	
HN	IS COLLINGV	VOOD - WSM O	FFICES / COMPOUND - 708059 - COLW	01000640							
Ш	2491051	Ground	Jackson Galley - Foyer	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	2 No.	
	2491052	Ground	Jackson Galley - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2491053	Ground	Jackson Galley - D10 Switch Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2491054	Ground	Jackson Galley - Store 1 (now main office)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	2 No.	
$\prod$	2491055	Ground	Jackson Galley - Store 2 (now main office)	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
Ш	2491056	Ground	Jackson Galley - Store 2 Kitchen (now main office)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A	
	2491057	Ground	Jackson Galley - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2491058	Ground	Jackson Galley - Cleaners Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A	
	2492421	Ground	Jackson Galley - 15 Male Changing Room	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492422	Ground	Jackson Galley - 16 Dry Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492423	Ground	Jackson Galley - 17 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492424	Ground	Jackson Galley - 18 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492425	Ground	Jackson Galley - 19 Office	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
	2492426	Ground	Jackson Galley - 20 Cleaners Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
	2492427	Ground	Jackson Galley - 21 Corridor 2	1	Yes	Pipe Flanges	Presumed Asbestos Content	Monitor	8 Low	2 No.	
	2492428	Ground	Jackson Galley - 22 Porch	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492429	Ground	Jackson Galley - 23 Dry Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
	2492430	Ground	Jackson Galley - 24 Vegetable Prep	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
	2492431	Ground	Jackson Galley - 25 Raw Meat Prep	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
Ш	2492432	Ground	Jackson Galley - 26 Walk In Freezer	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
HH	2492433	Ground	Jackson Galley - 27 Pot Wash	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
H	2492434	Ground	Jackson Galley - 28 Corridor	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	
H	2492435	Ground	Jackson Galley - 29 Porch	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A	

	Defence			•	carillionamey					
	Infra Orga	structure anisation			Ashesto	osReais	ter		carillion	amey
ПТ	2492436	Ground	Jackson Galley - 30 Kitchen	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492437	Ground	Jackson Galley - 31 Cellar	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492438	Ground	Jackson Galley - 32 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492439	Ground	Jackson Galley - 33 Cold Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492440	Ground	Jackson Galley - 34 Cold Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492441	Ground	Jackson Galley - 35 Servery	1	Yes	Ductwork	No Asbestos Detected	No Action	0 No Risk	1 LM
$\prod$	2492442	Ground	Jackson Galley - 35 Servery	1	Yes	Door Header	No Asbestos Detected	No Action	0 No Risk	4 m2
	2492443	Ground	Jackson Galley - 35 Servery	1	Yes	Skylight Upstands	Amosite and Chrysotile	Monitor	9 <mark>Medium</mark>	16 m2
	2492444	Ground	Jackson Galley - 36 Store	1	Yes	Boxing	Amosite and Chrysotile	Monitor	9 <mark>Medium</mark>	3 m2
	2492445	Ground	Jackson Galley - 36 Store	1	Yes	Grey Plaster	No Asbestos Detected	No Action	0 No Risk	12 m2
$\prod$	2492446	Ground	Jackson Galley - 36 Store	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
$\prod$	2492447	Ground	Jackson Galley - 37 Store	1	Yes	Panels to Ceiling and	Amosite and Chrysotile	Remove	10 <mark>Medium</mark>	3 m2
	2492448	Ground	Jackson Galley - 37 Store	1	Yes	Panels to Ceiling and	Crocidolite and Chrysotile	Remove	10 Medium	3 m2
	2492449	Ground	Jackson Galley - 38 Tea Point	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
П	2492450	Ground	Jackson Galley - 39 Store	1	Yes	Paint to Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
	2492451	Ground	Jackson Galley - 40 Servery	1	Yes	Expansion Joint	No Asbestos Detected	No Action	0 No Risk	12 LM
	2491059	Ground	Jackson Galley - Lobby Outside Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491060	Ground	Jackson Galley - Mens Toilet	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491061	Ground	Jackson Galley - Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491062	Ground	Jackson Galley - CCTV Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491063	Ground	Jackson Galley - Conference Room (now archive stor	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491064	Ground	Jackson Galley - Call Centre (now rest room)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491065	Ground	Jackson Galley - Recreation Room (now kitchen)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491066	Ground	Jackson Galley - Electrical Workshop (now training	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	4 No.
	2491067	Ground	Jackson Galley - Plumbers Shop	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	2 No.
	2491068	Ground	Jackson Galley - Locker Room	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A


		ence	Re	aiona	l Prim	e Contra	act Central		**	
		astructure anisation		_	_	osRegis			carillion	amey
	2491069	Ground	Jackson Galley - Chippies Toilet (now store)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491070	Ground	Jackson Galley - Chippies (now store)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
Ш	2491071	Ground	Jackson Galley - Machine Shop	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491072	Ground	Jackson Galley - Machine Shop	1	Yes	Panels to AC unit	No Asbestos Detected	No Action	0 No Risk	0 N/A
П	2491073	Ground	Jackson Galley - Archive / IT	1	Yes	Window Sill		No Action	0 No Risk	0 N/A
	2491074	Ground	Jackson Galley - Archive / IT Comm Equipment Stora	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491075	Ground	Jackson Galley - Store 3	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491076	Ground	Jackson Galley - Workshop	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491077	Ground	Jackson Galley - Beneath Stairs	1	Yes	Panel to underside of	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491078	Ground	Jackson Galley - office/kitchen (now office 2)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491079	Ground	Jackson Galley - AP Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491080	Ground	Jackson Galley - Inflammable Store	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491081	Ground	Jackson Galley - Schedule B Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
Ш	2491082	Ground	Jackson Galley - Assett office (now office 4)	1	Yes	Window Sill	Chrysotile	Monitor	6 Low	0 N/A
	2491083	First	Jackson Galley - D12 Site Manager	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491084	First	Jackson Galley - D13 Admin Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491085	First	Jackson Galley - D17 Kitchen	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491086	First	Jackson Galley - D18 Small Passage Outside Toilets	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491087	First	Jackson Galley - D19 Ladies Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2492452	Ground	Jackson Galley - 40 Servery	1	Yes	Edges of Quarry Tile	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492453	Ground	Jackson Galley - 40 Servery	1	Yes	Ductwork	No Asbestos Detected	No Action	0 No Risk	1 m2
ПТ	2492454	Ground	Jackson Galley - 40 Servery	1	Yes	Beneath	Chrysotile	Monitor	6 Low	20 m2
	2492455	Ground	Jackson Galley - 40 Servery	1	Yes	Felt to Skylight	No Asbestos Detected	No Action	0 No Risk	8 LM
	2492456	Ground	Jackson Galley - 41 Servery	1	Yes	Pipework Flange	No Asbestos Detected	No Action	0 No Risk	1 No.
$\Box$	2492457	Ground	Jackson Galley - 42 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A

	Defence Infrastructure Organisation		R		carillion amey  0 No Risk 0 N/A					
				A:	sbesto	sRegis	ter		carillion amey >	
	2492458	Ground	Jackson Galley - 43 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492459	Ground	Jackson Galley - 44 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492460	Ground	Jackson Galley - 45 Plant Room	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492461	Ground	Jackson Galley - 46 Store	1	Yes	Ductwork Joints (Seal)	No Asbestos Detected	No Action	0 No Risk	8 LM
	2492462	Ground	Jackson Galley - 46 Store	1	Yes	Paint to Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
	2492463	Ground	Jackson Galley - 46 Store	1	Yes	Ductwork (Putty)	No Asbestos Detected	No Action	0 No Risk	8 LM
HH	2492464	Ground	Jackson Galley - 47 Store	1	Yes	(i dity)	No Sample Required	No Action	0 No Risk	0 N/A
	2492465	Ground	Jackson Galley - 48 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492466	Ground	Jackson Galley - 49 Cupboard	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492467	Ground	Jackson Galley - 50 Store	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492468	Ground	Jackson Galley - 51 Corridor	1	Yes	Paint to Walls	No Asbestos Detected	No Action	0 No Risk	100 m2
	2492469	Ground	Jackson Galley - 52 Office	1	Yes	Skylight	Chrysotile	Control Access	10 <mark>Medium</mark>	1 m2
	2492470	Ground	Jackson Galley - 52 Office	1	Yes	Floor (Blue Tiles)	No Asbestos Detected	No Action	0 No Risk	12 m2
	2492471	Ground	Jackson Galley - 52 Office	1	Yes	Floor	Chrysotile	Monitor	6 Low	12 m2
	2492472	Ground	Jackson Galley - 53 Corridor	1	Yes	Floor (Blue Tiles)	No Asbestos Detected	No Action	0 No Risk	3 m2
	2492473	Ground	Jackson Galley - 53 Corridor	1	Yes	Floor	Chrysotile	Monitor	5 Low	3 m2
	2492474	Ground	Jackson Galley - 53 Corridor	1		Ductwork (Debris)	Amosite and Chrysotile	Control Access	12 Medium	1 m2
	2492475	Ground	Jackson Galley - 54 Rest Room	1	Yes	Ductwork (Debris)	Amosite and Chrysotile	Control Access	13 Medium	1 m2
	2492476	Ground	Jackson Galley - 54 Rest Room	1	Yes	Floor (Blue Tiles)	No Asbestos Detected	No Action	0 No Risk	15 m2
	2492477	Ground	Jackson Galley - 54 Rest Room	1	Yes	Floor	Chrysotile	Monitor	7 Low	15 m2
	2492478	Ground	Jackson Galley - 55 Toilet	1	Yes	Ductwork (Debris)	Amosite and Chrysotile	Control Access	12 Medium	1 m2
	2492479	Ground	Jackson Galley - 56 Rest Room	1	Yes	Floor	Chrysotile	Monitor	7 Low	6 m2
	2492480	Ground	Jackson Galley - 56 Rest Room	1	Yes	Floor	Chrysotile	Monitor	7 Low	6 m2
	2492481	Ground	Jackson Galley - 57 Store	1	Yes	Floor (Beige	Chrysotile	Monitor	5 Low	6 m2
	2492482	Ground	Jackson Galley - 57 Store	1	Yes	Floor	Chrysotile	Monitor	5 Low	6 m2
	2492483	Ground	Jackson Galley - 58 Toilet	1		Ductwork (Debris)	Amosite and Chrysotile	Control Access	12 Medium	1 m2
	2492484	Ground	Jackson Galley - 59 Toilet	1	Yes	Skylight	Chrysotile	Control Access	9 <mark>Medium</mark>	1 m2
	2492485	Ground	Jackson Galley - 59 Toilet	1	Yes	Flue Pipe	Chrysotile	Monitor	7 Low	1 LM
	2492486	External	Jackson Galley - External	1		Floor (Debris)	Amosite and Chrysotile	Remove	10 Medium	1 m2

	Defence		F	carillionamey						
A STATES	Infra Orga	structure anisation				osReais			carillion	amey
	2492401	Ground	Jackson Galley - 01 Corridor	1	Yes	Damper to Ductwork	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492402	Ground	Jackson Galley - 01 Corridor	1	Yes	Ceiling Void (Debris)	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492403	Ground	Jackson Galley - 01 Corridor	1	Yes	Timber Beam	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492404	Ground	Jackson Galley - 02 Serving Area	1	Yes	Ductwork (Putty)	No Asbestos Detected	No Action	0 No Risk	4 LM
	2492405	Ground	Jackson Galley - 03 Plate Wash	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492406	Ground	Jackson Galley - 04 Servery	1	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	16 LM
	2492407	Ground	Jackson Galley - 05 Pantry	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492408	Ground	Jackson Galley - 06 Corridor	1	Yes	Pipework (Lining)	No Asbestos Detected	No Action	0 No Risk	5 LM
	2492409	Ground	Jackson Galley - 07 Female Changing Room	1	Yes	0,	No Sample Required	No Action	0 No Risk	0 N/A
	2492410	Ground	Jackson Galley - 08 Male Toilet / Shower	1	Yes	Bitumen Drips	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492411	Ground	Jackson Galley - 08 Male Toilet / Shower	1	Yes	Drain	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492412	Ground	Jackson Galley - 08 Male Toilet / Shower	1	Yes	Drain (Seal)	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492413	Ground	Jackson Galley - 08 Male Toilet / Shower	1	Yes	Debris	Amosite	Remove	15 High	1 m2
	2492414	Ground	Jackson Galley - 08 Male Toilet / Shower	1	Yes	Cistern Boxing	Amosite and Chrysotile	Remove	15 High	1 m2
	2492415	Ground	Jackson Galley - 09 Female Toilet / Shower	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492416	Ground	Jackson Galley - 10 Staff Room	1	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 m2
	2492417	Ground	Jackson Galley - 11 Back Porch	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492418	Ground	Jackson Galley - 12 Electrical Distribution	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492419	Ground	Jackson Galley - 13 Office	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2492420	Ground	Jackson Galley - 14 Cash Office	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
	2491088	First	Jackson Galley - D20 Mens Toilet	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491089	First	Jackson Galley - D22 Electrical supplies	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491090	Loft	Jackson Galley - Loft Area	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491091	First	Jackson Galley - D15 Supervisors Office	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491092	First	Jackson Galley - D14	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A

Defence										
The state of the s		structure anisation		ca	carillionamey					
	2491093	First	Jackson Galley - Corridor	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A
	2491094	First	Jackson Galley - Stairwell	1	Yes	Throughout	No Asbestos Detected	No Action	0 No Risk	0 N/A











Run By: CD\\svc\_ProRepuser










































































Run By: CD\\svc\_ProRepuser

























































































































































































Run By: CD\\svc\_ProRepuser



Run By: CD\\svc\_ProRepuser


















































































Run By: CD\\svc\_ProRepuser


































Run By: CD\\svc\_ProRepuser



































Run By: CD\\svc\_ProRepuser











