



Ministry
of Defence

Secretariat
Defence Infrastructure Organisation
Kingston Road
Sutton Coldfield
B75 7RL

E-mail: diosec-parli@mod.uk
www.gov.uk/DIO

[REDACTED]
Ref. FOI2017/03792

31 March 2017

Dear [REDACTED]

Thank you for your email of 22 March 2017 requesting the following information:

"In light of your letter dated 20th February 2017, we can limit our request to the following:

1. A copy of the asbestos register for Weeton Barracks.
2. Details of any asbestos removal on the Barracks from 1989 to date."

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD) and I can confirm that some information, in scope of your request is held.

The information you have requested for item 1 can be found enclosed at annex A.

The information you have requested for item 2 from 2006 to date can be found enclosed at annex B.

The information you have requested for item 2 from 1989 to 2005 is not held.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <http://www.ico.org.uk>.

Yours sincerely,

DIO Secretariat

Establishment	Subcontractor	Order No	Location	Problem	Job Type	Order Receive	Perm Fix By	Allocated	Allocated
WEETON CAMP	Lar Ltd	0832-0534	WEET01WEE015 SOCIAL CLUB	AWS Ref: 0007073 - Repairs to ceiling	IRL	10/03/2016	10/03/2017	10/03/2016	11/05/2016
WEETON CAMP	Lar Ltd	1093-2043	WEETXXsitewide Site Wide Asselt	Weeton Barracks, Bldg 15, Ground Floor Corridors: Please carry out the encapsulation of artex ceiling to corridors on ground floor with White ET150	STC	07/02/2017	07/03/2017	07/02/2016	23/02/2016
WEETON CAMP	Lar Ltd	5673-0542	WEET01WEE039 NAFF// NURSERY/ WIVES CLUB	Please carry out encapsulation of artex ceilings with White ET150	ADW	20/06/2016	20/06/2017	22/06/2016	25/07/2016
WEETON CAMP	Lar Ltd	5706-0141	WEET01WEE041 MEDICAL AND DENTAL CENTRE	Plant / Calorifier Room-Asbestos specialist contractor to re-fit damaged light fitting to ceiling of plant room and make good any damaged ACM in the vicinity of the light fitting.	RES	13/01/2015	10/02/2015	13/01/2015	23/01/2015
WEETON CAMP	Lar Ltd	8395-0531	WEET01WEE016 JUNIOR RANKS MESS / ELECTRICITY SUB STATION	AWS Ref: 0006997 - Asbestos Removal of window cills in Chefs toilet and changing rooms, Weeton Barracks, Building 016	ADW	12/02/2016	11/02/2017	15/02/2016	04/05/2016

Spec024	Job Type	Order Number	Order Description	Item Description	Received date	perm fix actual
WEETO1WEE015	RLCR	8218-0081	This P	Replace Fire Alarm panel and Detectors	2010-12-16 17:59:25.000	2011-06-27 12:00:00.000
WEETO1WEE016	ADW	8355-0514	POC	Lair Ltd	2016-02-12 14:53:08.000	2016-05-04 08:11:32.530
WEETO1WEE039	IFA	9797-0098	TK	BC/0879 Weeton Bks Bldg 39 Environmental Clean	2012-02-09 13:37:20.000	2012-03-08 16:00:00.000
WEETO1WEE015	MNW	9780-0125	Task code to be added by DSP	WEETO1WEE015 SPF Refurbishment of SLA Accommodation to 1st Floor Building 15	2013-12-03 18:32:74.000	2014-06-18 12:00:00.000
WEETO1WEE021	IWRK	7007-0136	Task code to be added by DSP	BC 4279 Carry Out Encapsulation of Cracked Asbestos Ceiling - option 3	2014-09-05 11:49:15.000	2014-10-08 16:30:00.000
WEETO1WEE040	HSM	3538-0110	G23 - HOLE IN SIDE OF WALL AND CHIPPED WINDOW SILL (ASBESTOS)	GM PPM FIRE ALARM INSTALLATION	2012-12-01 17:00:00.000	2013-02-14 09:30:00.000
WEETO1WEE001	RES	6048-2033	G23 - HOLE IN SIDE OF WALL AND CHIPPED WINDOW SILL (ASBESTOS)		2016-12-20 08:19:52.000	2017-01-10 08:15:00.000
Bldgs. 9, 10, 11, 12, 12a, 17, 18			Window sills removed as part of window refurb programme			2013
Building 39			Window sills replaced as part of a refurb of the playgroup			2016

Criteria: SEAT Location: TFM - SDA 9 - North West England
 Establishment: WEETON CAMP Building: All
 Spec024: Option: All

Item UID	Floor	Room Description	Room ID	Access Made	Position	Asbestos Analysis Result	Asbestos Status	Total Risk Score	Identified Risk	Approx Amount
WEETON CAMP - 25m Small Arms Barrack Range - 755844 - WEET01XRA001										
2084581	Ground	Firing Range	1	Yes			No Action	0	No Risk	0 N/A
2084593	Ground	Storage Shed	2	Yes			No Action	0	No Risk	0 N/A
2084599	External	Externals	3	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - ABSDA (DISTRIBUTION OUTLET) PACKED FUEL STORE - 866575 - WEET02WEE0N3										
2044855	Ground	Fuel Store	1	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - ALLWEATHER PITCH - 833964 - WEET01XSP002										
2111414	All	Astro Turf 5 A Side Football Pitch	0	Yes		No Sample Required	No Action	0	No Risk	0 N/A
WEETON CAMP - B COY OFFICE - 755827 - WEET01WEE014										
2043468	Ground	Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043453	Ground	Cleaners Store	2	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043454	Ground	Cleaners Store	2	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043464	Ground	Platoon Commanders Office	3	Yes	Window Sill	Chrysotile	Monitor	7		3 No.
2043449	Ground	CSM Office	4	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2043474	Ground	Officers Toilet	5	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043473	Ground	Officers Toilet	5	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043475	Ground	Locker Room / Toilet	6	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043476	Ground	Locker Room / Toilet	6	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043467	Ground	Locker Room / Toilet	6	Yes	Window Sill	Chrysotile	Monitor	6		30 LM
2335026	Ground	Bedding Store	7	Yes	Floor	No Asbestos Detected	No Action	0	No Risk	6 m2
2043469	Ground	Bedding Store	7	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043460	Ground	I.C. Office	8	Yes	Window Sill	Chrysotile	Monitor	7		2 No.

Run Date:
16/01/2017 03:43:47

Page:
1 of 113

Run By:
CD\\svc_ProRepuser

2043462	Ground	Officer In Commands Office	9	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2340146	Ground	Officer In Commands Office	9	Yes	Safe	Presumed Asbestos Content	Monitor	7		1 No.
2043448	Ground	Entrance	10	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043472	Ground	Cleaners Store	11	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043471	Ground	Cleaners Store	11	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043465	Ground	CSM Office	12	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2043456	Ground	Officers Toilet	13	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043455	Ground	Officers Toilet	13	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043466	Ground	Locker Room / Toilet	14	Yes	Window Sill	Chrysotile	Monitor	6		30 LM
2043458	Ground	Locker Room / Toilet	14	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043457	Ground	Locker Room / Toilet	14	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043451	Ground	Bedding Store	15	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043450	Ground	Bedding Store	15	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043470	Ground	Bedding Store	15	Yes	Floor (Brown Tiles)	Chrysotile	Monitor	5		6 m2
2043452	Ground	Bedding Store	15	Yes	Floor	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043463	Ground	Company Clerks Office	16	Yes	Window Sill	Chrysotile	Monitor	7		3 No.
2043459	Ground	Second In Commands Office	17	Yes	Window Sill	Chrysotile	Monitor	7		1 No.
2340147	Ground	Officer In Commands Office	18	Yes	Safe	Presumed Asbestos Content	Monitor	7		1 No.
2043461	Ground	Officer In Commands Office	18	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2043478	Ground	Calorifier Room	19	Yes	Flange	Chrysotile	Asbestos Removed	0	No Risk	0 N/A
2043481	Ground	Calorifier Room	19	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0	No Risk	1 No.
2043477	Ground	Calorifier Room	19	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043479	Ground	Calorifier Room	19	Yes	Area	Chrysotile	Asbestos Removed	0	No Risk	0 N/A
2043480	Roof	Roof	20	Yes	Roof	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043483	External	External	21	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - BAND ACCOMMODATION - 755807 - WEET01WEE031										
2044458	Ground	Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044459	Ground	Entrance	1	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
2 of 113

Run By:
CD\svc_ProRepuser

2333147	Ground	Music Practise Room	2	Yes	Window Sill	Chrysotile	Monitor	7	██████████	2 No.
2044461	Ground	Music Practise Room	2	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044492	Ground	Music Store	3	Yes	Window Sill	Chrysotile	Monitor	6	██████████	1 No.
2044470	Ground	Main Library / Store	4	Yes	Window Sill	Chrysotile	Monitor	7	██████████	1 No.
2044473	Ground	Library / Store	5	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044474	Ground	Library / Store	5	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044462	Ground	Instrument Store	6	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044476	Ground	Instrument Store	6	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044463	Ground	Instrument Store	6	Yes	Window Sill	Chrysotile	Asbestos Removed	0	No Risk	1 m2
2044493	Ground	Corridor	7	Yes			No Action	0	No Risk	0 N/A
2044487	Ground	Locker / Store Room	8	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	24 m2
2044488	Ground	Locker / Store Room	8	Yes	Window Sill	Chrysotile	Monitor	7	██████████	3 No.
2044475	Ground	Locker / Store Room	8	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044468	Ground	Instruction Room	9	Yes	Window Sill	Chrysotile	Monitor	6	██████████	2 No.
2044477	Ground	Instruction Room	9	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044478	Ground	Male Toilet	10	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044479	Ground	Male Toilet	10	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044472	Ground	Male Toilet	10	Yes	Window Sill	Chrysotile	Monitor	6	██████████	2 No.
2044480	Ground	Female Toilet	11	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044471	Ground	Female Toilet	11	Yes	Window Sill	Chrysotile	Monitor	6	██████████	1 No.
2044483	Ground	Cleaners Cupboard	12	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044482	Ground	Utility Room	13	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044481	Ground	Utility Room	13	Yes	Sink	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044467	Ground	Utility Room	13	Yes	Window Sill	Chrysotile	Monitor	6	██████████	1 No.
2044466	Ground	Bandmaster Office	14	Yes	Window Sill	Chrysotile	Monitor	7	██████████	2 No.
2044465	Ground	Director of Music	15	Yes	Window Sill	Chrysotile	Monitor	7	██████████	2 No.
2044484	Ground	Band Sergeant Major	16	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044464	Ground	Band Sergeant Major	16	Yes	Window Sill	Chrysotile	Monitor	7	██████████	1 No.
2044490	Ground	Boiler House	17	Yes	Pipework	No Asbestos Detected	No Action	0	No Risk	1 No.

2044491	Ground	Boiler House	17	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2044485	Ground	Boiler House	17	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044486	Ground	Boiler House	17	Yes	Pump Joint	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044494	Roof	Roof	18	Yes			No Action	0 No Risk	0 N/A
2044495	External	External	19	Yes			No Action	0 No Risk	0 N/A
2044460	Roof Void	Roof Void	20	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 753540 - WEET01WEE009									
2338350	First	F18 Bedroom	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338349	First	F18 Bedroom	1	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042756	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2338351	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338352	First	F17 Bedroom	2	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042757	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.
2042758	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2338354	First	F16 Bedroom	3	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338353	First	F16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338356	First	F15 Bedroom	4	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042759	First	F15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2338355	First	F15 Bedroom	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338358	First	F14 Bedroom	5	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042760	First	F14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2338357	First	F14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338360	First	F12 Common Room	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042763	First	F12 Common Room	6	Yes	Window Sills		No Action	0 No Risk	2 No.
2338359	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2338362	First	F11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338361	First	F11 Bedroom	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042755	First	F11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2338364	First	F10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

Run Date:
16/01/2017 03:43:47

Page:
4 of 113

Run By:
CD\\svc_ProRepuser

2042754	First	F10 Bedroom	8	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338363	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338365	First	F09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338366	First	F09 Bedroom	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042753	First	F09 Bedroom	9	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338367	First	F08 Bedroom	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338368	First	F08 Bedroom	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042752	First	F08 Bedroom	10	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338370	First	F07 Bedroom	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338369	First	F07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042751	First	F07 Bedroom	11	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338371	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042762	First	F05 Bedroom	12	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	2 No.
2042749	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042761	First	F04 Bedroom	13	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	2 No.
2042748	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338372	First	F03 Utility Room	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042773	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2042765	First	F03 Utility Room	14	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2042747	First	Drying Room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338375	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	3 m2
2042743	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2042772	First	F02 Ablutions	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2338373	First	F02 Ablutions	16	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	3 No.
2338376	First	F02 Ablutions	16	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2338379	First	16a - F02A Toilets	16	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2338380	First	16a - F02A Toilets	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338374	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338377	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2

Run Date:
16/01/2017 03:43:47

Page:
5 of 113

Run By:
CD\\svc_ProRepuser

2338378	First	F02G Riser	17	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042744	First	17a - F02B Cleaners Store	17	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2336662	First	17a - F02B Cleaners Store	17	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042771	First	Cupboard	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042742	First	F01 Corridor	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338381	First	F01 Corridor	19	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2338383	First	F01 Corridor	19	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2338382	First	F01 Corridor	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042787	First	Electrical Cupboard	20	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042764	First	F25 Common Room	21	Yes	Window Sill		No Action	0 No Risk	2 No.
2042769	First	F25 Common Room	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042836	First	F24 Ablutions	22	Yes	Window Sills		No Action	0 No Risk	4 No.
2335045	First	F24 Ablutions	22	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2338387	First	F24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338384	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2042770	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338389	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338386	First	F24 Ablutions	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338388	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338385	First	F24 Ablutions	22	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2336663	First	23a - F24B Cleaners Store	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2042785	First	F24G Riser	23	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338390	First	23a - F24B Cleaners Store	23	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042746	First	F22 Utility Room	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2042750	First	F22 Utility Room	24	Yes	Window Sill		No Action	0 No Risk	1 No.
2338391	First	F22 Utility Room	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042774	First	Drying Room	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338393	First	F21 Bedroom	26	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338392	First	F21 Bedroom	26	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2

2042768	First	F21 Bedroom	26	Yes	Window Sills		No Action	0 No Risk	2 No.
2335044	First	F21 Bedroom	26	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338395	First	F20 Bedroom	27	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338394	First	F20 Bedroom	27	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042767	First	F20 Bedroom	27	Yes	Window Sills		No Action	0 No Risk	2 No.
2335043	First	F20 Bedroom	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2335042	First	F19 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338396	First	F19 Bedroom	28	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042766	First	F19 Bedroom	28	Yes	Window Sills		No Action	0 No Risk	2 No.
2338397	First	F19 Bedroom	28	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042832	First	F13 Corridor	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338398	First	F13 Corridor	29	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338401	Ground	G16 Entrance Lobby	30	Yes	Wall at Base of	No Asbestos Detected	No Action	0 No Risk	3 m2
2042706	First	Landing / Stairs	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2338399	Ground	G16 Entrance Lobby	30	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2338400	Ground	G16 Entrance Lobby	30	Yes	Ceiling Under Stairs	No Asbestos Detected	No Action	0 No Risk	1 m2
2042777	First	Landing / Stairs	30	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042730	Ground	G21 Bedroom	31	Yes	Window Sill		No Action	0 No Risk	1 No.
2338403	Ground	G21 Bedroom	31	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338402	Ground	G21 Bedroom	31	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338405	Ground	G20 Bedroom	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338404	Ground	G20 Bedroom	32	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042729	Ground	G20 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	1 No.
2338407	Ground	G19 Bedroom	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042728	Ground	G19 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	1 No.
2338406	Ground	G19 Bedroom	33	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338409	Ground	G18 Bedroom	34	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042727	Ground	G18 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2338408	Ground	G18 Bedroom	34	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2042710	Ground	G15 Common Room	35	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042714	Ground	G15 Common Room	35	Yes	Window Sills		No Action	0 No Risk	2 No.
2338410	Ground	G14 Bedroom	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042724	Ground	G14 Bedroom	36	Yes	Window Sill		No Action	0 No Risk	1 No.
2338411	Ground	G14 Bedroom	36	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338412	Ground	G13 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338413	Ground	G13 Bedroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042723	Ground	G13 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2338415	Ground	G12 Bedroom	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338414	Ground	G12 Bedroom	38	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042722	Ground	G12 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	1 No.
2338417	Ground	G11 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042721	Ground	G11 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	1 No.
2338416	Ground	G11 Bedroom	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338419	Ground	G10 Bedroom	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338418	Ground	G10 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042720	Ground	G10 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2338421	Ground	G08 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338420	Ground	G08 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042716	Ground	G08 Bedroom	41	Yes	Window Sills		No Action	0 No Risk	2 No.
2338423	Ground	G07 Bedroom	42	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338422	Ground	G07 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042715	Ground	G07 Bedroom	42	Yes	Window Sills		No Action	0 No Risk	2 No.
2042712	Ground	G05 Utility Room	43	Yes	Window Sill		No Action	0 No Risk	1 No.
2042711	Ground	G05 Utility Room	43	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338424	Ground	G05 Utility Room	43	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042713	Ground	Drying Room	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042733	Ground	G04 Ablutions	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338426	Ground	G04 Ablutions	45	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2

2338429	Ground	G04 Ablutions	45	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338425	Ground	G04 Ablutions	45	Yes	Window Sills		No Action	0 No Risk	3 No.
2338428	Ground	G04 Ablutions	45	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338427	Ground	G04 Ablutions	45	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2042734	Ground	46a - G04B Cleaners Store	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2336660	Ground	G04F Riser	46	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2335041	Ground	G03 Store	47	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338430	Ground	G02 Corridor	48	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2042741	Ground	G02 Corridor	48	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338431	Ground	G02 Corridor	48	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042789	Ground	Electrical Cupboard	49	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338432	Ground	G28 Sitting Room	50	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042731	Ground	G28 Sitting Room	50	Yes	Window Sills		No Action	0 No Risk	2 No.
2042732	Ground	G28 Sitting Room	50	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2338436	Ground	G27 Ablutions	51	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338433	Ground	G27 Ablutions	51	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2042708	Ground	G27 Ablutions	51	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2042725	Ground	G27 Ablutions	51	Yes	Window Sills		No Action	0 No Risk	4 No.
2338434	Ground	G27 Ablutions	51	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338435	Ground	G27 Ablutions	51	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2336661	Ground	G27F Riser	52	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042709	Ground	52a - G27B Cleaners Store	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2042735	Ground	G26 Utility Room	53	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2338437	Ground	G26 Utility Room	53	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042726	Ground	G26 Utility Room	53	Yes	Window Sill		No Action	0 No Risk	1 No.
2042736	Ground	Drying Room	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042737	Ground	G25 Bedroom	55	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338438	Ground	G25 Bedroom	55	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042719	Ground	G25 Bedroom	55	Yes	Window Sills		No Action	0 No Risk	2 No.

2042738	Ground	G24 Bedroom	56	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338439	Ground	G24 Bedroom	56	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042718	Ground	G24 Bedroom	56	Yes	Window Sills		No Action	0 No Risk	2 No.
2042739	Ground	G23 Bedroom	57	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338440	Ground	G23 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042717	Ground	G23 Bedroom	57	Yes	Window Sills		No Action	0 No Risk	2 No.
2042707	Ground	G17 Corridor	58	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042740	Ground	G17 Corridor	58	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	3 m2
2338441	Ground	G17 Corridor	58	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042778	Ground	G16B General Store	59	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042776	Ground	Calorifier Room	60	Yes	Pipework	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2042775	Ground	G16A Plant Room	60	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2338442	Ground	G16A Plant Room	60	Yes	Electrical Box (Flash Guards)	Presumed Asbestos Content	Monitor	6	1 m2
2042780	Ground	Calorifier Room	60	Yes	Fuse box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2042745	Roof	Roof	61	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042786	Roof	Roof	61	Yes	Undercloaking	No Asbestos Detected	No Action	0 No Risk	45 LM
2042837	Roof	Roof	61	Yes	Flue Pipe	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2042790	External	External	62	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2042779	Ground	Fire Escape Stairs	63	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338443	All	External / Internal	64	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755823 - WEET01WEE010									
2337736	First	F18 Bedroom	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337735	First	F18 Bedroom	1	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042903	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2337738	First	F17 Bedroom	2	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337737	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042902	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.

2337740	First	F16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042901	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2337739	First	F16 Bedroom	3	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042900	First	F15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2337741	First	F14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042899	First	F14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2337742	First	F14 Bedroom	5	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337743	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042883	First	F12 Common Room	6	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2042897	First	F12 Common Room	6	Yes	Window Sills		No Action	0 No Risk	2 No.
2042894	First	F11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2337744	First	F11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337745	First	F11 Bedroom	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337746	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337747	First	F10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042893	First	F10 Bedroom	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2042892	First	F09 Bedroom	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2337749	First	F09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337748	First	F09 Bedroom	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042891	First	F08 Bedroom	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2337750	First	F08 Bedroom	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337751	First	F08 Bedroom	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042890	First	F07 Bedroom	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2337753	First	F07 Bedroom	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337752	First	F07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337754	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042889	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042905	First	F05 Bedroom	12	Yes	Window Sills		No Action	0 No Risk	2 No.
2337755	First	F04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2

2042904	First	F04 Bedroom	13	Yes	Window Sills	No Action	0 No Risk	2 No.
2042888	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	25 m2
2337756	First	F03 Utility Room	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	16 m2
2042895	First	F03 Utility Room	14	Yes	Window Sill	No Action	0 No Risk	1 No.
2042884	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	16 m2
2042886	First	Drying Room	15	Yes	Ironing Board	Chrysotile	Asbestos Removed	1 m2
2042885	First	Drying Room	15	Yes	Walls	No Asbestos Detected	No Action	0 N/A
2042882	First	F02 Ablutions	16	Yes	Ceiling	No Asbestos Detected	No Action	20 m2
2042880	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	16 m2
2337758	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	3 m2
2337757	First	F02 Ablutions	16	Yes	Window Sills	No Action	0 No Risk	3 No.
2337760	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	2 m2
2337759	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	8 m2
2336653	First	17a - F02B Cleaners Store	17	Yes	Walls	No Asbestos Detected	No Action	1 m2
2337761	First	17a - F02B Cleaners Store	17	Yes	Ceiling Composition	No Asbestos Detected	No Action	1 m2
2042881	First	F02G Riser	17	Yes		No Sample Required	No Action	0 N/A
2042921	First	Cupboard	18	Yes		No Sample Required	No Action	0 N/A
2337762	First	F01 Corridor	19	Yes	Suspended Ceiling	No Asbestos Detected	No Action	2 m2
2042877	First	F01 Corridor	19	Yes	Walls	No Asbestos Detected	No Action	20 m2
2042876	First	F01 Corridor	19	Yes	Ceiling	No Asbestos Detected	No Action	20 m2
2042922	First	F26 Electric Cupboard	20	Yes		No Sample Required	No Action	0 N/A
2042898	First	F25 Common Room	21	Yes	Window Sills	No Action	0 No Risk	2 No.
2337764	First	F25 Common Room	21	Yes	Ceiling Composition	No Asbestos Detected	No Action	16 m2
2337763	First	F25 Common Room	21	Yes	Wall Composition	No Asbestos Detected	No Action	16 m2
2337766	First	F24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	4 m2
2337765	First	F24 Ablutions	22	Yes	Window Sills	No Action	0 No Risk	3 No.
2042909	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	12 m2
2337767	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	8 m2
2042911	First	F24 Ablutions	22	Yes	Ceiling	No Asbestos Detected	No Action	20 m2

2042910	First	Cupboard	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336654	First	23a Cleaners Cupboard	23	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337769	First	F24 Toilet	24	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337768	First	F24 Toilet	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2337770	First	F24 Toilet	24	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2337771	First	F24 Toilet	24	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2146270	First	F24 Toilet	24	Yes	Window Sill		No Action	0 No Risk	1 No.
2042912	First	F22 Utility Room	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2042896	First	F22 Utility Room	25	Yes	Window Sill		No Action	0 No Risk	1 No.
2337772	First	F22 Utility Room	25	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2042913	First	Drying Room	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042916	First	F21 Bedroom	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337773	First	F21 Bedroom	27	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042908	First	F21 Bedroom	27	Yes	Window Sills		No Action	0 No Risk	2 No.
2042915	First	F20 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042907	First	F20 Bedroom	28	Yes	Window Sills		No Action	0 No Risk	2 No.
2337774	First	F20 Bedroom	28	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042914	First	F19 Bedroom	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337775	First	F19 Bedroom	29	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042906	First	F19 Bedroom	29	Yes	Window Sills		No Action	0 No Risk	2 No.
2337776	First	F13 Corridor	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042878	First	F13 Corridor	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337780	Ground	G16 Entrance Lobby	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 m2
2337778	Ground	G16 Entrance Lobby	31	Yes	Entrance Doors	No Asbestos Detected	No Action	0 No Risk	1 m2
2337781	Ground	G16 Entrance Lobby	31	Yes	Wall at Base of	No Asbestos Detected	No Action	0 No Risk	3 m2
2337779	Ground	G16 Entrance Lobby	31	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2337777	Ground / First	Stairwell	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2042879	Ground / First	Stairwell	31	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337782	Ground	G21 Bedroom	32	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2337783	Ground	G21 Bedroom	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042858	Ground	G21 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	1 No.
2337785	Ground	G20 Bedroom	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337784	Ground	G20 Bedroom	33	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042857	Ground	G20 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	1 No.
2337787	Ground	G19 Bedroom	34	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042856	Ground	G19 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2337786	Ground	G19 Bedroom	34	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337789	Ground	G18 Bedroom	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337788	Ground	G18 Bedroom	35	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2181252	Ground	G18 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	1 No.
2181254	Ground	G15 Common Room	36	Yes	Window Sills		No Action	0 No Risk	2.No.
2337790	Ground	G15 Common Room	36	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2337791	Ground	G15 Common Room	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337792	Ground	G14 Bedroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337793	Ground	G14 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2181256	Ground	G14 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2337794	Ground	G13 Bedroom	38	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337795	Ground	G13 Bedroom	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2181258	Ground	G13 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	1 No.
2337797	Ground	G12 Bedroom	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2181262	Ground	G12 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	1 No.
2337796	Ground	G12 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337799	Ground	G11 Bedroom	40	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337798	Ground	G11 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2336648	First	G11 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2337801	Ground	G10 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2181266	Ground	G10 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.
2337800	Ground	G10 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2042863	Ground	G08 Bedroom	42	Yes	Window Sills		No Action	0 No Risk	2 No.
2337802	Ground	G08 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042848	Ground	G08 Bedroom	42	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042862	Ground	G07 Bedroom	43	Yes	Window Sills		No Action	0 No Risk	2 No.
2337803	Ground	G07 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042847	Ground	G07 Bedroom	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337804	Ground	G05 Utility Room	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2042846	Ground	G05 Utility Room	44	Yes	Window Sill		No Action	0 No Risk	1 No.
2042844	Ground	G05 Utility Room	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2042845	Ground	Drying Room	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337807	Ground	G04 Ablutions	46	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2337805	Ground	G04 Ablutions	46	Yes	Window Sills		No Action	0 No Risk	3 No.
2337808	Ground	G04 Ablutions	46	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2337806	Ground	G04 Ablutions	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042841	Ground	G04 Ablutions	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2042842	Ground	G04F Riser	47	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2336652	Ground	47a - G04a Cleaners Store	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2337809	Ground	47a - G04a Cleaners Store	47	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042923	Ground	G03 Store	48	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337810	Ground	G02 Corridor	49	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042840	Ground	G02 Corridor	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042924	Ground	G29 Electric Cupboard	50	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042860	Ground	G28 Sitting Room	51	Yes	Window Sills		No Action	0 No Risk	2 No.
2042867	Ground	G28 Sitting Room	51	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337813	Ground	G27 Ablutions	52	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337811	Ground	G27 Ablutions	52	Yes	Window Sill		No Action	0 No Risk	3 No.
2337814	Ground	G27 Ablutions	52	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2042868	Ground	G27 Ablutions	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2337812	Ground	G27 Ablutions	52	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2

2337815	Ground	53a - G27B Cleaners Store	53	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042869	Ground	G27G Riser	53	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2336651	Ground	53a - G27B Cleaners Store	53	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2337818	Ground	G27 Toilet	54	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2337817	Ground	G27 Toilet	54	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042925	Ground	G27 Toilet	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2042859	Ground	G27 Toilet	54	Yes	Window Sill		No Action	0 No Risk	1 No.
2337816	Ground	G27 Toilet	54	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2042861	Ground	G26 Utility Room	55	Yes	Window Sill		No Action	0 No Risk	1 No.
2042871	Ground	G26 Utility Room	55	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	16 m2
2042870	Ground	G26 Utility Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2042872	Ground	Drying Room	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042866	Ground	G25 Bedroom	57	Yes	Window Sills		No Action	0 No Risk	2 No.
2337819	Ground	G25 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042873	Ground	G25 Bedroom	57	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337820	Ground	G24 Bedroom	58	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042874	Ground	G24 Bedroom	58	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042865	Ground	G24 Bedroom	58	Yes	Window Sills		No Action	0 No Risk	2 No.
2042864	Ground	G23 Bedroom	59	Yes	Window Sills		No Action	0 No Risk	2 No.
2337821	Ground	G23 Bedroom	59	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042875	Ground	G23 Bedroom	59	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042917	Ground	G17 Corridor	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2042839	Ground	G17 Corridor	60	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2146261	Ground	G16B General Store	61	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2042919	Ground	G16A Plant Room	62	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2337822	Ground	G16A Plant Room	62	Yes	Electrical Box (Flash Guards)	Presumed Asbestos Content	Monitor	6	1 m2
2042918	Ground	G16A Plant Room	62	Yes	Flange	No Asbestos Detected	No Action	0 No Risk	0 N/A
2146353	Ground	Calorifier Room	62	Yes	Fuse boxes	Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.

2146354	Ground	Calorifier Room	62	Yes	Pipework	Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2042887	Roof Void	Roof Void	63	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2146477	Roof Void	Roof	63	Yes	Roof		No Action	0 No Risk	0 N/A
2146468	Roof Void	Roof	63	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	45 LM
2146481	External	External	64	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2042960	External	External / Internal	64	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2
2042920	First	Fire Escape Stairs	65	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755824 - WEET01WEE011									
2043049	First	F18 Bedroom	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043014	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2338155	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043013	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.
2043048	First	F17 Bedroom	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338156	First	F16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043012	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2043047	First	F16 Bedroom	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338157	First	F15 Bedroom	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043011	First	F15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2043046	First	F15 Bedroom	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043010	First	F14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 m2
2043045	First	F14 Bedroom	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043039	First	F12 Common Room	6	Yes	Window Sills		No Action	0 No Risk	2 No.
2338159	First	F12 Common Room	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043040	First	F12 Common Room	6	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2338158	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043005	First	F11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2338160	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043006	First	F10 Bedroom	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2338161	First	F10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

Run Date:
16/01/2017 03:43:47

Page:
17 of 113

Run By:
CD\svc_ProRepuser

2338163	First	F09 Bedroom	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338162	First	F09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043007	First	F09 Bedroom	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2043008	First	F08 Bedroom	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2043009	First	F07 Bedroom	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2338165	First	F07 Bedroom	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338164	First	F07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043028	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338166	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042996	First	F05 Bedroom	12	Yes	Window Sills		No Action	0 No Risk	2 No.
2043029	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042995	First	F04 Bedroom	13	Yes	Window Sills		No Action	0 No Risk	2 No.
2338167	First	F04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338168	First	F03 Utility Room	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2043032	First	F03 Utility Room	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2043043	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2043062	First	Drying Room	15	Yes			No Action	0 No Risk	0 N/A
2043024	First	F02 Ablutions	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2338169	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338172	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2338171	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	3 m2
2043023	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338170	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043076	First	F02 Ablutions	16	Yes	Window Sills		No Action	0 No Risk	3 No.
2338173	First	F02A Toilets	17	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2043063	First	F02A Toilets	17	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2338174	First	F02A Toilets	17	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043064	First	F02B Cleaners Store	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2338175	First	F02B Cleaners Store	18	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2

2043065	First	F02G Cistern Riser	19	Yes	No Sample Required	No Action	0 No Risk	0 N/A
2043066	First	Electrics Cupboard	20	Yes	No Sample Required	No Action	0 No Risk	0 N/A
2043038	First	F25 Platoon Office	21	Yes	Window Sill	No Action	0 No Risk	2 No.
2338177	First	F24 Ablutions	22	Yes	Boxing	No Asbestos Detected	No Action	2 m2
2338180	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	8 m2
2043041	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	12 m2
2338176	First	F24 Ablutions	22	Yes	Window Sills	No Action	0 No Risk	3 No.
2338178	First	F24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	3 m2
2338181	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	4 m2
2338179	First	F24 Ablutions	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	12 m2
2338182	First	F24A Toilets	23	Yes	Ceiling Composition	No Asbestos Detected	No Action	8 m2
2043033	First	F24A Toilets	23	Yes	Window Sill	No Action	0 No Risk	1 No.
2338184	First	F24A Toilets	23	Yes	Wall Composition	No Asbestos Detected	No Action	2 m2
2338183	First	F24A Toilets	23	Yes	Window Frame Void	No Asbestos Detected	No Action	1 m2
2043067	First	F24A Toilets	23	Yes	Walls	No Asbestos Detected	No Action	8 m2
2043042	First	F24B Cleaners Store	24	Yes	Walls	No Asbestos Detected	No Action	1 m2
2043025	First	F24B Cleaners Store	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	1 m2
2043068	First	F24G Cistern Riser	25	Yes	No Sample Required	No Action	0 No Risk	0 N/A
2338185	First	F22 Utility Room	26	Yes	Ceiling Composition	No Asbestos Detected	No Action	15 m2
2043035	First	F22 Utility Room	26	Yes	Window Sill	No Action	0 No Risk	1 No.
2043026	First	F22 Utility Room	26	Yes	Walls	No Asbestos Detected	No Action	15 m2
2043044	First	Drying Room	27	Yes	Walls	No Asbestos Detected	No Action	0 N/A
2043027	First	Drying Room	27	Yes	Walls	No Asbestos Detected	No Action	0 N/A
2338186	First	F21 Bedroom	28	Yes	Wall Composition	No Asbestos Detected	No Action	25 m2
2042999	First	F21 Bedroom	28	Yes	Window Sills	No Action	0 No Risk	2 No.
2043052	First	F21 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	25 m2
2042998	First	F20 Bedroom	29	Yes	Window Sills	No Action	0 No Risk	2 No.
2338187	First	F20 Bedroom	29	Yes	Wall Composition	No Asbestos Detected	No Action	25 m2
2043051	First	F20 Bedroom	29	Yes	Ceiling	No Asbestos Detected	No Action	25 m2

2338188	First	F19 Bedroom	30	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042997	First	F19 Bedroom	30	Yes	Window Sills		No Action	0 No Risk	2 No.
2043050	First	F19 Bedroom	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043020	First	F13 Corridor	31	Yes	Stair Nosing	No Asbestos Detected	No Action	0 No Risk	1 No.
2043070	First	F13 Corridor	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043019	First	F13 Corridor	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338189	First	F01 Corridor	32	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2043021	First	F01 Corridor	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338190	First	F01 Corridor	32	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2043022	First	F01 Corridor	32	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043069	First	Riser Cupboard	33	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043060	Ground	G21 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2338192	Ground	G20 Bedroom	35	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043059	Ground	G20 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	1 No.
2338191	Ground	G20 Bedroom	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338194	Ground	G19 Bedroom	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043058	Ground	G19 Bedroom	36	Yes	Window Sill		No Action	0 No Risk	1 No.
2338193	Ground	G19 Bedroom	36	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043057	Ground	G18 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2043053	Ground	G16B General Store	38	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043036	Ground	G15 Accommodation Store	39	Yes	Window Sills		No Action	0 No Risk	2 No.
2043037	Ground	G15 Accommodation Store	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042985	Ground	G15 Accommodation Store	39	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043004	Ground	G14 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2338195	Ground	G13 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043003	Ground	G13 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.
2338196	Ground	G13 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043002	Ground	G12 Bedroom	42	Yes	Window Sill		No Action	0 No Risk	1 No.
2338197	Ground	G12 Bedroom	42	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2338198	Ground	G12 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043001	Ground	G11 Bedroom	43	Yes	Window Sill		No Action	0 No Risk	1 No.
2043000	Ground	G10 Bedroom	44	Yes	Window Sill		No Action	0 No Risk	1 No.
2338199	Ground	G08 Bedroom	45	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042991	Ground	G08 Bedroom	45	Yes	Window Sills		No Action	0 No Risk	2 No.
2338200	Ground	G08 Bedroom	45	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338202	Ground	G07 Bedroom	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338201	Ground	G07 Bedroom	46	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042990	Ground	G07 Bedroom	46	Yes	Window Sills		No Action	0 No Risk	2 No.
2042986	Ground	G05 Utility Room	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2042989	Ground	G05 Utility Room	47	Yes	Window Sill		No Action	0 No Risk	1 No.
2042987	Ground	G05 Utility Room	47	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2043018	Ground	Drying Room	48	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043071	Ground	Drying Room	48	Yes			No Action	0 No Risk	0 N/A
2338205	Ground	G04 Ablutions	49	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338208	Ground	G04 Ablutions	49	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338207	Ground	G04 Ablutions	49	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338203	Ground	G04 Ablutions	49	Yes	Window Sills		No Action	0 No Risk	3 No.
2338206	Ground	G04 Ablutions	49	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2043015	Ground	G04 Ablutions	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338204	Ground	G04 Ablutions	49	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2043072	Ground	G04A Toilets	50	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2338209	Ground	G04A Toilets	50	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338210	Ground	G04A Toilets	50	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2043073	Ground	G04B Cleaners Store	51	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2338211	Ground	G04B Cleaners Store	51	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2043074	Ground	G04F Riser	52	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043016	Ground	Cupboard	53	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043075	Ground	Electrical Cupboard	54	Yes		No Sample Required	No Action	0 No Risk	0 N/A

2338213	Ground	G28 Sitting Room	55	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2338212	Ground	G28 Sitting Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043061	Ground	G28 Sitting Room	55	Yes	Window Sills		No Action	0 No Risk	2 No.
2338216	Ground	G27A Toilets	56	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2043034	Ground	G27A Toilets	56	Yes	Window Sill		No Action	0 No Risk	1 No.
2338215	Ground	G27A Toilets	56	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338214	Ground	G27A Toilets	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2338217	Ground	G27 Ablutions	57	Yes	Window Sills		No Action	0 No Risk	3.No.
2338218	Ground	G27 Ablutions	57	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338221	Ground	G27 Ablutions	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042983	Ground	G27 Ablutions	57	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2338220	Ground	G27 Ablutions	57	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2338219	Ground	G27 Ablutions	57	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338222	Ground	G27 Ablutions	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338223	Ground	G27B Cleaners Store	58	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042984	Ground	G27B Cleaners Store	58	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2043077	Ground	G27G Cistern Riser	59	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043031	Ground	G26 Utility Room	60	Yes	Window Sill		No Action	0 No Risk	1 No.
2338224	Ground	G26 Utility Room	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2338225	Ground	G26 Utility Room	60	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2042988	Ground	Drying Room	61	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338227	Ground	G25 Bedroom	62	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338226	Ground	G25 Bedroom	62	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042994	Ground	G25 Bedroom	62	Yes	Window Sills		No Action	0 No Risk	2 No.
2338229	Ground	G24 Bedroom	63	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338228	Ground	G24 Bedroom	63	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042993	Ground	G24 Bedroom	63	Yes	Window Sills		No Action	0 No Risk	2 No.
2338231	Ground	G23 Bedroom	64	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2042992	Ground	G23 Bedroom	64	Yes	Window Sills		No Action	0 No Risk	2 No.

2338230	Ground	G23 Bedroom	64	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338233	Ground	G17 Corridor	65	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042981	Ground	G17 Corridor	65	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	3 m2
2338232	Ground	G17 Corridor	65	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338235	Ground	G02 Corridor	66	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338234	Ground	G02 Corridor	66	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2042982	Ground	G02 Corridor	66	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043078	Ground	G16 Entrance Lobby	67	Yes	Wall at Base of	No Asbestos Detected	No Action	0 No Risk	3 m2
2338237	Ground	G16 Entrance Lobby	67	Yes	Ceiling Under Stairs	No Asbestos Detected	No Action	0 No Risk	1 m2
2338238	Ground	G16 Entrance Lobby	67	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2338236	First	Stairwell	67	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2338239	Ground	G16A Plant Room	68	Yes	Electrical Box (Flash Guards)	Presumed Asbestos Content	Monitor	6	1 m2
2043055	Ground	G16A Plant Room	68	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043081	Ground	Calorifier Room	68	Yes	Fuse box	Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2043017	Ground	G16A Plant Room	68	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043054	Ground	G16A Plant Room	68	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2043082	Roof	Roof	69	Yes	Fillets	No Asbestos Detected	No Action	0 No Risk	45 LM
2338240	External	External	70	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2043083	External	External	70	Yes	Pipes	No Sample Required	No Action	0 No Risk	14 No.
2043056	First	Fire Exit Spiral Staircases	71	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043030	Roof Void	Roof Void	72	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338241	All	External / Internal	73	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755825 - WEET01WEE012									
2043158	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2338242	First	F18 Bedroom	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338243	First	F18 Bedroom	1	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338245	First	F17 Bedroom	2	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043157	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.

2338244	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043156	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2338247	First	F16 Bedroom	3	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338246	First	F16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338248	First	F15 Bedroom	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043155	First	F15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2338249	First	F15 Bedroom	4	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338250	First	F14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338251	First	F14 Bedroom	5	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043154	First	F14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2338253	First	F12 Common Room	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043161	First	F12 Common Room	6	Yes	Window Sills		No Action	0 No Risk	2 No.
2338252	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2338255	First	F11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043153	First	F11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2338254	First	F11 Bedroom	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338257	First	F10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338256	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043152	First	F10 Bedroom	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2338259	First	F09 Bedroom	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338258	First	F09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043151	First	F09 Bedroom	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2338261	First	F08 Bedroom	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043150	First	F08 Bedroom	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2338260	First	F08 Bedroom	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338263	First	F07 Bedroom	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338262	First	F07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043149	First	F07 Bedroom	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2043163	First	F05 Bedroom	12	Yes	Window Sills		No Action	0 No Risk	2 No.

2335057	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338264	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338265	First	F04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2335058	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043162	First	F04 Bedroom	13	Yes	Window Sills		No Action	0 No Risk	2 No.
2338266	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2043127	First	F03 Utility Room	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2338267	First	F03 Utility Room	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2043174	First	F03A Drying Room	15	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338268	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338271	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338269	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2043159	First	F02 Ablutions	16	Yes	Window Sills		No Action	0 No Risk	3 No.
2338270	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	3 m2
2338272	First	F02 Ablutions	16	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338273	First	F02A Toilet	17	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2043176	First	F02A Toilet	17	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338274	First	F02A Toilet	17	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	3 m2
2338275	First	F02A Toilet	17	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043177	First	F02B Cleaners Store	18	Yes			No Action	0 No Risk	0 N/A
2043178	First	Cistern Riser	19	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043179	First	Electrical Cupboard	20	Yes			No Action	0 No Risk	0 N/A
2338277	First	F25 Common Room	21	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2338276	First	F25 Common Room	21	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043160	First	F25 Common Room	21	Yes	Window Sills		No Action	0 No Risk	2 No.
2338280	First	F24 Ablutions	22	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338279	First	F24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338282	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2043181	First	F24 Ablutions	22	Yes	Window Sills		No Action	0 No Risk	3 No.

Run Date:
16/01/2017 03:43:47

Page:
25 of 113

Run By:
CD\svc_ProRepuer

2338278	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338281	First	F24 Ablutions	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338284	First	F24A Toilet	23	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338286	First	F24A Toilet	23	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338285	First	F24A Toilet	23	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2043182	First	F24A Toilet	23	Yes	Window Sill		No Action	0 No Risk	1 No.
2338287	First	F24A Toilet	23	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2338283	First	F24A Toilet	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338288	First	F24B Cleaners Store	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2043183	First	F24B Cleaners Store	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2043184	First	F24G Riser	25	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338289	First	F22 Utility Room	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2338290	First	F22 Utility Room	26	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043138	First	F22 Utility Room	26	Yes	Window Sill		No Action	0 No Risk	1 No.
2043186	First	F23 Drying Room	27	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338291	First	F21 Bedroom	28	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043164	First	F21 Bedroom	28	Yes	Window Sills		No Action	0 No Risk	2 No.
2335061	First	F21 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338292	First	F20 Bedroom	29	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2335060	First	F20 Bedroom	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043165	First	F20 Bedroom	29	Yes	Window Sills		No Action	0 No Risk	2 No.
2043166	First	F19 Bedroom	30	Yes	Window Sills		No Action	0 No Risk	2 No.
2335059	First	F19 Bedroom	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338293	First	F19 Bedroom	30	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043190	First	F13 Corridor	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338295	First	Stairwell	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2338294	First	F13 Corridor	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338297	First	F01 Corridor	32	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2043191	First	F01 Corridor	32	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2

2338296	First	F01 Corridor	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043192	First	Riser Cupboard	33	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338298	Ground	G21 Bedroom	34	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043137	Ground	G21 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2338299	Ground	G21 Bedroom	34	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338301	Ground	G20 Bedroom	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338300	Ground	G20 Bedroom	35	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043136	Ground	G20 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	1 No.
2338303	Ground	G19 Bedroom	36	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043135	Ground	G19 Bedroom	36	Yes	Window Sill		No Action	0 No Risk	1 No.
2338302	Ground	G19 Bedroom	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338305	Ground	G18 Bedroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043134	Ground	G18 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2338304	Ground	G18 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043197	Ground	G16B General Store	38	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2333149	Ground	G15 Common Room	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2335048	Ground	G15 Common Room	39	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2043140	Ground	G15 Common Room	39	Yes	Window Sills		No Action	0 No Risk	2 No.
2043198	Ground	Common Room	39	Yes	Ironing board		Asbestos Removed	0 No Risk	1 m2
2043199	Ground	G14 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2338306	Ground	G14 Bedroom	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043133	Ground	G14 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338308	Ground	G13 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043132	Ground	G13 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.
2338307	Ground	G13 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338309	Ground	G12 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043131	Ground	G12 Bedroom	42	Yes	Window Sill		No Action	0 No Risk	1 No.
2338310	Ground	G12 Bedroom	42	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338312	Ground	G11 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2338311	Ground	G11 Bedroom	43	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043130	Ground	G11 Bedroom	43	Yes	Window Sill		No Action	0 No Risk	1 No.
2043204	Ground	G10 Bedroom	44	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338313	Ground	G10 Bedroom	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043129	Ground	G10 Bedroom	44	Yes	Window Sill		No Action	0 No Risk	1 No.
2338314	Ground	G08 Bedroom	45	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043143	Ground	G08 Bedroom	45	Yes	Window Sills		No Action	0 No Risk	2 No.
2335050	Ground	G08 Bedroom	45	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338315	Ground	G07 Bedroom	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043142	Ground	G07 Bedroom	46	Yes	Window Sills		No Action	0 No Risk	2 No.
2335049	Ground	G07 Bedroom	46	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043148	Ground	G05 Utility Room	47	Yes	Window Sill		No Action	0 No Risk	1 No.
2338317	Ground	G05 Utility Room	47	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2338316	Ground	G05 Utility Room	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2043208	Ground	Drying Room	48	Yes			No Action	0 No Risk	0 N/A
2338319	Ground	G04 Ablutions	49	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338322	Ground	G04 Ablutions	49	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338321	Ground	G04 Ablutions	49	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338320	Ground	G04 Ablutions	49	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2043216	Ground	G04 Ablutions	49	Yes	Window Sills		No Action	0 No Risk	3 No.
2338318	Ground	G04 Ablutions	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338323	Ground	G04A Toilet	50	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338326	Ground	G04A Toilet	50	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2043210	Ground	G04A Toilet	50	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2338324	Ground	G04A Toilet	50	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338325	Ground	G04A Toilet	50	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043211	Ground	Cleaners Cupboard	51	Yes			No Action	0 No Risk	0 N/A
2043212	Ground	Cupboard	52	Yes			No Action	0 No Risk	0 N/A
2043213	Ground	Riser Cupboard	53	Yes		No Sample Required	No Action	0 No Risk	0 N/A

2043214	Ground	Electrical Cupboard	54	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338327	Ground	G28 Sitting Room	55	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043141	Ground	G28 Sitting Room	55	Yes	Window Sills		No Action	0 No Risk	2 No.
2335052	Ground	G28 Sitting Room	55	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2338328	Ground	G27A Toilet	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338331	Ground	G27A Toilet	56	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338330	Ground	G27A Toilet	56	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338329	Ground	G27A Toilet	56	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338332	Ground	G27A Toilet	56	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2043139	Ground	G27A Toilet	56	Yes	Window Sill		No Action	0 No Risk	1 No.
2338335	Ground	G27 Ablutions	57	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043217	Ground	G27 Ablutions	57	Yes	Window Sills		No Action	0 No Risk	3 No.
2338337	Ground	G27 Ablutions	57	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2338334	Ground	G27 Ablutions	57	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338333	Ground	G27 Ablutions	57	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338336	Ground	G27 Ablutions	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043218	Ground	G27B Cleaners Store	58	Yes			No Action	0 No Risk	0 N/A
2043219	Ground	Cistern Riser	59	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2335053	Ground	G26 Utility Room	60	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	16 m2
2338338	Ground	G26 Utility Room	60	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	16 m2
2043147	Ground	G26 Utility Room	60	Yes	Window Sill		No Action	0 No Risk	1 No.
2043221	Ground	Drying Room	61	Yes			No Action	0 No Risk	0 N/A
2335054	Ground	G25 Bedroom	62	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043144	Ground	G25 Bedroom	62	Yes	Window Sills		No Action	0 No Risk	2 No.
2338339	Ground	G25 Bedroom	62	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043145	Ground	G24 Bedroom	63	Yes	Window Sills		No Action	0 No Risk	2 No.
2338340	Ground	G24 Bedroom	63	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2335055	Ground	G24 Bedroom	63	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2335056	Ground	G23 Bedroom	64	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2

2338341	Ground	G23 Bedroom	64	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043146	Ground	G23 Bedroom	64	Yes	Window Sills		No Action	0 No Risk	2 No.
2338342	Ground	G17 Corridor	65	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043226	Ground	G17 Corridor	65	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338344	Ground	G02 Corridor	66	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2338343	Ground	G02 Corridor	66	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043227	Ground	G02 Corridor	66	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338346	Ground	G16 Entrance Lobby	67	Yes	Ceiling Under Stairs	No Asbestos Detected	No Action	0 No Risk	1 m2
2338345	Ground	G16 Entrance Lobby	67	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2043228	Ground	G16 Entrance Lobby	67	Yes	Wall at Base of Ceiling	No Asbestos Detected	No Action	0 No Risk	3 m2
2335051	Ground	G16A Plant Room	68	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2338347	Ground	G16A Plant Room	68	Yes	Electrical Box (Flash Guards)	Presumed Asbestos Content	Monitor	6	1 m2
2043229	Ground	Calorifier Room	68	Yes	Fuse box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2043231	Roof	Roof	69	Yes	Pipes	Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2043230	Roof	Roof	69	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	80 m2
2043232	External	External	70	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2338348	All	External / Internal	71	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2

WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755830 - WEET01WEE017

2043702	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2337631	First	F18 Bedroom	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043746	First	F18 Bedroom	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337632	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043701	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.
2043747	First	F17 Bedroom	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043700	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2337633	First	F16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043748	First	F16 Bedroom	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337634	First	F15 Bedroom	4	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

Run Date:
16/01/2017 03:43:47

Page:
30 of 113

Run By:
CD\svc_ProRepuser

2043699	First	F15 Bedroom	4	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043749	First	F15 Bedroom	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337635	First	F14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043698	First	F14 Bedroom	5	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043750	First	F14 Bedroom	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337636	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043722	First	F12 Common Room	6	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043704	First	F12 Common Room	6	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	2 No.
2337637	First	F11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337638	First	F11 Bedroom	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043697	First	F11 Bedroom	7	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043726	First	F11 Bedroom	7	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337640	First	F10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337639	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043696	First	F10 Bedroom	8	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043727	First	F10 Bedroom	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043695	First	F09 Bedroom	9	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043728	First	F09 Bedroom	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337641	First	F09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2043729	First	F08 Bedroom	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337642	First	F08 Bedroom	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043694	First	F08 Bedroom	10	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043730	First	F07 Bedroom	11	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2337643	First	F07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043693	First	F07 Bedroom	11	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043707	First	F05 Bedroom	12	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	2 No.
2043732	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337644	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043706	First	F04 Bedroom	13	Yes	Window Sills	No Asbestos Detected	No Action	0 No Risk	2 No.

2337645	First	F04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043731	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043724	First	F03 Utility Room	14	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	16 m2
2043723	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2043691	First	F03 Utility Room	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2043725	First	Drying Room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043719	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2337648	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2337647	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043720	First	F02 Ablutions	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337646	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2337649	First	F02 Ablutions	16	Yes	Window Sills		No Action	0 No Risk	3 No.
2043721	First	Cupboard	17	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336667	First	17a - F02B Cleaners Store	17	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043765	First	Cupboard	18	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043754	First	Common /Bedroom	19	Yes	Ironing Board	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2043734	First	F25 Common Room	19	Yes	Window Sills		No Action	0 No Risk	2 No.
2043705	First	F25 Common Room	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043735	First	F25 Common Room	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2337650	First	F24 Ablutions	20	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043703	First	F24 Ablutions	20	Yes	Window Sills		No Action	0 No Risk	4 No.
2337651	First	F24 Ablutions	20	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043737	First	F24 Ablutions	20	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043736	First	F20 Ablutions	20	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2337652	First	F24 Ablutions	20	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2337653	First	21a - F24B Cleaners Store	21	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2043738	First	F24G Riser	21	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2336668	First	21a - F24B Cleaners Store	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2043692	First	F22 Utility Room	22	Yes	Window Sill		No Action	0 No Risk	1 No.

Run Date:
16/01/2017 03:43:47

Page:
32 of 113

Run By:
CD\svc_ProRepuser

2043740	First	F22 Utility Room	22	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	16 m2
2043739	First	F22 Utility Room	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2043742	First	Drying Room	23	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043741	First	Drying Room	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337654	First	F21 Bedroom	24	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043743	First	F21 Bedroom	24	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043708	First	F21 Bedroom	24	Yes	Window Sills		No Action	0 No Risk	2 No.
2043709	First	F20 Bedroom	25	Yes	Window Sills		No Action	0 No Risk	2 No.
2337655	First	F20 Bedroom	25	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043744	First	F20 Bedroom	25	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043710	First	F19 Bedroom	26	Yes	Window Sills		No Action	0 No Risk	2 No.
2043745	First	F19 Bedroom	26	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337657	First	F13 Corridor	27	Yes	Notice Board	No Asbestos Detected	No Action	0 No Risk	2 m2
2337656	First	F13 Corridor	27	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043715	First	F13 Corridor	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043777	First	Electrics Cupboard	28	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337662	Ground	G16 Entrance Lobby	29	Yes	Wall at Base of	No Asbestos Detected	No Action	0 No Risk	3 m2
2337660	Ground	G16 Entrance Lobby	29	Yes	Entrance	No Asbestos Detected	No Action	0 No Risk	4 m2
2337659	Ground	G16 Entrance Lobby	29	Yes	Ceiling (Under	No Asbestos Detected	No Action	0 No Risk	1 m2
2337658	Ground	G16 Entrance Lobby	29	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2337661	Ground / First	Stairwell	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2043753	Ground / First	Stairwell	29	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043718	Ground / First	Stairwell	29	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337664	Ground	G21 Bedroom	30	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337663	Ground	G21 Bedroom	30	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043681	Ground	G21 Bedroom	30	Yes	Window Sill		No Action	0 No Risk	1 No.
2337665	Ground	G20 Bedroom	31	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337666	Ground	G20 Bedroom	31	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043680	Ground	G20 Bedroom	31	Yes	Window Sill		No Action	0 No Risk	1 No.

2337668	Ground	G19 Bedroom	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337667	Ground	G19 Bedroom	32	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043679	Ground	G19 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	1 No.
2337669	Ground	G18 Bedroom	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043678	Ground	G18 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	1 No.
2337670	Ground	G18 Bedroom	33	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043751	Ground	G16B General Store	34	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2043757	Ground	Calorifier Room	35	Yes	Gaskets	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2043755	Ground	Calorifier Room	35	Yes	Fuse box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2043756	Ground	G16A Plant Room	35	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	1 No.
2043752	Ground	G16A Plant Room	35	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2043669	Ground	G15 Common Room	36	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2337671	Ground	G15 Common Room	36	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043684	Ground	G15 Common Room	36	Yes	Window Sills		No Action	0 No Risk	2 No.
2337672	Ground	G14 Bedroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043677	Ground	G14 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2337673	Ground	G14 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337674	Ground	G13 Bedroom	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043676	Ground	G13 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	1 No.
2337675	Ground	G13 Bedroom	38	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337677	Ground	G12 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043675	Ground	G12 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	1 No.
2337676	Ground	G12 Bedroom	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337679	Ground	G11 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043674	Ground	G11 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2337678	Ground	G11 Bedroom	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337680	Ground	G10 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043673	Ground	G10 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.

2337681	Ground	G10 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043687	Ground	G08 Bedroom	42	Yes	Window Sills		No Action	0 No Risk	2 No.
2337683	Ground	G07 Bedroom	43	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2337682	Ground	G07 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043686	Ground	G07 Bedroom	43	Yes	Window Sills		No Action	0 No Risk	2 No.
2043671	Ground	G05 Utility Room	44	Yes	Window Sill		No Action	0 No Risk	1 No.
2043670	Ground	G05 Utility Room	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2337684	Ground	G05 Utility Room	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2043672	Ground	Drying Room	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337686	Ground	G04 Ablutions	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337689	Ground	G04 Ablutions	46	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2043667	Ground	G04 Ablutions	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2337685	Ground	G04 Ablutions	46	Yes	Window Sills		No Action	0 No Risk	3 No.
2337688	Ground	G04 Ablutions	46	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2337687	Ground	G04 Ablutions	46	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2337690	Ground	47a - G04B Cleaners Store	47	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2336665	Ground	47a - G04B Cleaners Store	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2043712	Ground	G04F Riser	47	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043666	Ground	G02 Corridor	48	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2337691	Ground	G02 Corridor	48	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043665	Ground	G02 Corridor	48	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2043776	Ground	Riser Cupboard	49	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043775	Ground	Electric Cupboard	50	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043685	Ground	G28 Accommodation Store	51	Yes	Window Sills		No Action	0 No Risk	2 No.
2337693	Ground	G28 Accommodation Store	51	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337692	Ground	G28 Accommodation Store	51	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337694	Ground	G27 Ablutions	52	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337697	Ground	G27 Ablutions	52	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2337695	Ground	G27 Ablutions	52	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2

2337696	Ground	G27 Ablutions	52	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043711	Ground	G27 Ablutions	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2043683	Ground	G27 Ablutions	52	Yes	Window Sills		No Action	0 No Risk	4 No.
2337698	Ground	53a - G27B Cleaners Store	53	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2336666	Ground	53a - G27B Cleaners Store	53	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2043668	Ground	G27G Riser	53	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043713	Ground	G26 Utility Room	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2043682	Ground	G26 Utility Room	54	Yes	Window Sill		No Action	0 No Risk	1 No.
2337699	Ground	G26 Utility Room	54	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2043714	Ground	Drying Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337701	Ground	G25 Bedroom	56	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2337700	Ground	G25 Bedroom	56	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043688	Ground	G25 Bedroom	56	Yes	Window Sills		No Action	0 No Risk	2 No.
2337703	Ground	G24 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2337702	Ground	G24 Bedroom	57	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043689	Ground	G24 Bedroom	57	Yes	Window Sills		No Action	0 No Risk	2 No.
2337704	Ground	G23 Bedroom	58	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043690	Ground	G23 Bedroom	58	Yes	Window Sills		No Action	0 No Risk	2 No.
2337705	Ground	G23 Bedroom	58	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043774	Ground	G17 Corridor	59	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	3 m2
2337706	Ground	G17 Corridor	59	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337708	Ground	G17 Corridor	59	Yes	Notice Board	No Asbestos Detected	No Action	0 No Risk	1 m2
2337707	Ground	G17 Corridor	59	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2337709	First	F01 Corridor	60	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2043717	First	F01 Corridor	60	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043716	First	F01 Corridor	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2337710	First	F01 Corridor	60	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2043773	Roof	Roof	61	Yes	Fillets	No Asbestos Detected	No Action	0 No Risk	45 LM
2043758	Roof	Roof	61	Yes	Pipes	No Sample Required	No Action	0 No Risk	14 No.

2043772	External	External	62	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2043733	Roof Void	Roof Void	63	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337711	All	Internal / External	64	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100m2
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755831 - WEET01WEE018									
2043843	First	F18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2043902	First	F18 Bedroom	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043901	First	F17 Bedroom	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043842	First	F17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.
2338097	First	F17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043900	First	F16 Bedroom	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043841	First	F16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2043840	First	F15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 m2
2043899	First	F15 Bedroom	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043898	First	F14 Bedroom	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338098	First	F14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043839	First	F14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2043846	First	F12 Common Room	6	Yes	Window Sill		No Action	0 No Risk	2 No.
2338099	First	F12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043886	First	F11 Bedroom	7	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043838	First	F11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2338100	First	F11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043837	First	F10 Bedroom	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2338101	First	F10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043887	First	F10 Bedroom	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043836	First	F09 Bedroom	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2043890	First	F09 Bedroom	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043888	First	F09 Bedroom	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043835	First	F08 Bedroom	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2043834	First	F07 Bedroom	11	Yes	Window Sill		No Action	0 No Risk	1 No.

Run Date:
16/01/2017 03:43:47

Page:
37 of 113

Run By:
CD\svc_ProRepuSer

2043889	First	F05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2336655	First	F05 Bedroom	12	Yes	Window Sill		No Action	0 No Risk	2 No.
2338102	First	F05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338104	First	F04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043847	First	F04 Bedroom	13	Yes	Window Sill		No Action	0 No Risk	2 No.
2338103	First	F04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043823	First	F03 Utility Room	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2043883	First	F03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043884	First	Drying Room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043881	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338106	First	F02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338107	First	F02 Ablutions	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043880	First	F02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338105	First	F02 Ablutions	16	Yes	Window Sill		No Action	0 No Risk	3 No.
2338108	First	F02 Ablutions	16	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2043882	First	F02 Ablutions	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2335066	First	17a - Cisterns F02G	17	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2208726	First	F02B Cleaners Cupboard	17	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 m2
2208727	First	Riser	18	Yes			No Action	0 No Risk	0 N/A
2043878	First	F01 Corridor	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043877	First	F01 Corridor	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2208729	First	Electric Cupboard	20	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043891	First	F25 Common Room	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043892	First	F25 Common Room	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043848	First	F25 Common Room	21	Yes	Window Sill		No Action	0 No Risk	2 No.
2338110	First	F24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043895	First	F24 Ablutions	22	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338109	First	F24 Ablutions	22	Yes	Window Sills		No Action	0 No Risk	3 No.
2338112	First	F24 Ablutions	22	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2

2043894	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338111	First	F24 Ablutions	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043893	First	F24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2208732	First	Cistern Riser	23	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2336669	First	23a - F24B Cleaners Store	23	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338115	First	F24 Toilets	24	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338113	First	F24 Toilets	24	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2338116	First	F24 Toilets	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338114	First	F24 Toilets	24	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2043849	First	F24 Toilets	24	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2208731	First	F24 Toilets	24	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2043833	First	F22 Utility Room	25	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2043896	First	F22 Utility Room	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043897	First	Drying Room	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338117	First	F21 Bedroom	27	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043905	First	F21 Bedroom	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336656	First	F21 Bedroom	27	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 No.
2043904	First	F20 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043850	First	F20 Bedroom	28	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 No.
2338118	First	F19 Bedroom	29	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043903	First	F19 Bedroom	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043851	First	F19 Bedroom	29	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 No.
2208733	First	F13 Corridor	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043805	Ground	G01 Entrance Lobby	31	Yes	Wall at Base of	No Asbestos Detected	No Action	0 No Risk	4 m2
2043879	Ground / First	Stairwell	31	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043870	First	Stairwell	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2043876	Ground	G01 Entrance Lobby	31	Yes	Ceiling Under Stairs	No Asbestos Detected	No Action	0 No Risk	1 m2
2043806	First	G01 Entrance Lobby	31	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2043872	Ground	G21 Bedroom	32	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2

2043822	Ground	G21 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	1 No.
2338119	Ground	G21 Bedroom	32	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338120	Ground	G20 Bedroom	33	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043871	Ground	G20 Bedroom	33	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043821	Ground	G20 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	1 No.
2338121	Ground	G19 Bedroom	34	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043820	Ground	G19 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2335065	Ground	G19 Bedroom	34	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043869	Ground	G18 Bedroom	35	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043819	Ground	G18 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	1 No.
2338122	Ground	G18 Bedroom	35	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043845	Ground	G15 Common Room	36	Yes	Window Sill		No Action	0 No Risk	2 No.
2335063	Ground	G15 Common Room	36	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2338123	Ground	G15 Common Room	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043854	Ground	G14 Bedroom	37	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338124	Ground	G14 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043818	Ground	G14 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2043855	Ground	G13 Bedroom	38	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2336659	Ground	G13 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	1 No.
2338125	Ground	G13 Bedroom	38	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043817	Ground	G12 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	1 No.
2043856	Ground	G12 Bedroom	39	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338126	Ground	G12 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338127	Ground	G11 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043857	Ground	G11 Bedroom	40	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2043816	Ground	G11 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2043858	Ground	G10 Bedroom	41	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338128	Ground	G10 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043815	Ground	G10 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.

2043860	Ground	G08 Bedroom	42	Yes	Ironing Board	No Asbestos Detected	No Action	0 No Risk	1 m2
2043828	Ground	G08 Bedroom	42	Yes	Window Sill		No Action	0 No Risk	2 No.
2043859	Ground	G08 Bedroom	42	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338129	Ground	G08 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2338130	Ground	G07 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2208710	Ground	G07 Bedroom	43	Yes	Window Sill		No Action	0 No Risk	2 No.
2043827	Ground	G07 Bedroom	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043814	Ground	G05 Utility Room	44	Yes	Window Sill		No Action	0 No Risk	1 No.
2043813	Ground	G05 Utility Room	44	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043811	Ground	G05 Utility Room	44	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043812	Ground	G05 Utility Room	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043852	Ground	G06 Drying Room	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043853	Ground	G06 Drying Room	45	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	5 m2
2338133	Ground	G04 Ablutions	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2208735	Ground	G04 Ablutions	46	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338135	Ground	G04 Ablutions	46	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2338131	Ground	G04 Ablutions	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338134	Ground	G04 Ablutions	46	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338132	Ground	G04 Ablutions	46	Yes	Window Sill		No Action	0 No Risk	3 No.
2043810	Ground	G04B Cleaners Store	47	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043807	Ground	G04B Cleaners Store	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043808	Ground	G04B Cleaners Store	47	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 m2
2335062	Ground	47a - Cisterns G04F	47	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043809	Ground	G04B Cleaners Store	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2208736	Ground	G03 Store	48	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 m2
2208738	Ground	G02 Corridor	49	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338137	Ground	G02 Corridor	49	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	2 m2
2338136	Ground	G02 Corridor	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2208739	Ground	Electric Cupboard	50	Yes		No Sample Required	No Action	0 No Risk	0 N/A

2338138	Ground	G28 Sitting Room	51	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043908	Ground	G28 Sitting Room	51	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043826	Ground	G28 Sitting Room	51	Yes	Window Sill		No Action	0 No Risk	2 No.
2338141	Ground	G27 Ablutions	52	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2338139	Ground	G27 Ablutions	52	Yes	Window Sill		No Action	0 No Risk	3 No.
2338142	Ground	G27 Ablutions	52	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043861	Ground	G27 Ablutions	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2043862	Ground	G27 Ablutions	52	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338140	Ground	G27 Ablutions	52	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2208740	Ground	Cistern Riser	53	Yes			No Action	0 No Risk	0 N/A
2338144	Ground	G27A Toilet	54	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2338145	Ground	G27A Toilet	54	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2208741	Ground	G27A Toilet	54	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2335064	Ground	G27A Toilet	54	Yes	Window Sill		No Action	0 No Risk	1 No.
2338143	Ground	G27A Toilet	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338146	Ground	G27A Toilet	54	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	4 m2
2043866	Ground	G26 Utility Room	55	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043865	Ground	G26 Utility Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2043844	Ground	G26 Utility Room	55	Yes	Window Sill		No Action	0 No Risk	1 No.
2043867	Ground	G26A Drying Room	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043868	Ground	G26A Drying Room	56	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	5 m2
2338147	Ground	G25 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043875	Ground	G25 Bedroom	57	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043829	Ground	G25 Bedroom	57	Yes	Window Sill		No Action	0 No Risk	2 No.
2338148	Ground	G24 Bedroom	58	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043874	Ground	G24 Bedroom	58	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043830	Ground	G24 Bedroom	58	Yes	Window Sill		No Action	0 No Risk	2 No.
2043831	Ground	G23 Bedroom	59	Yes	Window Sill		No Action	0 No Risk	2 No.
2043873	Ground	G23 Bedroom	59	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2

2338149	Ground	G23 Bedroom	59	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2208743	Ground	G17 Corridor	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338150	Ground	G17 Corridor	60	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338151	Ground	G17 Corridor	60	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2208744	Ground	G16B General Store	61	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043906	Ground	G16A Plant Room	62	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2208720	Ground	Calorifier Room	62	Yes	Pipework	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2208718	Ground	Calorifier Room	62	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2338152	Ground	G16A Plant Room	62	Yes	Isolator Box (Flash Guards)	Presumed Asbestos Content	Monitor	6	1 m2
2208722	Roof	Roof	63	Yes	Cowl	No Sample Required	No Action	0 No Risk	0 N/A
2338153	External	External	64	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2208723	External	External	64	Yes	Fillets	No Asbestos Detected	No Action	0 No Risk	80 m
2043863	Ground	Cleaners Cupboard	65	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043864	Ground	Cleaners Cupboard	65	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043885	Roof Void	Roof Void	66	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338154	All	External / Internal	67	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2
WEETON CAMP - BARRACK BLOCK (SLA-Permanent) - 755843 - WEET01WE012A									
2043294	First	1.18 Bedroom	1	Yes	Window Sill		No Action	0 No Risk	1 No.
2337498	First	1.18 Bedroom	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337497	First	1.18 Bedroom	1	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337500	First	1.17 Bedroom	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043295	First	1.17 Bedroom	2	Yes	Window Sill		No Action	0 No Risk	1 No.
2337499	First	1.17 Bedroom	2	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043296	First	1.16 Bedroom	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2337502	First	1.16 Bedroom	3	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337501	First	1.16 Bedroom	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043297	First	1.15 Bedroom	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2337504	First	1.15 Bedroom	4	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2337503	First	1.15 Bedroom	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337506	First	1.14 Bedroom	5	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043298	First	1.14 Bedroom	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2337505	First	1.14 Bedroom	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337507	First	1.12 Common Room	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043371	First	1.12 Common Room	6	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2337508	First	1.12 Common Room	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2043291	First	1.11 Bedroom	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2337510	First	1.11 Bedroom	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337509	First	1.11 Bedroom	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043290	First	1.10 Bedroom	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2337512	First	1.10 Bedroom	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337511	First	1.10 Bedroom	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337514	First	1.09 Bedroom	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337513	First	1.09 Bedroom	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043289	First	1.09 Bedroom	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2337516	First	1.08 Bedroom	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337515	First	1.08 Bedroom	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043288	First	1.08 Bedroom	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2337517	First	1.07 Bedroom	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337518	First	1.07 Bedroom	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043287	First	1.07 Bedroom	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2043303	First	1.07 Bedroom	11	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337519	First	1.05 Bedroom	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043379	First	1.05 Bedroom	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043293	First	1.05 Bedroom	12	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043380	First	1.04 Bedroom	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337520	First	1.04 Bedroom	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043292	First	1.04 Bedroom	13	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.

2043372	First	1.03 Utility Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2336647	First	1.03 Utility Room	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2337521	First	1.03 Utility Room	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2043373	First	1.03A - Drying Room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2337522	First	1.02 Ablutions	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2337523	First	1.02 Ablutions	16	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2043348	First	1.02 Ablutions	16	Yes	Window Sills		No Action	0 No Risk	3 No.
2337524	First	1.02 Ablutions	16	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	10 m2
2043349	First	1.02G - Cistern Cupboard	17	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043350	First	1.02F - Service Riser	18	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337525	First	1.01 Corridor	19	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2333253	First	1.01 Corridor	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2043369	First	1.01 Corridor	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043351	First	1.16 - Electrics Cupboard	20	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043381	First	1.25 Common Room	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2336646	First	1.25 Common Room	21	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2337526	First	1.25 Common Room	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2337529	First	1.24 Ablutions	22	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	10 m2
2043370	First	1.24 Ablutions	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2337527	First	1.24 Ablutions	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2337530	First	1.24 Ablutions	22	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2337528	First	1.24 Ablutions	22	Yes	Window Sills		No Action	0 No Risk	3 No.
2043327	First	1.24G - Cupboard	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337531	First	1.24a - Toilet	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2337534	First	1.24a - Toilet	24	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk	2 m2
2337533	First	1.24a - Toilet	24	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	10 m2
2043342	First	1.24a - Toilet	24	Yes	Window Sill		No Action	0 No Risk	1 No.
2337532	First	1.24a - Toilet	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2337535	First	1.22 Utility Room	25	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2

2043383	First	1.22 Utility Room	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2
2335039	First	1.22 Utility Room	25	Yes	Window Sill		No Action	0 No Risk	1 No.
2043384	First	1.23 - Drying Room	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2043392	First	1.21 Bedroom	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337536	First	1.21 Bedroom	27	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043301	First	1.21 Bedroom	27	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043391	First	1.20 Bedroom	28	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337537	First	1.20 Bedroom	28	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043300	First	1.20 Bedroom	28	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043299	First	1.19 Bedroom	29	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043390	First	1.19 Bedroom	29	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337538	First	1.19 Bedroom	29	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043315	First	1.13 Corridor	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043312	First	1.13 Corridor	30	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043336	First	1.13 Corridor	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2337540	Ground	G01 Entrance Lobby	31	Yes	Ceiling (Under Ceiling)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337539	Ground / First	Stairwell	31	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2043314	Ground / First	Stairwell	31	Yes	Stair Nosing	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337541	Ground	G01 Entrance Lobby	31	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2043285	Ground	G21 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	1 No.
2337542	Ground	G21 Bedroom	32	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337543	Ground	G21 Bedroom	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043284	Ground	G20 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	1 No.
2337545	Ground	G20 Bedroom	33	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337544	Ground	G20 Bedroom	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337547	Ground	G19 Bedroom	34	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337546	Ground	G19 Bedroom	34	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043283	Ground	G19 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	1 No.
2337548	Ground	G18 Bedroom	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2043286	Ground	G18 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	1 No.
2337549	Ground	G18 Bedroom	35	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043304	Ground	G15 Common Room	36	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2043272	Ground	G15 Common Room	36	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043278	Ground	G15 Common Room	36	Yes	Window Sill		No Action	0 No Risk	1 m2
2043265	Ground	G15 Common Room	36	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337551	Ground	G14 Bedroom	37	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337550	Ground	G14 Bedroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043271	Ground	G14 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	1 No.
2043270	Ground	G13 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	1 No.
2337552	Ground	G13 Bedroom	38	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337553	Ground	G13 Bedroom	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337554	Ground	G12 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337555	Ground	G12 Bedroom	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043269	Ground	G12 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	1 No.
2337557	Ground	G11 Bedroom	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043268	Ground	G11 Bedroom	40	Yes	Window Sill		No Action	0 No Risk	1 No.
2337556	Ground	G11 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043352	Ground	G10 Bedroom	41	Yes	Window Sill		No Action	0 No Risk	1 No.
2337559	Ground	G10 Bedroom	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337558	Ground	G10 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2043273	Ground	G08 Bedroom	42	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043340	Ground	G08 Bedroom	42	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337560	Ground	G08 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043274	Ground	G07 Bedroom	43	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043341	Ground	G07 Bedroom	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337561	Ground	G07 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043262	Ground	G05 Utility Room	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	16 m2
2043339	Ground	G05 Utility Room	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	16 m2

2043275	Ground	G05 Utility Room	44	Yes	Window Sill	No Action	0 No Risk	1 No.
2043263	Ground	G05 Utility Room	44	Yes	Window Sill	No Action	0 No Risk	1 m2
2043360	Ground	G/06 - Drying Room	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 35 m2
2337563	Ground	G04 Ablutions	46	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk 10 m2
2337562	Ground	G04 Ablutions	46	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 30 m2
2043337	Ground	G04 Ablutions	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 16 m2
2337564	Ground	G04 Ablutions	46	Yes	Window Sills	No Action	0 No Risk	3 No.
2043353	Ground	G04F - Cistern Riser	47	Yes		No Sample Required	No Action	0 No Risk 0 N/A
2043354	Ground	G03 Riser	48	Yes		No Sample Required	No Action	0 No Risk 0 N/A
2337566	Ground	G02 Corridor	49	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk 20 m2
2043257	Ground	G02 Corridor	49	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337565	Ground	G02 Corridor	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 20 m2
2043355	Ground	G29 - Electrics Cupboard	50	Yes		No Sample Required	No Action	0 No Risk 0 N/A
2043264	Ground	G28 Sitting Room	51	Yes	Window Sill (x2)	No Action	0 No Risk	2 No.
2043279	Ground	G28 Sitting Room	51	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 25 m2
2043338	Ground	G28 Sitting Room	51	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 25 m2
2043267	Ground	G27 Ablutions	52	Yes	Window Sills	No Action	0 No Risk	3 No.
2043358	Ground	G27 Ablutions	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 16 m2
2043277	Ground	G27 Ablutions	52	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 30 m2
2337567	Ground	G27 Ablutions	52	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk 2 m2
2337568	Ground	G27 Ablutions	52	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk 3 m2
2043356	Ground	G27 - Cistern Riser	53	Yes		No Sample Required	No Action	0 No Risk 0 N/A
2337571	Ground	G27a - Toilet	54	Yes	Boxing	No Asbestos Detected	No Action	0 No Risk 2 m2
2337569	Ground	G27a - Toilet	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 16 m2
2337572	Ground	G27a - Toilet	54	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk 3 m2
2337570	Ground	G27a - Toilet	54	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 30 m2
2043361	Ground	G27a - Toilet	54	Yes	Window Sill	No Action	0 No Risk	1 No.
2337573	Ground	G26 Utility Room	55	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 16 m2
2043359	Ground	G26 Utility Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 16 m2

2043266	Ground	G26 Utility Room	55	Yes	Window Sill		No Action	0 No Risk	1 No.
2043308	Ground	G26B - Drying Room	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043282	Ground	G25 Bedroom	57	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2337574	Ground	G25 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043368	Ground	G25 Bedroom	57	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043281	Ground	G24 Bedroom	58	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2337575	Ground	G24 Bedroom	58	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2043367	Ground	G24 Bedroom	58	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043280	Ground	G23 Bedroom	59	Yes	Window Sill (x2)		No Action	0 No Risk	2 No.
2043366	Ground	G23 Bedroom	59	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337576	Ground	G23 Bedroom	59	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	25 m2
2337577	Ground	G17 Corridor	60	Yes	Ceiling Beam	No Asbestos Detected	No Action	0 No Risk	2 m2
2043258	Ground	G17 Corridor	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2337578	Ground	G17 Corridor	60	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2043333	Ground	G16B General Store	61	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2043345	Ground	Calorifier Room	62	Yes	Gaskets	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2043335	Ground	Calorifier Room	62	Yes	Pipework	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2043344	Ground	G16A Plant Room	62	Yes	Electrical Box (Flash Guards)	Presumed Asbestos Content	Monitor	5	1 m2
2043334	Ground	G16A Plant Room	62	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2043343	Roof	Roof	63	Yes	Flue pipes	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	14 No.
2043346	Roof	Roof	63	Yes	Fillets	No Asbestos Detected	No Action	0 No Risk	80 m
2043357	External	External	64	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2043321	First	Roof Void	65	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043318	First	Cleaners Cupboard	66	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043306	Ground	Cleaners Cupboard	67	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043260	Ground	Cleaners Cupboard	68	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336664	First	Cupboard	69	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337579	All	Internal / External	70	Yes	Metal Windows	No Asbestos Detected	No Action	0 No Risk	100 m2

WEETON CAMP - BATTALION HQ /ARMOURY /DETENTION CENTRE - 755832 - WEET01WEE020

2044108	Ground	Entrance Hall	1	Yes			No Action	0 No Risk	0 N/A
2335070	Ground	Reception	2	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 m2
2044153	Ground	Reception	2	Yes	Safe	Presumed Asbestos Content	Monitor	10 Medium	1 No.
2044094	Ground	Reception	2	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2200329	Ground	Corridor / Hall	3	Yes			No Action	0 No Risk	0 N/A
2044160	Ground	Cell	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044093	Ground	Cell	4	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044030	Ground	Hall	5	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	1 m2
2044161	Ground	Cleaners Cupboard	6	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044033	Ground	Cleaners Cupboard	6	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	1 m2
2200336	Ground	Electric Cupboard	7	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044154	Ground	Male Toilet	8	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044158	Ground	Male Toilet	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044116	Ground	Prisoners Toilet	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044169	Ground	Prisoners Toilet	9	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044055	Ground	Cell	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044045	Ground	Cell	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 No.
2044117	Ground	Cell	11	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044044	Ground	Cell	11	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044037	Ground	Cell	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044031	Ground	Cell	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1-m2
2044115	Ground	Cell	13	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044127	Ground	Cell	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044059	Ground	Cell	14	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044058	Ground	Cell	14	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044038	Ground	Cell	15	Yes			No Action	0 No Risk	0 N/A
2044087	First	Stairwell	16	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	12 LM
2044061	Ground	Stairwell	16	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
50 of 113

Run By:
CD\svc_ProRepuser

2044060	Ground	Stairwell	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044122	Ground	Guard Quarters G20	17	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335071	Ground	Guard Quarters G20	17	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044048	Ground	Guard Quarters G20	17	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335077	Ground	Guards Quarters G19	18	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 m2
2044159	Ground	Guards Quarters G19	18	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044046	Ground	Store	19	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044051	Ground	Store	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044164	Ground	Hall	20	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044032	Ground	Hall	20	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044012	Ground	Ammo Store	21	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044013	Ground	Ammo Store	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044099	Ground	Ammo Store	22	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044014	Ground	Ammo Store	22	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044049	Ground	Ammo Store	23	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044036	Ground	Ammo Store	23	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044039	Ground	Standby Generator	24	Yes			No Action	0 No Risk	0 N/A
2044020	Ground	Stairwell To First & Second	25	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044021	Ground	Stairwell To First & Second	25	Yes	Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044019	Ground	Stairwell To First & Second	25	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044040	Ground	Corridor	26	Yes			No Action	0 No Risk	0 N/A
2044052	Ground	Post Room	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044128	Ground	Post Room	27	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044088	Ground	Calorifier Room	28	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2044024	Ground	Calorifier Room	28	Yes	Pipe Flange	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044168	Ground	Fire Equipment Room	29	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044155	Ground	Fire Equipment Room	29	Yes	Fuse Box		No Action	0 No Risk	1 No.
2044054	Ground	Female Toilet	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044053	Ground	Armoury	31	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A

2044050	Ground	Armoury	32	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044078	Ground	Armoury	33	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044041	Ground	Armoury	34	Yes			No Action	0 No Risk	0 N/A
2044111	Ground	Armoury	35	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044043	Ground	Armourers Shop G32	36	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335072	Ground	Armourers Shop G32	36	Yes	Window Sill	Chrysotile	Monitor	9 Medium	2 No.
2044047	Ground	Armoury	37	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	40 m2
2044131	Ground	Corridor	38	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044042	Ground	Armoury	39	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044079	Ground	Armoury	40	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044152	First	Male Toilet	41	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 No.
2044100	First	Officers Toilet	42	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044144	First	Officers Toilet	42	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044015	First	Cleaners Cupboard	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044016	First	Computer Room	44	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044151	First	Computers	44	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044083	First	RSMs Office	45	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	2 No.
2044084	First	Office	46	Yes	Safe	Presumed Asbestos Content	Monitor	11 Medium	1 No.
2044098	First	Office	46	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044118	First	RCMOs Office	47	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044062	First	Office	48	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	2 m2
2044063	First	Office	49	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	3 m2
2044029	First	Typist Office	50	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 m2
2044064	First	Office F18	51	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 m2
2335073	First	Office F15	52	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 m2
2044025	First	Office F15	52	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044026	First	Orderly Office F14	53	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335074	First	Orderly Office F14	53	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 m2
2044105	First	Office	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
52 of 113

Run By:
CD\svc_ProRepuer

2044112	First	Office	54	Yes	Window Sill	Chrysotile	Monitor	6		1 No.
2044028	First	Corridor	55	Yes	Wall	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044065	First	Service Duct	56	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044066	First	Electric Cupboard	57	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044067	First	Corridor	58	Yes			No Action	0	No Risk	0 N/A
2044068	First	Stationery Cupboard	59	Yes			No Action	0	No Risk	0 N/A
2044142	First	Admin Office	60	Yes	Window Sill	Chrysotile	Monitor	6		3 No.
2044069	First	Office	61	Yes			No Action	0	No Risk	0 N/A
2044119	First	Male Toilet	62	Yes	Window Sill	Chrysotile	Monitor	6		1 No.
2044103	First	Corridor	63	Yes	Wall	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044022	First	Corridor	63	Yes	Wall	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044104	First	Corridor	63	Yes	Wall	No Asbestos Detected	No Action	0	No Risk	0 N/A
2377734	First	RANO Office	64	Yes	Safe	Presumed Asbestos Content	Monitor	10	Medium	1 No.
2044143	First	RANO Office	64	Yes	Window Sill	Chrysotile	Monitor	6		2 No.
2044023	First	Office	65	Yes	Wall	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044162	First	Office	65	Yes	Safe	Presumed Asbestos Content	Monitor	11	Medium	1 No.
2044157	First	Office	65	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2044070	First	Store	66	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044071	First	Secure Room	67	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044072	First	Store	68	Yes	Window Sill	Chrysotile	Monitor	6		3 No.
2044073	First	Corridor	69	Yes			No Action	0	No Risk	0 N/A
2044102	First	Board Room	70	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044101	First	Board Room	70	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2335075	First	Board Room	70	Yes	Window Sill	Chrysotile	Monitor	8		4 m2
2044074	First	Office	71	Yes	Window Sill	Chrysotile	Monitor	8		1 m2
2044018	First	Kitchen	72	Yes	Sink		No Action	0	No Risk	1 No.
2044017	First	Kitchen	72	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044075	Second	Ops Balcony	73	Yes			No Action	0	No Risk	0 N/A

2044027	Roof	Roof	74	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	70 m2
2044076	External	External	75	Yes			No Action	0 No Risk	0 N/A
2044077	Ground	Exchange Store	76	Yes			No Action	0 No Risk	0 N/A
2044056	Ground	Battery Room	77	Yes			No Action	0 No Risk	0 N/A
2044034	Ground	Lobby	78	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2044057	First	Balcony Comms Cupboard	79	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044080	First	Service Duct	80	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044081	Roof Void	Roof Void	81	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2335076	First	Storage Area Former Lockout	82	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	24 m2
WEETON CAMP - BOILER HOUSE - 755822 - WEET01WEE030									
2044435	Ground	Tank Room	1	Yes	Pipework	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044447	Ground	Tank Room	1	Yes	Window Sill	Chrysotile	Monitor	3 [REDACTED]	7 LM
2085955	Ground	Tank Room	1	Yes	Electric Boxes	No Sample Required	No Action	0 No Risk	3 No.
2085962	Ground	Tank Room	1	Yes	Gasket	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044436	Ground	Corridor	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2086037	Ground	Shower	3	Yes			No Action	0 No Risk	0 N/A
2044438	Ground	Toilet	4	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 m2
2044437	Ground	Toilet	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044439	Ground	Office	5	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 m2
2086036	Ground	Boiler House	6	Yes	Gasket	No Asbestos Detected	No Action	0 No Risk	1 No.
2044445	Ground	Boiler Room	6	Yes	Area	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2085973	Ground	Boiler Room	6	Yes	Fuse boxes	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	6 No.
2086024	Ground	Boiler House	6	Yes	Gasket	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	5 No.
2044443	Ground	Boiler Room	6	Yes	Ash Hopper	Chrysotile	Asbestos Removed	0 No Risk	1 No.
2044446	Ground	Boiler Room	6	Yes	Ash Silo	Chrysotile	Asbestos Removed	0 No Risk	1 No.
2086019	Ground	Boiler Room	6	Yes	Shelf	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	2 No.
2044440	Ground	Ash Silo	7	Yes	Ash Hopper	Chrysotile	Asbestos Removed	0 No Risk	1 No.
2044441	Ground	Ash Silo	7	Yes	Ash Hopper	Chrysotile	Asbestos Removed	0 No Risk	1 No.

Run Date:
16/01/2017 03:43:47

Page:
54 of 113

Run By:
CD\svc_ProRepuser

2149101	Ground	Ash Silo	7	Yes	Pipework	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2149102	Ground	Ash Silo	7	Yes	Fuse box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2044442	Ground	Ash Silo	7	Yes	Ash Hopper	Chrysotile	Asbestos Removed	0 No Risk	2 No.
2149100	Ground	Ash Silo	7	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2149103	Ground	Tipping Compound	8	Yes	Fuse Boxes	No Sample Required	No Action	0 No Risk	2 No.
2149104	Ground	Coal Silo	9	Yes			No Action	0 No Risk	0 N/A
2149105	Ground	Generator Room	10	Yes			No Action	0 No Risk	0 N/A
2044444	Roof	Roof	11	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2149106	External	External	12	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - C COY OFFICE - 755826 - WEET01WEE013									
2043403	Ground	Entrance	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043394	Ground	Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043400	Ground	Cleaners Cupboard	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043399	Ground	Cleaners Cupboard	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043409	Ground	Platoon Commanders Office	3	Yes	Window Sill	Chrysotile	Monitor	7	3 No.
2043395	Ground	CSM Office	4	Yes	Window Sill	Chrysotile	Monitor	8	2 No.
2043402	Ground	Officers Toilet	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043401	Ground	Officers Toilet	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043404	Ground	Locker Room / Toilet	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043412	Ground	Locker Room / Toilet	6	Yes	Window Sill	Chrysotile	Monitor	7	30 LM
2043397	Ground	Bedding Store	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043396	Ground	Bedding Store	7	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043398	Ground	Bedding Store	7	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043405	Ground	Second In Commands Office	8	Yes	Window Sill	Chrysotile	Monitor	8	1 No.
2340145	Ground	Officer In Commands Office	9	Yes	Safe	Presumed Asbestos Content	Monitor	7	1 No.
2043407	Ground	Officer In Commands Office	9	Yes	Window Sill	Chrysotile	Monitor	7	2 No.
2043422	Ground	Entrance	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043414	Ground	Entrance	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
55 of 113

Run By:
CD\svc_ProRepuser

2043417	Ground	Cleaners Cupboard	11	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043419	Ground	Cleaners Cupboard	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043410	Ground	Platoon Commanders Office	12	Yes	Window Sill	Chrysotile	Monitor	7	3 No.
2043411	Ground	CSM	13	Yes	Window Sill	Chrysotile	Monitor	7	2 No.
2043421	Ground	Officers Toilet	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043420	Ground	Officers Toilet	14	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043423	Ground	Locker Room / Toilet	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043413	Ground	Locker Room / Toilet	15	Yes	Window Sill	Chrysotile	Monitor	7	30 LM
2043416	Ground	Bedding Store	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043418	Ground	Bedding Store	16	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043415	Ground	Bedding Store	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043406	Ground	Second In Commands Office	17	Yes	Window Sill	Chrysotile	Monitor	8	1 No.
2043408	Ground	Officer In Commands Office	18	Yes	Window Sill	Chrysotile	Monitor	7	2 No.
2043424	Ground	Calorifier Room	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043427	Ground	Calorifier Room	19	Yes	Pipework	Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2043425	Ground	Calorifier Room	19	Yes	Flange	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2043428	Ground	Calorifier Room	19	Yes	Fuse box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2043426	Roof	Roof	20	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043447	External	External	21	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - CLIMBING WALL - 3004000 - WEET01XPT002									
2219117	All	Climbing Wall	0	Yes		No Sample Required	No Action	0 No Risk	0 N/A
WEETON CAMP - CONTRACTORS WORKS BUILDING / MAIN INTAKE SUBSTATION - 755837 - WEET01WEE027									
2085412	Ground	Yard	1	Yes			No Action	0 No Risk	0 N/A
2085414	Ground	POL Store	2	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2085415	Ground	Store	3	Yes			No Action	0 No Risk	0 N/A
2044403	Ground	Store	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044406	Ground	Yard	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044390	Ground	Workshop G13	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

2335037	Ground	Workshop G13	6	Yes	Window Sill	Chrysotile	Monitor	8	[REDACTED]	2 No.
2044401	Ground	Kitchen / Mess Room	7	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044402	Ground	Kitchen / Mess Room	7	Yes	Sink		No Action	0	No Risk	1 No.
2044404	Ground	EWC Office G09	8	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044394	Ground	EWC Office G09	8	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	1 No.
2044407	Ground	Workshop 1	9	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044395	Ground	Workshop 1 G06	9	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	2 No.
2085419	Ground	Cleaners Cupboard	10	Yes			No Action	0	No Risk	0 N/A
2085420	Ground	Electric Cupboard	11	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044396	Ground	Workshop 2 G03	12	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	3 No.
2044405	Ground	Workshop 2	12	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044398	Ground	Office G02	13	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	1 No.
2044399	Ground	Office G05	14	Yes	Window Sill	Chrysotile	Monitor	8	[REDACTED]	3 No.
2044397	Ground	Office G08	15	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	2 No.
2085422	Ground	Store	16	Yes			No Action	0	No Risk	0 N/A
2044393	Ground	Supervisor Toilet	17	Yes	Window Sill	Chrysotile	Monitor	6	[REDACTED]	1 No.
2044400	Ground	Supervisor Toilet	17	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044389	Ground	Industrial Toilets	18	Yes	Window Sill	Chrysotile	Monitor	7	[REDACTED]	2 No.
2044388	Ground	Industrial Toilets	18	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2085425	Ground	Cupboard	19	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044387	Ground	Corridor	20	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2085428	Ground	Sub Station	21	Yes			No Action	0	No Risk	0 N/A
2085381	Ground	Switch Room	22	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	1 No.
2085384	Ground	Switch Room	22	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	1 No.
2085432	Ground	Meter Room	23	Yes			No Action	0	No Risk	0 N/A
2085391	Ground	Transformer Room	24	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	1 No.
2085388	Ground	Transformer Room	24	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	1 No.
2085395	Ground	Switch Room	25	Yes	Fuse Boxes	No Sample Required	No Action	0	No Risk	0 N/A
2085397	Ground	Switch Room	25	Yes	Fuse Boxes	No Sample Required	No Action	0	No Risk	0 N/A

2085400	Ground	Calorifier Room	26	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2044409	Ground	Calorifier Room	26	Yes	Flange	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085406	Roof	Roof	27	Yes	Pipe	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	25 m
2044391	Roof	Roof	27	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044392	Roof	Roof	27	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044408	External	External	28	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - COY (NON TECHNICAL) STORES - 754016 - WEET01WEE025									
2044350	Ground	Mortar platoon store	1	Yes			No Action	0 No Risk	0 N/A
2044349	Ground	Milan store	2	Yes			No Action	0 No Risk	0 N/A
2044348	Ground	Store	3	Yes			No Action	0 No Risk	0 N/A
2044347	Ground	Toilet	4	Yes			No Action	0 No Risk	0 N/A
2044344	Ground	Toilet	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044352	Ground	Paint store	5	Yes			No Action	0 No Risk	0 N/A
2044351	Ground	Empty cartridge store	6	Yes			No Action	0 No Risk	0 N/A
2044353	Ground	Compound	7	Yes			No Action	0 No Risk	0 N/A
2084964	Ground	Lobby	8	Yes			No Action	0 No Risk	0 N/A
2084968	Ground	Electric Cupboard	9	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2084969	Ground	Hose Cupboard	10	Yes			No Action	0 No Risk	0 N/A
2044346	Ground	External roofing	11	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044354	External	External	12	Yes			No Action	0 No Risk	0 N/A
2044345	Roof Void	Roof Void	13	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - CQM STORES - 755836 - WEET01WEE026									
2340829	Ground	All Areas	0	Yes	Window Sills	Presumed Asbestos Content	Monitor	7	0 N/A
2044355	Ground	Adventure Training Store	1	Yes			No Action	0 No Risk	0 N/A
2044356	Ground	Regimental Signals Equipment Store	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044357	Ground	Store	3	Yes			No Action	0 No Risk	0 N/A
2044358	Ground	Unserviceable Store	4	Yes			No Action	0 No Risk	0 N/A

2044359	Ground	Fire Hose Reel	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 m2
2044360	Ground	Issues 5	6	Yes			No Action	0 No Risk	0 N/A
2044361	Ground	Stores Office	7	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044362	Ground	Unserviceable Store	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044363	Ground	Issues 4	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044364	Ground	Stores Office	10	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044365	Ground	Unserviceable Store	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044366	Ground	Issues 3	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044367	Ground	Stores Office	13	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044368	Ground	Unserviceable Store	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044369	Ground	Issues 2	15	Yes			No Action	0 No Risk	0 N/A
2044370	Ground	Stores Office	16	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044371	Ground	Unserviceable Store	17	Yes			No Action	0 No Risk	0 N/A
2044372	Ground	Issues 1	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044373	Ground	Stores Office	19	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044374	Ground	Unserviceable Store	20	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044375	Roof	Roof	21	Yes			No Action	0 No Risk	0 N/A
2044376	External	External	22	Yes			No Action	0 No Risk	0 N/A

WEETON CAMP - EMPTY (SUBSTATION EQUIPMENT REMOVED) - 755759 - WEET02WETH84

2091152	Ground	Electricity Substation (4 No. Store Room)	1	Yes	Wall	Chrysotile	Monitor	9 Medium	0 m2
2333154	Ground	Electricity Substation (Redundant)	2	Yes			No Action	0 No Risk	0 N/A
2333155	Ground	Electricity Substation (Redundant)	3	Yes			No Action	0 No Risk	0 N/A
2333156	Ground	Electricity Substation (Redundant)	4	Yes			No Action	0 No Risk	0 N/A

WEETON CAMP - FAMILIES CENTRE/HIVE/WELFARE OFFICE/WATERING HOLE - 755813 - WEET01WEE040

2129070	Ground	Entrance	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2129068	Ground	Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2085217	Ground	Beauty Therapy Room	2	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	2 No.
2085227	Ground	Beauty Therapy Room	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2085223	Ground	Beauty Therapy Room	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	40 m2

Run Date:
16/01/2017 03:43:47

Page:
59 of 113

Run By:
CD\svc_ProRepuser

2044647	Roof Void	Roof Void	3	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044644	Ground	Female Toilets	4	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2129075	Ground	Female Toilets	4	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	15 m2
2129072	Ground	Female Toilets	4	Yes	Lobby Ceiling	No Asbestos Detected	No Action	0 No Risk	0 m2
2129077	Ground	Telephone	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 m2
2129080	Ground	Telephone	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2129083	Ground	Cleaners Cupboard	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2333243	Ground	Cleaners Cupboard	6	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 m2
2129085	Ground	Sluice	7	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	4 m2
2333244	Ground	Sluice	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2129097	Ground	Male Toilets	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2044643	Ground	Male Toilets	8	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2129090	Ground	Male Toilets Lobby area	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	1 m2
2044631	Ground	Electrical Cupboard	9	Yes	Ceiling	Chrysotile	Monitor	4 [REDACTED]	1 m2
2044632	Ground	Electrical cupboard	9	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2129112	Ground	Cleaner	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2129104	Ground	Cleaner	10	Yes	Ceiling	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2129115	Ground	Girls Toilet	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2129118	Ground	Boys Toilet	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2044627	Ground	Boys Toilet	12	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2129122	Ground	Community Hall Lounge	13	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	100 m2
2129125	Ground	Community Hall Lounge	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	100 m2
2333249	Ground	Bar	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	35 m2
2085237	Ground	Bar	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085228	Ground	Bar	14	Yes	Sink Unit	No Asbestos Detected	No Action	0 No Risk	3 No.
2333247	Ground	Activity Room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	45 m2
2333246	Ground	Activity Room	15	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2085250	Ground	Activity Room	15	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	4 No.
2085265	Ground	Games Room	16	Yes			No Action	0 No Risk	0 N/A

2085266	Ground	Corridor	17	Yes			No Action	0 No Risk	0 N/A
2044668	Ground	Kitchen	18	Yes	Sink Unit	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044623	Ground	Kitchen	18	Yes	Sink Unit	No Asbestos Detected	No Action	0 No Risk	0 N/A
2129130	Ground	Kitchen	18	Yes	Walls	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2129132	Ground	Activity 1	19	Yes			No Action	0 No Risk	0 N/A
2129135	Ground	Activity 1	19	Yes	Ceiling	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	0 N/A
2085268	Ground	Store Office	20	Yes			No Action	0 No Risk	0 N/A
2085269	Ground	Activity 2	21	Yes			No Action	0 No Risk	0 N/A
2085270	Ground	Activity 3	22	Yes			No Action	0 No Risk	0 N/A
2129138	Ground	Corridor	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	60 m2
2129143	Ground	Corridor	23	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	40 m2
2129147	Ground	Waiting Room	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	35 m2
2044660	Ground	Waiting Room	24	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044659	Ground	Photocopy	25	Yes	Window Sill	Chrysotile	Monitor	6	1 No.
2044658	Ground	Office Clerk	26	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044657	Ground	UWO Office	27	Yes	Window Sill	Chrysotile	Monitor	7	2 No.
2085256	Ground	Cleaners	28	Yes	Sink Unit	No Asbestos Detected	No Action	0 No Risk	1 No.
2333242	Ground	Cleaners	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2333248	Ground	Cleaners	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	6 m2
2044661	Ground	SNCO Office	29	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044662	Ground	Unit Welfare	30	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044663	Ground	Welfare Drivers	31	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044664	Ground	UWO Clerk	32	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2044656	Ground	Female Toilets	33	Yes	Window Sill	Chrysotile	Monitor	6	2 No.
2129149	Ground	Female Toilet	33	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2044655	Ground	Male Toilets	34	Yes	Window Sill	Chrysotile	Monitor	6	2 No.
2129152	Ground	Male Toilet	34	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2044652	Ground	Store Room	35	Yes		No Sample Required	No Action	0 No Risk	0 N/A

2085272	Ground	Baby Changing Area	36	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2129154	Ground	Community Room	37	Yes			No Action	0 No Risk	0 N/A
2044651	Ground	Community Room	37	Yes	Sill		Asbestos Removed	0 No Risk	2 m2
2044654	Ground	Commanding Officer	38	Yes			No Action	0 No Risk	0 N/A
2044653	Ground	General Offices	39	Yes			No Action	0 No Risk	0 N/A
2044671	Ground	Calorifier Room	40	Yes	Pipework	Chrysotile	Monitor	10 Medium	6 No.
2085264	Ground	Calorifier	40	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	2 No.
2333245	Ground	Calorifier Room	40	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 m2
2377730	Ground	Calorifier Room	40	Yes	Electrics Box	Presumed Asbestos Content	Monitor	10 Medium	1 m2
2129157	Ground	Calorifier Room	40	Yes	Ceiling	Chrysotile	Monitor	9 Medium	20 m2
2333148	Ground	Store Room	41	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2085273	Roof	Roof	42	Yes			No Action	0 No Risk	0 N/A
2044672	External	External	43	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044673	External	External	43	Yes	Gutter	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - FIBUA SKILLS HOUSE - 755818 - WEET02WEE0N1									
2044853	Ground	Hall	1	Yes			No Action	0 No Risk	0 N/A
2146679	Ground	Room 2	2	Yes			No Action	0 No Risk	0 N/A
2146681	Ground	Room 3	3	Yes			No Action	0 No Risk	0 N/A
2146689	Ground	Room 4	4	Yes			No Action	0 No Risk	0 N/A
2146695	Ground	Room 5	5	Yes			No Action	0 No Risk	0 N/A
2146702	First	Hall	6	Yes			No Action	0 No Risk	0 N/A
2146705	First	Room 7	7	Yes			No Action	0 No Risk	0 N/A
2146707	First	Room 8	8	Yes			No Action	0 No Risk	0 N/A
2146712	First	Room 9	9	Yes			No Action	0 No Risk	0 N/A
2146715	First	Room 10	10	Yes			No Action	0 No Risk	0 N/A
2146720	Second	Room 11	11	Yes			No Action	0 No Risk	0 N/A
2146725	Roof Void	Roof Void	12	Yes			No Action	0 No Risk	0 N/A
2146729	Basement	Room 13	13	Yes			No Action	0 No Risk	0 N/A

2146733	Basement	Room 14	14	Yes			No Action	0 No Risk	0 N/A
2146737	Basement	Landing	15	Yes			No Action	0 No Risk	0 N/A
2146780	External	External	17	Yes	Floor		Asbestos Removed	0 No Risk	1.m2
2146762	Ground	Garage	18	Yes	Floor	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2146772	Roof	Garage	18	Yes	Roof	Chrysotile	Asbestos Removed	0 No Risk	10 m2
WEETON CAMP - Gas Distribution Network - 1219111 - WEET01XGD001									
2111024	All	Gas Network	0	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - Grounds Maintenance - WEET - WEETXXGROUND									
2336658	External	Grounds Maintenance	1	Yes	Plant Bedding Pots	No Asbestos Detected	No Action	0 No Risk	4 No.
WEETON CAMP - HEADQUARTERS COY OFFICE - 754015 - WEET01WEE019									
2147078	Ground	Front Entrance	1	Yes			No Action	0 No Risk	0 N/A
2043970	Ground	Male Toilet	2	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 m2
2044010	Ground	Electrics Cupboard	3	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043972	Ground	Female Toilet	4	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 m2
2043971	Ground	Bedding Store	5	Yes			No Action	0 No Risk	0 N/A
2043980	Ground	Locker	6	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	30 LM
2043990	Ground	Bugle Section	7	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	4 No.
2043978	Ground	CSM Clerk	8	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 m2
2043977	Ground	Cleaners Store	9	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 No.
2335067	Ground	Office in Command	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2043976	Ground	Office in Command	10	Yes	Safe	Presumed Asbestos Content	Monitor	12 Medium	1 No.
2148330	Ground	Office In Command	10	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 No.
2043975	Ground	CSM Office	11	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 No.
2335068	Ground	CSM Office	11	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2043974	Ground	COS Office	12	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2335069	Ground	COS Office	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2043979	Ground	Calorifier Room	13	Yes			No Action	0 No Risk	0 N/A
2043981	Ground	Laundry	14	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2

2147083	Ground	Shower Room	15	Yes	Window Sill	Chrysotile	Monitor	6		4 No.
2147088	Roof	Roof	16	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044009	External	External	17	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - JUNIOR RANKS MESS / ELECTRICITY SUB STATION - 755829 - WEET01WEE016										
2043602	Ground	0.01 - Entrance	1	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043603	Ground	0.01 - Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043605	Ground	0.02 - Male Toilet	2	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043604	Ground	0.03 - Female Toilet	3	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043606	Ground	0.04 - Cleaners Cupboard	4	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043608	Ground	0.05 - Dining Room	5	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043607	Ground	0.05 - Dining Room	5	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043646	Ground	0.06 - Riser	6	Yes			No Action	0	No Risk	0 N/A
2043632	Ground	0.07 - Crockery Wash Room G/04	7	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043635	Ground	0.07 - Crockery Wash Room G/04	7	Yes	Work Tops	Chrysotile Trace	Monitor	7		4 m2
2043631	Ground	0.08 - Crockery Store	8	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043637	Ground	0.09 - Wash Room	9	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	28 m2
2043636	Ground	0.09 - Wash Room	9	Yes	Work Tops	No Asbestos Detected	No Action	0	No Risk	6 m2
2043630	Ground	0.10 - Equipment Store	10	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043639	Ground	0.11 - Wash Room	11	Yes	Work Tops	Chrysotile Trace	Monitor	7		5.m2
2043638	Ground	0.11 - Wash Room	11	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	30 m2
2043628	Ground	0.12 - Vegetable Preparation G/34	12	Yes	Sink	Chrysotile	Monitor	9	Medium	3 m2
2043627	Ground	0.12 - Vegetable Preparation G/34	12	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043626	Ground	0.13 - Kitchen Entrance	13	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043640	Ground	0.14 - Ration Office	14	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2043625	Ground	0.14 - Ration Office	14	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043642	Ground	0.15 - Grocery Store	15	Yes	Pipework		No Action	0	No Risk	4 No.
2043624	Ground	0.15 - Grocery Store	15	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043641	Ground	0.15 - Grocery Store	15	Yes	Window Sill	Chrysotile	Monitor	7		3 No.
2043622	Ground	0.16 - Butchery G/33	16	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A

2043623	Ground	0.16 - Butchery G/33	16	Yes	Sink	Chrysotile	Monitor	7		1 m2
2043610	Ground	0.17 - Kitchen	17	Yes	Work Surfaces	Chrysotile	Monitor	8		2 m
2043609	Ground	0.17 - Kitchen	17	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043643	Ground	0.18 - Prep Room	18	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	30 m2
2043647	Ground	0.19 - Electrics	19	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2043612	Ground	0.20 - Corridor	20	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043629	Ground	0.21 - Female Changing Room	21	Yes	Skylight	No Asbestos Detected	No Action	0	No Risk	4 m2
2044230	Ground	0.21 - Female Changing Room	21	Yes	Floor Covering	No Asbestos Detected	No Action	0	No Risk	12 m2
2043613	Ground	0.21 - Female Changing Room	21	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	12 m2
2043616	Ground	0.22 - Rest Room G/17A	22	Yes	Window Sill		No Action	0	No Risk	1 No.
2043614	Ground	0.22 - Rest Room G/17A	22	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2336650	Ground	0.22 - Electrics Cupboard (22a)	22	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2043648	Ground	0.23 - Female Toilet G/17C	23	Yes	Window Sill		No Action	0	No Risk	1 No.
2043615	Ground	0.23 - Female Toilet G/17C	23	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	20 m2
2043644	Ground	0.24 - Male Locker Room G/15	24	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	20 m2
2043618	Ground	0.24 - Male Locker Room G/15	24	Yes	Window Sill		No Action	0	No Risk	2 No.
2043620	Ground	0.24 - Male Locker Room G/15	24	Yes	Floor Covering	No Asbestos Detected	No Action	0	No Risk	12 m2
2043617	Ground	0.25 - Male Toilet G/15B	25	Yes	Window Sill		No Action	0	No Risk	1 No.
2043645	Ground	0.25 - Male Toilet G/15B	25	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	18 m2
2043621	Ground	0.26 - Cleaners Cupboard G/14	26	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2335032	Ground	0.26 - Cleaners Cupboard G/14	26	Yes	Window Sill	Chrysotile	Monitor	5		1 No.
2043649	Ground	0.27 - Shower Room	27	Yes	Skylight	No Asbestos Detected	No Action	0	No Risk	4 m2
2043611	Ground	0.28 - Catering Office	28	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2043619	Ground	Catering Office	28	Yes	Window Sill	Chrysotile	Asbestos Removed	0	No Risk	1 m2
2043650	Ground	0.29 - Staff Dining	29	Yes			No Action	0	No Risk	0 N/A
2043651	Ground	0.30 - Kitchen Store	30	Yes			No Action	0	No Risk	0 N/A
2043652	Ground	0.31 - Switch Gear	31	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2043653	Ground	0.32 - Switch Gear	32	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2043654	Ground	0.33 - Bin Store	33	Yes			No Action	0	No Risk	0 N/A

2043655	Ground	0.34 - Room	34	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2335033	Ground	0.35 - Calorifier Room	35	Yes		No Asbestos Detected	No Action	0 No Risk	0 N/A
2043633	Ground	0.35 - Calorifier Room	35	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336657	Ground	0.36 - Boxing Gym (Weapons Cleaning Room)	36	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	20 LM
2043634	Roof Void	Roof Void	37	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043656	Roof	Roof	38	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043657	External	External	39	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - MEDICAL AND DENTAL CENTRE - 753599 - WEET01WEE041									
2044704	Ground	Covered Entrance	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044705	Ground	Entrance / Corridor	2	Yes	Ceiling	Chrysotile	Monitor	8 [REDACTED]	25 m2
2044763	Ground	Male Toilet Lobby (03a)	3	Yes	Ceiling	Chrysotile	Monitor	5 [REDACTED]	1 m2
2044730	Ground	Male Toilet	3	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044747	Ground	Male Toilet	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044764	Ground	Electrical Cupboard	4	Yes	Ceiling		No Action	0 No Risk	1 m2
2486210	Ground	Electrical Cupboard	4	Yes	Electric Boxes	Presumed Asbestos Content	Monitor	9 Medium	1 m2
2044765	Ground	Electrical Cupboard	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044766	Ground	Electrical Cupboard	4	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044749	Ground	Store	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044751	Ground	Female Toilet	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044752	Ground	Waiting Room / Reception Lobby	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044753	Ground	Waiting Room / Reception Lobby	7	Yes	Ceiling	Chrysotile	Monitor	9 Medium	10 m2
2044756	Ground	Clinic	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044731	Ground	Clinic	8	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 No.
2044754	Ground	Clinic	8	Yes	Sink	Chrysotile	Monitor	6 [REDACTED]	2 No.
2340151	Ground	Consulting Room	9	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044755	Ground	Consulting Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044750	Ground	Medical Store	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2147352	Ground	Waiting Room	11	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.

2044757	Ground	Dental Store	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044733	Ground	Recovery Room	13	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044761	Ground	Recovery Room	13	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044758	Ground	Dental Surgery	14	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2044759	Ground	Dental Surgery	14	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2044734	Ground	Dental Surgery	14	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044760	Ground	Dark Room	15	Yes	Sink	Chrysotile	Monitor	6 [REDACTED]	2 No.
2044736	Ground	Dark Room	15	Yes	Sill		No Action	0 No Risk	1 m2
2044735	Ground	Plaster Room	16	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044737	Ground	Documentation Room	17	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044738	Ground	Consulting Room	18	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044706	Ground	Consulting Room	18	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044732	Ground	Consulting Room	18	Yes	Sill		No Action	0 No Risk	1 m2
2044707	Ground	Consulting Room	18	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 No.
2044739	Ground	Consulting Room	18	Yes	Sill		No Action	0 No Risk	1 m2
2044719	Ground	Female Toilets	19	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044709	Ground	Cleaners Room	20	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044718	Ground	Medical Staff Toilet	21	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044727	Ground	Medical Staff Toilet	21	Yes	Sill		No Action	0 No Risk	1 m2
2044711	Ground	Sluice Room	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044720	Ground	Nurses Room	23	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044717	Ground	Servery	24	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 No.
2044715	Ground	Servery	24	Yes	Sink and Drainer	Chrysotile	Monitor	7 [REDACTED]	2 No.
2044714	Ground	Servery	24	Yes	Sink and Drainer	Chrysotile	Monitor	7 [REDACTED]	2 No.
2044713	Ground	Servery	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044716	Ground	Dining Room	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044721	Ground	Dining Room	25	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	3 No.
2044722	Ground	Ward B	26	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044740	Ground	Ward B	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

2044708	Ground	Toilet	27	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044770	Ground	Toilet	27	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044741	Ground	Bathroom	28	Yes	Ceiling	Chrysotile	Monitor	6 [REDACTED]	2 m2
2044742	Ground	Linen Cupboard	29	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044723	Ground	Ward A	30	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 No.
2044743	Ground	Rest Room	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044771	Ground	Bathroom	31	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044744	Ground	Staff Lockers	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044724	Ground	Staff Locker Room	32	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044725	Ground	Mental Health Nurse	33	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 No.
2044729	Ground	Treatment Room	34	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044745	Ground	Treatment Room	34	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2340152	Ground	Male Toilet	35	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044710	Ground	Male Toilet	35	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044728	Ground	Shower Room	36	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044748	Ground	Shower Room	36	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044712	Ground	Reception	37	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044726	Ground	Reception	37	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 No.
2044746	Ground	Reception	37	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2044768	Ground	Calorifier Room	38	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044767	Ground	Calorifier Room	38	Yes	Ceiling	Chrysotile	Encapsulate/Repair	6 [REDACTED]	10 m2
2044779	Ground	Calorifier Room	38	Yes	Electrical Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	2 No.
2044769	Roof	Roof	39	Yes	Soffit	No Asbestos Detected	No Action	0 No Risk	0 N/A
2197117	Roof	Roof	39	Yes	Roofing Felt	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044762	Roof	Roof	39	Yes	Flue	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	40 m
2044777	External	External	40	Yes			No Action	0 No Risk	0 N/A
2044772	Ground	Gas Cylinder Housing	41	Yes			No Action	0 No Risk	0 N/A
2175382	Roof Void	Roof Void	42	Yes			No Action	0 No Risk	0 N/A

WEETON CAMP - MOPED SHELTER - 754017 - WEET01WEE003

2042327	Ground	Moped Shelter	1	Yes			No Action	0 No Risk	0 N/A
2042326	Roof	Roof	2	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042328	External	External	3	Yes	Fuse Box	No Sample Required	No Action	0 No Risk	1 No.

WEETON CAMP - NAFFI/ NURSERY/ WIVES CLUB - 755812 - WEET01WEE039

2085262	Ground	0.01 - Electric Cupboard	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044586	Ground	0.02 - Kitchen	2	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2085581	Ground	0.02 - Kitchen	2	Yes	Sink	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044575	Ground	Male Locker	3	Yes	Sill	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2044580	Ground	0.03 - Male Changing Room	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044576	Ground	Female Locker	4	Yes	Sill	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2044581	Ground	0.04 - Female Changing Room	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085207	Ground	0.05 - Corridor	5	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	1 No.
2044577	Ground	0.05 - Corridor	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085246	Ground	Corridor	5	Yes	Fire Blanket	Chrysotile	Asbestos Removed	0 No Risk	1 No.
2085190	Ground	0.06 - Empties	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	50 m2
2085255	Ground	0.06 - Empties	6	Yes	Ceiling	Chrysotile Trace	Monitor	7 [REDACTED]	20 m2
2085583	Ground	0.07 - Compressor Room	7	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044572	Ground	0.08 - General Office	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2044573	Ground	0.08 - General Office	8	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2044571	Ground	0.08 - General Office	8	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085176	Ground	0.09 - Londis Shop	9	Yes	Safe	Presumed Asbestos Content	Monitor	10 Medium	1 No.
2044570	Ground	0.09 - Londis Shop	9	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044567	Ground	0.09 - Londis Shop	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	130 m2
2044568	Ground	0.09 - Londis Shop	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044569	Ground	0.09 - Londis Shop	9	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	0 N/A
2085584	Ground	0.10 - Main Entrance	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2410561	Ground	0.10 - Main Entrance	10	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	8 m2
2044597	Ground	0.11 - Staff Room	11	Yes	Flooring	No Asbestos Detected	No Action	0 No Risk	12 m2

Run Date:
16/01/2017 03:43:47

Page:
69 of 113

Run By:
CD\\svc_ProRepuser

2044585	Ground	0.11 - Staff Room	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2044584	Ground	0.11 - Staff Room	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2410562	Ground	0.12 - Store	12	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	8 m2
2085253	Ground	0.12 - Store	12	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2044590	Ground	0.13 - Baby Room	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2410556	Ground	0.14 - Baby Area	14	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	12 m2
2085203	Ground	0.14 - Baby Area	14	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	2 No.
2044579	Ground	0.14 - Baby Area	14	Yes	Sink and Drainer	No Asbestos Detected	No Action	0 No Risk	1 No.
2044574	Ground	0.14 - Baby Area	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2044578	Ground	0.14 - Baby Area	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	30 m2
2044592	Ground	0.14 - Baby Area	14	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2410563	Ground	0.15 - Honeypots Classroom 2	15	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	67 m2
2085201	Ground	0.15 - Honeypots Classroom 2	15	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 m2
2044589	Ground	0.15 - Honeypots Classroom 2	15	Yes	Window Sill		No Action	0 No Risk	4 No.
2410555	Ground	0.15 - Honeypots Classroom 2	15	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	67 m2
2044594	Ground	0.15 - Honeypots Classroom 2	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2410559	Ground	0.16 - Staff Toilet	16	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	4 m2
2410560	Ground	0.16 - Staff Toilet	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	4 m2
2044595	Ground	0.16 - Staff Toilet	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2085586	Ground	0.17 - Childrens Toilet	17	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	12 m2
2410557	Ground	0.18 - Honeypots Classroom 1	18	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	6 m2
2044588	Ground	0.18 - Honeypots Classroom 1	18	Yes	Window Sill		No Action	0 No Risk	1 No.
2410558	Ground	0.18 - Honeypots Classroom 1	18	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	45 m2
2044596	Ground	0.18 - Honeypots Classroom 1	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2085199	Ground	0.18 - Honeypots Classroom 1	18	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 m2
2044587	Ground	0.19 - Baby Sleep Area	19	Yes	Floor Covering	No Asbestos Detected	No Action	0 No Risk	4 m2
2085589	Ground	0.19 - Baby Sleep Area	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2044591	Ground	0.19 - Baby Sleep Area	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	4 m2
2085249	Ground	0.20 - External Store	20	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2

2044583	Ground	0.21 - Calorifier Room	21	Yes	Flange	Chrysotile	Monitor	7		6 No.
2044582	Ground	0.21 - Calorifier Room	21	Yes	Ceiling	Chrysotile	Monitor	7		16 m2
2340150	Ground	0.21 - Calorifier Room	21	Yes	Electrics (Flash Guards)	Presumed Asbestos Content	Monitor	6		1 No.
2335038	Ground	0.21 - Calorifier Room	21	Yes	Floor (Debris)		No Action	0	No Risk	16 m2
2334598	Ground	0.22 - Managers Office	22	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2085165	Ground	Calorifier Room	22	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0	No Risk	1 No.
2334597	Ground	0.22 - Managers Office	22	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	12 m2
2334599	Ground	0.23 - Londis Shop Store	23	Yes		No Sample Required	No Action	0	No Risk	0 N/A
2044593	Ground	0.24 - Above Suspended Ceiling	24	Yes	Lining	No Asbestos Detected	No Action	0	No Risk	0 N/A
2085594	Roof	Roof	25	Yes			No Action	0	No Risk	0 N/A
2085592	External	External	26	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - OFFICERS GARAGES - 755839 - WEET01WEE007										
2084541	Ground	Garage	1	Yes			No Action	0	No Risk	0 N/A
2084550	Ground	Garage	2	Yes			No Action	0	No Risk	0 N/A
2084551	Ground	Garage	3	Yes			No Action	0	No Risk	0 N/A
2084554	Ground	Garage	4	Yes			No Action	0	No Risk	0 N/A
2084556	Ground	Garage	5	Yes			No Action	0	No Risk	0 N/A
2084561	Ground	Garage	6	Yes			No Action	0	No Risk	0 N/A
2084567	Ground	Garage	7	Yes			No Action	0	No Risk	0 N/A
2084569	Ground	Garage	8	Yes			No Action	0	No Risk	0 N/A
2084571	Ground	Garage	9	Yes			No Action	0	No Risk	0 N/A
2084573	Ground	Garage	10	Yes			No Action	0	No Risk	0 N/A
2084577	Ground	Garage	11	Yes			No Action	0	No Risk	0 N/A
2084579	Ground	Garage	12	Yes			No Action	0	No Risk	0 N/A
2084582	Ground	Garage	13	Yes			No Action	0	No Risk	0 N/A
2084586	Ground	Garage	14	Yes			No Action	0	No Risk	0 N/A
2084589	Ground	Garage	15	Yes			No Action	0	No Risk	0 N/A
2084591	Ground	Garage	16	Yes			No Action	0	No Risk	0 N/A

2084594	Ground	Garage	17	Yes		No Action	0 No Risk	0 N/A
2084598	Ground	Garage	18	Yes		No Action	0 No Risk	0 N/A
2084601	Ground	Garage	19	Yes		No Action	0 No Risk	0 N/A
2084604	Roof	Roof	20	Yes		No Action	0 No Risk	0 N/A
2084608	External	Externals	21	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - OFFICERS MESS (SLA-Permanent) - 755853 - WEET01WEE005								
2337175	Ground	Entrance Hall Lobby (External)	1	Yes	Roof	No Asbestos Detected	No Action	0 No Risk 9 m2
2206828	Ground	Entrance	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2206678	Ground	Entrance	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 0 N/A
2206663	Ground	Bar	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337176	Ground	G01 Entrance Hall	2	Yes	Upper Wall	No Asbestos Detected	No Action	0 No Risk 60 m2
2206662	Ground	Bar	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337177	Ground	G01 Entrance Hall	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 60 m2
2337180	Ground	Corridor 1	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 25 m2
2337178	Ground	Corridor 1	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 25 m2
2206467	Ground	Beer Liquor Store	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337179	Ground	Corridor 1	3	Yes	Wall	No Asbestos Detected	No Action	0 No Risk 4 m2
2337182	Ground	G06 Meeting Room	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 15 m2
2337181	Ground	G06 Meeting Room	4	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk 4 m2
2206458	Ground	General Store	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337183	Ground	G06 Meeting Room	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 15 m2
2337186	Ground	G09 TV Room	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 25 m2
2337184	Ground	G09 TV Room	5	Yes	Window Sill (x2)	No Action	No Action	0 No Risk 1 m2
2206451	Ground	Corridor	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2337185	Ground	G09 TV Room	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 25 m2
2337188	Ground	G12 Mess Office	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 7 m2
2337187	Ground	G12 Mess Office	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 7 m2
2337190	Ground	G12 Mess Office	6	Yes		No Action	No Action	0 No Risk 1 No.
2207010	Ground	Electric Cupboard	6	Yes		No Sample Required	No Action	0 No Risk 0 N/A

2206949	Ground	G12 Mess Office	6	Yes	Safe	Presumed Asbestos Content	Monitor	10 Medium	1 No.
2337189	Ground	G12 Mess Office	6	Yes	Window Sill		No Action	0 No Risk	1 m2
2206493	Ground	Staff Quarters	7	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337192	Ground	G11 PMC	7	Yes	Window Sill		No Action	0 No Risk	1 m2
2206250	Ground	G46 Staff Quarters	7	Yes	Window Sill		No Action	0 No Risk	2 m2
2206502	Ground	Staff Quarters	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206476	Ground	Staff Quarters	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337191	Ground	G11 PMC	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337193	Ground	G11 PMC	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206501	Ground	Staff Quarters	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337194	Ground	G14 Cleaners Store	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2206605	Ground	Cleaners Cupboard	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337195	Ground	G14 Cleaners Store	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2206612	Ground	Female Rest Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206615	Ground	Female Rest Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206613	Ground	Female Rest Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206246	Ground	G44 Female Rest Room / Toilet	9	Yes	Window Sill		No Action	0 No Risk	1 m2
2337197	Ground	G15 Laundry R & D	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2337196	Ground	G15 Laundry R & D	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2337199	Ground	G31 Lockers	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	9 m2
2206234	Ground	G43 Silver Store	10	Yes	Window Sill		No Action	0 No Risk	1 m2
2206635	Ground	Silver Store	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337198	Ground	G31 Lockers	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	9 m2
2206642	Ground	Silver Store	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206618	Ground	Locker Room	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206943	Ground	G30 Laundry and Drying Room	11	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	2 No.
2337201	Ground	G30 Laundry and Drying Room	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	9 m2
2206257	Ground	G42 Locker Room	11	Yes	Window Sill		No Action	0 No Risk	1 m2
2337200	Ground	G30 Laundry and Drying Room	11	Yes	Window Sill		No Action	0 No Risk	1 m2

2337202	Ground	G30 Laundry and Drying Room	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	9 m2
2206628	Ground	Male Rest Room	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337203	Ground	G19 Store	12	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337204	Ground	G19 Store	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2337207	Ground	G13 Corridor 2	13	Yes	Wall (Lining)	No Asbestos Detected	No Action	0 No Risk	15 m2
2337206	Ground	G13 Corridor 2	13	Yes	Internal Fire Doors	No Asbestos Detected	No Action	0 No Risk	2 m2
2207015	Ground	G47 Lobby	13	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337205	Ground	G13 Corridor 2	13	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2337208	Ground	G13 Corridor 2	13	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2206222	Ground	G47A Kitchen Office	14	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337209	Ground	G16 Corridor 3	14	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	18 m2
2206447	Ground	G47A Kitchen Office	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337210	Ground	G16 Corridor 3	14	Yes	Wall (Lining)	No Asbestos Detected	No Action	0 No Risk	18 m2
2206438	Ground	Kitchen	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206441	Ground	Kitchen	15	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337212	Ground	G32 Corridor 4	15	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2337211	Ground	G32 Corridor 4	15	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337214	Ground	G03A Bar and Lounge	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2207018	Ground	Kitchen Store	16	Yes			No Action	0 No Risk	0 N/A
2337215	Ground	G03A Bar and Lounge	16	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	2 m2
2337213	Ground	G03A Bar and Lounge	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2337216	Ground	G03 Ante Room and Dining Room	17	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	100 m2
2337217	Ground	G03 Ante Room and Dining Room	17	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	100 m2
2207023	Ground	G54E Utensil Store	17	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337220	Ground	G54 Still Room / Servery	18	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	15 m2
2206935	Ground	G54 Still Room / Servery	18	Yes	Work Tops	Chrysotile Trace	Monitor	7 [REDACTED]	4 m2
2337219	Ground	G54 Still Room / Servery	18	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337218	Ground	G54 Still Room / Servery	18	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2337221	Ground	G54B Silver Plate	19	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2

2337222	Ground	G54B Silver Plate	19	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	6 m2
2337225	Ground	G53A Kitchen	20	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	35 m2
2337223	Ground	G53A Kitchen	20	Yes	Upper Level Walls	No Asbestos Detected	No Action	0 No Risk	35 m2
2337224	Ground	G53A Kitchen	20	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	35 m2
2207030	Ground	Silver Plate Room	20	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2206217	Ground	G53A Kitchen	20	Yes	Sink	Chrysotile	Monitor	7 [REDACTED]	1 No.
2337227	Ground	G54D Crockery and Utensil Wash	21	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	18 m2
2206657	Ground	Dining Room	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206651	Ground	Dining Room	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206925	Ground	G54D Crockery and Utensil Wash	21	Yes	Work Tops	Chrysotile Trace	Monitor	7 [REDACTED]	6 m2
2337226	Ground	G54D Crockery and Utensil Wash	21	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	18 m2
2337229	Ground	G52 Kitchen Lobby Entrance	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2337228	Ground	G52 Kitchen Lobby Entrance	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2206300	Ground	G07 Female Rest Room / Toilet	22	Yes	Window Sill		No Action	0 No Risk	1 m2
2206847	Ground	Female Rest Room / Toilet	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337230	Ground	G47 Kitchen Office Lobby	23	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2207035	Ground	Electric Cupboard	23	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337231	Ground	G47 Kitchen Office Lobby	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2206860	Ground	Male Rest Room / Toilet	24	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337232	Ground	G47A Kitchen Office	24	Yes	Window Sill		No Action	0 No Risk	1 m2
2206268	Ground	G10 Male Rest Room / Toilet	24	Yes	Window Sill		No Action	0 No Risk	1 m2
2337234	Ground	G47A Kitchen Office	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2337233	Ground	G47A Kitchen Office	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	5 m2
2337236	Ground	G50A Bar Servery	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2206311	Ground	G11 PMC	25	Yes	Window Sill		No Action	0 No Risk	1 m2
2337235	Ground	G50A Bar Servery	25	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	4 m2
2206471	Ground	G50A Bar Servery	25	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2207037	Ground	G16 / G32 Corridor	26	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2206350	Ground	G50 Cellar / Store	26	Yes	Sink	Chrysotile	Monitor	6 [REDACTED]	1 No.

2337237	Ground	G50 Cellar / Store	26	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337238	Ground	G50 Cellar / Store	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2337239	Ground	G49 Liquor Store Lobby	27	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2337240	Ground	G49 Liquor Store Lobby	27	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	1 m2
2206507	Ground	G31 Locker / Changing Room	27	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2207041	Ground	G33 Male Toilet	28	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337241	Ground	G40 Kitchen Staff Corridor	28	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	15 m2
2337242	Ground	G40 Kitchen Staff Corridor	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2337245	Ground	G42 Lockers	29	Yes	Window Sill		No Action	0 No Risk	1 m2
2337244	Ground	G42 Lockers	29	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	6 m2
2206314	Ground	G34 Bedroom	29	Yes	Window Sill		No Action	0 No Risk	2 m2
2337243	Ground	G42 Lockers	29	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337246	Ground	G41 Gents WC Lobby	30	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	1 m2
2206317	Ground	G35 Bedroom	30	Yes	Window Sill		No Action	0 No Risk	2 m2
2337248	Ground	G41 Gents WC Lobby	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2337247	Ground	G41 Gents WC Lobby	30	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2337250	Ground	G41A Gents WC	31	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2206513	Ground	G30 Laundry Cleaning / Ironing	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335040	Ground	G30 Laundry Cleaning / Ironing	31	Yes	Sill		No Action	0 No Risk	1 m2
2337251	Ground	G41A Gents WC	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337249	Ground	G41A Gents WC	31	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337252	Ground	G41A Gents WC	31	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2206518	Ground	Bedroom	32	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337254	Ground	G44A Rest Room	32	Yes	Window Sill		No Action	0 No Risk	1 m2
2337255	Ground	G44A Rest Room	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	6 m2
2206345	Ground	G17 Bedroom	32	Yes	Window Sill		No Action	0 No Risk	2 m2
2337253	Ground	G44A Rest Room	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337256	Ground	G44 Rest Room Lobby	33	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	2 m2
2206520	Ground	Bedroom	33	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A

2337258	Ground	G44 Rest Room Lobby	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337257	Ground	G44 Rest Room Lobby	33	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2206338	Ground	G20 Bedroom	33	Yes	Window Sill		No Action	0 No Risk	2 m2
2337260	Ground	G44B Ladies WC	34	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337261	Ground	G44B Ladies WC	34	Yes	Window Sill		No Action	0 No Risk	1 m2
2206334	Ground	G21 Bedroom	34	Yes	Window Sill		No Action	0 No Risk	2 m2
2206528	Ground	Bedroom	34	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337262	Ground	G44B Ladies WC	34	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337259	Ground	G44B Ladies WC	34	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2206321	Ground	F10 Bedroom	35	Yes	Window Sill		No Action	0 No Risk	2 m2
2337264	Ground	G45 Cleaners Store	35	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2337263	Ground	G45 Cleaners Store	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337266	Ground	G46 Staff Quarters Lobby	36	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337265	Ground	G46 Staff Quarters Lobby	36	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	3 m2
2206319	Ground	G25 Bedroom	36	Yes	Window Sill		No Action	0 No Risk	2 m2
2337268	Ground	G46B Bathroom	37	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2206339	Ground	G26 Bedroom	37	Yes	Window Sill		No Action	0 No Risk	2 m2
2337267	Ground	G46B Bathroom	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2337270	Ground	G46B Bathroom	37	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337269	Ground	G46B Bathroom	37	Yes	Window Sill		No Action	0 No Risk	1 m2
2206326	Ground	G23 Bedroom	38	Yes	Window Sill		No Action	0 No Risk	2 m2
2337272	Ground	G46C Toilet	38	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2206530	Ground	Bedroom	38	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337273	Ground	G46C Toilet	38	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337271	Ground	G46C Toilet	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337274	Ground	G46C Toilet	38	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337277	Ground	G26 Bedroom	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337276	Ground	G26 Bedroom	39	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206329	Ground	G22 Bedroom	39	Yes	Window Sill		No Action	0 No Risk	2 m2

2337275	Ground	G26 Bedroom	39	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337281	Ground	G25 Bedroom	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337278	Ground	G25 Bedroom	40	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337280	Ground	G25 Bedroom	40	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337279	Ground	G25 Bedroom	40	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337282	Ground	G24 Bedroom	41	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337285	Ground	G24 Bedroom	41	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2207054	Ground	G18 Toilets	41	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337284	Ground	G24 Bedroom	41	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337283	Ground	G25 Bedroom	41	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206312	Ground	Laundry	42	Yes	Window Sill	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2337287	Ground	G23 Bedroom	42	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206892	Ground	Laundry Room	42	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337286	Ground	G23 Bedroom	42	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337289	Ground	G23 Bedroom	42	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337288	Ground	G23 Bedroom	42	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2206885	Ground	Cleaners Cupboard	43	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337291	Ground	G20 Bedroom	43	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337292	Ground	G20 Bedroom	43	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337293	Ground	G20 Bedroom	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2337290	Ground	G20 Bedroom	43	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337295	Ground	G22 Bedroom	44	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337294	Ground	G22 Bedroom	44	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2206307	Ground	G12 Mess Office	44	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337296	Ground	G22 Bedroom	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337299	Ground	G21 Bedroom	45	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337297	Ground	G21 Bedroom	45	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2206853	Ground	TV Room	45	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337300	Ground	G21 Bedroom	45	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2

2337298	Ground	G21 Bedroom	45	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2206303	Ground	G09 TV Room	45	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 m2
2206535	Ground	TV Room	45	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337304	Ground	G17 Bedroom	46	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2206840	Ground	Female Toilet	46	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337301	Ground	G17 Bedroom	46	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337303	Ground	G17 Bedroom	46	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337302	Ground	G17 Bedroom	46	Yes	Window Sill (x2)	No Asbestos Detected	No Action	0 No Risk	1 m2
2206545	Ground	Stairwell To First / Landing	47	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206542	Ground	Stairwell To First / Landing	47	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337305	Ground	G34 Sitting Room	47	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337306	Ground	G34 Sitting Room	47	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337308	Ground	G34 Bedroom	47	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337307	Ground	G34 Sitting Room	47	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337310	Ground	G34A Bedroom	48	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206554	First	Corridor	48	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337311	Ground	G34A Bedroom	48	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337309	Ground	G48A Bedroom	48	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2206380	First	F23 Bedroom	49	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 m2
2337314	Ground	G35 Sitting Room	49	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337313	Ground	G35 Sitting Room	49	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337312	Ground	G35 Sitting Room	49	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337315	Ground	G35 Sitting Room	49	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337318	Ground	G35A Bedroom	50	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206367	First	F06 Bedroom	50	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 m2
2337316	Ground	G35A Bedroom	50	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2337317	Ground	G35A Bedroom	50	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206366	First	F07 Bedroom	51	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	2 m2
2337320	First	1/22 Sitting Room	51	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2

2337319	First	1/22 Sitting Room	51	Yes	Window Sill		No Action	0 No Risk	1 m2
2337321	First	1/22 Sitting Room	51	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337322	First	1/22A Bedroom	52	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337323	First	1/22A Bedroom	52	Yes	Window Sill		No Action	0 No Risk	1 m2
2206365	First	F01 Bedroom	52	Yes	Window Sill		No Action	0 No Risk	2 m2
2337324	First	1/22A Bedroom	52	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337327	First	1/21 Sitting Room	53	Yes	Window Sill		No Action	0 No Risk	1 m2
2206363	First	F11 Bedroom	53	Yes	Window Sill		No Action	0 No Risk	2 m2
2337326	First	1/21 Sitting Room	53	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337325	First	1/21 Sitting Room	53	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2207044	First	F12 Bedroom	54	Yes	Sill		No Action	0 No Risk	2 m2
2337329	First	1/21A Bedroom	54	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337328	First	1/21A Bedroom	54	Yes	Window Sill		No Action	0 No Risk	1 m2
2337330	First	1/21A Bedroom	54	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337333	First	1/19 Sitting Room	55	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337332	First	1/19 Sitting Room	55	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337331	First	1/19 Sitting Room	55	Yes	Window Sill		No Action	0 No Risk	1 m2
2207046	First	F09 Bedroom	55	Yes	Sill		No Action	0 No Risk	2 m2
2337336	First	1/19A Bedroom	56	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337334	First	1/19A Bedroom	56	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2207051	First	F08 Bedroom	56	Yes	Sill		No Action	0 No Risk	2 m2
2337335	First	1/19A Bedroom	56	Yes	Window Sill		No Action	0 No Risk	1 m2
2337338	First	1/3 Bedroom	57	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337337	First	1/3 Bedroom	57	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337339	First	1/3 Bedroom	57	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206591	First	Crockery Store	57	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337342	First	1/6 Bedroom	58	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206600	First	Bathroom	58	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337341	First	1/6 Bedroom	58	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2

2337340	First	1/6 Bedroom	58	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337343	First	1/8 Bedroom	59	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206570	First	Cleaners Cupboard	59	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337344	First	1/8 Bedroom	59	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337345	First	1/8 Bedroom	59	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206565	First	Drying Room	60	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337348	First	1/7 Bedroom	60	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337347	First	1/7 Bedroom	60	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337346	First	1/7 Bedroom	60	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2206420	First	F15 Drying Store	60	Yes	Window Sill		No Action	0 No Risk	1 m2
2206412	First	General Store	61	Yes	Window Sill		No Action	0 No Risk	1 m2
2337349	First	1/9 Bedroom	61	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2206560	First	General Store	61	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337350	First	1/9 Bedroom	61	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337351	First	1/9 Bedroom	61	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337354	First	1/10 Bedroom	62	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206404	First	F17 Baggage Store	62	Yes	Window Sill		No Action	0 No Risk	1 m2
2206558	First	Baggage Store	62	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337353	First	1/10 Bedroom	62	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337352	First	1/10 Bedroom	62	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337355	First	1/11 Bedroom	63	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2207056	First	Electric Cupboard	63	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337357	First	1/11 Bedroom	63	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337356	First	1/11 Bedroom	63	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337359	First	1/12 Bedroom	64	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2206577	First	Bathroom / Toilet	64	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337360	First	1/12 Bedroom	64	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337358	First	1/12 Bedroom	64	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337363	Ground	G46D Bedroom	65	Yes	Window Sill		No Action	0 No Risk	1 m2

2337362	Ground	G46D Bedroom	65	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2206400	First	F21 Bedroom	65	Yes	Window Sill		No Action	0 No Risk	2 m2
2337361	Ground	G46D Bedroom	65	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337364	Ground	G46A Bedroom	66	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337366	Ground	G46A Bedroom	66	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2206585	First	Bedroom	66	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2206399	First	F22 Bedroom	66	Yes	Window Sill		No Action	0 No Risk	2 m2
2337365	Ground	G46A Bedroom	66	Yes	Window Sill		No Action	0 No Risk	1 m2
2337368	Ground	Silver Store	67	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2206382	First	F08 Bedroom	67	Yes	Window Sill		No Action	0 No Risk	2 m2
2337367	Ground	Silver Store	67	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2206193	Ground	Calorifier Room	68	Yes	Pipework	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2206970	Ground	Calorifier Room	68	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2337370	Ground	G51 General Store	68	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	5 m2
2337369	Ground	G51 General Store	68	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2206961	Ground	Calorifier Room	69	Yes	Gasket	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2202827	Ground	Calorifier Room	69	Yes	Pump	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2337372	Ground	G07 Powder Room	69	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2206900	Ground	Calorifier Room	69	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337371	Ground	G07 Powder Room	69	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	8 m2
2337374	Ground	G07A Ladies WC	70	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2337373	Ground	G07A Ladies WC	70	Yes	Window Sill		No Action	0 No Risk	1 m2
2337376	Ground	G07A Ladies WC	70	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337375	Ground	G07A Ladies WC	70	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	5 m2
2337378	Ground	G10 Male Cloaks	71	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337379	Ground	G10 Male Cloaks	71	Yes	Window Sill (x2)		No Action	0 No Risk	1 m2
2337380	Ground	G10 Male Cloaks	71	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	2 m2
2337377	Ground	G10 Male Cloaks	71	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2337382	Ground	G10A Gents WC	72	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2

2337381	Ground	G10A Gents WC	72	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	10 m2
2337384	Ground	G33 Bathroom & Toilets	73	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337383	Ground	G33 Bathroom & Toilets	73	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	8 m2
2337386	Ground	G18 Bathroom & Toilets	74	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337387	Ground	G18 Bathroom & Toilets	74	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337385	Ground	G18 Bathroom & Toilets	74	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	12 m2
2337388	First	1/1 Lobby	75	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2337390	First	1/1 Lobby	75	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337389	First	1/1 Lobby	75	Yes	Fire Doors (Seal)	No Asbestos Detected	No Action	0 No Risk	2 m2
2206176	External	External	75	Yes	Floor		Asbestos Removed	0 No Risk	15 m2
2337392	First	1/14 Cleaners Store	76	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2206874	Roof Void	Roof Void	76	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337391	First	1/14 Cleaners Store	76	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337393	First	1/15 Drying Room	77	Yes	Window Sill		No Action	0 No Risk	1 m2
2337395	First	1/15 Drying Room	77	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	6 m2
2337394	First	1/15 Drying Room	77	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337397	First	1/16 General Store	78	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2337396	First	1/16 General Store	78	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2337399	First	1/17 Baggage Store	79	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337398	First	1/17 Baggage Store	79	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2337400	First	1/17 Baggage Store	79	Yes	Window Sill		No Action	0 No Risk	1 m2
2337402	First	1/5 Baggage Store	80	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2337401	First	1/5 Baggage Store	80	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337404	First	1/2 Corridor	81	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	18 m2
2337405	First	1/2 Corridor	81	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	18 m2
2337403	First	1/2 Corridor	81	Yes	Above Doorway	No Asbestos Detected	No Action	0 No Risk	1 m2
2337406	Loft	Loft Space - 1/2 Corridor	82	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337409	First	1/4 Bathroom & Toilets	83	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	3 m2
2337408	First	1/4 Bathroom & Toilets	83	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2

2337407	First	1/4 Bathroom & Toilets	83	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	12 m2
2337410	First	1/18 Corridor	84	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2337411	First	1/18 Corridor	84	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2337412	Loft	Loft Space - 1/18 Corridor	85	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337413	First	1/18.1 Electrical Cupboard	86	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337416	First	1/20 Bathroom & Toilets	87	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2337414	First	1/20 Bathroom & Toilets	87	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	8 m2
2337415	First	1/20 Bathroom & Toilets	87	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2337417	Ground / First	G28 Stairwell	88	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2206549	Ground / First	G28 Stairwell	88	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337418	Loft	Loft Space - 1/1 Lobby	89	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337419	Ground	G57 Plant Room	90	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2337420	Ground	G39 Plant Room	91	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	9 m2
2337421	Ground	G08 Electrical Cupboard	92	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2207063	Ground	G55 Refuse	93	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2207067	Ground	G56 Swill	94	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2207070	Ground	Yard	95	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2207073	Ground	Garden Store	96	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2206907	Roof	Roof	97	Yes	Fillets	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337422	External	External	98	Yes	Metal Window	No Asbestos Detected	No Action	0 No Risk	100 m2
2337423	All	Internal / External	99	Yes	Metal Sash	No Asbestos Detected	No Action	0 No Risk	100 m2
WEETON CAMP - OIL AND PAINT STORE - 755821 - WEET01WEE029									
2084916	Ground	Paint Store	1	Yes			No Action	0 No Risk	0 N/A
2084917	Ground	Oil Store	2	Yes			No Action	0 No Risk	0 N/A
2084918	Ground	Acetylene Full Store	3	Yes			No Action	0 No Risk	0 N/A
2084919	Ground	Acetylene Empty Store	4	Yes			No Action	0 No Risk	0 N/A
2084920	Ground	Oxygen Full Store	5	Yes			No Action	0 No Risk	0 N/A
2084921	Ground	Oxygen Empty Store	6	Yes			No Action	0 No Risk	0 N/A
2084951	Roof	Roof	7	Yes			No Action	0 No Risk	0 N/A

ID	Location	Room	Count	Yes	Material	Asbestos Detected	Action	Risk	Area
2044434	External	External	8	Yes	Wall	No Sample Required	No Action	0 No Risk	1 No.
WEETON CAMP - P & RTC - 755833 - WEET01WEE021									
2104947	Ground	Issues Room	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	40 m2
2104936	Ground	Main Corridor	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	35 m2
2044175	Ground	Main Corridor	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044204	Ground	Male Changing Room	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	30 m2
2044178	Ground	Male Toilets	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044179	Ground	Male Changing Room	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2341450	Ground	Male Showers	6	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044207	Ground	Electrics Cupboard	7	Yes			No Action	0 No Risk	0 N/A
2044206	Ground	Female Changing Room	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2044182	Ground	Female Toilets	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044205	Ground	Female Showers / Toilets	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2044195	Ground	Corridor	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2044171	Ground	Cleaners Cupboard	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044193	Ground	Squash Court 1	12	Yes			No Action	0 No Risk	0 N/A
2044211	Ground	Squash Court	13	Yes			No Action	0 No Risk	0 N/A
2044197	Ground	Gym	14	Yes			No Action	0 No Risk	0 N/A
2044196	Ground	Store	15	Yes	Walls	No Sample Required	No Action	0 No Risk	15 m2
2044199	Ground	Main Store	16	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044200	Ground	Instructors Office	17	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	30 m2
2044174	Ground	APTL Instructors Office	18	Yes	Ceiling	Chrysotile	Monitor	7	8 m2
2044173	Ground	APTL Instructors Office	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2104916	First	Stairwell	19	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	8 m2
2044186	First	Stairwell	19	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044185	First	Stairwell	19	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044194	First	Weights Room F1	20	Yes			No Action	0 No Risk	0 N/A
2044209	First	Viewing Gallery	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	15 m2
2044208	First	Tank Room	22	Yes			No Action	0 No Risk	0 N/A

2044192	Ground	Calorifier Room	23	Yes	Gasket	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044190	Ground	Calorifier Room	23	Yes	Gasket	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044210	Ground	Calorifier Room	23	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2044191	Ground	Calorifier Room	23	Yes	Gasket	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2044189	Ground	Calorifier Room	23	Yes			No Action	0 No Risk	0 N/A
2086917	Roof	Roof	24	Yes	Roof (Coating)	No Asbestos Detected	No Action	0 No Risk	200 m2
2044212	External	External	25	Yes			No Action	0 No Risk	0 N/A
2044183	Roof Void	Roof Void	26	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - POL STORE - 754014 - WEET02WEE0N2									
2044854	Ground	Unknown	1	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - QM OFFICE COMPLEX - 755835 - WEET01WEE024									
2044297	Ground	Entrance Corridor - G/01	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044306	Ground	QM Tech - G/02	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044309	Ground	QM Tech - G/02	2	Yes	Sill		Asbestos Removed	0 No Risk	1 m2
2044301	Ground	Electric Cupboard	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044305	Ground	Cleaners Cupboard - G/03	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044298	Ground	Regimental AFG 1098 Store - G/04	5	Yes			No Action	0 No Risk	0 N/A
2044328	Ground	Tech Sergeant And Clerk - G/05	6	Yes			No Action	0 No Risk	0 N/A
2044329	Ground	Unserviceable Store - G/07A	7	Yes			No Action	0 No Risk	0 N/A
2044312	Ground	Store - G/10A	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044324	Ground	Male Toilet - G/06	9	Yes	Window Sill	Chrysotile	Monitor	7	2 No.
2044307	Ground	TQMS - G/08	10	Yes	Window Sill	Chrysotile	Monitor	8	1 m2
2044308	Ground	Clerks - G/09	11	Yes	Window Sill	Chrysotile	Monitor	8	1 m2
2044323	Ground	Electric Cupboard	12	Yes			No Action	0 No Risk	0 N/A
2044330	Ground	Quartermasters - G/11	13	Yes	Window Sill	Chrysotile	Monitor	8	1 m2
2044322	Ground	Furniture Store - G/12	14	Yes			No Action	0 No Risk	0 N/A
2044325	Ground	Workshop - G12A	15	Yes	Window Sill	Chrysotile	Monitor	8	1 No.
2044310	Ground	G14/G11 Offices & Regimental Quartermaster - G/	16	Yes	Window Sill	Chrysotile	Monitor	8	1 m2

Run Date:
16/01/2017 03:43:47

Page:
86 of 113

Run By:
CD\svc_ProRepuSer

2044331	Ground	Office - G/14	17	Yes	Window Sill	Chrysotile	Monitor	8		1 m2
2044332	Ground	Reception - G/15	18	Yes			No Action	0	No Risk	0 N/A
2044320	Ground	Unserviceable Store - G/22A	19	Yes			No Action	0	No Risk	0 N/A
2044299	Ground	Exchange Clothing Store	20	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044292	Ground	Kitchen - G/25	21	Yes	Sink and Drainer		No Action	0	No Risk	2 No.
2044290	Ground	Conference Room	22	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044296	Ground	Male Toilet - G/24	23	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044326	Ground	Male Toilet - G/24	23	Yes	Window Sill	Chrysotile	Monitor	6		1 No.
2044327	Ground	Female Toilet - G/23	24	Yes	Window Sill	Chrysotile	Monitor	6		1 No.
2044295	Ground	Female Toilet - G/23	24	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044293	Ground	Corridor - G/22	25	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044294	Ground	Corridor - G/22	25	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044333	Ground	Tailors Shop - G/21	26	Yes			No Action	0	No Risk	0 N/A
2044334	Ground	Equipment Repair Shop - G/20	27	Yes			No Action	0	No Risk	0 N/A
2044335	Ground	Bricklayers Shop - G/19	28	Yes			No Action	0	No Risk	0 N/A
2044336	Ground	Carpenters Shop	29	Yes			No Action	0	No Risk	0 N/A
2044337	Ground	Signatures Shop	30	Yes			No Action	0	No Risk	0 N/A
2044314	Ground	Calorifier Room - G/33	31	Yes	Gaskets	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044304	Roof	Roof	32	Yes	Roof	No Asbestos Detected	No Action	0	No Risk	0 N/A
2044343	External	External	33	Yes			No Action	0	No Risk	0 N/A
2044291	Roof Void	Roof Void	34	Yes	Roof	No Asbestos Detected	No Action	0	No Risk	0 N/A
WEETON CAMP - RADIAC STORE - 755811 - WEET01WEE036										
2044565	Ground	External Radiac Store	1	Yes	Wall	No Sample Required	No Action	0	No Risk	1 No.
2085148	Roof	Roof	2	Yes			No Action	0	No Risk	0 N/A
2044566	External	External	3	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - RECEPTION CENTRE - 755851 - WEET01WEE001										
2042315	Ground	Entrance Hall	1	Yes			No Action	0	No Risk	0 N/A
2042293	Ground	Entrance Hall	1	Yes	Walls	No Asbestos Detected	No Action	0	No Risk	0 N/A
2042304	Ground	Reception	2	Yes	Window Sill	Chrysotile	Monitor	7		4 No.

2042294	Ground	Reception	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042311	Ground	Interview Room 1	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042301	Ground	Interview Room 1	3	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2042322	Ground	Interview Room 1	3	Yes			No Action	0 No Risk	0 N/A
2042309	Ground	Interview Room 2	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042306	Ground	Interview Room 2	4	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 No.
2042323	Ground	Interview Room 2	4	Yes			No Action	0 No Risk	0 N/A
2042305	Ground	Post Room	5	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2042321	Ground	Post Room	5	Yes			No Action	0 No Risk	0 N/A
2042302	Ground	Female Toilets	6	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2042312	Ground	Female Toilets	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042320	Ground	Female Toilets	6	Yes			No Action	0 No Risk	0 N/A
2042303	Ground	Male Toilets	7	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	2 No.
2042308	Ground	Male Toilets	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042319	Ground	Male Toilets	7	Yes			No Action	0 No Risk	0 N/A
2042299	Ground	Corridor	8	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2042298	Ground	Corridor	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042307	Ground	Corridor	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042318	Ground	Corridor	8	Yes			No Action	0 No Risk	0 N/A
2042295	Ground	Tea Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042296	Ground	Tea Room	9	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2042297	Ground	Tea Room	9	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	1 No.
2042317	Ground	Tea Room	9	Yes			No Action	0 No Risk	0 N/A
2042300	Ground	Waiting Room	10	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 No.
2042316	Ground	Waiting Room	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2084724	Ground	Plant Room	11	Yes			No Action	0 No Risk	0 N/A
2042310	Ground	Roof Void	12	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042325	Roof	Roof	13	Yes			No Action	0 No Risk	0 N/A
2042313	External	External	14	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A

2042314	Ground	Calorifier Room	15	Yes		No Action	0 No Risk	0 N/A
2042324	Ground	Calorifier Room	15	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - REFUSE SHELTER - 755840 - WEET01WE008B								
2084537	Ground	Refuse Store	1	Yes		No Action	0 No Risk	0 N/A
2084539	Roof	Roof	2	Yes		No Action	0 No Risk	0 N/A
2084540	External	External	3	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - REFUSE SHELTER - 755841 - WEET01WE008C								
2084491	Ground	Refuse Shelter	1	Yes		No Action	0 No Risk	0 N/A
2084493	Roof	Roof	2	Yes		No Action	0 No Risk	0 N/A
2084494	External	External	3	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - REFUSE SHELTER - 755842 - WEET01WE008D								
2084470	Ground	Refuse Shelter	1	Yes		No Action	0 No Risk	0 N/A
2084471	Roof	Roof	2	Yes		No Action	0 No Risk	0 N/A
2084472	External	External	3	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - REFUSE SHELTER - 755856 - WEET01WE008A								
2084506	Ground	Refuse Shelter	1	Yes		No Action	0 No Risk	0 N/A
2084507	Roof	Roof	2	Yes		No Action	0 No Risk	0 N/A
2084509	External	External	3	Yes		No Action	0 No Risk	0 N/A
WEETON CAMP - SERGEANTS MESS (SLA-Permanent) - 755854 - WEET01WEE006								
2042686	Ground	Entrance - G01	1	Yes		No Action	0 No Risk	0 N/A
2337848	Ground	Bedroom G26	1	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 10 m2
2337849	Ground	Bedroom G26	1	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 10 m2
2337850	Ground	Bedroom G26	1	Yes	Window Sill		No Action	0 No Risk 1 No.
2337853	Ground	Bedroom G27	2	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk 10 m2
2337852	Ground	Bedroom G27	2	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk 10 m2
2337851	Ground	Bedroom G27	2	Yes	Window Sill		No Action	0 No Risk 1 No.
2042536	Ground	TV Room - G14	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2042535	Ground	TV Room - G14	2	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk 0 N/A

2337854	Ground	Bedroom G25	3	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042554	Ground	Toilets G17	3	Yes	Window Sill		No Action	0 No Risk	1 m2
2042565	Ground	Toilets G17	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337855	Ground	Bedroom G25	3	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337856	Ground	Bedroom G25	3	Yes	Window Sill		No Action	0 No Risk	1 No.
2042566	Ground	Toilets G17	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337859	Ground	Bedroom G24	4	Yes	Window Sill		No Action	0 No Risk	1 No.
2337858	Ground	Bedroom G24	4	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042571	Ground	Cleaners Cupboard G19	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337857	Ground	Bedroom G24	4	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042541	Ground	Cleaners Cupboard G19	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042556	Ground	Cleaners Cupboard G19	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337862	Ground	Bedroom G23	5	Yes	Window Sill		No Action	0 No Risk	1 No.
2337860	Ground	Bedroom G23	5	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042542	Ground	G20B Bathroom	5	Yes	Sill		No Action	0 No Risk	1 m2
2337861	Ground	Bedroom G23	5	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337864	Ground	Bedroom G22	6	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042545	Ground	Bedroom G 23	6	Yes	Window Sill		No Action	0 No Risk	1 m2
2337863	Ground	Bedroom G22	6	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337865	Ground	Bedroom G22	6	Yes	Window Sill		No Action	0 No Risk	1 No.
2337868	First	Bedroom F17	7	Yes	Window Sill		No Action	0 No Risk	1 No.
2337866	First	Bedroom F17	7	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042547	Ground	Bedroom G 24	7	Yes	Window Sill		No Action	0 No Risk	1 m2
2337867	First	Bedroom F17	7	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042555	Ground	Bedroom G 27	8	Yes	Window Sill		No Action	0 No Risk	1 m2
2337869	First	Bedroom F18	8	Yes	Window Sill		No Action	0 No Risk	1 No.
2337871	First	Bedroom F18	8	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337870	First	Bedroom F18	8	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337873	First	Bedroom F15	9	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2

2337872	First	Bedroom F15	9	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337874	First	Bedroom F15	9	Yes	Window Sill		No Action	0 No Risk	1 No.
2042552	Ground	Bedroom G 26	9	Yes	Window Sill		No Action	0 No Risk	1 m2
2337877	First	Bedroom F16	10	Yes	Window Sill		No Action	0 No Risk	1 No.
2337875	First	Bedroom F16	10	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337876	First	Bedroom F16	10	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042548	Ground	Bedroom G 25	10	Yes	Window Sill		No Action	0 No Risk	1 m2
2337880	First	Bedroom F14	11	Yes	Window Sill		No Action	0 No Risk	1 No.
2337879	First	Bedroom F14	11	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337878	First	Bedroom F14	11	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042546	Ground	Bedroom G 22	11	Yes	Window Sill		No Action	0 No Risk	1 m2
2337881	First	Bedroom F13	12	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042572	Ground	Baggage Store	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337882	First	Bedroom F13	12	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042576	Ground	Baggage Store	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337883	First	Bedroom F13	12	Yes	Window Sill		No Action	0 No Risk	1 No.
2337886	First	Bedroom F12	13	Yes	Window Sill		No Action	0 No Risk	1 No.
2042570	Ground	Drying Room	13	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042544	Ground	G18 Drying Room	13	Yes	Window Sill		No Action	0 No Risk	1 m2
2337885	First	Bedroom F12	13	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337884	First	Bedroom F12	13	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042569	Ground	Drying Room	13	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042543	Ground	G16 Laundry	14	Yes	Window Sill		No Action	0 No Risk	1 m2
2337888	First	Bedroom F11	14	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337887	First	Bedroom F11	14	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337889	First	Bedroom F11	14	Yes	Window Sill		No Action	0 No Risk	1 No.
2042567	Ground	Laundry & Drying Room	14	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337892	First	Bedroom F08	15	Yes	Window Sill		No Action	0 No Risk	1 No.
2042564	Ground	Billiard room	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

2337891	First	Bedroom F08	15	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042563	Ground	Billiard room	15	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337890	First	Bedroom F08	15	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337893	First	Bedroom F07	16	Yes	Window Sill		No Action	0 No Risk	1 No.
2042523	Ground	Ante Room	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337894	First	Bedroom F07	16	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042524	Ground	Ante Room	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337895	First	Bedroom F07	16	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337898	First	Bedroom F03	17	Yes	Window Sill		No Action	0 No Risk	1 No.
2337897	First	Bedroom F03	17	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337896	First	Bedroom F03	17	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042506	Ground	Servery	18	Yes	Sill	Chrysotile	Asbestos Removed	0 No Risk	2 m2
2042517	Ground	Servery	18	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337900	First	Bedroom F36	18	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337899	First	Bedroom F36	18	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042522	Ground	Servery Cupboard	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337901	First	Bedroom F36	18	Yes	Window Sill		No Action	0 No Risk	1 No.
2042518	Ground	Servery	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042521	Ground	Servery Cupboard	18	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337904	First	Bedroom F35	19	Yes	Window Sill		No Action	0 No Risk	1 No.
2337903	First	Bedroom F35	19	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337902	First	Bedroom F35	19	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337905	First	Bedroom F33	20	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042508	Ground	G41A Kitchen Store	20	Yes	Window Sill		No Action	0 No Risk	1 No.
2337906	First	Bedroom F33	20	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337907	First	Bedroom F33	20	Yes	Window Sill		No Action	0 No Risk	1 No.
2337910	First	Bedroom F34	21	Yes	Window Sill		No Action	0 No Risk	1 No.
2337909	First	Bedroom F34	21	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042505	Ground	G41D Kitchen Office	21	Yes	Window Sill		No Action	0 No Risk	1 No.

2337908	First	Bedroom F34	21	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042519	Ground	Kitchen Office	21	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337911	First	Bedroom F31	22	Yes	Window Sill		No Action	0 No Risk	1 No.
2337912	First	Bedroom F31	22	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337913	First	Bedroom F31	22	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337916	First	Bedroom F32	23	Yes	Window Sill		No Action	0 No Risk	1 No.
2337915	First	Bedroom F32	23	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337914	First	Bedroom F32	23	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042527	Ground	Empty Room	23	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337917	First	Bedroom F29	24	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042528	Ground	Beer & Liquor Store	24	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337918	First	Bedroom F29	24	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337919	First	Bedroom F29	24	Yes	Window Sill		No Action	0 No Risk	1 No.
2042526	Ground	Beer & Liquor Store	24	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337922	First	Bedroom F30	25	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337921	First	Bedroom F30	25	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337920	First	Bedroom F30	25	Yes	Window Sill		No Action	0 No Risk	1 No.
2042534	Ground	Bar	25	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337923	First	Bedroom F30	25	Yes	Wall Above Window	No Asbestos Detected	No Action	0 No Risk	1 m2
2042530	Ground	Bar Serving Area	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042533	Ground	Bar	25	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337926	First	Bedroom F26	26	Yes	Window Sill		No Action	0 No Risk	1 No.
2337924	First	Bedroom F26	26	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042510	Ground	Corridor	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337925	First	Bedroom F26	26	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042500	Ground	Corridor	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337927	First	Bedroom F25	27	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337929	First	Bedroom F25	27	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337928	First	Bedroom F25	27	Yes	Window Sill		No Action	0 No Risk	1 No.

2042685	Ground	Electric Cupboard G 40A	27	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337931	First	Bedroom F24	28	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042516	Ground	Male Toilet (kitchen)	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337930	First	Bedroom F24	28	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337932	First	Bedroom F24	28	Yes	Window Sill		No Action	0 No Risk	1 No.
2042509	Ground	G46 Male Toilet	28	Yes	Window Sill		No Action	0 No Risk	1 m2
2337935	First	Bedroom F23	29	Yes	Window Sill		No Action	0 No Risk	1 No.
2337933	First	Bedroom F23	29	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2042515	Ground	Cleaners (kitchen)	29	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337934	First	Bedroom F23	29	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2337937	Ground	G02 Mess Office	30	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	7 m2
2337938	Ground	G02 Mess Office	30	Yes	Window Sill		No Action	0 No Risk	1 No.
2042507	Ground	G38 Female Rest Room	30	Yes	Window Sill		No Action	0 No Risk	1 m2
2042692	Ground	G02 Mess Office	30	Yes	Safe	Strongly Presumed Asbestos Content	Monitor	13 Medium	1 No.
2337936	Ground	G02 Mess Office	30	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	7 m2
2337939	Ground	G06 Families Room	31	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	3 m2
2337942	Ground	G06 Families Room	31	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2042512	Ground	Rest Room (Female) Entrance	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337941	Ground	G06 Families Room	31	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	30 m2
2042513	Ground	Female Rest Room	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337940	Ground	G06 Families Room	31	Yes	Window Sills		No Action	0 No Risk	2 No.
2337943	Ground	G08 General Store	32	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	2 m2
2042502	Ground	G37 Staff Accommodation - Bathroom	32	Yes	Window Sill		No Action	0 No Risk	1 m2
2042499	Ground	Staff Bedroom (G37)	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042501	Ground	Staff Accommodation - Bathroom	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337944	Ground	G08 General Store	32	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2042504	Ground	G36 Rest Room	33	Yes	Window Sill		No Action	0 No Risk	1 m2
2337946	Ground	G09 Laundry	33	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	7 m2

2337945	Ground	G09 Laundry	33	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	7 m2
2042511	Ground	Rest Room	33	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042551	Ground	Locker room	34	Yes	Sill	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2042514	Ground	Lockers	34	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337948	Ground	G10B - Servery	34	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	5 m2
2042531	Ground	G10B - Servery	34	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2042557	Ground	Locker Room	34	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337947	Ground	G10B - Servery	34	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	4 m2
2042532	Ground	G10B - Servery	34	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2042687	Ground	Laundry G 09	35	Yes	Window Sill	Chrysotile	Asbestos Removed	0 No Risk	1 m2
2337950	Ground	G10C - Empties / Liquor Store	35	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	8 m2
2042562	Ground	Laundry (G 09)	35	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2333158	Ground	Laundry (G 09)	35	Yes	Sill		No Action	0 No Risk	1 m2
2337949	Ground	G10C - Empties / Liquor Store	35	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	8 m2
2337952	Ground	G37B - Staff Bedroom	36	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	7 m2
2042684	Ground	General Store G 08	36	Yes			No Action	0 No Risk	0 N/A
2337953	Ground	G37B - Staff Bedroom	36	Yes	Window Sill		No Action	0 No Risk	1 No.
2337951	Ground	G37B - Staff Bedroom	36	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	7 m2
2337954	Ground	G34 Kitchen Staff Lobby	37	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	12 m2
2337955	Ground	G34 Kitchen Staff Lobby	37	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042553	Ground	G07 Female Cloaks	37	Yes	Window Sill		No Action	0 No Risk	1 m2
2337956	Ground	G37A - Bathroom	38	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	4 m2
2042683	Ground	Lockers & Shower G 06	38	Yes	Window Sill		No Action	0 No Risk	2 No.
2337957	Ground	G37A - Bathroom	38	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2337958	Ground	G37 Lobby	39	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337959	Ground	G37 Lobby	39	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	2 m2
2042682	Ground	Cleaners Cupboard	39	Yes			No Action	0 No Risk	0 N/A
2337960	Ground	G35 Lockers	40	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337961	Ground	G35 Lockers	40	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2

2042539	Ground	Gents Cloakroom	40	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042549	Ground	G04 Gents Cloaks	40	Yes	Window Sill		No Action	0 No Risk	1 m2
2042540	Ground	Gents Cloaks	40	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337964	Ground	G36 Rest Room	41	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	12 m2
2042681	Ground	Electric Cupboard G 03	41	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2337962	Ground	G36 Rest Room	41	Yes	Window Sill		No Action	0 No Risk	1 No.
2337963	Ground	G36 Rest Room	41	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2337966	Ground	G39 Cleaners Store	42	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2337965	Ground	G39 Cleaners Store	42	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2042550	Ground	G02 Mess Office	42	Yes	Window Sill		No Action	0 No Risk	1 m2
2042538	Ground	Mess Office	42	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337967	Ground	G41D - Kitchen Office	43	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2042574	Ground	Staircase - Landing	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042573	Ground	Staircase	43	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337969	Ground	G41D - Kitchen Office	43	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4 m2
2337968	Ground	G41D - Kitchen Office	43	Yes	Window Sill		No Action	0 No Risk	1 No.
2337971	Ground	G41 Kitchen	44	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	30 m2
2338096	Ground	G41 Kitchen	44	Yes	Work Surfaces	Chrysotile	Monitor	8	2 No.
2042607	First	Corridor	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337972	Ground	G41 Kitchen	44	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042537	First	Corridor	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337970	Ground	G41 Kitchen	44	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	30 m2
2337973	Ground	G41 Kitchen	44	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	30 m2
2042606	First	Corridor	44	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042695	First	F23 Bedroom	45	Yes	Window Sill		No Action	0 No Risk	1 No.
2337975	Ground	G11H - Servery	45	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	18 m2
2337974	Ground	G11H - Servery	45	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	18 m2
2042584	First	Bedroom F 23	45	Yes	Window Sill		No Action	0 No Risk	1 m2
2042520	Ground	G11H - Servery	45	Yes	Work Surfaces	Chrysotile	Monitor	8	2 No.

2337977	Ground	G38 Ladies Rest Room Lobby	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2337978	Ground	G38 Ladies Rest Room Lobby	46	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2042600	First	Bedroom F 26	46	Yes	Window Sill		No Action	0 No Risk	1 m2
2337976	Ground	G38 Ladies Rest Room Lobby	46	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	1 m2
2337979	Ground	G38B - Ladies WC	47	Yes	Window Sill		No Action	0 No Risk	1 No.
2337981	Ground	G38B - Ladies WC	47	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2042582	First	Toilets F 27	47	Yes	Window Sill		No Action	0 No Risk	1 m2
2042612	First	Toilet F 27	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2337980	Ground	G38B - Ladies WC	47	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2042581	First	Bedroom F 30	48	Yes	Window Sill		No Action	0 No Risk	1 m2
2337983	Ground	G38C WC	48	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2337984	Ground	G38C WC	48	Yes	Window Sill		No Action	0 No Risk	1 No.
2337982	Ground	G38C WC	48	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2337985	Ground	G38A Rest Room	49	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	6 m2
2042580	First	Bedroom F 31 & 32	49	Yes	Window Sill		No Action	0 No Risk	1 m2
2337986	Ground	G38A Rest Room	49	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2337989	Ground	G40 Gents WC Lobby	50	Yes	Floor	No Asbestos Detected	No Action	0 No Risk	2 m2
2042579	First	Bedroom F 34	50	Yes	Window Sill		No Action	0 No Risk	1 m2
2337988	Ground	G40 Gents WC Lobby	50	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2337987	Ground	G40 Gents WC Lobby	50	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2337990	Ground	G40B Gents WC	51	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	3 m2
2337991	Ground	G40B Gents WC	51	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	3 m2
2337992	Ground	G40B Gents WC	51	Yes	Window Sill		No Action	0 No Risk	1 No.
2042578	First	Bedroom F 35	51	Yes	Window Sill		No Action	0 No Risk	1 m2
2042604	First	Bedroom F36	52	Yes	Window Sill		No Action	0 No Risk	1 m2
2337994	Ground	G40C WC	52	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2
2337993	Ground	G40C WC	52	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2042603	First	Bedroom F 33	53	Yes	Window Sill		No Action	0 No Risk	1 m2
2337995	Ground	G40A Electrics Cupboard	53	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	1 m2

2337996	Ground	G11 Ante Room	54	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	110 m2
2042503	Ground	Staff Bathroom G37A	54	Yes	Window Sill		No Action	0 No Risk	1 m2
2337997	Ground	G11 Ante Room	54	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	110 m2
2042602	First	Bedroom F 29	55	Yes	Window Sill		No Action	0 No Risk	1 m2
2337999	Ground	G12 Billiard Room	55	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2337998	Ground	G12 Billiard Room	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2338001	Ground	G10 Bar / Lounge	56	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2042601	First	Bathroom / Showers F 28	56	Yes	Sill		No Action	0 No Risk	1 m2
2338000	Ground	G10 Bar / Lounge	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2338002	Ground	G03 Electrics Cupboard	57	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042599	First	Bedroom F 25	57	Yes	Window Sill		No Action	0 No Risk	1 m2
2042598	First	Bedroom F 24	58	Yes	Window Sill		No Action	0 No Risk	1 m2
2338004	Ground	G07 Ladies Powder Room Lobby	58	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	1 m2
2338003	Ground	G07 Ladies Powder Room Lobby	58	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	1 m2
2338006	Ground	G07A Ladies Powder Room	59	Yes	Window Sill		No Action	0 No Risk	1 No.
2338007	Ground	G07A Ladies Powder Room	59	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	2 m2
2338005	Ground	G07A Ladies Powder Room	59	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	6 m2
2338008	Ground	G07A Ladies Powder Room	59	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	8 m2
2042605	First	Cleaners Cupboard	59	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338011	Ground	G07B Ladies WC	60	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2338013	Ground	G07B Ladies WC	60	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338010	Ground	G07B Ladies WC	60	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	4 m2
2042680	First	Electric Cupboard	60	Yes			No Action	0 No Risk	0 N/A
2338009	Ground	G07B Ladies WC	60	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338012	Ground	G07B Ladies WC	60	Yes	Riser (Dust)	No Asbestos Detected	No Action	0 No Risk	1 m2
2338015	Ground	G05 Cleaners Store	61	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2042609	First	Laundry	61	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338014	Ground	G05 Cleaners Store	61	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	2 m2
2338016	Ground	G04 Cloaks Lobby	62	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2

2042597	First	Drying Room F 05	62	Yes	Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338017	Ground	G04 Cloaks Lobby	62	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2042610	First	Drying Room F 06	62	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042674	First	F 06 Toilets	63	Yes	Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338018	Ground	G04A Male Cloaks	63	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	9 m2
2338020	Ground	G04A Male Cloaks	63	Yes	Ceiling Tiles	No Asbestos Detected	No Action	0 No Risk	9 m2
2338019	Ground	G04A Male Cloaks	63	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338021	Ground	G04A Male Cloaks	63	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338024	Ground	G04B Male WC	64	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2338022	Ground	G04B Male WC	64	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	20 m2
2042596	First	Shower / Bathroom F 09	64	Yes	Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338025	Ground	G04B Male WC	64	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	9 m2
2042611	First	Toilet	64	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338023	Ground	G04B Male WC	64	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338027	Ground	Corridor 1	65	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2042595	First	Bedroom F 12	65	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338026	Ground	Corridor 1	65	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338029	Ground	G01 Entrance Hall	66	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	50 m2
2338028	Ground	G01 Entrance Hall	66	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2042594	First	Bedroom F 13	66	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2042593	First	Bedroom F 15	67	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338030	Ground	Entrance Porch	67	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042592	First	Bedroom F 18	68	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 m2
2338033	Ground	G14 Television Room	68	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	2 m2
2338031	Ground	G14 Television Room	68	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	25 m2
2338032	Ground	G14 Television Room	68	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	25 m2
2338035	Ground	Corridor 2	69	Yes	Fireglass (Lining)	No Asbestos Detected	No Action	0 No Risk	2 m2
2338034	Ground	Corridor 2	69	Yes	Ceiling (Residues)	No Asbestos Detected	No Action	0 No Risk	20 m2
2338037	Ground	Corridor 2	69	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2

2042591	First	Bedroom F 17	69	Yes	Window Sill		No Action	0 No Risk	1 m2
2338036	Ground	Corridor 2	69	Yes	Suspended Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2338039	Ground	G16A Ironing	70	Yes	Window Sill		No Action	0 No Risk	1 No.
2338040	Ground	G16A Ironing	70	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2042590	First	Bedroom F 16	70	Yes	Window Sill		No Action	0 No Risk	1 m2
2338038	Ground	G16A Ironing	70	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338041	Ground	G16A Ironing	70	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338043	Ground	G16 Laundry	71	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338042	Ground	G16 Laundry	71	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042568	Ground	G16 Laundry	71	Yes	Sink		No Action	0 No Risk	2 No.
2042589	First	Bedroom F 14	71	Yes	Window Sill		No Action	0 No Risk	1 m2
2042588	First	Bedroom F 11	72	Yes	Window Sill		No Action	0 No Risk	1 m2
2338045	Ground	G18 Drying Room	72	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338046	Ground	G18 Drying Room	72	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	7 m2
2338044	Ground	G18 Drying Room	72	Yes	Window Sill		No Action	0 No Risk	1 No.
2338047	Ground	G18 Drying Room	72	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2042587	First	Bedroom F 08	73	Yes	Window Sill		No Action	0 No Risk	1 m2
2338049	Ground	G21 Baggage Store	73	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2338048	Ground	G21 Baggage Store	73	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2338051	Ground	G20 Bathroom / Shower	74	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2338052	Ground	G20 Bathroom / Shower	74	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	6 m2
2042586	First	Bedroom F 07	74	Yes	Window Sill		No Action	0 No Risk	1 m2
2338050	Ground	G20 Bathroom / Shower	74	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338053	Ground	G19 Cleaners Store	75	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2042585	First	Bedroom F 03	75	Yes	Window Sill		No Action	0 No Risk	1 m2
2338054	Ground	G19 Cleaners Store	75	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2338057	Ground	G17 Toilets	76	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2042675	First	F 20 Store	76	Yes			No Action	0 No Risk	0 N/A
2338055	Ground	G17 Toilets	76	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	7 m2

2338056	Ground	G17 Toilets	76	Yes	Window Sill	No Asbestos Detected	No Action	0 No Risk	1 No.
2338058	Ground	G17 Toilets	76	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2042575	Ground / First	G13 Stairwell	77	Yes	Stair Nosings	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338059	First	G13 Stairwell	77	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	15 m2
2338062	First	F01 Lobby Area	78	Yes	Fireglass (Lining)	No Asbestos Detected	No Action	0 No Risk	1 m2
2338060	First	F01 Lobby Area	78	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2338061	First	F01 Lobby Area	78	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	5 m2
2338063	First	F20 Baggage Store	79	Yes			No Action	0 No Risk	0 N/A
2042693	Ground	E & P	80	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338065	First	F21 Cleaners Store	80	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	2 m2
2338064	First	F21 Cleaners Store	80	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	2 m2
2042688	Ground	Calorifer Room	81	Yes	Fuse Box	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2338067	First	F22 Corridor 3	81	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	20 m2
2042613	Ground	Calorifier Room	81	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338066	First	F22 Corridor 3	81	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	20 m2
2338068	Loft	Loft Space (Corridor 3)	82	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338069	First	F28 Bathroom / Showers	83	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2338071	First	F28 Bathroom / Showers	83	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2338070	First	F28 Bathroom / Showers	83	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	1 m2
2338073	First	F27 Toilets	84	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	7 m2
2338074	First	F27 Toilets	84	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	7 m2
2338072	First	F27 Toilets	84	Yes	Window Sill		No Action	0 No Risk	1 No.
2338077	First	F02 Corridor 4	85	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	9 m2
2338075	First	F02 Corridor 4	85	Yes	Fireglass (Lining)	No Asbestos Detected	No Action	0 No Risk	2 m2
2042577	External	External	85	Yes			No Action	0 No Risk	0 N/A
2338076	First	F02 Corridor 4	85	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	9 m2
2042608	Roof Void	Roof Void	86	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338078	Loft	Loft Space (Corridor 4)	86	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338080	First	F04 Laundry	87	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	5 m2

Run Date:
16/01/2017 03:43:47

Page:
101 of 113

Run By:
CD\svc_ProRepuuser

2338079	First	F04 Laundry	87	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	5 m2
2042668	First	F 24 Bathroom	87	Yes			No Action	0 No Risk	0 N/A
2338082	First	F04A Ironing	88	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338081	First	F04A Ironing	88	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338084	First	F05 Drying Room	89	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	4.m2
2338083	First	F05 Drying Room	89	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	4 m2
2338086	First	F06 Toilets	90	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	5 m2
2338085	First	F06 Toilets	90	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	5 m2
2338088	First	F09 Bathroom / Shower	91	Yes	Ceiling Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2338089	First	F09 Bathroom / Shower	91	Yes	Wall Composition	No Asbestos Detected	No Action	0 No Risk	10 m2
2338087	First	F09 Bathroom / Shower	91	Yes	Window Frame Void	No Asbestos Detected	No Action	0 No Risk	2 m2
2338090	First	F10 Corridor 5	92	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	12 m2
2338091	First	F10 Corridor 5	92	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2338092	Loft	Loft Space (Corridor 5)	93	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2338093	First	F02.1 Electrics Cupboard	94	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042614	Ground	G42 Plant Room	95	Yes	Valve	No Asbestos Detected	No Action	0 No Risk	0 N/A
2338094	Ground	G42 Plant Room	95	Yes	Plasterboard Ceiling	No Asbestos Detected	No Action	0 No Risk	7 m2
2338095	Ground	G46 Electrical Cupboard	96	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042525	Ground	General Store	97	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042561	Ground	General Store	97	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2042629	Ground	Utensil Store	98	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042628	Ground	Silver Plate	99	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042529	Ground	G10D Beer and Liquor Store	100	Yes	Sink		No Action	0 No Risk	1 No.
2042691	Ground	Refuse	101	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042690	Ground	Fuel Store	102	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042689	Ground	Swill	103	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042679	Ground	Yard	104	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042694	Ground	Garden Furniture	105	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2042615	Roof	Roof	106	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A

2338096	External	External	107	Yes	Window Frames	No Asbestos Detected	No Action	0 No Risk	100 m2
2042678	All	External / Internal	108	Yes	Window Frame	No Asbestos Detected	No Action	0 No Risk	100 m2
WEETON CAMP - SOCIAL CLUB - 755828 - WEET01WEE015									
2043503	Ground	Restaurant	1	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043504	Ground	Restaurant	1	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	96 m2
2043595	Ground	Servery / Wash Up	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043553	Ground	Kitchen	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043556	Ground	Kitchen	3	Yes	Window Sill	Chrysotile	Monitor	10 Medium	1 m2
2043549	Ground	Kitchen	3	Yes	Work Surfaces	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2043554	Ground	Kitchen	3	Yes	Sink	Chrysotile	Asbestos Removed	0 No Risk	1 No.
2043548	Ground	Kitchen	3	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043550	Ground	Store 1	4	Yes	Ceiling	Chrysotile	Monitor	5	2 m2
2043551	Ground	Store 2	5	Yes	Ceiling	Chrysotile	Monitor	5	6 m2
2043552	Ground	Store 3	6	Yes	Ceiling	Chrysotile	Monitor	6	2 m2
2043565	Ground	Corridor	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211337	Ground	Office	8	Yes	Safe	Presumed Asbestos Content	Monitor	12 Medium	1 No.
2211342	Ground	Office	8	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2043566	Ground	Office	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2340148	Ground	Staff Dining Room	9	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2043567	Ground	Staff Dining Room	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211345	Ground	Lockers	10	Yes	Window Sill	Chrysotile	Monitor	7	1 No.
2043568	Ground	Lockers	10	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2336649	Ground	Female Toilet	11	Yes	Window Sill	Chrysotile	Monitor	6	2 No.
2043569	Ground	Female Toilet	11	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043570	Ground	Male Toilet	12	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043572	Ground	Bulk Store	13	Yes	Ceiling	Chrysotile	Monitor	7	10 m2
2043571	Ground	Bulk Store	13	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2210990	Ground	Beer Store	14	Yes			No Action	0 No Risk	0 N/A
2043573	Ground	Store (G45)	15	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
103 of 113

Run By:
CD\\svc_ProRepuuser

2043541	Ground	Bar / Servery	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043546	Ground	Bar / Servery	16	Yes	Work Surfaces	Chrysotile	Monitor	8 [REDACTED]	4 No.
2043547	Ground	Bar / Servery	16	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2210999	Ground	Electric Cupboard	17	Yes			No Action	0 No Risk	0 N/A
2043543	Ground	Corporals Bar	18	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2043539	Ground	Corporals Bar	18	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043542	Ground	Corporals Bar	18	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2043540	Ground	Corporals Bar	18	Yes	Ceiling	Chrysotile	Monitor	11 Medium	15 m2
2043538	Ground	Corporals TV / Billiard Room	19	Yes	Ceiling	Chrysotile	Monitor	10 Medium	35 m2
2043537	Ground	Corporals TV / Billiard Room	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043535	Ground	Male Toilet - Corporals Mess	20	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043536	Ground	Male Toilet - Corporals Mess	20	Yes	Ceiling	Chrysotile	Monitor	8 [REDACTED]	18 m2
2043593	Ground	Male Toilet - Corporals Mess	20	Yes			No Action	0 No Risk	0 N/A
2043519	Ground	Male Toilet - Corporals Mess	20	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 m2
2211000	Ground	Electric Cupboard	21	Yes			No Action	0 No Risk	0 N/A
2043518	Ground	Female Toilet - Corporals Mess	22	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	1 m2
2043534	Ground	Female Toilet - Corporals Mess	22	Yes	Ceiling	Chrysotile	Asbestos Removed	0 No Risk	6 m2
2043533	Ground	Female Toilet - Corporals Mess	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2333150	Ground	Female Toilet - Corporals Mess	22	Yes	Ceiling	Chrysotile	Monitor	6 [REDACTED]	2 m2
2043596	Ground	Lobby	23	Yes	Ceiling	Chrysotile	Monitor	7 [REDACTED]	15 m2
2043544	Ground	Tavern Bar	24	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2377731	Ground	Tavern Bar	24	Yes	Window Sill	Presumed Asbestos Content	Monitor	8 [REDACTED]	10 LM
2043578	Ground	Tavern Bar	24	Yes			No Action	0 No Risk	0 N/A
2043582	Ground	Tavern Bar	24	Yes			No Action	0 No Risk	0 N/A
2043514	Ground	Corporals Bar	24	Yes	Sill	Chrysotile	Asbestos Removed	0 No Risk	3 m2
2043545	Ground	Tavern Bar	24	Yes	Sink	No Asbestos Detected	No Action	0 No Risk	1 No.
2043505	Ground	Tavern Bar, Snooker Bar and Lounge Bar	24	Yes	Ceiling	Chrysotile	Monitor	10 Medium	50 m2
2377732	Ground	Lounge Bar	25	Yes	Window Sill	Presumed Asbestos Content	Monitor	8 [REDACTED]	12 LM

2336642	Ground	Lounge Bar	25	Yes	Wooden Ledge	No Action	0 No Risk	1 m2
2043577	Ground	Lounge Bar	25	Yes	Ceiling	Chrysotile	Monitor	9 Medium 50 m2
2043506	Ground	Corridor 1	26	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043507	Ground	Corridor 1	26	Yes	Ceiling	Chrysotile	Encapsulate/Repair	11 Medium 40 m2
2333251	Ground	Shop	27	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 55 m2
2333252	Ground	Shop	27	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED] 2 m2
2043598	Ground	Shop	27	Yes	Floor	No Asbestos Detected	No Action	0 No Risk 40 m2
2043532	Ground	Hairdressers	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2211170	Ground	Social Activities (Bar Area)	29	Yes	Ceiling	Chrysotile	Monitor	9 Medium 45 m2
2377733	Ground	Social Activities (Bar Area)	29	Yes	Window Sill	Presumed Asbestos Content	Monitor	8 [REDACTED] 12 LM
2043531	Ground	Cleaners Cupboard	30	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043517	Ground	Reading Room	31	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED] 2 m2
2043528	Ground	Reading Room	31	Yes	Ceiling	Chrysotile	Monitor	8 [REDACTED] 10 m2
2043527	Ground	Reading Room	31	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043530	Ground	Church	32	Yes	Ceiling	Chrysotile	Monitor	7 [REDACTED] 25 m2
2043529	Ground	Church	32	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2340149	Ground	SODEXO Office	33	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED] 3 No.
2043526	Ground	SODEXO Office	33	Yes	Ceiling	Chrysotile	Monitor	9 Medium 25 m2
2043525	Ground	Games Room	33	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043523	Ground	TV Room 2	34	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043524	Ground	SODEXO Site Office	34	Yes	Ceiling	Chrysotile	Monitor	9 Medium 10 m2
2043516	Ground	TV Room 2	34	Yes	Sill		No Action	0 No Risk 1 m2
2043521	Ground	TV Room 1	35	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043522	Ground	TV Room 1	35	Yes	Ceiling	Chrysotile	Monitor	9 Medium 10 m2
2043515	Ground	TV Room 1	35	Yes	Sill		No Action	0 No Risk 1 m2
2043520	Ground	Social Activities Store	36	Yes	Walls	No Asbestos Detected	No Action	0 No Risk 0 N/A
2043597	Ground	Corridor	37	Yes	Ceiling	Chrysotile	Encapsulate/Repair	8 [REDACTED] 25 m2
2043512	Ground	38a Female / Disabled Toilet	38	Yes		No Sample Required	No Action	0 No Risk 0 N/A
2043557	Ground	Female Toilet	38	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED] 1 m2

2336643	Ground	38b Female / Disabled Toilet	38	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043510	Ground	Female / Disabled Toilet / Lobby	38	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043511	Ground	Female Toilet	38	Yes	Ceiling	Chrysotile	Monitor	6 [REDACTED]	6 m2
2043509	Ground	Male Toilet	39	Yes	Ceiling	Chrysotile	Monitor	6 [REDACTED]	8 m2
2043508	Ground	Male Toilet	39	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043513	Ground	Male Toilet	39	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 m2
2043564	Ground	Staircase / Corridor	40	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043563	Ground	Staircase / Corridor	40	Yes	Stairs	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211273	First	Electrical Cupboard	41	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2211007	First	Store Room	42	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043561	First	Kitchen F18	43	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211353	First	Kitchen	43	Yes	Sink Pad	Presumed Asbestos Content	Asbestos Removed	0 No Risk	1 No.
2211011	First	Managers F19	44	Yes	Window Sill		No Action	0 No Risk	2 No.
2211013	First	Assistant Managers F20	45	Yes	Window Sill		No Action	0 No Risk	2 No.
2043560	First	Bathroom F21	46	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2340705	First	Bathroom F21	46	Yes	Bath (Pad)		No Action	0 No Risk	1 m2
2211365	First	Bathroom F21	46	Yes	Window Sill		No Action	0 No Risk	1 No.
2211017	First	Airing Cupboard	47	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2211018	First	Lobby	48	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2211019	First	Male Bedroom F14	49	Yes	Window Sill		No Action	0 No Risk	1 No.
2211021	First	Airing Cupboard	50	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2340706	First	Bathroom F12	51	Yes	Bath (Pad)		No Action	0 No Risk	1 m2
2043562	First	Bathroom F12	51	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211374	First	Bathroom F12	51	Yes	Window Sill		No Action	0 No Risk	1 No.
2211022	First	Corridor	52	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2211378	First	Kitchen	53	Yes	Window Sill		No Action	0 No Risk	2 No.
2211023	First	Kitchen	53	Yes	Sink		No Action	0 No Risk	1 No.
2211024	First	Corridor	54	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043555	First	Toilet F08	55	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A

2336644	First	Toilet F08	55	Yes	Window Sill		No Action	0 No Risk	1 No.
2043559	First	Bathroom F07	56	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2211381	First	Bathroom F07	56	Yes	Window Sill		No Action	0 No Risk	1 No.
2340707	First	Bathroom F07	56	Yes	Bath (Pad)		No Action	0 No Risk	1 m2
2211025	First	Female Bedroom F06	57	Yes	Window Sill		No Action	0 No Risk	1 No.
2211026	First	Female Bedroom F05	58	Yes	Window Sill		No Action	0 No Risk	2 No.
2211028	First	Female Bedroom F04	59	Yes	Window Sill		No Action	0 No Risk	2 No.
2211029	First	Female Bedroom F03	60	Yes	Window Sill		No Action	0 No Risk	1 No.
2211030	First	Sitting Room F02	61	Yes	Window Sill		No Action	0 No Risk	1 No.
2211418	First	Female Bedroom	62	Yes	Ceiling		No Action	0 No Risk	15 m2
2211031	First	Female Bedroom	62	Yes	Window Sill		No Action	0 No Risk	2 No.
2211033	First	Bathroom	63	Yes	Ceiling		No Action	0 No Risk	4 m2
2340708	First	Bathroom	63	Yes	Bath (Pad)		No Action	0 No Risk	1 m2
2211426	First	Bathroom	63	Yes	Window Sill		No Action	0 No Risk	1 No.
2211436	First	Kitchen	64	Yes	Ceiling		No Action	0 No Risk	6 m2
2211034	First	Kitchen	64	Yes	Sink		No Action	0 No Risk	1 m2
2211447	First	Female Bedroom F04	65	Yes	Window Sill		No Action	0 No Risk	2 No.
2211036	First	Female Bedroom F04	65	Yes	Ceiling		No Action	0 No Risk	15 m2
2211038	First	Lobby	66	Yes	Ceiling		No Action	0 No Risk	3 m2
2043575	Ground	Calorifier Room	67	Yes	Flange	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2334831	First	Store	67	Yes	Ceiling		No Action	0 No Risk	1 m2
2340709	First	Airing Cupboard	68	Yes	Ceiling		No Action	0 No Risk	1 m2
2340710	First	Staircase	69	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2336645	Ground	70a - Plant Room G31	70	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043574	Ground	Calorifier Room	70	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2043601	Ground	Booster Pump Room	71	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2334830	Ground	Service Duct G27D	72	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2043558	Roof Space	Roof Space	73	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2334832	Roof Space	Roof Space	74	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	40m2

2340711	Roof Space	Roof Space	75	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	70 m2
2340712	Roof Space	Roof Space	76	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	15 m2
2340713	Roof Space	Roof Space	77	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	50 m2
2211039	Roof	Roof	78	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	45 LM
2211040	External	External	79	Yes		No Sample Required	No Action	0 No Risk	0 N/A
WEETON CAMP - SPORTS PAVILION - 755815 - WEET01WEE043									
2085570	Ground	Entrance Lobby	1	Yes			No Action	0 No Risk	0 N/A
2085572	Ground	Common Room	2	Yes			No Action	0 No Risk	0 N/A
2044811	Ground	Common Room	2	Yes	Sink Unit	Chrysotile	Monitor	6 [REDACTED]	2 No.
2044815	Ground	Officials Changing	3	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044810	Ground	Female Toilet	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044825	Ground	Female Toilet	4	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2044808	Ground	Female Toilet	4	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044814	Ground	Corridor	5	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044813	Ground	Corridor	5	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044816	Ground	Changing Room 1	6	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044820	Ground	Changing Room 1	6	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2044809	Ground	Changing Room 2	7	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044821	Ground	Changing Room 2	7	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2044822	Ground	Changing Room 3	8	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2044817	Ground	Changing Room 3	8	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044823	Ground	Male Toilet	9	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2044819	Ground	Male Toilet	9	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044818	Ground	Male Toilet	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044824	Ground	Machinery and P.O.L Store	10	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	2 m2
2044807	Ground	Sports Equipment Store	11	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 m2
2337433	Ground	Plant Room G13	12	Yes	Base of Calorifiers	No Asbestos Detected	No Action	0 No Risk	2 m2
2337432	Ground	Plant Room G13	12	Yes	Wall Mounted Electric Box	Presumed Asbestos Content	Monitor	6 [REDACTED]	1 m2
2337435	Ground	Plant Room G13	12	Yes	Block Wall		No Action	0 No Risk	10 m2

Run Date:
16/01/2017 03:43:47

Page:
108 of 113

Run By:
CD\svc_ProRepuuser

2337438	Ground	Plant Room G13	12	Yes	Pipework Elbows	No Asbestos Detected	No Action	0 No Risk	1 m2
2337441	Ground	Plant Room G13	12	Yes	Calorifiers 1 & 2		No Action	0 No Risk	1 m2
2044828	Ground	Plant Room G13	12	Yes	Compressor		No Action	0 No Risk	1 m2
2333161	Ground	Plant Room G13 Loft Space	12	Yes	Wall	No Asbestos Detected	No Action	0 No Risk	5 m2
2337448	Ground	Plant Room G13 Loft Space	12	Yes	Flue Pipe Surround	No Asbestos Detected	No Action	0 No Risk	1 m2
2337436	Ground	Plant Room G13	12	Yes	Calorifiers 1 & 2	No Asbestos Detected	No Action	0 No Risk	1 m2
2337439	Ground	Plant Room G13	12	Yes	Calorifiers 1 & 2	No Asbestos Detected	No Action	0 No Risk	1 m2
2337442	Ground	Plant Room G13	12	Yes	Calorifiers 1 & 2		No Action	0 No Risk	1 m2
2337445	Ground	Plant Room G13	12	Yes	Base of Boiler	No Asbestos Detected	No Action	0 No Risk	1 m2
2333159	Ground	Plant Room	12	Yes	Boiler	No Asbestos Detected	No Action	0 No Risk	1 m2
2337440	Ground	Plant Room G13	12	Yes	Calorifiers 1 & 2	No Asbestos Detected	No Action	0 No Risk	1 m2
2337443	Ground	Plant Room G13	12	Yes	Boiler Interior (Seal)	No Asbestos Detected	No Action	0 No Risk	1 m2
2337446	Ground	Plant Room G13	12	Yes	Metal Flue Pipe	No Asbestos Detected	No Action	0 No Risk	2 m2
2085588	Ground	Plant Room	12	Yes	Calorifier	No Asbestos Detected	No Action	0 No Risk	2 No.
2333160	Ground	Plant Room G13	12	Yes	Plasterboard Ceiling	No Asbestos Detected	No Action	0 No Risk	10 m2
2337444	Ground	Plant Room G13	12	Yes	Boiler Interior	No Asbestos Detected	No Action	0 No Risk	1 m2
2337447	Ground	Plant Room G13	12	Yes	Boiler	No Asbestos Detected	No Action	0 No Risk	4 No.
2337450	Ground	Plant Room G13 Loft Space	12	Yes	Pipework (Lagging)	No Asbestos Detected	No Action	0 No Risk	10 LM
2337449	Ground	Plant Room G13 Loft Space	12	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	10 m2
2044829	Ground	Plant Room	12	Yes	Pipework	No Asbestos Detected	No Action	0 No Risk	2 No.
2337431	Ground	Plant Room G13	12	Yes	Wall Mounted		No Action	0 No Risk	1 m2
2337434	Ground	Plant Room G13	12	Yes	Base of Boiler	No Asbestos Detected	No Action	0 No Risk	1 m2
2337437	Ground	Plant Room G13	12	Yes	Pipework (Lagging)	No Asbestos Detected	No Action	0 No Risk	10 LM
2085600	Ground	Plant Room	12	Yes	Fuse Box	No Sample Required	No Action	0 No Risk	1 No.
2333157	Ground	Plant Room	12	Yes	Boiler Burner	No Asbestos Detected	No Action	0 No Risk	1 No.
2085608	Roof	Roof	13	Yes	Flue Pipes	Strongly Presumed Asbestos Content	Asbestos Removed	0 No Risk	4 No.
2044827	Roof	Roof	13	Yes	Verge	No Asbestos Detected	No Action	0 No Risk	5 LM
2337451	External	External	14	Yes	Double Door Frame	No Asbestos Detected	No Action	0 No Risk	4 m2
2044826	External	External	14	Yes	Fillet	No Asbestos Detected	No Action	0 No Risk	0 N/A

Run Date:
16/01/2017 03:43:47

Page:
109 of 113

Run By:
CD\svc_ProRepuser

2044812	Roof Void	Roof Void	15	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044830	Roof Void	Roof Void	15	Yes	Roof Void	No Asbestos Detected	No Action	0 No Risk	0 N/A
WEETON CAMP - STORE - 755810 - WEET01WEE035									
2044563	Ground	Store	1	Yes			No Action	0 No Risk	0 N/A
2085191	Ground	Ammo Store	2	Yes			No Action	0 No Risk	0 N/A
2085193	Roof	Roof	3	Yes			No Action	0 No Risk	0 N/A
2044564	External	External	4	Yes	Fuse Box	No Sample Required	No Action	0 No Risk	1 No.
WEETON CAMP - SUBSTATION - 755814 - WEET01WEE042									
2084416	Ground	Electric Station	1	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2084421	Ground	Electric Station	2	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2084422	Ground	Electric Station	3	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2084423	Roof	Roof	4	Yes			No Action	0 No Risk	0 N/A
2084425	External	External	5	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - TRAINING WING - 755834 - WEET01WEE023									
2044232	Ground	Corridor	1	Yes	Window Sill		No Action	0 No Risk	2 m2
2044221	Ground	Office	2	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2148108	Ground	Office	2	Yes	Window Sill	Chrysotile	Monitor	7	1 m2
2148113	Ground	Office	3	Yes	Window Sill	Chrysotile	Monitor	7	1 m2
2044224	Ground	Office	4	Yes	Window Sill	Chrysotile	Monitor	7	1 m2
2044226	Ground	Male Toilet	5	Yes	Window Sill	Chrysotile	Monitor	6	2 m2
2044222	Ground	Cleaners Cupboard	6	Yes	Window Sill	Chrysotile	Monitor	7	1 m2
2044228	Ground	Electrics Cupboard	7	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044238	Ground	Classroom	8	Yes			No Action	0 No Risk	0 N/A
2044231	Ground	Store	9	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044234	Ground	Lobby	10	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044235	Ground	Electrics Cupboard	11	Yes		No Sample Required	No Action	0 No Risk	0 N/A
2044236	Ground	Corridor	12	Yes			No Action	0 No Risk	0 N/A
2044239	Ground	Classroom	13	Yes			No Action	0 No Risk	0 N/A
2044240	Ground	Classroom	14	Yes			No Action	0 No Risk	0 N/A

2044241	Ground	Classroom	15	Yes			No Action	0 No Risk	0 N/A
2044244	Ground	Classroom	16	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044223	Ground	Library	17	Yes	Window Sill	Chrysotile	Monitor	7 [REDACTED]	2 m2
2044245	Ground	Classroom	18	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044217	Ground	Classroom	18	Yes	Window Sill	Chrysotile	Encapsulate/Repair	9 Medium	2 No.
2044246	Ground	Classroom	19	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044227	Ground	Indoor Range	20	Yes	Window Sill		No Action	0 No Risk	1 m2
2044255	Ground	Projector Store	21	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044243	Ground	Store	22	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044242	Ground	Lobby	23	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044259	Ground	Electric Cupboard	24	Yes	Fuse Box	No Sample Required	No Action	0 No Risk	1 No.
2044257	Ground	Calorifier Room	25	Yes			No Action	0 No Risk	0 N/A
2044258	Ground	Calorifier Room	25	Yes	Gaskets	Chrysotile	Asbestos Removed	0 No Risk	0 N/A
2333250	First	Corridor	26	Yes	Ceiling	Chrysotile	Monitor	7 [REDACTED]	45 m2
2044237	First	Corridor	26	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	6 LM
2044247	First	Classroom	27	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335034	First	Classroom	27	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	3 m2
2044248	First	Classroom	28	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335035	First	Classroom	28	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	3 m2
2044260	First	Office	29	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044261	First	Office	30	Yes	Window Sill	Chrysotile	Monitor	6 [REDACTED]	1 No.
2044253	First	Female Toilet	31	Yes	Window Sill	Chrysotile	Monitor	5 [REDACTED]	2 No.
2044239	First	Classroom	32	Yes	Window Sill	Chrysotile	Monitor	9 Medium	3 m2
2044249	First	Classroom	32	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044251	First	Classroom	33	Yes	Walls	No Asbestos Detected	No Action	0 No Risk	0 N/A
2335036	First	Classroom	33	Yes	Window Sill	Chrysotile	Monitor	8 [REDACTED]	2 m2
2044252	First	Classroom	33	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044262	Roof Void	Roof Void	34	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	50 m2
2044263	Roof Void	Roof Void	35	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	25 m2

2044250	Roof	Roof	36	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044289	External	External	37	Yes			No Action	0 No Risk	0 N/A
2044225	Ground	Chaplin	38	Yes			No Action	0 No Risk	0 N/A
2044229	Ground	Weapons Training Officer	39	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - UNIT GARAGES - 755809 - WEET01WEE034									
2044561	Ground	Garage	1	Yes			No Action	0 No Risk	0 N/A
2044560	Ground	Camouflage Netting Store	2	Yes			No Action	0 No Risk	0 N/A
2044559	Ground	Heated Garage	3	Yes			No Action	0 No Risk	0 N/A
2044551	Ground	Secure store G/ 09C	4	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044557	Ground	Secure Store 2	5	Yes			No Action	0 No Risk	0 N/A
2044556	Ground	Secure Store G 08/A	6	Yes			No Action	0 No Risk	0 N/A
2044555	Ground	Garage	7	Yes			No Action	0 No Risk	0 N/A
2044553	Ground	Secure G 08E	8	Yes			No Action	0 No Risk	0 N/A
2044554	Ground	Secure Store G 08F	9	Yes			No Action	0 No Risk	0 N/A
2044552	Ground	Assault Pioneer Store	10	Yes			No Action	0 No Risk	0 N/A
2044558	Ground	Secure Store G 09L	11	Yes			No Action	0 No Risk	0 N/A
2044550	Roof	Lining To Roof	12	Yes	Roof	No Asbestos Detected	No Action	0 No Risk	0 N/A
2044562	External	External	13	Yes			No Action	0 No Risk	0 N/A
WEETON CAMP - UNIT GARAGES AND MT OFFICES - 755808 - WEET01WEE033									
2044505	Ground	Entrance	1	Yes			No Action	0 No Risk	0 N/A
2044510	Ground	RRWO	2	Yes	Window Sill	Chrysotile	Monitor	6	2 No.
2044509	Ground	Control Office	3	Yes	Window Sill	Chrysotile	Monitor	7	4 No.
2044511	Ground	Office	4	Yes	Window Sill	Chrysotile	Monitor	8	1 No.
2044508	Ground	Drivers Locker Room	5	Yes	Window Sill	Chrysotile	Monitor	6	2 No.
2044514	Ground	Store	6	Yes			No Action	0 No Risk	0 N/A
2044512	Ground	Office	7	Yes	Window Sill	Chrysotile	Monitor	6	1 No.
2044519	Ground	Office	8	Yes	Ceiling	No Asbestos Detected	No Action	0 No Risk	12 m2
2333254	Ground	Office	8	Yes	Window Sill	Chrysotile	Monitor	6	1 No.
2044542	Ground	Office	9	Yes	Window Sill	Chrysotile	Monitor	6	1 No.

Run Date:
16/01/2017 03:43:47

Page:
112 of 113

Run By:
CD\svc_ProRepuser

2044515	Ground	Workshop Office	10	Yes	Window Sill	Chrysotile	Monitor	8		1 No.
2044516	Ground	Officers Toilet	11	Yes	Window Sill	Chrysotile	Monitor	7		1 No.
2044517	Ground	Staff Toilet	12	Yes	Window Sill	Chrysotile	Monitor	6		4 No.
2044513	Ground	USA Office / Store	13	Yes	Window Sill		No Action	0	No Risk	1 m2
2044521	Ground	Accounts	14	Yes	Window Sill	Chrysotile	Monitor	8		1 No.
2044540	Ground	Electric Room	15	Yes			No Action	0	No Risk	0 N/A
2044518	Ground	Locker Room	16	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2044526	Ground	Workshop	17	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	5 No.
2044527	Ground	Store	18	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	5 No.
2044524	Ground	Store	18	Yes	Window Sill	No Asbestos Detected	No Action	0	No Risk	2 m2
2044506	Ground	Treatment Plant Room	19	Yes			No Action	0	No Risk	0 N/A
2044520	Ground	Mess Room	20	Yes	Window Sill	Chrysotile	Monitor	7		2 No.
2044541	Ground	Office	21	Yes			No Action	0	No Risk	0 N/A
2044531	Ground	Observation Room	22	Yes	Fuse Box	No Sample Required	No Action	0	No Risk	1 No.
2044546	Ground	Calorifier Room	23	Yes			No Action	0	No Risk	0 N/A
2044548	Ground	Battery Charge	24	Yes			No Action	0	No Risk	0 N/A
2044547	Ground	Acid Store	25	Yes			No Action	0	No Risk	0 N/A
2044532	Roof	Roof	26	Yes			No Action	0	No Risk	0 N/A
2044549	External	External	27	Yes			No Action	0	No Risk	0 N/A
WEETON CAMP - WO AND RANK AND FILE GARAGES - 755852 - WEET01WEE004										
2042329	Ground	Garages	1	Yes	Ceiling	No Asbestos Detected	No Action	0	No Risk	0 N/A
2042330	Ground	Garages	1	Yes			No Action	0	No Risk	0 N/A
2042331	External	External	2	Yes			No Action	0	No Risk	0 N/A